

**YOU STAY SAFE  
WHEREVER YOU ARE GOING**




**TURKOMOTIVE**  
■ ■ ■ ■ AFTERMARKET SOLUTIONS

[www.turkomotive.com](http://www.turkomotive.com)

**MERCEDES PARTS**

**TURKOMOTIVE** AFTERMARKET SOLUTIONS' RELIABLE OE-MATCHING QUALITY COMPONENTS ENSURE  
**YOU STAY SAFE , WHEREVER YOU ARE GOING**




**FOLLOW US**

**#turkomotive**

# TURKO

YOU STAY SAFE  
WHEREVER YOU ARE GOING










[www.turkomotive.com](http://www.turkomotive.com)

MOTIVE



















| TM No.  | Replaces Ref. No: | Description          | Model / Details  |
|---|-------------------|----------------------|------------------|
| <b>TM01338</b><br>   |                   | Gasket, Rocker Cover | 979 ACCELO       |
|   |                   |                      | 375 ACTROS       |
|   |                   |                      | 375 ATEGO        |
|   |                   |                      | 970 ATEGO        |
|   |                   |                      | 972 ATEGO        |
|   |                   |                      | 975 ATEGO        |
|   |                   |                      | 976 ATEGO        |
| <b>TM01266</b><br>   | 4030160321        | Gasket, Rocker Cover | 363 LP 2226/6X4  |
|   | 4420160121        |                      | 363 LP 2232/6X4  |
|   | 4420160221        |                      | 363 LPB 2226/6X4 |
|   | 4420160421        |                      | 363 LPK 2226/6X4 |
|   |                   |                      | 363 LPK 2232/6X4 |
|   |                   |                      | 363 LPS 2226/6X4 |
|   |                   |                      | 363 LPS 2232/6X4 |
| <b>TM01325</b><br>  | 4570160121        | Gasket, Rocker Cover | 979 ACCELO       |
|   | 4570160221        |                      | 950 ACTROS       |
|   |                   |                      | 952 ACTROS       |
|   |                   |                      | 953 ACTROS       |
|   |                   |                      | 954 ACTROS       |
|   |                   |                      | 930 ACTROS 2/3   |
|   |                   |                      | 932 ACTROS 2/3   |
| <b>TM01332</b><br> | 4570160021        | Gasket, Rocker Cover | 375 AXOR         |
|   |                   |                      | 374 AXOR 2       |
|   |                   |                      | 940 AXOR 2       |
|   |                   |                      | 942 AXOR 2       |
|   |                   |                      | 943 AXOR 2       |
|   |                   |                      | 944 AXOR 2       |
|   |                   |                      | 695 LS 1634EL    |
| <b>TM01324</b><br> | 5410160321        | Gasket, Rocker Cover | 979 ACCELO       |
|   |                   |                      | 950 ACTROS       |
|   |                   |                      | 952 ACTROS       |
|   |                   |                      | 953 ACTROS       |
|   |                   |                      | 954 ACTROS       |
|   |                   |                      | 930 ACTROS 2/3   |
|   |                   |                      | 932 ACTROS 2/3   |
| 933 ACTROS 2/3  |                   |                      |                  |
| <b>TM01311</b><br> | 5410160421        | Gasket, Rocker Cover | 979 ACCELO       |
|   |                   |                      | 950 ACTROS       |
|   |                   |                      | 952 ACTROS       |
|   |                   |                      | 953 ACTROS       |
|   |                   |                      | 954 ACTROS       |
|   |                   |                      | 930 ACTROS 2/3   |
|   |                   |                      | 932 ACTROS 2/3   |
| <b>TM01440</b><br> | 9060160421        | Gasket, Rocker Cover | 375 ACTROS       |
|   |                   |                      | 970 ATEGO        |
|   |                   |                      | 972 ATEGO        |
|   |                   |                      | 975 ATEGO        |
|   |                   |                      | 976 ATEGO        |
|   |                   |                      | 970 ATEGO 2      |
|   |                   |                      | 972 ATEGO 2      |





| Model / Details  | Description                      | Replaces Ref. No:                                    | TM No.  |
|--|----------------------------------|--|---|
| 979 ACCELO<br>375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>970 ATEGO 2<br>972 ATEGO 2<br>975 ATEGO 2              | Gasket, Rocker Cover             | 9040160521<br>9040160621                             | <b>TM01439</b><br>   |
| 375 ACTROS<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>970 ATEGO 2<br>972 ATEGO 2<br>974 ATEGO 2              | Gasket, Rocker Cover             | 9060160621<br>9060161121                             | <b>TM01441</b><br>   |
| 375 ACTROS<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>375 ATEGO 2<br>958 ATEGO 2<br>970 ATEGO 2              | Gasket, Rocker Cover             | 0000160521   | <b>TM01347</b><br>  |
| 979 ACCELO<br>375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>958 ATEGO 2<br>970 ATEGO 2                | Gasket, Rocker Cover             | 0000160421   | <b>TM01355</b><br> |
| 979 ACCELO<br>375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>970 ATEGO 2<br>972 ATEGO 2<br>975 ATEGO 2              | Gasket, Rocker Cover             | 9040160421   | <b>TM01438</b><br> |
| 979 ACCELO<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 | Adjusting Screw, Rocker<br>Shaft | 5410550320<br>5410550420<br>5410550620               | <b>TM01631</b><br> |
| 979 ACCELO<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3                   | Gasket, Cylinder Head            | 5410100920<br>5410160320<br>5410160420<br>5410160520 | <b>TM01165</b><br> |



| TM No.  | Replaces Ref. No:                      | Description               | Model / Details |
|---|--|---------------------------|-----------------|
| <b>TM00331</b><br>   | 4220160022<br>4420160020<br>4420160220 | Gasket, Cylinder Head     | -               |
| <b>TM01350</b><br>   | 4600110180<br>5410110180               | Gasket, Cylinder Head     | -               |
| <b>TM01172</b><br>   | 4230100320<br>4440100020<br>4440100120 | Gasket Kit, Cylinder Head | -               |
| <b>TM02535</b><br> | 4220160420S                            | Gasket Kit, Cylinder Head | -               |
| <b>TM36540</b><br> | 4572000558                             | Water Pipe, Cylinder Head | -               |
| <b>TM01729</b><br> | 51917010274                            | Sleeve, Cylinder Block    | -               |
| <b>TM36541</b><br> | 4030110107                             | Cylinder Block Cover      | -               |





| Model / Details  | Description                  | Replaces Ref. No:                                    | TM No.  |
|--|------------------------------|--|---|
| 957 ECONIC<br>397 LP 1014 MBSA-RSA<br>397 LP 1114,1214 MBSA-RSA<br>397 LP/LPK 1314 MBSA-RSA<br>397 LPK 1414 MBSA-RSA<br>674 LK/LN2<br>676 LK/LN2<br>677 LK/LN2 | Filter, Cylinder Block Cover | 3520100162<br>3520100062                             | <b>TM01912</b><br>   |
| 671 O 345  | Filter, Cylinder Block Cover | 0000181335<br>4030100162                             | <b>TM01851</b><br>   |
| 650 MK<br>651 MK<br>652 MK<br>653 MK<br>654 MK<br>615 NG<br>616 NG<br>617 NG   | Filter, Cylinder Block Cover | 0000183735<br>4230100062                             | <b>TM01851</b><br>  |
| 344 L 1113<br>344 L 1113/L 1114<br>344 LK 1113/LK 1114<br>345 L 1313<br>345 L 1313,1314<br>345 L 1313,1314,1316<br>345 L 1313,1316<br>345 L 1513,1514,1516     | Filter, Cylinder Block Cover | 0000185735<br>0000184735<br>0000184635<br>0000185535 | <b>TM36542</b><br> |
| 650 MK<br>651 MK<br>652 MK<br>653 MK<br>654 MK<br>615 NG<br>616 NG<br>617 NG   | Filter, Cylinder Block Cover | 000018383<br>4230100162<br>4030100062<br>0000181135  | <b>TM01852</b><br> |
| 363 LP 2226/6X4<br>363 LP 2232/6X4<br>363 LPB 2226/6X4<br>363 LPK 2226/6X4<br>363 LPK 2232/6X4<br>363 LPS 2226/6X4<br>363 LPS 2232/6X4<br>650 MK               | Nozzle, Piston               | 4421800543<br>4421800343<br>4221800043<br>4031801043 | <b>TM01130</b><br> |
| 375 AXOR<br>374 AXOR 2<br>940 AXOR 2<br>942 AXOR 2<br>943 AXOR 2<br>944 AXOR 2<br>958 AXOR 2<br>695 LS 1634EL  | Nozzle, Piston               | 4571801043<br>4571801243<br>4571801443               | <b>TM02064</b><br> |







| TM No.  | Replaces Ref. No:                                    | Description            | Model / Details  |
|---|--|------------------------|--|
| <b>TM01144</b><br>   | 9061800543   | Nozzle, Piston         | 979 ACCELO<br>375 ACTROS<br>375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>375 ATEGO 2                 |
| <b>TM01138</b><br>   | 5411800843<br>5411800743                             | Nozzle, Piston         | 979 ACCELO<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 |
| <b>TM36543</b><br>  | 5411800943   | Nozzle, Piston         | 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3   |
| <b>TM36544</b><br> | 6510300703   | Pulley, Crank Shaft    | 906 SPRINTER<br>636 VIANO  |
| <b>TM36545</b><br> | 0049979347<br>0039976746                             | Seal Ring, Crank Shaft | 360 L 1817,1819/6X4<br>360 L 1819/6X4<br>352 OF SERIES<br>355 OF SERIES  |
| <b>TM00686</b><br> | 0149974647<br>0039971347<br>0069972347<br>0099973447 | Seal Ring, Crank Shaft | 979 ACCELO<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 |
| <b>TM00346</b><br> | 0059972647<br>0069973347<br>0219975347<br>0079972446 | Seal Ring, Crank Shaft | 363 LP 2232/6X4<br>363 LPK 2232/6X4<br>363 LPS 2232/6X4<br>615 NG<br>616 NG<br>617 NG<br>619 NG<br>620 NG                |












| Model / Details  | Description                                  | Replaces Ref. No:                                    | TM No.  |
|--|--|--|---|
| 338 L 1418<br>338 LK 1418<br>338 LP 1418<br>338 LPS 1418<br>338 LS 1418<br>343 T2/L<br>343 T2/LN1<br>345 L 1418 MBTC-USA                         | Seal Ring, Crank Shaft                       | 0049973947<br>0049976046<br>0059978247<br>0119975647 | <b>TM36546</b><br>   |
| 336 LP 1924<br>336 LPS 1924<br>343 T2/L<br>343 T2/LN1<br>345 L 1519<br>345 L 1519,1520<br>345 L 2219,2220  | Seal Ring, Crank Shaft                       | 0079972247<br>0049976946<br>0099974646               | <b>TM31946</b><br>   |
| 979 ACCELO<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3                         | Thrust Ring, Crank Shaft<br>Surface Hardened | 4030320309S<br>4030320109S                           | <b>TM36547</b><br>  |
| 363 LP 2226/6X4<br>363 LPB 2226/6X4<br>363 LPK 2226/6X4<br>363 LPS 2226/6X4<br>655 SK  | Thrust Ring, Crank Shaft<br>Surface Hardened | 4030310127S<br>4030310627S<br>4030310727S            | <b>TM36548</b><br> |
| 979 ACCELO<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3                         | Thrust Ring, Crank Shaft<br>Surface Hardened | 4420310027   | <b>TM01796</b><br> |
| 375 AXOR<br>374 AXOR 2<br>940 AXOR 2<br>942 AXOR 2<br>943 AXOR 2<br>944 AXOR 2<br>386 L 1625,1725<br>386 L 1633                                  | Gasket, Timing Case                          | 4470150080<br>4070150080<br>4290150080               | <b>TM01328</b><br> |
| 363 LP 2226/6X4<br>363 LP 2232/6X4<br>363 LPB 2226/6X4<br>363 LPK 2226/6X4<br>363 LPK 2232/6X4<br>363 LPS 2226/6X4<br>363 LPS 2232/6X4<br>650 MK | Gasket, Timing Case                          | 4420150060   | <b>TM00967</b><br> |












| TM No.  | Replaces Ref. No: | Description         | Model / Details  |
|---|-------------------|---------------------|--|
| <b>TM01349</b><br>   | 5410151380        | Gasket, Timing Case | 979 ACCELO<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3     |
|   | 5410150260        |                     |  |
| <b>TM01373</b><br>   | 5410150980        | Gasket, Timing Case | 979 ACCELO<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3     |
|   |                   |                     |  |
| <b>TM01359</b><br>   | 4570110280        | Gasket, Timing Case | 934 ACTROS 2/3<br>374 AXOR 2<br>940 AXOR 2<br>942 AXOR 2<br>943 AXOR 2<br>944 AXOR 2<br>958 AXOR 2<br>375 AXOR               |
|   | 4570110880        |                     |  |
| <b>TM02017</b><br> | 5410180712        | Hose, Timing Case   | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3 |
|   |                   |                     |  |
| <b>TM02019</b><br> | 5410181112        | Hose, Timing Case   | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3 |
|   |                   |                     |  |
| <b>TM36549</b><br> | 5410180812        | Hose, Timing Case   | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3 |
|   |                   |                     |  |
| <b>TM01857</b><br> | 3520303905        | Flywheel            | 318 LP<br>344 L 1113<br>344 L 1113/L 1114<br>344 L 1116<br>344 L 1118<br>344 LA 1113<br>344 LAK 1113<br>344 LK 1113          |
|   | 3440307205        |                     |  |





















| Model / Details  | Description | Replaces Ref. No:                      | TM No.  |
|--|-------------|--|---|
| 398 LO 814<br>673 LK/LN2<br>674 LK/LN2<br>688 1114<br>688 912<br>688 913<br>688 914<br>688 L 710   | Flywheel    | 3640300105                             | <b>TM36550</b><br>   |
| 397 LP 1014 MBSA-RSA<br>397 LP 1114,1214 MBSA-RSA<br>397 LP/LPK 1314 MBSA-RSA<br>397 LPK 1414 MBSA-RSA<br>676 LK/LN2<br>677 LK/LN2<br>679 LK/LN2<br>695 L 1623 | Flywheel    | 3660300905                             | <b>TM01956</b><br>   |
| 363 LP 2226/6X4<br>363 LPB 2226/6X4<br>363 LPK 2226/6X4<br>363 LPS 2226/6X4<br>615 NG<br>616 NG<br>617 NG<br>619 NG  | Flywheel    | 4030301305<br>4030301605<br>4030301205 | <b>TM01876</b><br>   |
| 621 NG<br>623 NG<br>624 NG<br>645 NG<br>646 NG<br>647 NG<br>648 NG<br>649 NG   | Flywheel    | 4220300505                             | <b>TM01959</b><br> |
| 617 NG<br>619 NG<br>620 NG<br>625 SK   | Flywheel    | 4410300405                             | <b>TM36551</b><br> |
| 650 MK<br>651 MK<br>652 MK<br>653 MK<br>615 NG<br>617 NG<br>621 NG<br>624 NG   | Flywheel    | 4420301905<br>4420300505<br>4420300205 | <b>TM01222</b><br> |
| 979 ACCELO<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3                                       | Flywheel    | 5410300105                             | <b>TM01958</b><br> |





| TM No.  | Replaces Ref. No:                                    | Description | Model / Details   |
|---|--|-------------|---|
| <b>TM02023</b><br>   | 9060301905   | Flywheel    | 375 ACTROS<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>970 ATEGO 2<br>972 ATEGO 2<br>974 ATEGO 2   |
| <b>TM02024</b><br>   | 9060303205<br>9060303805                             | Flywheel    | 979 ACCELO<br>375 ACTROS<br>375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>958 ATEGO 2  |
| <b>TM01955</b><br>  | 4570300605   | Flywheel    | 375 AXOR<br>374 AXOR 2<br>940 AXOR 2<br>942 AXOR 2<br>943 AXOR 2<br>944 AXOR 2<br>958 AXOR 2<br>386 LS 1625   |
| <b>TM02141</b><br> | 4570302105<br>4570301305<br>4570302305<br>4570302605 | Flywheel    | 634 TOURO<br>613 TOURISMO<br>634 CBC-FAHRGESTELL<br>2-ACHSER<br>634 IBC 1836 / OC 500 RF<br>634 IBC 1842<br>634 IBC 2242<br>634 IBC FAHRGESTELL<br>2-ACHSER |
| <b>TM02025</b><br> | 9060302005<br>9060301605                             | Flywheel    | 979 ACCELO<br>375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>970 ATEGO 2<br>972 ATEGO 2<br>975 ATEGO 2   |
| <b>TM02043</b><br> | 9060304605<br>9060303905<br>9060303305               | Flywheel    | 375 ACTROS<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>958 ATEGO 2<br>970 ATEGO 2<br>972 ATEGO 2   |
| <b>TM02022</b><br> | 9060303005<br>9060303705                             | Flywheel    | 979 ACCELO<br>375 ACTROS<br>375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>375 ATEGO 2  |










| Model / Details  | Description       | Replaces Ref. No:                                    | TM No.  |
|--|-------------------|--|---|
| 386 L 1621,1721<br>386 L 1621,L 1721<br>386 L 1622<br>386 L 2318,2418<br>386 LK 1621,1721<br>386 LK 2318,2418<br>386 LS 1622<br>397 LP 1014 MBSA-RSA | Flywheel          | 3760301305<br>3520306605                             | <b>TM01858</b><br>   |
| 979 ACCELO<br>375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>970 ATEGO 2<br>972 ATEGO 2<br>975 ATEGO 2  | Flywheel          | 9060302105<br>9060301705                             | <b>TM01221</b><br>   |
| 363 LP 2232/6X4<br>363 LPK 2232/6X4<br>363 LPS 2232/6X4<br>650 MK<br>652 MK<br>653 MK<br>654 MK<br>615 NG  | Flywheel          | 4470301805<br>4030301405<br>4030300805<br>4470300705 | <b>TM01877</b><br>   |
| 958 AXOR 2<br>695 LS 1634EL<br>695 LS 1634EL 1635 S<br>696 L 1938<br>696 L 2638<br>696 LK 2638<br>696 LS 1938<br>696 LS 2638                         | Flywheel          | 4570300105<br>4570300705                             | <b>TM01955</b><br> |
| 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS   | Flywheel          | 4710302305<br>4710303305                             | <b>TM02154</b><br> |
| 979 ACCELO<br>375 ACTROS<br>375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>958 ATEGO 2   | Starter Ring Gear | 3520321305   | <b>TM01917</b><br> |
| 979 ACCELO<br>314 LP<br>316 LP<br>318 LP<br>341 L 1112<br>341 L 1114<br>341 L 911<br>341 L 914   | Starter Ring Gear | 3520321105<br>3440327005                             | <b>TM01153</b><br> |





















| TM No.  | Replaces Ref. No:                                    | Description       | Model / Details  |
|---|--|-------------------|--|
| <b>TM02070</b><br>   | 9060320005   | Starter Ring Gear | 979 ACCELO<br>375 ACTROS<br>963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS<br>375 ATEGO<br>970 ATEGO         |
| <b>TM00801</b><br>   | 3660320105   | Starter Ring Gear | 979 ACCELO<br>375 ACTROS<br>963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS<br>375 ATEGO<br>970 ATEGO         |
| <b>TM01159</b><br>  | 4030320305<br>4030320405<br>4030320505<br>4030320005 | Starter Ring Gear | 979 ACCELO<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 |
| <b>TM01947</b><br> | 4030320705   | Starter Ring Gear | 979 ACCELO<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 |
| <b>TM11763</b><br> | 0001539520<br>0011532020<br>0011531820<br>0011531620 | Sensor, Flywheel  | 979 ACCELO<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 |
| <b>TM01879</b><br> | 0049812125<br>0029818925                             | Bearing, Flywheel | 979 ACCELO<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 |
| <b>TM01475</b><br> | 4230100033<br>4230100133                             | Housing, Flywheel | 625 SK<br>655 SK<br>656 SK<br>659 SK   |



| Model / Details  | Description       | Replaces Ref. No:                                    | TM No.  |
|--|-------------------|--|---|
| 979 ACCELO<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3   | Housing, Flywheel | 5410102533I<br>5410103033                            | <b>TM02077</b><br>   |
| 363 LP 2226/6X4<br>363 LP 2232/6X4<br>363 LPB 2226/6X4<br>363 LPK 2226/6X4<br>363 LPK 2232/6X4<br>363 LPS 2226/6X4<br>363 LPS 2232/6X4<br>650 MK                             | Housing, Flywheel | 4030104633<br>4230100833<br>4230101033<br>4230105033 | <b>TM01895</b><br>   |
| 375 AXOR<br>374 AXOR 2<br>940 AXOR 2<br>942 AXOR 2<br>943 AXOR 2<br>944 AXOR 2<br>634 IBC-FAHRGESTELL-BUGGY<br>2-ACHSER NAFTA<br>634 IBC-FAHRGESTELL-BUGGY<br>3-ACHSER NAFTA | Housing, Flywheel | 4570151302<br>4570151902<br>4570152602               | <b>TM36552</b><br>   |
| 375 ACTROS<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>958 ATEGO 2<br>970 ATEGO 2<br>972 ATEGO 2  | Housing, Flywheel | 9060100733<br>9060100833<br>9060101333<br>9060101433 | <b>TM36553</b><br> |
| 314 LP<br>316 LP<br>318 LP<br>328 T2/L<br>352 L 1313<br>352 L 1813/6X2<br>352 L 1813/6X4<br>352 LA 1313  | Oil Pump          | 3641800101<br>3521806301<br>3521807001<br>3521806401 | <b>TM00073</b><br> |
| 318 LP<br>344 L 1113<br>344 L 1116<br>344 LA 1113<br>344 LAK 1113<br>344 LAS 1113<br>344 LK 1113<br>344 LS 1113  | Oil Pump          | 3661800401<br>3661800101                             | <b>TM01865</b><br> |
| 363 LP 2232/6X4<br>363 LPK 2232/6X4<br>363 LPS 2232/6X4<br>652 MK<br>620 NG<br>621 NG<br>622 NG<br>623 NG  | Oil Pump          | 4231802501<br>4231802301<br>4231800501<br>4231800101 | <b>TM01515</b><br> |





| TM No.  | Replaces Ref. No: | Description | Model / Details   |
|---|-------------------|-------------|---|
| <b>TM01889</b><br>   | 4031801701        | Oil Pump    | 363 LP 2226/6X4<br>363 LP 2232/6X4<br>363 LPB 2226/6X4<br>363 LPK 2226/6X4<br>363 LPK 2232/6X4<br>363 LPS 2226/6X4<br>363 LPS 2232/6X4<br>386 L 1625,1725 |
|   | 4031800601        |             |   |
| <b>TM01973</b><br>   | 5421800201        | Oil Pump    | 979 ACCELO<br>950 ACTROS<br>952 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>934 ACTROS 2/3  |
|   | 5421800101        |             |   |
| 5421800001  |                   |             |   |
|   |                   |             |   |
| <b>TM01916</b><br>   | 4031802701        | Oil Pump    | 397 OF SERIES<br>397 1924 S MBSA-RSA<br>307 O 305<br>307 O 307<br>671 O 345   |
|   |                   |             |   |
| <b>TM01986</b><br> | 9061800201        | Oil Pump    | 979 ACCELO<br>375 ACTROS<br>375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>958 ATEGO 2  |
|   | 9061800601        |             |   |
|   | 9061800801        |             |   |
|   | 9061801101        |             |   |
| <b>TM36554</b><br> | 6461800601        | Oil Pump    | -   |
|   |                   |             |   |
| <b>TM36555</b><br> | 6111800301        | Oil Pump    | -   |
|   |                   |             |   |
| <b>TM02235</b><br> | 6461801601        | Oil Pump    | 906 SPRINTER<br>909 SPRINTER<br>906 SPRINTER<br>909 SPRINTER  |
|   |                   |             |   |





| Model / Details  | Description      | Replaces Ref. No:                                    | TM No.  |
|--|------------------|--|---|
| 906 SPRINTER<br>639 VIANO<br>906 SPRINTER<br>636 VIANO<br>639 VIANO<br>639 VITO  | Oil Pump         | 6461801401<br>6461800301                             | <b>TM36556</b><br>   |
| 338 L 1418<br>338 LK 1418<br>338 LS 1418<br>351 L 1526<br>351 LS 1526<br>363 LP 2226/6X4<br>363 LP 2232/6X4<br>363 LPB 2226/6X4                                | Sensor, Oil Pump | 0025421717   | <b>TM36557</b><br>   |
| 336 LP 1924<br>336 LPS 1924<br>338 LK 1418<br>338 LP 1418<br>338 LPS 1418<br>343 T2/L<br>343 T2/LN1<br>346 L 1924  | Sensor, Oil Pump | 0045424317<br>6845427117<br>0015428217               | <b>TM01836</b><br>  |
| 308 L/LO 608 D<br>309 T2/L<br>309 TL2/L<br>310 LF 508 D/LF 608 D<br>310 LT 608 D<br>310 T2/L<br>312 L 312<br>313 T2/L  | Sensor, Oil Pump | 0045428917<br>0015424917<br>3455427317<br>6845427317 | <b>TM01822</b><br> |
| 375 AXOR<br>374 AXOR 2<br>940 AXOR 2<br>942 AXOR 2<br>943 AXOR 2<br>944 AXOR 2<br>386 LS 1625<br>634 TOURO   | Nozzle, Oil Pump | 4571801943<br>4601800443                             | <b>TM36558</b><br> |
| 979 ACCELO<br>375 ACTROS<br>375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>970 ATEGO 2   | Nozzle, Oil Pump | 9061800243   | <b>TM36559</b><br> |
| 79 ACCELO<br>318 LP<br>344 L 1118<br>344 LK 1118<br>345 L 1316,L 1317,L 1318<br>345 L 1516,L 1517,L 1518<br>345 L 1518 ,LS 1518<br>345 LK 1316,LK 1317,LK 1318 | Nozzle, Oil Pump | 3521800143<br>3661800143                             | <b>TM01134</b><br> |











| TM No.  | Replaces Ref. No:                                    | Description  | Model / Details   |
|---|--|--|---|
| <b>TM01146</b><br>   | 6111800043<br>6041800143                             | Nozzle, Oil Pump   | 979 ACCELO<br>906 SPRINTER<br>909 SPRINTER<br>639 VIANO<br>690 SPRINTER<br>901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER |
| <b>TM36560</b><br>   | 6511800343   | Nozzle, Oil Pump   | 639 VIANO<br>900 SPRINTER<br>906 SPRINTER<br>636 VIANO<br>639 VIANO<br>639 VITO   |
| <b>TM03400</b><br>   | 5411800083   | Oil Filter<br>Repl. Mann: ZR 902 x<br>Repl. Hengst: Z10D64       | 952 ACTROS<br>934 ACTROS 2/3  |
| <b>TM01904</b><br> | 4411800309<br>4411800209<br>4411800109<br>4411800009 | Oil Filter<br>Repl. Mann: HU9471Z2<br>Repl. Hengst: E197HD23     | 650 MK<br>651 MK<br>652 MK<br>653 MK<br>654 MK<br>621 NG<br>624 NG<br>625 SK  |
| <b>TM01983</b><br> | 0001801609<br>9041800210<br>9041800310<br>9041800009 | Oil Filter<br>Repl. Mann: HU9315X<br>Repl. Hengst:<br>E160H01D28 | 979 ACCELO<br>375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>958 ATEGO 2<br>970 ATEGO 2               |
| <b>TM00455</b><br> | 0001802909<br>0001802109<br>4571840125               | Oil Filter<br>Repl. Mann: HU12110X<br>Repl. Hengst: E175HD129    | 375 AXOR<br>374 AXOR 2<br>940 AXOR 2<br>942 AXOR 2<br>943 AXOR 2<br>944 AXOR 2<br>958 AXOR 2<br>634 O 500               |
| <b>TM02106</b><br> | 6021800009<br>6061800009<br>6061800109<br>6061840025 | Oil Filter<br>Repl. Mann: HU951X<br>Repl. Hengst: E172HD35       | 901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER<br>667 VARIO<br>668 VARIO<br>670 VARIO<br>638 VITO         |



| Model / Details  | Description   | Replaces Ref. No:                                    | TM No.  |
|--|---|--|---|
| 690 SPRINTER<br>901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER<br>905 SPRINTER<br>906 SPRINTER<br>636 VIANO  | Oil Filter<br>Repl. Mann: HU7181K<br>Repl. Hengst: E11HD57          | 6111800009<br>1121840025                             | <b>TM02050</b><br>   |
| 979 ACCELO<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3   | Oil Filter<br>Repl. Mann: HU 12 140 x<br>Repl. Hengst: E500HD37     | 5411800009<br>5411800209<br>5411840325<br>5411840225 | <b>TM01905</b><br>   |
| 375 ACTROS<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>970 ATEGO 2<br>972 ATEGO 2<br>974 ATEGO 2                | Oil Filter<br>Repl. Mann: HU 945/2 x<br>Repl. Hengst:<br>E161H01D28 | 9061800009<br>0001801709<br>9061800209               | <b>TM01928</b><br>   |
| 318 LP<br>352 L 1313<br>352 L 1813/6X4<br>352 LA 1313<br>352 LAK 1313<br>352 LAKO 1313<br>352 LAS 1313<br>352 LF 1313      | Oil Filter<br>Repl. Mann: H 1275 x<br>Repl. Hengst: E174HD11        | 4011800009<br>0011840225<br>0011840425<br>0011840525 | <b>TM02565</b><br> |
| -  | Oil Filter<br>Repl. Mann: HU 13 120                                 | -  | <b>TM36561</b><br> |
| 950 ACTROS<br>930 ACTROS 2/3<br>934 ACTROS 2/3<br>963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS<br>940 AXOR 2 | Oil Filter<br>Repl. Mann: H 623<br>Repl. Hengst: E70H               | 0004662904   | <b>TM02031</b><br> |
| 375 ACTROS<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>375 ATEGO 2<br>958 ATEGO 2<br>970 ATEGO 2                | Cover, Oil Filter<br>Plastic  | 0001802438   | <b>TM02053</b><br> |












| TM No.  | Replaces Ref. No:                                    | Description  | Model / Details  |
|---|--|--|--|
| <b>TM02054</b><br>   | 0001802338   | Cover, Oil Filter<br>Plastic   | 979 ACCELO<br>375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>958 ATEGO 2<br>970 ATEGO 2                    |
| <b>TM01984</b><br>   | 5411840208   | Cover, Oil Filter<br>Plastic   | 979 ACCELO<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3     |
| <b>TM24086</b><br>   | 0001800915   | Repair Kit, Oil Filter   | 979 ACCELO<br>375 ACTROS<br>375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>375 ATEGO 2<br>375 ATEGO 2                   |
| <b>TM36562</b><br> | 4421800111   | Housing, Oil Filter  | 650 MK<br>659 SK<br>613 TOURISMO   |
| <b>TM02030</b><br> | 5411800109   | Oil Filter Kit, Oil Filter<br>Repl. Mann: SP 2041-2 x<br>Repl. Hengst: E502H02<br>D121 | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3 |
| <b>TM01924</b><br> | 0000101285<br>0000100285<br>1110180302<br>1020180802 | Cap, Oil Filler  | 979 ACCELO<br>375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3         |
| <b>TM02435</b><br> | 9405281282<br>9405281307<br>9405280682               | Hose, Oil Filler   | 375 ACTROS<br>375 AXOR<br>374 AXOR 2<br>375 AXOR 2<br>950 AXOR 2<br>952 AXOR 2<br>953 AXOR 2<br>954 AXOR 2                   |











| Model / Details   | Description      | Replaces Ref. No:        | TM No.  |
|---|------------------|--------------------------|---|
| 375ACTROS<br>375 AXOR<br>374 AXOR 2<br>375 AXOR 2<br>950 AXOR 2<br>952 AXOR 2<br>953 AXOR 2<br>954 AXOR 2 | Hose, Oil Filler | 9405280882               | <b>TM02415</b><br>   |
| 650 MK<br>651 MK<br>652 MK<br>653 MK<br>654 MK<br>617 NG<br>619 NG<br>620 NG                              | Hose, Oil Filler | 4410180012               | <b>TM01655</b><br>   |
| 653 MK<br>621 NG<br>623 NG<br>624 NG<br>645 NG<br>646 NG<br>647 NG<br>648 NG                              | Hose, Oil Filler | 4420180212<br>4420180712 | <b>TM02390</b><br>  |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS  | Hose, Oil Filler | 9425280582<br>9425281282 | <b>TM02406</b><br> |
| 950 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>934 ACTROS 2/3  | Hose, Oil Filler | 9425280682               | <b>TM02436</b><br> |
| 650 MK<br>651 MK<br>652 MK<br>653 MK<br>654 MK<br>615 NG<br>616 NG<br>617 NG                              | Hose, Oil Filler | 6205280182<br>6205280282 | <b>TM08237</b><br> |
| 375 AXOR<br>374 AXOR 2<br>940 AXOR 2<br>942 AXOR 2<br>943 AXOR 2<br>944 AXOR 2<br>958 AXOR 2              | Hose, Oil Filler | 9405280709               | <b>TM01578</b><br> |





| TM No.  | Replaces Ref. No:        | Description      | Model / Details  |
|---|--------------------------|------------------|--|
| <b>TM36563</b><br>   | 9425280809               | Pipe, Oil Filler | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3 |
| <b>TM36564</b><br>   | 9425200106<br>9425281009 | Pipe, Oil Filler | 950 ACTROS<br>952 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>934 ACTROS 2/3                                 |
| <b>TM36565</b><br>   | 9425280909               | Pipe, Oil Filler | 950 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>934 ACTROS 2/3   |
| <b>TM36566</b><br> | 9425200606               | Pipe, Oil Filler | 950 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>934 ACTROS 2/3   |
| <b>TM02038</b><br> | 9060101313<br>9060100513 | Oil Sump         | 375 ACTROS<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>375 ATEGO 2<br>958 ATEGO 2<br>970 ATEGO 2                  |
| <b>TM36567</b><br> | 5420100813               | Oil Sump         | 950 ACTROS<br>952 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>934 ACTROS 2/3                                 |
| <b>TM36568</b><br> | 5410101213               | Oil Sump         | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3 |



| Model / Details  | Description           | Replaces Ref. No:                                    | TM No.  |
|--|-----------------------|--|---|
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3 | Oil Sump              | 5410100713<br>5410100313                             | <b>TM02039</b><br>   |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3 | Oil Sump              | 5410100213   | <b>TM36569</b><br>   |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3 | Oil Sump              | 5410102013   | <b>TM36570</b><br>   |
| 979 ACCELO<br>375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>958 ATEGO 2<br>970 ATEGO 2                    | Oil Sump              | 9040103813   | <b>TM36571</b><br> |
| 375 AXOR<br>374 AXOR 2<br>940 AXOR 2<br>942 AXOR 2<br>943 AXOR 2<br>944 AXOR 2<br>958 AXOR 2                                 | Oil Sump<br>Aluminium | 4570140602<br>4570140802<br>4570140902<br>4570141602 | <b>TM36572</b><br> |
| 964 AROCS<br>963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS   | Oil Sump              | 4710106913   | <b>TM36573</b><br> |
| 650 MK<br>651 MK<br>652 MK<br>653 MK<br>654 MK<br>615 NG<br>616 NG<br>617 NG   | Gasket, Oil Sump      | 4010140122<br>4410140022<br>4410140422               | <b>TM01289</b><br> |





| TM No.  | Replaces Ref. No: | Description      | Model / Details  |
|---|-------------------|------------------|--|
| <b>TM01329</b><br>   | 5410140122        | Gasket, Oil Sump | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3 |
|   | 5410140422        |                  |  |
|   | 5410140522        |                  |  |
|   | 5410140622        |                  |  |
|   |                   |                  |  |
| <b>TM01314</b><br>   | 5410140022        | Gasket, Oil Sump | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3 |
|   | 5410140322        |                  |  |
| <b>TM01372</b><br>   | 5410140822        | Gasket, Oil Sump | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3 |
|   |                   |                  |  |
| <b>TM01370</b><br> | 9040140722        | Gasket, Oil Sump | 979 ACCELO<br>375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>958 ATEGO 2<br>970 ATEGO 2                    |
|   |                   |                  |  |
| <b>TM01356</b><br> | 0000140122        | Gasket, Oil Sump | 375 ACTROS<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>375 ATEGO 2<br>958 ATEGO 2<br>970 ATEGO 2                  |
|   | 9060140522        |                  |  |
| <b>TM01435</b><br> | 4570140222        | Gasket, Oil Sump | 375 AXOR<br>374 AXOR 2<br>940 AXOR 2<br>942 AXOR 2<br>943 AXOR 2<br>944 AXOR 2<br>958 AXOR 2<br>386 LS 1625                  |
|   |                   |                  |  |
| <b>TM01330</b><br> | 5420140022        | Gasket, Oil Sump | 979 ACCELO<br>950 ACTROS<br>952 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>934 ACTROS 2/3                   |
|   | 5420140322        |                  |  |



















| Model / Details   | Description            | Replaces Ref. No:                            | TM No.  |
|---|------------------------|--|---|
| 979 ACCELO<br>950 ACTROS<br>952 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>934 ACTROS 2/3                  | Gasket, Oil Sump       | 5420140122<br>5420140422<br>5420140622       | <b>TM01331</b><br>   |
| 375 ACTROS<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>375 ATEGO 2<br>958 ATEGO 2<br>970 ATEGO 2                 | Gasket, Oil Sump       | 9060140422<br>9060140922                     | <b>TM01339</b><br>   |
| 363 LP 2232/6X4<br>363 LPK 2232/6X4<br>363 LPS 2232/6X4<br>620 NG<br>621 NG<br>623 NG<br>624 NG<br>625 NG                   | Gasket, Oil Sump       | 4030140222<br>4030140322<br>4430140022       | <b>TM01283</b><br>  |
| 979 ACCELO<br>375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3        | Plug, Oil Sump         | 000908020001                                 | <b>TM04955</b><br> |
| 958 ATEGO 2<br>976 ATEGO 2<br>944 AXOR 2<br>958 AXOR 2<br>338 L 1418<br>338 LK 1418<br>338 LP 1418<br>338 LPS 1418          | Plug, Oil Sump         | 4039970230<br>4039970032                     | <b>TM01565</b><br> |
| 964 AROCS<br>958 AXOR 2<br>963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>967 ATEGO 3<br>930 ACTROS 2/3<br>934 ACTROS 2/3 | Plug, Oil Sump         | 000908022000<br>000908022001<br>000908022011 | <b>TM04954</b><br> |
| 650 MK<br>651 MK<br>652 MK<br>653 MK<br>654 MK<br>617 NG<br>619 NG  | Oil Dipstick, Oil Sump | 4420103272                                   | <b>TM01933</b><br> |












| TM No.  | Replaces Ref. No: | Description            | Model / Details  |
|---|-------------------|------------------------|------------------|
| <b>TM01331</b><br>   | 5420140122        | Gasket, Oil Sump       | 979 ACCELO       |
|   | 5420140422        |                        | 950 ACTROS       |
|   | 5420140622        |                        | 952 ACTROS       |
|   |                   |                        | 954 ACTROS       |
|   | 930 ACTROS 2/3    |                        | 932 ACTROS 2/3   |
|   | 934 ACTROS 2/3    |                        |                  |
| <b>TM01339</b><br>   | 9060140422        | Gasket, Oil Sump       | 375 ACTROS       |
|   | 9060140922        |                        | 970 ATEGO        |
|   |                   |                        | 972 ATEGO        |
|   |                   |                        | 975 ATEGO        |
|   | 976 ATEGO         |                        | 375 ATEGO 2      |
|   | 958 ATEGO 2       |                        | 970 ATEGO 2      |
| <b>TM01283</b><br>   | 4030140222        | Gasket, Oil Sump       | 363 LP 2232/6X4  |
|   | 4030140322        |                        | 363 LPK 2232/6X4 |
|   | 4430140022        |                        | 363 LPS 2232/6X4 |
|   |                   |                        | 620 NG           |
|   | 621 NG            |                        | 623 NG           |
|   | 624 NG            |                        | 625 NG           |
| <b>TM04955</b><br> | 000908020001      | Plug, Oil Sump         | 979 ACCELO       |
|   |                   |                        | 375 ACTROS       |
|   |                   |                        | 950 ACTROS       |
|   |                   |                        | 952 ACTROS       |
|   | 953 ACTROS        |                        | 954 ACTROS       |
|   | 930 ACTROS 2/3    |                        | 932 ACTROS 2/3   |
| <b>TM01565</b><br> | 4039970230        | Plug, Oil Sump         | 958 ATEGO 2      |
|   | 4039970032        |                        | 976 ATEGO 2      |
|   |                   |                        | 944 AXOR 2       |
|   |                   |                        | 958 AXOR 2       |
|   | 338 L 1418        |                        | 338 LK 1418      |
|   | 338 LP 1418       |                        | 338 LPS 1418     |
| <b>TM04954</b><br> | 000908022000      | Plug, Oil Sump         | 964 AROCS        |
|   | 000908022001      |                        | 958 AXOR 2       |
|   | 000908022011      |                        | 963 ACTROS MP4   |
|   |                   |                        | 964 ACTROS MP4   |
|   | 964 ANTOS         |                        | 967 ATEGO 3      |
|   | 930 ACTROS 2/3    |                        | 934 ACTROS 2/3   |
| <b>TM01933</b><br> | 4420103272        | Oil Dipstick, Oil Sump | 650 MK           |
|   |                   |                        | 651 MK           |
|   |                   |                        | 652 MK           |
|   |                   |                        | 653 MK           |
|   | 654 MK            |                        | 617 NG           |
|   | 619 NG            |                        |                  |










| Model / Details  | Description            | Replaces Ref. No:                      | TM No.  |
|--|------------------------|--|---|
| 619 NG<br>620 NG<br>621 NG<br>622 NG<br>623 NG<br>624 NG   | Oil Dipstick, Oil Sump | 4220100072                             | <b>TM01868</b><br>   |
| 671 O 345  | Oil Dipstick, Oil Sump | 4270100072                             | <b>TM36574</b><br>   |
| 979 ACCELO<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3 | Oil Dipstick, Oil Sump | 5410100572<br>5410101072               | <b>TM01998</b><br>  |
| 375 AXOR<br>374 AXOR 2<br>940 AXOR 2<br>942 AXOR 2<br>943 AXOR 2<br>944 AXOR 2<br>958 AXOR 2           | Oil Dipstick, Oil Sump | 4570101472                             | <b>TM36507</b><br> |
| 375 ACTROS<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>958 ATEGO 2<br>970 ATEGO 2           | Oil Dipstick, Oil Sump | 9060101072                             | <b>TM36508</b><br> |
| 979 ACCELO<br>375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>970 ATEGO 2             | Oil Dipstick, Oil Sump | 9040101372<br>9040100172<br>9040108272 | <b>TM36575</b><br> |
| 979 ACCELO<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3 | Sensor, Oil Sump       | 0061531928                             | <b>TM36576</b><br> |



| TM No.  | Replaces Ref. No:                                    | Description           | Model / Details  |
|---|--|-----------------------|--|
| <b>TM36577</b>  | 0009845136   | Locking Pin, Oil Sump | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3                                 |
|    |  |                       |  |
| <b>TM36578</b>  | 0009846436   | Locking Pin, Oil Sump | 634 TOURO<br>628 CITARO<br>628 CONECTO<br>671 CONECTO<br>628 SETRA<br>634 CBC - FAHRGESTELL<br>2-ACHSER<br>634 IBC FAHRGESTELL<br>2-ACHSER |
|    |  |                       |  |
| <b>TM01706</b>  | 0021881701<br>0021881801<br>0021884301<br>0021887901 | Oil Cooler            | 375 AXOR<br>374 AXOR 2<br>940 AXOR 2<br>942 AXOR 2<br>943 AXOR 2<br>944 AXOR 2<br>958 AXOR 2   |
|    |  |                       |  |
| <b>TM01705</b>  | 5411880201   | Oil Cooler            | 979 ACCELO<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3                                     |
|  |  |                       |  |
| <b>TM01844</b>  | 0001886401<br>0001887601<br>0001888101<br>0001888401 | Oil Cooler            | 363 LP 2226/6X4<br>363 LP 2232/6X4<br>363 LPB 2226/6X4<br>363 LPK 2226/6X4<br>363 LPK 2232/6X4<br>363 LPS 2226/6X4<br>363 LPS 2232/6X4     |
|  |  |                       |  |
| <b>TM36579</b>  | 5411882704<br>5411882204<br>5411881204               | Oil Cooler            | 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>979 ACCELO               |
|  |  |                       |  |
| <b>TM36580</b>  | 5411882804<br>5411882504<br>5411880704               | Oil Cooler            | 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>979 ACCELO               |
|  |  |                       |  |










| Model / Details  | Description        | Replaces Ref. No:                      | TM No.  |
|--|--------------------|--|---|
| 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>979 ACCELO     | Oil Cooler         | 5411883004<br>5411882404               | <b>TM36512</b><br>   |
| 979 ACCELO<br>375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>958 ATEGO 2                                       | Gasket, Oil Cooler | 9041880280                             | <b>TM01362</b><br>   |
| 375 ACTROS<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>375 ATEGO 2<br>958 ATEGO 2                                     | Gasket, Oil Cooler | 9061880280                             | <b>TM01464</b><br>   |
| 979 ACCELO<br>375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>958 ATEGO 2                                       | Gasket, Oil Cooler | 0001883280                             | <b>TM01361</b><br> |
| 375 ACTROS<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>375 ATEGO 2<br>958 ATEGO 2                                     | Gasket, Oil Cooler | 0001883380                             | <b>TM01351</b><br> |
| 944 AXOR 2<br>363 LP 2226/6X4<br>363 LP 2232/6X4<br>363 LPB 2226/6X4<br>363 LPK 2226/6X4<br>363 LPK 2232/6X4<br>363 LPS 2226/6X4 | Gasket, Oil Cooler | 4421880580<br>4031840280<br>4421880280 | <b>TM01281</b><br> |
| 934 ACTROS 2/3<br>375 AXOR<br>374 AXOR 2<br>940 AXOR 2<br>942 AXOR 2<br>943 AXOR 2<br>944 AXOR 2                                 | -                  | 4571880280                             | <b>TM01358</b><br> |







| TM No.  | Replaces Ref. No: | Description                         | Model / Details  |
|---|-------------------|-------------------------------------|------------------|
| <b>TM01280</b><br>   | 4421840580        | Gasket, Oil Cooler                  | 363 LP 2226/6X4  |
|   | 4031840180        |                                     | 363 LP 2232/6X4  |
|   | 4031840380        |                                     | 363 LPB 2226/6X4 |
|   | 4421840180        |                                     | 363 LPK 2226/6X4 |
|   |                   |                                     | 363 LPK 2232/6X4 |
|   | 363 LPS 2226/6X4  |                                     | 363 LPS 2232/6X4 |
| <b>TM01360</b><br>   | 9061840280        | Gasket, Oil Cooler                  | 979 ACCELO       |
|   |                   |                                     | 375 ACTROS       |
|   |                   |                                     | 375 ATEGO        |
|   |                   |                                     | 970 ATEGO        |
|   |                   |                                     | 972 ATEGO        |
|   |                   |                                     | 975 ATEGO        |
|   | 976 ATEGO         |                                     |                  |
| <b>TM01326</b><br>   | 5411840580        | Gasket, Oil Cooler<br>Material: NBR | 979 ACCELO       |
|   | 5411840780        |                                     | 950 ACTROS       |
|   | 5411840980        |                                     | 952 ACTROS       |
|   |                   |                                     | 953 ACTROS       |
|   |                   |                                     | 954 ACTROS       |
|   |                   |                                     | 930 ACTROS 2/3   |
|   | 932 ACTROS 2/3    |                                     |                  |
| <b>TM36581</b><br> | 5411840480        | Gasket, Oil Cooler                  | 979 ACCELO       |
|   |                   |                                     | 950 ACTROS       |
|   |                   |                                     | 952 ACTROS       |
|   |                   |                                     | 953 ACTROS       |
|   |                   |                                     | 954 ACTROS       |
|   |                   |                                     | 930 ACTROS 2/3   |
|   | 932 ACTROS 2/3    |                                     |                  |
| <b>TM07843</b><br> | 0005012915        | Filler Cap, Radiator                | 309 T2/L         |
|   | 0005010215        |                                     | 314 LP           |
|   |                   |                                     | 316 LP           |
|   |                   |                                     | 328 T2/L         |
|   |                   |                                     | 352 L 1313       |
|   |                   |                                     | 352 L 1813/6X2   |
|   | 352 L 1813/6X4    |                                     |                  |
| <b>TM07795</b><br> | 0005016215        | Filler Cap, Radiator                | 629 SETRA        |
|   |                   |                                     | 690 SPRINTER     |
|   |                   |                                     | 901 SPRINTER     |
|   |                   |                                     | 902 SPRINTER     |
|   |                   |                                     | 903 SPRINTER     |
|   |                   |                                     | 904 SPRINTER     |
|   | 905 SPRINTER      |                                     |                  |
| <b>TM08359</b><br> | 9405011582        | Hose, Radiator                      | 375 AXOR         |
|   |                   |                                     | 374 AXOR 2       |
|   |                   |                                     | 940 AXOR 2       |
|   |                   |                                     | 942 AXOR 2       |
|   |                   |                                     | 943 AXOR 2       |
|   |                   |                                     | 944 AXOR 2       |
|   | 958 AXOR 2        |                                     |                  |



| Model / Details  | Description    | Replaces Ref. No:        | TM No.         |
|--|----------------|--------------------------|----------------|
| 375 AXOR<br>374 AXOR 2<br>940 AXOR 2<br>942 AXOR 2<br>943 AXOR 2<br>944 AXOR 2<br>958 AXOR 2         | Hose, Radiator | 9405011282               | <b>TM08365</b> |
|  |                |                          |                |
| 375 AXOR<br>374 AXOR 2<br>940 AXOR 2<br>942 AXOR 2<br>943 AXOR 2<br>944 AXOR 2<br>958 AXOR 2         | Hose, Radiator | 9405011782               | <b>TM08366</b> |
|  |                |                          |                |
| 655 SK<br>656 SK<br>657 SK<br>658 SK<br>659 SK<br>397 2644 S/6X4                                     | Hose, Radiator | 6555014182               | <b>TM08287</b> |
|  |                |                          |                |
| 634 TOURO<br>628 CITARO<br>671 CONECTO<br>633 INTEGRO<br>632 TOURISMO<br>629 TRAVEGO<br>632 TRAVEGO  | Hose, Radiator | 6285014482               | <b>TM36582</b> |
|  |                |                          |                |
| 375 AXOR<br>374 AXOR 2<br>940 AXOR 2<br>942 AXOR 2<br>943 AXOR 2<br>944 AXOR 2<br>958 AXOR 2         | Hose, Radiator | 9405011882               | <b>TM35096</b> |
|  |                |                          |                |
| 634 TOURO<br>628 CITARO<br>633 INTEGRO<br>613 TOURISMO<br>632 TOURISMO<br>629 TRAVEGO<br>632 TRAVEGO | Hose, Radiator | 0015012382               | <b>TM36583</b> |
|  |                |                          |                |
| 634 TOURO<br>628 CITARO<br>613 TOURISMO<br>632 TOURISMO<br>629 TRAVEGO<br>632 TRAVEGO<br>410 SETRA   | Hose, Radiator | 0015013782<br>0015012482 | <b>TM36584</b> |
|  |                |                          |                |












| TM No.  | Replaces Ref. No: | Description    | Model / Details   |
|---|-------------------|----------------|---|
| <b>TM36585</b><br>   | 3575011082        | Hose,Radiator  | 357 O 405<br>612 O 405<br>671 O 345   |
| <b>TM08380</b><br>   | 6285010782        | Hose, Radiator | 628 CITARO<br>671 CONECTO<br>633 INTEGRO<br>632 TOURISMO<br>632 TRAVEGO<br>628 SETRA<br>632 SETRA |
| <b>TM36586</b><br>   | 6285010982        | Hose, Radiator | 628 CITARO<br>628 CONECTO<br>671 CONECTO<br>628 SETRA   |
| <b>TM36587</b><br> | 6385011282        | Hose, Radiator | 638 V-CLASS   |
| <b>TM36588</b><br> | 6385011482        | Hose, Radiator | 638 V-CLASS   |
| <b>TM36589</b><br> | 6385011582        | Hose, Radiator | 638 V-CLASS   |
| <b>TM36590</b><br> | 6385011982        | Hose, Radiator | 638 V-CLASS   |



| <i>Model / Details</i>   | <i>Description</i> | <i>Replaces Ref. No:</i> | <i>TM No.</i>   |
|--|--------------------|--------------------------|---|
| 901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER   | Hose, Radiator     | 901501182                | <b>TM08393</b><br>   |
| 901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER   | Hose, Radiator     | 9015011582               | <b>TM08394</b><br>   |
| 901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER   | Hose, Radiator     | 9015011882               | <b>TM08397</b><br>   |
| 690 SPRINTER<br>901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER<br>905 SPRINTER<br>909 SPRINTER | Hose, Radiator     | 9015012682               | <b>TM08387</b><br> |
| 690 SPRINTER<br>901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER<br>905 SPRINTER<br>909 SPRINTER | Hose, Radiator     | 9015012782<br>6905018482 | <b>TM08396</b><br> |
| 906 SPRINTER   | Hose, Radiator     | 9065010182               | <b>TM36591</b><br> |
| 906 SPRINTER   | Hose, Radiator     | 9065010682               | <b>TM08409</b><br> |





| TM No.  | Replaces Ref. No: | Description    | Model / Details |
|---|-------------------|----------------|-----------------|
| <b>TM08360</b><br>   | 9405011482        | Hose, Radiator | 375 AXOR        |
|   |                   |                | 374 AXOR 2      |
|   |                   |                | 940 AXOR 2      |
|   |                   |                | 942 AXOR 2      |
|   |                   |                | 943 AXOR 2      |
|   |                   |                | 944 AXOR 2      |
|   |                   |                | 958 AXOR 2      |
| <b>TM08368</b><br>   | 9405011682        | Hose, Radiator | 375 AXOR        |
|   | 9405012882        |                | 374 AXOR 2      |
|   |                   |                | 940 AXOR 2      |
|   |                   |                | 942 AXOR 2      |
|   |                   |                | 943 AXOR 2      |
|   |                   |                | 944 AXOR 2      |
|   |                   |                | 958 AXOR 2      |
| <b>TM08370</b><br>   | 9585011282        | Hose, Radiator | 958 ATEGO 2     |
|   | 9735010282        |                |                 |
| <b>TM36592</b><br> | 9585012582        | Hose, Radiator | 958 ATEGO 2     |
|   | 9705010282        |                |                 |
| <b>TM36593</b><br> | 0009872037        | Hose, Radiator | 634 TOURO       |
|   | 0009871437        |                | 628 CITARO      |
|   |                   |                | 628 CONECTO     |
|   |                   |                | 629 TRAVEGO     |
|   |                   |                | 410 SETRA       |
|   |                   |                | 628 SETRA       |
|   |                   |                | 629 SETRA       |
| <b>TM35088</b><br> | 9405061635        | Hose, Radiator | 375 ACTROS      |
|   |                   |                | 375 AXOR        |
|   |                   |                | 374 AXOR 2      |
|   |                   |                | 375 AXOR 2      |
|   |                   |                | 950 AXOR 2      |
|   |                   |                | 952 AXOR 2      |
|   |                   |                | 953 AXOR 2      |
| <b>TM36594</b><br> | 9405063635        | Hose, Radiator | 950 AXOR 2      |
|   |                   |                | 952 AXOR 2      |
|   |                   |                | 953 AXOR 2      |
|   |                   |                | 954 AXOR 2      |
|   |                   |                | 958 AXOR 2      |


















| Model / Details  | Description    | Replaces Ref. No:                        | TM No.         |
|--|----------------|--|----------------|
| 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3                                       | Hose, Radiator | 9305060135                               | <b>TM35077</b> |
| 620 NG<br>621 NG<br>622 NG<br>623 NG<br>624 NG<br>625 NG<br>645 NG   | Hose, Radiator | 6205060235                               | <b>TM23586</b> |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS   | Hose, Radiator | 9425061635                               | <b>TM35074</b> |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 | Hose, Radiator | 9425064135                               | <b>TM35076</b> |
| 620 NG<br>621 NG<br>622 NG<br>623 NG<br>624 NG<br>625 NG<br>645 NG   | Hose, Radiator | 3835060035                               | <b>TM07484</b> |
| 375 ACTROS<br>375 AXOR<br>375 AXOR 2   | Hose, Radiator | 3755060035<br>9405061235                 | <b>TM36595</b> |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO                | Hose, Radiator | 900271018038<br>9738320194<br>9738320294 | <b>TM35075</b> |





| TM No.  | Replaces Ref. No: | Description    | Model / Details  |
|---|-------------------|----------------|--|
| <b>TM08270</b><br>   | 9425010682        | Hose, Radiator | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 |
| <b>TM35073</b><br>   | 9425063535        | Hose, Radiator | 950ACTROS<br>952ACTROS<br>953 ACTROS<br>954 ACTROS   |
| <b>TM35072</b><br>  | 9425063635        | Hose, Radiator | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS   |
| <b>TM08265</b><br> | 9425063135        | Hose, Radiator | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 |
| <b>TM35089</b><br> | 9405061335        | Hose, Radiator | 375 ACTROS<br>375 AXOR<br>374 AXOR 2<br>375 AXOR 2<br>950 AXOR 2<br>952 AXOR 2<br>953 AXOR 2               |
| <b>TM08271</b><br> | 9425010782        | Hose, Radiator | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 |
| <b>TM08215</b><br> | 6205060035        | Hose, Radiator | 620 NG<br>621 NG<br>622 NG<br>623 NG<br>624 NG<br>625 NG<br>625 SK   |



| Model / Details  | Description    | Replaces Ref. No: | TM No.  |
|--|----------------|-------------------|---|
| 650 MK<br>651 MK<br>652 MK<br>653 MK<br>654 MK<br>625 SK<br>655 SK | Hose, Radiator | 6555011482        | <b>TM08236</b><br>   |
| 650 MK<br>651 MK<br>652 MK<br>653 MK<br>654 MK<br>625 SK<br>655 SK | Hose, Radiator | 6555060535        | <b>TM35059</b><br>   |
| 650 MK<br>651 MK<br>652 MK<br>653 MK<br>654 MK<br>625 SK<br>655 SK | Hose, Radiator | 6555060635        | <b>TM35058</b><br>   |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>957 ECONIC | Hose, Radiator | 9425062035        | <b>TM35082</b><br> |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>957 ECONIC | Hose, Radiator | 9425062135        | <b>TM35083</b><br> |
| 651 MK<br>653 MK<br>654 MK<br>655 SK<br>656 SK<br>657 SK<br>658 SK | Hose, Radiator | 6525012382        | <b>TM08240</b><br> |
| 950 AXOR 2<br>952 AXOR 2<br>953 AXOR 2<br>954 AXOR 2<br>958 AXOR 2 | Hose, Radiator | 9405063735        | <b>TM36602</b><br> |





| TM No.  | Replaces Ref. No: | Description    | Model / Details   |
|---|-------------------|----------------|---|
| <b>TM08219</b><br>   | 6205012882        | Hose, Radiator | 376 LP 1219 MBTC-USA<br>376 LP 1419 MBTC-USA<br>376 LPS 1525 MBTC-USA<br>615 LK/LN2<br>615 NG<br>616 NG<br>617 NG |
| <b>TM08266</b><br>   | 9425063235        | Hose, Radiator | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3        |
| <b>TM36603</b><br>   | 9405012282        | Hose, Radiator | 950 AXOR 2<br>952 AXOR 2<br>953 AXOR 2<br>954 AXOR 2<br>958 AXOR 2<br>384 OF SERIES                               |
| <b>TM08233</b><br> | 6565010382        | Hose, Radiator | 650 MK<br>651 MK<br>652 MK<br>653 MK<br>654 MK<br>625 SK<br>655 SK  |
| <b>TM08260</b><br> | 9415010382        | Hose, Radiator | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3        |
| <b>TM08208</b><br> | 6205011082        | Hose, Radiator | 620 NG<br>621 NG<br>622 NG<br>623 NG<br>624 NG<br>625 NG<br>645 NG  |
| <b>TM08220</b><br> | 6555011082        | Hose, Radiator | 652 MK<br>625 SK<br>655 SK<br>656 SK<br>657 SK<br>658 SK<br>659 SK  |



| Model / Details  | Description    | Replaces Ref. No:                      | TM No.  |
|--|----------------|--|---|
| 621 NG<br>624 NG<br>625 NG<br>655 SK<br>656 SK<br>659 SK   | Hose, Radiator | 6175014982<br>6205010882<br>6205011182 | <b>TM08222</b><br>   |
| 651 MK<br>652 MK<br>653 MK<br>654 MK<br>625 SK<br>655 SK<br>656 SK   | Hose, Radiator | 6525012082                             | <b>TM08253</b><br>   |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3             | Hose, Radiator | 9425011582                             | <b>TM08261</b><br>  |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3             | Hose, Radiator | 9415010782                             | <b>TM08263</b><br> |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3             | Hose, Radiator | 9425011682                             | <b>TM08262</b><br> |
| 651 MK<br>652 MK<br>653 MK<br>654 MK<br>620 NG<br>621 NG<br>622 NG   | Hose, Radiator | 6555011282<br>6205013882               | <b>TM08221</b><br> |
| 620 NG<br>621 NG<br>622 NG<br>623 NG<br>624 NG<br>371 1928 S OTOMARSAN/<br>TUERKEI<br>371 2628 K OTOMARSAN/<br>TUERKEI | Hose, Radiator | 6205010382                             | <b>TM08209</b><br> |







| TM No.  | Replaces Ref. No: | Description    | Model / Details  |
|---|-------------------|----------------|--|
| <b>TM08269</b><br>   | 9415010582        | Hose, Radiator | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS   |
| <b>TM08250</b><br>   | 6555014982        | Hose, Radiator | 652 MK<br>653 MK<br>654 MK<br>625 SK<br>655 SK<br>656 SK<br>657 SK   |
| <b>TM08347</b><br>   | 9405012182        | Hose, Radiator | 950 AXOR 2<br>952 AXOR 2<br>953 AXOR 2<br>954 AXOR 2<br>958 AXOR 2   |
| <b>TM08267</b><br> | 9425061035        | Hose, Radiator | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 |
| <b>TM35087</b><br> | 9405000375        | Hose, Radiator | 950 AXOR 2<br>952 AXOR 2   |
| <b>TM08235</b><br> | 6555010482        | Hose, Radiator | 625 SK<br>655 SK<br>656 SK<br>657 SK<br>658 SK<br>659 SK   |
| <b>TM08254</b><br> | 6525012282        | Hose, Radiator | 651 MK<br>652 MK<br>653 MK<br>654 MK<br>625 SK<br>655 SK<br>656 SK   |



| Model / Details  | Description    | Replaces Ref. No:        | TM No.  |
|--|----------------|--------------------------|---|
| 620 NG<br>621 NG<br>622 NG<br>623 NG<br>624 NG<br>645 NG<br>646 NG | Hose, Radiator | 6205013082               | <b>TM08228</b><br>   |
| 650 MK<br>651 MK<br>652 MK<br>653 MK<br>654 MK<br>625 SK<br>655 SK | Hose, Radiator | 6565011482               | <b>TM08244</b><br>   |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS               | Hose, Radiator | 9425061535               | <b>TM36604</b><br>   |
| 620 NG<br>621 NG<br>622 NG<br>623 NG<br>624 NG<br>625 NG<br>645 NG | Hose, Radiator | 6205012082               | <b>TM08212</b><br> |
| 950 AXOR 2<br>952 AXOR 2<br>953 AXOR 2<br>954 AXOR 2<br>958 AXOR 2 | Hose, Radiator | 9405000075               | <b>TM08349</b><br> |
| 950 AXOR 2<br>952 AXOR 2<br>953 AXOR 2<br>954 AXOR 2<br>958 AXOR 2 | Hose, Radiator | 9405000175               | <b>TM36605</b><br> |
| 685 TOURINO  | Hose, Radiator | 6855013682<br>9439972182 | <b>TM08286</b><br> |





| TM No.  | Replaces Ref. No:        | Description    | Model / Details  |
|---|--------------------------|----------------|--|
| <b>TM08268</b><br>   | 900271060004             | Hose, Radiator | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 |
| <b>TM08225</b><br>   | 6205012982               | Hose, Radiator | 620 NG<br>621 NG<br>622 NG<br>623 NG<br>624 NG<br>645 NG<br>646 NG   |
| <b>TM08234</b><br>   | 6555014082               | Hose, Radiator | 625 SK<br>655 SK<br>656 SK<br>657 SK<br>658 SK<br>659 SK<br>397 1735 S                                     |
| <b>TM08348</b><br> | 3755010582<br>9405010982 | Hose, Radiator | 375 ACTROS<br>375 AXOR<br>375 AXOR 2   |
| <b>TM08204</b><br> | 3875011582               | Hose, Radiator | 387 NG<br>389 NG<br>391 NG<br>393 NG<br>395 NG   |
| <b>TM08227</b><br> | 6205013782               | Hose, Radiator | 620 NG<br>621 NG<br>622 NG<br>623 NG<br>624 NG<br>645 NG<br>646 NG   |
| <b>TM08264</b><br> | 9415010282<br>9425011082 | Hose, Radiator | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 |



| Model / Details  | Description    | Replaces Ref. No:        | TM No.         |
|--|----------------|--------------------------|----------------|
| 343 T2/L<br>343 T2/LN1<br>346 L 1924<br>346 LA 1924<br>346 LAK 1924<br>346 LAS 1924<br>346 LK 1924 | Hose, Radiator | 3465015182               | <b>TM08196</b> |
| 375 ACTROS<br>375 AXOR<br>375 AXOR 2   | Hose, Radiator | 3755010482<br>9405010782 | <b>TM08343</b> |
| 970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>970 ATEGO 2<br>972 ATEGO 2<br>975 ATEGO 2      | Hose, Radiator | 9745011282<br>9745010782 | <b>TM36606</b> |
| 655 SK<br>656 SK<br>657 SK<br>658 SK<br>659 SK<br>397 2644 S/6X4                                   | Hose, Radiator | 6555012082               | <b>TM08241</b> |
| 615 NG<br>616 NG<br>617 NG<br>619 NG<br>625 NG   | Hose, Radiator | 6175012782<br>6175011382 | <b>TM08224</b> |
| 650 MK<br>651 MK<br>652 MK<br>653 MK<br>654 MK<br>625 SK<br>655 SK                                 | Hose, Radiator | 6525015282               | <b>TM08242</b> |
| 655 SK<br>656 SK<br>658 SK<br>659 SK   | Hose, Radiator | 6555013082<br>6555011882 | <b>TM08239</b> |





| TM No.  | Replaces Ref. No:         | Description                | Model / Details  |
|---|---------------------------|----------------------------|--|
| <b>TM08346</b><br>   | 9405000275                | Hose, Radiator             | 950 AXOR 2<br>952 AXOR 2<br>953 AXOR 2<br>954 AXOR 2<br>958 AXOR 2<br>384 OF SERIES                    |
| <b>TM36607</b><br>   | 0009872443                | Hose, Radiator<br>Silicone | 634 TOURO<br>628 CITARO<br>671 CONECTO<br>444 TOURINO<br>685 TOURINO<br>629 TRAVEGO<br>632 TRAVEGO     |
| <b>TM08358</b><br>   | 0015012282<br>0015013982  | Hose, Radiator             | 634 TOURO<br>628 CITARO<br>633 INTEGRO<br>613 TOURISMO<br>632 TOURISMO<br>629 TRAVEGO<br>632 TRAVEGO   |
| <b>TM33075</b><br> | 9415011282<br>3015010682  | Hose, Radiator             | 979 ACCELO<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3 |
| <b>TM08376</b><br> | 00000005008<br>0015014682 | Hose, Radiator             | 634 TOURO<br>628 CITARO<br>671 CONECTO<br>633 INTEGRO<br>613 TOURISMO<br>632 TOURISMO<br>629 TRAVEGO   |
| <b>TM36608</b><br> | 9705011682                | Hose, Radiator             | 375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>375 ATEGO 2<br>958 ATEGO 2            |
| <b>TM36609</b><br> | 6565010782<br>6555014682  | Hose, Radiator             | 655 SK<br>656 SK<br>657 SK<br>658 SK<br>659 SK   |












| Model / Details  | Description    | Replaces Ref. No:                      | TM No.  |
|--|----------------|--|---|
| 375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>958 ATEGO 2<br>970 ATEGO 2                  | Hose, Radiator | 9705011782<br>9705011382               | <b>TM36610</b><br>   |
| 970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>970 ATEGO 2<br>972 ATEGO 2<br>975 ATEGO 2                | Hose, Radiator | 9705012582<br>9705012682<br>9735011282 | <b>TM08384</b><br>   |
| 690 SPRINTER<br>901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER<br>905 SPRINTER<br>909 SPRINTER | Hose, Radiator | 9015012582                             | <b>TM08395</b><br>  |
| 903 SPRINTER<br>904 SPRINTER   | Hose, Radiator | 9015013182                             | <b>TM36611</b><br> |
| 903 SPRINTER<br>904 SPRINTER   | Hose, Radiator | 9015013082                             | <b>TM36612</b><br> |
| 906 SPRINTER   | Hose, Radiator | 9065012482                             | <b>TM36613</b><br> |
| 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3   | Hose, Radiator | 9305060035                             | <b>TM35097</b><br> |












| TM No.  | Replaces Ref. No:        | Description    | Model / Details |
|---|--------------------------|----------------|-----------------|
| <b>TM36614</b>  | 9065010882               | Hose, Radiator | 906 SPRINTER    |
|    |                          |                |                 |
| <b>TM36615</b>  | 9065013882               | Hose, Radiator | 906 SPRINTER    |
|    |                          |                |                 |
| <b>TM36616</b>  | 9065012382               | Hose, Radiator | 906 SPRINTER    |
|    |                          |                |                 |
| <b>TM08408</b>  | 9065010782               | Hose, Radiator | 906 SPRINTER    |
|  |                          |                |                 |
| <b>TM36617</b>  | 9065013182<br>9065014482 | Hose, Radiator | 906 SPRINTER    |
|  |                          |                |                 |
| <b>TM36618</b>  | 9065010582               | Hose, Radiator | 906 SPRINTER    |
|  |                          |                |                 |
| <b>TM36619</b>  | 9065013582               | Hose, Radiator | 906 SPRINTER    |
|  |                          |                |                 |



| <i>Model / Details</i> | <i>Description</i> | <i>Replaces Ref. No:</i> | <i>TM No.</i>   |
|------------------------|--------------------|--------------------------|---|
| 906 SPRINTER           | Hose, Radiator     | 9065012182               | <b>TM36620</b>  |
|                        |                    |                          |    |
| 906 SPRINTER           | Hose, Radiator     | 9065012082               | <b>TM36621</b>  |
|                        |                    |                          |    |
| 906 SPRINTER           | Hose, Radiator     | 9065010482               | <b>TM08407</b>  |
|                        |                    |                          |    |
| 906 SPRINTER           | Hose, Radiator     | 9065013282               | <b>TM36622</b>  |
|                        |                    |                          |  |
| 906 SPRINTER           | Hose, Radiator     | 9065013382               | <b>TM36623</b>  |
|                        |                    |                          |  |
| 906 SPRINTER           | Hose, Radiator     | 9065013782               | <b>TM36624</b>  |
|                        |                    |                          |  |
| 906 SPRINTER           | Hose, Radiator     | 9065013682               | <b>TM36625</b>  |
|                        |                    |                          |  |





| TM No.  | Replaces Ref. No:        | Description    | Model / Details  |
|---|--------------------------|----------------|--|
| <b>TM36626</b>  | 9065012982               | Hose, Radiator | 906 SPRINTER   |
|    |                          |                |  |
| <b>TM08410</b>  | 9065011482<br>9065013082 | Hose, Radiator | 906 SPRINTER   |
|    |                          |                |  |
| <b>TM36627</b>  | 9015285382               | Hose, Radiator | 903 SPRINTER<br>904 SPRINTER   |
|    |                          |                |  |
| <b>TM08371</b>  | 9705010182<br>9705011282 | Hose, Radiator | 375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>958 ATEGO 2<br>970 ATEGO 2  |
|  |                          |                |  |
| <b>TM08406</b>  | 9305010182               | Hose, Radiator | 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3                         |
|  |                          |                |  |
| <b>TM08374</b>  | 9305060335               | Hose, Radiator | 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3                         |
|  |                          |                |  |
| <b>TM36628</b>  | 6559973782               | Hose, Radiator | 375 AXOR<br>374 AXOR 2<br>940 AXOR 2<br>942 AXOR 2<br>943 AXOR 2<br>944 AXOR 2<br>958 AXOR 2 |
|  |                          |                |  |












| Model / Details   | Description              | Replaces Ref. No:                      | TM No.         |
|---|--------------------------|--|----------------|
| 375 ACTROS<br>375 AXOR<br>374 AXOR 2<br>375 AXOR 2<br>940 AXOR 2<br>942 AXOR 2<br>943 AXOR 2                          | Rubber Bushing, Radiator | 9405040214                             | <b>TM08357</b> |
| 611 T1/TN<br>601 207 D/208 D<br>601 208/210<br>602 307 D/308 D<br>602 307 D/308D<br>602 308 D<br>602 308/310          | Mounting, Radiator       | 6089880011                             | <b>TM36629</b> |
| 976 ATEGO<br>976 ATEGO 2<br>308 L 608 E,L 708 E<br>308 L/LO 608 D<br>308 LO 608 D,LO 708 D/E<br>309 T2/L<br>309 TL2/L | Mounting, Radiator       | 0019875240<br>3225040212<br>0019872640 | <b>TM06445</b> |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS  | Mounting, Radiator       | 9425040214                             | <b>TM07741</b> |
| 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3<br>949 ZETROS                                    | Mounting, Radiator       | 9305040114                             | <b>TM08430</b> |
| 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS  | Mounting, Radiator       | 9605041514                             | <b>TM36630</b> |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3            | Expansion Tank, Radiator | 0005003049<br>0005003449<br>0005003849 | <b>TM07810</b> |














| TM No.  | Replaces Ref. No:  | Description   | Model / Details  |
|---|--|---|--|
| <b>TM07930</b><br>   | 674500049<br>6735000149                                  | Expansion Tank, Radiator<br>Repl. Hella: 8MA 376<br>705-301 | 397 LP 1014 MBSA-RSA<br>397 LP 1114,1214 MB-SA-RSA<br>397 LP 1214 A MBSA-RSA<br>397 LP 1517<br>397 LP 1617 A MBSA-RSA<br>397 LP/LPK 1314 MB-SA-RSA<br>397 LP/LPK 1417,1617 |
| <b>TM36631</b><br>   | 3005001049S<br>3575000249S<br>3575000949S<br>3575001049S | Expansion Tank, Radiator<br>Behr type, Without Cap          | 382 OH SERIES<br>382 O 500<br>634 TOURO<br>628 CITARO<br>633 INTEGRO<br>633 INTOURO<br>444 TOURINO   |
| <b>TM07813</b><br>   | 9705000449<br>9705000349<br>9705000249                   | Expansion Tank, Radiator                                    | 375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>375 ATEGO 2<br>958 ATEGO 2  |
| <b>TM07929</b><br> | 0005003149   | Expansion Tank, Radiator                                    | 950 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>934 ACTROS 2/3<br>957 ECONIC   |
| <b>TM07931</b><br> | 9405010003   | Expansion Tank, Radiator                                    | 375 AXOR<br>374 AXOR 2<br>940 AXOR 2<br>942 AXOR 2<br>943 AXOR 2<br>944 AXOR 2<br>950 AXOR 2   |
| <b>TM07895</b><br> | 0005002149   | Expansion Tank, Radiator<br>Repl. Hella: 8MA 376<br>705-191 | 650 MK<br>651 MK<br>652 MK<br>653 MK<br>654 MK<br>699 MK<br>625 SK   |
| <b>TM07859</b><br> | 0005002249   | Expansion Tank, Radiator<br>Repl. Hella: 8MA 376<br>705-201 | 650 MK<br>651 MK<br>652 MK<br>653 MK<br>654 MK<br>625 SK<br>655 SK   |










| Model / Details  | Description                     | Replaces Ref. No:  | TM No.  |
|--|---------------------------------|--|---|
| 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS   | Expansion Tank, Radiator        | 9605014103<br>9605018003                                     | <b>TM08120</b><br>   |
| 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS   | Expansion Tank, Radiator        | 9605014203   | <b>TM08121</b><br>   |
| 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS   | Expansion Tank, Radiator        | 9605014303   | <b>TM08122</b><br>  |
| 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3 | Sensor, Radiator                | 9425420017<br>9425420217                                     | <b>TM10676</b><br> |
| 979 ACCELO<br>375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>375 ATEGO 2             | Sensor, Radiator                | 9705450124   | <b>TM07548</b><br> |
| 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3                                   | Plug, Radiator                  | 007604014100<br>007604014101<br>007604014106<br>007604014110 | <b>TM04100</b><br> |
| 979 ACCELO<br>375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3     | Expansion Tank Cap,<br>Radiator | 0005016415<br>0005015615<br>0000401908                       | <b>TM07863</b><br> |












| TM No.  | Replaces Ref. No: | Description                     | Model / Details      |
|---|-------------------|---------------------------------|----------------------|
| <b>TM07499</b><br>   | 0005014615        | Expansion Tank Cap,             | 314 LP               |
|   | 0005017215        | Radiator                        | 316 LP               |
|   | 0005017315        |                                 | 318 LP               |
|   | 0005015315        |                                 | 343 T2/L             |
|   |                   |                                 | 346 L 1928           |
|   |                   |                                 | 346 LK 1928          |
|   |                   |                                 | 346 LS 1928          |
| <b>TM07938</b><br>   | 0005000206        | Expansion Tank Cap,<br>Radiator | 950 ACTROS           |
|   |                   |                                 | 952 ACTROS           |
|   |                   |                                 | 953 ACTROS           |
|   |                   |                                 | 954 ACTROS           |
|   |                   |                                 | 930 ACTROS 2/3       |
|   |                   |                                 | 932 ACTROS 2/3       |
|   |                   | 933 ACTROS 2/3                  |                      |
| <b>TM07866</b><br>  | 0005016715        | Expansion Tank Cap,<br>Radiator | 375 ACTROS           |
|   | 0005017015        |                                 | 375 AXOR             |
|   |                   |                                 | 374 AXOR 2           |
|   |                   |                                 | 375 AXOR 2           |
|   |                   |                                 | 940 AXOR 2           |
|   |                   |                                 | 942 AXOR 2           |
|   |                   | 943 AXOR 2                      |                      |
| <b>TM08044</b><br> | 9705280110        | Expansion Tank Cap,<br>Radiator | 375 ATEGO            |
|   |                   |                                 | 970 ATEGO            |
|   |                   |                                 | 972 ATEGO            |
|   |                   |                                 | 975 ATEGO            |
|   |                   |                                 | 976 ATEGO            |
|   |                   |                                 | 375 ATEGO 2          |
|   |                   | 958 ATEGO 2                     |                      |
| <b>TM07833</b><br> | 3552001501        | Water Pump                      | 336 LP 1924          |
|   | 3552001101        |                                 | 336 LPS 1924         |
|   | 3552000901        |                                 | 343 T2/L             |
|   | 3552000801        |                                 | 343 T2/LN1           |
|   |                   |                                 | 346 L 1924           |
|   |                   |                                 | 346 L 1928           |
|   |                   |                                 | 346 LA 1924          |
| <b>TM36632</b><br> | 3662000401S       | Water Pump                      | 384 L 1214           |
|   | 3662005901S       | Without Plate                   | 384 L 1215           |
|   | 3662000901S       |                                 | 384 L 1218           |
|   |                   |                                 | 384 L 1414           |
|   |                   |                                 | 384 L 1418 ,L 1418 E |
|   |                   |                                 | 384 LA 1418          |
|   |                   | 384 LAK 1418                    |                      |
| <b>TM07116</b><br> | 4032007001        | Water Pump                      | 363 LP 2232/6X4      |
|   | 4032004901        | Repl. Hella: 8MP 376            |                      |
|   | 4032003501        | 808-564                         |                      |
|   | 4032003401        |                                 |                      |



| Model / Details  | Description                                   | Replaces Ref. No:                                    | TM No.  |
|--|---|--|---|
| 363 LP 2226/6X4<br>363 LP 2232/6X4<br>363 LPB 2226/6X4<br>363 LPK 2226/6X4<br>363 LPK 2232/6X4<br>363 LPS 2226/6X4<br>363 LPS 2232/6X4 | Water Pump                                    | 4032007101<br>4032005101<br>4032004401               | <b>TM07338</b><br>   |
| 363 LP 2226/6X4<br>363 LP 2232/6X4<br>363 LPB 2226/6X4<br>363 LPK 2226/6X4<br>363 LPK 2232/6X4<br>363 LPS 2226/6X4<br>363 LPS 2232/6X4 | Water Pump                                    | 4032007701<br>4032007601                             | <b>TM07853</b><br>   |
| 615 NG<br>616 NG<br>617 NG<br>619 NG<br>621 NG<br>625 SK<br>655 SK   | Water Pump<br>Repl. Hella: 8MP 376<br>808-174 | 4222001101<br>4222000601                             | <b>TM07130</b><br>   |
| 651 MK<br>624 NG<br>655 SK<br>656 SK<br>600 O 303  | Water Pump<br>Repl. Hella: 8MP 376<br>808-764 | 4222001201<br>4222000701                             | <b>TM07341</b><br> |
| 624 NG<br>625 NG<br>645 NG<br>625 SK   | Water Pump<br>Repl. Laso: 20200130            | 4222001001<br>4222000501                             | <b>TM07456</b><br> |
| 650 MK<br>651 MK<br>652 MK<br>653 MK<br>654 MK<br>615 NG<br>617 NG   | Water Pump                                    | 4412000201<br>4412000101                             | <b>TM36633</b><br> |
| 979 ACCELO<br>375 ACTROS<br>375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO  | Water Pump<br>Repl. Hella: 8MP 376<br>808-254 | 9042004901<br>9042002601<br>9042000801<br>9042000401 | <b>TM07085</b><br> |





| TM No.  | Replaces Ref. No: | Description          | Model / Details      |
|---|-------------------|----------------------|----------------------|
| <b>TM07898</b><br>   | 5412000101        | Water Pump           | 950 ACTROS           |
|   | 5412001201        | Repl. Hella: 8MP 376 | 952 ACTROS           |
|   | 5412001101        | 808-204              | 953 ACTROS           |
|   | 5412001401        |                      | 954 ACTROS           |
|   |                   |                      | 930 ACTROS 2/3       |
|   |                   |                      | 932 ACTROS 2/3       |
|   |                   |                      | 933 ACTROS 2/3       |
| <b>TM07897</b><br>   | 5422001901        | Water Pump           | 979 ACCELO           |
|   | 5422001501        | Repl. Hella: 8MP 376 | 950 ACTROS           |
|   | 5422000501        | 808-244              | 952 ACTROS           |
|   |                   |                      | 953 ACTROS           |
|   |                   |                      | 954 ACTROS           |
|   |                   | 930 ACTROS 2/3       |                      |
|   |                   | 932 ACTROS 2/3       |                      |
| <b>TM07139</b><br>   | 5422002001        | Water Pump           | 979 ACCELO           |
|   | 5422001601        |                      | 950 ACTROS           |
|   | 5422000601        |                      | 952 ACTROS           |
|   |                   |                      | 953 ACTROS           |
|   |                   |                      | 954 ACTROS           |
|   |                   | 930 ACTROS 2/3       |                      |
|   |                   | 932 ACTROS 2/3       |                      |
| <b>TM07899</b><br> | 5422002201        | Water Pump           | 979 ACCELO           |
|   |                   | Repl. Hella: 8MP 376 | 950 ACTROS           |
|   |                   | 809-274              | 952 ACTROS           |
|   |                   |                      | 953 ACTROS           |
|   |                   |                      | 954 ACTROS           |
|   |                   | 930 ACTROS 2/3       |                      |
|   |                   | 932 ACTROS 2/3       |                      |
| <b>TM07424</b><br> | 5422002101        | Water Pump           | 979 ACCELO           |
|   |                   | Repl. Hella: 8MP 376 | 950 ACTROS           |
|   |                   | 808-234              | 952 ACTROS           |
|   |                   |                      | 953 ACTROS           |
|   |                   |                      | 954 ACTROS           |
|   |                   | 930 ACTROS 2/3       |                      |
|   |                   | 932 ACTROS 2/3       |                      |
| <b>TM07426</b><br> | 4572000801        | Water Pump           | 375 AXOR             |
|   | 4572002301        | Repl. Hella: 8MP 376 | 374 AXOR 2           |
|   |                   | 809-014              | 940 AXOR 2           |
|   |                   |                      | 942 AXOR 2           |
|   |                   |                      | 943 AXOR 2           |
|   |                   | 944 AXOR 2           |                      |
|   |                   | 386 LS 1625          |                      |
| <b>TM07900</b><br> | 4572000201        | Water Pump           | 958 AXOR 2           |
|   | 4572000501        | Repl. Hella: 8MP 376 | 695 LS 1634EL        |
|   | 4032005301        | 808-264              | 695 LS 1634EL 1635 S |
|   | 4032007301        |                      | 696 L 1938           |
|   |                   |                      | 696 L 2638           |
|   |                   | 696 LK 2638          |                      |
|   |                   | 696 LS 1938          |                      |


















| Model / Details  | Description                                   | Replaces Ref. No:                                    | TM No.             |
|--|---|--|--------------------|
| 382 OH SERIES<br>382 O 500<br>634 O 500<br>634 O 500 RSD /<br>2736/8X2/30<br>634 CBC - FAHRGESTELL<br>2-ACHSER<br>634 CBC - FAHRGESTELL<br>OC500 CNG GAS | Water Pump<br>Repl. Hella: 8MP 376<br>809-024 | 4572000901<br>4572001001<br>4572002401               | <b>TM07896</b><br> |
| 375 ACTROS<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>958 ATEGO 2<br>970 ATEGO 2   | Water Pump<br>Repl. Dayco: DP092              | 9062006501<br>9062005401<br>9062002901<br>9062002201 | <b>TM07987</b><br> |
| 673 LK/LN2<br>674 LK/LN2<br>418 UNIMOG   | Water Pump<br>Repl. Hella: 8MP 376<br>808-674 | 3642002001<br>3642000901<br>3642000101               | <b>TM07132</b><br> |
| 958 AXOR 2<br>386 L 1625,1725<br>386 L 1633<br>386 L 2325,2425,LA<br>2425/6X6<br>386 LB 2325,2425<br>386 LK 2325,2425                                    | Water Pump                                    | 4572000101<br>4752000201<br>4752000101               | <b>TM36634</b><br> |
| 979 ACCELO<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3   | Water Pump                                    | 5422002401   | <b>TM07988</b><br> |
| 900 SPRINTER<br>906 SPRINTER   | Water Pump<br>With Gasket                     | 6512002301S  | <b>TM36635</b><br> |
| 671 CONECTO  | Water Pump<br>Repl. Hella: 8MP 376<br>809-184 | 9062002601<br>9062002701                             | <b>TM07462</b><br> |





| TM No.  | Replaces Ref. No: | Description                                   | Model / Details  |
|---|-------------------|---|------------------|
| <b>TM07992</b><br>   | 4572000601        | Water Pump                                    | 375 AXOR         |
|   | 4602002801        |   | 374 AXOR 2       |
| 4602003001  | 940 AXOR 2        |   |                  |
|   |                   |   | 942 AXOR 2       |
|   |                   |   | 943 AXOR 2       |
|   |                   |   | 944 AXOR 2       |
| <b>TM07425</b><br>   | 9042005101        | Water Pump                                    | 375 ATEGO        |
|   |                   |   | 970 ATEGO        |
|   | 972 ATEGO         |   |                  |
|   | 976 ATEGO         |   |                  |
|   | 375 ATEGO 2       |   |                  |
|   | 970 ATEGO 2       |   |                  |
|   | 972 ATEGO 2       |   |                  |
| <b>TM07945</b><br>   | 9062006401        | Water Pump<br>Repl. Hella: 8MP 376<br>808-464 | 958 ATEGO 2      |
|   | 9062004801        |   | 976 ATEGO 2      |
|   | 9062004201        |   | 958 AXOR 2       |
|   | 9062003201        |   | 384 OF SERIES    |
|   |                   |   | 368 OH SERIES    |
|   | 382 OH SERIES     |   |                  |
|   | 390 OH SERIES     |   |                  |
| <b>TM07465</b><br> | 9062003701        | Water Pump<br>Repl. Hella: 8MP 376<br>809-244 | 970 ATEGO        |
|   | 9062005501        |   | 972 ATEGO        |
|   | 9062006201        |   | 975 ATEGO        |
|   |                   |   | 976 ATEGO        |
|   |                   |   | 958 ATEGO 2      |
|   | 970 ATEGO 2       |   |                  |
|   | 972 ATEGO 2       |   |                  |
| <b>TM08145</b><br> | 5412002701        | Water Pump<br>Repl. Laso: 20200025A           | 930 ACTROS 2/3   |
|   | 5412001801        |   | 932 ACTROS 2/3   |
|   |                   |   | 933 ACTROS 2/3   |
|   |                   |   | 934 ACTROS 2/3   |
| <b>TM07290</b><br> | 4422010080        | Gasket, Water Pump                            | 363 LP 2226/6X4  |
|   | 4032011080        |   | 363 LP 2232/6X4  |
|   |                   |   | 363 LPB 2226/6X4 |
|   |                   |   | 363 LPK 2226/6X4 |
|   |                   |   | 363 LPK 2232/6X4 |
|   |                   |   | 363 LPS 2226/6X4 |
|   |                   |   | 363 LPS 2232/6X4 |
| <b>TM07720</b><br> | 9062030180        | Gasket, Water Pump                            | 979 ACCELO       |
|   |                   |   | 375 ATEGO        |
|   |                   |   | 970 ATEGO        |
|   |                   |   | 972 ATEGO        |
|   |                   |   | 975 ATEGO        |
|   |                   |   | 976 ATEGO        |
|   | 375 ATEGO 2       |   |                  |










| Model / Details  | Description            | Replaces Ref. No:                                    | TM No.  |
|--|------------------------|--|---|
| 611 T1/TN<br>408 UNIMOG<br>901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER<br>667 VARIO<br>668 VARIO                                  | Gasket, Water Pump     | 6012030076   | <b>TM07718</b><br>   |
| 979 ACCELO<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3   | Seal Ring, Water Pump  | 0012011919<br>0012011819<br>0002019919<br>0002015719 | <b>TM07710</b><br>   |
| 397 LP 1014 MBSA-RSA<br>397 LP 1114,1214 MB-SA-RSA<br>397 LP/LPK 1314 MB-SA-RSA<br>397 LPK 1414 MBSA-RSA<br>615 LK/LN2<br>674 LK/LN2<br>675 LK/LN2 | Repair Kit, Water Pump | 3662000804<br>3662000604<br>3662000304<br>3662000004 | <b>TM36636</b><br>  |
| 363 LP 2226/6X4<br>363 LP 2232/6X4<br>363 LPB 2226/6X4<br>363 LPK 2226/6X4<br>363 LPK 2232/6X4<br>363 LPS 2226/6X4<br>363 LPS 2232/6X4             | Repair Kit, Water Pump | 4222000604<br>4222000304<br>4232000104<br>4232000004 | <b>TM07539</b><br> |
| 624 NG<br>625 NG<br>645 NG<br>625 SK   | Repair Kit, Water Pump | 4222000504<br>4222000404<br>4222000204<br>4222000004 | <b>TM07537</b><br> |
| 650 MK<br>651 MK<br>652 MK<br>653 MK<br>654 MK<br>615 NG<br>617 NG   | Repair Kit, Water Pump | 4412000204<br>4412000104<br>4412000004<br>4222000104 | <b>TM07529</b><br> |
| 979 ACCELO<br>375 ACTROS<br>375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO  | Repair Kit, Water Pump | 9042000004<br>9062000004                             | <b>TM08459</b><br> |










| TM No.  | Replaces Ref. No: | Description            | Model / Details      |
|---|-------------------|------------------------|----------------------|
| <b>TM08456</b><br>   | 5422000004        | RepairKit, Water Pump  | 979 ACCELO           |
|   | 5422000104        |                        | 950 ACTROS           |
|   |                   |                        | 952 ACTROS           |
|   |                   |                        | 953 ACTROS           |
|   |                   |                        | 954 ACTROS           |
|   |                   |                        | 930 ACTROS 2/3       |
|   |                   |                        | 932 ACTROS 2/3       |
| <b>TM36637</b><br>   | 5422002601S       | Repair Kit, Water Pump | 979 ACCELO           |
|   | 5422002201S       |                        | 950 ACTROS           |
|   | 5422001801S       |                        | 952 ACTROS           |
|   |                   |                        | 953 ACTROS           |
|   |                   |                        | 954 ACTROS           |
|   |                   |                        | 930 ACTROS 2/3       |
|   |                   |                        | 932 ACTROS 2/3       |
| <b>TM08461</b><br>   | 4572000104        | Repair Kit, Water Pump | 375 AXOR             |
|   |                   |                        | 374 AXOR 2           |
|   |                   |                        | 940 AXOR 2           |
|   |                   |                        | 942 AXOR 2           |
|   |                   |                        | 943 AXOR 2           |
|   |                   |                        | 944 AXOR 2           |
|   |                   |                        | 958 AXOR 2           |
| <b>TM07478</b><br> | 3662032515        | Pipe, Water Pump       | 979 ACCELO           |
|   |                   |                        | 384 L 1214           |
|   |                   |                        | 384 L 1215           |
|   |                   |                        | 384 L 1218           |
|   |                   |                        | 384 L 1414           |
|   |                   |                        | 384 L 1418 ,L 1418 E |
|   |                   |                        | 384 LA 1418          |
| <b>TM07725</b><br> | 9062030015        | Pipe, Water Pump       | 979 ACCELO           |
|   | 9062030615        |                        | 375 ACTROS           |
|   | 9062030415        |                        | 375 ATEGO            |
|   |                   |                        | 970 ATEGO            |
|   |                   |                        | 972 ATEGO            |
|   |                   |                        | 975 ATEGO            |
|   |                   |                        | 976 ATEGO            |
| <b>TM36638</b><br> | 4572030630        | Pipe, Water Pump       | 375 AXOR             |
|   |                   |                        | 374 AXOR 2           |
|   |                   |                        | 940 AXOR 2           |
|   |                   |                        | 942 AXOR 2           |
|   |                   |                        | 943 AXOR 2           |
|   |                   |                        | 944 AXOR 2           |
|   |                   |                        | 958 AXOR 2           |
| <b>TM36639</b><br> | 6112031082        | Hose, Water Pump       | -                    |
|   |                   |                        |                      |



| Model / Details  | Description  | Replaces Ref. No:        | TM No.  |
|--|--|--------------------------|---|
| 979 ACCELO<br>690 SPRINTER<br>901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER<br>905 SPRINTER | Hose, Water Pump   | 6112030482<br>6112032682 | <b>TM08411</b><br>   |
| 979 ACCELO<br>690 SPRINTER<br>901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER<br>905 SPRINTER | Hose, Water Pump   | 6112030582<br>6112032782 | <b>TM08412</b><br>   |
| 901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER   | Hose, Water Pump   | 6012030682               | <b>TM36640</b><br>   |
| 375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>958 ATEGO 2<br>970 ATEGO 2                | Hose, Water Pump   | 9705010082               | <b>TM08369</b><br> |
| 906 SPRINTER<br>909 SPRINTER<br>636 VIANO<br>639 VIANO   | Hose, Water Pump   | 6462030282               | <b>TM36641</b><br> |
| 901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER<br>667 VARIO                                  | Blade, Fan<br>For 200.192, 200.196 and<br>200.200                        | 0032050306<br>6172000323 | <b>TM08048</b><br> |
| 901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER<br>667 VARIO                                  | Blade, Fan<br>For 200.192 and 200.196<br>Repl. Hella: 8MV 376<br>733-171 | 0032051306               | <b>TM08047</b><br> |












| TM No.  | Replaces Ref. No: | Description          | Model / Details                |
|---|-------------------|----------------------|--------------------------------|
| <b>TM07831</b><br>   | 3452007724        | Blade,Fan            | 336 LP 1924                    |
|   | 4752000024        | Metal                | 336 LPS 1924                   |
|   | 3552001124        | ø600 mm              | 343 T2/L                       |
|   | 3552001024        |                      | 343 T2/LN1                     |
|   |                   |                      | 346 L 1924                     |
|   |                   |                      | 346 L 1928                     |
|   |                   |                      | 346 LA 1924                    |
| <b>TM07844</b><br>   | 0022059306        | Blade, Fan           | 386 L 1625,1725                |
|   | 0022059206        | Aluminium            | 386 L 1633                     |
|   | 0022050306        | Repl. Hella: 8MV 376 | 386 L 2325,2425,LA<br>2425/6X6 |
|   |                   | 733-121              | 386 LB 2325,2425               |
|   |                   | ø680 mm              | 386 LK 2325,2425               |
|   |                   |                      | 386 LS 1630                    |
|   |                   |                      | 386 LS 1633                    |
| <b>TM07889</b><br>   | 0022057006        | Blade, Fan           | 619 NG                         |
|   | 0012051106        | Aluminium            | 621 NG                         |
|   | 4032003024        | ø620 mm              | 624 NG                         |
|   |                   |                      | 397 OF SERIES                  |
|   |                   |                      | 397 OH SERIES                  |
|   |                   |                      | 397 1924 S MBSA-RSA            |
| <b>TM07924</b><br> | 0032051606        | Blade, Fan           | 650 MK                         |
|   | 0032050606        | For 200.165          | 651 MK                         |
|   |                   | Repl. Hella: 8MV 376 | 652 MK                         |
|   |                   | 733-071              | 653 MK                         |
|   |                   | ø680 mm              | 654 MK                         |
|   |                   |                      | 655 SK                         |
|   |                   |                      | 656 SK                         |
| <b>TM07887</b><br> | 0032050006        | Blade, Fan           | 650 MK                         |
|   | 5412050106        | For 200.164          | 652 MK                         |
|   |                   | Repl. Hella: 8MV 376 | 653 MK                         |
|   |                   | 733-151              | 654 MK                         |
|   |                   | ø750 mm              | 624 NG                         |
|   |                   |                      | 625 SK                         |
|   |                   |                      | 655 SK                         |
| <b>TM07967</b><br> | 3142001223        | Blade, Fan           | 314 LP                         |
|   |                   | ø470 mm              | 316 LP                         |
|   |                   |                      | 398 LO 814                     |
|   |                   |                      | 688 1114                       |
|   |                   |                      | 688 709                        |
|   |                   |                      | 688 912                        |
|   |                   | 688 913              |                                |
| <b>TM07440</b><br> | 3522003523        | Blade, Fan           | 318 LP                         |
|   | 3442057106        | ø510 mm              | 344 L 1113                     |
|   | 3522052306        |                      | 344 L 1116                     |
|   | 3522050406        |                      | 344 L 1118                     |
|   |                   |                      | 344 LA 1113                    |
|   |                   |                      | 344 LAK 1113                   |
|   |                   |                      | 344 LAS 1113                   |



















| Model / Details  | Description  | Replaces Ref. No:        | TM No.  |
|--|--|--------------------------|---|
| 374 AXOR 2   | Blade, Fan<br>ø685 mm  | 0032052906               | <b>TM36642</b><br>   |
| 901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER<br>667 VARIO                                | Blade, Fan<br>For 200.192 and 200.196                                    | 0032050206               | <b>TM36643</b><br>   |
| -  | Blade, Fan<br>ø455 mm  | 6022000423               | <b>TM36644</b><br>   |
| 690 SPRINTER<br>901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER<br>905 SPRINTER<br>638 VITO | Blade, Fan<br>For 200.197 and 200.198<br>Repl. Hella: 8MV 376<br>733-281 | 1032000423               | <b>TM08046</b><br> |
| 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3                                     | Blade, Fan   | 5412050006               | <b>TM07918</b><br> |
| 979 ACCELO<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3   | Blade, Fan<br>For 200.164<br>Repl. Hella: 8MV 376<br>733-081<br>ø750 mm  | 0032050106               | <b>TM07920</b><br> |
| 979 ACCELO<br>375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>970 ATEGO 2               | Blade, Fan<br>For 200.171<br>Repl. Hella: 8MV 376<br>757-741<br>ø600 mm  | 9042050406<br>9042050206 | <b>TM07919</b><br> |





| TM No.  | Replaces Ref. No:        | Description   | Model / Details  |
|---|--------------------------|---|--|
| <b>TM07926</b>  | 9062050406               | Blade, Fan<br>For 200.169<br>Repl. Hella: 8MV 376<br>733-181<br>ø704 mm                         | 979 ACCELO<br>375 ACTROS<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>375 ATEGO 2                |
|    |                          |   |  |
| <b>TM07923</b>  | 0032053606               | Blade, Fan<br>For 200.189 and 200.166<br>Repl. Hella: 8MV 376<br>733-261<br>ø750 mm             | 979 ACCELO<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3     |
|    |                          |   |  |
| <b>TM07932</b>  | 9062050106               | Blade, Fan<br>For 200.169<br>ø654 mm  | 375 ACTROS<br>375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>958 ATEGO 2                 |
|    |                          |   |  |
| <b>TM07933</b>  | 9062050606               | Blade, Fan<br>ø704 mm   | -  |
|  |                          |   |  |
| <b>TM07968</b>  | 0032054506               | Blade, Fan<br>For 200.173, 200.189 and<br>200.166<br>Repl. Hella: 8MV 376<br>756-081<br>ø750 mm | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 |
|  |                          |   |  |
| <b>TM07921</b>  | 0032054206<br>0032053906 | Blade, Fan  | 979 ACCELO<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3     |
|  |                          |   |  |
| <b>TM08138</b>  | 4712050606               | Blade, Fan<br>Repl. Hella: 8MV 376<br>791-251   | 964 AROCS<br>963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS   |
|  |                          |   |  |



| Model / Details  | Description                | Replaces Ref. No:        | TM No.  |
|--|----------------------------|--------------------------|---|
| 668 VARIO  | Blade, Fan<br>For 041.401  | 6032000423               | <b>TM36645</b>  |
|  |                            |                          |    |
| 650 MK<br>651 MK<br>652 MK<br>653 MK<br>654 MK<br>615 NG<br>617 NG   | Rubber Ring, Fan           | 4422000195<br>4232000195 | <b>TM07854</b>  |
|  |                            |                          |    |
| 375 AXOR<br>374 AXOR 2<br>940 AXOR 2<br>942 AXOR 2<br>943 AXOR 2<br>944 AXOR 2<br>958 AXOR 2                           | Pulley, Fan                | 4572020210               | <b>TM07827</b>  |
|  |                            |                          |    |
| 357 O 405<br>612 O 405<br>671 O 345  | Pulley, Fan<br>ø64xø187x34 | 3575060210               | <b>TM07469</b>  |
|  |                            |                          |  |
| 906 SPRINTER   | Visco Fan                  | 0002008123               | <b>TM08102</b>  |
|  |                            |                          |  |
| 694 L 1218 R<br>694 L 1418 R<br>694 LK 1218 R<br>694 LK 1418 R<br>695 L 1620<br>695 L 1622 / L 1620<br>695 L 1622/1624 | Visco Fan                  | 9042000523               | <b>TM36646</b>  |
|  |                            |                          |  |
| 958 ATEGO 2<br>976 ATEGO 2<br>958 AXOR 2<br>695 L 1622 / L 1620<br>695 L 1622/1624<br>384 OF SERIES<br>693 1728        | Visco Fan                  | 9062001723<br>9062000723 | <b>TM36647</b>  |
|  |                            |                          |  |





| TM No.  | Replaces Ref. No:  | Description   | Model / Details  |
|---|--|---|--|
| <b>TM36648</b><br>   | 5412001222   | ViscoDrive, Fan<br>Electronic controlled<br>Repl. Hella: 8MV 376<br>757-461               | 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3                         |
| <b>TM36649</b><br>   | 4572000322S<br>4572000522S<br>4572000722S<br>4572000822S | Visco Drive, Fan<br>Converted to Mechanical<br>Type                                       | 375 AXOR<br>374 AXOR 2<br>940 AXOR 2<br>942 AXOR 2<br>943 AXOR 2<br>944 AXOR 2               |
| <b>TM07975</b><br>   | 0002008622<br>5412001122<br>5412001322<br>5412001522     | Visco Drive, Fan<br>Electronic controlled   | 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3                         |
| <b>TM07974</b><br> | 0002008522<br>5412000922                                 | Visco Drive, Fan<br>Electronic controlled   | 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3                         |
| <b>TM07882</b><br> | 0002007022<br>0002004222<br>0002004722<br>0002003522     | Visco Drive, Fan<br>For 200.160 and 200.161<br>Repl. Hella: 8MV 376<br>728-401<br>ø233 mm | 650 MK<br>652 MK<br>653 MK<br>654 MK<br>624 NG<br>625 SK<br>655 SK                           |
| <b>TM07972</b><br> | 0002006722<br>0002009022<br>0002909322                   | Visco Drive, Fan<br>For 200.174 and 200.179<br>Repl. Hella: 8MV 376<br>730-101<br>ø233 mm | 375 AXOR<br>374 AXOR 2<br>940 AXOR 2<br>942 AXOR 2<br>943 AXOR 2<br>944 AXOR 2<br>958 AXOR 2 |
| <b>TM07885</b><br> | 9062000822<br>9062000522<br>9062001822                   | Visco Drive, Fan<br>For 200.175 and 200.163<br>Repl. Hella: 8MV 376<br>731-351<br>ø203 mm | 979 ACCELO<br>375 ACTROS<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>958 ATEGO 2  |










| Model / Details  | Description  | Replaces Ref. No:  | TM No.  |
|--|--|--|---|
| 375 AXOR<br>374 AXOR 2<br>940 AXOR 2<br>942 AXOR 2<br>943 AXOR 2<br>944 AXOR 2<br>958 AXOR 2               | Visco Drive, Fan<br>With Pulley, For 200.166<br>ø233 mm                                    | 0002006722S1<br>4572020210S1                             | <b>TM36650</b><br>   |
| 979 ACCELO<br>375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>970 ATEGO 2                 | Visco Drive, Fan<br>For 200.162<br>ø165 mm   | 9042000822   | <b>TM07970</b><br>   |
| 673 LK/LN2<br>674 LK/LN2<br>682 1215<br>682 1214<br>682 1214 K<br>682 1414<br>682 1714                     | Visco Drive, Fan   | 3662000422   | <b>TM36651</b><br>   |
| 979 ACCELO<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3     | Visco Drive, Fan<br>For 200.179<br>Repl. Hella: 8MV 376<br>730-061                         | 0002008222<br>0002007422<br>0002004123<br>0002004422     | <b>TM36652</b><br> |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 | Visco Drive, Fan<br>Converted to Mechanical<br>Type  | 5412000622S<br>5412000422S<br>5412000322S<br>5412000222S | <b>TM36653</b><br> |
| 375 AXOR<br>374 AXOR 2<br>940 AXOR 2<br>942 AXOR 2<br>943 AXOR 2<br>944 AXOR 2                             | Visco Drive, Fan<br>For 200.174 and 200.179<br>Repl. Hella: 8MV 376<br>734-371             | 0002007722   | <b>TM08098</b><br> |
| 901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER<br>667 VARIO                                  | Visco Drive, Fan<br>For 200.152, 200.153 and<br>200.181<br>Repl. Hella: 8MV 376<br>732-061 | 0002005122   | <b>TM08090</b><br> |







| TM No.  | Replaces Ref. No: | Description              | Model / Details |
|---|-------------------|--------------------------|-----------------|
| <b>TM07973</b><br>   | 9042000322        | Visco Drive, Fan         | 970 ATEGO 2     |
|   | 9042000922        | Repl. Hella: 8MV 376     | 668 VARIO       |
|   | 9042001122        | 732-051                  | 670 VARIO       |
|   |                   |                          |                 |
| <b>TM36654</b><br>   | 6162000322        | Visco Drive, Fan         | 611 T1/TN       |
|   | 0002002022        | Repl. Hella: 8MV 376     | 601 207 D/208 D |
|   |                   | 731-131                  | 601 208/210     |
|   |                   |                          | 602 307 D/308 D |
|   |                   |                          | 602 307 D/308D  |
|   |                   |                          | 602 308 D       |
|   |                   |                          | 602 308/310     |
| <b>TM08088</b><br>  | 0002003722        | Visco Drive, Fan         | 901 SPRINTER    |
|   |                   | For 200.152, 200.153 and | 902 SPRINTER    |
|   |                   | 200.181                  | 903 SPRINTER    |
|   |                   | Repl. Hella: 8MV 376     | 904 SPRINTER    |
|   |                   | 732-071                  | 667 VARIO       |
| <b>TM08086</b><br> | 0002005822        | Visco Drive, Fan         | 690 SPRINTER    |
|   |                   | For 200.199              | 901 SPRINTER    |
|   |                   | Repl. Hella: 8MV 376     | 902 SPRINTER    |
|   |                   | 758-441                  | 903 SPRINTER    |
|   |                   |                          | 904 SPRINTER    |
|   |                   |                          | 905 SPRINTER    |
|   |                   |                          | 638 VITO        |
| <b>TM08089</b><br> | 0002003822        | Visco Drive, Fan         | 901 SPRINTER    |
|   |                   | For 200.152              | 902 SPRINTER    |
|   |                   | Repl. Hella: 8MV 376     | 903 SPRINTER    |
|   |                   | 732-491                  | 904 SPRINTER    |
|   |                   |                          | 667 VARIO       |
| <b>TM08141</b><br> | 6022000122        | Visco Drive, Fan         | 611 T1/TN       |
|   | 6032000522        | For 200.203              | 601 209 D/210 D |
|   |                   | Repl. Hella: 8MV 376     | 602 309 D/310 D |
|   |                   | 732-481                  | 602 310 D       |
|   |                   |                          | 631 O 100 CITY  |
|   |                   |                          | 668 VARIO       |
| <b>TM36655</b><br> | 6032000022        | Visco Drive, Fan         | BM MODEL        |
|   |                   | Repl. Hella: 8MV 376     | 668 VARIO       |
|   |                   | 732-251                  |                 |
|   |                   |                          |                 |












| Model / Details  | Description   | Replaces Ref. No:                                    | TM No.  |
|--|---|--|---|
| -  | Visco Drive, Fan<br>Repl. Hella: 8MV 376<br>757-321       | 6042000022   | <b>TM36656</b><br>   |
| -  | Visco Drive, Fan<br>Repl. Hella: 8MV 376<br>732-121       | 0002000422   | <b>TM36657</b><br>   |
| 619 NG<br>621 NG<br>624 NG<br>655 SK<br>371 1922 K OTOMARSAN/<br>TUERKEI<br>371 2622/6X2/48<br>OTOMARSAN/TUERKEI | Support, Fan<br>ø74x77/146                                | 4032000926   | <b>TM07840</b><br>   |
| 375 AXOR<br>374 AXOR 2<br>940 AXOR 2<br>942 AXOR 2<br>943 AXOR 2<br>944 AXOR 2<br>958 AXOR 2                     | Belt Tensioner, Fan<br>Repl. Dayco: APV2821<br>ø74x42,5   | 4572004070<br>4572002270                             | <b>TM07980</b><br> |
| 979 ACCELO<br>375 ACTROS<br>375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO                        | Belt Tensioner, Fan<br>Repl. Dayco: APV1055<br>ø74x34     | 9062002070<br>9062001770<br>9062000270<br>9062001470 | <b>TM07878</b><br> |
| 375 ACTROS<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>970 ATEGO 2<br>972 ATEGO 2                     | Belt Tensioner, Fan<br>Repl. Dayco: APV1105<br>ø74x39     | 9062001870<br>9062001570<br>9062000570<br>4572002370 | <b>TM07577</b><br> |
| 375 ACTROS<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>958 ATEGO 2<br>970 ATEGO 2                     | Belt Tensioner, Fan<br>Repl. Dayco: APV1110<br>ø81,3x32,9 | 9062002670   | <b>TM07580</b><br> |












| TM No.  | Replaces Ref. No: | Description                         | Model / Details   |
|---|-------------------|-------------------------------------|---|
| <b>TM07953</b><br>   | 0002001570        | Belt Tensioner, Fan                 | 375 ACTROS  |
|   | 0002001070        | Repl. Dayco: APV2803<br>ø70,2x34,64 | 950 ACTROS<br>952 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>934 ACTROS 2/3                            |
| <b>TM07575</b><br>   | 9062004670        | Belt Tensioner, Fan                 | 979 ACCELO  |
|   | 9062001270        | Repl. Dayco: APV1102                | 375 ACTROS  |
|   | 9062000370        | ø74x35,5                            | 375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO   |
| <b>TM07572</b><br>   | 5412002370        | Belt Tensioner, Fan                 | 979 ACCELO  |
|   | 5412001670        | Repl. Dayco: APV1098                | 950 ACTROS  |
|   | 5412000470        | ø74x46,3                            | 952 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3  |
| <b>TM36658</b><br> | 4572003670S       | Belt Tensioner, Fan                 | 634 O 500   |
|   | 4572001670S       | Repl. Dayco: APV1094<br>ø74x38,3    | 634 O 500 RSD /<br>2736/8X2/30<br>634 TOURO<br>613 TOURISMO<br>634 IBC 1836 / OC 500 RF<br>634 IBC 1842<br>634 IBC 2242 |
| <b>TM07571</b><br> | 5412001570        | Belt Tensioner, Fan                 | 979 ACCELO  |
|   | 5412000870        | Repl. Dayco: APV1097<br>ø74x34      | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3                                |
| <b>TM07559</b><br> | 4572002170        | Belt Tensioner, Fan                 | 944 AXOR 2  |
|   | 4572001570        | Repl. Dayco: APV2451                | 386 LS 1625   |
|   | 4572000170        | 80x33,5                             | 671 CONECTO<br>634 CBC - FAHRGESTELL<br>2-ACHSER<br>634 IBC FAHRGESTELL<br>2-ACHSER                                     |
| <b>TM07569</b><br> | 4572003470        | Belt Tensioner, Fan                 | 696 L 1938  |
|   | 4572001770        | Repl. Dayco: APV1095                | 696 L 2638  |
|   | 4572000070        | ø74x38,3                            | 696 LK 2638<br>696 LS 1938<br>696 LS 2638<br>693 1938<br>693 1938 S   |

| <i>Model / Details</i>   | <i>Description</i>                                       | <i>Replaces Ref. No:</i>                             | <i>TM No.</i>   |
|--|--|--|---|
| 375 AXOR<br>374 AXOR 2<br>940 AXOR 2<br>942 AXOR 2<br>943 AXOR 2<br>944 AXOR 2<br>958 AXOR 2               | Belt Tensioner, Fan<br>Repl. Dayco: APV2446<br>ø78x42    | 4572002970<br>4572004370<br>4572003170<br>4572004570 | <b>TM07977</b><br>   |
| 979 ACCELO<br>375 ACTROS<br>375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO                  | Belt Tensioner, Fan<br>Repl. Dayco: APV2817<br>ø78x32,71 | 9062005970<br>9062004570<br>9062003770               | <b>TM07576</b><br>   |
| 382 OH SERIES<br>382 O 500<br>634 O 500<br>634 O 500 RSD /<br>2736/8X2/30                                  | Belt Tensioner, Fan<br>Repl. Dayco: APV2816<br>ø75x37    | 4572003270<br>4572002770<br>9042000370<br>5412000970 | <b>TM07956</b><br>  |
| 979 ACCELO<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3     | Belt Tensioner, Fan<br>ø80x45                            | 5412001070<br>5412000370                             | <b>TM07601</b><br> |
| 979 ACCELO<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3     | Belt Tensioner, Fan<br>Repl. Dayco: APV2458<br>ø80x48    | 5412001870<br>5412002470<br>5412002570<br>5412001170 | <b>TM36659</b><br> |
| 979 ACCELO<br>690 SPRINTER<br>901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER<br>905 SPRINTER | Belt Tensioner, Fan<br>Repl. Dayco: APV2232<br>ø70x28    | 6112000570<br>6462000270                             | <b>TM08015</b><br> |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 | Belt Tensioner, Fan<br>Repl. Dayco: APV2462<br>ø80x47    | 5412003470<br>5412001370<br>5412002270               | <b>TM07915</b><br> |



| TM No.  | Replaces Ref. No:        | Description                       | Model / Details   |
|---|--------------------------|-----------------------------------|---|
| <b>TM07570</b><br>   | 4572001970               | Belt Tensioner, Fan               | 375 AXOR  |
|   | 4602000970               | Repl. Dayco: APV1096<br>ø80x34    | 374 AXOR 2<br>940 AXOR 2<br>942 AXOR 2<br>943 AXOR 2<br>944 AXOR 2<br>958 AXOR 2        |
| <b>TM07916</b><br>   | 9062000670               | Belt Tensioner, Fan               | 979 ACCELO  |
|   |                          | Repl. Dayco: APV1101<br>ø74x39    | 375 ACTROS<br>375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO             |
| <b>TM07579</b><br>   | 9062002470               | Belt Tensioner, Fan               | 970 ATEGO   |
|   | 9062003170               | Repl. Dayco: APV1109<br>ø74x34    | 972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>970 ATEGO 2<br>972 ATEGO 2<br>974 ATEGO 2        |
| <b>TM07574</b><br> | 9042000070               | Belt Tensioner, Fan               | 375 ATEGO   |
|   |                          | Repl. Dayco: APV1100<br>74x39     | 970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>970 ATEGO 2<br>972 ATEGO 2          |
| <b>TM07979</b><br> | 9062002370               | Belt Tensioner, Fan               | 375 ATEGO   |
|   | 9062001670<br>9062000770 | Repl. Dayco: APV1108<br>ø90x34    | 970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>958 ATEGO 2<br>970 ATEGO 2          |
| <b>TM07981</b><br> | 9062001370               | Belt Tensioner, Fan               | 958 ATEGO 2   |
|   | 9062000970               | Repl. Dayco: APV1104<br>81,3x32,9 | 952 AXOR 2<br>957 ECONIC<br>693 2423B/ 6X4<br>693 2423K/ 6X4<br>382 O 500 R / 1830 / 30 |
| <b>TM07976</b><br> | 4572003070               | Belt Tensioner, Fan               | 375 AXOR  |
|   | 4572004270<br>4572004470 | ø78,5x34                          | 374 AXOR 2<br>940 AXOR 2<br>942 AXOR 2<br>943 AXOR 2<br>944 AXOR 2<br>958 AXOR 2        |



| Model / Details  | Description   | Replaces Ref. No:                      | TM No.  |
|--|---|--|---|
| 375 ACTROS<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>375 ATEGO 2<br>958 ATEGO 2 | Belt Tensioner, Fan<br>Repl. Dayco: APV2824<br>ø75x40 | 9062004370                             | <b>TM07954</b><br>   |
| -  | Belt Tensioner, Fan<br>Repl. Dayco: APV2275<br>ø65x30 | 6112000670<br>6462000070<br>6462000470 | <b>TM08126</b><br>   |
| 00 SPRINTER<br>906 SPRINTER<br>636 VIANO<br>639 VIANO  | Belt Tensioner, Fan<br>Repl. Dayco: APV3182<br>ø65x26 | 6512001270                             | <b>TM08074</b><br>   |
| 900 SPRINTER<br>906 SPRINTER<br>636 VIANO<br>639 VIANO                                       | Belt Tensioner, Fan<br>Repl. Dayco: APV2982<br>ø65x26 | 6512000470<br>6512001870               | <b>TM08075</b><br> |
| 375 ACTROS<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>375 ATEGO 2<br>958 ATEGO 2 | Belt Tensioner, Fan<br>Repl. Dayco: APV1093           | 4572000270<br>4572001470               | <b>TM07567</b><br> |
| 979 ACCELO<br>375 ACTROS<br>375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO    | Belt Tensioner, Fan<br>Repl. Dayco: APV1107           | 9042000170<br>9062002270               | <b>TM07578</b><br> |
| 979 ACCELO<br>375 ACTROS<br>375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO    | Belt Tensioner, Fan<br>Repl. Dayco: APV1130           | 4602000770                             | <b>TM07957</b><br> |







| TM No.  | Replaces Ref. No:          | Description                                      | Model / Details  |
|---|----------------------------|--|--|
| <b>TM07978</b>  | 9062003970                 | Belt Tensioner, Fan<br>Repl. Dayco: APV2820      | 375 ACTROS<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>375 ATEGO 2<br>970 ATEGO 2               |
|    |                            |  |  |
| <b>TM07962</b>  | 0005501333                 | Tension Roller, Fan<br>Repl. Dayco: APV2455      | 375 AXOR<br>374 AXOR 2<br>940 AXOR 2<br>942 AXOR 2<br>943 AXOR 2<br>944 AXOR 2<br>634 TOURO                |
|    |                            |  |  |
| <b>TM36660</b>  | 0005501833<br>4572001370   | Tension Roller, Fan                              | 979 ACCELO<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3     |
|   |                            |  |  |
| <b>TM08006</b>  | 0005501233<br>0005502233   | Tension Roller, Fan<br>Repl. Dayco: APV2452      | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 |
|  |                            |  |  |
| <b>TM36661</b>  | 1032000570                 | Tension Roller, Fan<br>Repl. Dayco: APV2087      | 408 UNIMOG<br>667 VARIO  |
|  |                            |  |  |
| <b>TM36662</b>  | 4572001970S<br>4602000970S | Tension Roller, Fan<br>For 202.052<br>ø20xø80x34 | 375 AXOR<br>374 AXOR 2<br>940 AXOR 2<br>942 AXOR 2<br>943 AXOR 2<br>944 AXOR 2<br>958 AXOR 2               |
|  |                            |  |  |
| <b>TM08110</b>  | 6422000670                 | Tension Roller, Fan<br>Repl. Dayco: APV3002      | 906 SPRINTER   |
|  |                            |  |  |





| Model / Details  | Description                                 | Replaces Ref. No:                         | TM No.  |
|--|---|---|---|
| 900 SPRINTER<br>906 SPRINTER<br>636 VIANO<br>639 VIANO   | Tension Roller, Fan<br>Repl. Dayco: APV2829 | 6512000270                                | <b>TM08095</b>  |
|  |   |   |    |
| 900 SPRINTER<br>906 SPRINTER<br>636 VIANO<br>639 VIANO   | Tension Roller, Fan                         | 6512000670                                | <b>TM08096</b>  |
|  |   |   |    |
| 900 SPRINTER<br>906 SPRINTER<br>636 VIANO<br>639 VIANO   | Tension Roller, Fan                         | 6512000770                                | <b>TM08097</b>  |
|  |   |   |    |
| -  | Tension Roller, Fan<br>For 204.039          | 6112000670S<br>6462000070S<br>6462000470S | <b>TM36663</b>  |
|  |   |   |  |
| 611 T1/TN<br>601 207 D/208 D<br>601 209 D/210 D<br>602 307 D/308 D<br>602 307 D/308D<br>602 308 D<br>602 309 D/310 D | Tension Roller, Fan<br>ø8,3/ø14,6xø64x22    | 6012001070                                | <b>TM08080</b>  |
|  |   |   |  |
| 901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER<br>905 SPRINTER<br>906 SPRINTER<br>909 SPRINTER         | Tension Roller, Fan<br>ø17xø64x22,7         | 0002020919<br>0002020019                  | <b>TM07830</b>  |
|  |   |   |  |
| 611 T1/TN<br>408 UNIMOG<br>601 207 D/208 D<br>601 208/210<br>601 209 D/210 D<br>602 307 D/308 D<br>602 307 D/308D    | Tension Roller, Fan<br>ø8,3/ø14,6xø70x22    | 6012000770                                | <b>TM08094</b>  |
|  |   |   |  |



| TM No.  | Replaces Ref. No:  | Description                                | Model / Details   |
|---|--|--|---|
| <b>TM08093</b><br>   | 6612003070S<br>6012000970                                | Tension Roller, Fan<br>ø8,3/ø14,6xø80x31,5 | 611 T1/TN<br>408 UNIMOG<br>601 207 D/208 D<br>601 208/210<br>601 209 D/210 D<br>602 307 D/308 D<br>602 307 D/308D |
| <b>TM08008</b><br>   | 6112340193<br>6112340293                                 | Tension Roller, Fan<br>ø10,2xø119x22,7     | 979 ACCELO<br>900 SPRINTER<br>901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER<br>905 SPRINTER        |
| <b>TM07583</b><br>   | 0005500433   | Tension Roller, Fan<br>ø10,3xø79,5x44      | 375 ACTROS<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>375 ATEGO 2<br>958 ATEGO 2                      |
| <b>TM07960</b><br> | 0005501733<br>0005502533<br>0005502433<br>0005501633     | Tension Roller, Fan<br>ø10,3xø79,5x48      | 375 ACTROS<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>375 ATEGO 2<br>958 ATEGO 2                      |
| <b>TM07964</b><br> | 0005501933<br>4572001070                                 | Tension Roller, Fan<br>ø20xø74x38          | 375 AXOR<br>374 AXOR 2<br>940 AXOR 2<br>942 AXOR 2<br>943 AXOR 2<br>944 AXOR 2<br>958 AXOR 2                      |
| <b>TM07958</b><br> | 0005500633   | Tension Roller, Fan<br>ø10,3xø79,5x33      | 375 ACTROS<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>958 ATEGO 2<br>970 ATEGO 2                      |
| <b>TM36664</b><br> | 9062002070S<br>9062001770S<br>9062001470S<br>9062000270S | Tension Roller, Fan<br>For 200.029         | 979 ACCELO<br>375 ACTROS<br>375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO                         |



| Model / Details   | Description                                      | Replaces Ref. No:  | TM No.  |
|---|--|--|---|
| 375 ACTROS<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>375 ATEGO 2<br>958 ATEGO 2  | Tension Roller, Fan<br>For 200.028<br>ø20xø74x47 | 4572002270S<br>4572004070S                               | <b>TM36665</b><br>   |
| 375 AXOR<br>374 AXOR 2<br>940 AXOR 2<br>942 AXOR 2<br>943 AXOR 2<br>944 AXOR 2<br>958 AXOR 2  | Tension Roller, Fan<br>For 200.039<br>ø17xø78x42 | 4572003170S<br>4572002970S<br>4572004370S<br>4572004570S | <b>TM36666</b><br>   |
| 375 AXOR<br>374 AXOR 2<br>940 AXOR 2<br>942 AXOR 2<br>943 AXOR 2<br>944 AXOR 2<br>958 AXOR 2  | Tension Roller, Fan<br>ø17xø77x34                | 4572003070S  | <b>TM36667</b><br>  |
| 634 TOURO<br>613 TOURISMO<br>634 IBC 1836 / OC 500 RF<br>634 IBC 1842<br>634 IBC 2242<br>634 IBC FAHRGESTELL<br>2-ACHSER<br>634 IBC FAHRGESTELL<br>3-ACHSER | Tension Roller, Fan<br>ø30xø75x37                | 4572002070S  | <b>TM36668</b><br> |
| 979 ACCELO<br>375 ACTROS<br>375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO   | Tension Roller, Fan<br>For 200.040<br>ø75x33     | 9062004570S  | <b>TM36669</b><br> |
| 650 MK<br>659 SK<br>356 O 404<br>671 O 345<br>613 TOURISMO<br>634 IBC 1836 / OC 500 RF<br>634 IBC 1842  | Tension Roller, Fan<br>ø10xø95x50                | 0005500033<br>0005500333                                 | <b>TM07582</b><br> |
| 650 MK<br>621 NG<br>656 SK<br>659 SK<br>356 O 404<br>613 TOURISMO   | Tension Roller, Fan                              | 4422000770   | <b>TM07581</b><br> |



| TM No.  | Replaces Ref. No:          | Description                        | Model / Details  |
|---|----------------------------|------------------------------------|--|
| <b>TM07860</b><br>   | 4072000670                 | Tension Roller, Fan                | 397 OF SERIES<br>397 1924 S MBSA-RSA<br>307 O 305<br>307 O 307<br>671 O 345                                |
| <b>TM07573</b><br>   | 5412020319<br>5412020219   | Tension Roller, Fan                | 979 ACCELO<br>950 ACTROS<br>952 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 |
| <b>TM08007</b><br>   | 5412001470                 | Tension Roller, Fan                | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 |
| <b>TM07955</b><br> | 9062000470<br>9062001170   | Tension Roller, Fan                | 979 ACCELO<br>375 ACTROS<br>375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO                  |
| <b>TM07963</b><br> | 9062004470<br>9062003370   | Tension Roller, Fan                | 375 ACTROS<br>375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>375 ATEGO 2                 |
| <b>TM36670</b><br> | 4572004270S<br>4572004470S | Tension Roller, Fan<br>For 202.281 | 375 AXOR<br>374 AXOR 2<br>940 AXOR 2<br>942 AXOR 2<br>943 AXOR 2<br>944 AXOR 2<br>958 AXOR 2               |
| <b>TM07894</b><br> | 6205050355                 | Shroud, Fan                        | 620 NG<br>621 NG<br>622 NG<br>623 NG<br>624 NG<br>645 NG<br>646 NG   |



| Model / Details  | Description                    | Replaces Ref. No: | TM No.         |
|--|--------------------------------|-------------------|----------------|
| 651 MK<br>652 MK<br>653 MK<br>654 MK<br>625 SK<br>655 SK<br>656 SK   | Shroud, Fan                    | 6525050855        | <b>TM07969</b> |
| 906 SPRINTER   | Shroud, Fan                    | 9065050455        | <b>TM36671</b> |
| 900 SPRINTER<br>906 SPRINTER   | Shroud, Fan<br>470x628,5x739,5 | 9065050855        | <b>TM36672</b> |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3   | Shroud, Fan                    | 9425050955        | <b>TM07941</b> |
| 611 T1/TN<br>601 209 D/210 D<br>602 309 D/310 D<br>602 310 D   | -Shroud, Fan                   | 6015051655        | <b>TM36673</b> |
| 901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER   | Shroud, Fan                    | 9015050655        | <b>TM36674</b> |
| 690 SPRINTER<br>901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER<br>905 SPRINTER<br>909 SPRINTER | Shroud, Fan                    | 9015051655        | <b>TM36675</b> |





| TM No.  | Replaces Ref. No: | Description                | Model / Details  |
|---|-------------------|----------------------------|--|
| <b>TM36676</b><br>   | 9065050155        | Shroud, Fan<br>470x630x735 | 906 SPRINTER   |
| <b>TM36677</b><br>   | 6565050255        | Shroud, Fan                | 655 SK<br>656 SK<br>657 SK<br>658 SK<br>659 SK<br>397 2644 S/6X4   |
| <b>TM36678</b><br>   | 9425051255        | Shroud, Fan                | 930 ACTROS 2/3<br>934 ACTROS 2/3   |
| <b>TM36679</b><br> | 6745050330        | Shroud, Fan                | 397 LP 1114,1214 MB-SA-RSA<br>397 LP 1214 A MBSA-RSA<br>397 LP/LPK 1314 MB-SA-RSA<br>397 LPK 1414 MBSA-RSA<br>674 LK/LN2<br>675 LK/LN2<br>678 LK/LN2 |
| <b>TM36680</b><br> | 6205050555        | Shroud, Fan                | 620 NG<br>621 NG<br>622 NG<br>623 NG<br>624 NG   |
| <b>TM07940</b><br> | 9425050455        | Shroud, Fan                | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3   |
| <b>TM07939</b><br> | 9425050555        | Shroud, Fan                | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3   |





| Model / Details   | Description  | Replaces Ref. No: | TM No.  |
|---|--|-------------------|---|
| 375 AXOR<br>374 AXOR 2<br>940 AXOR 2<br>942 AXOR 2<br>943 AXOR 2<br>944 AXOR 2<br>958 AXOR 2                    | Shroud, Fan  | 9405000055        | <b>TM36681</b>  |
|   |  |                   |    |
| 375 ACTROS<br>375 AXOR<br>374 AXOR 2<br>375 AXOR 2<br>950 AXOR 2<br>952 AXOR 2<br>953 AXOR 2                    | Shroud, Fan  | 9405050255        | <b>TM36682</b>  |
|   |  |                   |    |
| 906 SPRINTER  | Shroud, Fan  | 9065050955        | <b>TM36683</b>  |
|   |  |                   |    |
| 979 ACCELO<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3          | Flange, Fan<br>ø182xø167x139,5                       | 5410350214        | <b>TM07942</b>  |
|   |  |                   |  |
| 611 T1/TN<br>408 UNIMOG<br>601 207 D/208 D<br>601 209 D/210 D<br>602 307 D/308 D<br>602 307 D/308D<br>602 308 D | Tensioner Lever, Fan                                 | 6012001773        | <b>TM36684</b>  |
|   |  |                   |  |
| 408 UNIMOG<br>901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER<br>667 VARIO<br>668 VARIO            | Tensioner Lever, Fan                                 | 6062000073        | <b>TM08083</b>  |
|   |  |                   |  |
| 408 UNIMOG<br>901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER<br>667 VARIO<br>668 VARIO            | Tensioner Lever, Fan<br>With Repair Kit<br>95x68x140 | 6062000073S       | <b>TM36685</b>  |
|   |  |                   |  |





| TM No.  | Replaces Ref. No:        | Description                       | Model / Details  |
|---|--------------------------|-----------------------------------|--|
| <b>TM25322</b>  | 0149975492               | Multi Ribbet Belt, Fan<br>10x2020 | -  |
|    |                          |                                   |  |
| <b>TM08333</b>  | 9069937196               | Multi Ribbet Belt, Fan<br>8x1427  | 368 OH SERIES<br>375 AXOR<br>375 ACTROS<br>375 AXOR 2<br>950 AXOR 2<br>952 AXOR 2<br>954 AXOR 2<br>958 ATEGO 2         |
|    |                          |                                   |  |
| <b>TM08381</b>  | 0019930496<br>6019970592 | Multi Ribbet Belt, Fan<br>6x997   | 613 TOURISMO<br>932 ACTROS 2/3<br>934 ACTROS 2/3<br>940 AXOR 2<br>942 AXOR 2<br>943 AXOR 2<br>944 AXOR 2<br>950 ACTROS |
|    |                          |                                   |  |
| <b>TM08354</b>  | 0149976492               | Multi Ribbet Belt, Fan<br>6x1380  | 613 TOURISMO<br>932 ACTROS 2/3<br>934 ACTROS 2/3<br>940 AXOR 2<br>942 AXOR 2<br>943 AXOR 2<br>944 AXOR 2<br>950 ACTROS |
|  |                          |                                   |  |
| <b>TM07847</b>  | 0019933796               | Multi Ribbet Belt, Fan<br>6x1412  | 906 SPRINTER<br>906 SPRINTER   |
|  |                          |                                   |  |
| <b>TM08323</b>  | 9069971792               | Multi Ribbet Belt, Fan<br>8x1150  | 405 UNIMOG<br>405 UNIMOG<br>668 VARIO<br>670 VARIO   |
|  |                          |                                   |  |
| <b>TM08319</b>  | 9069971492<br>9069935196 | Multi Ribbet Belt, Fan<br>8x1175  | 368 OH SERIES<br>670 VARIO<br>668 VARIO<br>676 LK/LN2<br>970 ATEGO 2<br>970 ATEGO<br>972 ATEGO 2<br>972 ATEGO          |
|  |                          |                                   |  |



| Model / Details  | Description                      | Replaces Ref. No:        | TM No.  |
|--|----------------------------------|--------------------------|---|
| 368 OH SERIES<br>375 AXOR<br>375 ACTROS<br>375 AXOR 2<br>949 ZETROS<br>950 AXOR 2<br>952 AXOR 2<br>953 AXOR 2    | Multi Ribbet Belt, Fan<br>8x1190 | 9069971392<br>9069934996 | <b>TM25286</b><br>   |
| 436 UNIMOG<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>970 ATEGO 2<br>970 ATEGO<br>972 ATEGO 2    | Multi Ribbet Belt, Fan<br>8x1205 | 9069931696<br>0009938196 | <b>TM08307</b><br>   |
| 930 ACTROS 2/3<br>953 ACTROS<br>954 ACTROS<br>979 ACCELO   | Multi Ribbet Belt, Fan<br>8x1215 | 0029932496<br>5419972892 | <b>TM25249</b><br>  |
| 368 OH SERIES<br>979 ACCELO<br>670 VARIO<br>668 VARIO<br>405 UNIMOG<br>436 UNIMOG<br>437 UNIMOG<br>374 AXOR 2    | Multi Ribbet Belt, Fan<br>8x1370 | 9069933996               | <b>TM25281</b><br> |
| -  | Multi Ribbet Belt, Fan<br>8x1376 | 9069937996               | <b>TM24725</b><br> |
| 368 OH SERIES<br>976 ATEGO<br>979 ACCELO<br>670 VARIO<br>374 AXOR 2<br>375 ATEGO<br>375 AXOR<br>375 ACTROS       | Multi Ribbet Belt, Fan<br>8x1390 | 0009934296<br>9069934296 | <b>TM25295</b><br> |
| 368 OH SERIES<br>958 ATEGO 2<br>970 ATEGO 2<br>970 ATEGO<br>972 ATEGO 2<br>972 ATEGO<br>974 ATEGO 2<br>975 ATEGO | Multi Ribbet Belt, Fan<br>8x1412 | 0019930296<br>9049970392 | <b>TM25279</b><br> |





| TM No.  | Replaces Ref. No:                                    | Description                      | Model / Details   |
|---|--|----------------------------------|---|
| <b>TM24641</b><br>   | 9069972492   | Multi Ribbet Belt, Fan<br>8x1420 | 368 OH SERIES<br>374 AXOR 2<br>375 ATEGO<br>375 AXOR<br>375 ACTROS<br>375 AXOR 2<br>670 VARIO<br>950 AXOR 2       |
| <b>TM25283</b><br>   | 9069970892<br>0009934496                             | Multi Ribbet Belt, Fan<br>8x1448 | 368 OH SERIES<br>950 AXOR 2<br>952 AXOR 2<br>954 AXOR 2<br>958 ATEGO 2<br>970 ATEGO 2<br>970 ATEGO<br>972 ATEGO 2 |
| <b>TM07265</b><br>   | 9069970792   | Multi Ribbet Belt, Fan<br>8x1480 | 368 OH SERIES<br>375 AXOR<br>375 ACTROS<br>952 AXOR 2<br>953 AXOR 2<br>954 AXOR 2<br>972 ATEGO 2<br>976 ATEGO     |
| <b>TM24642</b><br> | 0139976092   | Multi Ribbet Belt, Fan<br>8x1580 | 693 1938<br>693 1944 S<br>693 1938 S  |
| <b>TM24643</b><br> | 0159973292<br>0159971192<br>0149977892<br>0019932596 | Multi Ribbet Belt, Fan<br>8x1610 | 374 AXOR 2<br>375 AXOR<br>940 AXOR 2<br>942 AXOR 2<br>943 AXOR 2<br>944 AXOR 2<br>958 AXOR 2                      |
| <b>TM07096</b><br> | 9369932296<br>9269930596<br>9069939696<br>9069936796 | Multi Ribbet Belt, Fan<br>8x1635 | 976 ATEGO 2<br>374 AXOR 2<br>375 AXOR<br>375 ACTROS<br>375 AXOR 2<br>975 ATEGO<br>975 ATEGO 2                     |
| <b>TM08329</b><br> | 9069976792   | Multi Ribbet Belt, Fan<br>8x1730 | 368 OH SERIES<br>634 O 500<br>952 AXOR 2<br>958 ATEGO 2<br>957 ECONIC<br>685 TOURINO<br>972 ATEGO 2<br>970 ATEGO  |



| Model / Details  | Description                      | Replaces Ref. No:        | TM No.  |
|--|----------------------------------|--------------------------|---|
| 368 OH SERIES<br>375 AXOR<br>375 ACTROS<br>375 AXOR 2<br>954 AXOR 2<br>970 ATEGO 2<br>970 ATEGO                | Multi Ribbet Belt, Fan<br>8x1740 | 9069932796               | <b>TM25280</b><br>   |
| 976 ATEGO 2<br>958 AXOR 2<br>384 OF SERIES<br>368 OH SERIES<br>382 OH SERIES<br>382 O 500<br>634 O 500         | Multi Ribbet Belt, Fan<br>8x1780 | 9069934396               | <b>TM25254</b><br>   |
| 970 ATEGO<br>972 ATEGO<br>970 ATEGO 2<br>972 ATEGO 2<br>974 ATEGO 2<br>976 ATEGO 2<br>436 UNIMOG<br>437 UNIMOG | Multi Ribbet Belt, Fan<br>8x1795 | 9069938996               | <b>TM25297</b><br>  |
| 375 ACTROS<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>958 ATEGO 2<br>970 ATEGO 2<br>972 ATEGO 2    | Multi Ribbet Belt, Fan<br>8x1850 | 0009939996<br>9069973192 | <b>TM07048</b><br> |
| 375 ACTROS<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>958 ATEGO 2<br>970 ATEGO 2<br>972 ATEGO 2    | Multi Ribbet Belt, Fan<br>8x1910 | 9069972892               | <b>TM25289</b><br> |
| 979 ACCELO<br>375 ACTROS<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>958 ATEGO 2<br>970 ATEGO 2     | Multi Ribbet Belt, Fan<br>8x1940 | 9069973592<br>9069934096 | <b>TM07097</b><br> |
| 979 ACCELO<br>375 ACTROS<br>375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>958 ATEGO 2       | Multi Ribbet Belt, Fan<br>8x1955 | 9069937496               | <b>TM07098</b><br> |





| <i>TM No.</i>   | <i>Replaces Ref. No:</i> | <i>Description</i>               | <i>Model / Details</i>   |
|---|--------------------------|----------------------------------|--|
| <b>TM07658</b><br>   | 9069973292<br>0009934696 | Multi Ribbet Belt, Fan<br>8x1985 | 958 ATEGO 2<br>952 AXOR 2<br>957 ECONIC  |
| <b>TM08320</b><br>   | 9069971292<br>9069934696 | Multi Ribbet Belt, Fan<br>8x2000 | 979 ACCELO<br>375 ACTROS<br>375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>970 ATEGO 2     |
| <b>TM08335</b><br>   | 9069973792               | Multi Ribbet Belt, Fan<br>8x2020 | 979 ACCELO<br>390 OH SERIES  |
| <b>TM25285</b><br> | 9069971092               | Multi Ribbet Belt, Fan<br>8x2063 | 979 ACCELO<br>375 ACTROS<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>958 ATEGO 2<br>970 ATEGO 2   |
| <b>TM08284</b><br> | 9069971192               | Multi Ribbet Belt, Fan<br>8x2080 | 979 ACCELO<br>375 ACTROS<br>375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>958 ATEGO 2     |
| <b>TM08337</b><br> | 9069932496               | Multi Ribbet Belt, Fan<br>8x2497 | 970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>958 ATEGO 2<br>970 ATEGO 2<br>972 ATEGO 2<br>974 ATEGO 2 |
| <b>TM08325</b><br> | 9069974192               | Multi Ribbet Belt, Fan<br>8x2515 | 375 ACTROS<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>970 ATEGO 2<br>972 ATEGO 2<br>974 ATEGO 2  |





| Model / Details  | Description                      | Replaces Ref. No:                                    | TM No.  |
|--|----------------------------------|--|---|
| 979 ACCELO<br>375 ACTROS<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>958 ATEGO 2<br>970 ATEGO 2               | Multi Ribbet Belt, Fan<br>8x2560 | 9069973692   | <b>TM08324</b><br>   |
| 979 ACCELO<br>375 ACTROS<br>375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>958 ATEGO 2                 | Multi Ribbet Belt, Fan<br>8x2604 | 9069970992   | <b>TM25284</b><br>   |
| -  | Multi Ribbet Belt, Fan<br>9x1691 | 0009938496   | <b>TM08338</b><br>   |
| 375 ACTROS<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>375 ATEGO 2<br>958 ATEGO 2<br>970 ATEGO 2              | Multi Ribbet Belt, Fan<br>9x1725 | 0019935796<br>0129976092<br>0009937496               | <b>TM07253</b><br> |
| 979 ACCELO<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 | Multi Ribbet Belt, Fan<br>9x1890 | 5419970892   | <b>TM08255</b><br> |
| 375 ACTROS<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>958 ATEGO 2<br>970 ATEGO 2<br>972 ATEGO 2              | Multi Ribbet Belt, Fan<br>9x1900 | 0149975392   | <b>TM25277</b><br> |
| -  | Multi Ribbet Belt, Fan<br>9x1920 | 0019937396<br>0019934996<br>0019937196<br>0019934896 | <b>TM08306</b><br> |





| TM No.  | Replaces Ref. No: | Description                      | Model / Details  |
|---|-------------------|----------------------------------|--|
| <b>TM25300</b><br>   | 0159971792        | Multi Ribbet Belt, Fan<br>9x2010 | 375 AXOR<br>374 AXOR 2<br>940 AXOR 2<br>942 AXOR 2<br>943 AXOR 2<br>944 AXOR 2<br>634 TOURO<br>671 CONECTO                   |
|   | 0009939296        |                                  |  |
|   | 0019930096        |                                  |  |
| <b>TM08314</b><br>   | 0139976192        | Multi Ribbet Belt, Fan<br>9x2060 | 375 AXOR<br>374 AXOR 2<br>940 AXOR 2<br>942 AXOR 2<br>943 AXOR 2<br>944 AXOR 2<br>671 CONECTO                                |
|   |                   |                                  |  |
| <b>TM25252</b><br>   | 0129973892        | Multi Ribbet Belt, Fan<br>9x2080 | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3 |
|   | 0019935096        |                                  |  |
| <b>TM08282</b><br> | 0149976092        | Multi Ribbet Belt, Fan<br>9x2100 | 375 AXOR<br>374 AXOR 2<br>940 AXOR 2<br>942 AXOR 2<br>943 AXOR 2<br>944 AXOR 2<br>958 AXOR 2<br>671 CONECTO                  |
|   |                   |                                  |  |
| <b>TM25251</b><br> | 0019935696        | Multi Ribbet Belt, Fan<br>9x2125 | 375 ACTROS<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>958 ATEGO 2<br>970 ATEGO 2<br>972 ATEGO 2                  |
|   | 0129972092        |                                  |  |
| <b>TM25317</b><br> | 0019932796        | Multi Ribbet Belt, Fan<br>9x2140 | 375 AXOR<br>374 AXOR 2<br>940 AXOR 2<br>942 AXOR 2<br>943 AXOR 2<br>944 AXOR 2<br>958 AXOR 2                                 |
|   | 0049930196        |                                  |  |
| <b>TM08257</b><br> | 0149976892        | Multi Ribbet Belt, Fan<br>9x2295 | 375 AXOR<br>374 AXOR 2<br>940 AXOR 2<br>942 AXOR 2<br>943 AXOR 2<br>944 AXOR 2<br>958 AXOR 2                                 |
|   | 5419971092        |                                  |  |



| Model / Details  | Description                       | Replaces Ref. No:                      | TM No.  |
|--|-----------------------------------|--|---|
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3 | Multi Ribbet Belt, Fan<br>9x2325  | 0019937096<br>0019933596               | <b>TM25302</b><br>   |
| 934 ACTROS 2/3<br>375 AXOR<br>374 AXOR 2<br>940 AXOR 2<br>942 AXOR 2<br>943 AXOR 2<br>944 AXOR 2<br>958 AXOR 2               | Multi Ribbet Belt, Fan<br>9x2338  | 0019932496                             | <b>TM08330</b><br>   |
| 979 ACCELO<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3     | Multi Ribbet Belt, Fan<br>9x2835  | 5419970992                             | <b>TM08256</b><br>   |
| 934 ACTROS 2/3<br>375 AXOR<br>374 AXOR 2<br>940 AXOR 2<br>942 AXOR 2<br>943 AXOR 2<br>944 AXOR 2<br>958 AXOR 2               | Multi Ribbet Belt, Fan<br>9x2871  | 0019937296<br>0009937896<br>5429970392 | <b>TM25266</b><br> |
| 375 ACTROS<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>958 ATEGO 2<br>970 ATEGO 2<br>972 ATEGO 2                  | Multi Ribbet Belt, Fan<br>10x1350 | 9069972692                             | <b>TM25288</b><br> |
| 375 ACTROS<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>375 ATEGO 2<br>958 ATEGO 2<br>970 ATEGO 2                  | Multi Ribbet Belt, Fan<br>10x1405 | 9069932696                             | <b>TM24654</b><br> |
| 375 ACTROS<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>958 ATEGO 2<br>970 ATEGO 2<br>972 ATEGO 2                  | Multi Ribbet Belt, Fan<br>0x1620  | 9069974092                             | <b>TM07607</b><br> |












| TM No.  | Replaces Ref. No:        | Description                       | Model / Details  |
|---|--------------------------|-----------------------------------|--|
| <b>TM07493</b><br>   | 9069974692               | Multi Ribbet Belt, Fan<br>10x1670 | 375 ACTROS<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>958 ATEGO 2<br>970 ATEGO 2<br>972 ATEGO 2                          |
| <b>TM08341</b><br>   | 9069936596               | Multi Ribbet Belt, Fan<br>10x1675 | 375 ACTROS<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>375 ATEGO 2<br>958 ATEGO 2<br>970 ATEGO 2                          |
| <b>TM25287</b><br>   | 9069972192               | Multi Ribbet Belt, Fan<br>10x1768 | 957 ECONIC   |
| <b>TM08326</b><br> | 9069974792<br>9069936696 | Multi Ribbet Belt, Fan<br>10x1815 | 375 ACTROS<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>958 ATEGO 2<br>970 ATEGO 2<br>972 ATEGO 2                          |
| <b>TM08312</b><br> | 0139972992<br>0019935996 | Multi Ribbet Belt, Fan<br>0x1850  | 375 ACTROS<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>375 ATEGO 2<br>958 ATEGO 2<br>970 ATEGO 2                          |
| <b>TM25291</b><br> | 9069973892               | Multi Ribbet Belt, Fan<br>10x2240 | 979 ACCELO<br>375 ACTROS<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>375 ATEGO 2<br>958 ATEGO 2                           |
| <b>TM08258</b><br> | 5419972692               | Multi Ribbet Belt, Fan<br>11x1890 | BM MODEL<br>979 ACCELO<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 |



| Model / Details  | Description                            | Replaces Ref. No:        | TM No.  |
|--|--|--------------------------|---|
| 375 ACTROS<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>375 ATEGO 2<br>958 ATEGO 2<br>970 ATEGO 2                  | Multi Ribbet Belt, Fan<br>11x2040      | 0019936196<br>0129976392 | <b>TM25271</b><br>   |
| 979 ACCELO<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3     | Multi Ribbet Belt, Fan<br>11x2835      | 5419972792               | <b>TM25250</b><br>   |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3 | Multi Ribbet Belt, Fan<br>12x1507      | 5419973092               | <b>TM08352</b><br>   |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3 | Multi Ribbet Belt, Fan<br>12x1515      | 5419972592               | <b>TM24763</b><br> |
| 979 ACCELO<br>950 ACTROS<br>952 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3 | Multi Ribbet Belt, Fan<br>12x2135      | 5429970192               | <b>TM25278</b><br> |
| 979 ACCELO<br>950 ACTROS<br>952 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>934 ACTROS 2/3                   | Multi Ribbet Belt, Fan<br>12x2490      | 5429970092               | <b>TM08283</b><br> |
| BM MODEL<br>979 ACCELO<br>375 ACTROS<br>375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO                        | Multi Ribbet Belt Kit, Fan<br>8x1420mm | 9062002070S1             | <b>TM08011</b><br> |



| TM No.  | Replaces Ref. No:                      | Description                            | Model / Details  |
|---|--|--|--|
| <b>TM08012</b>  | 9062002070S2                           | Multi Ribbet Belt Kit, Fan<br>8x1480mm | 979 ACCELO<br>375 ACTROS<br>375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO              |
|    |  |  |  |
| <b>TM08014</b>  | 9062002070S4                           | Multi Ribbet Belt Kit, Fan<br>8x2080mm | 979 ACCELO<br>375 ACTROS<br>375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO              |
|    |  |  |  |
| <b>TM36686</b>  | 6112000315<br>6112000515               | Thermostat                             | -  |
|    |  |  |  |
| <b>TM36687</b>  | 4002030174<br>9062030174               | Cover, Thermostat                      | 979 ACCELO<br>375 ACTROS<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>958 ATEGO 2            |
|  |  |  |  |
| <b>TM25032</b>  | 0039975748<br>0209971148<br>0249972848 | Gasket, Thermostat                     | 979 ACCELO<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3 |
|  |  |  |  |
| <b>TM07423</b>  | 6512000615                             | Flange Pipe, Thermostat                | 900 SPRINTER<br>906 SPRINTER<br>636 VIANO<br>639 VIANO   |
|  |  |  |  |
| <b>TM36688</b>  | 9015284782S                            | Hose, Intercooler<br>Without Plastic   | 901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER   |
|  |  |  |  |





| Model / Details   | Description                               | Replaces Ref. No:                      | TM No.  |
|---|---|--|---|
| 906 SPRINTER  | Hose, Intercooler                         | 9065281182                             | <b>TM08404</b>  |
|   |   |  |    |
| 957 ECONIC<br>396 OH SERIES<br>373 O 304<br>600 O 340<br>356 O 404<br>357 O 405<br>612 O 405        | Hose, Intercooler<br>Silicone<br>ø100x100 | 0020946982<br>0020943482               | <b>TM08350</b>  |
|   |   |  |    |
| 676 LK/LN2<br>677 LK/LN2<br>679 LK/LN2<br>695 L 1620<br>695 LK 1620<br>650 MK<br>651 MK             | Hose, Intercooler<br>ø80/ø85x215          | 6845011082<br>0010948582<br>0020941682 | <b>TM36689</b>  |
|   |   |  |    |
| 629 TRAVEGO<br>632 TRAVEGO<br>410 SETRA<br>629 SETRA  | Hose, Intercooler<br>Silicone<br>ø115x160 | 0029975452                             | <b>TM36690</b>  |
|   |   |  |  |
| 628 CITARO<br>633 INTEGRO<br>632 TOURISMO<br>629 TRAVEGO<br>632 SETRA<br>633 SETRA                  | Hose, Intercooler<br>Silicone<br>ø100x150 | 0249970782                             | <b>TM08181</b>  |
|   |   |  |  |
| 374 AXOR 2<br>634 TOURO<br>628 CITARO<br>633 INTEGRO<br>632 TOURISMO<br>629 TRAVEGO<br>632 TRAVEGO  | Hose, Intercooler<br>Silicone<br>ø100x190 | 0249970382                             | <b>TM08345</b>  |
|   |   |  |  |
| 958 ATEGO 2<br>375 AXOR<br>375 AXOR 2<br>958 AXOR 2<br>384 OF SERIES<br>368 OH SERIES<br>628 CITARO | Hose, Intercooler<br>Silicone<br>ø85x200  | 0015018082<br>0005016182<br>0005010182 | <b>TM08280</b>  |
|   |   |  |  |





| TM No.  | Replaces Ref. No: | Description       | Model / Details        |
|---|-------------------|-------------------|------------------------|
| <b>TM08232</b><br>   | 0020946382        | Hose, Intercooler | 375 AXOR               |
|   | 0010947982        | Silicone          | 374 AXOR 2             |
|   | 0020945482        | ø100x205          | 940 AXOR 2             |
|   |                   |                   | 942 AXOR 2             |
|   |                   |                   | 943 AXOR 2             |
|   |                   |                   | 944 AXOR 2             |
|   |                   |                   | 958 AXOR 2             |
| <b>TM36691</b><br>   | 0015017982        | Hose, Intercooler | 375 ATEGO              |
|   | 0005016082        | Silicone          | 970 ATEGO              |
|   | 0005010082        | ø85x200           | 972 ATEGO              |
|   |                   |                   | 975 ATEGO              |
|   |                   |                   | 976 ATEGO              |
|   |                   |                   | 375 ATEGO 2            |
|   |                   |                   | 958 ATEGO 2            |
| <b>TM08259</b><br>   | 0020945582        | Hose, Intercooler | -979 ACCELO            |
|   | 0020946682        | Silicone          | 950 ACTROS             |
|   | 0020940882        | ø115x210          | 952 ACTROS             |
|   | 0020945782        |                   | 953 ACTROS             |
|   |                   |                   | 954 ACTROS             |
|   |                   |                   | 930 ACTROS 2/3         |
|   |                   |                   | 932 ACTROS 2/3         |
| <b>TM36692</b><br> | 0020946082        | Hose, Intercooler | 685 L 1217             |
|   |                   | Silicone          | 685 L 1218             |
|   |                   | ø100x235          | 685 L 1417             |
|   |                   |                   | 685 L 1418             |
|   |                   |                   | 685 L 1419             |
|   |                   |                   | 685 L 1617             |
|   |                   |                   | 685 L 1618             |
| <b>TM08231</b><br> | 0020945282        | Hose, Intercooler | 650 MK                 |
|   | 0020945982        | Silicone          | 651 MK                 |
|   | 0010947882        | ø100x250          | 652 MK                 |
|   |                   |                   | 653 MK                 |
|   |                   |                   | 654 MK                 |
|   |                   |                   | 620 NG                 |
|   |                   |                   | 621 NG                 |
| <b>TM36693</b><br> | 3715018082        | Hose, Intercooler | 673 LK/LN2             |
|   |                   | Silicone          | 674 LK/LN2             |
|   |                   | ø79/ø84x320       | 676 LK/LN2             |
|   |                   |                   | 371 1821 AK/4X4/36 MBT |
|   |                   |                   | 371 1821 K/4X2/36 MBT  |
|   |                   |                   | 371 2521/6X2/48        |
|   |                   |                   | OTOMARSAN/TUERKEI      |
|   |                   |                   | 371 2521K/6X2/36       |
|   |                   |                   | OTOMARSAN/TUERKEI      |
| <b>TM36694</b><br> | 3715017982        | Hose, Intercooler | 673 LK/LN2             |
|   |                   | Silicone          | 674 LK/LN2             |
|   |                   | ø79/ø84x320       | 676 LK/LN2             |
|   |                   |                   | 371 1821 AK/4X4/36 MBT |
|   |                   |                   | 371 1821 K/4X2/36 MBT  |
|   |                   |                   | 371 2521/6X2/48        |
|   |                   |                   | OTOMARSAN/TUERKEI      |
|   |                   |                   | 371 2521K/6X2/36       |
|   |                   |                   | OTOMARSAN/TUERKEI      |



| Model / Details   | Description                                     | Replaces Ref. No:        | TM No.  |
|---|---|--------------------------|---|
| 629 TRAVEGO<br>632 TRAVEGO<br>410 SETRA<br>629 SETRA  | Hose, Intercooler<br>Silicone<br>ø115x100       | 0029970852               | <b>TM36695</b><br>   |
| 629 TRAVEGO<br>632 TRAVEGO<br>410 SETRA<br>629 SETRA<br>632 SETRA   | Hose, Intercooler<br>Silicone<br>ø115x870       | 0029974252               | <b>TM36696</b><br>   |
| 632 TRAVEGO<br>629 SETRA  | Hose, Intercooler<br>Silicone<br>ø115/ø100x1400 | 0029978752               | <b>TM36697</b><br>   |
| 634 O 500<br>634 O 500 RSD /<br>2736/8X2/30<br>634 TOURO<br>632 TOURISMO<br>629 TRAVEGO<br>632 TRAVEGO<br>629 SETRA | Hose, Intercooler<br>Silicone<br>ø100/ø115x130  | 0009970653               | <b>TM36698</b><br> |
| 906 SPRINTER  | Hose, Intercooler                               | 9065281082<br>9065283382 | <b>TM08421</b><br> |
| 906 SPRINTER  | Hose, Intercooler                               | 9065280182               | <b>TM08403</b><br> |
| 638 VITO<br>638 V-CLASS   | Hose, Intercooler                               | 6385281982<br>6385283182 | <b>TM36699</b><br> |





| TM No.  | Replaces Ref. No:                      | Description       | Model / Details              |
|---|--|-------------------|------------------------------|
| <b>TM08426</b>  | 9065281582<br>9065283782               | Hose, Intercooler | 900 SPRINTER<br>906 SPRINTER |
|    |  |                   |                              |
| <b>TM08425</b>  | 9065285082                             | Hose, Intercooler | 900 SPRINTER<br>906 SPRINTER |
|    |  |                   |                              |
| <b>TM36700</b>  | 9065281482<br>9065284082<br>9065284182 | Hose, Intercooler | 906 SPRINTER                 |
|   |  |                   |                              |
| <b>TM36701</b>  | 9065282582                             | Hose, Intercooler | 906 SPRINTER                 |
|  |  |                   |                              |
| <b>TM36702</b>  | 6385280582<br>6385281182<br>6385282682 | Hose, Intercooler | 638 VITO<br>638 V-CLASS      |
|  |  |                   |                              |
| <b>TM08419</b>  | 9065280382                             | Hose, Intercooler | 906 SPRINTER                 |
|  |  |                   |                              |
| <b>TM08405</b>  | 9065280282<br>9065282282               | Hose, Intercooler | 906 SPRINTER                 |
|  |  |                   |                              |



| Model / Details  | Description  | Replaces Ref. No:        | TM No.         |
|--|--|--------------------------|----------------|
| 639 VIANO  | Hose, Intercooler  | 6395281982               | <b>TM36703</b> |
|  |  |                          |                |
| 906 SPRINTER   | Hose, Intercooler  | 9065280882<br>9065283282 | <b>TM36704</b> |
|  |  |                          |                |
| 906 SPRINTER   | Hose, Intercooler  | 9065280082<br>9065283182 | <b>TM36705</b> |
|  |  |                          |                |
| 979 ACCELO<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3 | Clamp, Intercooler   | 0019951910<br>0059971490 | <b>TM07943</b> |
|  |  |                          |                |
| 958 ATEGO 2<br>958 ATEGO 2<br>958 ATEGO 2  | Air Filter<br>Complete   | 9585200653<br>9735280606 | <b>TM36706</b> |
|  |  |                          |                |
| 405 UNIMOG   | Air Filter Cartridge<br>Repl. Mann: C257301<br>Repl. Hengst: E307L | 4050940004               | <b>TM06915</b> |
|  |  |                          |                |
| -  | Air Filter Cartridge<br>Repl. Mann: C339203<br>Repl. Hengst: E119L | 8690940003               | <b>TM06264</b> |
|  |  |                          |                |



| TM No.  | Replaces Ref. No: | Description                       | Model / Details |
|---|-------------------|-----------------------------------|-----------------|
| <b>TM06038</b><br>   | 0010944204        | Air Filter Cartridge              | 674 LK/LN2      |
|   | 0010945204        | Repl. Mann: C 20 325/2            | 675 LK/LN2      |
|   | 0020940004        | Repl. Hengst: E115L               | 676 LK/LN2      |
|   | 0130941802        | ø8,5xø103xø198x378                | 652 MK          |
|   |                   |                                   | 622 NG          |
|   |                   | 647 NG                            | 625 SK          |
| <b>TM06298</b><br>   | 0030949104        | Air Filter Cartridge              | 950 ACTROS      |
|   |                   | Repl. Mann: C421729               | 952 ACTROS      |
|   |                   | Repl. Hengst: E312L               | 953 ACTROS      |
|   |                   | ø10,5/ø254xø420x317               | 954 ACTROS      |
|   |                   |                                   | 930 ACTROS 2/3  |
|   |                   |                                   | 932 ACTROS 2/3  |
|   |                   | 933 ACTROS 2/3                    |                 |
| <b>TM06296</b><br>  | 0030944204        | Air Filter Cartridge              | 650 MK          |
|   | 0030944904        | Repl. Mann: C331015               | 651 MK          |
|   |                   | Repl. Hengst: E273L               | 652 MK          |
|   |                   | ø10,5/ø161xø327x258               | 653 MK          |
|   |                   |                                   | 654 MK          |
|   |                   | 625 SK                            | 655 SK          |
| <b>TM36707</b><br> | 0004094330        | Air Filter Cartridge              | 950 ACTROS      |
|   | 0040943304        | Repl. Mann: C421404               | 952 ACTROS      |
|   | 0030949204        | Repl. Hengst: E297L               | 953 ACTROS      |
|   |                   | ø10,5/ø254xø420x263               | 954 ACTROS      |
|   |                   |                                   | 930 ACTROS 2/3  |
|   |                   |                                   | 932 ACTROS 2/3  |
|   |                   | 933 ACTROS 2/3                    |                 |
| <b>TM06327</b><br> | 0040942504        | Air Filter Cartridge              | 375 ACTROS      |
|   | 0040942404        | Repl. Mann: C411776               | 950 ACTROS      |
|   |                   | Repl. Hengst: E497L               | 952 ACTROS      |
|   |                   | ø221,8xø406/<br>ø518,5x332,3      | 953 ACTROS      |
|   |                   |                                   | 954 ACTROS      |
|   |                   | 930 ACTROS 2/3                    | 932 ACTROS 2/3  |
| <b>TM06350</b><br> | 0000902651        | Air Filter Cartridge              | 906 SPRINTER    |
|   | 0000903751        | Repl. Mann: C4312/1               |                 |
|   |                   | Repl. Hengst: E821L<br>265x355x58 |                 |
| <b>TM06300</b><br> | 0030949504        | Air Filter Cartridge              | 970 ATEGO       |
|   | 0030949604        | Repl. Mann: C2910321              | 972 ATEGO       |
|   | 0040947404        | Repl. Hengst: E361L               | 975 ATEGO       |
|   |                   | ø127xø281,5/ø346x352              | 976 ATEGO       |
|   |                   |                                   | 970 ATEGO 2     |
|   |                   | 972 ATEGO 2                       | 974 ATEGO 2     |





| Model / Details  | Description   | Replaces Ref. No:                                    | TM No.  |
|--|---|--|---|
| 940 AXOR 2<br>942 AXOR 2<br>943 AXOR 2<br>695 L 1634<br>695 LS 1634<br>695 LS 1634EL<br>695 LS 1634EL 1635 S   | Air Filter Cartridge<br>Repl. Mann: C2713203<br>Repl. Hengst: E603L<br>ø170xø267x533                | 4760940004<br>0040943504                             | <b>TM06325</b><br>   |
| 388 L 1929<br>388 L 1935<br>388 L 1938<br>388 L 1945<br>388 L 2635/6X4/54<br>388 LK 2635/6X4/40<br>388 LS 1935 | Air Filter Cartridge<br>Repl. Mann: C 30 850/2<br>Repl. Hengst: E118L<br>ø10,5/ø190,7xø303/476      | 3880947004<br>0040945004<br>8690940020<br>0030945004 | <b>TM06462</b><br>   |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3     | Air Filter Cartridge<br>Repl. Mann: C2912191<br>Repl. Hengst: E314L<br>ø127xø281,5/ø346x406         | 0040940204   | <b>TM06299</b><br>  |
| 336 LP 1924<br>336 LPS 1924<br>346 L 1928<br>346 LK 1928<br>346 LS 1928<br>373 O 330<br>698 BGU-25             | Air Filter Cartridge<br>Repl. Mann: C 24 650/6<br>Repl. Hengst: E117L<br>ø132xø242/ø10,5/498        | 0010947904<br>3860947304<br>3500947004<br>0120948702 | <b>TM06040</b><br> |
| 650 MK<br>651 MK<br>652 MK<br>380 NG<br>381 NG<br>383 NG<br>385 NG   | Air Filter Cartridge<br>Repl. Mann: C 28 715<br>Repl. Hengst: E275L<br>ø10,5xø338/<br>ø133xø276/254 | 0010949304   | <b>TM06216</b><br> |
| 387 NG<br>389 NG<br>391 NG<br>393 NG<br>395 NG<br>616 NG<br>617 NG   | Air Filter Cartridge<br>Repl. Mann: C 33 922<br>Repl. Hengst: E276L<br>ø10,5xø386/<br>ø167xø327/258 | 0010948304   | <b>TM06297</b><br> |
| 954 ACTROS<br>934 ACTROS 2/3<br>944 AXOR 2<br>625 SK<br>655 SK<br>656 SK<br>658 SK                             | Air Filter Cartridge<br>Repl. Mann: C 33 1840<br>Repl. Hengst: E272L<br>ø10,5/ø191xø327x483         | 0030947004   | <b>TM06297</b><br> |





| TM No.  | Replaces Ref. No: | Description             | Model / Details |
|---|-------------------|-------------------------|-----------------|
| <b>TM06328</b><br>   | 0030949004        | Air Filter Cartridge    | 950 ACTROS      |
|   | 0040941104        | Repl. Mann: C 64 1500/1 | 952 ACTROS      |
|   | 0040946604        | Repl. Hengst: E315L01   | 953 ACTROS      |
|   | 0040948704        |                         | 954 ACTROS      |
|   |                   |                         |                 |
| <b>TM36708</b><br>   | 0010943003        | Cover, Air Filter       | 950 ACTROS      |
|   |                   |                         | 952 ACTROS      |
|   |                   |                         | 953 ACTROS      |
|   |                   |                         | 954 ACTROS      |
|   |                   |                         | 930 ACTROS 2/3  |
|   |                   |                         | 932 ACTROS 2/3  |
| <b>TM36709</b><br>  | 0010944603        | Cover, Air Filter       | 958 AXOR 2      |
|   |                   |                         |                 |
| <b>TM36710</b><br> | 0010944103        | Cover, Air Filter       | 930 ACTROS 2/3  |
|   |                   |                         | 932 ACTROS 2/3  |
|   |                   |                         | 933 ACTROS 2/3  |
|   |                   |                         | 934 ACTROS 2/3  |
|   |                   |                         | 374 AXOR 2      |
|   |                   |                         | 942 AXOR 2      |
| <b>TM06446</b><br> | 9425280382        | Hose, Air Filter        | 375 ACTROS      |
|   |                   |                         | 950 ACTROS      |
|   |                   |                         | 952 ACTROS      |
|   |                   |                         | 953 ACTROS      |
|   |                   |                         | 954 ACTROS      |
|   |                   |                         | 930 ACTROS 2/3  |
|   |                   |                         | 932 ACTROS 2/3  |
| <b>TM36711</b><br> | 9405280982        | Hose, Air Filter        | 375 ACTROS      |
|   |                   |                         | 970 ATEGO       |
|   |                   |                         | 972 ATEGO       |
|   |                   |                         | 975 ATEGO       |
|   |                   |                         | 976 ATEGO       |
|   |                   |                         | 958 ATEGO 2     |
|   |                   |                         | 970 ATEGO 2     |
| <b>TM36712</b><br> | 6010940391        | Hose, Air Filter        | 668 VARIO       |
|   |                   |                         |                 |








| Model / Details  | Description                                   | Replaces Ref. No: | TM No.  |
|--|---|-------------------|---|
| 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3     | Bellow, Air Filter<br>190x220x280             | 9425280091        | <b>TM36713</b>  |
|  |   |                   |    |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 | Bellow, Air Filter<br>ø130xø168x125           | 9415281182        | <b>TM06449</b>  |
|  |   |                   |    |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 | Bellow, Air Filter<br>88x272x160              | 9415280291        | <b>TM06447</b>  |
|  |   |                   |   |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 | Bellow, Air Filter<br>ø215x207x257,2          | 9415281282        | <b>TM36714</b>  |
|  |   |                   |  |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 | Bellow, Air Filter<br>ø218x448x234,3          | 9415280882        | <b>TM06448</b>  |
|  |   |                   |  |
| 611 T1/TN<br>601 208/210<br>602 308/310  | Mounting, Air Filter<br>M6x1/ø24,5x18         | 6179880111        | <b>TM36715</b>  |
|  |   |                   |  |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 | Mounting, Air Filter<br>M8x1,25/ø50x29,5/61,5 | 0019877140        | <b>TM33074</b>  |
|  |   |                   |  |












| TM No.  | Replaces Ref. No:                                    | Description                       | Model / Details   |
|---|--|-----------------------------------|---|
| <b>TM36716</b>  | 6110940385<br>6110940085                             | Gasket, Air Filter                | -   |
|    |  |                                   |   |
| <b>TM36717</b>  | 0180946302S  | Housing, Air Filter<br>With Cover | 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3      |
|    |  |                                   |   |
| <b>TM36718</b>  | 9585200353   | Housing, Air Filter               | 375 AXOR<br>940 AXOR 2<br>942 AXOR 2<br>943 AXOR 2<br>944 AXOR 2<br>958 AXOR 2                              |
|    |  |                                   |   |
| <b>TM01364</b>  | 9060170660<br>9060170760<br>9060170860               | Nozzle, Injector                  | 979 ACCELO<br>375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3          |
|  |  |                                   |   |
| <b>TM36719</b>  | 0001400368<br>0001403268                             | Nozzle, Injector                  | 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3<br>375 ATEGO<br>970 ATEGO<br>972 ATEGO |
|  |  |                                   |   |
| <b>TM23581</b>  | 9060701433<br>9060702133<br>9060702233               | Pipe, Injector                    | 979 ACCELO<br>375 ACTROS<br>375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO                   |
|  |  |                                   |   |
| <b>TM23569</b>  | 5410701133<br>5410701933<br>5410701733<br>5410701533 | Pipe, Injector                    | 979 ACCELO<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3      |
|  |  |                                   |   |



| Model / Details  | Description        | Replaces Ref. No:                                    | TM No.  |
|--|--------------------|--|---|
| 934 ACTROS 2/3<br>375 AXOR<br>374 AXOR 2<br>940 AXOR 2<br>942 AXOR 2<br>943 AXOR 2<br>944 AXOR 2       | Pipe, Injector     | 4570700933<br>4570701033<br>4570701333<br>4570701533 | <b>TM23568</b><br>   |
| 979 ACCELO<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3 | Pipe, Injector     | 5410705632   | <b>TM36720</b><br>   |
| 903 SPRINTER<br>904 SPRINTER<br>906 SPRINTER<br>639 VIANO  | Pipe, Injector     | 6110701133   | <b>TM23584</b><br>  |
| 906 SPRINTER<br>909 SPRINTER<br>636 VIANO<br>639 VIANO   | Pipe, Injector     | 6460700233   | <b>TM36721</b><br> |
| 900 SPRINTER<br>906 SPRINTER<br>636 VIANO<br>639 VIANO   | Pipe, Injector     | 6510702433   | <b>TM23605</b><br> |
| 900 SPRINTER<br>906 SPRINTER<br>636 VIANO<br>639 VIANO   | Pipe, Injector     | 6510702533   | <b>TM23606</b><br> |
| 621 NG<br>623 NG<br>624 NG<br>645 NG<br>646 NG<br>647 NG<br>648 NG                                     | Pipe Kit, Injector | 4420708333<br>4420707933<br>4420706033               | <b>TM24068</b><br> |





| TM No.  | Replaces Ref. No:   | Description        | Model / Details  |                  |
|---|---|--------------------|--|------------------|
| <b>TM24067</b><br>   | 4220705433  | Pipe Kit, Injector | 621 NG<br>623 NG<br>624 NG<br>645 NG<br>646 NG<br>647 NG<br>648 NG |                  |
|   | <b>TM24079</b><br> | 4420706333         | Pipe Kit, Injector   | 652 MK           |
|   |   | 4420708133         |  | 625 SK           |
|   |   |                    |  | 655 SK           |
|   |   |                    |  | 656 SK           |
|   |   |                    |  | 657 SK           |
|   |   |                    |  | 658 SK<br>659 SK |
| <b>TM24080</b><br>  | 4420706433  | Pipe Kit, Injector | 652 MK   |                  |
|   | 4420709633  |                    | 625 SK   |                  |
|   |   |                    | 655 SK   |                  |
|   |   |                    | 656 SK   |                  |
|   |   |                    | 657 SK<br>658 SK<br>659 SK   |                  |
| <b>TM24076</b><br> | 4410705333  | Pipe Kit, Injector | 650 MK   |                  |
|   | 4410706733  |                    | 651 MK   |                  |
|   |   |                    | 652 MK   |                  |
|   |   |                    | 653 MK   |                  |
|   |   |                    | 654 MK   |                  |
|   |   |                    | 625 SK<br>655 SK   |                  |
| <b>TM24077</b><br> | 4410705433  | Pipe Kit, Injector | 650 MK   |                  |
|   | 4410706433  |                    | 651 MK   |                  |
|   |   |                    | 652 MK   |                  |
|   |   |                    | 653 MK   |                  |
|   |   |                    | 654 MK   |                  |
|   |   |                    | 625 SK<br>655 SK   |                  |
| <b>TM24074</b><br> | 4410705533  | Pipe Kit, Injector | 650 MK   |                  |
|   |   |                    | 651 MK   |                  |
|   |   |                    | 652 MK   |                  |
|   |   |                    | 653 MK   |                  |
|   |   |                    | 654 MK   |                  |
|   |   |                    | 617 NG<br>619 NG   |                  |
| <b>TM24075</b><br> | 4410701133  | Pipe Kit, Injector | 650 MK   |                  |
|   |   |                    | 651 MK   |                  |
|   |   |                    | 652 MK   |                  |
|   |   |                    | 653 MK   |                  |
|   |   |                    | 654 MK   |                  |
|   |   |                    | 617 NG<br>619 NG   |                  |












| Model / Details  | Description                       | Replaces Ref. No:                      | TM No.  |
|--|-----------------------------------|--|---|
| 659 SK<br>613 TOURISMO   | Pipe Kit, Injector                | 4420708433                             | <b>TM24078</b>  |
|  |                                   |  |    |
| 979 ACCELO<br>314 LP<br>318 LP<br>328 T2/L<br>336 LP 1924<br>341 L 1112<br>341 L 1114                    | Seal Ring, Injector<br>ø9,5xø20x1 | 3880170160<br>3460170160               | <b>TM00065</b>  |
|  |                                   |  |    |
| 979 ACCELO<br>375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3       | Seal Ring, Injector<br>ø7xø15x1,5 | 0000170776<br>5410170260<br>9060170260 | <b>TM23186</b>  |
|  |                                   |  |    |
| 314 LP<br>316 LP<br>318 LP<br>328 T2/L<br>352 L 1313<br>352 L 1813/6X2<br>352 L 1813/6X4                 | Clamp, Injector                   | 0009951107<br>3520780186               | <b>TM23256</b>  |
|  |                                   |  |  |
| 673 LK/LN2<br>674 LK/LN2<br>652 MK<br>615 NG<br>616 NG<br>617 NG<br>619 NG                               | Clamp, Injector                   | 0009951807<br>4220780186               | <b>TM23257</b>  |
|  |                                   |  |  |
| 314 LP<br>316 LP<br>673 LK/LN2<br>674 LK/LN2<br>650 MK<br>651 MK<br>652 MK                               | Clamp, Injector                   | 0009951407<br>4220700166<br>4220780386 | <b>TM23255</b>  |
|  |                                   |  |  |
| 979 ACCELO<br>950 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>934 ACTROS 2/3<br>375 AXOR<br>374 AXOR 2 | Screw, Injector<br>M12x1,5        | 4429905563                             | <b>TM36722</b>  |
|  |                                   |  |  |












| TM No.  | Replaces Ref. No: | Description                | Model / Details |
|---|-------------------|----------------------------|-----------------|
| <b>TM25445</b><br>   | 0000741671        | Screw, Injector<br>M8x1/22 | 979 ACCELO      |
|   | 0000746671        |                            | 375 ACTROS      |
|   | 007623002100      |                            | 950 ACTROS      |
|   | 3269900163        |                            | 952 ACTROS      |
|   |                   |                            | 953 ACTROS      |
|   |                   |                            | 954 ACTROS      |
|   |                   |                            | 930 ACTROS 2/3  |
| <b>TM36723</b><br>   | 4429905763        | Screw, Injector            | 979 ACCELO      |
|   |                   |                            | 950 ACTROS      |
|   |                   |                            | 952 ACTROS      |
|   |                   |                            | 953 ACTROS      |
|   |                   |                            | 954 ACTROS      |
|   |                   |                            | 930 ACTROS 2/3  |
|   |                   |                            | 932 ACTROS 2/3  |
| <b>TM01627</b><br>   | 5410170188        | Guide, Injector            | 979 ACCELO      |
|   |                   |                            | 375 ACTROS      |
|   |                   |                            | 950 ACTROS      |
|   |                   |                            | 952 ACTROS      |
|   |                   |                            | 953 ACTROS      |
|   |                   |                            | 954 ACTROS      |
|   |                   |                            | 930 ACTROS 2/3  |
| <b>TM01625</b><br> | 9060170488        | Guide, Injector            | 979 ACCELO      |
|   |                   |                            | 375 ACTROS      |
|   |                   |                            | 950 ACTROS      |
|   |                   |                            | 952 ACTROS      |
|   |                   |                            | 953 ACTROS      |
|   |                   |                            | 954 ACTROS      |
|   |                   |                            | 930 ACTROS 2/3  |
| <b>TM36724</b><br> | 4570100455        | Return Pipe, Injector      | 375 AXOR        |
|   | 4570101755        |                            | 374 AXOR 2      |
|   |                   |                            | 940 AXOR 2      |
|   |                   |                            | 942 AXOR 2      |
|   |                   |                            | 943 AXOR 2      |
|   |                   |                            | 944 AXOR 2      |
|   | 958 AXOR 2        |                            |                 |
| <b>TM36725</b><br> | 5410101055        | Return Pipe, Injector      | 950 ACTROS      |
|   |                   |                            | 952 ACTROS      |
|   |                   |                            | 953 ACTROS      |
|   |                   |                            | 954 ACTROS      |
|   |                   |                            | 930 ACTROS 2/3  |
|   |                   |                            | 932 ACTROS 2/3  |
|   |                   |                            | 933 ACTROS 2/3  |
| <b>TM36726</b><br> | 5420100255        | Return Pipe, Injector      | 979 ACCELO      |
|   | 5420100355        |                            | 950 ACTROS      |
|   |                   |                            | 952 ACTROS      |
|   |                   |                            | 954 ACTROS      |
|   |                   |                            | 930 ACTROS 2/3  |
|   |                   |                            | 932 ACTROS 2/3  |
|   | 934 ACTROS 2/3    |                            |                 |





| Model / Details  | Description           | Replaces Ref. No:                                    | TM No.  |
|--|-----------------------|--|---|
| 906 SPRINTER<br>639 VIANO  | Return Pipe, Injector | 6420702032<br>6420703232<br>6420705632               | <b>TM36727</b><br>   |
| 906 SPRINTER<br>909 SPRINTER   | Return Pipe, Injector | 6460700932   | <b>TM36728</b><br>   |
| 636 VIANO<br>639 VIANO   | Return Pipe, Injector | 6460701532   | <b>TM36729</b><br>  |
| 900 SPRINTER<br>906 SPRINTER<br>636 VIANO<br>639 VIANO   | Return Pipe, Injector | 6510700132   | <b>TM36730</b><br> |
| 900 SPRINTER<br>906 SPRINTER<br>636 VIANO<br>639 VIANO   | Return Pipe, Injector | 6510702432   | <b>TM36731</b><br> |
| 901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER<br>639 VIANO<br>638 VITO<br>638 V-CLASS                                   | Return Pipe, Injector | 6460701132<br>6110700032<br>6110704532<br>6110706032 | <b>TM23572</b><br> |
| 363 LP 2226/6X4<br>363 LP 2232/6X4<br>363 LPB 2226/6X4<br>363 LPK 2226/6X4<br>363 LPK 2232/6X4<br>363 LPS 2226/6X4<br>363 LPS 2232/6X4 | Return Pipe, Injector | 0119977782<br>0129974082<br>0129976582<br>0139976782 | <b>TM23293</b><br> |












| TM No.  | Replaces Ref. No: | Description               | Model / Details                              |
|---|-------------------|---------------------------|--|
| <b>TM23571</b><br>   | 6120703832        | Return Pipe, Injector     | 902 SPRINTER                                 |
|   | 6120703032        |                           | 903 SPRINTER                                 |
|   | 6120701032        |                           | 904 SPRINTER                                 |
|   |                   |                           | 905 SPRINTER                                 |
| <b>TM36732</b><br>   | 6120700032        | Return Pipe, Injector     | 979 ACCELO                                   |
|   |                   |                           | 902 SPRINTER                                 |
|   |                   |                           | 903 SPRINTER                                 |
|   |                   |                           | 904 SPRINTER                                 |
|   |                   |                           | 905 SPRINTER                                 |
| <b>TM36733</b><br>   | 6020704732        | Return Pipe, Injector     | 408 UNIMOG                                   |
|   |                   |                           | 901 SPRINTER                                 |
|   |                   |                           | 902 SPRINTER                                 |
|   |                   |                           | 903 SPRINTER                                 |
|   |                   |                           | 904 SPRINTER                                 |
|   |                   |                           | 667 VARIO                                    |
| <b>TM36734</b><br> | 6420705532        | Return Pipe, Injector     | 653 MK                                       |
|   | 6420701932        |                           | 654 MK                                       |
|   | 6420703032        |                           | 655 SK                                       |
|   |                   |                           | 656 SK                                       |
|   |                   |                           | 658 SK<br>659 SK                             |
| <b>TM01594</b><br> | 4030170271        | Nut, Injector             | 363 LP 2226/6X4                              |
|   | 4030170171        |                           | 363 LP 2232/6X4                              |
|   | 4030170071        |                           | 386 L 1625,1725                              |
|   |                   |                           | 386 L 1633                                   |
|   |                   |                           | 386 LB 2325,2425<br>388 L 1929<br>388 L 1935 |
| <b>TM36735</b><br> | 6020704732S       | Return Hose End, Injector | 408 UNIMOG                                   |
|   |                   |                           | 901 SPRINTER                                 |
|   |                   |                           | 902 SPRINTER                                 |
|   |                   |                           | 903 SPRINTER                                 |
|   |                   |                           | 904 SPRINTER                                 |
|   |                   |                           | 667 VARIO                                    |
| <b>TM36736</b><br> | 6120700032S       | Return Hose End, Injector | 979 ACCELO                                   |
|   |                   |                           | 902 SPRINTER                                 |
|   |                   |                           | 903 SPRINTER                                 |
|   |                   |                           | 904 SPRINTER                                 |
|   |                   |                           | 905 SPRINTER                                 |



| Model / Details   | Description                                  | Replaces Ref. No:                                      | TM No.  |
|---|--|--|---|
| 690 SPRINTER<br>901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER<br>639 VIANO<br>639 VITO                                 | Return Hose End, Injector                    | 6110708432S<br>6110700032S                             | <b>TM36737</b><br>   |
| 386 L 1625,1725<br>386 L 1633<br>386 L 2325,2425,LA<br>2425/6X6<br>386 LB 2325,2425<br>386 LK 2325,2425<br>386 LS 1630<br>386 LS 1633 | Seal Ring, Injection Pump<br>ø35xø47x7 / FPM | 0149974747   | <b>TM23346</b><br>   |
| 336 LP 1924<br>336 LPS 1924<br>338 L 1418<br>338 LK 1418<br>338 LP 1418<br>338 LPS 1418<br>338 LS 1418                                | Seal Ring, Injection Pump<br>ø25xø35x7 / NBR | 0119974746<br>0029972747<br>0099979746<br>003760025100 | <b>TM23357</b><br>  |
| 979 ACCELO<br>690 SPRINTER<br>901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER<br>905 SPRINTER                            | Pipe, Injection Pump                         | 6110700533<br>6110701433                               | <b>TM36738</b><br> |
| 903 SPRINTER<br>904 SPRINTER<br>906 SPRINTER<br>639 VIANO   | Pipe, Injection Pump                         | 6110701033   | <b>TM23586</b><br> |
| 653 MK<br>656 SK<br>659 SK<br>906 SPRINTER<br>639 VIANO   | Pipe, Injection Pump                         | 6420700033   | <b>TM36739</b><br> |
| 906 SPRINTER<br>909 SPRINTER<br>636 VIANO<br>639 VIANO  | Pipe, Injection Pump                         | 6460700333   | <b>TM36740</b><br> |












| TM No.  | Replaces Ref. No:        | Description          | Model / Details   |
|---|--------------------------|----------------------|---|
| <b>TM36741</b><br>   | 6510703033               | Pipe, Injection Pump | 900 SPRINTER<br>906 SPRINTER<br>636 VIANO<br>639 VIANO  |
| <b>TM36742</b><br>   | 6110702932               | Pipe, Injection Pump | 690 SPRINTER<br>901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER<br>638 V-CLASS<br>638 VITO |
| <b>TM36743</b><br>  | 6110707632<br>6110706432 | Pipe, Injection Pump | 690 SPRINTER<br>901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER                            |
| <b>TM23603</b><br> | 6110702032               | Pipe, Injection Pump | 690 SPRINTER<br>901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER<br>638 V-CLASS<br>638 VITO |
| <b>TM23604</b><br> | 6110701932               | Pipe, Injection Pump | 690 SPRINTER<br>901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER                            |
| <b>TM36744</b><br> | 6110702132               | Pipe, Injection Pump | 638 V-CLASS<br>638 VITO   |
| <b>TM36745</b><br> | 6110706832               | Pipe, Injection Pump | 901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER<br>905 SPRINTER<br>638 V-CLASS<br>638 VITO |








| Model / Details  | Description  | Replaces Ref. No:        | TM No.  |
|--|--|--------------------------|---|
| -  | Pipe, Injection Pump                                   | 6110703232               | <b>TM36746</b>  |
|  |  |                          |    |
| -  | Pipe, Injection Pump                                   | 6110704932               | <b>TM36747</b>  |
|  |  |                          |    |
| -  | Pipe, Injection Pump                                   | 6110703432               | <b>TM36748</b>  |
|  |  |                          |   |
| -  | Pipe, Injection Pump                                   | 6110707332<br>6110705632 | <b>TM36749</b>  |
|  |  |                          |  |
| -  | Pipe, Injection Pump                                   | 6120703232<br>6650700132 | <b>TM36750</b>  |
|  |  |                          |  |
| 314 LP<br>318 LP<br>328 T2/L<br>336 LP 1924<br>338 L 1418<br>338 LK 1418<br>338 LP 1418                              | Valve, Injection Pump<br>Repl. Bosch: 1 417 413<br>000 | 0000740515               | <b>TM23242</b>  |
|  |  |                          |  |
| 611 T1/TN<br>601 207 D/208 D<br>601 209 D/210 D<br>602 307 D/308 D<br>602 307 D/308D<br>602 308 D<br>602 309 D/310 D | Valve, Injection Pump<br>Repl. Bosch: 1 417 413<br>046 | 0000747284<br>0000740384 | <b>TM24368</b>  |
|  |  |                          |  |



| TM No.  | Replaces Ref. No:   | Description  | Model / Details   |
|---|---|--|---|
| <b>TM23748</b><br>   | 5410700646  | Valve, Injection Pump  | 979 ACCELO  |
|   | 5410700546  |  | 950 ACTROS  |
| 5410700246  | 930 ACTROS 2/3<br>932 ACTROS 2/3<br>934 ACTROS 2/3                          |  |   |
| <b>TM23248</b><br>   | 0000911310  | Valve, Injection Pump<br>Repl. Bosch: 2 447 419<br>002                 | 374 AXOR 2  |
|   | 0000910810  |  | 958 AXOR 2<br>386 L 1625,1725<br>386 L 1633<br>386 LB 2325,2425<br>388 L 1929<br>388 L 1935 |
| <b>TM23765</b><br>  | 5410980057  | Valve, Injection Pump  | 688 LO 812  |
|   |   |  | 688 LO 814<br>694 L 1218 R<br>694 L 1418 R<br>694 LK 1218 R<br>694 LK 1418 R<br>695 L 1620  |
| <b>TM23782</b><br> | 4570700246  | Valve, Injection Pump  | 375 AXOR  |
|   |   |  | 374 AXOR 2<br>940 AXOR 2<br>942 AXOR 2<br>943 AXOR 2<br>944 AXOR 2<br>958 AXOR 2            |
| <b>TM02065</b><br> | 9060921210  | Valve, Injection Pump  | 979 ACCELO  |
|   |   |  | 375 ACTROS<br>375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO                 |
| <b>TM23715</b><br> | 0000770425  | Washer, Injection Pump<br>Repl. Bosch: 3 411 190<br>503                | 336 LP 1924   |
|   | 0000770325  |  | 338 L 1418  |
| 0000770435  | 338 LK 1418<br>338 LP 1418<br>343 T2/L<br>343 T2/LN1<br>345 L 1418 MBTC-USA |  |   |
| <b>TM24842</b><br> | 007603014106  | Washer, Injection Pump<br>Repl. Bosch: 2 916 710<br>610<br>ø14xø20x1,5 | 979 ACCELO  |
|   | 0000741959  |  | 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS<br>958 ATEGO 2<br>967 ATEGO 3    |




| Model / Details   | Description  | Replaces Ref. No:                                    | TM No.  |
|---|--|--|---|
| BM MODEL<br>384 L 1214<br>384 L 1215<br>384 L 1218<br>384 L 1414<br>384 L 1418 ,L 1418 E<br>384 LA 1418<br>384 LAK 1418 | Cylinder, Injection Pump<br>Stroke: -32/+50 / Max.<br>Operating<br>Pres.: 8 Bar<br>Repl. Wabco: 421 441<br>000 0<br>Con-Rod: M8 / Port<br>Threads: M12x1,5 | 0000721512<br>0000721812<br>0000722212<br>0000721912 | <b>TM23627</b><br>   |
| 615 LK/LN2<br>673 LK/LN2<br>674 LK/LN2<br>675 LK/LN2<br>676 LK/LN2<br>677 LK/LN2<br>678 LK/LN2                          | Cylinder, Injection Pump<br>Stroke: -32/+50 / Max.<br>Operating<br>Pres.: 8 Bar<br>Repl. Knorr: I58893<br>Con-Rod: M6 / Port<br>Threads: M12x1,5           | 0000720112   | <b>TM23468</b><br>   |
| 336 LP 1924<br>336 LPS 1924<br>338 L 1418<br>338 LK 1418<br>338 LP 1418<br>338 LPS 1418<br>338 LS 1418                  | Cylinder, Injection Pump<br>ø19 x M6 - Strok 19  | 6583001715<br>3550700475                             | <b>TM23716</b><br>  |
| 676 LK/LN2<br>650 MK<br>651 MK<br>652 MK<br>653 MK<br>615 NG<br>617 NG  | Cylinder, Injection Pump<br>Repl. Wabco: 421 444<br>020 0  | 0000702183<br>0000723212<br>0000701783<br>0000701583 | <b>TM23628</b><br> |
| 601 207 D/208 D<br>611 T1/TN<br>631 O 100 CITY<br>408 UNIMOG<br>668 VARIO   | Timing Device, Injection<br>Pump   | 6010702045<br>6010701245<br>6010701045               | <b>TM36751</b><br> |
| -   | Feed Pump<br>Repl. Bosch: 0 440 008<br>007 S   | 0010916701S  | <b>TM36752</b><br> |
| 406 UNIMOG  | Feed Pump<br>Repl. Bosch: 0 440 003<br>190   | 0010911501<br>0020916001                             | <b>TM36753</b><br> |





| TM No.  | Replaces Ref. No:                      | Description                             | Model / Details  |
|---|--|---|--|
| <b>TM36754</b><br>   | 0030914201                             | Feed Pump<br>Repl. Bosch: 0 440 008 076 | -  |
| <b>TM23820</b><br>   | 0000909250                             | Feed Pump<br>Repl. Bosch: 0 440 011 021 | 375 AXOR<br>374 AXOR 2<br>940 AXOR 2<br>942 AXOR 2<br>943 AXOR 2<br>944 AXOR 2<br>958 AXOR 2             |
| <b>TM36755</b><br>   | 0000911990                             | Feed Pump<br>Repl. Bosch: 0 440 011 011 | -  |
| <b>TM36756</b><br> | 0000901550<br>0010919601               | Feed Pump<br>Repl. Bosch: 0 440 008 008 | -  |
| <b>TM23225</b><br> | 0030910601<br>0000903150               | Feed Pump<br>Repl. Bosch: 0 440 008 989 | 386 L 1625,1725<br>386 L 1633<br>386 LB 2325,2425<br>620 NG<br>621 NG<br>624 NG<br>645 NG                |
| <b>TM23608</b><br> | 0000900250<br>0010911101               | -                                       | 312 L 312<br>341 L 1112<br>341 L 1114<br>341 L 911<br>341 L 914<br>341 LA 1112<br>341 LA 1114            |
| <b>TM23719</b><br> | 0000900350<br>0010912501<br>0010916101 | -                                       | 336 LP 1924<br>338 L 1418<br>338 LK 1418<br>338 LP 1418<br>343 T2/L<br>343 T2/LN1<br>345 L 1418 MBTC-USA |



| Model / Details  | Description  | Replaces Ref. No:  | TM No.  |
|--|--|--|---|
| 343 T2/L<br>343 T2/LN1<br>650 MK<br>652 MK<br>615 NG<br>617 NG<br>619 NG   | Feed Pump<br>Without Gasket<br>Repl. Bosch: 0 440 008<br>994 | 0000902150<br>0020914901                                 | <b>TM23723</b><br>   |
| 979 ACCELO<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3                                 | Feed Pump  | 0000906050   | <b>TM23728</b><br>   |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3                             | Feed Pump  | 0000907350   | <b>TM23750</b><br>   |
| 363 LP 2226/6X4<br>363 LP 2232/6X4<br>363 LPB 2226/6X4<br>363 LPK 2226/6X4<br>363 LPK 2232/6X4<br>363 LPS 2226/6X4<br>363 LPS 2232/6X4 | Feed Pump  | 0000900550S<br>0010917801S                               | <b>TM36757</b><br> |
| 363 LP 2226/6X4<br>363 LP 2232/6X4<br>363 LPB 2226/6X4<br>363 LPK 2226/6X4<br>363 LPK 2232/6X4<br>363 LPS 2226/6X4<br>363 LPS 2232/6X4 | Feed Pump<br>Repl. Bosch: 0 440 008<br>027 S                 | 0000900650S<br>0010918401S                               | <b>TM36758</b><br> |
| 979 ACCELO<br>375 ACTROS<br>375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO  | Feed Pump  | 0030917401   | <b>TM23752</b><br> |
| 979 ACCELO<br>375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3                                     | Repair Kit, Feed Pump  | 0000902051S<br>0000900751S<br>0000924105S<br>0000901351S | <b>TM24070</b><br> |






| TM No.  | Replaces Ref. No:        | Description                   | Model / Details  |
|---|--------------------------|-------------------------------|--|
| <b>TM23641</b><br>   | 0000910840               | Repair Kit, Feed Pump         | 314 LP   |
|   | 0000910640<br>0000900151 | Repl. Bosch: 2 447 010<br>017 | 316 LP<br>318 LP<br>328 T2/L<br>338 L 1418<br>338 LK 1418<br>338 LP 1418   |
| <b>TM24054</b><br>   | 0000900210               | Repair Kit, Feed Pump         | 314 LP   |
|   | 0005861307               | Repl. Bosch: 2 447 010<br>011 | 318 LP<br>328 T2/L<br>336 LP 1924<br>338 L 1418<br>338 LK 1418<br>338 LP 1418  |
| <b>TM23221</b><br>   | 0000912190               | Hand Pump, Feed Pump          | 376 L 1117 MBTC-USA  |
|   |                          | Repl. Bosch: 0 440 011<br>007 | 376 L 1319 MBTC-USA<br>386 L 1625,1725<br>386 L 1633<br>386 L 2325,2425,LA<br>2425/6X6<br>386 LB 2325,2425<br>386 LK 2325,2425 |
| <b>TM36759</b><br> | 0000908850               | Hand Pump, Feed Pump          | 314 LP   |
|   |                          | Repl. Bosch: 2 447 222<br>125 | 318 LP<br>328 T2/L<br>336 LP 1924<br>338 L 1418<br>338 LK 1418<br>338 LP 1418  |
| <b>TM36760</b><br> | 0000910990               | Hand Pump, Feed Pump          | 655 SK   |
|   |                          | Repl. Bosch: 0 440 011<br>002 | 656 SK   |
| <b>TM36761</b><br> | 0000904050               | Hand Pump, Feed Pump          | 695 L 1620   |
|   | 0000911490               | Repl. Bosch: 2 447 010<br>020 | 695 LK 1620<br>384 OF SERIES<br>693 1720<br>693 1720 K   |
| <b>TM24115</b><br> | 0010914501               | Hand Pump, Feed Pump          | 312 L 312  |
|   | 0000911101               | Repl. Bosch: 2 447 222        | 314 LP   |
|   | 0000900050               | 023                           | 318 LP   |
|   | 0000910790               |                               | 328 T2/L<br>341 L 1112<br>341 L 1114<br>341 L 911  |












| Model / Details  | Description  | Replaces Ref. No:                         | TM No.  |
|--|--|---|---|
| -  | Intake Manifold  | 6110940080                                | <b>TM36762</b><br>   |
| -  | Intake Manifold  | 6110940180                                | <b>TM36763</b><br>   |
| 906 SPRINTER<br>906 SPRINTER   | Intake Manifold  | 6460901637<br>6460903137                  | <b>TM36764</b><br>   |
| 979 ACCELO<br>375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3 | Sensor, Intake Manifold<br>Repl. Bosch: 0 281 002<br>244 | 0041531828<br>0041531928                  | <b>TM11761</b><br> |
| 979 ACCELO<br>375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3 | Sensor, Intake Manifold<br>Repl. Bosch: 0 281 002<br>468 | 0041537028<br>0041537628                  | <b>TM11762</b><br> |
| -  | -  | 51089020054<br>51089020078<br>51089020079 | <b>TM01278</b><br> |
| -  | -  | 5410980280<br>5410980380<br>5410980480    | <b>TM01312</b><br> |





| TM No.  | Replaces Ref. No: | Description   | Model / Details  |
|---|-------------------|---|--|
| <b>TM36765</b><br>   | 4421410880        | Gasket, Intake Manifold   | 650 MK   |
|   | 4421410980        |   | 652 MK<br>653 MK<br>625 SK<br>655 SK<br>656 SK<br>657 SK   |
| <b>TM01348</b><br>   | 4571410080        | Gasket, Intake Manifold   | 375 AXOR   |
|   |                   |   | 374 AXOR 2<br>940 AXOR 2<br>942 AXOR 2<br>943 AXOR 2<br>944 AXOR 2<br>695 LS 1634EL  |
| <b>TM01357</b><br>  | 9041410280        | Gasket, Intake Manifold   | 979 ACCELO   |
|   |                   |   | 375 ACTROS<br>375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO  |
| <b>TM01380</b><br> | 9061410180        | Gasket, Intake Manifold   | 979 ACCELO   |
|   | 9061410480        |   | 375 ACTROS<br>375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO  |
| <b>TM36766</b><br> | 4421411880        | Gasket, Intake Manifold<br>With Silicone Line   | 363 LP 2226/6X4  |
|   |                   |   | 363 LPB 2226/6X4<br>363 LPK 2226/6X4<br>363 LPS 2226/6X4<br>386 L 1625,1725<br>386 L 1633<br>386 L 2325,2425,LA<br>2425/6X6            |
| <b>TM01346</b><br> | 4571420180        | Gasket, Intake Manifold   | 375 AXOR   |
|   |                   |   | 374 AXOR 2<br>940 AXOR 2<br>942 AXOR 2<br>943 AXOR 2<br>944 AXOR 2<br>958 AXOR 2   |
| <b>TM23263</b><br> | 0018354447        | Fuel Filter<br>Repl. Mann: WDK 725<br>Repl. Hengst: H70WDK1<br>16x1,5/ø62xø71/ø76/155 | 634 TOURO  |
|   |                   |   | 628 CITARO<br>628 CONECTO<br>671 CONECTO<br>444 TOURINO<br>444 TOURINO(O 510)<br>444 MBC-FAHRGESTELL<br>EURO 3 634 TOURO<br>628 CITARO |



| Model / Details  | Description   | Replaces Ref. No:                                    | TM No.  |
|--|---|--|---|
| 688 914<br>371 2524/6X2/48 OT-<br>TOMARSAN/TUERKEI   | Fuel Filter<br>Repl. Bosch: 2 447 010<br>042  | 0000900407<br>0000900807                             | <b>TM23510</b><br>   |
| 979 ACCELO<br>375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3     | Fuel Filter<br>Repl. Mann: WK 1080/7 x<br>Repl. Hengst: H701WK<br>1-14 UNS/ø108x3 3/4-<br>10UNS/216 | 0004771302<br>0004770103                             | <b>TM23744</b><br>   |
| 979 ACCELO<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3 | Fuel Filter<br>Repl. Mann: PU 999/1 x<br>Repl. Hengst: E500K-<br>P02D36<br>ø95xø14/ø46/204          | 5410900051<br>5410900151<br>5410920305<br>5410920405 | <b>TM23739</b><br>   |
| 375 ATEGO<br>628 CITARO<br>671 CONECTO   | Fuel Filter<br>Repl. Mann: WK 1060/3 x<br>Repl. Hengst: H7090WK30<br>1-14 UNS/ø108/146              | 3754770002   | <b>TM23274</b><br> |
| 979 ACCELO<br>375 ACTROS<br>375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO              | Fuel Filter<br>Repl. Mann: PU 1046/1 x<br>Repl. Hengst: E52KPD36<br>ø44,9xø91,8/ø27/102,7           | 0000901551<br>0000901251<br>9060900051<br>9060920105 | <b>TM23359</b><br> |
| 328 T2/L<br>338 L 1418<br>338 LK 1418<br>338 LS 1418<br>343 T2/L<br>343 T2/LN1<br>345 L 1418 MBTC-USA  | Fuel Filter<br>Repl. Hengst: E10KP D10<br>ø13xø83/ø13/146   | 0004773515<br>0004774015<br>0004774515<br>3554700192 | <b>TM23211</b><br> |
| 620 NG<br>621 NG<br>622 NG<br>623 NG<br>624 NG<br>688 OF 809<br>688 OF SERIES                          | Fuel Filter<br>Repl. Bosch: 2 457 434<br>010  | 0004770702<br>3445867207                             | <b>TM23717</b><br> |





| TM No.  | Replaces Ref. No:        | Description                                     | Model / Details   |
|---|--------------------------|---|---|
| <b>TM23894</b><br>   | 0004702190               | Fuel Filter                                     | 979 ACCELO  |
|   | 0004700469               | Complete  | 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3                                |
| <b>TM23754</b><br>   | 5410900452               | Fuel Filter                                     | 979 ACCELO  |
|   | 5410900552<br>5410900852 |   | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3                            |
| <b>TM23267</b><br>   | 0000900751               | Repair Kit, Fuel Filter                         | 979 ACCELO  |
|   | 0000901351<br>0000924105 | Repl. Mann: PU 50 z<br>Repl. Hengst: E11S03 D65 | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3                            |
| <b>TM36767</b><br> | 4570703732               | Pipe, Fuel Filter                               | 934 ACTROS 2/3  |
|   | 4570704832               |   | 375 AXOR<br>374 AXOR 2<br>940 AXOR 2<br>942 AXOR 2<br>943 AXOR 2<br>944 AXOR 2                                      |
| <b>TM36769</b><br> | 6110704832               | Pipe, Fuel Filter                               | -   |
| <b>TM23473</b><br> | 0004770002               | Precleaner, Fuel Filter                         | 363 LP 2226/6X4   |
|   | 0000927901               | Repl. Bosch: 1 457 434<br>000                   | 363 LP 2232/6X4<br>363 LPB 2226/6X4<br>363 LPK 2226/6X4<br>363 LPK 2232/6X4<br>363 LPS 2226/6X4<br>363 LPS 2232/6X4 |
| <b>TM23774</b><br> | 0004774508               | Head, Fuel Filter                               | 979 ACCELO  |
|   |                          |   | 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3                                |



| Model / Details  | Description  | Replaces Ref. No:        | TM No.  |
|--|--|--------------------------|---|
| 979 ACCELO<br>375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3         | Head, Fuel Filter<br>Without Sensor                  | 0004774508S              | <b>TM36770</b>  |
|  |  |                          |    |
| 979 ACCELO<br>375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3         | Cover, Fuel Filter<br>Plastic<br>Te112x3/85,5x25Nm   | 0000925208<br>0000924708 | <b>TM23350</b>  |
|  |  |                          |    |
| 979 ACCELO<br>375 ACTROS<br>375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO                  | Cover, Fuel Filter<br>Plastic<br>Te55x2/36,5x25Nm    | 0000900087               | <b>TM36771</b>  |
|  |  |                          |    |
| 979 ACCELO<br>375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3         | Bowl, Fuel Filter                                    | 0004772516<br>0004773516 | <b>TM23766</b>  |
|  |  |                          |  |
| 312 L 312<br>314 LP<br>316 LP<br>318 LP<br>328 T2/L<br>341 L 1112<br>341 L 1114                            | Bowl, Fuel Filter<br>Repl. Bosch: 2 459 999<br>002   | 0000910040               | <b>TM23352</b>  |
|  |  |                          |  |
| 312 L 312<br>314 LP<br>316 LP<br>318 LP<br>328 T2/L<br>336 LP 1924<br>336 LPS 1924                         | Gasket, Fuel Filter<br>Repl. Bosch: 2 440 109<br>005 | 0009970040               | <b>TM36772</b>  |
|  |  |                          |  |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 | Fuel Tank  | 9414700401               | <b>TM23851</b>  |
|  |  |                          |  |





| TM No.  | Replaces Ref. No: | Description                     | Model / Details  |
|---|-------------------|---------------------------------|--|
| <b>TM36773</b><br>   | 9314700401        | Fuel Tank                       | 950 ACTROS   |
|   | 9424700401        | 400L, Aluminium<br>1250x640x560 | 952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3                       |
| <b>TM23850</b><br>   | 9414701101        | Fuel Tank                       | 950 ACTROS   |
|   | 9414700201        | 300L, Steel<br>945x560x640      | 952 ACTROS<br>953 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3<br>934 ACTROS 2/3 |
| <b>TM36774</b><br>   | 9314700501        | Fuel Tank                       | 950 ACTROS   |
|   | 9424700501        | 500L, Aluminium<br>1550x560x640 | 952 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>934 ACTROS 2/3<br>934 ACTROS 2/3<br>930 ACTROS 2/3<br>375 AXOR       |
| <b>TM36775</b><br> | 9314700601        | Fuel Tank                       | 950 ACTROS   |
|   | 9424700601        | 590L, Aluminium<br>850x560x640  | 952 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>934 ACTROS 2/3<br>934 ACTROS 2/3<br>930 ACTROS 2/3<br>375 AXOR       |
| <b>TM36776</b><br> | 9424701001        | Fuel Tank                       | 952 ACTROS   |
|   |                   | 300L, Aluminium<br>65x700x700   | 954 ACTROS<br>930 ACTROS 2/3<br>934 ACTROS 2/3<br>930 ACTROS 2/3<br>375 AXOR<br>930 ACTROS 2/3<br>944 AXOR 2       |
| <b>TM23852</b><br> | 9344700101        | Fuel Tank                       | 952 ACTROS   |
|   | 9424701301        | 400L, Aluminium<br>910x700x700  | 954 ACTROS<br>932 ACTROS 2/3<br>934 ACTROS 2/3<br>954 ACTROS<br>375 AXOR<br>944 AXOR 2<br>954 AXOR 2               |
| <b>TM23866</b><br> | 9344700201        | Fuel Tank                       | 952 ACTROS   |
|   | 9424701101        | 460L, Aluminium<br>1070x700x700 | 954 ACTROS<br>934 ACTROS 2/3<br>954 ACTROS<br>375 AXOR<br>944 AXOR 2<br>954 AXOR 2                                 |





| Model / Details  | Description                                  | Replaces Ref. No:                                    | TM No.  |
|--|--|--|---|
| 950 ACTROS<br>952 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>934 ACTROS 2/3<br>954 ACTROS<br>934 ACTROS 2/3<br>940 AXOR 2 | Fuel Tank<br>550L, Aluminium<br>1275x700x700 | 9344700301<br>9424701401                             | <b>TM23853</b><br>   |
| 952 ACTROS<br>954 ACTROS<br>934 ACTROS 2/3<br>934 ACTROS 2/3<br>374 AXOR 2<br>375 AXOR<br>944 AXOR 2<br>954 AXOR 2       | Fuel Tank<br>650L, Aluminium<br>1500x700x700 | 9344700401<br>9344700001<br>9424700901               | <b>TM23856</b><br>   |
| 343 T2/L<br>346 L 1924<br>346 L 1928<br>346 LK 1924<br>346 LK 1928<br>346 LS 1924<br>346 LS 1928                         | Float, Fuel Tank                             | 0085428017<br>0055423817<br>0045423717<br>0025429417 | <b>TM23727</b><br>   |
| 385 NG<br>620 NG<br>621 NG<br>623 NG<br>624 NG<br>645 NG<br>646 NG   | Float, Fuel Tank                             | 0055424117   | <b>TM23746</b><br> |
| 674 LK/LN2<br>675 LK/LN2<br>676 LK/LN2<br>653 MK<br>654 MK<br>699 MK<br>387 NG   | Float, Fuel Tank                             | 0085428117<br>0055423917<br>0055422317               | <b>TM23724</b><br> |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3               | Float, Fuel Tank                             | 0125427917<br>0135427117<br>0135427617               | <b>TM23767</b><br> |
| 950 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3<br>375 AXOR             | Float, Fuel Tank                             | 0125429517<br>0135427317                             | <b>TM23770</b><br> |












| TM No.  | Replaces Ref. No: | Description  | Model / Details |
|---|-------------------|--|-----------------|
| <b>TM36777</b><br>   | 0085426917        | Float, Fuel Tank   | 950 ACTROS      |
|   | 0085429117        |  | 952 ACTROS      |
| 0115426117  | 953 ACTROS        |  |                 |
|   |                   |  | 954 ACTROS      |
|   |                   |  | 651 MK          |
|   |                   |  | 652 MK          |
|   |                   |  | 653 MK          |
| <b>TM23790</b><br>   | 0145428717        | Float, Fuel Tank<br>L : 503mm                              | 930 ACTROS 2/3  |
|   |                   |  | 932 ACTROS 2/3  |
|   |                   |  | 933 ACTROS 2/3  |
|   |                   |  | 934 ACTROS 2/3  |
|   |                   |  | 970 ATEGO       |
|   |                   |  | 972 ATEGO       |
|   |                   |  | 970 ATEGO 2     |
| <b>TM23769</b><br>   | 0135427217        | Float, Fuel Tank   | 950 ACTROS      |
|   |                   |  | 952 ACTROS      |
|   |                   |  | 953 ACTROS      |
|   |                   |  | 954 ACTROS      |
|   |                   |  | 374 AXOR 2      |
|   |                   |  | 950 AXOR 2      |
|   |                   |  | 952 AXOR 2      |
| <b>TM23726</b><br> | 3094700005        | Filler Cap, Fuel Tank<br>Cr/Ni Coating, Without Key<br>ø80 | 314 LP          |
|   | 3044700005        |  | 316 LP          |
| 3524700405  | 318 LP            |  |                 |
| 0004700005  | 328 T2/L          |  |                 |
|   | 336 LP 1924       |  |                 |
|   | 336 LPS 1924      |  |                 |
|   |                   |  | 338 L 1418      |
| <b>TM23311</b><br> | 0004711230        | Filler Cap, Fuel Tank<br>Cr/Ni Coating, With Key<br>ø80    | 328 T2/L        |
|   | 3024710130        |  | 699 MK          |
| <b>TM23699</b><br> | 0004700405        | Filler Cap, Fuel Tank<br>With Two Keys                     | 375 ACTROS      |
|   |                   |  | 950 ACTROS      |
|   |                   |  | 952 ACTROS      |
|   |                   |  | 953 ACTROS      |
|   |                   |  | 954 ACTROS      |
|   |                   |  | 930 ACTROS 2/3  |
|   |                   |  | 932 ACTROS 2/3  |
| <b>TM36778</b><br> | 4030700055        | Hose, Fuel Tank<br>ø3,2xø9x25m                             | 375 ACTROS      |
|   | 4030700255        |  | 950 ACTROS      |
| 4030700355  | 952 ACTROS        |  |                 |
| 4030780074  | 953 ACTROS        |  |                 |
|   | 954 ACTROS        |  |                 |
|   |                   |  | 930 ACTROS 2/3  |
|   |                   |  | 932 ACTROS 2/3  |










| Model / Details  | Description                         | Replaces Ref. No:        | TM No.         |
|--|-------------------------------------|--------------------------|----------------|
| 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3                     | Hose, Fuel Tank                     | 3054760126<br>3124760026 | <b>TM25774</b> |
| -  | Strainer, Fuel Tank<br>ø80 / 178 mm | -                        | <b>TM36779</b> |
| -  | -                                   | 0004710435               | <b>TM00078</b> |
| 375 AXOR<br>374 AXOR 2<br>940 AXOR 2<br>942 AXOR 2<br>943 AXOR 2<br>944 AXOR 2<br>958 AXOR 2                               | Fuel Pump                           | 4570910401<br>4570910601 | <b>TM23753</b> |
| 979 ACCELO<br>375 ACTROS<br>375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO                                  | -                                   | 0040910501               | <b>TM36780</b> |
| -  | Fuel Pump                           | 4570910501               | <b>TM36781</b> |
| 979 ACCELO<br>690 SPRINTER<br>904 SPRINTER<br>904 SPRINTER<br>690 SPRINTER<br>901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER | Valve, EGR<br>Blue                  | 0005450527               | <b>TM02204</b> |












| TM No.  | Replaces Ref. No:        | Description                          | Model / Details   |
|---|--------------------------|--------------------------------------|---|
| <b>TM36782</b><br>   | 0005450427               | Valve, EGR<br>Black                  | 638 V-CLASS<br>670 VARIO<br>638 V-CLASS<br>408 UNIMOG<br>904 SPRINTER<br>414 Vaneo<br>904 SPRINTER<br>901 SPRINTER                                |
| <b>TM36783</b><br>   | 9704920004               | Pipe, Exhaust<br>ø76,5/ø75/ø75       | 970 ATEGO<br>972 ATEGO<br>958 ATEGO 2<br>970 ATEGO 2<br>972 ATEGO 2   |
| <b>TM36784</b><br>   | 9704920001               | Pipe, Exhaust<br>ø76/ø75/ø75         | 375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>976 ATEGO<br>958 ATEGO 2<br>970 ATEGO 2<br>972 ATEGO 2   |
| <b>TM06364</b><br> | 9404921601<br>9404920401 | Pipe, Exhaust<br>ø88,9/ø100/ø88,9    | 374 AXOR 2<br>950 AXOR 2<br>952 AXOR 2<br>953 AXOR 2<br>954 AXOR 2  |
| <b>TM36785</b><br> | 6554904419               | Pipe, Exhaust<br>ø96,5/ø100/ø101,6   | 655 SK<br>656 SK<br>658 SK<br>659 SK<br>371 1938 S/35 LS/35<br>OTOMARSAN/TUERKEI<br>371 2635 S/6X4/32<br>OTOMARSAN/TUERKEI<br>371 2637 K/6X4/38,5 |
| <b>TM36786</b><br> | 6554904519               | Pipe, Exhaust<br>ø96,5/ø100/ø101,6   | 655 SK<br>656 SK<br>658 SK<br>659 SK<br>371 1938 S/35 LS/35<br>OTOMARSAN/TUERKEI<br>371 2635 S/6X4/32<br>OTOMARSAN/TUERKEI<br>371 2637 K/6X4/38,5 |
| <b>TM36787</b><br> | 6744901919<br>6744901119 | Pipe, Exhaust<br>ø50/ø50/ø89/ø50/ø89 | BM MODEL<br>674 LK/LN2<br>675 LK/LN2<br>678 LK/LN2  |



| Model / Details  | Description                | Replaces Ref. No:        | TM No.  |
|--|----------------------------|--------------------------|---|
| 950 ACTROS<br>952 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3 | Pipe, Exhaust<br>ø127/ø143 | 9424904319<br>9424903219 | <b>TM06335</b><br>   |
| 375 AXOR<br>374 AXOR 2<br>940 AXOR 2<br>944 AXOR 2<br>958 AXOR 2   | Pipe, Exhaust              | 9414900419               | <b>TM06336</b><br>   |
| 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3   | Pipe, Exhaust              | 9484905019<br>9484904519 | <b>TM06341</b><br>  |
| 375 AXOR<br>374 AXOR 2<br>940 AXOR 2<br>942 AXOR 2<br>943 AXOR 2<br>944 AXOR 2                                 | Pipe, Exhaust              | 3754902619<br>3754900319 | <b>TM36788</b><br> |
| 375 AXOR<br>940 AXOR 2<br>942 AXOR 2<br>943 AXOR 2<br>944 AXOR 2<br>958 AXOR 2                                 | Pipe, Exhaust<br>Front     | 9414900919<br>9414900719 | <b>TM36789</b><br> |
| 901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER   | Pipe, Exhaust              | 9014904921               | <b>TM06386</b><br> |
| 906 SPRINTER   | Pipe, Exhaust              | 9064900021               | <b>TM36790</b><br> |











| TM No.  | Replaces Ref. No:                      | Description                                   | Model / Details  |
|---|--|---|--|
| <b>TM36791</b>  | 9064900621                             | Pipe, Exhaust                                 | 906 SPRINTER   |
|    |  |   |  |
| <b>TM06383</b>  | 9064901981                             | Pipe, Exhaust                                 | 906 SPRINTER   |
|    |  |   |  |
| <b>TM06409</b>  | 9304900419                             | Pipe, Exhaust                                 | 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3<br>934 ACTROS 2/3       |
|   |  |   |  |
| <b>TM06408</b>  | 9304905419                             | Pipe, Exhaust                                 | 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3<br>934 ACTROS 2/3       |
|  |  |   |  |
| <b>TM36792</b>  | 9404901819                             | Pipe, Exhaust                                 | 950 AXOR 2<br>952 AXOR 2<br>953 AXOR 2<br>954 AXOR 2   |
|  |  |   |  |
| <b>TM06320</b>  | 9424902819                             | Flexible Pipe, Exhaust<br>ø153/ø129/ø127/ø128 | 950 ACTROS<br>952 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>934 ACTROS 2/3 |
|  |  |   |  |
| <b>TM06344</b>  | 9404901019<br>9404900519<br>9404920159 | Flexible Pipe, Exhaust<br>ø112/ø89,5/ø89/ø90  | 374 AXOR 2<br>950 AXOR 2<br>952 AXOR 2<br>953 AXOR 2<br>954 AXOR 2                           |
|  |  |   |  |







| Model / Details  | Description                           | Replaces Ref. No: | TM No.  |
|--|---------------------------------------|-------------------|---|
| 901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER                                   | Flexible Pipe, Exhaust<br>ø77/ø61/ø60 | 9014904519        | <b>TM36793</b><br>   |
| 673 LK/LN2<br>674 LK/LN2<br>675 LK/LN2<br>676 LK/LN2<br>677 LK/LN2<br>678 LK/LN2<br>679 LK/LN2 | Flexible Pipe, Exhaust<br>ø90x375     | 6744900065        | <b>TM06301</b><br>   |
| 673 LK/LN2<br>674 LK/LN2<br>675 LK/LN2<br>676 LK/LN2<br>677 LK/LN2<br>678 LK/LN2<br>679 LK/LN2 | Flexible Pipe, Exhaust<br>ø90x375     | -                 | <b>TM36794</b><br>  |
| 615 LK/LN2<br>670 T2/LN1<br>650 MK<br>651 MK<br>652 MK<br>653 MK<br>654 MK                     | Flexible Pipe, Exhaust<br>ø80x295     | 6204900365        | <b>TM06286</b><br> |
| -  | Flexible Pipe, Exhaust<br>ø80x295     | -                 | <b>TM36795</b><br> |
| 674 LK/LN2<br>675 LK/LN2<br>650 MK<br>651 MK<br>652 MK<br>653 MK<br>654 MK                     | Flexible Pipe, Exhaust<br>ø95x295     | 6204900465        | <b>TM06285</b><br> |
| 674 LK/LN2<br>675 LK/LN2<br>650 MK<br>651 MK<br>652 MK<br>653 MK<br>654 MK                     | Flexible Pipe, Exhaust<br>ø95x295     | -                 | <b>TM36796</b><br> |












| TM No.  | Replaces Ref. No:                      | Description                        | Model / Details  |
|---|--|------------------------------------|--|
| <b>TM06284</b><br>   | 6214900065                             | Flexible Pipe, Exhaust<br>ø105x295 | 650 MK<br>651 MK<br>652 MK<br>653 MK<br>654 MK<br>645 NG<br>646 NG   |
| <b>TM36797</b><br>   | -                                      | Flexible Pipe, Exhaust<br>ø105x295 | 650 MK<br>651 MK<br>652 MK<br>653 MK<br>654 MK<br>645 NG<br>646 NG   |
| <b>TM06323</b><br>   | 9424904219<br>9424903119<br>9424902319 | Flexible Pipe, Exhaust             | 950 ACTROS<br>952 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3 |
| <b>TM06321</b><br> | 9424904119<br>9424903019               | Flexible Pipe, Exhaust             | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3     |
| <b>TM06334</b><br> | 9424902019<br>9424901019               | Flexible Pipe, Exhaust             | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS   |
| <b>TM36798</b><br> | 9424902719                             | Flexible Pipe, Exhaust             | 950 ACTROS<br>952 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>934 ACTROS 2/3                   |
| <b>TM06322</b><br> | 9424904019<br>9424902219<br>9424901219 | Flexible Pipe, Exhaust             | 930 ACTROS 2/3<br>932 ACTROS 2/3<br>934 ACTROS 2/3   |



| Model / Details  | Description                       | Replaces Ref. No:          | TM No.         |
|--|-----------------------------------|----------------------------|----------------|
| 979 ACCELO<br>375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>958 ATEGO 2<br>970 ATEGO 2       | Flexible Pipe, Exhaust<br>ø77     | 9704900265                 | <b>TM36799</b> |
| 970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>958 ATEGO 2<br>970 ATEGO 2<br>972 ATEGO 2      | Flexible Pipe, Exhaust<br>ø90x345 | 9734900165                 | <b>TM06345</b> |
| 975 ATEGO<br>975 ATEGO 2   | Flexible Pipe, Exhaust<br>ø90x230 | 9734900265                 | <b>TM36800</b> |
| 972 ATEGO<br>970 ATEGO 2   | Flexible Pipe, Exhaust<br>ø77x270 | 9404900365                 | <b>TM36801</b> |
| 673 LK/LN2<br>674 LK/LN2<br>676 LK/LN2   | 65 Flexible Pipe, Exhaust         | 6734900265                 | <b>TM36802</b> |
| 375 AXOR<br>940 AXOR 2<br>942 AXOR 2<br>943 AXOR 2<br>944 AXOR 2<br>958 AXOR 2                     | Flexible Pipe, Exhaust            | 9414900165                 | <b>TM06372</b> |
| 343 T2/L<br>343 T2/LN1<br>346 L 1924<br>346 LA 1924<br>346 LAK 1924<br>346 LAS 1924<br>346 LK 1924 | Clamp, Exhaust<br>ø85,5           | 3034930643<br>071555085502 | <b>TM06265</b> |










| TM No.  | Replaces Ref. No:            | Description              | Model / Details   |
|---|------------------------------|--------------------------|---|
| <b>TM06086</b><br>   | 071555104501                 | Clamp, Exhaust<br>ø104,5 | 950 AXOR 2<br>952 AXOR 2<br>953 AXOR 2<br>954 AXOR 2<br>957 ECONIC<br>343 T2/L<br>346 L 1924  |
| <b>TM06368</b><br>   | 071555100501<br>071555100500 | Clamp, Exhaust<br>ø100,5 | 957 ECONIC<br>343 T2/L<br>346 L 1928<br>346 LK 1928<br>346 LS 1928<br>650 MK<br>651 MK  |
| <b>TM06087</b><br>  | 071555114500                 | Clamp, Exhaust<br>ø114,5 | 397 1729 S<br>397 2629 K/6X4<br>397 2637 S/6X4<br>357 O 405   |
| <b>TM36803</b><br> | 071555068500                 | Clamp, Exhaust<br>ø68,5  | 679 LK/LN2<br>321 O 362   |
| <b>TM06310</b><br> | 9424900041<br>9424900341     | Clamp, Exhaust<br>ø135   | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3                              |
| <b>TM06293</b><br> | 6254920040                   | Clamp, Exhaust<br>ø100   | 650 MK<br>651 MK<br>652 MK<br>653 MK<br>654 MK<br>625 NG<br>645 NG  |
| <b>TM06291</b><br> | 071555078502                 | Clamp, Exhaust<br>ø78,5  | 360 L 1817,1819/6X4<br>360 L 1819/6X4<br>363 LP 2226/6X4<br>363 LP 2232/6X4<br>363 LPB 2226/6X4<br>363 LPK 2226/6X4<br>363 LPK 2232/6X4 |










| Model / Details  | Description              | Replaces Ref. No:                        | TM No.  |
|--|--------------------------|--|---|
| 375 AXOR<br>940 AXOR 2<br>942 AXOR 2<br>943 AXOR 2<br>944 AXOR 2<br>958 AXOR 2<br>651 MK       | Clamp, Exhaust<br>ø110,5 | 071555110501<br>6524920640               | <b>TM06088</b><br>   |
| 950 AXOR 2<br>952 AXOR 2<br>953 AXOR 2<br>957 ECONIC<br>384 L 1214<br>384 L 1215<br>384 L 1218 | Clamp, Exhaust<br>ø94,5  | 071555094502<br>071555094501             | <b>TM06308</b><br>   |
| 375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>976 ATEGO<br>958 ATEGO 2<br>970 ATEGO 2<br>972 ATEGO 2  | Clamp, Exhaust<br>ø75,5  | 071555075502<br>071555075501             | <b>TM06307</b><br>  |
| -  | Clamp, Exhaust<br>ø80,5  | 071555080502                             | <b>TM36804</b><br> |
| 375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>976 ATEGO<br>958 ATEGO 2<br>970 ATEGO 2<br>972 ATEGO 2  | Clamp, Exhaust<br>ø77,5  | 9704900141                               | <b>TM36805</b><br> |
| 957 ECONIC<br>651 MK<br>652 MK<br>654 MK<br>395 NG<br>615 NG<br>616 NG                         | Clamp, Exhaust<br>ø90,5  | 6454921140<br>3954920040<br>071555090502 | <b>TM06229</b><br> |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3   | Clamp, Exhaust<br>ø131,5 | 9424920340                               | <b>TM36806</b><br> |






| TM No.  | Replaces Ref. No: | Description              | Model / Details |
|---|-------------------|--------------------------|-----------------|
| <b>TM36807</b><br>   | 6454920440        | Clamp, Exhaust<br>ø130,5 | 950 ACTROS      |
|   | 9424920140        |                          | 952 ACTROS      |
|   |                   |                          | 953 ACTROS      |
|   |                   |                          | 954 ACTROS      |
|   |                   |                          | 930 ACTROS 2/3  |
|   |                   |                          | 932 ACTROS 2/3  |
|   |                   |                          | 933 ACTROS 2/3  |
| <b>TM06367</b><br>   | 6734920140        | Clamp, Exhaust<br>ø74,5  | 375ATEGO        |
|   | 3133920340        |                          | 970 ATEGO       |
|   | 6684920040        |                          | 972 ATEGO       |
|   |                   |                          | 975 ATEGO       |
|   |                   |                          | 976 ATEGO       |
|   |                   |                          | 958 ATEGO 2     |
|   |                   |                          | 970 ATEGO 2     |
| <b>TM06331</b><br>   | 6764920040        | Clamp, Exhaust<br>ø90,5  | 970 ATEGO       |
|   |                   |                          | 972 ATEGO       |
|   |                   |                          | 975 ATEGO       |
|   |                   |                          | 976 ATEGO       |
|   |                   |                          | 375 ATEGO 2     |
|   |                   |                          | 958 ATEGO 2     |
|   |                   |                          | 970 ATEGO 2     |
| <b>TM36808</b><br> | 6684920340        | Clamp, Exhaust<br>ø79    | 375 ATEGO       |
|   |                   |                          | 970 ATEGO       |
|   |                   |                          | 972 ATEGO       |
|   |                   |                          | 975 ATEGO       |
|   |                   |                          | 958 ATEGO 2     |
|   |                   |                          | 970 ATEGO 2     |
|   |                   |                          | 972 ATEGO 2     |
| <b>TM06302</b><br> | 6744920040        | Clamp, Exhaust<br>ø95,5  | 375 ACTROS      |
|   |                   |                          | 375 ATEGO       |
|   |                   |                          | 970 ATEGO       |
|   |                   |                          | 972 ATEGO       |
|   |                   |                          | 975 ATEGO       |
|   |                   |                          | 976 ATEGO       |
|   |                   |                          | 375 ATEGO 2     |
| <b>TM36809</b><br> | 9484920040        | Clamp, Exhaust<br>ø135   | 950 ACTROS      |
|   |                   |                          | 952 ACTROS      |
|   |                   |                          | 953 ACTROS      |
|   |                   |                          | 930 ACTROS 2/3  |
|   |                   |                          | 932 ACTROS 2/3  |
|   |                   |                          | 933 ACTROS 2/3  |
| <b>TM06309</b><br> | 9429970290        | Clamp, Exhaust<br>ø128   | 950 ACTROS      |
|   |                   |                          | 952 ACTROS      |
|   |                   |                          | 953 ACTROS      |
|   |                   |                          | 954 ACTROS      |
|   |                   |                          | 930 ACTROS 2/3  |
|   |                   |                          | 932 ACTROS 2/3  |
|   |                   |                          | 933 ACTROS 2/3  |





| Model / Details  | Description                   | Replaces Ref. No:        | TM No.  |
|--|-------------------------------|--------------------------|---|
| 979 ACCELO<br>950 ACTROS<br>952 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>934 ACTROS 2/3 | Clamp, Exhaust<br>ø138        | 9429970090               | <b>TM06306</b><br>   |
| 976 ATEGO<br>976 ATEGO 2<br>673 LK/LN2<br>674 LK/LN2<br>675 LK/LN2<br>676 LK/LN2<br>677 LK/LN2             | Clamp, Exhaust<br>ø11x30x3    | 6744914541<br>6744912641 | <b>TM06363</b><br>   |
| -  | Clamp, Exhaust<br>ø88,9       | -                        | <b>TM36810</b><br>   |
| -  | Clamp, Exhaust<br>ø70         | -                        | <b>TM36811</b><br> |
| -  | Clamp, Exhaust<br>ø76,2       | -                        | <b>TM36812</b><br> |
| -  | Clamp, Exhaust<br>ø88,9xø93,6 | -                        | <b>TM36813</b><br> |
| -  | Clamp, Exhaust                | -                        | <b>TM36814</b><br> |










| TM No.     | Replaces Ref. No:   | Description                                      | Model / Details  |
|------------|---|--|--|
| TM06337    | 9404900101  | Silencer, Exhaust<br>102/ø101,6/397/565          | 374 AXOR 2<br>950 AXOR 2<br>952 AXOR 2<br>953 AXOR 2<br>954 AXOR 2<br>958 AXOR 2<br>957 ECONIC             |
|            |    |  |  |
| TM06421    | 3754900101  | Silencer, Exhaust                                | 375 ACTROS<br>375 AXOR<br>375 AXOR 2   |
|            | 3754900301  |  |  |
| TM06316    | 9424901501  | Silencer, Exhaust<br>ø130,5/<br>ø133/407/601/580 | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 |
|            | 9424903501  |  |  |
| TM06317    | 9424901301  | Silencer, Exhaust<br>ø132/ø132/407/601/580       | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 |
|            | 9424903301  |  |  |
| 9424902301 |   |  |  |
| TM06315    | 9424902701  | Silencer, Exhaust<br>ø130,5/<br>ø127/407/601/580 | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/  |
|            | 9424902101  |  |  |
| 9424901101 |   |  |  |
| 9424903701 |   |  |  |
| TM06312    | 9734900001  | Silencer, Exhaust<br>ø89/ø89/390/410/585         | 970 ATEGO<br>972 ATEGO<br>958 ATEGO 2<br>970 ATEGO 2<br>972 ATEGO 2<br>974 ATEGO 2<br>976 ATEGO 2          |
|            |  |  |  |
| TM06313    | 9704900001  | Silencer, Exhaust<br>ø76,1/<br>ø76,1/296/415/480 | 970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>958 ATEGO 2<br>970 ATEGO 2<br>972 ATEGO 2<br>975 ATEGO 2            |
|            |  |  |  |



| Model / Details  | Description  | Replaces Ref. No:                      | TM No.         |
|--|--|--|----------------|
| 651 MK<br>652 MK<br>653 MK<br>654 MK<br>625 SK<br>655 SK<br>656 SK   | Silencer, Exhaust<br>ø101,3/ø104,3/297/1150          | 6524900101                             | <b>TM06311</b> |
| 625 SK<br>655 SK<br>656 SK<br>658 SK<br>659 SK<br>371 1938 S/35 LS/35<br>OTOMARSAN/TUERKEI<br>371 2635 S/6X4/32<br>OTOMARSAN/TUERKEI | Silencer, Exhaust<br>ø101,5/ø101,5/<br>ø114/297/1160 | 6454902001                             | <b>TM06314</b> |
| 619 NG<br>620 NG<br>621 NG<br>623 NG<br>624 NG<br>396 OH SERIES<br>371 2622 K/6X4/38,5<br>OTOMARSAN/TUERKEI                          | Silencer, Exhaust<br>ø76,5/ø71/281/745               | 6204900001                             | <b>TM36815</b> |
| 674 LK/LN2<br>675 LK/LN2   | Silencer, Exhaust<br>ø90,5/<br>ø71/180/277/1000      | 6174902201<br>6744900001<br>6744900501 | <b>TM36816</b> |
| 675 LK/LN2<br>676 LK/LN2<br>677 LK/LN2<br>678 LK/LN2   | Silencer, Exhaust<br>ø90,5/ø90,5/234/1050            | 6764900501<br>6764900001               | <b>TM36817</b> |
| 950 ACTROS<br>952 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>934 ACTROS 2/3<br>375 AXOR                             | Silencer, Exhaust<br>ø131,5/407/601/580              | 9424902801<br>9424901601               | <b>TM06319</b> |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3                           | Silencer, Exhaust<br>ø130,5/<br>ø134/407/601/580     | 9424901401<br>9424903401<br>9424902401 | <b>TM06318</b> |










| TM No.  | Replaces Ref. No: | Description                                      | Model / Details   |            |                   |              |
|---|-------------------|--|---|------------|-------------------|--------------|
| <b>TM06210</b><br>   | 3834900201        | Silencer, Exhaust<br>ø130,5/<br>ø134/407/601/580 | 380 NG  |            |                   |              |
|   | 6734900001        |  | 381 NG  |            |                   |              |
| <b>TM06366</b><br>   | 9404900501        | Silencer, Exhaust<br>ø71/ø71/203/1060            | 383 NG  |            |                   |              |
|   |                   |  | 385 NG  |            |                   |              |
|   |                   |  | 615 NG  |            |                   |              |
|   |                   |  | 617 NG  |            |                   |              |
|   |                   |  | 619 NG  |            |                   |              |
|   |                   |  | 375 ACTROS  |            |                   |              |
| <b>TM06390</b><br>   | 9064900801        | Silencer, Exhaust                                | 375 AXOR  |            |                   |              |
|   |                   |  | 375 AXOR 2  |            |                   |              |
|   |                   |  | 950 AXOR 2  |            |                   |              |
|   |                   |  | 952 AXOR 2  |            |                   |              |
|   |                   |  | 953 AXOR 2  |            |                   |              |
| <b>TM36818</b><br> | 9064901201        | Silencer, Exhaust                                | 954 AXOR 2  |            |                   |              |
|   |                   |  | 906 SPRINTER  |            |                   |              |
|   |                   |  | <b>TM06394</b><br> | 9064902201 | Silencer, Exhaust | 906 SPRINTER |
|   |                   |  |   | 9064901601 |                   |              |
|   |                   |  | <b>TM06393</b><br> | 9064902101 | Silencer, Exhaust | 906 SPRINTER |
| 9064901501  |                   |  |   |            |                   |              |
| <b>TM06395</b><br> | 0004905014        | Silencer, Exhaust                                | 930 ACTROS 2/3  |            |                   |              |
|   | 0004908814        |  | 932 ACTROS 2/3  |            |                   |              |
|   | 0014900114        |  | 933 ACTROS 2/3  |            |                   |              |
|   | 0024900114        |  | 934 ACTROS 2/3  |            |                   |              |
|   |                   |  | 375 AXOR  |            |                   |              |
|   |                   |  | 375 AXOR 2  |            |                   |              |
|   |                   |  | 940 AXOR 2  |            |                   |              |



| Model / Details  | Description                     | Replaces Ref. No:                                    | TM No.  |
|--|---------------------------------|--|---|
| 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3<br>375 AXOR<br>940 AXOR 2<br>942 AXOR 2 | Silencer, Exhaust               | 0014900514<br>0024900514<br>0044900514               | <b>TM06419</b><br>   |
| 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3<br>375 AXOR<br>940 AXOR 2<br>942 AXOR 2 | Silencer, Exhaust               | 0014900414<br>0024900414<br>0044900414<br>0044908014 | <b>TM36819</b><br>   |
| 650 MK<br>651 MK<br>652 MK<br>653 MK<br>654 MK<br>645 NG<br>646 NG   | Repair Kit, Exhaust<br>ø105x295 | 6214900065S1   | <b>TM06412</b><br>  |
| 650 MK<br>651 MK<br>652 MK<br>53 MK<br>654 MK<br>645 NG<br>646 NG  | Repair Kit, Exhaust<br>ø105x295 | -  | <b>TM36820</b><br> |
| 615 LK/LN2<br>670 T2/LN1<br>650 MK<br>651 MK<br>652 MK<br>653 MK<br>654 MK                                   | Repair Kit, Exhaust<br>ø80x295  | 6204900365S1   | <b>TM06414</b><br> |
| 615 LK/LN2<br>670 T2/LN1<br>650 MK<br>651 MK<br>652 MK<br>653 MK<br>654 MK                                   | Repair Kit, Exhaust<br>ø80x295  | -  | <b>TM36821</b><br> |
| 674 LK/LN2<br>675 LK/LN2<br>650 MK<br>651 MK<br>652 MK<br>653 MK<br>654 MK                                   | Repair Kit, Exhaust<br>ø95x295  | 6204900465S1   | <b>TM06413</b><br> |










| TM No.  | Replaces Ref. No: | Description                               | Model / Details  |
|---|-------------------|---|--|
| <b>TM36822</b><br>   | -                 | Repair Kit, Exhaust<br>ø95x295            | 674 LK/LN2<br>675 LK/LN2<br>650 MK<br>651 MK<br>652 MK<br>653 MK<br>654 MK   |
| <b>TM06181</b><br>   | 3475040012        | Mounting, Exhaust<br>M10x1,5/ø55x35       | 336 LPS 1924<br>338 L 1418<br>338 LK 1418<br>338 LP 1418<br>338 LPS 1418<br>338 LS 1418  |
| <b>TM06444</b><br>  | 0019875340        | Mounting, Exhaust<br>M10x1,5/ø36,5x21     | 958 ATEGO 2<br>958 AXOR 2<br>309 T2/L<br>309 TL2/L<br>310 LF508 D/LF608 D<br>310 LT 608 D<br>310 T2/L                                    |
| <b>TM06375</b><br> | 9014920044        | Mounting, Exhaust<br>30x66x64             | 690 SPRINTER<br>900 SPRINTER<br>901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER<br>905 SPRINTER                             |
| <b>TM36823</b><br> | 6214900725        | Connecting Pipe, Exhaust<br>ø75/ø85,5/ø75 | 621 NG<br>624 NG<br>371 1922 K<br>OTOMARSAN/TUERKEI<br>371 2622 K/6X4/38,5<br>OTOMARSAN/TUERKEI<br>371 2622/6X2/48<br>OTOMARSAN/TUERKEI  |
| <b>TM36824</b><br> | 6214900625        | Connecting Pipe, Exhaust<br>ø75/ø76/ø75   | 621 NG<br>624 NG<br>371 1922 K OTOMARSAN/<br>TUERKEI<br>371 2622 K/6X4/38,5<br>OTOMARSAN/TUERKEI<br>371 2622/6X2/48<br>OTOMARSAN/TUERKEI |
| <b>TM36825</b><br> | 6554900125        | Connecting Pipe, Exhaust<br>ø75/ø84/ø75   | 655 SK<br>656 SK<br>657 SK<br>658 SK<br>659 SK<br>397 1729 S<br>397 2629 K/6X4   |



| Model / Details  | Description                              | Replaces Ref. No:                                    | TM No.  |
|--|--|--|---|
| 375 AXOR<br>374 AXOR 2<br>940 AXOR 2<br>942 AXOR 2<br>943 AXOR 2<br>944 AXOR 2                         | Exhaust Manifold<br>93x18x17             | 4571420601   | <b>TM36826</b><br>   |
| 979 ACCELO<br>375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>958 ATEGO 2             | Exhaust Manifold<br>46x17x17             | 9041401909   | <b>TM36827</b><br>   |
| 375 ACTROS<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>375 ATEGO 2<br>958 ATEGO 2           | Exhaust Manifold<br>Complete<br>67x15x17 | 9061420057S<br>9061421101S<br>9061421201S            | <b>TM36828</b><br>  |
| 375 AXOR<br>374 AXOR 2<br>940 AXOR 2<br>942 AXOR 2<br>943 AXOR 2<br>944 AXOR 2<br>958 AXOR 2           | Screw, Exhaust Manifold<br>M10x1,5/105   | 4579902001<br>4579901301<br>4479906104<br>4479905504 | <b>TM36829</b><br> |
| -375 AXOR<br>940 AXOR 2<br>942 AXOR 2<br>943 AXOR 2<br>944 AXOR 2<br>318 LP<br>343 T2/L                | Screw, Exhaust Manifold<br>M10x1,5/42    | 0009906005   | <b>TM25115</b><br> |
| 634 CBC - FAHRGESTELL<br>2-ACHSER<br>634 CBC - FAHRGESTELL<br>OC500 CNG GAS                            | Screw, Exhaust Manifold<br>M10x1,5/70    | 4579901001<br>4479905804<br>4479905204<br>4479907004 | <b>TM01549</b><br> |
| 979 ACCELO<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3 | Screw, Exhaust Manifold<br>M10x1,5/85    | 4579901201<br>4479906004<br>4479905404<br>4229900019 | <b>TM01611</b><br> |










| TM No.  | Replaces Ref. No:                      | Description                           | Model / Details  |
|---|--|---------------------------------------|--|
| <b>TM01636</b>  | -                                      | -                                     | -  |
|    |  |                                       |  |
| <b>TM01549</b>  | -                                      | -                                     | -  |
|    |  |                                       |  |
| <b>TM01611</b>  | -                                      | -                                     | -  |
|    |  |                                       |  |
| <b>TM01636</b>  | 9049900412<br>9049900312<br>9049900212 | Screw, Exhaust Manifold<br>M10x1,5/47 | 979 ACCELO<br>375 ACTROS<br>963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS<br>375 ATEGO                                    |
|  |  |                                       |  |
| <b>TM01624</b>  | 0019904605<br>0019904205<br>0009905705 | Screw, Exhaust Manifold<br>M10x1,5    | 979 ACCELO<br>375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3                                     |
|  |  |                                       |  |
| <b>TM01568</b>  | 4031420212                             | Bushing, Exhaust Manifold             | 979 ACCELO<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3                                 |
|  |  |                                       |  |
| <b>TM01271</b>  | 4031420380<br>4031420180               | Gasket, Exhaust Manifold              | 363 LP 2226/6X4<br>363 LP 2232/6X4<br>363 LPB 2226/6X4<br>363 LPK 2226/6X4<br>363 LPK 2232/6X4<br>363 LPS 2226/6X4<br>363 LPS 2232/6X4 |
|  |  |                                       |  |



| Model / Details  | Description  | Replaces Ref. No:                                    | TM No.  |
|--|--|--|---|
| 979 ACCELO<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3                   | Gasket, Exhaust Manifold   | 5411420180<br>5411420480<br>4601420080<br>5411420380 | <b>TM01313</b><br>   |
| 343 T2/L<br>345 L 2225<br>345 LS 1524/1525<br>346 L 1928<br>346 LK 1928<br>346 LS 1928<br>350 LS 1924A,1929              | Gasket, Exhaust Manifold   | 3504920080<br>6004920080                             | <b>TM00693</b><br>   |
| 979 ACCELO<br>384 L 1214<br>384 L 1215<br>384 L 1218<br>384 L 1414<br>384 L 1418 ,L 1418 E<br>384 LA 1418                | Gasket, Exhaust Manifold   | 3661420180<br>3661420480                             | <b>TM01305</b><br>   |
| 979 ACCELO<br>375 ACTROS<br>375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO                                | Gasket, Exhaust Manifold   | 9061420280<br>9061421180                             | <b>TM01163</b><br> |
| 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3<br>375 ATEGO<br>970 ATEGO<br>972 ATEGO              | Filter Set, SCR System<br>Repl. Mann: U 58/1 KIT<br>Repl. Hengst: E102U D179 | 0001420089<br>0001420289                             | <b>TM23776</b><br> |
| 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3<br>963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS    | Tank Cap, SCR System<br>Adblue Tank<br>ø40                                   | 0004701805<br>0004702405<br>0004702605<br>0004702705 | <b>TM25932</b><br> |
| 970 ATEGO 2<br>970 ATEGO<br>972 ATEGO 2<br>976 ATEGO<br>930 ACTROS 2/3<br>944 AXOR 2<br>933 ACTROS 2/3<br>934 ACTROS 2/3 | AdBlue Tank, SCR System  | 9304700815   | <b>TM01612</b><br> |












| TM No.  | Replaces Ref. No:                      | Description                                | Model / Details  |
|---|--|--|--|
| <b>TM36830</b><br>   | 9304700415                             | AdBlue Tank, SCR System                    | 930 ACTROS 2/3<br>375 AXOR<br>944 AXOR 2<br>934 ACTROS 2/3   |
| <b>TM01279</b><br>   | 4221440280                             | Gasket, Turbocharger                       | 650 MK<br>651 MK<br>652 MK<br>653 MK<br>654 MK<br>617 NG<br>619 NG   |
| <b>TM01273</b><br>  | 4221420080                             | Gasket, Turbocharger                       | 652 MK<br>620 NG<br>621 NG<br>622 NG<br>623 NG<br>624 NG<br>625 NG   |
| <b>TM02011</b><br> | 5411402603<br>5411402003<br>5411401603 | Pipe, Turbocharger<br>Right<br>ø47/ø47/ø51 | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 |
| <b>TM02009</b><br> | 5411402103<br>5411401203               | Pipe, Turbocharger<br>Left<br>ø47/ø47/ø51  | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 |
| <b>TM02012</b><br> | 5411402203<br>5411401303<br>5411400803 | Pipe, Turbocharger<br>Right<br>ø47/ø47/ø51 | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 |
| <b>TM02010</b><br> | 5411402503<br>5411401903<br>5411401503 | Pipe, Turbocharger<br>Left<br>ø47/ø47/ø51  | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 |



| Model / Details  | Description        | Replaces Ref. No:                                    | TM No.  |
|--|--------------------|--|---|
| 950 AXOR 2<br>343 T2/L<br>343 T2/LN1<br>346 L 1924<br>346 LK 1924<br>346 LK 1928<br>346 LS 1924            | Pipe, Turbocharger | 5411800922<br>5411800522                             | <b>TM01145</b><br>   |
| 375 AXOR<br>374 AXOR 2<br>940 AXOR 2<br>942 AXOR 2<br>943 AXOR 2<br>944 AXOR 2                             | Pipe, Turbocharger | 4571801722<br>4571801022                             | <b>TM36831</b><br>   |
| 979 ACCELO<br>950 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>934 ACTROS 2/3                             | Pipe, Turbocharger | 5421800322   | <b>TM36832</b><br>   |
| 979 ACCELO<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3     | Pipe, Turbocharger | 5421800922<br>5421800522                             | <b>TM01141</b><br> |
| 979 ACCELO<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3     | Pipe, Turbocharger | 5411801422<br>5421800822<br>5421800622<br>5421800422 | <b>TM01142</b><br> |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 | Pipe, Turbocharger | 5411801022<br>5411800322                             | <b>TM36833</b><br> |
| 375 AXOR<br>374 AXOR 2<br>940 AXOR 2<br>942 AXOR 2<br>943 AXOR 2<br>944 AXOR 2                             | Pipe, Turbocharger | 4570985707   | <b>TM36834</b><br> |








| TM No.  | Replaces Ref. No:                      | Description        | Model / Details  |
|---|--|--------------------|--|
| <b>TM36835</b><br>   | 4571801622                             | Pipe, Turbocharger | -  |
| <b>TM36836</b><br>   | 4571801222                             | Pipe, Turbocharger | 934 ACTROS 2/3<br>375 AXOR<br>374 AXOR 2<br>940 AXOR 2<br>942 AXOR 2<br>943 AXOR 2<br>944 AXOR 2           |
| <b>TM36837</b><br>   | 4571802020                             | Pipe, Turbocharger | 375 AXOR<br>374 AXOR 2<br>940 AXOR 2<br>942 AXOR 2<br>943 AXOR 2<br>944 AXOR 2<br>958 AXOR 2               |
| <b>TM36838</b><br> | 5421800120<br>5421800520               | Pipe, Turbocharger | 979 ACCELO<br>950 ACTROS<br>952 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>934 ACTROS 2/3 |
| <b>TM36839</b><br> | 5421800020<br>5421800420<br>5421800620 | Pipe, Turbocharger | 979 ACCELO<br>950 ACTROS<br>952 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>934 ACTROS 2/3 |
| <b>TM36194</b><br> | 5421801120                             | Pipe, Turbocharger | 979 ACCELO<br>950 ACTROS<br>952 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>934 ACTROS 2/3 |
| <b>TM36840</b><br> | 6111800620                             | Pipe, Turbocharger | 979 ACCELO<br>690 SPRINTER<br>901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER<br>905 SPRINTER |





| Model / Details  | Description        | Replaces Ref. No:        | TM No.  |
|--|--------------------|--------------------------|---|
| 375 ACTROS<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>375 ATEGO 2<br>958 ATEGO 2 | Pipe, Turbocharger | 9061871801               | <b>TM36841</b><br>   |
| 979 ACCELO<br>375 ACTROS<br>375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO    | Pipe, Turbocharger | 9062301556               | <b>TM36842</b><br>   |
| 906 SPRINTER<br>639 VIANO<br>906 SPRINTER<br>636 VIANO<br>639 VIANO<br>639 VITO              | Pipe, Turbocharger | 6461800120               | <b>TM36843</b><br>   |
| 906 SPRINTER<br>906 SPRINTER   | Pipe, Turbocharger | 6461800620               | <b>TM36844</b><br> |
| 906 SPRINTER   | Hose, Turbocharger | 9065282982<br>9065285382 | <b>TM36845</b><br> |
| 639 VIANO  | Hose, Turbocharger | 6395281882               | <b>TM36846</b><br> |
| 636 VIANO<br>639 VIANO   | Hose, Turbocharger | 6395282882<br>6395283782 | <b>TM36847</b><br> |





| TM No.  | Replaces Ref. No: | Description        | Model / Details  |
|---|-------------------|--------------------|--|
| <b>TM36848</b><br>   | 6385282882        | Hose, Turbocharger | 638 VITO<br>638 V-CLASS  |
| <b>TM36849</b><br>   | 6385282982        | Hose, Turbocharger | 638 VITO<br>638 V-CLASS  |
| <b>TM08401</b><br>  | 9015282282        | Hose, Turbocharger | 901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER                                 |
| <b>TM36850</b><br> | 6460980083        | Hose, Turbocharger | 906 SPRINTER<br>636 VIANO<br>639 VIANO   |
| <b>TM36851</b><br> | 9069970382        | Hose, Turbocharger | 375 ACTROS<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>375 ATEGO 2<br>958 ATEGO 2 |
| <b>TM36852</b><br> | 9015281882        | Hose, Turbocharger | 901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER                                 |
| <b>TM08351</b><br> | 9015284382        | Hose, Turbocharger | 690 SPRINTER<br>901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER<br>905 SPRINTER |



| Model / Details   | Description   | Replaces Ref. No:                                    | TM No.  |
|---|---|--|---|
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3                                | Hose, Turbocharger  | 5411800020<br>5411800420<br>5411800520<br>5411801020 | <b>TM01140</b><br>   |
| 979 ACCELO<br>375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3  | Accelerator Pedal   | 9413000104   | <b>TM01952</b><br>   |
| 376 LP 1219 MBTC-USA<br>376 LP 1419 MBTC-USA<br>376 LPS 1525 MBTC-USA<br>615 LK/LN2<br>650 MK<br>651 MK<br>652 MK                         | Repair Kit, Accelerator Pedal   | 6243000304   | <b>TM00944</b><br>   |
| 307 O 305<br>307 O 307<br>357 O 405<br>357 O 407  | Cylinder, Accelerator Pedal<br>Stroke: 85<br>Max. Operating Pres.: 10 Bar<br>Repl. Wabco: 421 411 306 0<br>Con-Rod: M8 / Port<br>Threads: M12x1,5 | 0004300226   | <b>TM00582</b><br> |
| 638 V-CLASS<br>670 VARIO<br>638 V-CLASS<br>690 SPRINTER<br>901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER                   | Pin, Accelerator Pedal  | 9013010674   | <b>TM36853</b><br> |
| 397 LP 1517<br>397 LP 1617 A MBSA-RSA<br>397 LP/LPK 1417,1617 MBSA-RSA<br>397 LPK 1617 MBSA-RSA<br>673 LK/LN2<br>674 LK/LN2<br>676 LK/LN2 | Accelerator Wire  | 6733010023   | <b>TM36854</b><br> |
| 901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER  | Accelerator Wire  | 9013001730   | <b>TM36855</b><br> |





| TM No.         | Replaces Ref. No: | Description | Model / Details |
|----------------|-------------------|-------------|-----------------|
| <b>TM01140</b> | -                 | -           | -               |
|                |                   |             |                 |
| <b>TM01952</b> | -                 | -           | -               |
|                |                   |             |                 |
| <b>TM00944</b> | -                 | -           | -               |
|                |                   |             |                 |
| <b>TM00582</b> | -                 | -           | -               |
|                |                   |             |                 |
| <b>TM36853</b> | -                 | -           | -               |
|                |                   |             |                 |
| <b>TM36854</b> | -                 | -           | -               |
|                |                   |             |                 |
| <b>TM36855</b> | -                 | -           | -               |
|                |                   |             |                 |



| Model / Details  | Description   | Replaces Ref. No:                                    | TM No.         |
|--|---|--|----------------|
| 668 T2/LN1<br>669 T2/LN1<br>670 T2/LN1<br>688 709<br>688 912<br>688 913<br>688 914                           | Mounting, Engine<br>With Support Metal<br>89x75,5x70                              | 6682420013   | <b>TM36856</b> |
| 667 VARIO<br>668 VARIO<br>670 VARIO  | Mounting, Engine<br>189x75,5x71,5   | 6682420513   | <b>TM36857</b> |
| 690 SPRINTER<br>901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER<br>905 SPRINTER<br>909 SPRINTER | Mounting, Engine<br>M12x1,5/M10x1,5   | 9012412513   | <b>TM02440</b> |
| 673 LK/LN2<br>674 LK/LN2<br>688 LO 914/42,5<br>688 LO 915/48<br>688 915E/31,5<br>667 VARIO<br>668 VARIO      | Mounting, Engine<br>ø20xø96,5x80  | 0002413613   | <b>TM36858</b> |
| 601 207 D/208 D<br>601 208/210<br>602 307 D/308 D<br>602 307 D/308D<br>602 308 D<br>602 308/310              | Mounting, Engine<br>ø16xø70x74  | 6012420013   | <b>TM36859</b> |
| 357 O 405<br>612 O 405<br>357 O 407<br>612 O 407<br>357 O 408<br>612 O 408<br>671 O 345                      | Mounting, Engine<br>Right, With One Metal<br>Sheet<br>M16x1,5/M12x1,5 / h:<br>135 | 3572400418<br>3572400118<br>6162400818<br>6162400718 | <b>TM00628</b> |
| 979 ACCELO<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3       | Mounting, Engine<br>Left, With One Metal Sheet<br>M16x1,5/M12x1,5 / h:<br>135     | 6712400117<br>3572400618<br>3572400318<br>3572400218 | <b>TM02389</b> |

| TM No.  | Replaces Ref. No:                                    | Description   | Model / Details  |
|---|--|---|--|
| <b>TM02437</b>  | 9402400917   | Mounting, Engine<br>Right<br>M14x1,5/M16x1,5/100x-<br>112,5x180   | 375 ACTROS<br>375 AXOR<br>375 AXOR 2<br>952 AXOR 2<br>953 AXOR 2<br>958 AXOR 2                               |
|    |  |   |  |
| <b>TM02432</b>  | 9402400817   | Mounting, Engine<br>Left<br>M14x1,5/M16x1,5/100x-<br>112,5x180  | 375 ACTROS<br>375 AXOR<br>375 AXOR 2<br>952 AXOR 2<br>953 AXOR 2<br>958 AXOR 2                               |
|    |  |   |  |
| <b>TM02402</b>  | 9412417713<br>9412415713<br>9412414713<br>9412411713 | Mounting, Engine<br>With One Metal Sheet<br>M14x1,5/M18x-<br>1,5/200x100x50x123,5                           | 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3<br>375 AXOR<br>940 AXOR 2<br>942 AXOR 2 |
|   |  |   |  |
| <b>TM02408</b>  | 9402401118   | Mounting, Engine<br>Without Metal Sheet, 55<br>ShA<br>M14x1,5/M18x-<br>1,5/100x96x130                       | 375 ACTROS<br>375 AXOR<br>374 AXOR 2<br>375 AXOR 2<br>950 AXOR 2<br>952 AXOR 2<br>953 AXOR 2                 |
|  |  |   |  |
| <b>TM02407</b>  | 9402401218   | Mounting, Engine<br>Without Metal Sheet, 65<br>ShA<br>M14x1,5/M18x-<br>1,5/100x96x130                       | 375 AXOR 2<br>950 AXOR 2<br>952 AXOR 2<br>953 AXOR 2<br>954 AXOR 2<br>958 AXOR 2<br>957 ECONIC               |
|  |  |   |  |
| <b>TM02430</b>  | 6292400218<br>6292400018<br>9402401318               | Mounting, Engine<br>With One Metal Sheet, 62<br>ShA<br>M14x1,5/M18x-<br>1,5/100x96x130                      | 950 AXOR 2<br>952 AXOR 2<br>953 AXOR 2<br>954 AXOR 2<br>958 AXOR 2<br>629 TRAVEGO<br>632 TRAVEGO             |
|  |  |   |  |
| <b>TM02403</b>  | 9412418813   | Mounting, Engine<br>With One Metal Sheet,<br>Casting Body,<br>65 ShA<br>M14x1,5/M18x-<br>1,5/200x100x50x121 | 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3<br>375 AXOR<br>374 AXOR 2<br>942 AXOR 2 |
|  |  |   |  |





| Model / Details  | Description  | Replaces Ref. No:                      | TM No.  |
|--|--|--|---|
| 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3<br>374 AXOR 2<br>940 AXOR 2<br>942 AXOR 2 | Mounting, Engine<br>With One Metal Sheet,<br>Casting Body,<br>55 ShA<br>M14x1,5/M18x-<br>1,5/200x100x50x120  | 9412418713                             | <b>TM02418</b><br>   |
| 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3<br>374 AXOR 2<br>940 AXOR 2<br>942 AXOR 2 | Mounting, Engine<br>With One Metal Sheet,<br>Casting Body,<br>55 ShA<br>M14x1,5/M18x-<br>1,5/200x100x50x115  | 9412419713                             | <b>TM02413</b><br>   |
| 930 ACTROS 2/3<br>934 ACTROS 2/3   | Mounting, Engine<br>Without Metal Sheet, Cast-<br>ing Body,<br>55 ShA<br>M14x1,5/M18x-<br>1,5/200x100x50x120 | 9412418313                             | <b>TM02429</b><br>  |
| 930 ACTROS 2/3<br>934 ACTROS 2/3   | Mounting, Engine<br>Without Metal Sheet, Cast-<br>ing Body,<br>70 ShA<br>M14x1,5/M18x-<br>1,5/200x100x50x120 | 9412418513                             | <b>TM02420</b><br> |
| 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3   | Mounting, Engine<br>Without Metal Sheet, Cast-<br>ing Body,<br>65 ShA<br>M14x1,5/M18x-<br>1,5/200x100x50x112 | 9412418213<br>9412418613<br>9412418413 | <b>TM02417</b><br> |
| 628 CITARO<br>633 INTEGRO<br>633 INTOURO<br>613 TOURISMO<br>632 TOURISMO<br>629 TRAVEGO<br>632 TRAVEGO         | Mounting, Engine<br>With Two Metal Sheets,<br>50 ShA<br>M14x1,5/M18x-<br>1,5/200x100x50x115                  | 6292400217<br>6292400017               | <b>TM02424</b><br> |
| 628 CITARO<br>628 CONECTO<br>671 CONECTO<br>628 SETRA  | Mounting, Engine<br>With Two Metal Sheets<br>M14x1,5/M18x-<br>1,5/200x100x50x120                             | 6282402317<br>6282400917               | <b>TM02422</b><br> |





| TM No.  | Replaces Ref. No: | Description  | Model / Details  |
|---|-------------------|--|--|
| <b>TM02401</b><br>   | 9412417913        | Mounting, Engine<br>With One Metal Sheet, 70<br>ShA<br>M14x1,5/M18x-<br>1,5/200x100x50x116,5 | 930 ACTROS 2/3   |
|   | 9412415913        |  | 932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3<br>696 L 2638<br>696 LK 2638<br>696 LS 2638 |
| <b>TM02425</b><br>   | 6282402017        | Mounting, Engine<br>With One Metal Sheet<br>M14x1,5/M18x-<br>1,5/200x100x50x123              | 696 L 1938   |
|   | 6282400717        |  | 696 LS 1938<br>693 1938<br>693 1938 S<br>693 1944 S<br>628 CITARO<br>671 CONECTO               |
| <b>TM36860</b><br>  | 9702400317        | Mounting, Engine<br>50 ShA<br>M16x1,5/205x198  | 979 ACCELO   |
|   |                   |  | 375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>375 ATEGO 2                   |
| <b>TM36861</b><br> | 9702400318        | Mounting, Engine<br>38 ShA<br>M16x1,5/M18x-<br>1,5/59x156x88x127                             | 979 ACCELO   |
|   |                   |  | 375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>958 ATEGO 2<br>970 ATEGO 2<br>972 ATEGO 2               |
| <b>TM36862</b><br> | 9732400318        | Mounting, Engine<br>50 ShA<br>M16x1,5/M18x-<br>1,5/59x156x88x127                             | 979 ACCELO   |
|   |                   |  | 375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>958 ATEGO 2<br>970 ATEGO 2<br>972 ATEGO 2               |
| <b>TM02423</b><br> | 6282402717        | Mounting, Engine<br>With Two Metal Sheets<br>M14x1,5/M18x-<br>1,5/200x100x50x122             | 628 CITARO   |
|   | 6282400117S       |  | 671 CONECTO  |
|   | 6282401717S       |  |  |
| <b>TM02419</b><br> | 9412416713        | Mounting, Engine<br>With One Metal Sheet, 58<br>ShA<br>M14x1,5/M18x-<br>1,5/200x100x50x116,5 | 930 ACTROS 2/3   |
|   |                   |  | 932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3<br>942 AXOR 2<br>943 AXOR 2<br>944 AXOR 2   |



| Model / Details  | Description  | Replaces Ref. No:                                    | TM No.  |
|--|--|--|---|
| 979 ACCELO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>970 ATEGO 2<br>972 ATEGO 2<br>975 ATEGO 2 | Mounting, Engine<br>38 ShA<br>M16x1,5/M18x-<br>1,5/59x156x88x127   | 9702400418   | <b>TM36863</b><br>   |
| 979 ACCELO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>970 ATEGO 2<br>972 ATEGO 2<br>975 ATEGO 2 | Mounting, Engine<br>50 ShA<br>M16x1,5/M18x-<br>1,5/59x156x88x127   | 9732400418   | <b>TM36864</b><br>   |
| 930 ACTROS 2/3<br>934 ACTROS 2/3   | Mounting, Engine<br>Without Metal Sheet, Cast-<br>ing Body,<br>60 ShA<br>M14x1,5/M18x-<br>1,5/200x100x50x123 | 9412418113   | <b>TM02416</b><br>   |
| 932 ACTROS 2/3<br>933 ACTROS 2/3   | Mounting, Engine<br>Without Metal Sheet<br>M14x1,5/M18x-<br>1,5/200x100x50x118,5                             | 9412417613<br>9412415613                             | <b>TM36865</b><br> |
| 930 ACTROS 2/3<br>934 ACTROS 2/3<br>628 CITARO<br>628 CONECTO                                  | Mounting, Engine<br>Without Metal Sheet<br>M14x1,5/M18x-<br>1,5/200x100x50x122                               | 9412417313<br>9412415313<br>9412414313<br>9412411313 | <b>TM02400</b><br> |
| 930 ACTROS 2/3<br>934 ACTROS 2/3<br>628 CITARO<br>628 CONECTO                                  | Mounting, Engine<br>Without Metal Sheet<br>M14x1,5/M18x-<br>1,5/200x100x50x124                               | 9412417113<br>9412415113<br>9412414113<br>9412411113 | <b>TM02396</b><br> |
| 930 ACTROS 2/3<br>934 ACTROS 2/3   | Mounting, Engine<br>Without Metal Sheet<br>M14x1,5/M18x-<br>1,5/200x100x50x123                               | 9412417513<br>9412415513<br>9412414513<br>9412411513 | <b>TM02398</b><br> |



| TM No.  | Replaces Ref. No: | Description   | Model / Details   |
|---|-------------------|---|---|
| <b>TM02397</b><br>   | 9412417213        | Mounting, Engine<br>Without Metal Sheet, Front,<br>60 ShA<br>M14x1,5/M18x-<br>1,5/200x100x50x116,5                | BM MODEL  |
|   | 9412415213        |   | 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3  |
| <b>TM02412</b><br>   | 9412418913        | Mounting, Engine<br>With One Metal Sheet,<br>Casting Body,<br>Rear, 67 ShA<br>M14x1,5/M18x-<br>1,5/200x100x50x115 | 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3<br>374 AXOR 2<br>940 AXOR 2<br>943 AXOR 2                          |
|   |                   |   |   |
| <b>TM36866</b><br>  | 9402400617        | Mounting, Engine<br>Left<br>M14x1,5/M16x-<br>1,5/100x120x187  | 374 AXOR 2<br>950 AXOR 2<br>954 AXOR 2<br>949 ZETROS  |
|   |                   |   |   |
| <b>TM36867</b><br> | 9402400717        | Mounting, Engine<br>Right<br>M14x1,5/M16x-<br>1,5/100x120x187   | 374 AXOR 2<br>950 AXOR 2<br>954 AXOR 2<br>949 ZETROS  |
|   |                   |   |   |
| <b>TM36868</b><br> | 9702400417        | Mounting, Engine<br>60 ShA<br>M16x1,5/205x198   | 970 ATEGO<br>970 ATEGO 2<br>974 ATEGO 2<br>694 L 1218/1318/1319<br>694 L 1418<br>694 LK 1218 - 1318 -<br>1319/42<br>695 L 1622 / L 1620 |
|   |                   |   |   |
| <b>TM02414</b><br> | 9412417813        | Mounting, Engine<br>With One Metal Sheet, 67<br>ShA<br>M14x1,5/M18x-<br>1,5/200x100x50x121                        | 696 L 1938  |
|   | 9412415813        |   | 696 LS 1938   |
|   | 9412414813        |   | 693 1938  |
|   | 9412411813        |   | 693 1938 S  |
|   |                   |   | 693 1944 S  |
|   |                   |   | 628 CITARO  |
|   |                   |   | 628 CONECTO   |
| <b>TM36869</b><br> | 6452400018        | Mounting, Engine<br>With One Metal Sheet,<br>Metal Surface<br>M16x1,5/M12x1,5                                     | 343 T2/L  |
|   | 6172400418        |   | 346 L 1924  |
|   | 3832400718        |   | 346 L 1928  |
|   |                   |   | 346 LK 1924   |
|   |                   |   | 346 LK 1928   |
|   |                   |   | 346 LS 1924   |
|   |                   |   | 346 LS 1928   |



| Model / Details   | Description  | Replaces Ref. No:                                    | TM No.  |
|---|--|--|---|
| 651 MK<br>652 MK<br>653 MK<br>654 MK<br>625 SK<br>655 SK<br>656 SK  | Mounting, Engine<br>With One Metal Sheet<br>M16x1,5/M12x1,5                              | 6522400318<br>6522400018<br>6522400118               | <b>TM00195</b><br>   |
| 652 MK<br>617 NG<br>301 O 303   | Mounting, Engine<br>Without Metal Sheet, 60<br>Sha<br>2 Bolts M16x1,5 / 1 Nut<br>M12x1,5 | 3012402917<br>3012401917                             | <b>TM36870</b><br>   |
| 650 MK<br>651 MK<br>652 MK<br>615 NG<br>616 NG<br>617 NG<br>396 OH SERIES   | Mounting, Engine<br>2 Bolts M16x1,5 / 2 Nut<br>M12x1,5                                   | 6172400017<br>3002400117                             | <b>TM02388</b><br>  |
| 397 OF SERIES<br>397 1419 MBSA-RSA<br>397 1419 S MBSA-RSA<br>397 2219 6X4 MBSA-RSA<br>397 2219 B/6X4 MB-<br>SA-RSA<br>397 2219 K/6X4 MB-<br>SA-RSA<br>300 O 303 | Mounting, Engine<br>2 Bolts M16x1,5 / 3 Nut<br>M12x1,5                                   | 3012403017<br>3972400417<br>3972400617<br>3972400717 | <b>TM36871</b><br> |
| 383 NG<br>385 NG  | Mounting, Engine<br>4 Bolts M16x1,5 / 3 Nut<br>M12x1,5                                   | 3832400317<br>3832401717<br>3832400917<br>3832400217 | <b>TM36872</b><br> |
| 653 MK<br>654 MK<br>619 NG<br>625 NG<br>625 SK<br>397 2426 /6X4<br>397 2426 B/6X4   | Mounting, Engine<br>With One Metal Sheet<br>4 Bolts M16x1,5 / 3 Nut<br>M12x1,5           | 6172400217   | <b>TM02386</b><br> |
| 620 NG<br>621 NG<br>622 NG<br>623 NG<br>624 NG<br>625 NG<br>645 NG  | Mounting, Engine<br>M16x1,5  | 6202400317   | <b>TM02383</b><br> |







| TM No.  | Replaces Ref. No:    | Description   | Model / Details                             |
|---|----------------------|---|---|
| <b>TM36873</b><br>   | 6202400717           | Mounting, Engine<br>M10x1,5/139x233   | 979 ACCELO                                  |
|   | 6202400017           |   | 950 ACTROS                                  |
|   | 6202400217           |   | 952 ACTROS                                  |
|   | 6202400117           |   | 954 ACTROS                                  |
|   |                      |   | 930 ACTROS 2/3                              |
|   | 932 ACTROS 2/3       |   | 934 ACTROS 2/3                              |
| <b>TM36874</b><br>   | 6582410013           | Mounting, Engine<br>M16x1,5   | 620 NG                                      |
|   | 6582410113           |   | 621 NG                                      |
|   | 6582410213           |   | 622 NG                                      |
|   |                      |   | 623 NG                                      |
|   |                      |   | 624 NG                                      |
|   |                      |   | 625 NG                                      |
|   | 645 NG               |   |   |
| <b>TM00942</b><br>   | 3862407218           | Mounting, Engine<br>Without Metal Sheet, Metal<br>Surface<br>M14x1,5/M12x1,5              | 344 L 1118                                  |
|   | 6152400218           |   | 344 LK 1118                                 |
|   | 6152400318           |   | 384 L 1214                                  |
|   | 6152400418           |   | 384 L 1215                                  |
|   |                      |   | 384 L 1218                                  |
|   |                      |   | 384 L 1414                                  |
|   | 384 L 1418 ,L 1418 E |   |   |
| <b>TM36875</b><br> | 6452400118           | Mounting, Engine<br>With One Metal Sheet<br>M16x1,5/M12x1,5 / h:<br>132                   | 343 T2/L                                    |
|   | 6172400318           |   | 346 L 1924                                  |
|   | 3872400218           |   | 346 L 1928                                  |
|   |                      |   | 346 LK 1924                                 |
|   |                      |   | 346 LK 1928                                 |
|   |                      |   | 346 LS 1924                                 |
|   | 346 LS 1928          |   |   |
| <b>TM02384</b><br> | 6452400418           | Mounting, Engine<br>With One Metal Sheet<br>M18x1,5/M14x1,5 / h:<br>130                   | 979 ACCELO                                  |
|   |                      |   | 950 ACTROS                                  |
|   |                      |   | 952 ACTROS                                  |
|   |                      |   | 953 ACTROS                                  |
|   |                      |   | 954 ACTROS                                  |
|   |                      |   | 930 ACTROS 2/3                              |
|   | 932 ACTROS 2/3       |   |   |
| <b>TM02394</b><br> | 6202400318           | Mounting, Engine<br>With Two Metal Sheets,<br>Metal Surface,<br>70 ShA<br>M18x1,5/M14x1,5 | 350 LS 1924A,1929,1930                      |
|   | 6452400318           |   | 350 LS 1932,1933                            |
|   |                      |   | 350 LS 1934                                 |
|   |                      |   | 386 L 1625,1725                             |
|   |                      |   | 386 L 1633                                  |
|   |                      |   | 386 L 2325,2425,LA<br>2425/6X6              |
|   | 386 LB 2325,2425     |   |   |
| <b>TM36876</b><br> | 6552410713           | Mounting, Engine<br>Right<br>M16x1,5  | 625 SK                                      |
|   | 6552410113           |   | 655 SK                                      |
|   |                      |   | 656 SK                                      |
|   |                      |   | 659 SK                                      |
|   |                      |   | 371 2624,2627/6X2/48<br>OTOMARSAN/TUERKEI   |
|   |                      |   | 371 2624K,2627K3027<br>6X4<br>38,5OTOMARSAN |





| Model / Details  | Description   | Replaces Ref. No:        | TM No.  |
|--|---|--------------------------|---|
| 625 SK<br>655 SK<br>656 SK<br>659 SK<br>371 2624,2627/6X2/48<br>OTOMARSAN/TUERKEI<br>371 2624K,2627K3027<br>6X4<br>38,5OTOMARSAN | Mounting, Engine<br>Left<br>M16x1,5   | 6552410613<br>6552410013 | <b>TM00119</b><br>   |
| 952 ACTROS<br>953 ACTROS   | Mounting, Engine<br>With One Metal Sheet, 65<br>ShA<br>M14x1,5/M18x-<br>1,5/200x100x50x115            | 9412417413<br>9412415413 | <b>TM02399</b><br>   |
| 624 NG   | Mounting, Engine<br>With Two Metal Sheets,<br>Metal Surface,<br>65 ShA<br>M18x1,5/M14x1,5 / h:<br>130 | 6452400918               | <b>TM36877</b><br>   |
| 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS   | Mounting, Engine<br>Rear, Right<br>M16x1,5/M18x1,5  | 9612416313               | <b>TM02450</b><br> |
| 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS   | Mounting, Engine<br>Rear, Left<br>M16x1,5/M18x1,5   | 9602412313<br>9602412413 | <b>TM02457</b><br> |
| 963 ACTROS MP4<br>964 AROCS  | Mounting, Engine<br>Rear<br>M16x1,5/M18x1,5   | 9602414313<br>9612417313 | <b>TM02462</b><br> |
| 375 AXOR<br>375 AXOR 2<br>950 AXOR 2<br>952 AXOR 2<br>953 AXOR 2   | Mounting, Engine<br>Rear<br>M18x1,5   | 9402402118               | <b>TM36878</b><br> |









| TM No.  | Replaces Ref. No:                                    | Description   | Model / Details  |
|---|--|---|--|
| <b>TM02438</b><br>   | 9602416313   | Mounting, Engine<br>Front, Right<br>M16x1,5/M18x1,5 | 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS |
| <b>TM02465</b><br>   | 9612414813<br>9612414313<br>9612419313               | Mounting, Engine<br>Front, Right<br>M16x1,5/M18x1,5 | 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS |
| <b>TM36879</b><br>  | 9602419213   | Mounting, Engine<br>Front, Left<br>M16x1,5/M18x1,5  | 963 ACTROS MP4<br>964 AROCS                                |
| <b>TM02453</b><br> | 9602417813<br>9602417313<br>9622410313               | Mounting, Engine<br>Front, Left<br>M16x1,5/M18x1,5  | 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS |
| <b>TM02452</b><br> | 9602417213<br>9602417713                             | Mounting, Engine<br>Front, Left<br>M16x1,5/M18x1,5  | 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS |
| <b>TM02459</b><br> | 9672410213   | Mounting, Engine<br>Front<br>M18x1,5                | 967 ATEGO 3  |
| <b>TM02449</b><br> | 9612411213<br>9622411213<br>9612411113<br>9622411113 | Mounting, Engine<br>Front<br>M16x1,5/M18x1,5        | 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS |



| Model / Details   | Description  | Replaces Ref. No:                      | TM No.  |
|---|--|--|---|
| 307 O 305<br>307 O 307<br>357 O 405<br>612 O 405<br>357 O 407<br>612 O 407<br>357 O 408 | Mounting, Engine<br>M14x1,5/M12x1,5                  | 3072400117<br>3072400017               | <b>TM00120</b><br>   |
| 387 NG<br>389 NG<br>391 NG<br>393 NG<br>395 NG<br>620 NG<br>621 NG                      | Mounting, Engine<br>M16x1,5/M12x1,5/<br>M14x1,5      | 3872400317<br>3872400417<br>3872400017 | <b>TM02382</b><br>   |
| 639 VIANO   | Mounting, Engine<br>40 ShA<br>M10x1,5/106x129        | 9062411013<br>9062411313<br>9062411813 | <b>TM00748</b><br>  |
| 639 VIANO   | Mounting, Engine<br>Front, 45 ShA<br>M10x1,5/106x129 | 9062411113<br>9062411213               | <b>TM02444</b><br> |
| 638 VITO<br>638 V-CLASS   | Mounting, Engine<br>ø12,25x80,5x70                   | 6382420313                             | <b>TM36880</b><br> |
| 906 SPRINTER  | Mounting, Engine<br>Rear<br>ø32,5                    | 9062420013                             | <b>TM02443</b><br> |
| 638 V-CLASS   | Mounting, Engine<br>Rear<br>ø100x137/M10x1,5         | 6382420013                             | <b>TM36881</b><br> |





| TM No.  | Replaces Ref. No:        | Description   | Model / Details  |
|---|--------------------------|---|--|
| <b>TM36882</b><br>   | 6382411413               | Mounting, Engine<br>Rear<br>M8x15                   | 638 VITO<br>638 V-CLASS                                    |
| <b>TM36883</b><br>   | 6382420113               | Mounting, Engine<br>Rear<br>M10x56,65               | 638 V-CLASS  |
| <b>TM36884</b><br>   | 4472410213               | Mounting, Engine<br>Front, Left<br>M10/168/128/140  | 447 VITO - 447 V CLASS                                     |
| <b>TM36885</b><br> | 4472410013               | Mounting, Engine<br>Front, Right<br>M10/168/128/140 | 447 VITO - 447 V CLASS                                     |
| <b>TM36886</b><br> | 9612414213<br>9612414713 | Mounting, Engine<br>Front, Right<br>M16x1,5/M18x1,5 | 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS |
| <b>TM02451</b><br> | 9602417113<br>9602417613 | Mounting, Engine<br>Front                           | 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS |
| <b>TM02455</b><br> | 9602412113               | Mounting, Engine<br>Rear, Right                     | 963 ACTROS MP4   |



| <b>Model / Details</b>                                     | <b>Description</b>                                 | <b>Replaces Ref. No:</b> | <b>TM No.</b>   |
|--|--|--------------------------|---|
| 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS | Mounting, Engine<br>Rear, Right<br>M16x1,5/M18x1,5 | 9612417213               | <b>TM02471</b><br>   |
| 963 ACTROS MP4<br>964 AROCS                                | Mounting, Engine<br>Rear<br>M16x1,5/M18x1,5        | 9602414213               | <b>TM36887</b><br>   |
| 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS | Mounting, Engine<br>Rear<br>M16x1,5/M18x1,5        | 9602412213               | <b>TM02456</b><br>   |
| 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS | Mounting, Engine<br>Front<br>M16x1,5/M18x1,5       | 9602419713               | <b>TM36888</b><br> |
| 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS | Mounting, Engine<br>Rear<br>M16x1,5/M18x1,5        | 9612416213               | <b>TM36889</b><br> |
| 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS | Mounting, Engine<br>Front<br>M16x1,5/M18x1,5       | 9602419813               | <b>TM36890</b><br> |
| 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS | Mounting, Engine<br>Rear, Right<br>M16x1,5/M18x1,5 | 9612416413               | <b>TM02454</b><br> |





| TM No.  | Replaces Ref. No: | Description        | Model / Details  |
|---|-------------------|--------------------|--|
| <b>TM02445</b><br> | 6682400217        | Repair Kit, Engine | 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3 |












| Model / Details  | Description   | Replaces Ref. No:                                    | TM No.  |
|--|---|--|---|
| 651 MK<br>652 MK<br>653 MK<br>654 MK<br>625 SK<br>655 SK<br>656 SK   | Main Cylinder<br>Repl. FTE: KG23031.0.2   | 0012957006   | <b>TM22412</b><br>   |
| 650 MK<br>651 MK<br>652 MK<br>653 MK<br>654 MK<br>684 OF SERIES<br>625 SK  | Main Cylinder<br>Repl. FTE: KG22019.1.1   | 0012957406   | <b>TM22415</b><br>   |
| 650 MK<br>651 MK<br>652 MK<br>653 MK<br>654 MK   | Main Cylinder<br>Fte Fag Type<br>Repl. FTE: KG190042.0.1<br>ø19,05                    | 0012957306   | <b>TM36891</b><br>   |
| 375 ACTROS<br>375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>958 ATEGO 2   | Main Cylinder<br>Fte Fag Type, Brake Fluid<br>Repl. FTE: KG20001.0.8<br>ø20,64        | 0012959106   | <b>TM22447</b><br> |
| 380 NG<br>381 NG<br>383 NG<br>385 NG<br>387 NG<br>389 NG<br>391 NG   | Main Cylinder<br>Fte Fag Type<br>Repl. FTE: KN3805J1<br>ø38,1                         | 0012950307<br>0012955307<br>0012958807<br>0022950407 | <b>TM21873</b><br> |
| 616 NG<br>617 NG<br>619 NG   | Main Cylinder<br>Fte Fag Type<br>Repl. FTE: KN28022D1<br>ø28,57                       | 0012954507<br>0012959607<br>0012955407               | <b>TM22414</b><br> |
| 308 L 608 E,L 708 E<br>308 L/LO 608 D<br>308 LO 608 D,LO 708 D/E<br>309 T2/L<br>309 TL2/L<br>310 LF 508 D/LF 608 D<br>310 LT 608 D | Main Cylinder<br>Without Ball Joint, Fte Fag<br>Type<br>Repl. FTE: KN2895A1<br>ø28,57 | 0002958307S<br>3082957007S                           | <b>TM36892</b><br> |












| TM No.  | Replaces Ref. No: | Description           | Model / Details       |
|---|-------------------|-----------------------|-----------------------|
| <b>TM22382</b><br>   | 0012956006        | Main Cylinder         | BM MODEL              |
|   | 0002956806        | Fte Fag Type          | 376 LP 1219 MBTC-USA  |
|   | 0012952906        | Repl. FTE: KG2395.1.7 | 376 LP 1419 MBTC-USA  |
|   |                   | ø23,81                | 376 LPS 1525 MBTC-USA |
| <b>TM22385</b><br>   | 0012953006        | Main Cylinder         | 620 NG                |
|   | 0012950806        | Fte Fag Type          | 621 NG                |
|   |                   | Repl. FTE: KG2604.1.1 | 623 NG                |
|   |                   | ø26,99                | 624 NG                |
| <b>TM36893</b><br>   | 0002956706        | Main Cylinder         | 373 O 302             |
|   | 0012955506        | Fte Fag Type          | 300 O 303             |
|   |                   | Repl. FTE: KG3401.0.2 |                       |
|   |                   | ø34,92                |                       |
| <b>TM22443</b><br> | 0022950706        | Main Cylinder         | 930 ACTROS 2/3        |
|   |                   | Mineral Oil           | 932 ACTROS 2/3        |
|   |                   | Repl. FTE:            | 933 ACTROS 2/3        |
|   |                   | MKG190110.4.2         | 934 ACTROS 2/3        |
| <b>TM22507</b><br> | 0002903212        | Main Cylinder         | 957 ECONIC            |
|   |                   |                       | 690 SPRINTER          |
|   |                   |                       | 901 SPRINTER          |
|   |                   |                       | 902 SPRINTER          |
| <b>TM22508</b><br> | 0022952107        | Main Cylinder         | 903 SPRINTER          |
|   | 0022950607        |                       | 904 SPRINTER          |
|   |                   |                       | 905 SPRINTER          |
|   |                   |                       | 909 SPRINTER          |
| <b>TM36894</b><br> | 6672900212        | Main Cylinder         | 408 UNIMOG            |
|   | 0012955206        | 19"                   | 690 SPRINTER          |
|   |                   |                       | 901 SPRINTER          |
|   |                   |                       | 902 SPRINTER          |
|   |                   |                       | 903 SPRINTER          |
|   |                   |                       | 904 SPRINTER          |



| Model / Details  | Description  | Replaces Ref. No:                                    | TM No.  |
|--|--|--|---|
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>957 ECONIC<br>628 CITARO<br>633 INTEGRO            | Main Cylinder<br>Brake Fluid<br>Repl. FTE: KG20001.0.10  | 0012959506<br>0012959306                             | <b>TM22416</b><br>   |
| 309 T2/L<br>309 TL2/L<br>310 LF 508 D/LF 608 D<br>310 LT 608 D<br>310 T2/L<br>313 T2/L<br>314 LP           | Main Cylinder<br>Repl. FTE: KG19046.1.2                  | 0012958706<br>0002957706<br>0012951506<br>3082957006 | <b>TM36895</b><br>   |
| 375 ACTROS<br>375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>375 ATEGO 2                 | Main Cylinder<br>Mineral Oil<br>Repl. FTE: MKG20003.4.2  | 0022951006   | <b>TM22489</b><br>   |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 | Main Cylinder<br>Brake Fluid<br>Repl. FTE: KG190084.0.2  | 0022950406   | <b>TM36896</b><br> |
| 374 AXOR 2<br>940 AXOR 2<br>942 AXOR 2<br>943 AXOR 2<br>944 AXOR 2<br>950 AXOR 2<br>952 AXOR 2             | Main Cylinder<br>Mineral Oil<br>Repl. FTE: MKG190110.4.1 | 0022950806   | <b>TM22490</b><br> |
| 958 ATEGO 2<br>375 AXOR<br>374 AXOR 2<br>940 AXOR 2<br>942 AXOR 2<br>943 AXOR 2<br>944 AXOR 2              | Main Cylinder<br>Brake Fluid<br>Repl. FTE: KG190084.0.1  | 0022950206   | <b>TM22488</b><br> |
| 328 T2/L<br>338 L 1418<br>338 LK 1418<br>338 LP 1418<br>338 LPS 1418<br>338 LS 1418<br>351 L 1514          | Main Cylinder  | 0024304101<br>3454307501<br>0024301401<br>0024302201 | <b>TM13697</b><br> |





| TM No.  | Replaces Ref. No: | Description               | Model / Details       |
|---|-------------------|---------------------------|-----------------------|
| <b>TM22514</b><br>   | 0012958606        | Main Cylinder             | 611 T1/TN             |
|   | 0012951106        | Repl. Sachs: 6284 600 110 | 601 207 D/208 D       |
|   | 0012957606        |                           | 601 208/210           |
|   | 0012957906        |                           | 601 209 D/210 D       |
|   |                   |                           | 602 307 D/308 D       |
|   |                   |                           | 602 307 D/308D        |
|   |                   |                           | 602 308 D             |
| <b>TM36897</b><br>   | 0002959606        | Main Cylinder             | 611 T1/TN             |
|   | 0002959706        | Fte Fag Type              | 601 207 D/208 D       |
|   |                   | Repl. FTE: KG19057.1.1    | 601 208/210           |
|   |                   |                           | 602 307 D/308 D       |
|   |                   |                           | 602 307 D/308D        |
|   |                   |                           | 602 308 D             |
| <b>TM36898</b><br>   | 0002904667S       | Repair Kit, Main Cylinder | 376 LP 1219 MBTC-USA  |
|   | 0002902612S       | For 096.120               | 376 LP 1419 MBTC-USA  |
|   |                   | Repl. FTE: RK23714 S      | 376 LPS 1525 MBTC-USA |
|   |                   |                           | 615 LK/LN2            |
|   |                   |                           | 380 NG                |
|   |                   |                           | 381 NG                |
|   |                   |                           | 383 NG                |
| <b>TM36899</b><br> | 0002900911S       | Repair Kit, Main Cylinder | 376 LP 1219 MBTC-USA  |
|   | 0005863129S       | For 096.095               | 376 LP 1419 MBTC-USA  |
|   |                   | Repl. FTE: RK38816K S     | 376 LPS 1525 MBTC-USA |
|   |                   |                           | 384 L 1214            |
|   |                   |                           | 384 L 1215            |
|   |                   |                           | 384 L 1218            |
|   |                   |                           | 384 L 1414            |
| <b>TM22474</b><br> | 0012955607        | Clutch Servo              | 958 ATEGO 2           |
|   |                   | Wabco Type, Brake Fluid   | 350 LS 1932,1933      |
|   |                   | Repl. Wabco: 970 051      | 350 LS 1934           |
|   |                   | 128 0                     | 386 L 1625,1725       |
|   |                   | ø100 / Stroke: 58,5       | 386 L 1633            |
|   |                   | 386 L 2325,2425,LA        |                       |
|   |                   |                           | 2425/6X6              |
|   |                   |                           | 386 LB 2325,2425      |
| <b>TM36901</b><br> | -                 | Clutch Servo              | -                     |
|   |                   | Wabco Type, Brake Fluid   |                       |
|   |                   | Repl. Wabco: 970 051      |                       |
|   |                   | 137 0                     |                       |
|   |                   | ø75 / Stroke: 85          |                       |
| <b>TM22085</b><br> | 0002951418        | Clutch Servo              | 650 MK                |
|   | 0002950918        | Wabco Type, Brake Fluid   | 651 MK                |
|   | 0002950218        | Repl. Wabco: 970 051      | 652 MK                |
|   |                   | 159 0                     | 653 MK                |
|   |                   | ø100 / Stroke: 75         | 654 MK                |
|   |                   |                           | 655 SK                |
|   |                   |                           | 656 SK                |



| Model / Details   | Description   | Replaces Ref. No:                                    | TM No.  |
|---|---|--|---|
| 653 MK<br>396 OH SERIES<br>625 SK<br>659 SK<br>356 O 404<br>382 O 500 M / 1728<br>634 O 500                       | Clutch Servo<br>Wabco Type, Brake Fluid<br>Repl. Wabco: 970 051<br>158 0<br>ø100 / Stroke: 75 | 0002951518<br>0002950618                             | <b>TM22408</b><br>   |
| 677 LK/LN2<br>679 LK/LN2<br>650 MK<br>651 MK<br>652 MK<br>653 MK<br>654 MK  | Clutch Servo<br>Wabco Type, Brake Fluid<br>Repl. Wabco: 970 051<br>151 0<br>ø85 / Stroke: 65  | 0002950818<br>0002950018                             | <b>TM22407</b><br>   |
| 958 ATEGO 2<br>384 OF SERIES<br>685 OF SERIES<br>368 OH SERIES<br>382 OH SERIES<br>390 OH SERIES<br>684 OH SERIES | Clutch Servo<br>Wabco Type, Brake Fluid<br>Repl. Wabco: 970 051<br>190 0<br>ø85 / Stroke: 60  | 0002540147   | <b>TM22475</b><br>   |
| 620 NG<br>621 NG<br>623 NG<br>624 NG  | Clutch Servo<br>Wabco Type, Brake Fluid<br>Repl. Wabco: 970 051<br>131 0<br>ø80 / Stroke: 72  | 0012952207<br>0012952107<br>0012953107<br>0012953907 | <b>TM22388</b><br> |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3        | Clutch Servo<br>Wabco Type, Brake Fluid<br>Repl. Wabco: 970 051<br>405 0<br>ø100 / Stroke: 85 | 0002540047<br>0002540247<br>0002952818               | <b>TM22094</b><br> |
| 695 L 1632<br>695 L 1634<br>695 LS 1632<br>695 LS 1634<br>695 LS 1634EL<br>695 LS 1634EL 1635 S<br>696 L 1938     | Clutch Servo<br>Wabco Type, Brake Fluid<br>Repl. Wabco: 970 051<br>164 0<br>ø100 / Stroke: 85 | 0002951318<br>0002950718                             | <b>TM22478</b><br> |
| 677 LK/LN2<br>617 NG<br>620 NG<br>621 NG<br>623 NG<br>624 NG<br>625 NG  | Clutch Servo<br>Wabco Type, Brake Fluid<br>Repl. Wabco: 970 051<br>114 0<br>ø75 / Stroke: 67  | 0012954706<br>0012954906<br>0002959906               | <b>TM22716</b><br> |





| TM No.  | Replaces Ref. No:        | Description  | Model / Details  |
|---|--------------------------|--|--|
| <b>TM22732</b><br>   | 0002540347               | Clutch Servo   | 382 O 500 M / 1728   |
|   | 0002953518               | Wabco Type, Brake Fluid<br>Repl. Wabco: 970 051<br>436 0 | 634 O 500<br>634 TOURO<br>671 CONECTO<br>671 O 345<br>613 TOURISMO<br>634 IBC 1836 / OC 500 RF |
| <b>TM22482</b><br>   | 0002570177               | Clutch Servo   | 375 ACTROS   |
|   | 0002570377<br>0002953418 | Haldex Type, Brake Fluid<br>Repl. Haldex: 321 027 001    | 970 ATEGO<br>972 ATEGO<br>976 ATEGO<br>958 ATEGO 2<br>970 ATEGO 2<br>972 ATEGO 2               |
| <b>TM21841</b><br>  | 0002954018               | Clutch Servo   | 375 ACTROS   |
|   | 0002570277               | Haldex Type, Mineral Oil<br>Repl. Haldex: 321 025 001    | 970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>970 ATEGO 2<br>972 ATEGO 2                 |
| <b>TM22409</b><br> | 0002540447               | Clutch Servo   | 930 ACTROS 2/3   |
|   |                          | Repl. Wabco: 970 051<br>441 0                            | 932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS |
| <b>TM22480</b><br> | 0002500062               | Clutch Servo   | 950 ACTROS   |
|   | 0002500562<br>0002501562 | Wabco Type<br>Repl. Wabco: 970 150<br>001 0              | 952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3   |
| <b>TM36902</b><br> | 0002950660S              | Repair Kit, Clutch Servo                                 | 958 ATEGO 2  |
|   |                          | For 096.084<br>Repl. Wabco: 970 051 906<br>2 S           | 350 LS 1932,1933<br>350 LS 1934<br>386 L 1633<br>386 LS 1630<br>386 LS 1633<br>388 L 1929      |
| <b>TM36903</b><br> | 0002903267S              | Repair Kit, Clutch Servo                                 | 620 NG   |
|   | 0002900667S              | For 096.146<br>Repl. Wabco: 970 051 903<br>2 S           | 621 NG<br>622 NG<br>623 NG<br>624 NG<br>645 NG<br>646 NG                                       |





| Model / Details  | Description  | Replaces Ref. No:                                    | TM No.  |
|--|--|--|---|
| -  | Repair Kit, Clutch Servo<br>For 096.151<br>Repl. Wabco: 970 051 949<br>2 S | -  | <b>TM36904</b><br>   |
| BM MODEL<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3     | Hose, Clutch Servo<br>L: 3900 mm   | 0002953935   | <b>TM22180</b><br>   |
| 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3   | Hose, Clutch Servo<br>L: 3900 mm   | 0002571866   | <b>TM22546</b><br>  |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3                 | Hose, Clutch Servo<br>L: 6650 mm   | 0002954335<br>0002954635                             | <b>TM22181</b><br> |
| 976 ATEGO<br>976 ATEGO 2<br>314 LP<br>316 LP<br>318 LP<br>344 L 1118<br>344 LK 1118  | Hose, Clutch Servo<br>L: 25000 mm  | 0009978952   | <b>TM25247</b><br> |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3                 | -Sensor, Clutch Servo<br>Repl. Wabco: 441 100<br>539 2                     | 0015429318   | <b>TM22481</b><br> |
| 350 LS 1924A,1929<br>350 LS 1924A,1929,1930<br>363 LP 2232/6X4<br>363 LPK 2232/6X4<br>363 LPS 2232/6X4<br>387 NG<br>389 NG | Pressure Plate, Clutch<br>Repl. Sachs: 1882 301 239<br>ø420 mm             | 0022503204<br>0022504104<br>0022509904<br>0032500004 | <b>TM22019</b><br> |





| TM No.  | Replaces Ref. No: | Description               | Model / Details      |
|---|-------------------|---------------------------|----------------------|
| <b>TM22426</b><br>   | 0052506404        | Pressure Plate, Clutch    | 950 ACTROS           |
|   | 0052506604        | Repl. Sachs: 3483 030 032 | 954 ACTROS           |
|   | 0072506104        | ø430 mm                   | 930 ACTROS 2/3       |
|   | 0072508104-       |                           | 934 ACTROS 2/3       |
|   |                   |                           | 695 L 1632           |
|   |                   |                           | 695 L 1634           |
|   |                   |                           | 695 LS 1632          |
| <b>TM22453</b><br>   | 0042508904        | Pressure Plate, Clutch    | 374 AXOR 2           |
|   | 0052506204        | Repl. Sachs: 3482 081 233 | 655 SK               |
|   |                   | ø430 mm                   | 656 SK               |
|   |                   |                           | 657 SK               |
|   |                   |                           | 658 SK               |
|   |                   |                           | 659 SK               |
|   |                   |                           | 634 O 500            |
| <b>TM22441</b><br>   | 0062504704        | Pressure Plate, Clutch    | 950 ACTROS           |
|   | 0062504804        | Repl. Sachs: 3488 023 031 | 952 ACTROS           |
|   | 0062504904        | ø400 mm                   | 954 ACTROS           |
|   | 0062508604        |                           |                      |
|   |                   |                           |                      |
| <b>TM22423</b><br> | 0042502404        | Pressure Plate, Clutch    | 376 L 1117 MBTC-USA  |
|   | 6952507104        | Repl. Sachs: 3482 051 131 | 376 L 1319 MBTC-USA  |
|   | 6952507004        | ø350 mm                   | 376 LP 1219 MBTC-USA |
|   |                   |                           | 376 LP 1419 MBTC-USA |
|   |                   |                           | 386 L 1621,1721      |
|   |                   |                           | 386 L 1621,L 1721    |
|   |                   |                           | 386 L 1622           |
| <b>TM22454</b><br> | 0062503004        | Pressure Plate, Clutch    | 979 ACCELO           |
|   | 0062506704        | Repl. Sachs: 3482 000 462 | 958 ATEGO 2          |
|   |                   | ø362 mm                   | 384 OF SERIES        |
|   |                   |                           | 382 OH SERIES        |
|   |                   |                           | 685 TOURINO          |
|   |                   |                           | 685 MBO 1018         |
|   |                   |                           | 685 MBO 1019         |
| <b>TM22045</b><br> | 0042501104        | Pressure Plate, Clutch    | 615 LK/LN2           |
|   | 0032509804        | Repl. Sachs: 3482 008 038 | 674 LK/LN2           |
|   |                   | ø310 mm                   | 675 LK/LN2           |
|   |                   |                           | 678 LK/LN2           |
|   |                   |                           | 615 NG               |
|   |                   |                           | 616 NG               |
|   |                   |                           | 617 NG               |
| <b>TM22452</b><br> | 0032509304        | Pressure Plate, Clutch    | 668 T2/LN1           |
|   |                   | Repl. Sachs: 3482 054 131 | 669 T2/LN1           |
|   |                   | ø280 mm                   | 670 T2/LN1           |
|   |                   |                           | 688 709              |
|   |                   |                           | 688 L 710 D          |
|   |                   |                           | 688 LO 809           |
|   |                   |                           | 692 L 710 D          |



| Model / Details  | Description  | Replaces Ref. No:                                    | TM No.  |
|--|--|--|---|
| 398 LO 814<br>669 T2/LN1<br>670 T2/LN1<br>688 1114<br>688 912<br>688 914<br>688 LO 812   | Pressure Plate, Clutch<br>Repl. Sachs: 3482 055 132<br>ø310 mm | 0042505104<br>0032509404                             | <b>TM22449</b><br>   |
| 652 MK<br>655 SK   | Clutch Disc<br>Repl. Sachs: 1878 004 832<br>ø430 mm / Z:10     | 0182508003   | <b>TM21895</b><br>   |
| 677 LK/LN2<br>679 LK/LN2<br>650 MK<br>684 OH SERIES<br>371 2524/6X2/48 OT-<br>TOMARSAN/TUERKEI<br>397 1623 S MBSA-RSA<br>699 1424 LAP AEGYPTEN | Clutch Disc<br>Repl. Sachs: 1878 000 105<br>ø380 mm / Z:10     | 0112500203<br>0112500103<br>0112500003<br>0022509703 | <b>TM36905</b><br>  |
| 625 SK<br>655 SK<br>656 SK<br>657 SK<br>658 SK<br>659 SK   | Clutch Disc<br>Repl. Sachs: 1878 080 037<br>ø430 mm / Z:10     | 0072505803<br>0072505903<br>0092502103<br>0092503103 | <b>TM21905</b><br> |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3                                     | Clutch Disc<br>Repl. Sachs: 1878 005 165<br>ø430 mm / Z:18     | 0192503003<br>0192504903<br>0192508803<br>0202504003 | <b>TM22512</b><br> |
| 950 ACTROS<br>952 ACTROS<br>954 ACTROS   | Clutch Disc<br>Repl. Sachs: 1878 002 024<br>ø400 mm / Z:18     | 0152507903<br>0152508003<br>0152508103<br>0172500303 | <b>TM22418</b><br> |
| 696 L 1938<br>696 L 2638<br>696 LK 2638<br>696 LS 1938<br>696 LS 2638  | Clutch Disc<br>Repl. Sachs: 1878 002 023<br>ø400 mm / Z:18     | 0152508303<br>0152508403<br>0152508503<br>0162509903 | <b>TM22419</b><br> |





| TM No.  | Replaces Ref. No: | Description               | Model / Details   |
|---|-------------------|---------------------------|---|
| <b>TM22059</b><br>   | 0032505603        | Clutch Disc               | 301 O 303   |
|   | 0032506203        | Repl. Sachs: 1878 001 070 |   |
|   | 0042507303        | ø350 mm / Z:10            |   |
|   | 0052503903        |                           |   |
|   |                   |                           |   |
| <b>TM22462</b><br>   | 0172500503        | Clutch Disc               | 970 ATEGO   |
|   | 0172500603        | Repl. Sachs: 1878 052 842 | 972 ATEGO   |
|   | 0192504203        | ø362 mm / Z:18            | 970 ATEGO 2   |
|   | 0192509103        |                           | 972 ATEGO 2   |
|   |                   |                           | 976 ATEGO 2<br>673 LK/LN2<br>674 LK/LN2                                     |
| <b>TM22047</b><br>   | 0012506003        | Clutch Disc               | 351 L 1514  |
|   | 0022503903        | Repl. Sachs: 1861 303 248 | 351 L 1517,1518   |
|   | 0022508803        | ø310 mm / Z:10            | 351 LS 1517,1518  |
|   | 0032508203        |                           | 352 LF 1313   |
|   |                   |                           | 358 LAF 1113 B<br>358 LF 1113 B<br>345 OH SERIES                            |
| <b>TM22456</b><br> | 0152504603        | Clutch Disc               | 375 ACTROS  |
|   | 0152506303        | Repl. Sachs: 1878 023 831 | 970 ATEGO   |
|   | 0192509503        | ø395 mm / Z:18            | 972 ATEGO   |
|   | 0192509903        |                           | 975 ATEGO   |
|   |                   |                           | 976 ATEGO<br>970 ATEGO 2<br>972 ATEGO 2                                     |
| <b>TM22868</b><br> | 0112500803        | Clutch Disc               | 652 MK  |
|   | 0122508603        | Repl. Sachs: 1878 634 027 | 653 MK  |
|   | 0122508803        | ø430 mm / Z:10            | 654 MK  |
|   | 0122509003        |                           | 625 SK  |
|   |                   |                           | 655 SK<br>656 SK<br>659 SK  |
| <b>TM22431</b><br> | 0082501903        | Clutch Disc               | 650 MK  |
|   | 0082502003        | Repl. Sachs: 1878 005 668 | 651 MK  |
|   | 0082503603        | ø430 mm / Z:10            | 652 MK  |
|   | 0082503703        |                           | 653 MK  |
|   |                   |                           | 654 MK<br>625 SK<br>655 SK  |
| <b>TM22420</b><br> | 0072504303        | Clutch Disc               | 343 T2/L  |
|   | 0072504203        | Repl. Sachs: 1878 002 706 | 346 L 1928  |
|   | 0052500203        | ø420 mm / Z:10            | 346 LK 1928   |
|   | 0052500103        |                           | 346 LS 1928   |
|   |                   |                           | 376 LPS 1525 MBTC-USA<br>386 L 2325,2425,LA<br>2425/6X6<br>386 LB 2325,2425 |



| Model / Details                   | Description               | Replaces Ref. No: | TM No.  |
|-----------------------------------|---------------------------|-------------------|---|
| 696 L 1938                        | Clutch Disc               | 0182508603        | <b>TM21897</b><br>   |
| 696 L 2638                        | Repl. Sachs: 1878 002 643 | 0182508803        |   |
| 696 LK 2638                       | ø400 mm / Z:10            | 0212501803        |   |
| 696 LS 1938                       |                           | 0212508803        |   |
| 696 LS 2638                       |                           |                   |   |
| 901 SPRINTER                      | Clutch Disc               | 0002525205        | <b>TM36906</b><br>   |
| 902 SPRINTER                      | Repl. Sachs: 1878 002 221 | 0002524005        |   |
| 903 SPRINTER                      | ø240 mm / Z:26            | 0002521805        |   |
| 904 SPRINTER                      |                           |                   |   |
| 905 SPRINTER                      |                           |                   |   |
| 313 T2/L                          | Clutch Disc               | 0042506603        | <b>TM21853</b><br>   |
| 318 LP                            | Repl. Sachs: 1861 919 134 | 0012503603        |   |
| 328 T2/L                          | ø280 mm / Z:10            | 0012500503        |   |
| 353 LP                            |                           | 0012504003        |   |
| 353 T2/L                          |                           |                   |   |
| 358 L 1113 B<br>358 L 1113 B MBSA |                           |                   |   |
| 384 L 1214                        | Clutch Disc               | 0112507403        | <b>TM22046</b><br> |
| 384 L 1215                        | Repl. Sachs: 1861 571 236 | 0072502903        |   |
| 384 L 1218                        | ø330 mm / Z:10            | 0072507203        |   |
| 384 L 1414                        |                           | 0052505303        |   |
| 384 L 1418 ,L 1418 E              |                           |                   |   |
| 384 LA 1418<br>384 LAK 1418       |                           |                   |   |
| 374 AXOR 2                        | Repair Kit, Clutch        | 0012509701        | <b>TM22579</b><br> |
|                                   | Repl. Sachs: 3400 122 801 | 0182509101        |   |
|                                   | ø430                      | 0182509901        |   |
|                                   |                           | 0192500001        |   |
| 650 MK                            | Clutch Fork               | 6502503813        | <b>TM22400</b><br> |
| 651 MK                            | ø30xø28x5                 | 6502503113        |   |
| 652 MK                            |                           | 6502501331        |   |
| 653 MK                            |                           | 6502500013        |   |
| 654 MK                            |                           |                   |   |
| 396 OH SERIES<br>625 SK           |                           |                   |   |
| 375 ACTROS                        | Clutch Fork               | 6552501513        | <b>TM22406</b><br> |
| 950 ACTROS                        | ø36xø28x110               |                   |   |
| 952 ACTROS                        |                           |                   |   |
| 953 ACTROS                        |                           |                   |   |
| 954 ACTROS                        |                           |                   |   |
| 930 ACTROS 2/3<br>932 ACTROS 2/3  |                           |                   |   |














| TM No.  | Replaces Ref. No: | Description                      | Model / Details                |
|---|-------------------|----------------------------------|--------------------------------|
| <b>TM36907</b><br>   | 6202540708        | Clutch Fork<br>ø32/ø37x150x92    | 615 NG                         |
|   | 6202540508        |                                  | 616 NG                         |
|   | 6202540308        |                                  | 617 NG                         |
|   | 6202540408        |                                  | 619 NG                         |
|   |                   |                                  | 621 NG                         |
|   |                   |                                  | 624 NG                         |
|   |                   |                                  | 396 OH SERIES                  |
| <b>TM22440</b><br>   | 6562500813        | Clutch Fork<br>ø28x120/ø30x154   | 382 O 500 M / 1728             |
|   | 6562500413        |                                  | 634 O 500                      |
|   | 6562500213        |                                  | 634 O 500 RSD /<br>2736/8X2/30 |
|   |                   |                                  | 634 TOURO                      |
|   |                   |                                  | 671 CONECTO                    |
|   |                   |                                  | 671 O 345                      |
|   |                   |                                  | 613 TOURISMO                   |
| <b>TM36908</b><br>   | 6202540108        | Clutch Fork<br>ø36x104,5/92      | 338 L 1418                     |
|   | 3372540208        |                                  | 338 LK 1418                    |
|   |                   |                                  | 338 LP 1418                    |
|   |                   |                                  | 338 LPS 1418                   |
|   |                   |                                  | 338 LS 1418                    |
|   |                   |                                  | 343 T2/L                       |
|   |                   |                                  | 346 L 1924                     |
| <b>TM36909</b><br> | 6552501813        | Clutch Fork<br>ø28x109/ø12,5x134 | -                              |
|   | 6562502013        |                                  |                                |
| <b>TM36910</b><br> | 0002541008        | Clutch Fork                      | 613 TOURISMO                   |
|   |                   |                                  |                                |
| <b>TM22498</b><br> | 9402500213        | Clutch Fork                      | 375 ACTROS                     |
|   |                   |                                  | 950 ACTROS                     |
|   |                   |                                  | 952 ACTROS                     |
|   |                   |                                  | 953 ACTROS                     |
|   |                   |                                  | 954 ACTROS                     |
|   |                   |                                  | 930 ACTROS 2/3                 |
|   |                   |                                  | 932 ACTROS 2/3                 |
| <b>TM36911</b><br> | 9012500021        | Clutch Fork                      | 670 VARIO                      |
|   |                   |                                  | 408 UNIMOG                     |
|   |                   |                                  | 690 SPRINTER                   |
|   |                   |                                  | 901 SPRINTER                   |
|   |                   |                                  | 902 SPRINTER                   |
|   |                   |                                  | 903 SPRINTER                   |
|   | 904 SPRINTER      |                                  |                                |





| Model / Details   | Description  | Replaces Ref. No:        | TM No.  |
|---|--|--------------------------|---|
| 376 L 1117 MBTC-USA<br>376 L 1319 MBTC-USA<br>376 LP 1219 MBTC-USA<br>376 LP 1419 MBTC-USA<br>376 LPS 1525 MBTC-USA<br>674 LK/LN2<br>676 LK/LN2 | Repair Kit, Clutch Fork<br>ø30xø11/187x213                     | 6202500214               | <b>TM22564</b><br>   |
| 650 MK<br>651 MK<br>652 MK<br>653 MK<br>654 MK<br>396 OH SERIES<br>625 SK   | Repair Kit, Clutch Fork<br>For 100.085                         | 6502540006S              | <b>TM22551</b><br>   |
| 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3  | Repair Kit, Clutch Fork<br>For 100.173, 100.289 and<br>203.475 | 6552540206S              | <b>TM36912</b><br>  |
| 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3  | Repair Kit, Clutch Fork<br>For 100.173, 100.289 and<br>203.475 | 6552540206S1             | <b>TM22603</b><br> |
| 382 O 500 M / 1728<br>634 O 500<br>634 O 500 RSD /<br>2736/8X2/30<br>634 TOURO<br>671 CONECTO<br>671 O 345 613 TOURIS-<br>MO                    | Repair Kit, Clutch Fork  | 6562540506S1             | <b>TM22577</b><br> |
| 343 T2/L<br>346 L 1928<br>346 LK 1928<br>346 LS 1928<br>380 NG<br>381 NG<br>383 NG  | Repair Kit, Clutch Fork  | 3852500014<br>3892500014 | <b>TM22106</b><br> |
| 613 TOURISMO  | Repair Kit, Clutch Fork<br>For 202.029                         | 0002541008S              | <b>TM36918</b><br> |





| TM No.  | Replaces Ref. No:                                    | Description   | Model / Details  |
|---|--|---|--|
| <b>TM36919</b><br>   | 3389920103   | Bushing, Clutch Fork<br>ø20xø44x20                  | 343 T2/L<br>346 L 1924<br>346 L 1928<br>346 LK 1924<br>346 LK 1928<br>346 LS 1924<br>346 LS 1928           |
|   |  |   |  |
| <b>TM22355</b><br>   | 0002540017   | Roller, Clutch Fork<br>ø12xø28x35                   | 979 ACCELO<br>375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3         |
|   |  |   |  |
| <b>TM36920</b><br>   | 0002540036<br>0002540136                             | Bracket, Clutch Fork                                | 613 TOURISMO   |
|   |  |   |  |
| <b>TM21927</b><br> | 0002543208<br>0032502215                             | Clutch Release Bearing                              | 634 IBC-FAHRGESTELL<br>2-ACHSER<br>634 IBC-FAHRGESTELL<br>3-ACHSER<br>634 MULTEGO                          |
|   |  |   |  |
| <b>TM21921</b><br> | 0002543008   | Clutch Release Bearing<br>Repl. Sachs: 3151 000 144 | 632 TRAVEGO<br>410 SETRA<br>632 SETRA  |
|   |  |   |  |
| <b>TM22073</b><br> | 0012500615<br>0012504915<br>0012506615<br>0012506715 | Clutch Release Bearing<br>Repl. Sachs: 3151 000 547 | 655 SK<br>656 SK<br>658 SK<br>659 SK<br>600 O 303  |
|   |  |   |  |
| <b>TM22075</b><br> | 0022508115<br>0022506715<br>0022504115<br>0022504715 | Clutch Release Bearing<br>Repl. Sachs: 3100 002 255 | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 |
|   |  |   |  |



| Model / Details   | Description   | Replaces Ref. No:                                    | TM No.  |
|---|---|--|---|
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/ | Clutch Release Bearing<br>Repl. Sachs: 3100 000 003 | 0022508215<br>0022506815<br>0022509915<br>0022504015 | <b>TM22076</b><br>   |
| 613 TOURISMO  | Clutch Release Bearing<br>Repl. Sachs: 3151 273 531 | 0032501515<br>0022508815<br>0012501815<br>0012509615 | <b>TM21932</b><br>   |
| 650 MK<br>651 MK<br>652 MK<br>653 MK<br>654 MK<br>625 SK<br>655 SK  | Clutch Release Bearing<br>Repl. Sachs: 3151 000 549 | 0012500915<br>0012504715<br>0012506215<br>0012506315 | <b>TM36522</b><br>   |
| 309 T2/L<br>310 LF 508 D/LF 608 D<br>310 LT 608 D<br>310 T2/L<br>313 T2/L<br>314 LP<br>316 LP             | Clutch Release Bearing<br>Repl. Sachs: 3151 044 031 | 0012509315<br>0012509115<br>0002504215<br>3812500415 | <b>TM22048</b><br> |
| 350 LS 1932,1933<br>350 LS 1934<br>376 LPS 1525 MBTC-USA<br>615 NG<br>616 NG<br>617 NG<br>619 NG          | Clutch Release Bearing<br>Repl. Sachs: 3151 126 031 | 0002507615   | <b>TM22392</b><br> |
| 343 T2/L<br>346 L 1928<br>346 LK 1928<br>346 LS 1928<br>383 NG<br>385 NG<br>387 NG                        | Clutch Release Bearing<br>Repl. Sachs: 3151 000 375 | 0002507715<br>0002501915<br>0002502515               | <b>TM22065</b><br> |
| 620 NG<br>621 NG<br>623 NG<br>624 NG<br>645 NG<br>646 NG<br>647 NG  | Clutch Release Bearing<br>Repl. Sachs: 3151 108 031 | 0002507515   | <b>TM22393</b><br> |









| TM No.  | Replaces Ref. No:                      | Description                            | Model / Details  |
|---|--|--|--|
| <b>TM22084</b><br>   | 0012502215                             | Clutch Release Bearing                 | 386 L 1621,1721  |
|   | 0002507015                             | Repl. Sachs: 3151 000 374              | 386 L 1621,L 1721<br>386 L 1622<br>386 LK 1621,1721<br>386 LS 1622<br>674 LK/LN2<br>676 LK/LN2 |
| <b>TM22074</b><br>   | 0012500815                             | Clutch Release Bearing                 | 398 LO 814   |
|   | 0002509515                             | Repl. Sachs: 3151 170 131              | 668 T2/LN1<br>669 T2/LN1<br>670 T2/LN1<br>688 1114<br>688 709<br>688 912                       |
| <b>TM36921</b><br>   | 0022504215                             | Clutch Release Bearing                 | 950 ACTROS   |
|   |  | Repl. Sachs: 3100 002 258              | 952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3   |
| <b>TM22501</b><br> | 0002541608                             | Clutch Release Bearing                 | 979 ACCELO   |
|   | 0002542508                             | With Pump<br>Repl. Sachs: 3182 997 804 | 690 SPRINTER<br>901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER<br>905 SPRINTER   |
| <b>TM22430</b><br> | 0022505215                             | Clutch Release Bearing                 | 375 ACTROS   |
|   | 0022503015<br>0022502515<br>0022502815 | Repl. Sachs: 3182 600 101              | 970 ATEGO<br>972 ATEGO<br>976 ATEGO<br>375 ATEGO 2<br>970 ATEGO 2<br>972 ATEGO 2               |
| <b>TM21928</b><br> | 0002540320                             | Clutch Release Bearing                 | 970 ATEGO  |
|   | 0002540420<br>0022502215<br>0022502715 | Repl. Sachs: 3182 998 501              | 972 ATEGO<br>975 ATEGO<br>970 ATEGO 2<br>972 ATEGO 2<br>975 ATEGO 2<br>976 ATEGO 2             |
| <b>TM22504</b><br> | 0002541808                             | Clutch Release Bearing                 | 638 VITO   |
|   | 0002541308                             | Repl. Sachs: 3182 997 801              | 638 V-CLASS  |



| Model / Details   | Description  | Replaces Ref. No:                      | TM No.  |
|---|--|--|---|
| 375 ACTROS<br>970 ATEGO<br>972 ATEGO<br>976 ATEGO<br>970 ATEGO 2<br>974 ATEGO 2<br>976 ATEGO 2                        | -Clutch Release Bearing<br>Repl. Sachs: 3182 600 166 | 0022507415<br>0022505815               | <b>TM22495</b><br>   |
| 375 ACTROS<br>375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>976 ATEGO<br>375 ATEGO 2<br>970 ATEGO 2                          | Clutch Release Bearing<br>Repl. Sachs: 3182 600 141  | 0022507315<br>0022505515               | <b>TM22473</b><br>   |
| 384 OF SERIES<br>368 OH SERIES<br>382 OH SERIES<br>684 OH SERIES<br>382 O 500 M / 1725 / 1726<br>685 TOURINO<br>685 - | Clutch Release Bearing                               | 0012509915<br>0022500015<br>0022506515 | <b>TM22077</b><br>   |
| 375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>976 ATEGO<br>375 ATEGO 2<br>970 ATEGO 2<br>972 ATEGO 2                         | Clutch Release Bearing<br>Repl. Sachs: 3182 600 189  | 0022505315<br>0022505715               | <b>TM22503</b><br> |
| 970 ATEGO<br>972 ATEGO<br>976 ATEGO<br>375 ATEGO 2<br>970 ATEGO 2<br>972 ATEGO 2<br>974 ATEGO 2                       | Clutch Release Bearing<br>Repl. Sachs: 3182 600 172  | 0022506015<br>0022507515               | <b>TM22472</b><br> |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3            | Clutch Release Bearing<br>Repl. Sachs: 3100 000 046  | 0022504315                             | <b>TM36922</b><br> |
| 650 MK<br>651 MK<br>652 MK<br>653 MK<br>654 MK<br>396 OH SERIES<br>625 SK   | Bearing Kit, Clutch Release Bearing                  | 0002520346                             | <b>TM22401</b><br> |





| TM No.  | Replaces Ref. No:        | Description                         | Model / Details   |
|---|--------------------------|-------------------------------------|---|
| <b>TM22139</b><br>   | 0002520646               | Bearing Kit, Clutch Release Bearing | 388 L 1929<br>388 L 1938  |
|   |                          | Repl. Sachs: 3496 006 000           | 388 LK 2635/6X4/40<br>388 LS 1929<br>388 LS 1935<br>388 LS 1938<br>388 LS 1941                                      |
| <b>TM22168</b><br>   | 3859970582               | Hose, Clutch Release Bearing        | 343 T2/L  |
|   | 3079970082               |                                     | 346 L 1924<br>346 L 1928<br>346 LK 1924<br>346 LK 1928<br>346 LS 1924<br>346 LS 1928                                |
| <b>TM02536</b><br>  | 4030100880               | Gasket Kit, Clutch Housing          | 363 LP 2226/6X4   |
|   | 4230104833               |                                     | 363 LP 2232/6X4<br>363 LPB 2226/6X4<br>363 LPK 2226/6X4<br>363 LPK 2232/6X4<br>363 LPS 2226/6X4<br>363 LPS 2232/6X4 |
| <b>TM02594</b><br> | 5410100933               | Gasket Kit, Clutch Housing          | 950 ACTROS  |
|   | 5410102033<br>5410102133 |                                     | 952 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3  |





| Model / Details  | Description   | Replaces Ref. No:                                    | TM No.  |
|--|---|--|---|
| 970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>970 ATEGO 2<br>972 ATEGO 2<br>975 ATEGO 2<br>343 T2/L           | Valve, Gear Box Housing<br>Repl. Knorr: SV3367            | 0012606757<br>0012606657<br>0012606257<br>0002609757 | <b>TM31751</b><br>   |
| 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3 | Valve, Gear Box Housing                                   | 0022606257<br>0022603057<br>0022602957<br>0022604057 | <b>TM32621</b><br>   |
| 676 LK/LN2<br>677 LK/LN2<br>650 MK<br>651 MK<br>652 MK<br>653 MK<br>654 MK                             | Valve, Gear Box Housing<br>Repl. Knorr: SV3371            | 0012608457<br>0012604757<br>0002605457<br>0012603557 | <b>TM31750</b><br>  |
| -  | Sensor, Gear Box Housing                                  | 0015457714   | <b>TM31638</b><br> |
| 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3 | Sensor, Gear Box Housing<br>Repl. Wabco: 441 100<br>072 0 | 0005429118   | <b>TM32605</b><br> |
| 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3 | Sensor, Gear Box Housing                                  | 0125421017   | <b>TM11766</b><br> |
| 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3 | Sensor, Gear Box Housing                                  | 0125425317<br>0135426717<br>0155422717               | <b>TM31861</b><br> |












| TM No.  | Replaces Ref. No: | Description                                   | Model / Details  |
|---|-------------------|---|--|
| <b>TM11782</b><br>   | 0015451609        | Sensor, Gear Box Housing                      | 375 ACTROS   |
|   | 0015457309        |   | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3 |
| <b>TM10675</b><br>   | 0015457409        | Sensor, Gear Box Housing                      | 979 ACCELO   |
|   | 0015454709        |   | 375 ACTROS   |
|   | 0015451709        |   | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3                   |
| <b>TM11783</b><br>  | 0015455009        | Sensor, Gear Box Housing                      | 375 ACTROS   |
|   | 0015451909        |   | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3 |
| <b>TM36923</b><br> | 0015459309        | Sensor, Gear Box Housing                      | 964 ACTROS MP4   |
|   |                   |   | 964 ANTOS<br>964 AROCS<br>967 ATEGO 3<br>382 O 500 M / 1728<br>634 O 500<br>671 O 345    |
| <b>TM31755</b><br> | 0139975647        | Sensor, Gear Box Housing<br>ø95xø115x13 / FPM | 950 ACTROS   |
|   | 0139977347        |   | 952 ACTROS   |
|   | 0159974247        |   | 953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3           |
| <b>TM30583</b><br> | 0079979847        | Sensor, Gear Box Housing<br>ø80xø100x10 / FPM | 375 ACTROS   |
|   | 0089970347        |   | 970 ATEGO  |
|   | 0099970646        |   | 972 ATEGO  |
|   | 0079973847        |   | 976 ATEGO<br>970 ATEGO 2<br>972 ATEGO 2<br>974 ATEGO 2                                   |
| <b>TM31956</b><br> | 0049970647        | Sensor, Gear Box Housing<br>ø85xø105x10 / FPM | 336 LP 1924  |
|   | 0079975947        |   | 336 LPS 1924   |
|   | 0089973347        |   | 343 T2/L   |
|   | 0129970647        |   | 343 T2/LN1   |
|   |                   |   | 346 L 1924<br>346 LA 1924<br>346 LAK 1924  |



| Model / Details   | Description   | Replaces Ref. No:                                    | TM No.  |
|---|---|--|---|
| 375 ACTROS<br>963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS<br>970 ATEGO<br>972 ATEGO                        | Seal Ring, Gear Box<br>Housing<br>ø80xø100x15,5 / FPM | 0239978847   | <b>TM30578</b><br>   |
| 345 L 2225<br>345 LS 1524/1525<br>350 LS 1924<br>350 LS 1924A,1929<br>350 LS 1924A,1929,1930<br>351 L 1526<br>351 LS 1526 | Seal Ring, Gear Box<br>Housing<br>ø48xø75x8 / FPM     | 0049970747<br>0109979246<br>0079975447<br>0069978747 | <b>TM01306</b><br>   |
| 677 LK/LN2<br>617 NG<br>620 NG<br>621 NG<br>623 NG<br>624 NG<br>625 NG  | Seal Ring, Gear Box<br>Housing<br>ø52xø68x8 / FPM     | 0119976247<br>0159971547<br>0159970647<br>0159971647 | <b>TM31963</b><br>  |
| 979 ACCELO<br>970 ATEGO<br>972 ATEGO<br>970 ATEGO 2<br>972 ATEGO 2<br>976 ATEGO 2<br>673 LK/LN2                           | Seal Ring, Gear Box<br>Housing<br>ø50xø65x8 / FPM     | 0219978047   | <b>TM32022</b><br> |
| 363 LP 2226/6X4<br>363 LPB 2226/6X4<br>363 LPK 2226/6X4<br>363 LPS 2226/6X4   | Seal Ring, Gear Box<br>Housing<br>ø48xø65x10 / NBR    | 0079972147<br>0099974746                             | <b>TM31983</b><br> |
| 979 ACCELO<br>963 ACTROS MP4<br>375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>976 ATEGO<br>375 ATEGO 2                           | Seal Ring, Gear Box<br>Housing<br>ø48xø65x10 / FPM    | 0109974247<br>0109972847<br>0109972747<br>0219971247 | <b>TM30318</b><br> |
| 343 T2/L<br>350 LS 1924<br>350 LS 1924A,1929<br>350 LS 1924A,1929,1930<br>350 LS 1932,1933<br>350 LS 1934<br>386 L 1622   | Seal Ring, Gear Box<br>Housing<br>ø105xø130x12 / ACM  | 0219976447<br>0099970747<br>0199977647               | <b>TM33112</b><br> |



| TM No.  | Replaces Ref. No:                                    | Description   | Model / Details  |
|---|--|---|--|
| <b>TM36924</b><br>   | 9452611933   | Cover, Gear Box Housing                                   | 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3     |
| <b>TM02323</b><br>   | 4571800601<br>4571800801                             | Oil Pump<br>Tooth Width: 49 mm /<br>Drive Gear : 49 Teeth | 375 AXOR<br>374 AXOR 2<br>940 AXOR 2<br>942 AXOR 2<br>943 AXOR 2<br>944 AXOR 2<br>958 AXOR 2               |
| <b>TM01988</b><br>  | 5411800401<br>5421800701                             | Oil Pump<br>Tooth Width: 43 mm /<br>Drive Gear : 43 Teeth | 979 ACCELO<br>950 ACTROS<br>952 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 |
| <b>TM02007</b><br> | 5421800401   | Oil Pump<br>Tooth Width: 49 mm /<br>Drive Gear : 43 Teeth | 979 ACCELO<br>950 ACTROS<br>952 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 |
| <b>TM01972</b><br> | 5411800001<br>5411800101<br>5411800201<br>5411800301 | Oil Pump<br>Tooth Width: 43 mm /<br>Drive Gear : 42 Teeth | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 |
| <b>TM01987</b><br> | 4571800001<br>4571800201<br>4571800401<br>5231801101 | Oil Pump<br>Tooth Width: 43 mm /<br>Drive Gear : 49 Teeth | 382 O 500<br>634 O 500<br>634 O 500 RSD /<br>2736/8X2/30<br>664 O 400 RSD BUGGY<br>664 O 400 RSE BUGGY     |
| <b>TM36925</b><br> | 4571880504<br>4421881804<br>4421881604<br>4421881304 | Cover, Oil Cooler   | 650 MK<br>651 MK<br>652 MK<br>653 MK<br>621 NG<br>624 NG<br>625 SK   |



| Model / Details  | Description          | Replaces Ref. No:                      | TM No.  |
|--|----------------------|--|---|
| 363 LP 2226/6X4<br>363 LP 2232/6X4<br>397 OF SERIES<br>655 SK<br>397 1419 MBSA-RSA<br>397 1924 MBSA-RSA<br>397 1928 MBSA-RSA | Cover, Oil Cooler    | 4031801438<br>4031800738<br>4031803438 | <b>TM36926</b><br>   |
| 650 MK<br>651 MK<br>652 MK<br>653 MK<br>615 NG<br>617 NG<br>619 NG   | Cover, Oil Cooler    | 4031803938                             | <b>TM01853</b><br>   |
| 970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>375 ATEGO 2<br>970 ATEGO 2<br>972 ATEGO 2                                | Cover, Oil Cooler    | 900271050012                           | <b>TM36927</b><br>   |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3                   | Cover, Oil Cooler    | 9439971582                             | <b>TM36928</b><br> |
| 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3   | Pipe Kit, Oil Cooler | 9302611683                             | <b>TM36929</b><br> |
| 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3   | Pipe Kit, Oil Cooler | 9302610183                             | <b>TM36930</b><br> |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3                   | Pipe Kit, Oil Cooler | 9412615483                             | <b>TM36931</b><br> |







| TM No.  | Replaces Ref. No:                                    | Description                                   | Model / Details  |
|---|--|---|--|
| <b>TM36932</b><br>   | 9412617883   | Pipe Kit, Oil Cooler                          | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 |
| <b>TM31953</b><br>   | 0079972047   | Seal Ring, Input Shaft<br>ø48xø69x10 / FPM    | 343 T2/L<br>346 L 1924<br>346 LK 1924<br>346 LS 1924<br>350 LS 1924<br>363 LP 2226/6X4<br>363 LPB 2226/6X4 |
| <b>TM36933</b><br>  | 0109972146   | Seal Ring, Input Shaft<br>ø46xø68x12 / FPM    | 352 LA 1313<br>384 L 1218<br>678 LK/LN2<br>615 NG<br>384 OF SERIES<br>684 OF SERIES<br>685 OF SERIES       |
| <b>TM36934</b><br> | 0239979447   | Seal Ring, Input Shaft<br>ø55xø75x8/9,2 / ACM | 336 LP 1924<br>336 LPS 1924<br>343 T2/L<br>343 T2/LN1<br>346 L 1924<br>346 LA 1924<br>346 LAK 1924         |
| <b>TM31961</b><br> | 0239977847<br>0239970647<br>0229978547<br>0209971747 | Seal Ring, Input Shaft<br>ø56xø72x8 / FPM     | 930 ACTROS 2/3<br>963 ACTROS MP4<br>964 AROCS<br>958 ATEGO 2<br>375 AXOR<br>374 AXOR 2<br>375 AXOR 2       |
| <b>TM32549</b><br> | 3872621093<br>3872620993<br>3872620693               | Spring, Input Shaft<br>ø3x147,5               | 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3     |
| <b>TM32550</b><br> | 3872620893<br>3872620793                             | Spring, Input Shaft<br>ø3,2x168               | 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3     |





| Model / Details   | Description  | Replaces Ref. No:                                    | TM No.         |
|---|--|--|----------------|
| 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3  | Spring, Input Shaft<br>ø3,6x177                              | 3892620293   | <b>TM32546</b> |
| 950 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>934 ACTROS 2/3<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS  | Bearing, Main Shaft<br>Repl. FAG: 32011X<br>ø55xø90x23       | 0159817705<br>0029811305<br>0029816605<br>0069815605 | <b>TM32633</b> |
| 970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>970 ATEGO 2<br>972 ATEGO 2<br>975 ATEGO 2<br>976 ATEGO 2   | Bearing, Reverse Shaft<br>Repl. FAG: 32306A<br>ø30xø72x29    | 0009819505<br>0019818305<br>0019818705<br>0069816605 | <b>TM25208</b> |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3                                      | Bearing, Counter Shaft<br>Repl. FAG: 30312A<br>ø60xø130x33,5 | 0169811205<br>0129819205<br>0129819405<br>0109815505 | <b>TM25194</b> |
| 972 ATEGO<br>976 ATEGO<br>958 ATEGO 2<br>970 ATEGO 2<br>972 ATEGO 2<br>976 ATEGO 2<br>341 LA 1114   | Bearing, Counter Shaft<br>Repl. FAG: 33209<br>ø45xø85x32     | 0039815305<br>0039815705<br>0049817205<br>0059814105 | <b>TM25223</b> |
| 958 ATEGO 2<br>341 LA 1114<br>345 L<br>2213,2214,2216,2217<br>345 L 2216,2217<br>345 LA 1313<br>345 LA 1313,1314,1317<br>345 LAK 1313,1314,1317 | Bearing, Counter Shaft<br>Repl. FAG: 33210<br>ø50xø90x32     | 0029817905<br>0039818305<br>0049814205<br>0059814005 | <b>TM26218</b> |
| 387 NG<br>389 NG<br>395 NG  | Bearing, Counter Shaft<br>Repl. FAG: 30217A<br>ø85xø150x30,5 | 000720030217   | <b>TM25310</b> |










| TM No.  | Replaces Ref. No: | Description           | Model / Details |
|---|-------------------|-----------------------|-----------------|
| <b>TM25208</b><br>   | 0009819505        | Bearing, Output Shaft | 970 ATEGO       |
|   | 0019818305        | Repl. FAG: 32306A     | 972 ATEGO       |
|   | 0019818705        | ø30xø72x29            | 975 ATEGO       |
|   | 0069816605        |                       | 970 ATEGO 2     |
|   |                   |                       | 972 ATEGO 2     |
|   |                   | 975 ATEGO 2           |                 |
|   |                   | 976 ATEGO 2           |                 |
| <b>TM26545</b><br>   | 0059810705        | Bearing, Output Shaft | 375 ACTROS      |
|   | 0149810605        | Repl. FAG: 33207      | 950 ACTROS      |
|   | 0059810605        | ø35xø72x28            | 952 ACTROS      |
|   |                   |                       | 953 ACTROS      |
|   |                   |                       | 954 ACTROS      |
|   |                   | 930 ACTROS 2/3        |                 |
|   |                   | 932 ACTROS 2/3        |                 |
| <b>TM25194</b><br>   | 0169811205        | Bearing, Output Shaft | 950 ACTROS      |
|   | 0129819205        | Repl. FAG: 30312A     | 952 ACTROS      |
|   | 0129819405        | ø60xø130x33,5         | 953 ACTROS      |
|   | 0109815505        |                       | 954 ACTROS      |
|   |                   |                       | 930 ACTROS 2/3  |
|   |                   | 932 ACTROS 2/3        |                 |
|   |                   | 933 ACTROS 2/3        |                 |
| <b>TM30665</b><br> | 3553560126        | Nut, Planetary Gear   | 972 ATEGO       |
|   | 9423560026        | M88x1,5x11            | 976 ATEGO       |
|   |                   |                       | 970 ATEGO 2     |
|   |                   |                       | 972 ATEGO 2     |
|   |                   |                       | 976 ATEGO 2     |
|   |                   | 967 ATEGO 3           |                 |
|   |                   | 950 AXOR 2            |                 |
| <b>TM32525</b><br> | 6202600040        | Knob, Gear Shift      | 375 ACTROS      |
|   | 6202670010        | ø16x48/60x168         | 950 ACTROS      |
|   | 6202680142        |                       | 952 ACTROS      |
|   |                   |                       | 953 ACTROS      |
|   |                   |                       | 954 ACTROS      |
|   |                   | 930 ACTROS 2/3        |                 |
|   |                   | 932 ACTROS 2/3        |                 |
| <b>TM32531</b><br> | 6202680042        | Knob, Gear Shift      | 970 ATEGO       |
|   |                   | ø20x49/60x168         | 972 ATEGO       |
|   |                   |                       | 976 ATEGO       |
|   |                   |                       | 970 ATEGO 2     |
|   |                   |                       | 972 ATEGO 2     |
|   |                   | 974 ATEGO 2           |                 |
|   |                   | 976 ATEGO 2           |                 |
| <b>TM32805</b><br> | 9432601209        | Knob, Gear Shift      | 930 ACTROS 2/3  |
|   | 9432600809        | Automatic             | 932 ACTROS 2/3  |
|   | 9432600209        |                       | 933 ACTROS 2/3  |
|   |                   |                       | 934 ACTROS 2/3  |










| Model / Details   | Description                           | Replaces Ref. No:        | TM No.  |
|---|---------------------------------------|--------------------------|---|
| 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3<br>958 ATEGO 2<br>374 AXOR 2<br>940 AXOR 2 | Knob, Gear Shift<br>Automatic         | 9432601509               | <b>TM32829</b><br>   |
| 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3  | Knob, Gear Shift<br>Automatic         | 9432601109               | <b>TM36935</b><br>   |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>375 AXOR<br>374 AXOR 2<br>940 AXOR 2                    | Knob, Gear Shift<br>Automatic         | 0002603298               | <b>TM31712</b><br>   |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>375 AXOR<br>944 AXOR 2<br>958 AXOR 2                    | Knob Cap, Gear Shift<br>ø24x30/33x22  | 6202680157               | <b>TM32532</b><br> |
| 310 T2/L<br>314 LP<br>316 LP<br>351 L 1517,1518<br>351 L 1518<br>351 LK 1518<br>351 LS 1517,1518                | Bushing, Gear Shift<br>ø48x28,5       | 3102680035<br>3142680435 | <b>TM36936</b><br> |
| 314 LP<br>316 LP  | Bushing, Gear Shift<br>ø18,5xø28x28,5 | 3142680243<br>3142680043 | <b>TM36937</b><br> |
| 318 LP<br>344 L 1113<br>344 L 1113/L 1114<br>344 L 1118<br>344 LK 1113<br>344 LK 1113/LK 1114<br>344 LK 1118    | Bushing, Gear Shift<br>ø35xø48x22     | 3522680335               | <b>TM36938</b><br> |





| TM No.  | Replaces Ref. No:        | Description                                | Model / Details  |
|---|--------------------------|--|--|
| <b>TM36939</b><br>   | 3522680050               | Bushing, Gear Shift<br>ø32,5xø38x64        | 318 LP<br>344 LP 1113<br>344 LPO/OF 1113/1114<br>353 LP<br>345 OF SERIES<br>352 OF SERIES<br>355 OF SERIES   |
| <b>TM36940</b><br>   | 3522680450               | Bushing, Gear Shift<br>ø28xø38x24          | 318 LP<br>344 LP 1113<br>344 LPO/OF 1113/1114<br>353 LP<br>345 OF SERIES<br>352 OF SERIES<br>355 OF SERIES   |
| <b>TM36941</b><br>   | 6112670250               | Bushing, Gear Shift<br>ø13,5xø21x13        | 611 T1/TN<br>601 207 D/208 D<br>601 208/210<br>601 209 D/210 D<br>602 307 D/308 D<br>602 307 D/308D<br>602 308 D   |
| <b>TM33070</b><br> | 6202680196<br>3852680696 | Dust Cover, Gear Shift<br>ø20xø58x21       | 376 LP 1219 MBTC-USA<br>376 LP 1419 MBTC-USA<br>376 LPS 1525 MBTC-USA<br>397 LP 1014 MBSA-RSA<br>397 LP 1114,1214 MB-<br>SA-RSA<br>397 LP 1214 A MBSA-RSA<br>397 LP 1517 |
| <b>TM36942</b><br> | 9702681897               | Dust Cover, Gear Shift<br>01,5x163,6x121,5 | 375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>375 ATEGO 2<br>958 ATEGO 2  |
| <b>TM36943</b><br> | 0002684197               | Dust Cover, Gear Shift                     | 904 SPRINTER<br>904 SPRINTER<br>901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER<br>905 SPRINTER   |
| <b>TM33102</b><br> | 3852681474SP             | Repair Kit, Gear Shift<br>ø42              | 376 LP 1219 MBTC-USA<br>376 LP 1419 MBTC-USA<br>376 LPS 1525 MBTC-USA<br>397 LP 1014 MBSA-RSA<br>397 LP 1114,1214 MB-<br>SA-RSA<br>397 LP 1214 A MBSA-RSA<br>397 LP 1517 |



| Model / Details  | Description                                  | Replaces Ref. No:                         | TM No.  |
|--|--|---|---|
| 376 LP 1219 MBTC-USA<br>376 LP 1419 MBTC-USA<br>376 LPS 1525 MBTC-USA<br>397 LP 1014 MBSA-RSA<br>397 LP 1114,1214 MB-<br>SA-RSA<br>397 LP 1214 A MBSA-RSA<br>397 LP 1517 | Repair Kit, Gear Shift<br>ø42                | 3852681474S                               | <b>TM33136</b><br>   |
| 970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>958 ATEGO 2<br>970 ATEGO 2<br>972 ATEGO 2  | Repair Kit, Gear Shift<br>ø16xø25x18         | 9702600298<br>9702600098                  | <b>TM33126</b><br>   |
| 970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>970 ATEGO 2<br>972 ATEGO 2<br>974 ATEGO 2  | Repair Kit, Gear Shift<br>ø16xø25x18         | 9702600398<br>9702600198                  | <b>TM36944</b><br>  |
| 375 AXOR<br>375 AXOR 2   | Repair Kit, Gear Shift<br>ø10,2xø30          | 0019882510S<br>9702600152S<br>9702680253S | <b>TM36945</b><br> |
| 970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>958 ATEGO 2<br>970 ATEGO 2<br>972 ATEGO 2  | Repair Kit, Gear Shift<br>With Screw and Nut | 9702600298S                               | <b>TM36946</b><br> |
| 690 SPRINTER<br>901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER   | Cable, Gear Shift                            | 9012601338                                | <b>TM32945</b><br> |
| 906 SPRINTER   | Cable, Gear Shift                            | 9062601451                                | <b>TM36947</b><br> |







| TM No.  | Replaces Ref. No: | Description                   | Model / Details  |
|---|-------------------|-------------------------------|--|
| <b>TM32625</b><br>   | 9415400545        | Switch, Gear Shift            | 375 ACTROS   |
|   | 0035454707        | Wabco Type                    | 950 ACTROS   |
|   | 0045459607        | Repl. Wabco: 441 036<br>000 0 | 952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3                   |
| <b>TM32552</b><br>   | 9705400045        | Switch, Gear Shift            | 970 ATEGO  |
|   |                   | Wabco Type                    | 972 ATEGO  |
|   |                   | Repl. Wabco: 441 036<br>001 0 | 976 ATEGO<br>970 ATEGO 2<br>972 ATEGO 2<br>974 ATEGO 2<br>976 ATEGO 2                        |
| <b>TM36948</b><br>   | 3872680089        | Joint, Gear Shift             | 376 LPS 1525 MBTC-USA  |
|   | 0002686489        |                               | 676 LK/LN2<br>677 LK/LN2<br>679 LK/LN2<br>650 MK<br>651 MK<br>652 MK                         |
| <b>TM32499</b><br> | 0012606457        | Valve, Gear Shift             | 679 LK/LN2   |
|   | 0012606357        |                               | 652 MK   |
|   | 0002609557        |                               | 653 MK   |
|   | 0012605357        |                               | 617 NG<br>619 NG<br>620 NG<br>621 NG   |
| <b>TM32598</b><br> | 0002607198        | Gear Shift Control            | 950 ACTROS   |
|   | 0002604098        | Repl. Kongsberg:<br>626321AM  | 952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 |
| <b>TM32798</b><br> | 0002606198        | Gear Shift Control            | 930 ACTROS 2/3   |
|   | 0002607998        | Repl. Kongsberg:<br>630388AM  | 932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3   |
| <b>TM32806</b><br> | 0002604198        | Gear Shift Control            | 950 AXOR 2   |
|   | 0002607298        | Repl. Kongsberg:<br>626661AM  | 952 AXOR 2<br>953 AXOR 2<br>954 AXOR 2<br>685 OF SERIES<br>368 OH SERIES<br>685 -            |













| Model / Details   | Description   | Replaces Ref. No:                                    | TM No.  |
|---|---|--|---|
| 950 AXOR 2<br>952 AXOR 2<br>953 AXOR 2<br>954 AXOR 2<br>382 O 500 M / 1728<br>634 O 500<br>634 TOURO                    | Gear Shift Control<br>Repl. Kongsberg:<br>626662AM            | 0002604298<br>0002607798                             | <b>TM32795</b><br>   |
| 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3<br>374 AXOR 2<br>940 AXOR 2<br>942 AXOR 2          | Gear Shift Control<br>Repl. Kongsberg:<br>629582AM            | 0002605998<br>0002607898                             | <b>TM32796</b><br>   |
| 950 AXOR 2<br>952 AXOR 2<br>953 AXOR 2<br>954 AXOR 2  | Gear Shift Control<br>Repl. Kongsberg:<br>629862AM            | 0002606098   | <b>TM32797</b><br>  |
| 343 T2/L<br>346 L 1924<br>346 L 1928<br>346 LK 1924<br>346 LK 1928<br>346 LS 1924<br>346 LS 1928                        | Cylinder, Gear Shift Control<br>Repl. Wabco: 422 010<br>000 0 | 0002603563<br>0002604763<br>0002601763<br>0002605363 | <b>TM32364</b><br> |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3              | Cylinder, Gear Shift Control<br>Repl. Kongsberg:<br>629614AM  | 0022600663<br>0012601863                             | <b>TM32556</b><br> |
| 950 AXOR 2<br>952 AXOR 2<br>953 AXOR 2<br>954 AXOR 2<br>382 O 500 M / 1728<br>634 O 500<br>634 TOURO                    | Cylinder, Gear Shift Control<br>Repl. Kongsberg:<br>627494AM  | 0012605963   | <b>TM32612</b><br> |
| 343 T2/L<br>350 LS 1924<br>350 LS 1924A,1929<br>350 LS 1924A,1929,1930<br>350 LS 1932,1933<br>350 LS 1934<br>386 L 1622 | Cylinder, Gear Shift Control                                  | 0002672119<br>0002670819<br>0002670419<br>0002670319 | <b>TM32542</b><br> |












| TM No.  | Replaces Ref. No:                      | Description   | Model / Details  |
|---|--|---|--|
| <b>TM32803</b><br>   | 0012602563                             | Cylinder, Gear Shift Control<br>Repl. Kongsberg:<br>626156AM                        | 950 AXOR 2<br>952 AXOR 2<br>953 AXOR 2<br>954 AXOR 2<br>685 OF SERIES<br>368 OH SERIES<br>382 O 500 M / 1728 |
| <b>TM32801</b><br>   | 0012609763                             | Cylinder, Gear Shift Control<br>Repl. Kongsberg:<br>629303AM                        | 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3       |
| <b>TM32802</b><br>   | 0012608863                             | Cylinder, Gear Shift Control<br>Repl. Kongsberg:<br>629137AM<br>M16x1,5x64/ø10,5x85 | 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3       |
| <b>TM32933</b><br> | 0022601663                             | Cylinder, Gear Shift Control<br>Repl. Kongsberg: AE4800                             | 950 AXOR 2<br>952 AXOR 2<br>954 AXOR 2   |
| <b>TM31947</b><br> | 0069974946                             | Seal Ring, Gear Shift Control<br>ø25xø35x7 / NBR                                    | 970 ATEGO 2<br>976 ATEGO 2<br>336 LP 1924<br>336 LPS 1924<br>343 T2/L<br>345 L 1519,1520<br>346 L 1924       |
| <b>TM31959</b><br> | 0002670197<br>0002670397               | Seal Ring, Gear Shift Control<br>ø21xø32x8  | 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3       |
| <b>TM31951</b><br> | 0002670697<br>0002670297<br>0002670097 | Seal Ring, Gear Shift Control<br>ø25xø38x10/14,50 /<br>FPM                          | 343 T2/L<br>350 LS 1924<br>386 L 1633<br>388 L 1929<br>388 L 1935<br>388 L 1938                              |



| Model / Details  | Description   | Replaces Ref. No:                                    | TM No.  |
|--|---|--|---|
| 930 ACTROS 2/3<br>963 ACTROS MP4<br>964 AROCS<br>375 AXOR<br>374 AXOR 2<br>958 AXOR 2<br>676 LK/LN2                              | Seal Ring, Gear Shift<br>Control                          | 0069976447<br>0209976647<br>0129973347               | <b>TM31957</b><br>   |
| 950 AXOR 2<br>952 AXOR 2<br>953 AXOR 2<br>954 AXOR 2<br>382 O 500 M / 1728<br>634 O 500<br>634 TOURO                             | Repair Kit, Gear Shift<br>Control                         | 0002605098   | <b>TM33127</b><br>   |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3                       | Repair Kit, Gear Shift<br>Control<br>ø23x38,8/ø25x38,8    | 0002604998   | <b>TM33122</b><br>   |
| 341 LA 1114<br>345 LA 1313<br>345 LA 1313,1314,1317<br>345 LAK 1313,1314,1317<br>345 LG 1819/1820<br>352 LA 1313<br>352 LAK 1313 | Sensor, Gear Shift Control<br>M18x1,5/M27x1x55x-<br>SW:27 | 0015453414<br>0015454414<br>0025458114<br>0035451614 | <b>TM31613</b><br> |
| 345 LG 1819/1820<br>667 T2/LN1<br>673 LK/LN2<br>674 LK/LN2<br>675 LK/LN2<br>676 LK/LN2<br>677 LK/LN2                             | Sensor, Gear Shift Control<br>M18x1,5/M27x1x43x-<br>SW:27 | 0015454111   | <b>TM36949</b><br> |
| 901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER<br>905 SPRINTER   | Cable, Gear Shift Control                                 | 9012601551   | <b>TM36950</b><br> |
| 901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER<br>905 SPRINTER   | Cable, Gear Shift Control                                 | 9012601538   | <b>TM32946</b><br> |








| TM No.  | Replaces Ref. No:         | Description               | Model / Details  |
|---|---------------------------|---------------------------|--|
| <b>TM36951</b>  | 9062600251<br>9062601651  | Cable, Gear Shift Control | 906 SPRINTER   |
|    |                           |                           |  |
| <b>TM36952</b>  | 9062600351<br>9062601751  | Cable, Gear Shift Control | 906 SPRINTER   |
|    |                           |                           |  |
| <b>TM36953</b>  | 9012601438                | Cable, Gear Shift Control | 901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER<br>905 SPRINTER |
|    |                           |                           |  |
| <b>TM36954</b>  | 6382600751<br>6382601051  | Cable, Gear Shift Control | 638 V-CLASS  |
|  |                           |                           |  |
| <b>TM36955</b>  | 63826006511<br>6382600951 | Cable, Gear Shift Control | 638 VITO<br>638 V-CLASS  |
|  |                           |                           |  |
| <b>TM36956</b>  | 0002680191                | Cable, Gear Shift Control | 638 VITO<br>638 V-CLASS  |
|  |                           |                           |  |
| <b>TM36957</b>  | 0002680091                | Cable, Gear Shift Control | 638 VITO<br>638 V-CLASS  |
|  |                           |                           |  |



| Model / Details   | Description               | Replaces Ref. No:        | TM No.  |
|---|---------------------------|--------------------------|---|
| 384 OF SERIES<br>634 O 500<br>634 O 500 RSD /<br>2736/8X2/30<br>634 TOURO<br>633 INTEGRO<br>632 TOURISMO<br>629 TRAVEGO | Cable, Gear Shift Control | 0002880173               | <b>TM36958</b><br>   |
| 375 ACTROS<br>375 AXOR<br>375 AXOR 2  | Link, Gear Shifting       | 3752600337               | <b>TM36959</b><br>   |
| 375 ACTROS<br>375 AXOR<br>375 AXOR 2  | Link, Gear Shifting       | 3752600037               | <b>TM36960</b><br>  |
| 375 ACTROS<br>375 AXOR<br>375 AXOR 2  | Link, Gear Shifting       | 3752600562               | <b>TM36961</b><br> |
| 375 ACTROS<br>970 ATEGO<br>972 ATEGO<br>976 ATEGO<br>970 ATEGO 2<br>972 ATEGO 2<br>974 ATEGO 2                          | Link, Gear Shifting       | 9762681515               | <b>TM36962</b><br> |
| 375 AXOR<br>374 AXOR 2<br>940 AXOR 2<br>942 AXOR 2<br>943 AXOR 2<br>944 AXOR 2<br>958 AXOR 2                            | Link, Gear Shifting       | 9452601937<br>9452601237 | <b>TM36963</b><br> |
| 375 AXOR<br>374 AXOR 2<br>940 AXOR 2<br>942 AXOR 2<br>943 AXOR 2<br>944 AXOR 2<br>958 AXOR 2                            | Link, Gear Shifting       | 9452601062<br>9452600762 | <b>TM36964</b><br> |





| TM No.  | Replaces Ref. No:                                    | Description   | Model / Details  |
|---|--|---|--|
| <b>TM32599</b><br>   | 0012603463   | Cylinder, Gear Shifting<br>Kongsberg Type, Brake<br>Fluid<br>Repl. Kongsberg:<br>626597AM | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3                       |
|   | 0002607063   | Cylinder, Gear Shifting<br>Repl. Wabco: 422 010<br>014 0                                  | -  |
| <b>TM32363</b><br>   | 0002604663   | Cylinder, Gear Shifting<br>Repl. Wabco: 422 010<br>012 0                                  | 343 T2/L<br>345 L 2225<br>345 LS 1524/1525<br>346 L 1928<br>346 LK 1928<br>346 LS 1928<br>351 L 1526                             |
|   | 0002604163<br>0002605463<br>0002602803               |   |  |
| <b>TM36965</b><br>  | 3852600563<br>3852600063<br>9412600063               | Cylinder, Gear Shifting   | 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>954 ACTROS<br>375 AXOR<br>374 AXOR 2<br>375 AXOR 2                                     |
|   |  |   |  |
| <b>TM32513</b><br> | 0012605957<br>0012600657<br>0002609857               | Valve, Gear Shifting<br>Repl. Wabco: 463 063<br>002 0                                     | 343 T2/L<br>350 LS 1924<br>677 LK/LN2<br>652 MK<br>653 MK<br>615 NG<br>617 NG  |
|   |  |   |  |
| <b>TM32016</b><br> | 0012600257<br>0002606857<br>0002606957<br>0012600057 | Valve, Gear Shifting<br>Repl. Knorr: SV3360   | 386 L 1625,1725<br>386 L 2325,2425,LA<br>2425/6X6<br>386 LB 2325,2425<br>386 LK 2325,2425<br>386 LS 1625<br>677 LK/LN2<br>617 NG |
|   |  |   |  |
| <b>TM36966</b><br> | 9452600057<br>9452601457<br>9702600457<br>9702601057 | Valve, Gear Shifting  | 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3                           |
|   |  |   |  |





| Model / Details  | Description  | Replaces Ref. No:                                    | TM No.         |
|--|--|--|----------------|
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 | Pipe, Gear Shifting                                    | 9412617983   | <b>TM36967</b> |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 | Pipe, Gear Shifting                                    | 9402614783<br>9412618083                             | <b>TM36968</b> |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 | Pipe, Gear Shifting                                    | 9432614583<br>9412615183                             | <b>TM36969</b> |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 | Pipe, Gear Shifting                                    | 9432614483<br>9412615083                             | <b>TM36970</b> |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>375 ATEGO<br>970 ATEGO<br>972 ATEGO                | Pipe, Gear Shifting                                    | 900331012338   | <b>TM32035</b> |
| 336 LP 1924<br>336 LPS 1924<br>343 T2/LN1<br>346 L 1924<br>346 LA 1924<br>346 LAK 1924<br>346 LAS 1924     | Reverse Lamp Switch,<br>Gear Shifting<br>M27x1/ø17,5   | 0005452806<br>0005455906<br>0015453014<br>0015457614 | <b>TM32497</b> |
| 676 LK/LN2<br>677 LK/LN2<br>650 MK<br>651 MK<br>652 MK<br>653 MK<br>654 MK                                 | Reverse Lamp Switch,<br>Gear Shifting<br>M16x1,5/M27x1 | 0005459409<br>0015451309<br>0015452909<br>0015455509 | <b>TM31641</b> |



| TM No.  | Replaces Ref. No:                                      | Description  | Model / Details  |
|---|--|--|--|
| <b>TM36971</b>  | 0119972246   | Seal Ring, Gear Selector Housing<br>ø25xø32x5 / NBR            | 970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>970 ATEGO 2<br>972 ATEGO 2<br>975 ATEGO 2<br>343 T2/L               |
|    |  |  |  |
| <b>TM23357</b>  | 0119974746<br>0029972747<br>0099979746<br>003760025100 | Seal Ring, Gear Selector Housing<br>ø25xø35x7 / NBR            | 336 LP 1924<br>336 LPS 1924<br>338 L 1418<br>338 LK 1418<br>338 LP 1418<br>338 LPS 1418<br>338 LS 1418     |
|    |  |  |  |
| <b>TM36972</b>  | 0002671597   | Seal Ring, Gear Selector Housing<br>ø22xø36x14,5 / FPM         | 397 1623 S MBSA-RSA<br>613 TOURISMO  |
|    |  |  |  |
| <b>TM31958</b>  | 0249978347   | Seal Ring, Gear Selector Housing<br>ø80xø90x18                 | 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3     |
|  |  |  |  |
| <b>TM36973</b>  | 0095421717   | Sensor, Gear Selector Housing<br>Repl. Wabco: 441 100<br>070 0 | 651 MK<br>652 MK<br>653 MK<br>654 MK<br>624 NG<br>625 NG<br>645 NG   |
|  |  |  |  |
| <b>TM11457</b>  | 0005429218<br>0005459209                               | Sensor, Gear Selector Housing                                  | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 |
|  |  |  |  |
| <b>TM31640</b>  | 0015454714<br>0015455709                               | Sensor, Gear Selector Housing                                  | 979 ACCELO<br>375 ATEGO<br>375 ATEGO 2<br>967 ATEGO 3<br>958 AXOR 2<br>352 LA 1313<br>353 T2/L             |
|  |  |  |  |




| Model / Details  | Description                                  | Replaces Ref. No:                      | TM No.  |
|--|--|--|---|
| 375 ACTROS<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS<br>970 ATEGO<br>972 ATEGO<br>976 ATEGO                        | Sensor, Gear Selector<br>Housing<br>86xSW:27 | 0015457209                             | <b>TM36974</b><br>   |
| 901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER   | Mounting, Gear Box<br>ø10xø73x88             | 9012421513<br>9012421413               | <b>TM01101</b><br>   |
| 611 T1/TN<br>601 207 D/208 D<br>601 209 D/210 D<br>602 307 D/308 D<br>602 307 D/308D<br>602 308 D<br>602 309 D/310 D | Mounting, Gear Box<br>M8/M12/ø8,5            | 6012400318                             | <b>TM36975</b><br>  |
| 639 VIANO  | Mounting, Gear Box<br>Rear<br>M8/10,75       | 6392420713                             | <b>TM36976</b><br> |
| 901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER   | Mounting, Gear Box<br>Rear<br>M10x30         | 2202400218<br>2122400418<br>2202400518 | <b>TM00340</b><br> |
| 447 VITO - 447 V CLASS -<br>448 VITO - 448<br>V CLASS  | Mounting, Gear Box<br>M8/11                  | 4472410113                             | <b>TM36977</b><br> |
| 611 T1/TN<br>414 Vaneo<br>601 209 D/210 D<br>602 309 D/310 D<br>901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER         | Hose, Gear Box                               | 0199978382                             | <b>TM36978</b><br> |










| TM No.  | Replaces Ref. No:                                      | Description   | Model / Details  |
|---|--|---|--|
| <b>TM36979</b><br>   | 0002366105   | Valve, Power Take Off   | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 |
| <b>TM31931</b><br>   | 0049970646<br>0119974347                               | Seal Ring, Power Take Off<br>ø85xø105x10 / NBR                | 336 LP 1924<br>336 LPS 1924<br>343 T2/L<br>343 T2/LN1<br>345 L 1519<br>345 L 1519,1520<br>345 L 2219,2220  |
| <b>TM30318</b><br>  | 0109974247<br>0109972847<br>0109972747<br>0219971247   | Seal Ring, Power Take Off<br>ø48xø65x10 / FPM                 | 979 ACCELO<br>963 ACTROS MP4<br>375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>976 ATEGO<br>375 ATEGO 2            |
| <b>TM26545</b><br> | 0059810705<br>0149810605<br>0059810605                 | Bearing, Power Take Off<br>Repl. FAG: 33207<br>ø35xø72x28     | 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3     |
| <b>TM36980</b><br> | 0019815705<br>0019812305                               | Bearing, Power Take Off<br>Repl. FAG: 30306A<br>ø30xø72x20,75 | 963 ACTROS MP4<br>375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>976 ATEGO<br>375 ATEGO 2<br>970 ATEGO 2           |
| <b>TM24604</b><br> | 0019811505<br>0019816505<br>000720032206<br>0019816105 | Bearing, Power Take Off<br>Repl. FAG: 32206A<br>ø30xø62x21,5  | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 |
| <b>TM33076</b><br> | 9425010582   | Hose, Retarder  | 979 ACCELO<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3     |



| Model / Details  | Description                         | Replaces Ref. No:            | TM No.  |
|--|-------------------------------------|------------------------------|---|
| 427 UNIMOG<br>437 UNIMOG<br>699 1424 LAP AEGYPTEN  | Fitting, Retarder<br>ø8xø11x9,5     | 003861008004<br>074297008202 | <b>TM25695</b><br>   |
| 310 LF 508 D/LF 608 D<br>310 T2/L<br>313 T2/L<br>314 LP<br>316 LP<br>318 LP<br>343 T2/L                | Fitting, Retarder<br>Brass<br>ø8/ø6 | 0007630043<br>915062006000   | <b>TM17748</b><br>   |
| 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3 | Sensor, Retarder                    | 0008210081<br>0015405217     | <b>TM12179</b><br>   |
| 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3                                   | Cooling Pipe, Retarder              | 5412030430                   | <b>TM36981</b><br> |
| -  | -                                   | -                            | -   |
| -  | -                                   | -                            | -   |
| -  | -                                   | -                            | -   |












| TM No.  | Replaces Ref. No:                                    | Description                | Model / Details  |
|---|--|----------------------------|--|
| <b>TM36982</b><br>   | 0304102031   | Joint Cross<br>ø38x105,8   | -  |
| <b>TM34070</b><br>   | 3354100031<br>0004100531                             | Joint Cross<br>ø52x133     | 336 LP 1924<br>336 LPS 1924<br>346 L 1924<br>346 LA 1924<br>346 LAK 1924<br>346 LAS 1924<br>346 LK 1924    |
| <b>TM34152</b><br>   |  | Joint Cross<br>ø65x172     | 388 LS 1935<br>388 LS 1941<br>388 LS 1945<br>649 NG<br>625 SK<br>655 SK<br>656 SK                          |
| <b>TM34151</b><br> | 9704100031   | Joint Cross<br>ø31x110     | 970 ATEGO 2<br>972 ATEGO 2<br>976 ATEGO 2  |
| <b>TM34153</b><br> | 9424100231   | Joint Cross<br>ø68x117     | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 |
| <b>TM36983</b><br> | -  | Joint Cross<br>ø24,06x73,6 | -  |
| <b>TM34143</b><br> | 3854100231<br>3024100031<br>3454107031<br>3104100031 | Joint Cross<br>ø38x100     | 385 410 02 31<br>302 410 00 31<br>345 410 70 31<br>310 410 00 31   |





| Model / Details  | Description              | Replaces Ref. No:  | TM No.  |
|--|--------------------------|--|---|
| 318 LP<br>352 L 1313<br>352 L 1813/6X2<br>352 L 1813/6X4<br>352 LA 1313<br>352 LAK 1313<br>352 LAKO 1313                                       | Joint Cross<br>ø42x106   | 6174100031<br>9714100031<br>0004104031                   | <b>TM34150</b><br>   |
| 338 L 1418<br>338 LK 1418<br>338 LP 1418<br>338 LPS 1418<br>338 LS 1418<br>360 L 1513<br>360 L 1817,1819/6X4                                   | Joint Cross<br>ø42x115   | 3854100131<br>3174100131<br>3374100031<br>3374105031     | <b>TM34149</b><br>   |
| 346 LA 1924<br>346 LAK 1924<br>346 LAS 1924<br>351 L 1521<br>360 L 1817,1819/6X4<br>360 L 1819/6X4<br>363 LP 2226/6X4                          | Joint Cross<br>ø45x120,4 | 3044100031<br>3174100031<br>3314100031<br>0004100031     | <b>TM34068</b><br>  |
| 345 L 2219,2220<br>345 L 2225<br>345 LB 2219,2220<br>345 LG 1819/1820<br>345 LK 2219,2220<br>397 2219 6X4 MBSA-RSA<br>397 2219 B/6X4 MB-SA-RSA | Joint Cross<br>ø48x126   | 3854100531<br>3814100231<br>9734100031<br>3604100231     | <b>TM34119</b><br> |
| 346 L 1924<br>346 LK 1924<br>346 LS 1924<br>349 L 1621<br>349 L 1921<br>349 LK 1621<br>349 LK 1921   | Joint Cross<br>ø53x135   | 3634100631<br>9424100131<br>6204100131<br>0004100231     | <b>TM34144</b><br> |
| 345 L 2225<br>346 L 1928<br>346 LK 1928<br>346 LS 1928<br>350 LS 1924A,1929<br>350 LS 1924A,1929,1930<br>351 L 1526                            | Joint Cross<br>ø57x152   | 3874100031S<br>9404100031S<br>0004100131S<br>6204100031S | <b>TM36984</b><br> |
| 696 LK 2638<br>696 LS 2638<br>693 1938 S   | Joint Cross<br>ø68x167   | 9424100031<br>6564100131                                 | <b>TM34078</b><br> |









| TM No.  | Replaces Ref. No: | Description                       | Model / Details |
|---|-------------------|-----------------------------------|-----------------|
| <b>TM34255</b><br>   | 9734100022        | Propeller Shaft Bearing<br>ø55x21 | 970 ATEGO       |
|   | 3854101722        |                                   | 972 ATEGO       |
|   | 3854100922        |                                   | 970 ATEGO 2     |
|   | 3854100122        |                                   | 974 ATEGO 2     |
|   |                   |                                   | 976 ATEGO 2     |
|   | 950 AXOR 2        |                                   | 952 AXOR 2      |
| <b>TM36985</b><br>   | 6014102110        | Propeller Shaft Bearing<br>ø45    | 611 T1/TN       |
|   | 6014101710        |                                   | 601 207 D/208 D |
|   | 6015860041        |                                   | 601 208/210     |
|   | 6014100410        |                                   | 601 209 D/210 D |
|   |                   |                                   | 602 307 D/308 D |
|   | 602 308 D         |                                   | 602 308 D       |
| <b>TM34148</b><br>  | 6554100122        | Propeller Shaft Bearing<br>ø70x20 | 386 L 1633      |
|   | 6554100022        |                                   | 386 LS 1630     |
|   | 3954100622        |                                   | 386 LS 1633     |
|   | 3954100022        |                                   | 388 L 1929      |
|   |                   |                                   | 388 L 1935      |
|   | 388 L 1938        |                                   | 388 L 1945      |
| <b>TM36986</b><br> | 6554100122S       | Propeller Shaft Bearing<br>ø109,5 | 386 L 1633      |
|   | 6554100022S       |                                   | 386 LS 1630     |
|   | 3954100622S       |                                   | 386 LS 1633     |
|   |                   |                                   | 388 L 1929      |
|   |                   |                                   | 388 L 1935      |
|   | 388 L 1938        |                                   | 388 L 1945      |
| <b>TM34258</b><br> | 3104100822        | Propeller Shaft Bearing<br>ø35    | 309 T2/L        |
|   | 3094100110        |                                   | 309 TL2/L       |
|   | 3095860141        |                                   | 310 T2/L        |
|   | 3104100922        |                                   | 313 T2/L        |
|   |                   |                                   | 317 O 317       |
|   | 309 O 309 D       |                                   | 310 O 309 D     |
| <b>TM34256</b><br> | 3814100010        | Propeller Shaft Bearing<br>ø45    | 669 T2/LN1      |
|   | 3814100222        |                                   | 670 T2/LN1      |
|   | 3814101222        |                                   | 674 LK/LN2      |
|   | 3814101522        |                                   | 675 LK/LN2      |
|   |                   |                                   | 676 LK/LN2      |
|   | 678 LK/LN2        |                                   | 380 NG          |
| <b>TM34254</b><br> | 6544100022        | Propeller Shaft Bearing<br>ø60x22 | 970 ATEGO 2     |
|   | 3894100222        |                                   | 976 ATEGO 2     |
|   | 3894100122        |                                   | 950 AXOR 2      |
|   | 3954100222        |                                   | 346 L 1924      |
|   |                   |                                   | 346 LK 1924     |
|   | 346 LS 1924       |                                   | 651 MK          |



| Model / Details  | Description                                | Replaces Ref. No:                      | TM No.  |
|--|--|--|---|
| 668 T2/LN1<br>669 T2/LN1<br>670 T2/LN1<br>673 LK/LN2   | Propeller Shaft Bearing<br>ø35             | 4604100022<br>4604100222               | <b>TM34146</b><br>   |
| 970 ATEGO<br>970 ATEGO 2<br>976 ATEGO 2<br>667 VARIO<br>668 VARIO<br>670 VARIO                   | Propeller Shaft Bearing<br>ø45             | 9704110012<br>6704110112<br>0004110212 | <b>TM34195</b><br>   |
| 970 ATEGO 2<br>976 ATEGO 2<br>950 AXOR 2   | Propeller Shaft Bearing<br>ø60             | 6544110012                             | <b>TM34263</b><br>   |
| 963 ACTROS MP4<br>964 ANTOS<br>964 AROCS<br>967 ATEGO 3  | Propeller Shaft Bearing<br>ø70             | 6564110212<br>6564110012               | <b>TM34259</b><br> |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3     | Propeller Shaft Bearing<br>ø80             | 6594110112                             | <b>TM34261</b><br> |
| 963 ACTROS MP4<br>964 AROCS<br>375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>375 ATEGO 2<br>970 ATEGO 2 | Propeller Shaft Bearing<br>ø55             | 9734110112<br>9734110012               | <b>TM34264</b><br> |
| 639 VIANO  | Propeller Shaft Bearing<br>Rear<br>ø30x148 | 6394100681                             | <b>TM34266</b><br> |












| TM No.  | Replaces Ref. No:  | Description                                       | Model / Details  |
|---|--|---|--|
| <b>TM34268</b><br>   | 6394100481   | Propeller Shaft Bearing<br>Front<br>ø30           | 639 VITO<br>636 VIANO<br>639 VIANO   |
| <b>TM34270</b><br>   | 9014110312<br>9014110412                                   | Propeller Shaft Bearing<br>ø45                    | 690 SPRINTER   |
| <b>TM36987</b><br>   | 9064100381S<br>9064101081S<br>9064100581S<br>9064100281S   | Propeller Shaft Bearing<br>With Washer<br>ø47x194 | 900 SPRINTER<br>906 SPRINTER   |
| <b>TM36988</b><br> | 6204136842   | Bracket, Propeller Shaft<br>Bearing<br>Left       | 623 NG<br>624 NG<br>625 SK<br>658 SK<br>659 SK                               |
| <b>TM36989</b><br> | 6204136942   | Bracket, Propeller Shaft<br>Bearing<br>Right      | 623 NG<br>624 NG<br>625 SK<br>658 SK<br>659 SK                               |
| <b>TM34260</b><br> | 9034100010<br>9014100310                                   | Repair Kit, Propeller Shaft<br>Bearing<br>ø45     | 901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER<br>905 SPRINTER |
| <b>TM36990</b><br> | 9064100381S1<br>9064101781S<br>9064100281S1<br>9064101181S | Repair Kit, Propeller Shaft<br>Bearing<br>ø47     | 906 SPRINTER   |



| Model / Details  | Description                         | Replaces Ref. No:        | TM No.         |
|--|-------------------------------------|--------------------------|----------------|
| 972 ATEGO<br>976 ATEGO<br>970 ATEGO 2<br>972 ATEGO 2<br>976 ATEGO 2<br>967 ATEGO 3<br>950 AXOR 2               | Lock Washer, Axle<br>ø88,5xø123x13  | 3553560173               | <b>TM26303</b> |
| 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>934 ACTROS 2/3     | Lock Washer, Axle<br>ø89xø106,5x1,5 | 3463560073               | <b>TM26302</b> |
| 950 ACTROS<br>930 ACTROS 2/3<br>934 ACTROS 2/3<br>963 ACTROS MP4<br>964 ANTOS<br>964 AROCS<br>375 ATEGO        | Lock Washer, Axle<br>ø81xø100x3,25  | 9763560052               | <b>TM26360</b> |
| 375 ACTROS<br>950 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>934 ACTROS 2/3<br>963 ACTROS MP4<br>964 ACTROS MP4 | Lock Washer, Axle<br>ø100,7xø16     | 9463560073               | <b>TM30726</b> |
| 375 ACTROS<br>950 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>934 ACTROS 2/3<br>963 ACTROS MP4<br>964 ACTROS MP4 | Lock Washer, Axle<br>ø101xø125x4    | 9463560152               | <b>TM32512</b> |
| 930 ACTROS 2/3<br>934 ACTROS 2/3<br>963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS<br>958 AXOR 2   | Axle Nut<br>M100x1,5                | 9463560226               | <b>TM36991</b> |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3     | Axle Nut<br>M40x1,5                 | 6523300088<br>3893320072 | <b>TM30673</b> |





| TM No.  | Replaces Ref. No:          | Description                      | Model / Details  |
|---|----------------------------|----------------------------------|--|
| <b>TM36992</b>  | 3853560026<br>070852075000 | Axle Nut<br>M75x1,5              | 375 AXOR 2<br>338 L 1418<br>338 LK 1418<br>338 LP 1418<br>338 LPS 1418<br>338 LS 1418<br>344 L 1113/L 1114 |
|    |                            |                                  |  |
| <b>TM26250</b>  | 6563300088                 | Axle Nut<br>M45x1,5              | 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3     |
|    |                            |                                  |  |
| <b>TM26257</b>  | 9709900050                 | Axle Nut<br>M80x1,5x21/SW94 RHT  | 970 ATEGO<br>970 ATEGO 2<br>967 ATEGO 3  |
|    |                            |                                  |  |
| <b>TM26258</b>  | 9709900150                 | Axle Nut<br>M80x1,5x21/SW94 LHT  | 970 ATEGO<br>970 ATEGO 2   |
|  |                            |                                  |  |
| <b>TM26268</b>  | 0009903260                 | Axle Nut<br>M105x1,5/10xSW 121,4 | 382 OH SERIES<br>382 O 500   |
|  |                            |                                  |  |
| <b>TM36993</b>  | 0029908150                 | Axle Nut<br>M70x1,5              | 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3     |
|  |                            |                                  |  |
| <b>TM36994</b>  | 9703530026                 | Axle Nut                         | 979 ACCELO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>970 ATEGO 2<br>972 ATEGO 2<br>975 ATEGO 2             |
|  |                            |                                  |  |





| Model / Details  | Description  | Replaces Ref. No:                       | TM No.  |
|--|--|---|---|
| 950 ACTROS<br>930 ACTROS 2/3<br>934 ACTROS 2/3<br>963 ACTROS MP4<br>964 ANTOS<br>964 AROCS<br>375 ATEGO            | Axle Nut   | 9763560026                              | <b>TM30552</b><br>   |
| 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3             | Axle Nut<br>Grooved<br>M88x1,5/ø112                    | 9423560126<br>3463560126                | <b>TM36995</b><br>   |
| 343 T2/LN1   | Axle Nut<br>M100x2                                     | 3439900050<br>3043340026                | <b>TM27152</b><br>   |
| 387 NG<br>389 NG<br>616 NG<br>617 NG<br>619 NG<br>620 NG<br>621 NG   | Seal Ring, Axle Steering<br>Knuckle<br>ø50xø58x4 / NBR | 0119973546<br>0109975246<br>0109974146  | <b>TM30603</b><br> |
| 601 207 D/208 D<br>601 208/210<br>601 209 D/210 D<br>602 307 D/308 D<br>602 307 D/308D<br>602 308 D<br>602 308/310 | King Pin Kit, Axle Steering<br>Knuckle<br>ø23x131,5    | 6013300419                              | <b>TM36996</b><br> |
| 601 207 D/208 D<br>601 208/210<br>601 209 D/210 D<br>602 307 D/308 D<br>602 307 D/308D<br>602 308 D<br>602 308/310 | King Pin Kit, Axle Steering<br>Knuckle<br>ø23x131,5    | 6013300019<br>6015865033<br>6013325306S | <b>TM36997</b><br> |
| 398 LO 814<br>670 T2/LN1<br>673 LK/LN2<br>674 LK/LN2<br>676 LK/LN2<br>688 1114<br>688 709                          | King Pin Kit, Axle Steering<br>Knuckle<br>ø30x186      | 6703300119<br>6753300119                | <b>TM30336</b><br> |












| TM No.  | Replaces Ref. No:        | Description  | Model / Details  |
|---|--------------------------|--|--|
| <b>TM36998</b><br>   | 6013300319               | King Pin Kit, Axle Steering<br>Knuckle<br>ø40xø70x46,5 | 601 207 D/208 D<br>601 208/210<br>601 209 D/210 D<br>602 307 D/308 D<br>602 307 D/308D<br>602 308 D<br>602 308/310 |
|   | 6753301419<br>6753300219 | King Pin Kit, Axle Steering<br>Knuckle<br>ø33x186      | 673 LK/LN2<br>674 LK/LN2<br>675 LK/LN2<br>676 LK/LN2<br>677 LK/LN2<br>678 LK/LN2<br>684 OF SERIES                  |
| <b>TM36999</b><br>   | 6113300419               | King Pin Kit, Axle Steering<br>Knuckle<br>ø26x136      | 611 T1/TN<br>602 307 D/308 D<br>602 307 D/308D<br>602 308 D<br>602 308/310<br>602 309 D/310 D<br>602 310 D         |
|   | 6753301919<br>6753300519 | King Pin Kit, Axle Steering<br>Knuckle<br>ø38x217      | 675 LK/LN2<br>676 LK/LN2<br>677 LK/LN2<br>678 LK/LN2<br>679 LK/LN2<br>650 MK<br>651 MK                             |
| <b>TM37001</b><br> | 6753301819<br>6753300419 | King Pin Kit, Axle Steering<br>Knuckle<br>ø38x217      | 675 LK/LN2<br>676 LK/LN2<br>677 LK/LN2<br>678 LK/LN2<br>679 LK/LN2<br>650 MK<br>651 MK                             |
|   | 3103300019               | King Pin Kit, Axle Steering<br>Knuckle<br>ø27x153      | King Pin Kit, Axle Steering<br>Knuckle   |
| <b>TM37003</b><br> | 6703300219<br>6753300019 | King Pin Kit, Axle Steering<br>Knuckle<br>ø30x186      | 670 T2/LN1<br>673 LK/LN2<br>674 LK/LN2<br>676 LK/LN2<br>688 LO 712/37<br>688 LO 812<br>688 LO 812 814 /42,5        |



| Model / Details  | Description   | Replaces Ref. No:        | TM No.  |
|--|---|--------------------------|---|
| 341 L 1114<br>341 L 914<br>341 LK 1114<br>341 LO 1114<br>341 LS 1114<br>344 L 1113/L 1114<br>344 L 1118                        | King Pin Kit, Axle Steering<br>Knuckle<br>ø38x217     | 3603300619<br>3605860033 | <b>TM37004</b><br>   |
| 673 LK/LN2<br>674 LK/LN2<br>675 LK/LN2<br>676 LK/LN2<br>677 LK/LN2<br>678 LK/LN2<br>684 OF SERIES                              | King Pin Kit, Axle Steering<br>Knuckle<br>ø33x186     | 6753301519<br>6753300319 | <b>TM37005</b><br>   |
| 351 L 1514<br>351 L 1517,1518<br>351 L 1521<br>351 LK 1514<br>351 LK 1518<br>351 LS 1517,1518<br>352 L 1313                    | King Pin Kit, Axle Steering<br>Knuckle<br>ø36,6x211   | 3603300719<br>3605860233 | <b>TM37006</b><br>  |
| 386 L 1614,1714<br>386 L 1618,1718<br>386 L 1620<br>386 L 1621,1721<br>386 L 1621,L 1721<br>386 L 1625,1725<br>386 L 2314,2414 | King Pin Kit, Axle Steering<br>Knuckle<br>ø45x218     | 3553300319<br>3555860033 | <b>TM30337</b><br> |
| 611 T1/TN<br>602 307 D/308 D<br>602 307 D/308D<br>602 308 D<br>602 308/310<br>602 309 D/310 D<br>602 310 D                     | King Pin Kit, Axle Steering<br>Knuckle<br>ø26x136     | 6113300319               | <b>TM37007</b><br> |
| 611 T1/TN<br>602 307 D/308 D<br>602 307 D/308D<br>602 308 D<br>602 308/310<br>602 309 D/310 D<br>602 310 D                     | King Pin Kit, Axle Steering<br>Knuckle<br>ø26x136     | 6113300019               | <b>TM37008</b><br> |
| 650 MK<br>651 MK<br>652 MK<br>653 MK<br>654 MK<br>617 NG<br>619 NG   | King Pin Kit, Axle Steering<br>Knuckle<br>ø50/ø51x223 | 3005860033<br>3003300019 | <b>TM37009</b><br> |





| TM No.  | Replaces Ref. No: | Description                 | Model / Details   |
|---|-------------------|-----------------------------|---|
| <b>TM30510</b><br>   | 3913300019        | King Pin Kit, Axle Steering | 343 T2/L  |
|   | 3895860033        | Knuckle                     | 343 T2/LN1  |
|   | 3915860033        | ø50/ø51x223                 | 346 L 1924<br>346 L 1928<br>346 LK 1924<br>346 LK 1928<br>346 LS 1924         |
| <b>TM30357</b><br>   | 3433300219        | King Pin Kit, Axle Steering | 336 LP 1924   |
|   | 3435860233        | Knuckle                     | 336 LPS 1924  |
|   | 3265860033        | ø45/ø46x225                 | 343 T2/LN1<br>346 L 1924<br>346 L 1928<br>346 LK 1924<br>346 LK 1928          |
| <b>TM37010</b><br>   | 6683300019        | King Pin Kit, Axle Steering | 309 T2/L  |
|   | 3103301219        | Knuckle                     | 309 TL2/L   |
|   |                   | ø27x153                     | 310 LF 508 D/LF 608 D<br>310 T2/L<br>313 T2/L<br>669 T2/LN1<br>670 T2/LN1     |
| <b>TM30662</b><br> | 6253300119        | King Pin Kit, Axle Steering | 950 ACTROS  |
|   |                   | Knuckle                     | 952 ACTROS  |
|   |                   | M24xø55x109                 | 954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>934 ACTROS 2/3<br>964 AROCS |
| <b>TM31012</b><br> | 6253300219        | King Pin Kit, Axle Steering | 624 NG  |
|   |                   | Knuckle                     | 625 NG  |
|   |                   | M24xø55/ø60x126             | 649 NG<br>625 SK<br>655 SK<br>656 SK<br>659 SK                                |
| <b>TM31002</b><br> | 6253300419        | King Pin Kit, Axle Steering | 950 ACTROS  |
|   |                   | Knuckle                     | 952 ACTROS  |
|   |                   | M24xø55/ø60x126             | 954 ACTROS<br>950 AXOR 2<br>624 NG<br>625 NG<br>649 NG                        |
| <b>TM30535</b><br> | 3463300019        | King Pin Kit, Axle Steering | 950 ACTROS  |
|   | 3465860033        | Knuckle                     | 952 ACTROS  |
|   |                   | Upper Front Axle            | 954 ACTROS  |
|   |                   | M24x1,5/ø50x109             | 930 ACTROS 2/3<br>932 ACTROS 2/3<br>934 ACTROS 2/3<br>964 AROCS               |



| Model / Details  | Description   | Replaces Ref. No:                         | TM No.  |
|--|---|---|---|
| 950 ACTROS<br>952 ACTROS<br>954 ACTROS<br>932 ACTROS 2/3<br>934 ACTROS 2/3<br>950 AXOR 2<br>952 AXOR 2     | King Pin Kit, Axle Steering<br>Knuckle<br>Lower Front Axle                | 3463300119<br>3465860133                  | <b>TM30536</b><br>   |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 | King Pin Kit, Axle Steering<br>Knuckle<br>Without King Pin                | 9423300219<br>6593300419<br>6593300319    | <b>TM30648</b><br>   |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 | King Pin Kit, Axle Steering<br>Knuckle<br>With King Pin                   | 9423300219S<br>6593300419S<br>6593300319S | <b>TM37011</b><br>  |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 | King Pin Kit, Axle Steering<br>Knuckle<br>Without King Pin                | 9423300319<br>6593300119<br>6593300019    | <b>TM31004</b><br> |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 | King Pin Kit, Axle Steering<br>Knuckle<br>With King Pin                   | 9423300319S<br>6593300119S<br>6593300019S | <b>TM37012</b><br> |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 | King Pin Kit, Axle Steering<br>Knuckle<br>Without King Pin<br>ø54xø82x25  | 9423300419                                | <b>TM30636</b><br> |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 | King Pin Kit, Axle Steering<br>Knuckle<br>With King Pin<br>ø54xø82x25/237 | 9423300419S                               | <b>TM37015</b><br> |












| TM No.  | Replaces Ref. No: | Description   | Model / Details  |
|---|-------------------|---|--|
| <b>TM37016</b><br>   | 9423300519        | King Pin Kit, Axle Steering<br>Knuckle<br>Without King Pin<br>ø54xø86x26                              | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 |
|   |                   | <b>TM37017</b><br>   | 9423300519S  |
| <b>TM31003</b><br>   | 3463300219        | King Pin Kit, Axle Steering<br>Knuckle<br>M24xø50/ø64x120   | 950 ACTROS<br>952 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>934 ACTROS 2/3<br>964 AROCS  |
|   |                   | <b>TM30647</b><br> | 6553300419   |
| <b>TM37020</b><br> | 6553300419S       | King Pin Kit, Axle Steering<br>Knuckle<br>With King Pin<br>ø50xø78x25/223                             | 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3     |
|   |                   | <b>TM30998</b><br> | 6553300419S1   |
| <b>TM31000</b><br> | 6553300519        | King Pin Kit, Axle Steering<br>Knuckle<br>Without King Pin<br>ø50xø80x25                              | 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3     |












| Model / Details   | Description   | Replaces Ref. No: | TM No.  |
|---|---|-------------------|---|
| 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3    | King Pin Kit, Axle Steering<br>Knuckle<br>With King Pin<br>M12x1,75/ø50/ø50,6/<br>ø51x223 | 6553300519S1      | <b>TM31001</b><br>   |
| 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3    | King Pin Kit, Axle Steering<br>Knuckle<br>Without King Pin<br>ø50xø78x25                  | 6553300619        | <b>TM30634</b><br>   |
| King Pin Kit, Axle Steering<br>Knuckle  | King Pin Kit, Axle Steering<br>Knuckle<br>With King Pin<br>ø50xø78x25/223                 | 6553300619S       | <b>TM37024</b><br>  |
| 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3    | King Pin Kit, Axle Steering<br>Knuckle<br>With King Pin<br>M12x1,75/ø50/ø50,6/<br>ø51x223 | 6553300619S1      | <b>TM30997</b><br> |
| 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3    | King Pin Kit, Axle Steering<br>Knuckle<br>Without King Pin<br>ø50xø80x25                  | 6553300719        | <b>TM30986</b><br> |
| 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3    | King Pin Kit, Axle Steering<br>Knuckle<br>With King Pin<br>ø50xø80x25/223                 | 6553300719S       | <b>TM37025</b><br> |
| 950 ACTROS<br>952 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>934 ACTROS 2/3<br>964 AROCS | King Pin Kit, Axle Steering<br>Knuckle<br>M24xø50/ø54X126                                 | 0003301319        | <b>TM30661</b><br> |










| TM No.  | Replaces Ref. No:          | Description  | Model / Details  |
|---|----------------------------|--|--|
| <b>TM31013</b><br>   | 6553300019S                | King Pin Kit, Axle Steering<br>Knuckle<br>With King Pin<br>ø50,3x223 | 650 MK<br>651 MK<br>652 MK<br>653 MK<br>654 MK<br>617 NG<br>619 NG   |
| <b>TM37028</b><br>   | 6553300119S<br>3573300019S | King Pin Kit, Axle Steering<br>Knuckle<br>With King Pin<br>ø50,3x223 | BM MODEL<br>650 MK<br>651 MK<br>652 MK<br>653 MK<br>654 MK<br>617 NG<br>619 NG   |
| <b>TM30635</b><br>  | 9423300019                 | King Pin Kit, Axle Steering<br>Knuckle<br>ø70                        | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3   |
| <b>TM37030</b><br> | 3463300019S                | King Pin Kit, Axle Steering<br>Knuckle<br>M24x1,5/ø50x109/119        | 950 ACTROS<br>952 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>934 ACTROS 2/3<br>964 AROCS  |
| <b>TM37037</b><br> | 3103300319<br>3105860133   | King Pin Kit, Axle Steering<br>Knuckle<br>ø26x154                    | 308 L 608 E, L 708 E<br>308 L/LO 608 D<br>308 LO 608 D, LO 708 D/E<br>309 L 406 DG, L 407 D<br>309 L 408 DG<br>309 L 408 G, L 409<br>309 L 408 G, L 409, L 410 |
| <b>TM33125</b><br> | 9703320406S                | King Pin Kit, Axle Steering<br>Knuckle<br>ø31,5/ø38x188              | 970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>970 ATEGO 2<br>972 ATEGO 2<br>975 ATEGO 2<br>976 ATEGO 2  |
| <b>TM37045</b><br> | 9723320106S                | King Pin Kit, Axle Steering<br>Knuckle<br>ø35/ø45x206                | 375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>375 ATEGO 2<br>970 ATEGO 2<br>972 ATEGO 2  |



| Model / Details  | Description  | Replaces Ref. No:          | TM No.  |
|--|--|----------------------------|---|
| 375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>970 ATEGO 2<br>972 ATEGO 2<br>974 ATEGO 2              | King Pin Kit, Axle Steering<br>Knuckle<br>ø38/ø39x223                | 9753320606S                | <b>TM37054</b><br>   |
| 970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>970 ATEGO 2<br>972 ATEGO 2<br>975 ATEGO 2<br>976 ATEGO 2            | King Pin Kit, Axle Steering<br>Knuckle<br>ø40                        | 0009807710                 | <b>TM32032</b><br>   |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 | King Pin Kit, Axle Steering<br>Knuckle<br>With King Pin<br>ø54       | 9423300119S<br>9423321606S | <b>TM37060</b><br>  |
| 375 AXOR 2<br>940 AXOR 2   | King Pin Kit, Axle Steering<br>Knuckle<br>ø54xø56x298                | 0003301219                 | <b>TM37063</b><br> |
| 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS   | King Pin Kit, Axle Steering<br>Knuckle<br>ø53,2xø86                  | 0003301619                 | <b>TM37064</b><br> |
| 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS   | King Pin Kit, Axle Steering<br>Knuckle<br>With King Pin<br>ø53,3xø86 | 0003301619S                | <b>TM37065</b><br> |
| 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS   | King Pin Kit, Axle Steering<br>Knuckle<br>With King Pin<br>ø53,6xø86 | 0003301619S1               | <b>TM37069</b><br> |










| TM No.  | Replaces Ref. No: | Description  | Model / Details  |
|---|-------------------|--|--|
| <b>TM37071</b><br>   | 0003301719        | King Pin Kit, Axle Steering<br>Knuckle<br>ø53,2xø86                                    | 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS |
| <b>TM37072</b><br>   | 0003301719S       | King Pin Kit, Axle Steering<br>Knuckle<br>With King Pin<br>ø53,3xø86                   | 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS |
| <b>TM37074</b><br>   | 0003301719S1      | King Pin Kit, Axle Steering<br>Knuckle<br>With King Pin<br>ø53,6xø86                   | 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS |
| <b>TM37075</b><br> | 3103300519        | King Pin Kit, Axle Steering<br>Knuckle<br>ø26x154                                      | -  |
| <b>TM37076</b><br> | 0009807810        | King Pin Kit, Axle Steering<br>Knuckle<br>ø53,3  | 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS |
| <b>TM37077</b><br> | 0009807810S       | King Pin Kit, Axle Steering<br>Knuckle<br>With King Pin<br>ø52xø52,3x206,78            | 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS |
| <b>TM37078</b><br> | 0009807810S1      | King Pin Kit, Axle Steering<br>Knuckle<br>With King Pin<br>ø52xø52,3x-<br>ø52,6x206,78 | 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS |



| Model / Details  | Description  | Replaces Ref. No:                      | TM No.  |
|--|--|--|---|
| 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS   | King Pin Kit, Axle Steering<br>Knuckle<br>ø52xø52,3x206,78                             | 0009807910                             | <b>TM37079</b><br>   |
| 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS   | King Pin Kit, Axle Steering<br>Knuckle<br>With King Pin<br>ø52xø52,3x-<br>ø52,6x206,78 | 0009807910S                            | <b>TM37080</b><br>   |
| 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS   | King Pin Kit, Axle Steering<br>Knuckle<br>With King Pin<br>ø53,3                       | 0009807910S1                           | <b>TM37081</b><br>   |
| BM MODEL<br>375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3         | Cover, Axle Steering<br>Knuckle<br>ø58   | 9433300956<br>9433300856               | <b>TM37082</b><br> |
| 958 ATEGO 2<br>344 L 1113/L 1114<br>344 L 1118<br>344 LK 1113/LK 1114<br>344 LK 1118<br>344 LPO/OF 1113/1114<br>345 L 1313 | Thrust Ring, Axle Steering<br>Knuckle<br>ø73,5xø100x16                                 | 3453340015<br>3603340115<br>3603340215 | <b>TM37083</b><br> |
| 749 AIRMASTER<br>749 STEERMASTER   | Repair Kit, Balance Arm<br>Axle  | 9463900250S                            | <b>TM37084</b><br> |
| 749 AIRMASTER<br>749 STEERMASTER   | Repair Kit, Balance Arm<br>Axle  | 9463900250S1                           | <b>TM37085</b><br> |










| TM No.  | Replaces Ref. No:                                    | Description  | Model / Details  |
|---|--|--|--|
| <b>TM37086</b><br>   | 3713280250   | Rubber Bushing, Balance Arm Axle<br>ø24xø57x102                | 375 AXOR 2   |
| <b>TM37087</b><br>   | 9463900050   | Rubber Bushing, Balance Arm Axle<br>ø31,5xø152x171             | -  |
| <b>TM27781</b><br>   | 9463900250   | Rubber Bushing, Balance Arm Axle                               | 749 AIRMASTER<br>749 STEERMASTER   |
| <b>TM37088</b><br> | 6393506101S  | Rubber Bushing, Balance Arm Axle                               | 639 VIANO<br>636 VIANO<br>639 VIANO<br>639 VITO  |
| <b>TM27782</b><br> | 9463900150   | Rubber Bushing, Balance Arm Axle<br>ø31,5xø160x92              | -  |
| <b>TM27654</b><br> | 9463280076   | Washer, Balance Arm Axle<br>ø178xø58,75x4,7                    | 934 ACTROS 2/3<br>970 ATEGO 2<br>749 AIRMASTER<br>749 STEERMASTER                                      |
| <b>TM26308</b><br> | 9423341501<br>9423341201<br>9423340701<br>9423340201 | Wheel Hub<br>Only Casting Body<br>ø22/ø130xø150/<br>ø383/183,5 | 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3 |





| Model / Details  | Description   | Replaces Ref. No:  | TM No.  |
|--|---|--|---|
| 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3     | Wheel Hub<br>With Alternative Bearing<br>ø22/ø70xø60/<br>ø383/183,5 | 9423341501S<br>9423341201S<br>9423340701S<br>9423340201S | <b>TM26331</b><br>   |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 | Wheel Hub<br>Only Casting Body<br>ø22/ø110xø150/<br>ø378/221,8      | 6243341001<br>6243340301<br>6243340201                   | <b>TM26371</b><br>   |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>950 AXOR 2<br>952 AXOR 2<br>953 AXOR 2             | Wheel Hub<br>Only Casting Body<br>ø22xø135/ø150/<br>ø176x263        | 9423560801<br>9423560001                                 | <b>TM26340</b><br>  |
| 343 T2/L<br>346 L 1924<br>346 L 1928<br>346 LK 1924<br>346 LK 1928<br>346 LS 1924<br>346 LS 1928           | Wheel Hub<br>Only Casting Body<br>ø22/ø180xø170/<br>ø375/219        | 3463562401<br>6253560101<br>3463561101<br>3463561001     | <b>TM26310</b><br> |
| 345 L 2225<br>619 NG<br>623 NG<br>659 SK   | Wheel Hub<br>Only Casting Body<br>ø22/ø140xø150/<br>ø378/235        | 3853561401<br>3853560601                                 | <b>TM37089</b><br> |
| 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3     | Wheel Hub<br>Only Casting Body<br>ø22/ø120xø150/<br>ø383/223,5      | 9423341401<br>9423340301                                 | <b>TM26324</b><br> |
| 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3     | Wheel Hub<br>With Bearing<br>ø22/ø55xø85/<br>ø383/223,5             | 9423341401S<br>9423340301S                               | <b>TM37090</b><br> |



| TM No.  | Replaces Ref. No:          | Description  | Model / Details  |
|---|----------------------------|--|--|
| <b>TM26364</b><br>   | 9763561101<br>9763560701   | Wheel Hub<br>Only Casting Body<br>ø20/ø130x150/<br>ø320x290          | 375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>375 ATEGO 2<br>970 ATEGO 2                                 |
| <b>TM26363</b><br>   | 9763561101S<br>9763560701S | Wheel Hub<br>With Alternative Bearing<br>ø20/ø100xø80/<br>ø320/290,2 | 375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>375 ATEGO 2<br>970 ATEGO 2<br>974 ATEGO 2                  |
| <b>TM26336</b><br>  | 9463560201                 | Wheel Hub<br>Only Casting Body<br>ø22/ø157x170/<br>ø377x297,5        | 375 ACTROS<br>950 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>934 ACTROS 2/3<br>963 ACTROS MP4<br>964 ACTROS MP4 |
| <b>TM26337</b><br> | 9463560201S                | Wheel Hub<br>With Alternative Bearing<br>ø22/ø100x110/<br>ø377x297,5 | 375 ACTROS<br>950 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>934 ACTROS 2/3<br>963 ACTROS MP4<br>964 ACTROS MP4 |
| <b>TM26334</b><br> | 9463561301<br>9463560101   | Wheel Hub<br>Only Casting Body<br>ø22/ø130x150/<br>ø382x187          | 934 ACTROS 2/3   |
| <b>TM26335</b><br> | 9463561301S<br>9463560101S | Wheel Hub<br>With Alternative Bearing<br>ø22/ø80x100/ø382x187        | 934 ACTROS 2/3   |
| <b>TM37091</b><br> | 0003560401                 | Wheel Hub<br>Only Casting Body<br>ø22,35/ø160x165/<br>ø369x243       | 671 CONECTO  |



| Model / Details  | Description   | Replaces Ref. No:  | TM No.  |
|--|---|--|---|
| 613 TOURISMO   | Wheel Hub<br>Only Casting Body<br>ø22/ø140xø150/<br>ø382/276          | 3563560001   | <b>TM37092</b><br>   |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 | Wheel Hub<br>Only Casting Body<br>ø22/ø170x180/<br>ø375x213           | 3463563101<br>3463563001                                 | <b>TM26351</b><br>   |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 | Wheel Hub<br>With Alternative Bearing<br>ø22/ø110x100/<br>ø375x213    | 3463563101S<br>3463563001S                               | <b>TM26352</b><br>   |
| 375 ACTROS<br>930 ACTROS 2/3<br>934 ACTROS 2/3<br>375 AXOR<br>374 AXOR 2<br>375 AXOR 2<br>940 AXOR 2       | Wheel Hub<br>Only Casting Body<br>ø22/ø160xø170/<br>ø380/313,1        | 9463560701   | <b>TM26338</b><br> |
| 375 ACTROS<br>930 ACTROS 2/3<br>934 ACTROS 2/3<br>375 AXOR<br>374 AXOR 2<br>375 AXOR 2<br>940 AXOR 2       | Wheel Hub<br>With Alternative Bearing<br>ø22/ø110xø100/<br>ø380/313,1 | 9463560701S  | <b>TM26339</b><br> |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 | Wheel Hub<br>Only Casting Body<br>ø22/ø157x170/<br>ø375x220           | 3463562901<br>9423561701<br>3463562801<br>9423561901     | <b>TM26322</b><br> |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 | Wheel Hub<br>With Alternative Bearing<br>ø22/ø110xø100/<br>ø375/220   | 3463562901S<br>9423561701S<br>3463562801S<br>9423561901S | <b>TM26333</b><br> |










| TM No.  | Replaces Ref. No:        | Description   | Model / Details   |
|---|--------------------------|---|---|
| <b>TM26403</b><br>   | 9493340801               | Wheel Hub   | 375 ACTROS  |
|   | 9493340501               | Only Casting Body<br>ø22/ø130x150/<br>ø384x191        | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3    |
| <b>TM26404</b><br>   | 9493340801S              | Wheel Hub   | 375 ACTROS  |
|   | 9493340501S              | With Alternative Bearing<br>ø22/ø70xø60/ø384/191      | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3    |
| <b>TM37093</b><br>   | 9463561901               | Wheel Hub   | 375 ACTROS  |
|   | 9463560901               | Only Casting Body<br>ø22/ø160x170/<br>ø380x198        | 950 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>934 ACTROS 2/3<br>375 AXOR<br>374 AXOR 2      |
| <b>TM37094</b><br> | 9463561901S              | Wheel Hub   | 375 ACTROS  |
|   | 9463560901S              | With Alternative Bearing<br>ø22/ø100x110/<br>ø380x198 | 950 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>934 ACTROS 2/3<br>375 AXOR<br>374 AXOR 2      |
| <b>TM26320</b><br> | 3463340601               | Wheel Hub   | 950 ACTROS  |
|   | 3463341101               | Only Casting Body<br>ø22/ø160x-<br>ø145/369x198,8     | 952 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>934 ACTROS 2/3<br>964 AROCS |
| <b>TM37095</b><br> | 9423561301               | Wheel Hub   | 375 ACTROS  |
|   |                          | Only Casting Body<br>ø22/ø157x170/<br>ø374,5263,3     | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3    |
| <b>TM26342</b><br> | 9423560901               | Wheel Hub   | 375 ACTROS  |
|   | 9423560101<br>9423561801 | Only Casting Body<br>ø22/ø157x170/<br>ø374,5x263      | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3    |



| Model / Details  | Description   | Replaces Ref. No:  | TM No.  |
|--|---|--|---|
| 749 AIRMASTER<br>749 STEERMASTER                                     | Wheel Hub<br>Only Casting Body  | 0003500535S1<br>9463560401S1<br>0003900525S1<br>0003502335S1 | <b>TM37096</b><br>   |
| 749 AIRMASTER<br>749 STEERMASTER                                     | Wheel Hub<br>With Alternative Bearing   | 0003500535S<br>0003502335S<br>0003900525S<br>9463560401S     | <b>TM26321</b><br>   |
| 749 AIRMASTER<br>749 STEERMASTER                                     | Wheel Hub<br>With Alternative Bearing,<br>Complete<br>ø22/ø140xø140/ø382/226<br>000 350 23 35 | 0003502335<br>0003500535<br>0003900525<br>9463560401         | <b>TM26369</b><br>  |
| 749 AIRMASTER<br>749 STEERMASTER                                     | Wheel Hub<br>With FAG Bearing, Com-<br>plete  | 0003502335<br>0003500535<br>0003900525<br>9463560401         | <b>TM26369</b><br> |
| 906 SPRINTER   | Wheel Hub<br>With Bearing<br>Repl. FAG: 805852<br>M12/x108,5xø152                             | 9063303420S<br>9063305020S<br>9069810406                     | <b>TM37097</b><br> |
| 638 V-CLASS<br>638 V-CLASS<br>638 V-CLASS<br>638 VITO<br>638 V-CLASS | Wheel Hub<br>Only Casting Body  | 6383560001   | <b>TM37098</b><br> |
| 638 V-CLASS<br>638 V-CLASS<br>638 V-CLASS<br>638 VITO<br>638 V-CLASS | Wheel Hub<br>Only Casting Body  | 6383340101   | <b>TM37099</b><br> |












| TM No.  | Replaces Ref. No:          | Description  | Model / Details  |
|---|----------------------------|--|--|
| <b>TM37100</b><br>   | 6393560401                 | Wheel Hub<br>Only Casting Body                               | 639 VIANO<br>636 VIANO<br>639 VIANO<br>639 VITO  |
| <b>TM26392</b><br>   | 9703500335<br>9703560301S  | Wheel Hub<br>With Bearing<br>ø18/ø130xø130/<br>ø286/102      | 967 ATEGO 3<br>970 ATEGO 2<br>970 ATEGO<br>972 ATEGO 2<br>972 ATEGO<br>975 ATEGO<br>975 ATEGO 2<br>976 ATEGO 2             |
| <b>TM26393</b><br>   | 9703560301<br>9703500335S  | Wheel Hub<br>Only Casting Body<br>ø18/ø130xø130/<br>ø286/102 | BM MODEL<br>967 ATEGO 3<br>970 ATEGO 2<br>970 ATEGO<br>972 ATEGO 2<br>972 ATEGO<br>975 ATEGO<br>975 ATEGO 2<br>976 ATEGO 2 |
| <b>TM26431</b><br> | 0139979447S<br>0169975647S | Repair Kit, Wheel Hub  | 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3                     |
| <b>TM37101</b><br> | 0159974947S                | Repair Kit, Wheel Hub  | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3                 |
| <b>TM26461</b><br> | 6243500135                 | Repair Kit, Wheel Hub  | 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3<br>375 AXOR<br>374 AXOR 2<br>375 AXOR 2               |
| <b>TM26460</b><br> | 6243500035                 | Repair Kit, Wheel Hub  | 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3<br>375 AXOR<br>374 AXOR 2<br>375 AXOR 2               |












| Model / Details  | Description           | Replaces Ref. No:                      | TM No.  |
|--|-----------------------|--|---|
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 | Repair Kit, Wheel Hub | 9403501135<br>9403500035               | <b>TM26465</b><br>   |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>950 AXOR 2<br>952 AXOR 2<br>953 AXOR 2             | Repair Kit, Wheel Hub | 9403500535                             | <b>TM30990</b><br>   |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 | Repair Kit, Wheel Hub | 9403501435<br>9403500335<br>9403501535 | <b>TM26474</b><br>  |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>950 AXOR 2<br>952 AXOR 2<br>953 AXOR 2             | Repair Kit, Wheel Hub | 9403502035<br>9403500935               | <b>TM26459</b><br> |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 | Repair Kit, Wheel Hub | 9403501235<br>9403500135               | <b>TM26437</b><br> |
| 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3     | Repair Kit, Wheel Hub | 9403501735<br>9403500635               | <b>TM26236</b><br> |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>950 AXOR 2<br>952 AXOR 2<br>953 AXOR 2             | Repair Kit, Wheel Hub | 9403501935<br>9403500835               | <b>TM30995</b><br> |






| TM No.  | Replaces Ref. No: | Description                   | Model / Details |
|---|-------------------|-------------------------------|-----------------|
| <b>TM30989</b><br>   | 6593500035        | Repair Kit, Wheel Hub         | 950 AXOR 2      |
|   | 6593500135        |                               | 343 T2/L        |
|   |                   |                               | 346 L 1924      |
|   |                   |                               | 346 L 1928      |
|   |                   |                               | 346 LK 1924     |
|   |                   |                               | 346 LK 1928     |
|   |                   |                               | 346 LS 1924     |
| <b>TM26405</b><br>   | 9403501835        | Repair Kit, Wheel Hub         | 375 ACTROS      |
|   | 9403500735        |                               | 950 ACTROS      |
|   |                   |                               | 952 ACTROS      |
|   |                   |                               | 953 ACTROS      |
|   |                   |                               | 954 ACTROS      |
|   |                   |                               | 930 ACTROS 2/3  |
|   |                   |                               | 932 ACTROS 2/3  |
| <b>TM30460</b><br>   | 9403501035        | Repair Kit, Wheel Hub         | 375 ACTROS      |
|   |                   |                               | 950 ACTROS      |
|   |                   |                               | 954 ACTROS      |
|   |                   |                               | 930 ACTROS 2/3  |
|   |                   |                               | 934 ACTROS 2/3  |
|   |                   |                               | 963 ACTROS MP4  |
|   |                   |                               | 964 ACTROS MP4  |
| <b>TM30462</b><br> | 9423503935        | Repair Kit, Wheel Hub         | 375 ACTROS      |
|   |                   |                               | 950 ACTROS      |
|   |                   |                               | 954 ACTROS      |
|   |                   |                               | 930 ACTROS 2/3  |
|   |                   |                               | 934 ACTROS 2/3  |
|   |                   |                               | 963 ACTROS MP4  |
|   |                   |                               | 964 ACTROS MP4  |
| <b>TM30666</b><br> | 9423301125        | Repair Kit, Wheel Hub         | 375 ACTROS      |
|   | 9423301025        |                               | 950 ACTROS      |
|   |                   |                               | 952 ACTROS      |
|   |                   |                               | 953 ACTROS      |
|   |                   |                               | 954 ACTROS      |
|   |                   |                               | 930 ACTROS 2/3  |
|   |                   |                               | 932 ACTROS 2/3  |
| <b>TM37102</b><br> | 6243560080S1      | Repair Kit, Wheel Hub         | 613 TOURISMO    |
|   |                   |                               |                 |
| <b>TM37103</b><br> | 0003502935        | Repair Kit, Wheel Hub<br>ø196 | 963 ACTROS MP4  |
|   |                   |                               | 964 ANTOS       |
|   |                   |                               | 964 AROCS       |
|   |                   |                               | 942 AXOR 2      |
|   |                   |                               | 943 AXOR 2      |



| Model / Details  | Description   | Replaces Ref. No:                                    | TM No.         |
|--|---|--|----------------|
| 375 ATEGO<br>970 ATEGO<br>375 ATEGO 2<br>970 ATEGO 2<br>974 ATEGO 2<br>976 ATEGO 2<br>967 ATEGO 3                            | Repair Kit, Wheel Hub<br>ø200                         | 0003502735   | <b>TM26473</b> |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3 | Repair Kit, Wheel Hub<br>ø120                         | 9433340301   | <b>TM26451</b> |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>934 ACTROS 2/3<br>950 AXOR 2     | Repair Kit, Wheel Hub                                 | 9423503835   | <b>TM26464</b> |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>375 AXOR 2                       | Seal Ring, Wheel Hub<br>ø145xø175/ø205x18/20<br>/ FPM | 0209970547   | <b>TM26192</b> |
| 344 LA 1113<br>344 LAK 1113<br>344 LAS 1113<br>352 LA 1313<br>352 LAKO 1313<br>353 T2/L<br>358 LA 1113 B                     | Seal Ring, Wheel Hub<br>ø125xø150x15 / NBR            | 0069971246<br>0029973347                             | <b>TM37105</b> |
| 343 T2/L<br>346 L 1924<br>346 L 1928<br>346 LK 1924<br>346 LK 1928<br>346 LS 1924<br>346 LS 1928                             | Seal Ring, Wheel Hub<br>ø120xø150x15 / NBR            | 0049971747<br>0029972047<br>0049971847<br>0109977347 | <b>TM26118</b> |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>375 AXOR 2                       | Seal Ring, Wheel Hub<br>ø145xø175x17/21 /<br>FPM      | 0209973947   | <b>TM30577</b> |





| TM No.  | Replaces Ref. No:                      | Description  | Model / Details  |
|---|--|--|--|
| <b>TM26206</b><br>   | 0219976947                             | Seal Ring, Wheel Hub<br>ø120xø150x14,3/20 /<br>NBR | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>375 AXOR 2         |
|   |  |  |  |
| <b>TM37106</b><br>   | 0199974847                             | Seal Ring, Wheel Hub<br>ø120xø150x15 / NBR         | 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3         |
|   | 0249976147<br>0209975847               |  |  |
| <b>TM26202</b><br>   | 0229975247                             | Seal Ring, Wheel Hub<br>ø125xø150x14 / FPM         | 963 ACTROS MP4<br>964 ANTOS<br>964 AROCS<br>375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO                   |
|   | 0239975947                             |  |  |
| <b>TM37104</b><br> | 0139975947                             | Seal Ring, Wheel Hub<br>ø145xø175x13 / FPM         | 343 T2/L<br>346 L 1924<br>346 L 1928<br>346 LK 1924<br>346 LK 1928<br>346 LS 1924<br>346 LS 1928               |
|   | 0139979447<br>0139979347<br>0139976547 |  |  |
| <b>TM26114</b><br> | 0119970046                             | Seal Ring, Wheel Hub<br>ø145xø175x14 / NBR         | 343 T2/L<br>346 L 1924<br>346 L 1928<br>346 LK 1924<br>346 LK 1928<br>346 LS 1924<br>346 LS 1928               |
|   | 0139970547<br>0039976647<br>3509977846 |  |  |
| <b>TM26129</b><br> | 0119970146                             | Seal Ring, Wheel Hub<br>ø145xø175x13 / NBR         | 343 T2/L<br>346 L 1924<br>346 L 1928<br>346 LK 1924<br>346 LK 1928<br>346 LS 1924<br>346 LS 1928               |
|   | 0119971246                             |  |  |
| <b>TM30582</b><br> | 0219978547                             | Seal Ring, Wheel Hub<br>ø85xø155x12/33 / FPM       | 375 ACTROS<br>950 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>934 ACTROS 2/3<br>963 ACTROS MP4<br>964 ACTROS MP4 |
|   | 0239977947                             |  |  |










| Model / Details  | Description                                  | Replaces Ref. No:                                    | TM No.  |
|--|--|--|---|
| 950 AXOR 2<br>343 T2/L<br>343 T2/LN1<br>346 L 1924<br>346 LK 1924<br>346 LK 1928<br>346 LS 1924                                | Seal Ring, Wheel Hub<br>ø100xø130x13 / NBR   | 0099976747<br>0109979046<br>0119972646<br>0119973646 | <b>TM26194</b><br>   |
| 398 LO 814<br>673 LK/LN2<br>674 LK/LN2<br>676 LK/LN2<br>688 1114<br>688 709<br>688 912   | Seal Ring, Wheel Hub<br>ø95xø115x13 / NBR    | 0109972447<br>0109975447<br>0109978747               | <b>TM30593</b><br>   |
| 343 T2/LN1<br>346 LA 1924<br>346 LAK 1924<br>346 LAS 1924  | Seal Ring, Wheel Hub<br>ø165xø190x13 / NBR   | 3049970447   | <b>TM37107</b><br>   |
| 375 ACTROS<br>950 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>934 ACTROS 2/3<br>375 AXOR<br>374 AXOR 2                           | Seal Ring, Wheel Hub<br>ø145xø175x8 / NBR    | 0139973646<br>0149970546                             | <b>TM30585</b><br> |
| 344 L 1113/L 1114<br>344 L 1118<br>344 LK 1113/LK 1114<br>344 LK 1118<br>344 LPO/OF 1113/1114<br>345 L 1313<br>345 L 1313,1314 | Seal Ring, Wheel Hub<br>ø120xø145x15 / NBR   | 0109978147<br>0069970546<br>3459978346<br>0109978547 | <b>TM26434</b><br> |
| 375 ATEGO<br>970 ATEGO<br>975 ATEGO<br>958 ATEGO 2<br>970 ATEGO 2<br>975 ATEGO 2<br>976 ATEGO 2                                | Seal Ring, Wheel Hub<br>ø125xø150x15 / FPM   | 0169977747<br>0159975647                             | <b>TM26173</b><br> |
| 352 LF 1313<br>352 OF SERIES   | Seal Ring, Wheel Hub<br>ø125xø152,4x15 / NBR | 0019973847<br>0029974046                             | <b>TM37108</b><br> |







| TM No.  | Replaces Ref. No: | Description  | Model / Details |
|---|-------------------|--|-----------------|
| <b>TM26215</b><br>   | 0189973147        | Seal Ring, Wheel Hub<br>ø55xø75x8 / NBR                    | 408 UNIMOG      |
|   | 0199973646        |  | 418 UNIMOG      |
|   | 0199973647        |  | 424 UNIMOG      |
|   | 0199973747        |  | 427 UNIMOG      |
|   |                   |  | 435 UNIMOG      |
|   |                   |  | 436 UNIMOG      |
|   |                   |  | 437 UNIMOG      |
| <b>TM26214</b><br>   | 0249975547        | Seal Ring, Wheel Hub<br>ø72xø90x12 / NBR                   | 671 CONECTO     |
|   |                   |  |                 |
| <b>TM26058</b><br>   | 0049971347        | Seal Ring, Wheel Hub<br>ø75xø100x10 / NBR                  | 405 UNIMOG      |
|   |                   |  | 408 UNIMOG      |
|   |                   |  | 418 UNIMOG      |
|   |                   |  | 424 UNIMOG      |
|   |                   |  | 427 UNIMOG      |
|   |                   |  | 435 UNIMOG      |
|   |                   | 436 UNIMOG   |                 |
| <b>TM26054</b><br> | 0029976547        | Seal Ring, Wheel Hub<br>ø70xø81,5x6 / NBR                  | 375 ACTROS      |
|   | 0029978847        |  | 950 ACTROS      |
|   |                   |  | 952 ACTROS      |
|   |                   |  | 953 ACTROS      |
|   |                   |  | 954 ACTROS      |
|   |                   |  | 930 ACTROS 2/3  |
|   |                   |  | 932 ACTROS 2/3  |
|   |                   |  |                 |
| <b>TM37109</b><br> | 0249974847        | Seal Ring, Wheel Hub<br>ø120xø150x14,30x20                 | 375 ACTROS      |
|   |                   |  |                 |
| <b>TM26200</b><br> | 0159974947        | Seal Ring, Wheel Hub<br>ø142,5xø175/<br>ø205x11/13,5 / NBR | 950 ACTROS      |
|   |                   |  | 952 ACTROS      |
|   |                   |  | 953 ACTROS      |
|   |                   |  | 954 ACTROS      |
|   |                   |  | 930 ACTROS 2/3  |
|   |                   |  | 932 ACTROS 2/3  |
|   |                   |  | 933 ACTROS 2/3  |
|   |                   |  |                 |
| <b>TM26186</b><br> | 0119971746        | Seal Ring, Wheel Hub<br>ø160xø180x10 / NBR                 | 621 NG          |
|   | 0159975847        |  | 623 NG          |
|   |                   |  | 624 NG          |
|   |                   |  | 625 NG          |
|   |                   |  | 646 NG          |
|   |                   |  | 648 NG          |
|   |                   | 649 NG   |                 |












| Model / Details  | Description  | Replaces Ref. No:                         | TM No.         |
|--|--|---|----------------|
| 695 LS 1634EL<br>695 LS 1634EL 1635 S<br>696 L 1938<br>696 L 2638<br>696 LK 2638<br>696 LS 1938<br>696 LS 2638 | Seal Ring, Wheel Hub<br>ø175xø143,5x1                              | 0159979045                                | <b>TM30611</b> |
| 695 LS 1634EL<br>695 LS 1634EL 1635 S<br>696 L 1938<br>696 L 2638<br>696 LK 2638<br>696 LS 1938<br>696 LS 2638 | Seal Ring, Wheel Hub<br>ø145xø175x16                               | 0139978946                                | <b>TM30586</b> |
| 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3         | Seal Ring, Wheel Hub<br>ø145xø175x15                               | 0139973546                                | <b>TM30584</b> |
| 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3         | Seal Ring, Wheel Hub<br>010.207 With Dust Lip<br>ø120xø150x15/20,2 | 0139977346                                | <b>TM37110</b> |
| 934 ACTROS 2/3<br>963 ACTROS MP4<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>970 ATEGO 2<br>972 ATEGO 2          | Seal Ring, Wheel Hub<br>ø86,5xø142,3x12,8                          | 9709970346                                | <b>TM37111</b> |
| 970 ATEGO 2<br>970 ATEGO<br>972 ATEGO 2<br>972 ATEGO<br>975 ATEGO<br>975 ATEGO 2<br>976 ATEGO 2                | Seal Ring, Wheel Hub<br>ø75xø110xø134/10x15<br>/ Z=80              | 9709970446<br>9709970546<br>9703300261    | <b>TM26204</b> |
| 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3         | Thrust Ring, Wheel Hub<br>No Hardened<br>ø115xø145x32              | 3463561415S<br>3463560315S<br>9423560415S | <b>TM37112</b> |





| TM No.  | Replaces Ref. No: | Description                              | Model / Details          |
|---|-------------------|--|--------------------------|
| <b>TM26072</b><br>   | 3463560315        | Thrust Ring, Wheel Hub                   | 375 ACTROS               |
|   | 3463561415        | Surface Hardened                         | 950 ACTROS               |
|   | 9423560415        | ø115xø145x32                             | 952 ACTROS               |
|   |                   |  | 953 ACTROS               |
|   |                   |  | 954 ACTROS               |
|   |                   |  | 930 ACTROS 2/3           |
|   |                   |  | 932 ACTROS 2/3           |
| <b>TM37113</b><br>   | 3553560915S       | Thrust Ring, Wheel Hub                   | 375 ACTROS               |
|   | 3553561215S       | No Hardened                              | 950 ACTROS               |
|   |                   | ø110xø145x32                             | 952 ACTROS               |
|   |                   |  | 953 ACTROS               |
|   |                   |  | 954 ACTROS               |
|   |                   |  | 930 ACTROS 2/3           |
|   |                   |  | 932 ACTROS 2/3           |
| <b>TM26301</b><br>   | 3553560915        | Thrust Ring, Wheel Hub                   | 375 ACTROS               |
|   | 3553561215        | Surface Hardened                         | 950 ACTROS               |
|   |                   | ø110xø145x32                             | 952 ACTROS               |
|   |                   |  | 953 ACTROS               |
|   |                   |  | 954 ACTROS               |
|   |                   |  | 930 ACTROS 2/3           |
|   |                   |  | 932 ACTROS 2/3           |
| <b>TM30689</b><br> | 3853560015        | Thrust Ring, Wheel Hub<br>ø105xø125x18   | 345 L 1513,1514,1516     |
|   |                   |  | 345 L 1516,L 1517,L 1518 |
|   |                   |  | 345 L 1518 ,LS 1518      |
|   |                   |  | 345 L 1519               |
|   |                   |  | 345 L 1519,1520          |
|   |                   |  | 345 L 2225               |
|   |                   |  | 345 LK 1513,1514,1516    |
|   |                   |  |                          |
| <b>TM26285</b><br> | 9463560015        | Thrust Ring, Wheel Hub<br>ø119xø145x26   | 375 ACTROS               |
|   |                   |  | 950 ACTROS               |
|   |                   |  | 954 ACTROS               |
|   |                   |  | 930 ACTROS 2/3           |
|   |                   |  | 934 ACTROS 2/3           |
|   |                   |  | 963 ACTROS MP4           |
|   |                   |  | 964 ACTROS MP4           |
|   |                   |  |                          |
| <b>TM26090</b><br> | 3603560415        | Thrust Ring, Wheel Hub                   | 375 AXOR 2               |
|   |                   |  | 338 LPS 1418             |
|   |                   |  | 338 LS 1418              |
|   |                   |  | 344 L 1113/L 1114        |
|   |                   |  | 344 L 1118               |
|   |                   |  | 344 LK 1113/LK 1114      |
|   |                   |  | 344 LK 1118              |
|   |                   |  |                          |
| <b>TM26397</b><br> | 6753560215        | Thrust Ring, Wheel Hub<br>ø101xø120x21,3 | 950 ACTROS               |
|   |                   |  | 930 ACTROS 2/3           |
|   |                   |  | 934 ACTROS 2/3           |
|   |                   |  | 972 ATEGO                |
|   |                   |  | 976 ATEGO                |
|   |                   |  | 970 ATEGO 2              |
|   |                   |  | 972 ATEGO 2              |



| Model / Details   | Description  | Replaces Ref. No:                                    | TM No.         |
|---|--|--|----------------|
| 346 L 1924<br>346 L 1928<br>346 LK 1924<br>346 LK 1928<br>346 LS 1924<br>346 LS 1928<br>349 L 1621  | Thrust Ring, Wheel Hub<br>No Hardened<br>ø70xø120x17,    | 3893340215   | <b>TM26282</b> |
| 963 ACTROS MP4<br>964 ANTOS<br>964 AROCS<br>375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO  | Thrust Ring, Wheel Hub<br>ø106xø125x21                   | 6523560015   | <b>TM30688</b> |
| 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3  | Bearing, Wheel Hub<br>Repl. FAG: 33022<br>ø110xø170x47   | 0049810705<br>0049810905<br>0059812105<br>0089813505 | <b>TM26047</b> |
| 950 ACTROS<br>952 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>934 ACTROS 2/3<br>950 AXOR 2                                      | Bearing, Wheel Hub<br>Repl. FAG: 30314A<br>ø70xø150x38   | 0019817505<br>0019817705<br>000720030314             | <b>TM31899</b> |
| 338 L 1418<br>338 LK 1418<br>338 LP 1418<br>338 LPS 1418<br>338 LS 1418   | Bearing, Wheel Hub<br>Repl. FAG: 32217A<br>ø85xø150x38,5 | 0009812205<br>3279812205<br>3279810405<br>0029811805 | <b>TM26329</b> |
| 343 T2/LN1<br>317 O 317   | Bearing, Wheel Hub<br>Repl. FAG: 32219A<br>ø95xø170x45,5 | 0023432219<br>0009812105                             | <b>TM26557</b> |
| 345 L 1513,1514,1516<br>345 L 1516,L 1517,L 1518<br>345 L 1518 ,LS 1518<br>345 L 1519<br>345 L 1519,1520<br>345 L 2225<br>345 LK 1513,1514,1516 | Bearing, Wheel Hub<br>Repl. FAG: 33117<br>ø85xø140x41    | 0019806702<br>0059818305<br>0059818605<br>0059819905 | <b>TM26328</b> |





| TM No.  | Replaces Ref. No: | Description  | Model / Details     |
|---|-------------------|--|---------------------|
| <b>TM30720</b><br>   | 0019816405        | Bearing, Wheel Hub<br>Repl. FAG: 32020X<br>ø100xø150x32  | 979 ACCELO          |
|   | 0049817405        |  | 375 ACTROS          |
|   | 0069810405        |  | 950 ACTROS          |
|   | 0019817205        |  | 952 ACTROS          |
|   |                   |  | 953 ACTROS          |
|   |                   |  | 954 ACTROS          |
|   |                   |  | 930 ACTROS 2/3      |
| <b>TM25192</b><br>   | 0049819805        | Bearing, Wheel Hub<br>Repl. FAG: 32314A<br>ø70xø150x54   | 950 ACTROS          |
|   | 0129813205        |  | 952 ACTROS          |
|   | 0049819905        |  | 953 ACTROS          |
|   | 0059810005        |  | 954 ACTROS          |
|   |                   |  | 930 ACTROS 2/3      |
|   |                   |  | 932 ACTROS 2/3      |
|   |                   |  | 933 ACTROS 2/3      |
| <b>TM26416</b><br>   | 0039812505        | Bearing, Wheel Hub<br>Repl. FAG: 32021X<br>ø105xø160x35  | 950 ACTROS          |
|   | 0039812705        |  | 952 ACTROS          |
|   |                   |  | 954 ACTROS          |
|   |                   |  | 930 ACTROS 2/3      |
|   |                   |  | 932 ACTROS 2/3      |
|   |                   |  | 934 ACTROS 2/3      |
|   |                   |  | 950 AXOR 2          |
| <b>TM25193</b><br> | 0069810805        | Bearing, Wheel Hub<br>Repl. FAG: 32311A<br>ø55xø120x45,5 | 375 ACTROS          |
|   | 0069816905        |  | 950 ACTROS          |
|   | 0069817405        |  | 952 ACTROS          |
|   | 0109819305        |  | 953 ACTROS          |
|   |                   |  | 954 ACTROS          |
|   |                   |  | 930 ACTROS 2/3      |
|   |                   |  | 932 ACTROS 2/3      |
| <b>TM25216</b><br> | 0069818705        | Bearing, Wheel Hub<br>Repl. FAG: 33017<br>ø85xø130x36    | 972 ATEGO           |
|   | 0069819705        |  | 970 ATEGO 2         |
|   | 0079814905        |  | 972 ATEGO 2         |
|   |                   |  | 976 ATEGO 2         |
|   |                   |  | 967 ATEGO 3         |
|   |                   |  | 674 LK/LN2          |
|   |                   |  | 675 LK/LN2          |
| <b>TM26325</b><br> | 0049812405        | Bearing, Wheel Hub<br>Repl. FAG: 528983B<br>ø70xø130x57  | 343 T2/L            |
|   | 0049812305        |  | 343 T2/LN1          |
|   | 0049813905        |  | 346 L 1924          |
|   |                   |  | 346 LK 1924         |
|   |                   |  | 346 LK 1928         |
|   |                   |  | 346 LS 1924         |
|   |                   |  | 346 LS 1928         |
| <b>TM30935</b><br> | 0039815205        | Bearing, Wheel Hub<br>Repl. FAG: 33214<br>ø70xø125x41    | 958 ATEGO 2         |
|   | 0039815605        |  | 360 L 1513          |
|   | 0069815205        |  | 360 L 1817,1819/6X4 |
|   | 0039818505        |  | 360 L 1819/6X4      |
|   |                   |  | 360 LK 1513         |
|   |                   |  | 360 LKO 1513        |
|   |                   |  | 360 LS 1513         |



| Model / Details  | Description  | Replaces Ref. No:                                      | TM No.         |
|--|--|--|----------------|
| 958 ATEGO 2<br>360 L 1513<br>360 L 1817,1819/6X4<br>360 L 1819/6X4<br>360 LK 1513<br>360 LKO 1513<br>360 LS 1513                                     | earing, Wheel Hub<br>Repl. FAG: 32214A<br>ø70xø125x33,25 | 0049817305   | <b>TM37114</b> |
| 673 LK/LN2<br>674 LK/LN2<br>675 LK/LN2<br>676 LK/LN2<br>678 LK/LN2<br>403 UNIMOG<br>405 UNIMOG   | Bearing, Wheel Hub<br>Repl. FAG: 32016X<br>ø80xø125x29   | 000720032016<br>0079819005<br>0079819305<br>0079819405 | <b>TM30772</b> |
| 343 T2/L<br>346 L 1924<br>346 L 1928<br>346 LK 1924<br>346 LK 1928<br>346 LS 1924<br>346 LS 1928   | Bearing, Wheel Hub<br>Repl. FAG: 30220A<br>ø100xø180x37  | 0049814905<br>0049812105<br>0079810005<br>000720030220 | <b>TM25209</b> |
| 964 AROCS<br>950 AXOR 2<br>952 AXOR 2<br>349 L 1621<br>349 LK 1621<br>349 LS 1621<br>349 LS 1624   | Bearing, Wheel Hub<br>Repl. FAG: 32019XA<br>ø95xø145x32  | 0019802602<br>0029815405<br>0039815105<br>0069814705   | <b>TM26358</b> |
| 318 LP<br>673 LK/LN2<br>674 LK/LN2<br>675 LK/LN2<br>676 LK/LN2<br>677 LK/LN2<br>678 LK/LN2   | Bearing, Wheel Hub<br>Repl. FAG: 33211<br>ø55xø100x35    | 0049816405<br>0049816505<br>0049816705<br>0069816005   | <b>TM25221</b> |
| 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3   | Bearing, Wheel Hub<br>Repl. FAG: 32210A<br>ø50xø90x24,75 | 0009813605<br>0019818905<br>0029811905<br>0029812205   | <b>TM32789</b> |
| 341 LA 1114<br>345 L<br>2213,2214,2216,2217<br>345 L 2216,2217<br>345 LA 1313<br>345 LA 1313,1314,1317<br>345 LAK 1313,1314,1317<br>345 LB 2213,2214 | Bearing, Wheel Hub<br>Repl. FAG: 33011<br>ø55xø90x27     | 0039814305<br>0029819305<br>0059814405<br>0079815705   | <b>TM25210</b> |





| TM No.  | Replaces Ref. No: | Description          | Model / Details |
|---|-------------------|----------------------|-----------------|
| <b>TM32633</b><br>   | 0159817705        | Bearing, Wheel Hub   | 950 ACTROS      |
|   | 0029811305        | Repl. FAG: 32011X    | 954 ACTROS      |
|   | 0029816605        | ø55xø90x23           | 930 ACTROS 2/3  |
|   | 0069815605        |                      | 934 ACTROS 2/3  |
|   |                   |                      | 964 ACTROS MP4  |
|   |                   |                      | 964 ANTOS       |
|   |                   |                      | 964 AROCS       |
| <b>TM32708</b><br>   | 0039811105        | Bearing, Wheel Hub   | 375 ACTROS      |
|   | 0039811605        | Repl. FAG: 33109     | 950 ACTROS      |
|   | 0039819605        | ø45xø80x26           | 952 ACTROS      |
|   | 0069815705        |                      | 953 ACTROS      |
|   |                   |                      | 954 ACTROS      |
|   |                   |                      | 930 ACTROS 2/3  |
|   |                   |                      | 932 ACTROS 2/3  |
| <b>TM33219</b><br>   | 0039813905        | Bearing, Wheel Hub   | 375 ACTROS      |
|   | 0039817205        | Repl. FAG: 33208     | 950 ACTROS      |
|   | 0049816805        | ø40xø80x32           | 952 ACTROS      |
|   | 0069816205        |                      | 953 ACTROS      |
|   |                   |                      | 954 ACTROS      |
|   |                   |                      | 930 ACTROS 2/3  |
|   |                   |                      | 932 ACTROS 2/3  |
| <b>TM25208</b><br> | 0009819505        | Bearing, Wheel Hub   | 970 ATEGO       |
|   | 0019818305        | Repl. FAG: 32306A    | 972 ATEGO       |
|   | 0019818705        | ø30xø72x29           | 975 ATEGO       |
|   | 0069816605        |                      | 970 ATEGO 2     |
|   |                   |                      | 972 ATEGO 2     |
|   |                   |                      | 975 ATEGO 2     |
|   |                   |                      | 976 ATEGO 2     |
| <b>TM26056</b><br> | 0039811005        | Bearing, Wheel Hub   | 343 T2/L        |
|   | 0039811505        | Repl. FAG: 33205     | 346 L 1924      |
|   | 0039819505        | ø25xø52x22           | 346 LK 1924     |
|   | 0069815805        |                      | 346 LS 1924     |
|   |                   |                      | 611 T1/TN       |
|   |                   |                      | 673 LK/LN2      |
|   |                   |                      | 688 709         |
| <b>TM26545</b><br> | 0059810705        | Bearing, Wheel Hub   | 375 ACTROS      |
|   | 0149810605        | Repl. FAG: 33207     | 950 ACTROS      |
|   | 0059810605        | ø35xø72x28           | 952 ACTROS      |
|   |                   |                      | 953 ACTROS      |
|   |                   |                      | 954 ACTROS      |
|   |                   |                      | 930 ACTROS 2/3  |
|   |                   |                      | 932 ACTROS 2/3  |
| <b>TM26355</b><br> | 0169812805        | Bearing, Wheel Hub   | 970 ATEGO       |
|   | 0149815105        | Repl. FAG: 805003CA. | 970 ATEGO 2     |
|   | 0149819305        | H195                 |                 |
|   | 0149819905        | ø82xø140x115         |                 |
|   |                   |                      |                 |












| Model / Details   | Description   | Replaces Ref. No:                                      | TM No.  |
|---|---|--|---|
| 375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>375 ATEGO 2<br>970 ATEGO 2   | Bearing, Wheel Hub<br>Repl. FAG: 32018XA<br>ø90xø140x32   | 000720032018<br>0059815605<br>0049814305<br>0069810005 | <b>TM25198</b><br>   |
| 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3  | Bearing, Wheel Hub<br>Repl. FAG: 33115<br>ø75xø125x37     | 0039813205   | <b>TM30353</b><br>   |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3                                      | Bearing, Wheel Hub<br>Repl. FAG: 33113<br>ø65xø110x34     | 0039814105<br>0009814518<br>0069818805<br>0039818205   | <b>TM25222</b><br>   |
| 972 ATEGO<br>976 ATEGO<br>958 ATEGO 2<br>970 ATEGO 2<br>972 ATEGO 2<br>976 ATEGO 2<br>341 LA 1114   | Bearing, Wheel Hub<br>Repl. FAG: 33209<br>ø45xø85x32      | 0039815305<br>0039815705<br>0049817205<br>0059814105   | <b>TM25223</b><br> |
| 958 ATEGO 2<br>341 LA 1114<br>345 L<br>2213,2214,2216,2217<br>345 L 2216,2217<br>345 LA 1313<br>345 LA 1313,1314,1317<br>345 LAK 1313,1314,1317 | Bearing, Wheel Hub<br>Repl. FAG: 33210<br>ø50xø90x32      | 0029817905<br>0039818305<br>0049814205<br>0059814005   | <b>TM26218</b><br> |
| 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3  | Bearing, Wheel Hub<br>Repl. FAG: 33217<br>85xø150x49      | 0119810805<br>0079817005                               | <b>TM26315</b><br> |
| 328 T2/L<br>341 L 1112<br>341 L 1114<br>341 L 914<br>341 LA 1112<br>341 LA 1114<br>341 LK 1114  | Bearing, Wheel Hub<br>Repl. FAG: 32216A<br>ø80xø140x35,25 | 0069810605<br>0009819405<br>0009812401<br>0009810305   | <b>TM24889</b><br> |





| TM No.  | Replaces Ref. No: | Description                      | Model / Details   |
|---|-------------------|----------------------------------|---|
| <b>TM25567</b><br>   | 0029818605        | Bearing, Wheel Hub               | 375 AXOR 2  |
|   | 0019802702        | Repl. FAG: 33215                 | 338 LPS 1418  |
|   | 0029818905        | ø75xø130x41                      | 338 LS 1418   |
|   |                   |                                  | 344 L 1113/L 1114<br>344 L 1118<br>344 LK 1113/LK 1114<br>344 LK 1118       |
| <b>TM24898</b><br>   | 0009809602        | Bearing, Wheel Hub               | 950 ACTROS  |
|   | 0029819005        | Repl. FAG: 33019                 | 952 ACTROS  |
|   | 0039818605        | ø95xø145x42                      | 954 ACTROS  |
|   | 0029818405        |                                  | 930 ACTROS 2/3<br>932 ACTROS 2/3<br>934 ACTROS 2/3<br>964 AROCS             |
| <b>TM24657</b><br>   | 0019806602        | Bearing, Wheel Hub               | 950 ACTROS  |
|   | 0059818405        | Repl. FAG: 33020                 | 930 ACTROS 2/3  |
|   | 0059818505        | ø100xø150x42                     | 934 ACTROS 2/3  |
|   | 0069810105        |                                  | 963 ACTROS MP4<br>964 ANTOS<br>964 AROCS<br>375 ATEGO                       |
| <b>TM24881</b><br> | 0019813705        | Bearing, Wheel Hub               | 341 LA 1112   |
|   | 0069814205        | Repl. FAG: 30309A                | 341 LA 1114   |
|   | 0099810305        | ø45xø100x27,25                   | 344 LA 1113   |
|   | 000720030309      |                                  | 344 LAK 1113<br>344 LAS 1113<br>345 L<br>2213,2214,2216,2217<br>345 LA 1313 |
| <b>TM25199</b><br> | 0019800902        | Bearing, Wheel Hub               | 375 ATEGO   |
|   | 0039813705        | Repl. FAG: 201086                | 970 ATEGO   |
|   | 0039817405        | ø65xø120x41                      | 972 ATEGO   |
|   | 0069816305        |                                  | 975 ATEGO<br>958 ATEGO 2<br>970 ATEGO 2<br>972 ATEGO 2                      |
| <b>TM37115</b><br> | 0720032013        | Bearing, Wheel Hub               | -   |
|   |                   | Repl. FAG: 32013X<br>ø65xø100x23 |   |
| <b>TM26327</b><br> | 0179814905        | Bearing, Wheel Hub               | 950 ACTROS  |
|   | 0129814105        | Repl. FAG: 33116                 | 930 ACTROS 2/3  |
|   | 0129814005        | ø80xø130x37                      | 934 ACTROS 2/3<br>963 ACTROS MP4<br>964 ANTOS<br>964 AROCS<br>375 ATEGO     |



| Model / Details | Description          | Replaces Ref. No: | TM No.  |
|-----------------|----------------------|-------------------|---|
| 950 ACTROS      | Bearing, Wheel Hub   | 0019812905        | <b>TM26312</b><br>   |
| 952 ACTROS      | Repl. FAG: 32310A    | 0019817405        |   |
| 953 ACTROS      | ø50xø110x42,25       | 0019817605        |   |
| 954 ACTROS      |                      | 0069819905        |   |
| 930 ACTROS 2/3  |                      |                   |   |
| 932 ACTROS 2/3  |                      |                   |   |
| 933 ACTROS 2/3  |                      |                   |   |
| 950 AXOR 2      | Bearing, Wheel Hub   | 0059818805        | <b>TM37116</b><br>   |
| 343 T2/L        | Repl. FAG: 534565    | 0059813105        |   |
| 343 T2/LN1      | ø70xø130x57          | 0059813005        |   |
| 346 L 1924      |                      |                   |   |
| 346 LK 1924     |                      |                   |   |
| 346 LK 1928     |                      |                   |   |
| 346 LS 1924     |                      |                   |   |
| 972 ATEGO       | Bearing, Wheel Hub   | 0089819405        | <b>TM37117</b><br>  |
| 976 ATEGO       | Repl. FAG: 523361    | 0089819505        |   |
| 958 ATEGO 2     | ø60xø100x30          | 0089814905        |   |
| 970 ATEGO 2     |                      |                   |   |
| 972 ATEGO 2     |                      |                   |   |
| 976 ATEGO 2     |                      |                   |   |
| 316 LP          |                      |                   |   |
| 314 LP          | Bearing, Wheel Hub   | 0009807502        | <b>TM25207</b><br> |
| 316 LP          | Repl. FAG: 33111     | 0029818205        |   |
| 318 LP          | ø55xø95x30           | 0069818205        |   |
| 353 LP          |                      | 0089813605        |   |
| 353 T2/L        |                      |                   |   |
| 398 LO 814      |                      |                   |   |
| 673 LK/LN2      |                      |                   |   |
| 972 ATEGO       | Bearing, Wheel Hub   | 0049814605        | <b>TM26569</b><br> |
| 970 ATEGO 2     | Repl. FAG: K580.572  | 0049814705        |   |
| 972 ATEGO 2     | ø82,55xø139,99x36,51 | 0049814805        |   |
| 976 ATEGO 2     |                      | 0009815605        |   |
| 318 LP          |                      |                   |   |
| 674 LK/LN2      |                      |                   |   |
| 675 LK/LN2      |                      |                   |   |
| 375 ACTROS      | Bearing, Wheel Hub   | 0139814205        | <b>TM26313</b><br> |
| 950 ACTROS      | Repl. FAG: 572813A   | 0139814305        |   |
| 952 ACTROS      | ø70xø150x64          | 0099810805        |   |
| 953 ACTROS      |                      | 0099816405        |   |
| 954 ACTROS      |                      |                   |   |
| 930 ACTROS 2/3  |                      |                   |   |
| 932 ACTROS 2/3  |                      |                   |   |
| 950 ACTROS      | Bearing, Wheel Hub   | 0039814505        | <b>TM26317</b><br> |
| 952 ACTROS      | Repl. FAG: 33220     | 0049811005        |   |
| 953 ACTROS      | ø100xø180x63         | 0089813405        |   |
| 954 ACTROS      |                      |                   |   |
| 930 ACTROS 2/3  |                      |                   |   |
| 932 ACTROS 2/3  |                      |                   |   |
| 933 ACTROS 2/3  |                      |                   |   |





| TM No.  | Replaces Ref. No:                                    | Description   | Model / Details   |
|---|--|---|---|
| <b>TM26357</b><br>   | 0159811905<br>0149815705                             | Bearing, Wheel Hub<br>Repl. FAG: 201050<br>ø60xø108x75                  | 970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>970 ATEGO 2<br>972 ATEGO 2<br>975 ATEGO 2<br>976 ATEGO 2     |
| <b>TM30283</b><br>   | 0029816405<br>0029816305                             | Bearing, Wheel Hub<br>Repl. FAG: 32308A<br>ø40xø90x35,25                | 352 L 1813/6X4<br>360 L 1817,1819/6X4<br>360 L 1819/6X4   |
| <b>TM24607</b><br>  | 3199810005   | Bearing, Wheel Hub<br>Repl. FAG: 32207A<br>ø35xø72x24,25                | 930 ACTROS 2/3<br>963 ACTROS MP4<br>964 AROCS<br>375 AXOR<br>374 AXOR 2<br>375 AXOR 2               |
| <b>TM26356</b><br> | 0159814805<br>0159814705                             | Bearing, Wheel Hub<br>Repl. FAG: 805312<br>ø100xø160x44                 | 75 ACTROS<br>950 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>934 ACTROS 2/3<br>375 AXOR<br>374 AXOR 2 |
| <b>TM37118</b><br> | 0119818905<br>0159815505<br>0179814605               | Bearing, Wheel Hub<br>ø49xø84x48  | 690 SPRINTER<br>901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER<br>909 SPRINTER        |
| <b>TM26354</b><br> | 0139812205<br>0139812305<br>0139819805               | Bearing, Wheel Hub<br>Repl. FAG: 805092.07 /<br>803194<br>ø78xø130x90,5 | 979 ACCELO<br>375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>375 ATEGO 2<br>970 ATEGO 2        |
| <b>TM26074</b><br> | 0039812605<br>0009809702<br>0039812805<br>0059814905 | Bearing, Wheel Hub<br>Repl. FAG: 33021<br>ø105xø160x45                  | 950 ACTROS<br>950 AXOR 2<br>952 ACTROS<br>952 AXOR 2<br>953 ACTROS<br>953 AXOR 2<br>954 ACTROS      |



| Model / Details   | Description  | Replaces Ref. No:                                    | TM No.  |
|---|--|--|---|
| 964 AROCS<br>932 ACTROS 2/3<br>934 ACTROS 2/3<br>950 ACTROS<br>950 AXOR 2<br>952 ACTROS<br>952 AXOR 2<br>954 ACTROS | Bearing, Wheel Hub<br>Repl. FAG: 528595<br>ø106xø160x37                          | 0019802502<br>0049811905<br>0049812005               | <b>TM26055</b><br>   |
| 964 ANTOS<br>963 ACTROS MP4<br>958 ACTROS MP4<br>375 AROCS<br>964 ACTROS 2/3<br>375 AXOR 2<br>950 ACTROS            | Bearing, Wheel Hub<br>Repl. FAG: 567549Repl.<br>SKF:<br>VKHB2329<br>ø100xø157x42 | 0099814305<br>0119812305<br>0119813505<br>0119813605 | <b>TM26316</b><br>   |
| 346 L 1924<br>346 L 1928<br>346 LK 1924<br>346 LK 1928<br>346 LS 1924<br>346 LS 1928<br>349 L 1621                  | Dust Cover, Wheel Hub<br>ø147xø174x2   | 9463560127<br>3463560027                             | <b>TM26196</b><br>   |
| 970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>970 ATEGO 2<br>972 ATEGO 2<br>975 ATEGO 2<br>976 ATEGO 2                     | Flange, Wheel Hub<br>Without Stud<br>ø18/ø290x49,5                               | 9703340145<br>9703340045<br>9703300144S              | <b>TM37119</b><br> |
| 375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>375 ATEGO 2<br>970 ATEGO 2<br>972 ATEGO 2                       | Flange, Wheel Hub<br>ø20/ø320x41   | 9753300544S  | <b>TM37120</b><br> |
| 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3              | Flange, Wheel Hub<br>ø22/ø382x26   | 9433340945<br>9433341045                             | <b>TM30842</b><br> |
| 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS  | Flange, Wheel Hub<br>ø380  | 9603341045<br>9603340545                             | <b>TM37121</b><br> |







| TM No.  | Replaces Ref. No:                                     | Description   | Model / Details  |
|---|---|---|--|
| <b>TM30692</b><br>   | 3463541662  | Thrust Washer, Wheel Hub  | 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3 |
| <b>TM30696</b><br>   | 3463541762  | Thrust Washer, Wheel Hub  | 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3 |
| <b>TM37122</b><br>  | 9423320362  | Thrust Washer, Wheel Hub  | 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3 |
| <b>TM27780</b><br> | 9433320462  | Thrust Washer, Wheel Hub  | 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3 |
| <b>TM26286</b><br> | 6563320062  | Thrust Washer, Wheel Hub  | 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3 |
| <b>TM26361</b><br> | 9433301225<br>9433301125<br>0003300725<br>9433340701S | Unit, Wheel Hub<br>With Alternative Bearing<br>ø140x140/ø199x147, | 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3 |
| <b>TM37123</b><br> | 0003300725<br>9433301125<br>9433301225<br>9433340701S | Unit, Wheel Hub<br>With FAG Bearing<br>ø140x140/ø199x147,5        | 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3 |





| Model / Details  | Description  | Replaces Ref. No:                                     | TM No.  |
|--|--|---|---|
| 375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>375 ATEGO 2<br>970 ATEGO 2<br>972 ATEGO 2              | Unit, Wheel Hub<br>ø130x130/ø168x148                     | 9753300825<br>9753300425                              | <b>TM26117</b><br>   |
| 375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>375 ATEGO 2<br>970 ATEGO 2<br>972 ATEGO 2              | Unit, Wheel Hub<br>With FAG Bearing<br>ø130x130/ø168x148 | 9753300825<br>9753300425                              | <b>TM37124</b><br>   |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 | Unit, Wheel Hub<br>ø130x130/ø168x148                     | 9433300825<br>9433340001S                             | <b>TM26367</b><br>   |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 | Unit, Wheel Hub<br>With FAG Bearing<br>ø130x130/ø168x148 | 9433300825<br>9433340001S                             | <b>TM26367</b><br> |
| 970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>970 ATEGO 2<br>972 ATEGO 2<br>975 ATEGO 2<br>976 ATEGO 2            | Unit, Wheel Hub<br>ø60xø144x115                          | 9723300125<br>9723300325<br>9723300425<br>9723340201S | <b>TM26350</b><br> |
| 970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>970 ATEGO 2<br>972 ATEGO 2<br>975 ATEGO 2<br>976 ATEGO 2            | Unit, Wheel Hub<br>With FAG Bearing<br>ø60xø144x115      | 9723300125<br>9723300325<br>9723300425<br>9723340201S | <b>TM26350</b><br> |
| 934 ACTROS 2/3<br>963 ACTROS MP4<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>970 ATEGO 2<br>972 ATEGO 2      | Unit, Wheel Hub<br>ø60xø144x115                          | 9723300625<br>9723340201S1                            | <b>TM37127</b><br> |





| TM No.  | Replaces Ref. No:                          | Description  | Model / Details  |
|---|--|--|--|
| <b>TM37128</b><br>   | 9723300625<br>9723340201S1                 | Unit, Wheel Hub<br>With FAG Bearing<br>ø60xø144x115    | 934 ACTROS 2/3<br>963 ACTROS MP4<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>970 ATEGO 2<br>972 ATEGO 2  |
| <b>TM26401</b><br>   | 9433301325                                 | Unit, Wheel Hub<br>With Alternative Bearing<br>M20x1,5 | 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS   |
| <b>TM26401</b><br>   | 9433301325                                 | Unit, Wheel Hub<br>With FAG Bearing<br>M20x1,5         | 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS   |
| <b>TM25125</b><br> | 0059906104<br>000912014091<br>000912014021 | Bolt, Wheel Hub<br>M12x1,5/25                          | 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3 |
| <b>TM37129</b><br> | 3553540371<br>6243540071<br>6243540171     | Bolt, Wheel Hub<br>M14x1,5/60                          | 950 AXOR 2<br>343 T2/L<br>346 L 1924<br>346 L 1928<br>346 LK 1924<br>346 LK 1928<br>346 LS 1924        |
| <b>TM26287</b><br> | 9453340351                                 | Spacer Ring, Wheel Hub<br>ø145xø174x21                 | 950 ACTROS<br>930 ACTROS 2/3<br>963 ACTROS MP4<br>964 AROCS<br>375 AXOR<br>375 AXOR 2<br>940 AXOR 2    |
| <b>TM26319</b><br> | 6243560020                                 | Hub Cap  | 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3 |



| Model / Details  | Description                    | Replaces Ref. No:        | TM No.  |
|--|--------------------------------|--------------------------|---|
| 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3                       | Hub Cap<br>ø9xø156x38,5        | 3273560120               | <b>TM37130</b>  |
|  |                                |                          |    |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3                   | Hub Cap<br>ø9/ø160x13          | 9473250013               | <b>TM27838</b>  |
|  |                                |                          |    |
| 749 AIRMASTER<br>749 STEERMASTER   | Hub Cap<br>ø143x63,5           | 9463560020<br>9463560420 | <b>TM37131</b>  |
|  |                                |                          |    |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>963 ACTROS MP4 | Hub Cap<br>ø95,5x162x30,45     | 3893340025               | <b>TM37132</b>  |
|  |                                |                          |  |
| 346 L 1924<br>346 L 1928<br>346 LK 1924<br>346 LK 1928<br>346 LS 1924<br>346 LS 1928<br>349 L 1621                           | Gasket, Hub Cap<br>ø275xø216x1 | 6503560080<br>6243560080 | <b>TM26190</b>  |
|  |                                |                          |  |
| 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3                       | Plug, Hub Cap<br>M24x1,5       | 6249970032               | <b>TM25098</b>  |
|  |                                |                          |  |
| 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3                       | Plug, Hub Cap                  | 3559970232               | <b>TM30670</b>  |
|  |                                |                          |  |





| TM No.  | Replaces Ref. No: | Description | Model / Details |
|---|-------------------|-------------|-----------------|
| <b>TM26110</b><br>   | 0004012471        | Stud        | 950 ACTROS      |
|   | 3894010071        | M22x1,5/80  | 952 ACTROS      |
|   | 3274010471        |             | 953 ACTROS      |
|   | 3814010171        |             | 954 ACTROS      |
|   |                   |             | 930 ACTROS 2/3  |
|   |                   |             | 932 ACTROS 2/3  |
|   |                   |             | 933 ACTROS 2/3  |
| <b>TM26888</b><br>   | 0004013871        | Stud        | 950 ACTROS      |
|   | 3814010671        | M22x1,5/105 | 952 ACTROS      |
|   | 3554010071        |             | 953 ACTROS      |
|   |                   |             | 954 ACTROS      |
|   |                   |             | 375 AXOR 2      |
|   |                   |             | 950 AXOR 2      |
|   |                   |             | 952 AXOR 2      |
| <b>TM26254</b><br>   | 3814010771        | Stud        | 950 ACTROS      |
|   | 3464010071        | M22x1,5/110 | 952 ACTROS      |
|   | 0004013771        |             | 953 ACTROS      |
|   |                   |             | 954 ACTROS      |
|   |                   |             | 930 ACTROS 2/3  |
|   |                   |             | 932 ACTROS 2/3  |
|   |                   |             | 933 ACTROS 2/3  |
| <b>TM26048</b><br> | 0004013971        | Stud        | 950 ACTROS      |
|   | 0004014071        | M22x1,5/97  | 952 ACTROS      |
|   | 3814010571        |             | 954 ACTROS      |
|   | 3814010471        |             | 930 ACTROS 2/3  |
|   |                   |             | 932 ACTROS 2/3  |
|   |                   |             | 934 ACTROS 2/3  |
|   |                   |             | 958 ATEGO 2     |
| <b>TM26253</b><br> | 3464025070        | Stud        | -               |
|   | 3154020170        | M18x2/125   |                 |
| <b>TM26128</b><br> | 3154020070        | Stud        | -               |
|   | 3874010270        | M18x2/110   |                 |
| <b>TM37133</b><br> | 3354010070        | Stud        | -               |
|   | 3634020170        | M18x2/68    |                 |



| Model / Details   | Description         | Replaces Ref. No:                      | TM No.         |
|---|---------------------|--|----------------|
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3                                | Stud<br>M20x2/115   | 6204010170                             | <b>TM37134</b> |
| 958 ATEGO 2<br>375 AXOR 2<br>694 L 1218 R<br>694 L 1218/1318/1319<br>694 L 1418<br>694 LK 1218 - 1318 -<br>1319/42<br>695 L 1622 / L 1620 | Stud<br>M22x1,5/115 | 3814010871                             | <b>TM37135</b> |
| 958 AXOR 2<br>338 L 1418<br>338 LK 1418<br>338 LP 1418<br>338 LPS 1418<br>338 LS 1418<br>352 L 1813/6X4                                   | Stud<br>M22x1,5/92  | 3894010171<br>3814010371<br>3274020471 | <b>TM26242</b> |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3                                | Stud<br>M20x2/57    | 6204010070                             | <b>TM26251</b> |
| 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3                                    | Stud<br>M22x1,5/68  | 9424010271<br>0004012371               | <b>TM26243</b> |
| 979 ACCELO<br>970 ATEGO<br>970 ATEGO 2<br>398 LO 814<br>673 LK/LN2<br>674 LK/LN2<br>676 LK/LN2  | Stud<br>M18x1,5/75  | 6744020171                             | <b>TM26249</b> |
| 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3                                    | Stud<br>M22x1,5/91  | 9424010371<br>0004014171               | <b>TM37136</b> |





| TM No.  | Replaces Ref. No:   | Description  | Model / Details   |
|---|---|--|---|
| <b>TM37137</b><br>   | 3524020071  | Stud<br>M20x1,5/77                                   | 375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>375 ATEGO 2<br>970 ATEGO 2 |
|   | <b>TM26033</b><br>   | 3094020171<br>3094020271<br>3194020471<br>3194020371 | Stud<br>M14x1,5/58  |
| <b>TM26248</b><br>   | 3184020071  | Stud<br>M18x1,5/65                                   | 979 ACCELO<br>972 ATEGO<br>970 ATEGO 2<br>972 ATEGO 2<br>316 LP<br>318 LP<br>398 LO 814     |
|   | <b>TM26240</b><br> | 3094010271<br>3094010171<br>3194010671<br>3194010971 | Stud<br>M14x1,5/51  |
| <b>TM37138</b><br> |   | 0004013071   | Stud<br>M22x1,5/93  |
|   | <b>TM37139</b><br> | 3814011371<br>0004013471                             | Stud<br>M22x1,5/125   |
| <b>TM37140</b><br> |   | 0004013371<br>3814011471                             | Stud<br>M22x1,5/130   |





| Model / Details  | Description | Replaces Ref. No:                                    | TM No.  |
|--|-------------|--|---|
| 972 ATEGO<br>976 ATEGO<br>970 ATEGO 2<br>972 ATEGO 2<br>976 ATEGO 2<br>967 ATEGO 3<br>675 LK/LN2               | Stud        | 0004015171<br>3274020371                             | <b>TM26111</b><br>   |
| 972 ATEGO<br>970 ATEGO 2<br>972 ATEGO 2<br>976 ATEGO 2<br>352 L 1313<br>352 LA 1313<br>352 LAK 1313            | Stud        | 3274020271<br>3024020071                             | <b>TM26241</b><br>   |
| 979 ACCELO<br>934 ACTROS 2/3<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>970 ATEGO 2<br>972 ATEGO 2              | Stud        | 9704010071   | <b>TM26256</b><br>   |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3     | Stud        | 3384015071   | <b>TM26068</b><br> |
| 375 ACTROS<br>950 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>934 ACTROS 2/3<br>963 ACTROS MP4<br>964 ACTROS MP4 | Stud        | 0004012971<br>9484010271<br>3814011271<br>9484010071 | <b>TM37141</b><br> |
| 312 L 312<br>318 LP<br>328 T2/L<br>341 L 911<br>341 LA 1112<br>341 LA 1114<br>341 LO 911                       | Stud        | 3124011171<br>3184020271<br>3274010071<br>3184010071 | <b>TM26246</b><br> |
| 979 ACCELO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>970 ATEGO 2<br>972 ATEGO 2<br>975 ATEGO 2                 | Stud        | 0004016871<br>6754020071                             | <b>TM26135</b><br> |





| TM No.  | Replaces Ref. No:                            | Description               | Model / Details   |
|---|--|---------------------------|---|
| <b>TM37142</b><br>   | 3054010071                                   | Stud<br>M22x1,5/77        | 345 OH SERIES<br>368 OH SERIES<br>382 OH SERIES<br>382 OH SERIES<br>382 O 500<br>384 OF SERIES<br>634 O 500 |
| <b>TM26244</b><br>   | 0004010972<br>0004011372<br>0004012372       | Nut, Stud<br>M22x1,5/39   | -   |
| <b>TM26765</b><br>   | 0009905053                                   | Nut, Stud<br>M18x1,5      | 979 ACCELO<br>934 ACTROS 2/3<br>963 ACTROS MP4<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>970 ATEGO 2        |
| <b>TM26245</b><br> | 0004011072<br>0009905753                     | Nut, Stud<br>M22x1,5/62   | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3  |
| <b>TM26891</b><br> | 0009901450<br>3159905051                     | Nut, Stud<br>M18x2/20     | 387 NG<br>389 NG<br>307 O 305<br>307 O 307  |
| <b>TM26979</b><br> | 074361022205<br>074361022203<br>074361022204 | Nut, Stud<br>M22x1,5/22   | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3  |
| <b>TM26178</b><br> | 0004010672<br>3854000124<br>6174000024       | Nut, Stud<br>M22x1,5/26,5 | 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3      |



| Model / Details  | Description            | Replaces Ref. No:                            | TM No.  |
|--|------------------------|--|---|
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 | Nut, Stud<br>M20x2     | 3464015072                                   | <b>TM26657</b>  |
|  |                        |  |    |
| 310 LT 608 D<br>310 T2/L<br>313 T2/L<br>314 LP<br>316 LP<br>318 LP<br>398 LO 814                           | Nut, Stud<br>M18x1,5   | 074361018205<br>074361018201                 | <b>TM26980</b>  |
|  |                        |  |    |
| 341 L 1112<br>341 L 1114<br>341 L 911<br>341 L 914<br>341 LA 1112<br>341 LA 1114<br>341 LK 1114            | Nut, Stud<br>M20x1,5   | 074361020204<br>074361020205                 | <b>TM26823</b>  |
|  |                        |  |   |
| 970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>970 ATEGO 2<br>972 ATEGO 2<br>974 ATEGO 2              | Rondela, Stud<br>ø20,5 | 074361020352<br>074361020351<br>3769907147   | <b>TM26582</b>  |
|  |                        |  |  |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 | Rondela, Stud<br>ø22,5 | 074361022351<br>074361022350<br>074361022352 | <b>TM26528</b>  |
|  |                        |  |  |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 | Rondela, Stud<br>ø22   | 3174020175                                   | <b>TM26069</b>  |
|  |                        |  |  |
| 970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>970 ATEGO 2<br>972 ATEGO 2<br>975 ATEGO 2<br>976 ATEGO 2            | Rondela, Stud<br>ø18,5 | 074361018352<br>074361018250<br>074361018350 | <b>TM26915</b>  |
|  |                        |  |  |



| TM No.  | Replaces Ref. No:          | Description                     | Model / Details   |
|---|----------------------------|---------------------------------|---|
| <b>TM37143</b><br>   | 3194020075                 | Rondela, Stud<br>ø14            | 308 L 608 E,L 708 E<br>308 L/LO 608 D<br>308 LO 608 D,LO 708 D/E<br>309 T2/L<br>309 TL2/L<br>310 LF 508 D/LF 608 D<br>310 T2/L  |
| <b>TM37144</b><br>   | 0004014171S<br>9424010371S | Repair Kit, Stud<br>M22x1,5/91  | 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3  |
| <b>TM37145</b><br>   | 9424010271S                | Repair Kit, Stud<br>M22x1,5     | 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3  |
| <b>TM26147</b><br> | 0004012471S2               | Repair Kit, Stud<br>M22x1,5     | 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3  |
| <b>TM26432</b><br> | 3524020071S                | Repair Kit, Stud<br>M20x1,5     | 375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>375 ATEGO 2<br>970 ATEGO 2<br>972 ATEGO 2  |
| <b>TM26428</b><br> | 0004013771S4               | Repair Kit, Stud<br>M22x1,5/110 | 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3  |
| <b>TM26429</b><br> | 3814010671S                | Repair Kit, Stud<br>M22x1,5/105 | 950 ACTROS<br>950 AXOR 2<br>349 L 1621<br>397 OF SERIES<br>371 1817 K/4X2/36 MBT<br>371 1821 AK/4X4/36 MBT<br>371 2517/6X2/42 OT-<br>TOMARSAN/TUERKEI<br>371 2517K/6X2/36 OT-<br>TOMARSAN/TUERKEI |



| Model / Details   | Description                     | Replaces Ref. No: | TM No.         |
|---|---------------------------------|-------------------|----------------|
| 352 L 1813/6X4<br>360 L 1513<br>360 LA 1513<br>360 LA 1513,LA 1517<br>360 LAK 1513<br>360 LAK 1517 MBSA<br>360 LAKO 1513<br>360 LK 1513 | Repair Kit, Stud<br>M22x1,5/115 | 3814010871S       | <b>TM37146</b> |
| 352 L 1813/6X4<br>360 L 1513<br>360 LA 1513<br>360 LA 1513,LA 1517<br>360 LAK 1513<br>360 LAK 1517 MBSA<br>360 LAKO 1513<br>360 LK 1513 | Repair Kit, Stud<br>M22x1,5/92  | 3814010371S       | <b>TM37147</b> |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3            | Repair Kit, Stud<br>M22x1,5/110 | 0004013771S1      | <b>TM26148</b> |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3            | Repair Kit, Stud<br>M22x1,5/110 | 0004013771S2      | <b>TM26146</b> |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3            | Repair Kit, Stud<br>M22x1,5/110 | 0004013771S3      | <b>TM26149</b> |
| 979 ACCELO<br>972 ATEGO<br>970 ATEGO 2<br>972 ATEGO 2<br>316 LP<br>318 LP<br>673 LK/LN2<br>673 LK/LN2                                   | Repair Kit, Stud<br>M18x1,5/65  | 3184020071S       | <b>TM37148</b> |
| 972 ATEGO<br>976 ATEGO<br>970 ATEGO 2<br>972 ATEGO 2<br>976 ATEGO 2<br>967 ATEGO 3<br>675 LK/LN2<br>675 LK/LN2                          | Repair Kit, Stud<br>M20x1,5/89  | 0004015171S       | <b>TM37149</b> |





| TM No.  | Replaces Ref. No: | Description                     | Model / Details   |
|---|-------------------|---------------------------------|---|
| <b>TM37150</b><br>   | 0004013971S1      | Repair Kit, Stud<br>M22x1,5/97  | 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3  |
| <b>TM37151</b><br>   | 3814010871S1      | Repair Kit, Stud<br>M22x1,5/115 | 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3  |
| <b>TM37152</b><br>   | 3464025070S       | Repair Kit, Stud<br>M18x2/125   | 387 NG<br>389 NG<br>307 O 305<br>307 O 307  |
| <b>TM37153</b><br> | 3154020070S       | Repair Kit, Stud                | 387 NG<br>389 NG<br>307 O 305<br>307 O 307  |
| <b>TM37154</b><br> | 3094010271S       | Repair Kit, Stud                | 308 L 608 E,L 708 E<br>308 L/LO 608 D<br>308 LO 608 D,LO 708 D/E<br>309 L 406 DG,L 407 D<br>309 L 408 DG<br>309 L 408 G,L 409<br>309 L 508 DG |
| <b>TM37155</b><br> | 6744020171S       | Repair Kit, Stud                | 979 ACCELO<br>970 ATEGO<br>970 ATEGO 2<br>398 LO 814<br>673 LK/LN2<br>674 LK/LN2<br>688 1114  |
| <b>TM37156</b><br> | 0004013371S       | Repair Kit, Stud<br>M22x1,5/130 | 950 ACTROS<br>952 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>934 ACTROS 2/3<br>952 AXOR 2                                    |







| Model / Details   | Description                      | Replaces Ref. No: | TM No.         |
|---|----------------------------------|-------------------|----------------|
| 972 ATEGO<br>970 ATEGO 2<br>972 ATEGO 2<br>976 ATEGO 2<br>352 L 1313<br>352 LA 1313<br>352 LAKO 1313                      | Repair Kit, Stud<br>M20x1,5/84   | 3274020271S       | <b>TM37157</b> |
| 950 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>934 ACTROS 2/3<br>958 ATEGO 2<br>950 AXOR 2<br>958 AXOR 2                   | Repair Kit, Stud<br>M22x1,5/93   | 0004013071S       | <b>TM37158</b> |
| 375 ACTROS<br>950 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>934 ACTROS 2/3<br>963 ACTROS MP4<br>964 ANTOS                 | Repair Kit, Stud<br>M22x1,5/96,5 | 0004012971S       | <b>TM26444</b> |
| 979 ACCELO<br>934 ACTROS 2/3<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>970 ATEGO 2<br>975 ATEGO 2                         | Repair Kit, Stud<br>M18x1,5/63   | 9704010071S       | <b>TM37159</b> |
| 950 ACTROS<br>952 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>934 ACTROS 2/3<br>958 ATEGO 2<br>950 AXOR 2 | Repair Kit, Stud<br>M22x1,5/97   | 0004013971S       | <b>TM37160</b> |
| 906 SPRINTER  | Cover, Rim                       | 9064000125        | <b>TM37161</b> |
| 639 VIANO<br>636 VIANO<br>639 VIANO<br>639 VITO   | Cover, Rim                       | 6394000025        | <b>TM37162</b> |











| TM No.  | Replaces Ref. No:                                       | Description  | Model / Details  |
|---|---|--|--|
| <b>TM37163</b><br>   | 6394010825  | Cover, Rim   | 639 VIANO<br>639 VITO  |
| <b>TM37164</b><br>   | 4474011600  | Cover, Rim   | 447 VITO   |
| <b>TM37165</b><br>   | 0003500733S<br>3463507533S<br>3553505033<br>3463507433S | Bell Hub<br>Without Planetary Carrier<br>h1: 282 mm / h2: 260 mm                 | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 |
| <b>TM26396</b><br> | 0003500733<br>3463507533<br>3463507433                  | Bell Hub<br>With Planetary Carrier<br>h1: 282 mm / h2: 260 mm                    | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 |
| <b>TM37166</b><br> | 3463507133S<br>0003500533S                              | Bell Hub<br>Without Planetary Carrier,<br>Wide Flange<br>h1: 268 mm / h2: 245 mm | 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3     |
| <b>TM37167</b><br> | 3463507133<br>0003500533                                | Bell Hub<br>With Planetary Carrier,<br>Wide Flange<br>h1: 268 mm / h2: 245 mm    | 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3     |
| <b>TM37168</b><br> | 9423501309S   | Bell Hub<br>Without Planetary Carrier,<br>Wide Flange<br>h1: 258 mm / h2: 236 mm | 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3     |



| Model / Details  | Description  | Replaces Ref. No: | TM No.  |
|--|--|-------------------|---|
| 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3     | Bell Hub<br>With Planetary Carrier,<br>Wide Flange,<br>without Screw<br>h1: 258 mm / h2: 236<br>mm | 9423501309S1      | <b>TM37169</b><br> |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 | Bell Hub<br>Without Planetary Carrier<br>h1: 272 mm / h2: 250<br>mm                                | 3463509233        | <b>TM26398</b><br> |
| -  | -  | -                 | -   |
| -  | -  | -                 | -   |
| -  | -  | -                 | -   |
| -  | -  | -                 | -   |
| -  | -  | -                 | -   |
| -  | -  | -                 | -   |



| TM No.  | Replaces Ref. No:                            | Description   | Model / Details  |
|---|--|---|--|
| <b>TM37170</b><br>   | 3463507233                                   | Bell Hub<br>Complete<br>h1=274 mm / h2=245<br>mm                  | 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3     |
| <b>TM37171</b><br>   | 3463507233S                                  | Bell Hub<br>Without Planetary Carrier<br>h1=274 mm / h2=245<br>mm | 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3     |
| <b>TM37172</b><br>   | 3463509133S                                  | Carrier, Wheel Hub  | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 |
| <b>TM37171</b><br> | 3463507233S                                  | Carrier, Wheel Hub  | 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3     |
| <b>TM37173</b><br> | 3553500254S                                  | Carrier, Wheel Hub<br>Complete                                    | 950 AXOR 2<br>650 MK<br>619 NG<br>621 NG<br>623 NG<br>624 NG<br>649 NG                                     |
| <b>TM37174</b><br> | 3463500654S                                  | Carrier, Wheel Hub<br>Complete                                    | 343 T2/L<br>346 L 1924<br>346 L 1928<br>346 LK 1924<br>346 LK 1928<br>346 LS 1924<br>346 LS 1928           |
| <b>TM37175</b><br> | 3553505133S1<br>3553504733S1<br>3463504733S1 | Carrier, Wheel Hub  | 386 L 1633<br>386 LS 1630<br>615 LK/LN2<br>650 MK<br>651 MK<br>652 MK<br>653 MK                            |



| Model / Details  | Description  | Replaces Ref. No:                                      | TM No.  |
|--|--|--|---|
| 950 AXOR 2<br>343 T2/L<br>346 L 1924<br>346 L 1928<br>346 LK 1924<br>346 LK 1928<br>346 LS 1924            | Carrier, Wheel Hub<br>h=67mm                                 | 3463501533S1<br>3553502533S1                           | <b>TM37176</b><br>   |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 | Carrier, Wheel Hub<br>h=77mm                                 | 3463507433S1<br>3463507533S1                           | <b>TM37177</b><br>   |
| 690 SPRINTER<br>901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>909 SPRINTER                               | Repair Kit, Differential                                     | 9023500323   | <b>TM31028</b><br>   |
| 405 UNIMOG<br>436 UNIMOG<br>437 UNIMOG   | Plug, Differential   | 0009972035<br>0009972632<br>0009973435<br>0009977535   | <b>TM37178</b><br> |
| 639 VIANO<br>636 VIANO<br>639 VIANO<br>639 VITO  | Plug, Differential<br>L: 410,5 mm                            | 6393506101<br>6393500842<br>6393500542<br>6393530347   | <b>TM37179</b><br> |
| 639 VIANO<br>636 VIANO<br>639 VIANO<br>639 VITO  | Rubber Bushing, Differential<br>ø14,7xø74x66,3               | 6399880510<br>4479970120<br>6393506101S<br>6393500842S | <b>TM37180</b><br> |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 | Seal Ring, Differential Gear<br>Housing<br>ø72xø105x19 / FPM | 0209970647<br>0119976847<br>0139974947<br>0109973746   | <b>TM26126</b><br> |





| TM No.  | Replaces Ref. No:   | Description  | Model / Details  |
|---|---|--|--|
| <b>TM31933</b><br>   | 0179972847  | Seal Ring, Differential Gear Housing<br>ø85xø105x13 / NBR    | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>934 ACTROS 2/3 |
|   | <b>TM31627</b><br>   | 0049979646<br>0089970047<br>0129974447<br>0099970746         | Seal Ring, Differential Gear Housing<br>ø80xø100x10 / NBR  |
| <b>TM26125</b><br>  | 0109973646<br>0099971246<br>0179972947  | Seal Ring, Differential Gear Housing<br>ø85xø105x13 / FPM    | 343 T2/L<br>346 L 1924<br>346 L 1928<br>346 LK 1924<br>346 LK 1928<br>346 LS 1924<br>346 LS 1928           |
|   | <b>TM37181</b><br> | 0099974546<br>0099979146<br>0119977047<br>0029970647         | Seal Ring, Differential Gear Housing<br>ø72xø105x13 / NBR  |
| <b>TM30591</b><br> | 0189971847  | Seal Ring, Differential Gear Housing<br>ø85xø145x12/32 / FPM | 970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>970 ATEGO 2<br>972 ATEGO 2<br>974 ATEGO 2              |
|   | <b>TM30610</b><br> | 0179975547   | Seal Ring, Differential Gear Housing<br>ø40xø70x13 / FPM   |
| <b>TM30575</b><br> | 0039974446<br>0089970747<br>0089970847<br>0109975746  | Seal Ring, Differential Gear Housing<br>ø68xø90x13 / FPM     | 328 T2/L<br>341 L 1112<br>341 LA 1112<br>341 LO 1112<br>341 LS 1112<br>344 L 1113<br>344 LA 1113           |












| Model / Details   | Description  | Replaces Ref. No:                                    | TM No.  |
|---|--|--|---|
| 343 T2/L<br>346 L 1924<br>346 L 1928<br>346 LK 1924<br>346 LK 1928<br>346 LS 1924<br>346 LS 1928  | Seal Ring, Differential Gear<br>Housing<br>ø85xø105x13 / NBR               | 0079979946<br>0099971146                             | <b>TM30506</b><br>   |
| 345 L 1513,1514,1516<br>345 L 1516,L 1517,L 1518<br>345 L 1518 ,LS 1518<br>345 L 1519<br>345 L 1519,1520<br>345 L 2225<br>345 LK 1513,1514,1516 | Seal Ring, Differential Gear<br>Housing<br>ø68xø85x10 / NBR                | 0059976847<br>0059977747<br>0059976647<br>0169976747 | <b>TM30570</b><br>   |
| 674 LK/LN2<br>675 LK/LN2<br>676 LK/LN2<br>677 LK/LN2<br>678 LK/LN2<br>679 LK/LN2<br>650 MK  | Seal Ring, Differential Gear<br>Housing<br>ø55xø80x8 / ACM                 | 0089971947<br>0109972946<br>0109979447<br>0139972646 | <b>TM31954</b><br>   |
| 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3  | Seal Ring, Differential Gear<br>Housing<br>ø85xø145x12/37 / FPM            | 0159974747<br>0129975947<br>0109975446<br>0219975947 | <b>TM30456</b><br> |
| 375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>970 ATEGO 2<br>975 ATEGO 2   | Seal Ring, Differential Gear<br>Housing<br>ø78xø135x12/21,5                | 0159976246<br>0189977647<br>0199976047               | <b>TM37182</b><br> |
| 979 ACCELO<br>375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3  | Bearing, Differential Gear<br>Housing<br>Repl. FAG: 32020X<br>ø100xø150x32 | 0019816405<br>0049817405<br>0069810405<br>0019817205 | <b>TM30720</b><br> |
| 979 ACCELO<br>375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3  | Bearing, Differential Gear<br>Housing<br>Repl. FAG: 32017X<br>ø85xø130x29  | 0059811405<br>0059811505<br>0159810005<br>0159810805 | <b>TM30390</b><br> |





| TM No.  | Replaces Ref. No:                                    | Description  | Model / Details  |
|---|--|--|--|
| <b>TM25217</b><br>   | 9429810205   | Bearing, Differential Gear Housing<br>Repl. FAG: 32215A<br>ø75x130x33,5                  | 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3<br>963 ACTROS MP4<br>964 ANTOS<br>964 AROCS |
|   | 9443500049   | Bearing, Differential Gear Housing<br>Repl. FAG: 30215A<br>ø75x130x27,5                  | 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3<br>963 ACTROS MP4<br>964 ANTOS<br>964 AROCS |
| <b>TM30746</b><br>   | 0059815505<br>0059816905<br>0069817605               | Bearing, Differential Gear Housing<br>Repl. FAG: 33014<br>ø70xø110x31                    | 954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3<br>972 ATEGO<br>970 ATEGO 2   |
|   | 0049819805<br>0129813205<br>0049819905<br>0059810005 | Bearing, Crown Wheel & Pinion<br>Repl. FAG: 32314A<br>ø70xø150x54                        | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3       |
| <b>TM24891</b><br> | 0029814505<br>0019800502<br>0139816205<br>0039810605 | Bearing, Crown Wheel & Pinion<br>Repl. FAG: 31313A<br>ø65xø140x36                        | 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3           |
|   | 0019806902<br>0019810005<br>0059812405<br>0059812505 | Bearing, Crown Wheel & Pinion<br>Repl. FAG:<br>KHM803146.803110<br>ø41,275xø88,90x30,162 | 358 L 1113 B<br>358 T2/L<br>611 T1/TN<br>601 207 D/208 D<br>601 208/210<br>601 209 D/210 D<br>602 307 D/308 D    |
| <b>TM30668</b><br> | 9463510072<br>3853510572<br>3463530072               | Nut, Crown Wheel & Pinion<br>M55x1,5   | 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3           |



| Model / Details  | Description                             | Replaces Ref. No:        | TM No.  |
|--|---|--------------------------|---|
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 | Nut, Crown Wheel & Pinion<br>M45x1,5    | 3853510672<br>3663530072 | <b>TM30667</b><br>   |
| 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3     | Bushing, Differential Spider            | 9423530150               | <b>TM37183</b><br>   |
| 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3     | Bushing, Differential Spider            | 3463530326               | <b>TM30806</b><br>   |
| 900 SPRINTER<br>906 SPRINTER   | Drive Shaft<br>Rear, Left               | 9063503910               | <b>TM37184</b><br> |
| 900 SPRINTER<br>906 SPRINTER   | Drive Shaft<br>Rear, Left, Without hub  | 9063503910S              | <b>TM37185</b><br> |
| 900 SPRINTER<br>906 SPRINTER   | Drive Shaft<br>Rear, Right              | 9063504010               | <b>TM37186</b><br> |
| 900 SPRINTER<br>906 SPRINTER   | Drive Shaft<br>Rear, Right, Without hub | 9063504010S              | <b>TM37187</b><br> |





| TM No.  | Replaces Ref. No: | Description   | Model / Details  |
|---|-------------------|---|--|
| <b>TM37188</b><br>   | 9063503710        | Drive Shaft<br>Rear, Left                                 | 906 SPRINTER   |
| <b>TM37189</b><br>   | 9063503710S       | Drive Shaft<br>Rear, Left, Without hub                    | 906 SPRINTER   |
| <b>TM37190</b><br>   | 9063503810        | Drive Shaft<br>Rear, Right                                | 906 SPRINTER   |
| <b>TM37191</b><br> | 9063503810S       | Drive Shaft<br>Rear, Right, Without hub                   | 906 SPRINTER   |
| <b>TM37192</b><br> | 000720032024      | Bearing, Drive Shaft<br>Repl. FAG: 32024X<br>ø120xø180x38 | 336 LP 1924<br>336 LPS 1924<br>346 L 1924<br>346 LA 1924<br>346 LAK 1924<br>346 LAS 1924<br>346 LK 1924            |
| <b>TM30808</b><br> | 9423500143        | Adjusting Ring, Drive Shaft                               | 375 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3<br>963 ACTROS MP4<br>964 ANTOS  |
| <b>TM30753</b><br> | 9703530025        | Adjusting Ring, Drive Shaft                               | 979 ACCELO<br>375 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3<br>963 ACTROS MP4 |



| Model / Details  | Description                             | Replaces Ref. No:        | TM No.         |
|--|---|--------------------------|----------------|
| 950 ACTROS<br>952 ACTROS<br>954 ACTROS<br>950 AXOR 2<br>952 AXOR 2<br>621 NG<br>624 NG                     | Repair Kit, Drive Shaft<br>ø45xø50x48   | 6593300251<br>6593300051 | <b>TM30982</b> |
| 950 ACTROS<br>952 ACTROS<br>954 ACTROS<br>950 AXOR 2<br>952 AXOR 2<br>621 NG<br>624 NG                     | Repair Kit, Drive Shaft<br>ø45xø50x55   | 6593300351               | <b>TM30987</b> |
| 638 VITO<br>638 V-CLASS  | Repair Kit, Drive Shaft                 | 0003301985               | <b>TM37193</b> |
| 638 VITO<br>638 V-CLASS  | Repair Kit, Drive Shaft                 | 0003302085<br>0003301785 | <b>TM37194</b> |
| 950 ACTROS<br>952 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>934 ACTROS 2/3<br>964 AROCS  | Repair Kit, Drive Shaft<br>Front<br>ø50 | 6593300651               | <b>TM30985</b> |
| 950 ACTROS<br>952 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>934 ACTROS 2/3<br>964 AROCS  | Repair Kit, Drive Shaft<br>Front<br>ø50 | 9443300560               | <b>TM34273</b> |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 | Nut, Drive Shaft<br>M48x1,5             | 3553530126               | <b>TM37195</b> |














| TM No.  | Replaces Ref. No:                      | Description  | Model / Details   |
|---|--|--|---|
| <b>TM30752</b>  | 9423530225                             | Nut, Drive Shaft   | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3                |
|    |  |  |   |
| <b>TM30749</b>  | 3463530925                             | Nut, Distribution Shaft                                  | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>934 ACTROS 2/3                |
|    |  |  |   |
| <b>TM30568</b>  | 3553530158                             | Thrust Ring, Distribution Shaft<br>ø69xø75xø82xø76x28    | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>930 ACTROS 2/3<br>375 AXOR 2<br>653 MK<br>617 NG                                |
|    |  |  |   |
| <b>TM30569</b>  | 3463530358<br>9423530117               | Thrust Ring, Distribution Shaft<br>ø82xø88xø86xø92x35    | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>934 ACTROS 2/3                |
|  |  |  |   |
| <b>TM30715</b>  | 3553530225                             | Synchronizing Ring, Distribution Shaft<br>ø90 / M102x1,5 | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>930 ACTROS 2/3<br>375 AXOR 2<br>345 L<br>2213,2214,2216,2217<br>345 L 2219,2220 |
|  |  |  |   |
| <b>TM11490</b>  | 0015458409<br>0015454909<br>0015451809 | Sensor, Differential Lock                                | 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3                    |
|  |  |  |   |















| Model / Details  | Description  | Replaces Ref. No:                                    | TM No.  |
|--|--|--|---|
| 638 VITO<br>638 V-CLASS  | Rubber Bushing, Steering<br>ø14xø41,5x75   | 6383330014   | <b>TM30893</b><br>   |
| 690 SPRINTER<br>901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER<br>905 SPRINTER<br>909 SPRINTER | Rubber Bushing, Steering<br>ø14xø44x80   | 9013330214   | <b>TM30892</b><br>   |
| 396 OH SERIES<br>373 O 302<br>373 O 303<br>600 O 303<br>373 O 304<br>373 O 330<br>600 O 330                  | Shock Absorber, Steering<br>Repl. Sachs: 314 672 /<br>200 341<br>Repl. Monroe: 1300018M<br>M12/ø14x558/878 | 0004636432<br>0004636232<br>0004636132<br>0004635932 | <b>TM05346</b><br>   |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>942 AXOR 2   | Cylinder, Steering   | 0004663492   | <b>TM05424</b><br> |
| 638 VITO<br>638 V-CLASS  | Repair Kit, Steering   | 6384602900S<br>6384602100S<br>6384600600             | <b>TM37196</b><br> |
| 690 SPRINTER<br>901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER                                 | Repair Kit, Steering   | 9014604100S  | <b>TM37197</b><br> |
| 970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>970 ATEGO 2<br>972 ATEGO 2<br>974 ATEGO 2                | Repair Kit, Steering<br>ø28xø40x8 / NBR  | 0149976947<br>0119977246                             | <b>TM37198</b><br> |












| TM No.  | Replaces Ref. No:                                    | Description            | Model / Details  |
|---|--|------------------------|--|
| <b>TM37199</b><br>   | 6743560226<br>070852060000                           | Nut, Steering          | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 |
| <b>TM05570</b><br>   | 9014605500   | Bellow, Steering       | 690 SPRINTER<br>901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER<br>909 SPRINTER<br>638 VITO   |
| <b>TM37200</b><br>   | 9014620396   | Bellow, Steering       | 690 SPRINTER<br>901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER<br>638 VITO<br>638 V-CLASS    |
| <b>TM05135</b><br> | 9064600096   | Bellow, Steering       | 900 SPRINTER<br>906 SPRINTER   |
| <b>TM37201</b><br> | 9064660924   | Pipe, Steering         | 906 SPRINTER   |
| <b>TM37202</b><br> | 0004600057<br>0004600157<br>3164600057<br>3164600157 | Joint, Steering Column | 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>375 ATEGO<br>970 ATEGO               |
| <b>TM11707</b><br> | 0005459508   | Steering Lock          | 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>375 ATEGO<br>970 ATEGO               |










| Model / Details  | Description               | Replaces Ref. No:                      | TM No.  |
|--|---------------------------|--|---|
| 699 MK<br>615 NG<br>616 NG<br>617 NG<br>619 NG<br>620 NG<br>621 NG                           | Steering Lock<br>With Key | 0014621130<br>3504607004               | <b>TM05352</b><br>   |
| 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>375 ATEGO<br>970 ATEGO | Steering Lock<br>With Key | 9424600004<br>9434600004               | <b>TM05376</b><br>   |
| 675 LK/LN2<br>676 LK/LN2<br>677 LK/LN2<br>679 LK/LN2   | Drag Link<br>L: 780 mm    | 6764601105<br>6764601505<br>6764600105 | <b>TM05456</b><br>   |
| 617 NG<br>619 NG   | Drag Link<br>L: 780 mm    | 6194602505<br>6194602905<br>6194605205 | <b>TM05397</b><br> |
| 675 LK/LN2<br>676 LK/LN2<br>677 LK/LN2<br>678 LK/LN2   | Drag Link<br>L: 780 mm    | 6754602205<br>6754601005<br>6754602805 | <b>TM05455</b><br> |
| 387 NG<br>389 NG<br>395 NG<br>620 NG<br>621 NG<br>622 NG<br>623 NG                           | Drag Link<br>L: 885 mm    | 6204602805<br>6204600005<br>6204603705 | <b>TM05355</b><br> |
| 650 MK<br>651 MK<br>652 MK<br>387 NG<br>389 NG<br>391 NG<br>393 NG                           | Drag Link<br>L : 865 mm   | 3874603205<br>3874603305<br>3874601405 | <b>TM05340</b><br> |












| TM No.  | Replaces Ref. No: | Description | Model / Details |
|---|-------------------|-------------|-----------------|
| <b>TM37203</b><br>   | 3434601405        | Drag Link   | 343 T2/L        |
|   | 3434601005        | L : 760 mm  | 343 T2/LN1      |
|   | 3434601205        |             | 346 L 1924      |
|   |                   |             | 346 L 1928      |
|   |                   |             | 346 LA 1924     |
|   |                   |             | 346 LAK 1924    |
|   |                   |             | 346 LAS 1924    |
| <b>TM05418</b><br>   | 6204602905        | Drag Link   | 621 NG          |
|   | 6204603005        | L : 865 mm  | 624 NG          |
|   | 6204600405        |             | 646 NG          |
|   |                   |             | 649 NG          |
|   |                   |             | 655 SK          |
|   |                   |             | 656 SK          |
|   |                   |             | 659 SK          |
| <b>TM05428</b><br>   | 6754602405        | Drag Link   | 675 LK/LN2      |
|   | 6754601205        | L : 717 mm  | 676 LK/LN2      |
|   | 6754603005        |             | 677 LK/LN2      |
|   |                   |             |                 |
| <b>TM05432</b><br> | 6684600905        | Drag Link   | BM MODEL        |
|   | 6684600505        | L : 505 mm  | 668 T2/LN1      |
|   | 6684601105        |             | 669 T2/LN1      |
|   |                   |             |                 |
| <b>TM04981</b><br> | 6734600605        | Drag Link   | 673 LK/LN2      |
|   | 6734600205        | L : 730 mm  | 674 LK/LN2      |
|   | 6734600405        |             | 676 LK/LN2      |
|   |                   |             |                 |
| <b>TM30459</b><br> | 3933300303        | Drag Link   | 950 ACTROS      |
|   | 3933300003        | L : 1620 mm | 930 ACTROS 2/3  |
|   | 3933300403        |             | 940 AXOR 2      |
|   |                   |             | 650 MK          |
|   |                   |             | 651 MK          |
|   |                   |             | 652 MK          |
|   |                   |             | 653 MK          |
| <b>TM05431</b><br> | 6174602805        | Drag Link   | 615 NG          |
|   | 6174600005        | L : 870 mm  | 616 NG          |
|   | 6174600205        |             | 617 NG          |
|   |                   |             | 619 NG          |



| Model / Details  | Description              | Replaces Ref. No:                      | TM No.  |
|--|--------------------------|--|---|
| 300 O 303<br>301 O 303<br>373 O 303<br>600 O 303<br>373 O 304<br>373 O 330<br>600 O 330                          | Drag Link<br>L : 1145 mm | 3004600405<br>3014600505<br>3004600505 | <b>TM05425</b><br>   |
| 300 O 303<br>301 O 303<br>600 O 303<br>307 O 305<br>307 O 307<br>698 BH 3-N<br>698 BH 4-23                       | Drag Link<br>L : 975 mm  | 3004600605<br>3054600305<br>3004600705 | <b>TM05395</b><br>   |
| 611 T1/TN<br>601 207 D/208 D<br>601 208/210<br>601 209 D/210 D<br>602 307 D/308 D<br>602 307 D/308D<br>602 308 D | Drag Link<br>L : 470 mm  | 6014601505<br>6014601305<br>6014600905 | <b>TM05478</b><br>  |
| 670 T2/LN1   | Drag Link<br>L : 495 mm  | 6704602805<br>6704602905               | <b>TM37204</b><br> |
| 950 ACTROS<br>950 AXOR 2<br>625 SK<br>659 SK   | Drag Link<br>L : 1565 mm | 9423300503<br>6253302603<br>6253302003 | <b>TM30556</b><br> |
| 398 LO 814<br>688 1114<br>688 709<br>688 912<br>688 913<br>688 914<br>688 L 710                                  | Drag Link<br>L : 1594 mm | 6703300203<br>6703300303<br>6703300103 | <b>TM30770</b><br> |
| 396 OH SERIES<br>357 O 405<br>612 O 405<br>357 O 407<br>612 O 407<br>357 O 408<br>612 O 408                      | Drag Link<br>L : 988 mm  | 3574601005<br>3574600405<br>3574601105 | <b>TM05392</b><br> |












| TM No.  | Replaces Ref. No: | Description | Model / Details |
|---|-------------------|-------------|-----------------|
| <b>TM30469</b><br>   | 9453300003        | Drag Link   | 950 ACTROS      |
|   | 9453300603        | L : 1735 mm | 954 ACTROS      |
|   | 9453300103        |             | 930 ACTROS 2/3  |
|   |                   |             | 934 ACTROS 2/3  |
|   |                   |             | 950 AXOR 2      |
|   |                   |             | 957 ECONIC      |
| <b>TM37205</b><br>   | 6704600905        | Drag Link   | 668 T2/LN1      |
|   | 6704601805        | L : 505 mm  | 669 T2/LN1      |
|   | 6704602205        |             | 670 T2/LN1      |
|   |                   |             |                 |
| <b>TM05390</b><br>   | 0014600305        | Drag Link   | 651 MK          |
|   | 0014600405        | L : 840 mm  | 652 MK          |
|   |                   |             | 653 MK          |
| <b>TM05385</b><br> | 0024604305        | Drag Link   | 950 ACTROS      |
|   | 0024604405        | L : 834 mm  | 952 ACTROS      |
|   | 0034604805        |             | 953 ACTROS      |
|   |                   |             | 954 ACTROS      |
|   |                   |             | 930 ACTROS 2/3  |
|   |                   |             | 932 ACTROS 2/3  |
|   |                   |             | 933 ACTROS 2/3  |
| <b>TM05394</b><br> | 3834604405        | Drag Link   | 380 NG          |
|   | 3834601405        | L : 890 mm  | 381 NG          |
|   | 3834600605        |             | 383 NG          |
|   |                   |             | 385 NG          |
| <b>TM05398</b><br> | 0014602905        | Drag Link   | 651 MK          |
|   | 0014603005        | L : 840 mm  | 652 MK          |
|   |                   |             | 653 MK          |
| <b>TM37209</b><br> | 6704602605        | Drag Link   | 670 T2/LN1      |
|   | 6704602705        | L : 495 mm  |                 |
|   |                   |             |                 |












| Model / Details  | Description              | Replaces Ref. No:                      | TM No.  |
|--|--------------------------|--|---|
| 357 O 405<br>612 O 405<br>698 BGT-25<br>698 BGU-25<br>698 BU 5-25  | Drag Link<br>L : 1066 mm | 3574601505<br>3574601405               | <b>TM05391</b><br>   |
| 375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>375 ATEGO 2<br>970 ATEGO 2<br>972 ATEGO 2              | Drag Link<br>L : 1607 mm | 9753300203<br>9753301703<br>9753300303 | <b>TM30307</b><br>   |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 | Drag Link<br>L : 1735 mm | 9413300103<br>9413300203<br>9413300303 | <b>TM30721</b><br>  |
| 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3     | Drag Link<br>L : 1730 mm | 9423300003<br>9423300703<br>9423301103 | <b>TM30718</b><br> |
| 307 O 305<br>307 O 307<br>357 O 407<br>612 O 407<br>357 O 408<br>612 O 408                                 | Drag Link<br>L : 1115 mm | 3574601205<br>3054600605<br>3574601305 | <b>TM37211</b><br> |
| 970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>970 ATEGO 2<br>972 ATEGO 2<br>975 ATEGO 2<br>976 ATEGO 2            | Drag Link<br>L : 1640 mm | 9703300003<br>9703300103<br>9703300203 | <b>TM30287</b><br> |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 | Drag Link<br>L : 1615 mm | 9423300803<br>9493300903<br>9493300203 | <b>TM30683</b><br> |












| TM No.  | Replaces Ref. No: | Description | Model / Details |
|---|-------------------|-------------|-----------------|
| <b>TM30742</b><br>   | 6253301203        | Drag Link   | 950 ACTROS      |
|   | 6253300903        | L : 1575 mm | 952 ACTROS      |
|   | 9443300203        |             | 954 ACTROS      |
|   |                   |             | 934 ACTROS 2/3  |
|   |                   |             | 950 AXOR 2      |
|   |                   |             | 952 AXOR 2      |
|   |                   |             | 624 NG          |
| <b>TM05446</b><br>   | 0004609305        | Drag Link   | 950 ACTROS      |
|   | 0014606905        | L : 870 mm  | 954 ACTROS      |
|   | 0004609205        |             |                 |
|   |                   |             |                 |
| <b>TM05433</b><br>   | 0004609505        | Drag Link   | 950 ACTROS      |
|   | 0014607105        | L : 900 mm  | 952 ACTROS      |
|   | 0004609405        |             | 953 ACTROS      |
|   |                   |             | 930 ACTROS 2/3  |
|   |                   |             | 932 ACTROS 2/3  |
|   |                   |             | 933 ACTROS 2/3  |
| <b>TM37213</b><br> | 0004600705        | Drag Link   | -               |
|   |                   | L : 885 mm  |                 |
| <b>TM05450</b><br> | 0014609005        | Drag Link   | 950 ACTROS      |
|   | 0014609105        | L : 1558 mm | 930 ACTROS 2/3  |
|   |                   |             | 950 AXOR 2      |
| <b>TM05498</b><br> | 6174603405        | Drag Link   | 615 LK/LN2      |
|   | 6174602005        | L : 850 mm  | 650 MK          |
|   | 6174602405        |             | 651 MK          |
|   |                   |             | 652 MK          |
|   |                   |             | 615 NG          |
|   |                   |             | 616 NG          |
|   |                   |             | 617 NG          |
| <b>TM04995</b><br> | 6254602505        | Drag Link   | 625 NG          |
|   |                   | L : 870 mm  | 625 SK          |
|   |                   |             | 655 SK          |
|   |                   |             | 656 SK          |
|   |                   |             | 658 SK          |










| Model / Details  | Description              | Replaces Ref. No:                      | TM No.  |
|--|--------------------------|--|---|
| 675 LK/LN2<br>676 LK/LN2<br>677 LK/LN2<br>679 LK/LN2                                   | Drag Link<br>L : 788 mm  | 6764603105<br>6764601905<br>6764602105 | <b>TM05463</b><br>   |
| 972 ATEGO<br>970 ATEGO 2<br>976 ATEGO 2  | Drag Link<br>L : 883 mm  | 9724601105<br>9724601305               | <b>TM37214</b><br>   |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS                                   | Drag Link<br>L : 877 mm  | 0004607105<br>0014606705<br>0004607205 | <b>TM05384</b><br>  |
| 353 T2/L<br>615 LK/LN2<br>650 MK<br>615 NG<br>616 NG<br>617 NG<br>684 1521AK INDONESIA | Drag Link<br>L : 1635 mm | 3853301603<br>3853300803<br>3853301803 | <b>TM30788</b><br> |
| 387 NG<br>389 NG<br>391 NG<br>393 NG<br>395 NG   | Drag Link<br>L : 865 mm  | 3874604405<br>3874600605<br>3874604505 | <b>TM05354</b><br> |
| 970 ATEGO 2<br>972 ATEGO 2<br>976 ATEGO 2  | Drag Link<br>L : 840 mm  | 9704600705<br>9704600905<br>9704601105 | <b>TM05426</b><br> |
| 970 ATEGO 2<br>972 ATEGO 2<br>976 ATEGO 2  | Drag Link<br>L : 847 mm  | 9704600805<br>9704601005<br>9704601205 | <b>TM05452</b><br> |












| TM No.  | Replaces Ref. No: | Description | Model / Details  |
|---|-------------------|-------------|--|
| <b>TM05414</b><br>   | 9724601405        | Drag Link   | 970 ATEGO  |
|   | 9724601605        | L : 836 mm  | 972 ATEGO<br>975 ATEGO<br>970 ATEGO 2<br>972 ATEGO 2<br>975 ATEGO 2                          |
| <b>TM05388</b><br>   | 0024604705        | Drag Link   | 950 ACTROS   |
|   | 0024604805        | L : 863 mm  | 952 ACTROS   |
|   | 0034604905        |             | 953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3               |
| <b>TM05393</b><br>   | 0004609805        | Drag Link   | 655 SK   |
|   | 0004609905        | L : 900 mm  | 656 SK<br>658 SK<br>659 SK<br>397 2435 S/6X4<br>397 2545 S/6X4<br>397 25XX S/6X4             |
| <b>TM30326</b><br> | 9493301003        | Drag Link   | 950 ACTROS   |
|   | 9493301703        | L : 1580 mm | 952 ACTROS   |
|   | 9493301103        |             | 953 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3           |
| <b>TM30722</b><br> | 9443301703        | Drag Link   | 950 ACTROS   |
|   | 6253303203        | L : 1588 mm | 952 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>934 ACTROS 2/3<br>950 AXOR 2 |
| <b>TM37215</b><br> | 3734601005        | Drag Link   | 373 O 302  |
|   |                   | L : 980 mm  | 373 O 303<br>373 O 304<br>373 O 330<br>600 O 330<br>600 O 340                                |
| <b>TM37216</b><br> | 3563300003        | Drag Link   | 356 O 404  |
|   | 6133300003        | L : 697 mm  | 613 TOURISMO<br>698 BH 4<br>698 BH 4-N   |



| Model / Details  | Description              | Replaces Ref. No:                      | TM No.  |
|--|--------------------------|--|---|
| 356 O 404<br>613 TOURISMO  | Drag Link<br>L : 506 mm  | 3563300103<br>6133300103               | <b>TM30285</b><br>   |
| 356 O 404<br>613 TOURISMO  | Drag Link<br>L : 1700 mm | 3564630015<br>6134630015               | <b>TM05434</b><br>   |
| 375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>375 ATEGO 2<br>970 ATEGO 2<br>974 ATEGO 2                          | Drag Link<br>L : 885 mm  | 9744601005<br>9744601205<br>0034604605 | <b>TM05453</b><br>  |
| 972 ATEGO<br>976 ATEGO<br>958 ATEGO 2<br>970 ATEGO 2<br>972 ATEGO 2<br>976 ATEGO 2                                     | Drag Link<br>L : 890 mm  | 9744602205<br>9744600405<br>9744600805 | <b>TM05454</b><br> |
| 972 ATEGO<br>970 ATEGO 2<br>976 ATEGO 2  | Drag Link<br>L : 873 mm  | 9724601005<br>9724601205               | <b>TM37217</b><br> |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3             | Drag Link<br>L : 1687 mm | 9493301603<br>9493300603<br>9493300703 | <b>TM30470</b><br> |
| BM MODEL<br>950 ACTROS<br>952 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>934 ACTROS 2/3<br>950 AXOR 2 | Drag Link<br>L : 1588 mm | 9443300503<br>3463304903<br>3463303903 | <b>TM30820</b><br> |












| TM No.  | Replaces Ref. No: | Description | Model / Details |
|---|-------------------|-------------|-----------------|
| <b>TM30719</b><br>   | 9493301203        | Drag Link   | 950 ACTROS      |
|   | 9493301803        | L : 1532 mm | 952 ACTROS      |
|   | 9493301303        |             | 953 ACTROS      |
|   |                   |             | 954 ACTROS      |
|   |                   |             | 930 ACTROS 2/3  |
|   |                   |             | 932 ACTROS 2/3  |
|   |                   |             | 933 ACTROS 2/3  |
| <b>TM30724</b><br>   | 9453300203        | Drag Link   | 950 ACTROS      |
|   | 9453300303        | L : 1465 mm | 954 ACTROS      |
|   | 9453300503        |             | 930 ACTROS 2/3  |
|   |                   |             | 934 ACTROS 2/3  |
|   |                   |             | 950 AXOR 2      |
|   |                   |             | 957 ECONIC      |
| <b>TM05448</b><br>   | 0024601205        | Drag Link   | 950 ACTROS      |
|   | 0014606105        | L : 1862 mm | 954 ACTROS      |
|   | 0014606205        |             | 930 ACTROS 2/3  |
|   |                   |             | 950 AXOR 2      |
| <b>TM05449</b><br> | 0024601305        | Drag Link   | 950 ACTROS      |
|   | 0014608905        | L : 1255 mm | 930 ACTROS 2/3  |
|   |                   |             | 950 AXOR 2      |
|   |                   |             |                 |
| <b>TM05429</b><br> | 0014601305        | Drag Link   | 950 ACTROS      |
|   | 0024600505        | L : 1095 mm | 952 ACTROS      |
|   | 0034603205        |             | 953 ACTROS      |
|   | 3754601505        |             | 930 ACTROS 2/3  |
|   |                   |             | 932 ACTROS 2/3  |
|   |                   |             | 933 ACTROS 2/3  |
|   |                   |             | 942 AXOR 2      |
| <b>TM05447</b><br> | 0014608605        | Drag Link   | 950 ACTROS      |
|   | 0014608705        | L : 954 mm  | 930 ACTROS 2/3  |
|   |                   |             | 950 AXOR        |
|   |                   |             |                 |
| <b>TM05444</b><br> | 0014605105        | Drag Link   | 950 ACTROS      |
|   | 0014608105        | L : 909 mm  | 930 ACTROS 2/3  |
|   |                   |             |                 |
|   |                   |             |                 |



















| Model / Details  | Description              | Replaces Ref. No:                      | TM No.  |
|--|--------------------------|--|---|
| 952 ACTROS<br>932 ACTROS 2/3   | Drag Link<br>L : 887 mm  | 0014604905<br>0014607405               | <b>TM05095</b><br>   |
| 950 ACTROS<br>952 ACTROS<br>954 ACTROS   | Drag Link<br>L : 888 mm  | 0014600705<br>0014607005<br>0014600805 | <b>TM05387</b><br>   |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 | Drag Link<br>L : 885 mm  | 0024605105<br>0024605205<br>0034604005 | <b>TM05012</b><br>  |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS   | Drag Link<br>L : 866 mm  | 0014609805<br>0014609905<br>0024606305 | <b>TM05386</b><br> |
| 952 ACTROS<br>932 ACTROS 2/3   | Drag Link<br>L : 708 mm  | 0024600605<br>0014605305               | <b>TM05460</b><br> |
| 615 LK/LN2<br>650 MK<br>651 MK<br>652 MK<br>615 NG<br>616 NG<br>617 NG                                     | Drag Link<br>L : 1635 mm | 3853302103<br>3853301303<br>3853302203 | <b>TM30332</b><br> |
| 357 O 405<br>612 O 405<br>698 BGT-N  | Drag Link<br>L : 1066 mm | 3574602305<br>3574602005               | <b>TM05718</b><br> |












| TM No.  | Replaces Ref. No: | Description | Model / Details |
|---|-------------------|-------------|-----------------|
| <b>TM04998</b><br>   | 0024604505        | Drag Link   | 375 ACTROS      |
|   | 0024604605        | L : 890 mm  | 950 ACTROS      |
|   | 3754600405        |             | 952 ACTROS      |
|   |                   |             | 953 ACTROS      |
|   |                   |             | 954 ACTROS      |
|   |                   |             | 930 ACTROS 2/3  |
|   |                   |             | 932 ACTROS 2/3  |
| <b>TM27557</b><br>   | 0003200132        | Drag Link   | 634 TOURO       |
|   | 0003201132        | Right       | 633 INTEGRO     |
|   | 0003200532        | L : 148 mm  | 633 INTOURO     |
|   | 0003200832        |             | 632 TOURISMO    |
|   |                   |             | 629 TRAVEGO     |
|   |                   |             | 632 TRAVEGO     |
|   |                   |             | 629 SETRA       |
| <b>TM27932</b><br>  | 0003200232        | Drag Link   | 634 TOURO       |
|   | 0003201032        | Left        | 633 INTEGRO     |
|   | 0003200632        | L : 148 mm  | 633 INTOURO     |
|   | 0003200932        |             | 632 TOURISMO    |
|   |                   |             | 629 TRAVEGO     |
|   |                   |             | 632 TRAVEGO     |
|   |                   |             | 629 SETRA       |
| <b>TM30781</b><br> | 6293300003        | Drag Link   | 633 INTEGRO     |
|   | 6293300603        | L : 880 mm  | 633 INTOURO     |
|   | 6323300103        |             | 632 TOURISMO    |
|   |                   |             | 629 TRAVEGO     |
|   |                   |             | 632 TRAVEGO     |
|   |                   |             | 629 SETRA       |
|   |                   |             | 632 SETRA       |
| <b>TM05047</b><br> | 0024609605        | Drag Link   | 934 ACTROS 2/3  |
|   | 0024609705        | L : 850 mm  |                 |
|   | 0034605705        |             |                 |
| <b>TM27927</b><br> | 6283200389        | Drag Link   | 628 CITARO      |
|   | 6283201389        | Right       | 671 CONECTO     |
|   |                   | L : 260 mm  |                 |
| <b>TM27926</b><br> | 6283200189        | Drag Link   | 628 CITARO      |
|   | 6283201289        | Left        | 671 CONECTO     |
|   |                   | L : 260 mm  |                 |



| Model / Details   | Description             | Replaces Ref. No:                                    | TM No.  |
|---|-------------------------|--|---|
| 634 TOURO<br>633 INTEGRO<br>633 INTOURO<br>632 TOURISMO<br>629 TRAVEGO<br>632 TRAVEGO<br>410 SETRA        | Drag Link<br>L : 197 mm | 6293200189<br>6323200232<br>0003201232<br>6283201489 | <b>TM27913</b><br>   |
| 375 AXOR<br>375 AXOR 2<br>940 AXOR 2<br>942 AXOR 2<br>943 AXOR 2  | Drag Link<br>L : 890 mm | 3754600605<br>3754601105                             | <b>TM05085</b><br>   |
| 375 ATEGO   | Drag Link<br>L : 894 mm | 3754600305<br>9724601805<br>9724602005               | <b>TM05427</b><br>   |
| 667 VARIO<br>668 VARIO<br>670 VARIO   | Drag Link<br>L : 504 mm | 6674601505<br>6674601705                             | <b>TM05011</b><br> |
| 950 AXOR 2  | Drag Link<br>L : 927 mm | 0024602405<br>0024603005                             | <b>TM05451</b><br> |
| 628 CITARO<br>628 CONECTO   | Drag Link<br>L : 928 mm | 6284601205<br>6284600305                             | <b>TM05443</b><br> |
| 50 ACTROS<br>952 ACTROS<br>953 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>942 AXOR 2 | Drag Link<br>L : 715 mm | 0014601505<br>0014607305<br>0034603305               | <b>TM05071</b><br> |












| TM No.  | Replaces Ref. No: | Description                     | Model / Details           |
|---|-------------------|---------------------------------|---------------------------|
| <b>TM30682</b><br>   | 9423300303        | Drag Link<br>L : 1664 mm        | 950 ACTROS                |
|   | 9423300403        |                                 | 952 ACTROS                |
|   | 9423301603        |                                 | 953 ACTROS                |
|   |                   |                                 | 954 ACTROS                |
|   |                   |                                 | 930 ACTROS 2/3            |
|   |                   |                                 | 932 ACTROS 2/3            |
|   |                   |                                 | 933 ACTROS 2/3            |
| <b>TM30321</b><br>   | 9493300403        | Drag Link<br>L : 1690 mm        | 950 ACTROS                |
|   | 9493300803        |                                 | 953 ACTROS                |
|   | 9493300503        |                                 | 930 ACTROS 2/3            |
|   | 9493301403        |                                 | 932 ACTROS 2/3            |
|   |                   |                                 | 933 ACTROS 2/3            |
|   |                   |                                 | 934 ACTROS 2/3            |
|   |                   |                                 | 942 AXOR 2                |
| <b>TM04985</b><br>   | 0024604905        | Drag Link<br>L : 885 mm         | 375 AXOR                  |
|   | 0024605005        |                                 | 374 AXOR 2                |
|   | 0034605605        |                                 | 940 AXOR 2                |
|   |                   |                                 | 944 AXOR 2                |
|   |                   |                                 | 950 AXOR 2                |
|   |                   |                                 | 952 AXOR 2                |
|   |                   |                                 | 953 AXOR 2                |
| <b>TM05416</b><br> | 0024606105        | Drag Link<br>L : 950 mm         | 950 ACTROS                |
|   | 0034604205        |                                 | 952 ACTROS                |
|   | 0024606205        |                                 | 953 ACTROS                |
|   |                   |                                 | 954 ACTROS                |
|   |                   |                                 | 930 ACTROS 2/3            |
|   |                   |                                 | 932 ACTROS 2/3            |
|   |                   |                                 | 933 ACTROS 2/3            |
| <b>TM05502</b><br> | 6704602005        | Drag Link<br>L : 505 mm         | 670 T2/LN1                |
|   | 6704600805        |                                 |                           |
|   | 6704601605        |                                 |                           |
| <b>TM37219</b><br> | 6714600305        | Drag Link<br>L : 925 mm         | 671 CONECTO               |
|   | 6714600105        |                                 | 671 O 345                 |
|   | 3574603205        |                                 |                           |
| <b>TM27900</b><br> | 6343230416        | Drag Link<br>Left<br>L : 375 mm | 382 OH SERIES             |
|   | 6343230216        |                                 | 382 O 500                 |
|   |                   |                                 | 382 O 500 M / 1725        |
|   |                   |                                 | 382 O 500 M / 1725 / 1726 |
|   |                   |                                 | 382 O 500 M / 1728        |
|   |                   | 382 O 500 R / 1830 / 30         |                           |
|   |                   | 634 O 500                       |                           |



| Model / Details   | Description                      | Replaces Ref. No:                      | TM No.  |
|---|----------------------------------|--|---|
| 382 OH SERIES<br>382 O 500<br>382 O 500 M / 1725<br>382 O 500 M / 1725 / 1726<br>382 O 500 M / 1728<br>382 O 500 R / 1830 / 30<br>634 O 500 | Drag Link<br>Right<br>L : 375 mm | 6343230516<br>6343230316               | <b>TM27893</b><br>   |
| 952 ACTROS<br>932 ACTROS 2/3  | Drag Link<br>L : 1057 mm         | 0034603405<br>0014605505<br>0024600705 | <b>TM05430</b><br>   |
| 952 ACTROS<br>932 ACTROS 2/3  | Drag Link<br>L : 955 mm          | 0024609405<br>0024609505               | <b>TM05461</b><br>  |
| 952 ACTROS<br>932 ACTROS 2/3  | Drag Link<br>L : 818 mm          | 0014606505<br>0014608405<br>0034603805 | <b>TM05462</b><br> |
| 952 ACTROS<br>932 ACTROS 2/3<br>934 ACTROS 2/3<br>964 AROCS   | Drag Link<br>L : 1520 mm         | 3574603505                             | <b>TM37220</b><br> |
| 690 SPRINTER<br>901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER  | Drag Link<br>L : 385 mm          | 9014600155<br>9014600255<br>9014600455 | <b>TM05480</b><br> |
| 900 SPRINTER<br>906 SPRINTER  | Drag Link<br>Left<br>L : 137 mm  | 9063201789                             | <b>TM27977</b><br> |












| TM No.  | Replaces Ref. No:                      | Description                      | Model / Details  |
|---|--|----------------------------------|--|
| <b>TM27978</b><br>   | 9063201889                             | Drag Link<br>Right<br>L : 137 mm | 900 SPRINTER<br>906 SPRINTER   |
| <b>TM30817</b><br>   | 9064600055<br>9064600155               | Drag Link<br>L : 400 mm          | 900 SPRINTER<br>906 SPRINTER   |
| <b>TM27983</b><br>  | 6383230268                             | Drag Link<br>M10x1,5/ L: 250 mm  | 638 VITO<br>638 V-CLASS  |
| <b>TM27984</b><br> | 6383230368                             | Drag Link<br>M10x1,5/ L: 250 mm  | 638 VITO<br>638 V-CLASS  |
| <b>TM27985</b><br> | 6383230468                             | Drag Link<br>M10x1,5/ L: 230 mm  | 638 VITO<br>638 V-CLASS  |
| <b>TM27986</b><br> | 6383230568                             | Drag Link<br>M10x1,5/ L: 230 mm  | 638 VITO<br>638 V-CLASS  |
| <b>TM05486</b><br> | 0024605905<br>0024606005<br>0034604105 | Drag Link<br>L: 935 mm           | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 |












| Model / Details  | Description              | Replaces Ref. No:                      | TM No.  |
|--|--------------------------|--|---|
| 690 SPRINTER<br>901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER<br>909 SPRINTER               | Drag Link<br>M16x1,5     | 9014600205                             | <b>TM05479</b><br>   |
| 638 VITO<br>638 V-CLASS  | Drag Link<br>M16x1,5     | 6384600205<br>6384600005               | <b>TM05481</b><br>   |
| 636 VIANO<br>639 VIANO   | Drag Link<br>L: 288,8 mm | 6394600255<br>6394600055               | <b>TM30818</b><br>  |
| 612 O 405  | Drag Link<br>L: 1281 mm  | 3574603505<br>9423301003<br>9423301703 | <b>TM37221</b><br> |
| 374 AXOR 2<br>940 AXOR 2<br>944 AXOR 2<br>950 AXOR 2<br>952 AXOR 2<br>953 AXOR 2<br>958 AXOR 2             | Drag Link<br>L: 916 mm   | 0024607705<br>0024607805<br>0034605105 | <b>TM05001</b><br> |
| 963 ACTROS MP4   | Drag Link<br>L: 776 mm   | 0034605505<br>0034607205<br>0034608305 | <b>TM05096</b><br> |
| 952 ACTROS<br>953 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>942 AXOR 2<br>943 AXOR 2 | Drag Link<br>L: 716 mm   | 0024608805<br>0024608905               | <b>TM05402</b><br> |












| TM No.  | Replaces Ref. No: | Description             | Model / Details |
|---|-------------------|-------------------------|-----------------|
| <b>TM05041</b><br>   | 0024608605        | Drag Link<br>L: 883 mm  | 950 ACTROS      |
|   | 0024608705        |                         | 952 ACTROS      |
|   |                   |                         | 953 ACTROS      |
|   |                   |                         | 954 ACTROS      |
|   |                   |                         | 930 ACTROS 2/3  |
|   |                   |                         | 932 ACTROS 2/3  |
|   |                   |                         | 933 ACTROS 2/3  |
| <b>TM05240</b><br>   | 0034607305        | Drag Link<br>L: 773 mm  | 963 ACTROS MP4  |
|   |                   |                         |                 |
| <b>TM27859</b><br>   | 0003220223        | Drag Link<br>L: 1815 mm | 950 ACTROS      |
|   | 0003220523        |                         | 952 ACTROS      |
|   |                   |                         | 953 ACTROS      |
|   |                   |                         | 930 ACTROS 2/3  |
|   |                   |                         | 932 ACTROS 2/3  |
|   |                   |                         | 933 ACTROS 2/3  |
| <b>TM30838</b><br> | 9753300003        | Drag Link<br>L: 1565 mm | 972 ATEGO       |
|   | 9753300403        |                         | 976 ATEGO       |
|   | 9753301003        |                         | 958 ATEGO 2     |
|   |                   |                         | 970 ATEGO 2     |
|   |                   |                         | 972 ATEGO 2     |
|   |                   |                         | 976 ATEGO 2     |
|   |                   |                         | 967 ATEGO 3     |
| <b>TM05075</b><br> | 0034601805        | Drag Link<br>L: 888 mm  | 934 ACTROS 2/3  |
|   | 0034601905        |                         |                 |
|   | 0034605805        |                         |                 |
| <b>TM37222</b><br> | 0024602605        | Drag Link<br>L: 743 mm  | 950 AXOR 2      |
|   | 0024603705        |                         |                 |
| <b>TM05523</b><br> | 0034601405        | Drag Link<br>L: 870 mm  | 964 ACTROS MP4  |
|   |                   |                         |                 |
|   |                   |                         | 964 AROCS       |



| Model / Details  | Description            | Replaces Ref. No:                      | TM No.  |
|--|------------------------|--|---|
| 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3                             | Drag Link<br>L: 711 mm | 0014601105<br>0024600405<br>0034603105 | <b>TM05457</b><br>   |
| 952 ACTROS<br>953 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 | Drag Link<br>L: 953 mm | 0024609205<br>0024609305<br>0034604505 | <b>TM05522</b><br>   |
| 970 ATEGO<br>970 ATEGO 2   | Drag Link<br>L: 875 mm | 9724600605                             | <b>TM37223</b><br>   |
| 655 SK<br>656 SK<br>658 SK   | Drag Link<br>L: 886 mm | 0024601505<br>0024601705<br>0024607505 | <b>TM37224</b><br> |
| 963 ACTROS MP4   | Drag Link<br>L: 801 mm | 0034605405<br>0034608205               | <b>TM37225</b><br> |
| 970 ATEGO<br>970 ATEGO 2   | Drag Link<br>L: 875 mm | 9744600005<br>9744600605               | <b>TM37226</b><br> |
| 972 ATEGO<br>976 ATEGO<br>970 ATEGO 2<br>972 ATEGO 2<br>976 ATEGO 2            | Drag Link<br>L: 884 mm | 9744600505<br>9744600905               | <b>TM37227</b><br> |












| TM No.  | Replaces Ref. No: | Description | Model / Details   |
|---|-------------------|-------------|---|
| <b>TM37229</b><br>   | 0024600205        | Drag Link   | 952 ACTROS  |
|   | 0024600305        | L: 893 mm   | 932 ACTROS 2/3  |
| <b>TM37230</b><br>   | 0024605305        | Drag Link   | 374 AXOR 2  |
|   | 0024605405        | L: 905 mm   | 950 AXOR 2<br>952 AXOR 2  |
| <b>TM28005</b><br>   | 9603263205        | Drag Link   | 963 ACTROS MP4  |
|   | 9603263247        | L: 350 mm   | 964 ACTROS MP4<br>964 ANTOS<br>964 AROCS                              |
| <b>TM37231</b><br> | 9603262947        | Drag Link   | 963 ACTROS MP4  |
|   |                   | L: 260 mm   |   |
| <b>TM37232</b><br> | 9724600705        | Drag Link   | 970 ATEGO   |
|   | 9724600905        | L: 875 mm   | 970 ATEGO 2   |
| <b>TM05550</b><br> | 0004608505        | Drag Link   | 950 ACTROS  |
|   | 0024601005        | L: 2070 mm  | 954 ACTROS  |
|   | 0034602905        |             | 934 ACTROS 2/3  |
| <b>TM05476</b><br> | 0034606005        | Drag Link   | 970 ATEGO   |
|   | 9724601905        | L: 895 mm   | 972 ATEGO   |
|   | 9724602105        |             | 975 ATEGO<br>970 ATEGO 2<br>972 ATEGO 2<br>974 ATEGO 2<br>975 ATEGO 2 |



| Model / Details  | Description             | Replaces Ref. No:                      | TM No.  |
|--|-------------------------|--|---|
| 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS             | Drag Link<br>L: 1680 mm | 9603302403<br>9603302503<br>9603303003 | <b>TM30334</b><br>   |
| 952 ACTROS<br>932 ACTROS 2/3   | Drag Link<br>L: 773 mm  | 0014605705<br>0034603505               | <b>TM05484</b><br>   |
| 964 AROCS  | Drag Link<br>L: 830 mm  | 0034607705                             | <b>TM37233</b><br>   |
| 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS             | Drag Link<br>L: 1660 mm | 9603301103<br>9603300803<br>9603303103 | <b>TM37234</b><br> |
| 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS             | Drag Link<br>L: 1636 mm | 9603300703<br>9603301003               | <b>TM37235</b><br> |
| 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS             | Drag Link<br>L: 1685 mm | 9603300403<br>9603300503               | <b>TM37236</b><br> |
| BM MODEL<br>963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS | Drag Link<br>L: 860 mm  | 0034607805<br>9604630915               | <b>TM05234</b><br> |












| TM No.  | Replaces Ref. No:        | Description             | Model / Details  |
|---|--------------------------|-------------------------|--|
| <b>TM05199</b><br>   | 0034605305<br>0034608105 | Drag Link<br>L: 783 mm  | 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS |
| <b>TM37237</b><br>   | 0034607905<br>9604630615 | Drag Link<br>L: 772 mm  | 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS |
| <b>TM05233</b><br>  | 0034608005<br>9604630815 | Drag Link<br>L: 999 mm  | 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS |
| <b>TM37238</b><br> | 0034607505               | Drag Link<br>L: 865 mm  | 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS |
| <b>TM37239</b><br> | 0034601505               | Drag Link<br>L: 863 mm  | 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS |
| <b>TM37240</b><br> | 9753301403               | Drag Link<br>L: 1540 mm | 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS |
| <b>TM30466</b><br> | 9603300103               | Drag Link<br>L: 1685 mm | 963 ACTROS MP4<br>964 AROCS                                |





| Model / Details  | Description                       | Replaces Ref. No:                                    | TM No.  |
|--|-----------------------------------|--|---|
| 964 AROCS  | Drag Link<br>L: 1000 mm           | 9604631215   | <b>TM37241</b><br>   |
| 963 ACTROS MP4<br>964 AROCS  | Drag Link<br>L: 1320 mm           | 9603900107   | <b>TM30328</b><br>   |
| -  | Drag Link                         | 6384600055<br>6384600255                             | <b>TM37242</b><br>   |
| 639 VIANO  | Drag Link<br>Left                 | 6393200089<br>6393200289<br>6393200489               | <b>TM27981</b><br> |
| 639 VIANO  | Drag Link<br>Right                | 6393200189<br>6393200389<br>6393200589               | <b>TM27982</b><br> |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 | Ball Joint<br>M30x1,5 R / L : 125 | 0014607748<br>0014600248<br>0014602248<br>0014600848 | <b>TM04973</b><br> |
| 950 ACTROS<br>952 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>934 ACTROS 2/3<br>375 ATEGO<br>970 ATEGO       | Ball Joint<br>M30x1,5 L / L : 125 | 0014603648<br>0014607848<br>0014602348<br>0014601448 | <b>TM05105</b><br> |









| TM No.  | Replaces Ref. No: | Description         | Model / Details    |
|---|-------------------|---------------------|--------------------|
| <b>TM05368</b><br>   | 0004602648        | Ball Joint          | 336 LP 1924        |
|   | 0004600148        | M30x1,5 R / L : 125 | 336 LPS 1924       |
|   | 0004602748        |                     | 343 T2/LN1         |
|   | 0014607448        |                     | 346 L 1924         |
|   |                   |                     | 346 LA 1924        |
|   |                   |                     | 346 LAK 1924       |
|   |                   |                     | 346 LAS 1924       |
| <b>TM04976</b><br>   | 0013300135        | Ball Joint          | 972 ATEGO          |
|   | 0004633429        | M30x1,5 R / L : 115 | 970 ATEGO 2        |
|   | 0003300248        |                     | 976 ATEGO 2        |
|   | 0004632229        |                     | 336 LP 1924        |
|   |                   |                     | 336 LPS 1924       |
|   |                   |                     | 341 L 1114         |
|   |                   |                     | 341 L 914          |
| <b>TM05145</b><br>  | 3023300235        | Ball Joint          | 336 LP 1924        |
|   | 3023300035        | M30x1,5 L / L : 115 | 336 LPS 1924       |
|   | 0003300148        |                     | 341 L 1114         |
|   | 3503307135        |                     | 341 L 914          |
|   |                   |                     | 341 LK 1114        |
|   |                   |                     | 341 LO 1114        |
|   |                   |                     | 341 LS 1114        |
| <b>TM04974</b><br> | 0023301335        | Ball Joint          | 353 LP             |
|   | 0003309735        | M24x1,5 R / L : 105 | 353 T2/L           |
|   | 0003301235        |                     | 358 L 1113 B       |
|   | 0003309935        |                     | 358 L 1113 B MBSA  |
|   |                   |                     | 358 LF 1113 B      |
|   |                   |                     | 358 LK 1113 B      |
|   |                   |                     | 358 LK 1113 B MBSA |
| <b>TM05924</b><br> | 0003309835        | Ball Joint          | 328 T2/L           |
|   | 0003301335        | M24x1,5 L / L : 105 | 353 LP             |
|   | 0013300035        |                     | 353 T2/L           |
|   | 0003307635        |                     | 358 L 1113 B       |
|   |                   |                     | 358 L 1113 B MBSA  |
|   |                   |                     | 358 LF 1113 B      |
|   |                   |                     | 358 LK 1113 B      |
| <b>TM05408</b><br> | 0013301835        | Ball Joint          | 621 NG             |
|   |                   | M38x1,5 R / L : 125 | 623 NG             |
|   |                   |                     | 624 NG             |
|   |                   |                     | 625 NG             |
|   |                   |                     | 648 NG             |
|   |                   |                     | 649 NG             |
|   |                   |                     | 625 SK             |
| <b>TM05350</b><br> | 0003308535        | Ball Joint          | 314 LP             |
|   | 0003300635        | M24x1,5 R / L : 95  | 316 LP             |
|   | 0003382410        |                     | 318 LP             |
|   | 0004633229        |                     | 328 T2/L           |
|   |                   |                     | 353 LP             |
|   |                   |                     | 353 T2/L           |
|   |                   |                     | 673 LK/LN2         |



| Model / Details  | Description                       | Replaces Ref. No:                                    | TM No.   |
|--|-----------------------------------|--|--|
| 625 SK   | Ball Joint<br>M26x1,5 R / L : 96  | 0004604948<br>0004634629<br>0024604948               | TM05049<br>   |
| 314 LP<br>668 T2/LN1<br>669 T2/LN1   | Ball Joint<br>M24x1,5 R / L : 95  | 0013301435<br>0003381610<br>0013301235<br>0003301035 | TM37206<br>   |
| 308 L 608 E,L 708 E<br>308 L/LO 608 D<br>308 LO 608 D,LO 708 D/E<br>309 T2/L<br>309 TL2/L<br>310 LF 508 D/LF 608 D<br>310 T2/L | Ball Joint<br>M24x1,5 L / L : 160 | 0013300835<br>0003302635<br>0013301035<br>0003306935 | TM37243<br>   |
| 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3                         | Ball Joint<br>M30x1,5 R / L : 125 | 0014607648<br>0014601748<br>0014600448<br>0004606848 | TM05370<br> |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3                     | Ball Joint<br>M30x1,5 L / L : 125 | 0014607948<br>0014600548<br>0004606948<br>0004605848 | TM05371<br> |
| 314 LP<br>316 LP<br>318 LP<br>352 LA 1313<br>352 LAK 1313<br>352 LAKO 1313<br>352 LAS 1313                                     | Ball Joint<br>M30x1,5 R / L : 115 | 0013300335<br>0003303135<br>0013300435<br>0003308135 | TM05106<br> |
| 345 L 1313<br>345 L 2219,2220<br>345 LB 2219,2220<br>345 LK 1313<br>345 LK 2219,2220<br>352 L 1313<br>352 L 1813/6X2           | Ball Joint<br>M28x1,5 R / L : 105 | 0003309335<br>0003301435<br>0003301535<br>0003383629 | TM05369<br> |










| TM No.  | Replaces Ref. No: | Description         | Model / Details           |
|---|-------------------|---------------------|---------------------------|
| <b>TM05367</b><br>   | 0003309435        | Ball Joint          | 345 L 1313                |
|   | 0003303335        | M28x1,5 L / L : 105 | 345 L 2219,2220           |
|   | 0003309635        |                     | 345 LB 2219,2220          |
|   | 0003307235        |                     | 345 LK 1313               |
|   |                   |                     | 345 LK 2219,2220          |
|   |                   |                     | 352 L 1313                |
|   |                   |                     | 352 L 1813/6X2            |
| <b>TM05256</b><br>   | 0003308635        | Ball Joint          | 314 LP                    |
|   | 0003300735        | M24x1,5 L / L : 95  | 316 LP                    |
|   | 0003306835        |                     | 318 LP                    |
|   | 0003308835        |                     | 328 T2/L                  |
|   |                   |                     | 353 LP                    |
|   |                   |                     | 353 T2/L                  |
|   |                   |                     | 673 LK/LN2                |
| <b>TM05366</b><br>   | 0013302135        | Ball Joint          | 655 SK                    |
|   | 0003304035        | M35x1,5 R / L : 150 | 307 O 305                 |
|   | 0013302635        |                     | 307 O 307                 |
|   | 0003307735        |                     | 382 O 500                 |
|   |                   |                     | 382 O 500 M / 1725        |
|   |                   |                     | 382 O 500 M / 1725 / 1726 |
| <b>TM05365</b><br> | 0013302235        | Ball Joint          | 655 SK                    |
|   | 0003304135        | M35x1,5 L / L : 150 | 307 O 305                 |
|   | 0013302735        |                     | 307 O 307                 |
|   | 0003307835        |                     | 382 O 500                 |
|   |                   |                     | 382 O 500 M / 1725        |
|   |                   |                     | 382 O 500 M / 1725 / 1726 |
|   |                   |                     | 382 O 500 M / 1728        |
| <b>TM37208</b><br> | 0014602948        | Ball Joint          | -                         |
|   | 0004609248        | M30x1,5 R / L : 146 |                           |
| <b>TM05469</b><br> | 0013300735        | Ball Joint          | 308 L 608 E, L 708 E      |
|   | 0003302735        | M24x1,5 R / L : 160 | 308 L/LO 608 D            |
|   | 0003307035        |                     | 308 LO 608 D, LO 708 D/E  |
|   | 0013300935        |                     | 309 T2/L                  |
|   |                   |                     | 309 TL2/L                 |
|   |                   |                     | 310 LF 508 D/LF 608 D     |
|   |                   |                     | 310 T2/L                  |
| <b>TM05334</b><br> | 0014605048        | Ball Joint          | 374 AXOR 2                |
|   | 0014608548        | M28x1,5 R / L : 141 | 950 AXOR 2                |
|   | 0014604248        |                     | 952 AXOR 2                |
|   | 0014608948        |                     | 953 AXOR 2                |
|   |                   |                     |                           |



| Model / Details  | Description                       | Replaces Ref. No:        | TM No.  |
|--|-----------------------------------|--------------------------|---|
| 950 ACTROS<br>952 ACTROS<br>954 ACTROS<br>934 ACTROS 2/3<br>950 AXOR 2<br>952 AXOR 2<br>624 NG | Ball Joint<br>M38x1,5 R / L : 135 | 0004601748               | <b>TM05372</b><br>   |
| 625 NG<br>625 SK   | Ball Joint<br>M26x1,5 R / L : 85  | 6244600348               | <b>TM05175</b><br>   |
| -  | Ball Joint<br>M30x1,5 R / L : 158 | 6994601648               | <b>TM05716</b><br>   |
| 625 SK   | Ball Joint<br>M30x1,5 R / L : 155 | 0014600648<br>0004604848 | <b>TM05409</b><br> |
| 356 O 404<br>613 TOURISMO<br>698 BH 4<br>698 BH 4-N  | Ball Joint<br>M24x1,5 R / L : 125 | 0004607748<br>0014602148 | <b>TM05467</b><br> |
| 356 O 404<br>613 TOURISMO<br>698 BH 4<br>698 BH 4-N  | Ball Joint<br>M24x1,5 L / L : 125 | 0004607848<br>0014602048 | <b>TM05468</b><br> |
| 634 IBC-FAHRG-<br>ESTELL-BUGGY 3-ACHS-<br>ER NAFTA   | Ball Joint<br>M30x1,5 R / L : 143 | 6293380010               | <b>TM05111</b><br> |





| TM No.  | Replaces Ref. No: | Description         | Model / Details  |
|---|-------------------|---------------------|--|
| <b>TM37244</b><br>   | 0003330827        | Ball Joint          | 356 O 404  |
|   | 0003300827        | M24x1,5 R / L : 115 | 613 TOURISMO   |
| <b>TM05419</b><br>   | 0014608248        | Ball Joint          | 375 ACTROS   |
|   |                   | M28x1,5 R / L : 115 | 375 AXOR<br>375 AXOR 2   |
| <b>TM32772</b><br>   | 3752600237        | Ball Joint          | 375 ACTROS   |
|   | 3752600537        | L: 91 mm            | 375 AXOR<br>375 AXOR 2   |
| <b>TM05379</b><br> | 0014605148        | Ball Joint          | 950 ACTROS   |
|   | 0014608648        | M30x1,5 R / L : 115 | 952 ACTROS   |
|   | 0014603848        |                     | 953 ACTROS   |
|   | 0014604848        |                     | 954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3                       |
| <b>TM05117</b><br> | 0009964845        | Ball Joint          | 625 NG   |
|   | 0014607048        | M26x1,5 R / L : 75  | 625 SK   |
| <b>TM37218</b><br> | 0004606748        | Ball Joint          | 357 O 405  |
|   |                   | M30x1,5 R / L : 125 | 612 O 405<br>698 BGT-N 2   |
| <b>TM05109</b><br> | 0014607248        | Ball Joint          | 384 OF SERIES  |
|   |                   | M32x1,5 / L: 141    | 382 OH SERIES<br>390 OH SERIES<br>390 OHL 1621<br>382 O 500<br>382 O 500 U / 1725 / 59 |









| Model / Details   | Description                       | Replaces Ref. No:  | TM No.  |
|---|-----------------------------------|--|---|
| 690 SPRINTER<br>901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER  | Ball Joint<br>M16x1,5             | 9014600048<br>9014600148<br>9014600248<br>9014600348     | <b>TM05466</b><br>   |
| 901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER<br>905 SPRINTER<br>909 SPRINTER                                  | Ball Joint<br>M20x1,5             | 9013331227<br>9013331127<br>9013330727<br>9013330627     | <b>TM30355</b><br>   |
| 906 SPRINTER  | Ball Joint<br>M16x1,5             | 9064600148<br>9064600048<br>9064600348                   | <b>TM05470</b><br>  |
| 638 VITO<br>638 V-CLASS   | Ball Joint<br>M16x1,5             | 6384600048   | <b>TM05490</b><br> |
| 639 VIANO   | Ball Joint<br>L: 75 mm            | 6393300510S<br>6393300410S<br>6393300810S<br>6393300910S | <b>TM37245</b><br> |
| 934 ACTROS 2/3<br>958 AXOR 2  | Ball Joint<br>M30x1,5 R / L : 146 | 0013309935<br>0014609848                                 | <b>TM37210</b><br> |
| 336 LP 1924<br>336 LPS 1924<br>363 LP 2226/6X4<br>363 LP 2232/6X4<br>363 LPB 2226/6X4<br>363 LPK 2226/6X4<br>363 LPK 2232/6X4 | Ball Joint<br>M14x1,5 R / L : 86  | 0002684889<br>0002680189                                 | <b>TM31885</b><br> |












| TM No.  | Replaces Ref. No:                      | Description                                | Model / Details   |
|---|--|--|---|
| <b>TM31607</b><br>   | 0002685289                             | Ball Joint<br>M14x1,5 R / L : 86           | 975 ATEGO<br>350 LS 1924<br>386 L 1621,1721<br>386 L 1621,L 1721<br>386 L 1622<br>386 L 1625,1725<br>386 L 1633           |
|   | 0002684789<br>0002686189<br>3662680489 | Ball Joint<br>Left<br>M12x1,75 L / L : 55  | 336 LP 1924<br>336 LPS 1924<br>343 T2/L<br>350 LS 1924<br>350 LS 1924A,1929<br>350 LS 1924A,1929,1930<br>350 LS 1932,1933 |
| <b>TM31752</b><br>  | 0002686289<br>0002684689<br>3662680389 | Ball Joint<br>Right<br>M12x1,75 R / L : 55 | 970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>970 ATEGO 2<br>972 ATEGO 2<br>975 ATEGO 2<br>336 LP 1924                           |
|   | 0002686989<br>0009965245<br>6732680189 | Ball Joint<br>M14x1,5 R / L : 50           | 952 ACTROS<br>653 MK<br>625 SK<br>655 SK<br>656 SK<br>659 SK<br>371 2624K,2627K3027<br>6X4/38,50TOMARSAN/<br>TUERKEI      |
| <b>TM31753</b><br> | 0002685989                             | Ball Joint<br>M14x1,5 R / L : 55           | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO                               |
|   | 0009966645<br>0009969345               | Ball Joint<br>Right<br>M12x1,75 R / L : 60 | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>673 LK/LN2<br>674 LK/LN2<br>653 MK                                |
| <b>TM33263</b><br> | 0009966745<br>0009969445               | Ball Joint<br>Left<br>M12x1,75 L / L : 60  | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>673 LK/LN2<br>674 LK/LN2<br>625 SK                                |









| Model / Details  | Description                                | Replaces Ref. No:                      | TM No.  |
|--|--|--|---|
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>375 ATEGO<br>970 ATEGO<br>972 ATEGO                | Ball Joint<br>M14x1,5 R / L : 55           | 0009967045<br>0009966845               | <b>TM31848</b><br>   |
| 950 ACTROS<br>954 ACTROS<br>375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO                  | Ball Joint<br>Right<br>M12x1,75 R / L : 56 | 0009965545<br>0009965045               | <b>TM32036</b><br>   |
| 375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>375 ATEGO 2<br>958 ATEGO 2                | Ball Joint<br>Left<br>M12x1,75 L / L : 56  | 0009965645<br>0009965145               | <b>TM32037</b><br>  |
| 396 OH SERIES  | Ball Joint<br>M30x1,5 R / L : 150          | 0004605248<br>0014609048               | <b>TM05796</b><br> |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>942 AXOR 2 | Ball Joint<br>M26x1,5 R / L : 75           | 0014601548<br>0014601648<br>0024600648 | <b>TM05122</b><br> |
| 343 T2/L<br>343 T2/LN1<br>346 L 1924<br>346 L 1928<br>346 LA 1924<br>346 LAK 1924<br>346 LAS 1924          | Ball Joint<br>M26x1,5 R / L : 90           | 0014606948                             | <b>TM05115</b><br> |
| -  | Ball Joint                                 | 6383300027<br>6383330027               | <b>TM37246</b><br> |












| TM No.  | Replaces Ref. No:   | Description  | Model / Details |  |
|---|---------------------|--|-----------------|--|
| <b>TM37247</b><br>   | 9063304007S         | Ball Joint   | 906 SPRINTER    |  |
|   | 9063304107S         |  |                 |  |
|   | 9063330227S         |  |                 |  |
|   | <hr/>               |  |                 |  |
| <b>TM05491</b><br>   | 6394600048          | Ball Joint<br>Left   | 639 VIANO       |  |
|   | 6394600448          |  |                 |  |
|   | 6394600648          |  |                 |  |
|   | <hr/>               |  |                 |  |
| <b>TM05492</b><br>   | 6394600348          | Ball Joint<br>Right  | 639 VIANO       |  |
|   | 6394600548          |  |                 |  |
|   | 6394600748          |  |                 |  |
|   | <hr/>               |  |                 |  |
| <b>TM04980</b><br> | 0003380250          | Sleeve, Drag Link<br>M30x1,5                               | 397 OH SERIES   |  |
|   | 364 O 370           |  |                 |  |
|   | 364 O 371           |  |                 |  |
|   | 664 O 371           |  |                 |  |
|   | 664 O 374           |  |                 |  |
|   | 664 O 400 RSD BUGGY |  |                 |  |
|   | 664 O 400 RSE BUGGY |  |                 |  |
| <hr/>   |                     |  |                 |  |
| <b>TM37248</b><br> | 3753910017          | Bushing, Drag Link<br>ø20xø63x72,5                         | 375 AXOR 2      |  |
|   | 3753230385          |  | 940 AXOR 2      |  |
| <hr/>   |                     |  |                 |  |
| <b>TM05361</b><br> | 0024606780          | Steering Pump<br>Without Fitting<br>Repl. ZF: 7685 955 134 | -               |  |
|   | 0014602880          |  |                 |  |
|   | 0004606880          |  |                 |  |
|   | 0004602680          |  |                 |  |
|   |                     |  |                 |  |
| <hr/>   |                     |  |                 |  |
| <b>TM05357</b><br> | 0024607580          | Steering Pump<br>Repl. ZF: 7684 955 190                    | 673 LK/LN2      |  |
|   | 0004606780          |  | 674 LK/LN2      |  |
|   | 0004602580          |  | 676 LK/LN2      |  |
|   | 0014664401          |  | 615 NG          |  |
|   |                     |  | 616 NG          |  |
|   | 617 NG              |  |                 |  |
|   | 619 NG              |  |                 |  |



| Model / Details  | Description   | Replaces Ref. No:                                    | TM No.  |
|--|---|--|---|
| -  | Steering Pump<br>Repl. ZF: 7673 955 534<br>M26x1,5/M18x1,5/120<br>bar | 0014661301   | <b>TM05360</b><br>   |
| 979 ACCELO<br>375 ACTROS<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>958 ATEGO 2            | Steering Pump<br>Repl. ZF: 7685 955 247<br>M26x1,5/M16x1,5/150<br>bar | 0024605380<br>0014608580                             | <b>TM05505</b><br>   |
| 652 MK<br>621 NG<br>625 SK<br>655 SK<br>658 SK<br>659 SK   | Steering Pump<br>Repl. ZF: 7677 955 201<br>M33x2/M22x1,5              | 0014600580<br>0014667601                             | <b>TM05380</b><br>  |
| 336 LP 1924<br>336 LPS 1924<br>343 T2/L<br>343 T2/LN1<br>346 L 1924<br>346 L 1928<br>346 LA 1924       | Steering Pump<br>Repl. LuK: 542 0032 10<br>M26x1,5/M16x1,5/100<br>bar | 0024607680<br>0014661001<br>0014660801<br>0004606680 | <b>TM05356</b><br> |
| 979 ACCELO<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3 | Steering Pump<br>Repl. LuK: 542 0047 10<br>M26x1,5/M16x1,5/180<br>bar | 0024603980<br>0024600880<br>0014603080<br>0024600780 | <b>TM05148</b><br> |
| 979 ACCELO<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3 | Steering Pump<br>Repl. LuK: 542 0051 10<br>M26x1,5/M16x1,5            | 0014607080<br>0024606580<br>0014607180               | <b>TM05328</b><br> |
| 979 ACCELO<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3 | Steering Pump<br>Repl. LuK: 542 0048 10<br>M26x1,5/M18x1,5/180<br>bar | 0034602180<br>0024604180<br>0034605180<br>0014603180 | <b>TM05439</b><br> |





| TM No.  | Replaces Ref. No: | Description            | Model / Details              |
|---|-------------------|------------------------|------------------------------|
| <b>TM05381</b><br>   | 0024606480        | Steering Pump          | 650 MK                       |
|   | 0014607280        | Repl. LuK: 542 0050 10 | 659 SK                       |
|   | 0014606880        | M26x1,5/M16x1,5/155    | 671 O 345                    |
|   | 0004606180        | bar                    | 613 TOURISMO                 |
|   |                   |                        |                              |
| <b>TM05362</b><br>   | 0004667001        | Steering Pump          | 341 LA 1114                  |
|   |                   | Repl. ZF: 7673 955 554 | 344 L 1113                   |
|   |                   | M26x1,5/M16x1,5/100    | 344 L 1113/L 1114            |
|   |                   | bar                    | 344 L 1116                   |
|   |                   |                        | 344 L 1118                   |
|   |                   |                        | 344 LA 1113                  |
|   |                   |                        | 344 LAK 1113                 |
| <b>TM05150</b><br>  | 0034604980        | Steering Pump          | 950 ACTROS                   |
|   | 0024608880        | Repl. LuK: 542 0453 10 | 952 ACTROS                   |
|   | 0024608980        | M26x1,5/M18x1,5/180    | 953 ACTROS                   |
|   |                   | bar                    | 954 ACTROS                   |
|   |                   |                        | 930 ACTROS 2/3               |
|   |                   |                        | 932 ACTROS 2/3               |
|   |                   |                        | 933 ACTROS 2/3               |
| <b>TM05412</b><br> | 0014604480        | Steering Pump          | 375 ACTROS                   |
|   | 0014607580        | Repl. LuK: 542 0042 10 | 375 ATEGO                    |
|   | 0024605480        | M26x1,5/M16x1,5        | 970 ATEGO                    |
|   |                   |                        | 972 ATEGO                    |
|   |                   |                        | 975 ATEGO                    |
|   |                   |                        | 976 ATEGO                    |
|   |                   |                        | 375 ATEGO 2                  |
| <b>TM05473</b><br> | 0014608480        | Steering Pump          | 958 ATEGO 2                  |
|   |                   | Repl. ZF: 7684 955 913 | 976 ATEGO 2                  |
|   |                   | M26x1,5/M16x1,5        | 694 L 1218 R                 |
|   |                   |                        | 694 L 1218/1318/1319         |
|   |                   |                        | 694 L 1418                   |
|   |                   |                        | 694 LK 1218 - 1318 - 1319/42 |
|   |                   |                        | 696 L 1938                   |
| <b>TM05155</b><br> | 0034660701        | Steering Pump          | 901 SPRINTER                 |
|   | 0024662601        | Repl. ZF: 7692 900 504 | 902 SPRINTER                 |
|   |                   |                        | 903 SPRINTER                 |
|   |                   |                        | 904 SPRINTER                 |
|   |                   |                        | 638 VITO                     |
| <b>TM05472</b><br> | 0024667501        | Steering Pump          | 690 SPRINTER                 |
|   |                   | Repl. ZF: 7692 900 510 | 901 SPRINTER                 |
|   |                   |                        | 902 SPRINTER                 |
|   |                   |                        | 903 SPRINTER                 |
|   |                   |                        | 904 SPRINTER                 |
|   |                   |                        | 905 SPRINTER                 |












| Model / Details | Description            | Replaces Ref. No: | TM No.  |
|-----------------|------------------------|-------------------|---|
| 375 ACTROS      | Steering Pump          | 0024601580        | <br><b>TM05348</b>   |
| 958 ATEGO 2     | Repl. LuK: 542 0092 10 | 0024604980        |   |
| 976 ATEGO 2     | M26x1,5/M16x1,5/180    | 0024601780        |   |
| 375 AXOR        | bar                    | 4574600280        |   |
| 374 AXOR 2      |                        |                   |   |
| 375 AXOR 2      |                        |                   |   |
| 940 AXOR 2      |                        |                   |   |
| <hr/>           |                        |                   |   |
| 979 ACCELO      | Steering Pump          | 0004609480        | <br><b>TM05358</b>   |
| 375 ATEGO       | Repl. LuK: 542 0049 10 | 0014604280        |   |
| 970 ATEGO       | M26x1,5/M16x1,5        | 0014608080        |   |
| 972 ATEGO       |                        | 0024605880        |   |
| 975 ATEGO       |                        |                   |   |
| 970 ATEGO 2     |                        |                   |   |
| 972 ATEGO 2     |                        |                   |   |
| <hr/>           |                        |                   |   |
| 375 ACTROS      | Steering Pump          | 0024603580        | <br><b>TM05438</b>  |
| 970 ATEGO       | Zf Type                | 0024605280        |   |
| 972 ATEGO       | Repl. ZF: 7685 955 249 |                   |   |
| 975 ATEGO       | M26x1,5/M18x1,5/150    |                   |   |
| 976 ATEGO       | bar                    |                   |   |
| 958 ATEGO 2     |                        |                   |   |
| 970 ATEGO 2     |                        |                   |   |
| <hr/>           |                        |                   |   |
| 950 ACTROS      | Steering Pump          | 0034600380        | <br><b>TM05410</b> |
| 952 ACTROS      | Right, 180 Bar         | 0034605280        |   |
| 953 ACTROS      | M26x1,5/M18x1,5/180    | 0034605580        |   |
| 954 ACTROS      | bar                    |                   |   |
| 930 ACTROS 2/3  |                        |                   |   |
| 932 ACTROS 2/3  |                        |                   |   |
| 933 ACTROS 2/3  |                        |                   |   |
| <hr/>           |                        |                   |   |
| 963 ACTROS MP4  | Steering Pump          | 0034603980        | <br><b>TM05504</b> |
| 964 ACTROS MP4  | Left, 185 Bar          | 0034604080        |   |
| 964 ANTOS       | Repl. Bosch: K S00 001 | 0034606180        |   |
| 964 AROCS       | 806                    |                   |   |
| 967 ATEGO 3     | M26x1,5/M18x1,5/185    |                   |   |
| 405 UNIMOG      | bar                    |                   |   |
| <hr/>           |                        |                   |   |
| 963 ACTROS MP4  | Steering Pump          | 0034601680        | <br><b>TM37249</b> |
| 964 ACTROS MP4  | Left, 200 Bar          | 0034606080        |   |
| 964 ANTOS       | M26x1,5/M18x1,5/200    |                   |   |
| 964 AROCS       | bar                    |                   |   |
| 967 ATEGO       |                        |                   |   |
|                 |                        |                   |   |
| <hr/>           |                        |                   |   |
| 906 SPRINTER    | Steering Pump          | 0064661701        | <br><b>TM05474</b> |
|                 | Repl. Zf: 7693 900 511 | 0064667801        |   |










| TM No.  | Replaces Ref. No: | Description   | Model / Details   |
|---|-------------------|---|---|
| <b>TM05507</b><br>   | 0024662501        | Steering Pump   | 901 SPRINTER  |
|   | 0024662701        | Repl. Bosch: K S00 000<br>587<br>Pulley: 129mm,6 Ribs | 902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER<br>638 VITO<br>638 V-CLASS |
| <b>TM05157</b><br>   | 0034669301        | Steering Pump   | 639 VIANO   |
|   |                   | Repl. Bosch: K S00 000<br>633<br>Pulley: 120mm,7 PK   | 906 SPRINTER<br>639 VIANO<br>639 VITO                                   |
| <b>TM05156</b><br>  | 0034667201        | Steering Pump   | 639 VIANO   |
|   | 0034667101        | Repl. Bosch: K S00 000<br>596                         | 906 SPRINTER<br>639 VIANO<br>639 VITO                                   |
| <b>TM05515</b><br> | 0064665201        | Steering Pump   | 639 VIANO   |
|   |                   | Repl. Bosch: K S00 000<br>672<br>Pulley: 120mm,7 PK   | 906 SPRINTER<br>639 VIANO<br>639 VITO                                   |
| <b>TM05508</b><br> | 0054662401        | Steering Pump   | 639 VIANO   |
|   | 0054662501        | Repl. Bosch: K S00 000<br>638<br>Pulley: 128mm,6 PK   | 906 SPRINTER<br>639 VIANO<br>639 VITO                                   |
| <b>TM05303</b><br> | 3439970582        | Hose, Steering Pump                                   | 375 AXOR  |
|   | 3609971182        |   | 375 AXOR 2  |
|   | 3859971682        |   | 940 AXOR 2  |
|   | 6999974082        |   | 942 AXOR 2<br>943 AXOR 2<br>957 ECONIC<br>343 T2/L                      |
| <b>TM05301</b><br> | 3609970982        | Hose, Steering Pump                                   | 375 ACTROS  |
|   |                   |   | 950 ACTROS  |
|   |                   |   | 952 ACTROS  |
|   |                   |   | 953 ACTROS  |
|   |                   |   | 375 AXOR  |
|   |                   |   | 375 AXOR 2<br>958 AXOR 2  |






| Model / Details  | Description                      | Replaces Ref. No:                                    | TM No.  |
|--|----------------------------------|--|---|
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3     | Hose, Steering Pump              | 6259971082   | <b>TM05302</b><br>   |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3     | Hose, Steering Pump              | 0019972752<br>0019972652<br>0129972382               | <b>TM05307</b><br>   |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>375 ATEGO      | Hose, Steering Pump              | 0009978152<br>0129972482<br>0019976352               | <b>TM05559</b><br>   |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3 | Hose, Steering Pump              | 0009978252<br>0129972582<br>0019976452               | <b>TM05308</b><br> |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3 | Hose, Steering Pump              | 0229976682<br>0199975582                             | <b>TM05565</b><br> |
| 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3   | Hose, Steering Pump<br>22x22x370 | 9424660681   | <b>TM05309</b><br> |
| 341 LA 1114<br>343 T2/L<br>343 T2/LN1<br>345 L 2225<br>345 LS 1524/1525<br>346 L 1924<br>346 L 1928            | Oil Container                    | 0004663802<br>0004664502<br>0004665502<br>0004666202 | <b>TM05225</b><br> |





| TM No.  | Replaces Ref. No: | Description               | Model / Details |
|---|-------------------|---------------------------|-----------------|
| <b>TM05048</b><br>   | 0004662804        | Filter, Oil Container     | 375 ACTROS      |
|   | 0004660604        | Repl. Mann: H 601/4       | 950 ACTROS      |
|   | 0004660204        | Repl. Hengst: E10H02      | 952 ACTROS      |
|   | 0004663004        | ø18xø60/ø18/100,5         | 953 ACTROS      |
|   |                   |                           | 954 ACTROS      |
|   |                   |                           | 930 ACTROS 2/3  |
|   |                   |                           | 932 ACTROS 2/3  |
| <b>TM05228</b><br>   | 0004661268        | Filler Cap, Oil Container | 375 ACTROS      |
|   | 0004660668        | M81x4/25                  | 950 ACTROS      |
|   |                   |                           | 952 ACTROS      |
|   |                   |                           | 953 ACTROS      |
|   |                   |                           | 954 ACTROS      |
|   |                   |                           | 930 ACTROS 2/3  |
|   |                   |                           | 932 ACTROS 2/3  |
| <b>TM05563</b><br>   | 9424660481        | Hose, Oil Container       | 950 ACTROS      |
|   | 9424660181        |                           | 952 ACTROS      |
|   |                   |                           | 953 ACTROS      |
|   |                   |                           | 954 ACTROS      |
|   |                   |                           | 930 ACTROS 2/3  |
|   |                   |                           | 932 ACTROS 2/3  |
|   |                   |                           | 933 ACTROS 2/3  |
| <b>TM05244</b><br> | 3754660081        | Hose, Oil Container       | 932 ACTROS 2/3  |
|   |                   |                           | 942 AXOR 2      |
|   |                   |                           | 943 AXOR 2      |
| <b>TM37250</b><br> | 6254660381        | Hose, Oil Container       | 375 ACTROS      |
|   |                   |                           | 950 ACTROS      |
|   |                   |                           | 952 ACTROS      |
|   |                   |                           | 953 ACTROS      |
|   |                   |                           | 930 ACTROS 2/3  |
|   |                   |                           | 932 ACTROS 2/3  |
|   |                   |                           | 933 ACTROS 2/3  |
| <b>TM05567</b><br> | 9424660281        | Hose, Oil Container       | 950 ACTROS      |
|   |                   |                           | 952 ACTROS      |
|   |                   |                           | 953 ACTROS      |
|   |                   |                           | 954 ACTROS      |
| <b>TM37251</b><br> | 3834660181        | Hose, Oil Container       | 343 T2/L        |
|   |                   |                           | 343 T2/LN1      |
|   |                   |                           | 346 L 1924      |
|   |                   |                           | 346 LA 1924     |
|   |                   |                           | 346 LAK 1924    |
|   |                   |                           | 346 LAS 1924    |
|   |                   | 346 LK 1924               |                 |



| Model / Details   | Description                         | Replaces Ref. No:                                    | TM No.  |
|---|-------------------------------------|--|---|
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3    | Hose, Oil Container                 | 5411800720<br>5411800820<br>5411801120<br>5411801520 | <b>TM01139</b><br>   |
| 375 ACTROS<br>950 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3<br>375 ATEGO | Hose, Oil Container                 | 6254660081   | <b>TM37252</b><br>   |
| 901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>909 SPRINTER  | Wishbone<br>Right                   | 9013302507<br>9013301907<br>9013301707               | <b>TM30792</b><br>   |
| 690 SPRINTER<br>901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>909 SPRINTER                                  | Wishbone<br>Left                    | 9013301807<br>9013301607                             | <b>TM30791</b><br> |
| 906 SPRINTER  | Wishbone<br>Left                    | 9063304007<br>9063304607                             | <b>TM30793</b><br> |
| 906 SPRINTER  | Wishbone<br>Right                   | 9063304107<br>9063304707                             | <b>TM30458</b><br> |
| 638 VITO<br>638 V-CLASS   | Wishbone<br>Front Axle, Right Lower | 6383300110<br>6383300610                             | <b>TM37253</b><br> |





| TM No.  | Replaces Ref. No:        | Description                              | Model / Details         |
|---|--------------------------|--|-------------------------|
| <b>TM37254</b><br>   | 6383300010<br>6383300510 | Wishbone<br>Front Axle, Left Lower       | 638 VITO<br>638 V-CLASS |
| <b>TM37255</b><br>   | 6393300510               | Wishbone<br>Right                        | 639 VIANO               |
| <b>TM37256</b><br>  | 6393300410               | Wishbone<br>Left                         | 639 VIANO               |
| <b>TM37257</b><br> | 6393301501<br>6393301307 | Wishbone<br>Front Axle, Right Lower      | 639 VIANO               |
| <b>TM37258</b><br> | 6393301401<br>6393301207 | Wishbone<br>Front Axle, Left Lower       | 639 VIANO               |
| <b>TM30477</b><br> | 9063330014<br>9063330114 | Rubber Bushing, Wishbone<br>ø14,3xø52x75 | 906 SPRINTER            |
| <b>TM37259</b><br> | 6383520650               | Rubber Bushing, Wishbone<br>ø14,5xø46x75 | 638 VITO<br>638 V-CLASS |





| <i>Model / Details</i> | <i>Description</i>                       | <i>Replaces Ref. No:</i> | <i>TM No.</i>   |
|------------------------|--|--------------------------|---|
| -                      | Rubber Bushing, Wishbone                 | 6383330814               | <b>TM37260</b><br>   |
| 639 VIANO              | Rubber Bushing, Wishbone<br>Front, Left  | 6393330514               | <b>TM37262</b><br>   |
| 964 AROCS<br>639 VIANO | Rubber Bushing, Wishbone<br>Front, Right | 6393330614               | <b>TM37263</b><br>   |
| 639 VIANO              | Rubber Bushing, Wishbone                 | 6393330014               | <b>TM37264</b><br> |





| TM No.  | Replaces Ref. No:        | Description                                     | Model / Details   |
|---|--------------------------|---|---|
| <b>TM15040</b><br>   | 3464230601               | Brake Drum<br>ø410x172/270ø298/<br>ø335x10xø23  | 343 T2/L  |
|   | 3464230001               |   | 650 MK<br>653 MK<br>617 NG<br>621 NG<br>623 NG<br>624 NG  |
| <b>TM15044</b><br>   | 6244210201               | Brake Drum<br>ø410x191/237xø298/<br>ø335x10xø23 | 388 L 2635/6X4/54<br>388 LK 2635/6X4/40<br>388 LS 2635/6X4/40<br>660 L 1929<br>660 L 1935<br>660 LS 1929<br>660 LS 1935 |
|   |                          |   |   |
| <b>TM15039</b><br>  | 3054230401               | Brake Drum<br>ø410x240/306xø298/<br>ø335x10xø23 | 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3<br>964 ACTROS MP4<br>964 AROCS<br>375 AXOR         |
|   | 3054230301               |   |   |
| <b>TM15042</b><br> | 3054210401               | Brake Drum<br>ø410x167/213xø298/<br>ø335x10xø23 | 958 ATEGO 2<br>343 T2/L<br>343 T2/LN1<br>346 L 1924<br>346 L 1928<br>346 LK 1924<br>346 LK 1928                         |
|   | 3054210101<br>3564210001 |   |   |
| <b>TM15041</b><br> | 3464230501               | Brake Drum<br>ø410x192/280xø298/<br>ø335x10xø23 | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3              |
|   | 3464230101               |   |   |
| <b>TM15098</b><br> | 3054230701               | Brake Drum<br>ø410x237/306xø298/<br>ø335x10xø23 | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3              |
|   |                          |   |   |
| <b>TM15047</b><br> | 3874210001               | Brake Drum<br>ø410x172/250xø298/<br>ø335x10xø23 | 621 NG<br>623 NG<br>624 NG<br>625 NG<br>646 NG<br>648 NG<br>649 NG  |
|   | 3464210301               |   |   |



| Model / Details  | Description   | Replaces Ref. No:                                    | TM No.  |
|--|---|--|---|
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 | Brake Drum<br>ø410x191/237xø298/<br>ø335x10xø23   | 6584210001   | <b>TM15043</b><br>   |
| 343 T2/L<br>346 L 1924<br>346 L 1928<br>346 LK 1924<br>346 LK 1928<br>346 LS 1924<br>346 LS 1928           | Brake Shoe, Brake Drum<br>Unlined, Thick 8 mm, With<br>Roller<br>ø410x180 mm                | 3504200319<br>6204200219<br>6594200319<br>6204200019 | <b>TM37265</b><br>   |
| 677 LK/LN2<br>679 LK/LN2<br>650 MK<br>651 MK<br>652 MK<br>653 MK<br>654 MK                                 | Brake Shoe, Brake Drum<br>Unlined, Thick 8 mm, With<br>Roller<br>ø410x220 mm                | 6204200119<br>6244200019<br>6244200219<br>6204200519 | <b>TM13916</b><br>   |
| 950 AXOR 2<br>397 2426 /6X4<br>397 2426 B/6X4<br>671 CONECTO<br>671 O 345                                  | Brake Shoe, Brake Drum<br>Unlined, With Roller<br>ø410x220 mm                               | 3054201319<br>3054200719                             | <b>TM15029</b><br> |
| 671 CONECTO<br>671 O 345   | Brake Shoe, Brake Drum<br>Unlined, With Roller<br>W: 160                                    | 3054201119   | <b>TM37266</b><br> |
| 374 AXOR 2<br>375 AXOR<br>375 AXOR 2<br>940 AXOR 2<br>942 AXOR 2<br>943 AXOR 2<br>944 AXOR 2               | Brake Shoe, Brake Drum<br>Unlined, With Roller,<br>100.309' s<br>Castle Type<br>ø410x220 mm | 6594200419<br>6594200519                             | <b>TM37267</b><br> |
| 343 T2/L<br>355 OF SERIES<br>397 OF SERIES<br>656 SK<br>655 SK<br>649 NG<br>653 MK                         | Brake Shoe, Brake Drum<br>Unlined, With Roller<br>ø410x180 mm                               | 3894206119   | <b>TM37268</b><br> |





| TM No.  | Replaces Ref. No: | Description                    | Model / Details      |
|---|-------------------|--------------------------------|----------------------|
| <b>TM15736</b><br> | 3464233210        | Lining Kit, Brake Drum         | 341 L 1114           |
|   | 3464233810        | Drum: ø410, 8 pcs. Brake       | 341 L 914            |
|   | 3464235810        | Lining                         | 341 LA 1114          |
|   | 3464236110        | Repl. WVA: 19494 / 19486       | 341 LK 1114          |
|   |                   |                                |                      |
|   |                   |                                | 345 L 1313,1314      |
|   |                   |                                | 345 L 1313,1314,1316 |
| <b>TM37269</b><br> | -                 | Lining Kit, Brake Drum         | 341 L 1114           |
|   |                   | Drum: ø410, 8 pcs. Brake       | 341 L 914            |
|   |                   | Lining, First                  | 341 LA 1114          |
|   |                   | Repair Type For 096.631        | 341 LK 1114          |
|   |                   | Repl. WVA: 19494+10 / 19486+10 | 341 LS 1114          |
|   |                   |                                | 345 L 1313,1314      |
|   |                   |                                | 345 L 1313,1314,1316 |
| <b>TM13866</b><br> | 3464233210        | Lining Kit, Brake Drum         | 341 L 1114           |
|   | 3464233810        | Drum: ø410, 8 pcs. Brake       | 341 L 914            |
|   | 3464235810        | Lining,                        | 341 LA 1114          |
|   | 3464236110        | Rivets: 8x20/8 pcs.            | 341 LK 1114          |
|   |                   | Repl. WVA: 19494 / 19486       | 341 LS 1114          |
|   |                   |                                | 345 L 1313,1314      |
|   |                   |                                | 345 L 1313,1314,1316 |

|   |  |  |  |
|---|--|--|--|
| - |  |  |  |
|---|--|--|--|

| Model / Details  | Description                                   | Replaces Ref. No:                                    | TM No.         |
|--|---|--|----------------|
| 374 AXOR 2<br>375 AXOR<br>375 AXOR 2<br>940 AXOR 2<br>942 AXOR 2<br>943 AXOR 2<br>944 AXOR 2               | Bushing, Brake Shoe<br>Bronze<br>ø30xø34x47,5 | 6744210050<br>6744210150                             | <b>TM16977</b> |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 | Spring, Brake Shoe<br>ø26x243                 | 6179931110<br>6179930610<br>3469930210<br>3469930219 | <b>TM13724</b> |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 | Spring, Brake Shoe<br>ø26x234                 | 3469930310<br>3469930110                             | <b>TM13736</b> |
| 673 LK/LN2<br>674 LK/LN2<br>675 LK/LN2<br>676 LK/LN2<br>678 LK/LN2<br>900 SPRINTER                         | Spring, Brake Shoe<br>ø25x66                  | 6739930410<br>6739930210                             | <b>TM37298</b> |
| 336 LP 1924<br>336 LPS 1924<br>343 T2/LN1<br>346 L 1924<br>346 LA 1924<br>346 LAK 1924<br>346 LAS 1924     | Spring, Brake Shoe<br>ø35x240                 | 3269930010   | <b>TM13639</b> |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 | Spring, Brake Shoe<br>ø30x229                 | 3469930810   | <b>TM15498</b> |
| 336 LP 1924<br>336 LPS 1924<br>343 T2/LN1<br>346 L 1924<br>346 L 1928<br>346 LK 1924<br>346 LK 1928        | Spring, Brake Shoe<br>ø35x225                 | 3354210192   | <b>TM15491</b> |



| TM No.  | Replaces Ref. No: | Description                       | Model / Details  |
|---|-------------------|-----------------------------------|--|
| <b>TM14843</b><br>   | 6779930310        | Spring, Brake Shoe<br>ø30x95      | 970 ATEGO<br>972 ATEGO<br>976 ATEGO<br>970 ATEGO 2<br>972 ATEGO 2<br>976 ATEGO 2<br>967 ATEGO 3            |
|   | 6779930210        |                                   |  |
| <b>TM15505</b><br>   | 9459930010        | Spring, Brake Shoe<br>ø27,5x231   | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 |
|   |                   |                                   |  |
| <b>TM14892</b><br>   | 9454210074        | Spring Pin, Brake Shoe<br>ø12x72  | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 |
|   | 3464210674        |                                   |  |
| <b>TM14886</b><br> | 6584210074        | Spring Pin, Brake Shoe<br>ø12x97  | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 |
|   | 3874210074        |                                   |  |
| <b>TM37299</b><br> | 3184200182        | Spring Pin, Brake Shoe<br>ø28x82  | 673 LK/LN2<br>674 LK/LN2<br>675 LK/LN2<br>676 LK/LN2<br>678 LK/LN2<br>900 SPRINTER                         |
|   |                   |                                   |  |
| <b>TM37300</b><br> | 6754200082        | Spring Pin, Brake Shoe<br>ø30x102 | 970 ATEGO<br>972 ATEGO<br>976 ATEGO<br>970 ATEGO 2<br>972 ATEGO 2<br>976 ATEGO 2<br>967 ATEGO 3            |
|   |                   |                                   |  |
| <b>TM37301</b><br> | 3954200041        | Spring Pin, Brake Shoe<br>ø30x94  | 950 AXOR 2<br>343 T2/L<br>343 T2/LN1<br>346 L 1924<br>346 L 1928<br>346 LK 1924<br>346 LK 1928             |
|   |                   |                                   |  |












| Model / Details  | Description                               | Replaces Ref. No:                      | TM No.         |
|--|---|--|----------------|
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 | Repair Kit, Brake Shoe<br>ø30x102         | 3074204102<br>4434200082               | <b>TM15688</b> |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 | Repair Kit, Brake Shoe<br>ø20x76          | 3074200339<br>4034200339               | <b>TM14408</b> |
| 950 AXOR 2<br>343 T2/L<br>343 T2/LN1<br>345 L 2225<br>346 L 1924<br>346 L 1928<br>346 LK 1924              | Repair Kit, Brake Shoe<br>ø30x102         | 3074204002<br>3954200082<br>3955860242 | <b>TM14510</b> |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 | Repair Kit, Brake Shoe<br>ø20xø52x39,3/76 | 3764200039                             | <b>TM37302</b> |
| 336 LP 1924<br>336 LPS 1924<br>343 T2/LN1<br>346 L 1924<br>346 L 1928<br>346 LA 1924<br>346 LAK 1924       | Repair Kit, Brake Shoe<br>ø20x90          | 3354200039                             | <b>TM15673</b> |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 | Brake Anchor, Brake Shoe                  | 3464230906<br>6524230006<br>9424230306 | <b>TM15028</b> |
| 346 L 1924<br>346 L 1928<br>346 LK 1924<br>346 LK 1928<br>346 LS 1924<br>346 LS 1928<br>349 L 1621         | Brake Anchor, Brake Shoe                  | 3464213106<br>3934210006               | <b>TM14497</b> |





| TM No.  | Replaces Ref. No:        | Description                                     | Model / Details  |
|---|--------------------------|---|--|
| <b>TM29020</b><br>   | 0009816031               | Bearing, Brake Cam Shaft<br>ø42xø62x20/25       | 374 AXOR 2<br>375 AXOR<br>375 AXOR 2<br>940 AXOR 2<br>942 AXOR 2<br>943 AXOR 2<br>944 AXOR 2               |
| <b>TM37303</b><br>   | 9424232033               | Bracket, Brake Cam Shaft<br>Right               | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 |
| <b>TM37304</b><br>   | 9424231933               | Bracket, Brake Cam Shaft<br>Left                | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 |
| <b>TM37305</b><br> | 9424230233               | Bracket, Brake Cam Shaft<br>Right               | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 |
| <b>TM37306</b><br> | 9424230133               | Bracket, Brake Cam Shaft<br>Left                | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 |
| <b>TM15654</b><br> | 3604200341<br>3605860342 | Repair Kit, Brake Cam<br>Shaft<br>ø42xø62x20/25 | 950 AXOR 2<br>343 T2/L<br>346 L 1924<br>346 L 1928<br>346 LK 1924<br>346 LK 1928<br>346 LS 1924            |
| <b>TM15630</b><br> | 3604200441<br>3605860442 | Repair Kit, Brake Cam<br>Shaft<br>ø42xø62x20/25 | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 |



| Model / Details  | Description  | Replaces Ref. No:                                    | TM No.  |
|--|--|--|---|
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3                       | Repair Kit, Brake Cam<br>Shaft<br>ø42  | 3054210750S  | <b>TM37307</b><br>   |
| 336 LP 1924<br>336 LPS 1924<br>343 T2/LN1<br>652 MK<br>355 OF SERIES   | Brake Slack Adjuster<br>Manuel Repl. Haldex: 100<br>001 021<br>120/150/180                           | 3354200338   | <b>TM13814</b><br>   |
| 397 2426 /6X4<br>397 2426 B/6X4<br>671 O 345   | Brake Slack Adjuster<br>Left, Automatic<br>Repl. Haldex: 72809<br>ø14x130x103° / Double<br>Bent      | 3574201338   | <b>TM15105</b><br>   |
| 397 2426 /6X4<br>397 2426 B/6X4<br>671 O 345   | Brake Slack Adjuster<br>Right, Automatic<br>Repl. Haldex: 72810<br>ø14x130x103° / Double<br>Bent     | 3574201438   | <b>TM15106</b><br> |
| 958 ATEGO 2<br>386 L 1625,1725<br>386 LS 1625<br>397 LP 1517<br>397 LP/LPK 1314 MB-<br>SA-RSA<br>397 LPK 1414 MBSA-RSA<br>615 LK/LN2<br>677 LK/LN2 | Brake Slack Adjuster<br>Left, Automatic<br>Repl. Haldex: 80010<br>ø14x145 / S-ABA / Dou-<br>ble Bent | 9454200838<br>3834200538                             | <b>TM15011</b><br> |
| 696 L 1938<br>696 L 2638<br>696 LK 2638<br>696 LS 1938<br>696 LS 2638<br>650 MK<br>651 MK<br>653 MK  | Brake Slack Adjuster<br>Automatic<br>Repl. Haldex: 70867<br>ø14x145x75° / Double<br>Bent             | 3894200738<br>6204200338<br>6204200238<br>3894200538 | <b>TM13761</b><br> |



| TM No.  | Replaces Ref. No:        | Description  | Model / Details  |
|---|--------------------------|--|--|
| <b>TM15001</b><br>   | 3874200038               | Brake Slack Adjuster   | 350 LS 1924A,1929,1930   |
|   | 6214200138<br>9424201138 | Left, Automatic<br>Repl. Haldex: 72173<br>ø14x145x144° / Double Bent     | 350 LS 1932,1933<br>350 LS 1934<br>388 L 1929<br>388 L 1935<br>388 L 1938<br>388 L 1945  |
| <b>TM15012</b><br>   | 9454200738               | Brake Slack Adjuster   | 958 ATEGO 2  |
|   | 3834200438               | Right, Automatic<br>Repl. Haldex: 80011<br>ø14x145 / S-ABA / Double Bent | 386 L 1625,1725<br>386 LS 1625<br>397 LP 1517<br>397 LP/LPK 1314 MB-SA-RSA<br>397 LPK 1414 MBSA-RSA<br>615 LK/LN2                        |
| <b>TM14718</b><br>   | 6524200238               | Brake Slack Adjuster   | 615 LK/LN2   |
|   |                          | Automatic<br>Repl. Haldex: 72596<br>ø14x145x127° / Double Bent           | 650 MK<br>651 MK<br>652 MK<br>653 MK<br>654 MK<br>615 NG   |
| <b>TM15102</b><br> | 6234200738               | Brake Slack Adjuster   | 958 AXOR 2   |
|   | 6234200538               | Right, Automatic<br>Repl. Haldex: 72038<br>ø14x145x7° / Double Bent      | 345 L 2225<br>650 MK<br>651 MK<br>652 MK<br>653 MK<br>654 MK   |
| <b>TM15101</b><br> | 6234200638               | Brake Slack Adjuster   | 958 AXOR 2   |
|   | 6234200438               | Left, Automatic<br>Repl. Haldex: 72039<br>ø14x145x7° / Double Bent       | 345 L 2225<br>650 MK<br>651 MK<br>652 MK<br>653 MK<br>654 MK   |
| <b>TM15009</b><br> | 9454200538               | Brake Slack Adjuster   | 972 ATEGO  |
|   | 3854201738               | Left, Automatic<br>Repl. Haldex: 80012<br>ø14x145 / S-ABA / Double Bent  | 976 ATEGO<br>958 ATEGO 2<br>970 ATEGO 2<br>972 ATEGO 2<br>976 ATEGO 2<br>967 ATEGO 3   |
| <b>TM15014</b><br> | 3574200738               | Brake Slack Adjuster   | 382 OH SERIES  |
|   |                          | Right, Automatic<br>Repl. Haldex: 72061<br>ø14x145x346° / Double Bent    | 382 O 500<br>382 O 500 M / 1725<br>382 O 500 M / 1725 / 1726<br>382 O 500 M / 1728<br>382 O 500 R / 1830 / 30<br>382 O 500 U / 1725 / 59 |



| Model / Details   | Description   | Replaces Ref. No:                      | TM No.  |
|---|---|--|---|
| 382 OH SERIES<br>382 O 500<br>382 O 500 M / 1725<br>382 O 500 M / 1725 / 1726<br>382 O 500 M / 1728<br>382 O 500 R / 1830 / 30<br>382 O 500 U / 1725 / 59       | Brake Slack Adjuster<br>Left, Automatic<br>Repl. Haldex: 72060<br>ø14x145x346° / Double<br>Bent     | 3574200638                             | <b>TM15013</b><br>   |
| 972 ATEGO<br>976 ATEGO<br>958 ATEGO 2<br>970 ATEGO 2<br>972 ATEGO 2<br>976 ATEGO 2<br>967 ATEGO 3   | Brake Slack Adjuster<br>Right, Automatic<br>Repl. Haldex: 80013<br>ø14x145 / S-ABA / Double<br>Bent | 9454200638<br>3854201838               | <b>TM15010</b><br>   |
| 958 ATEGO 2<br>345 L 1313,1314,1316<br>345 LS 1313,1314,1316<br>397 LP 1114,1214 MB-SA-RSA<br>397 LP 1517<br>397 LP/LPK 1314 MB-SA-RSA<br>397 LPK 1414 MBSA-RSA | Brake Slack Adjuster<br>Automatic<br>Repl. Haldex: 70954<br>ø14x145x86° / Double<br>Bent            | 6174200238                             | <b>TM15108</b><br>   |
| 396 OH SERIES   | Brake Slack Adjuster<br>Automatic<br>Repl. Haldex: 72213<br>ø14x130x337,5° / Double<br>Bent         | 3014201138                             | <b>TM15008</b><br> |
| 350 LS 1924A,1929,1930<br>350 LS 1932,1933<br>350 LS 1934<br>388 L 1929<br>388 L 1935<br>388 L 1938<br>388 L 1945   | Brake Slack Adjuster<br>Right, Automatic<br>Repl. Haldex: 72174<br>ø14x145x144° / Double<br>Bent    | 3874200138<br>9424201038<br>6214200038 | <b>TM15002</b><br> |
| 382 O 500<br>382 O 500 M / 1725<br>382 O 500 M / 1725 / 1726<br>382 O 500 M / 1728<br>382 O 500 R / 1830 / 30<br>634 O 500<br>634 O 500 RSD / 2736/8X2/30       | Brake Slack Adjuster<br>Automatic<br>Repl. Haldex: 72059<br>ø14x145x358° / Double<br>Bent           | 3574200538                             | <b>TM14998</b><br> |
| 382 O 500<br>382 O 500 M / 1725<br>382 O 500 M / 1725 / 1726<br>382 O 500 M / 1728<br>382 O 500 R / 1830 / 30<br>634 O 500<br>634 O 500 RSD / 2736/8X2/30       | Brake Slack Adjuster<br>Right, Automatic<br>Repl. Haldex: 80014<br>ø14x145 / S-ABA / Double<br>Bent | 9454200438                             | <b>TM15006</b><br> |







| TM No.  | Replaces Ref. No: | Description                   | Model / Details |
|---|-------------------|-------------------------------|-----------------|
| <b>TM14999</b><br>   | 9454200038        | Brake Slack Adjuster          | 950 ACTROS      |
|   | 9424200938        | Left, Automatic               | 952 ACTROS      |
|   | 9424201238        | Repl. Haldex: 80008           | 953 ACTROS      |
|   | 6584200238        | ø14x145 / S-ABA / Double Bent | 954 ACTROS      |
|   |                   |                               |                 |
| <b>TM15000</b><br>   | 9454200138        | Brake Slack Adjuster          | 950 ACTROS      |
|   | 9424201338        | Right, Automatic              | 952 ACTROS      |
|   | 9424200838        | Repl. Haldex: 80009           | 953 ACTROS      |
|   | 6194200138        | ø14x145 / S-ABA / Double Bent | 954 ACTROS      |
|   |                   |                               |                 |
| <b>TM15107</b><br>   | 9454200238        | Brake Slack Adjuster          | 950 ACTROS      |
|   | 6554200038        | Left, Automatic               | 952 ACTROS      |
|   | 9424200238        | Repl. Haldex: 80000           | 953 ACTROS      |
|   | 3874200338        | ø14x145 / S-ABA / Double Bent | 954 ACTROS      |
|   |                   |                               |                 |
| <b>TM15104</b><br> | 9454200338        | Brake Slack Adjuster          | 950 ACTROS      |
|   | 9424200338        | Right, Automatic              | 952 ACTROS      |
|   | 3874200238        | Repl. Haldex: 80001           | 953 ACTROS      |
|   | 6554200138        | ø14x145 / S-ABA / Double Bent | 954 ACTROS      |
|   |                   |                               |                 |
| <b>TM15005</b><br> | 9454200938        | Brake Slack Adjuster          | 950 ACTROS      |
|   |                   | Left, Automatic               | 952 ACTROS      |
|   |                   | Repl. Haldex: 80030           | 953 ACTROS      |
|   |                   | ø14x145 / S-ABA / Double Bent | 954 ACTROS      |
|   |                   |                               |                 |
| <b>TM15255</b><br> | 9454201238        | Brake Slack Adjuster          | 950 ACTROS      |
|   |                   | Left, Automatic               | 952 ACTROS      |
|   |                   | Repl. Haldex: 80163           | 953 ACTROS      |
|   |                   | ø14x145 / S-ABA / Double Bent | 954 ACTROS      |
|   |                   |                               |                 |
| <b>TM15256</b><br> | 9454201338        | Brake Slack Adjuster          | 950 ACTROS      |
|   |                   | Right, Automatic              | 952 ACTROS      |
|   |                   | Repl. Haldex: 80164           | 953 ACTROS      |
|   |                   | ø14x145 / S-ABA / Double Bent | 954 ACTROS      |
|   |                   |                               |                 |












| Model / Details  | Description  | Replaces Ref. No: | TM No.  |
|--|--|-------------------|---|
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 | Brake Slack Adjuster<br>Left, Automatic<br>Repl. Haldex: 80165<br>ø14x145 / S-ABA / Double Bent  | 9454201038        | <b>TM15257</b><br>   |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 | Brake Slack Adjuster<br>Right, Automatic<br>Repl. Haldex: 80166<br>ø14x145 / S-ABA / Double Bent | 9454201138        | <b>TM15258</b><br>   |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 | Brake Slack Adjuster<br>Right, Automatic<br>Repl. Haldex: 80167<br>ø14x145 / S-ABA / Double Bent | 9454201438        | <b>TM15259</b><br>  |
| 958 AXOR 2<br>343 T2/L<br>346 L 1924<br>346 L 1928<br>346 LK 1924<br>346 LK 1928<br>346 LS 1924            | Brake Slack Adjuster<br>Left, Manuel<br>Repl. Haldex: 104 407 401<br>145 / +56mm                 | 3464201738        | <b>TM14923</b><br> |
| 958 AXOR 2<br>343 T2/L<br>346 L 1924<br>346 L 1928<br>346 LK 1924<br>346 LK 1928<br>346 LS 1924            | Brake Slack Adjuster<br>Right, Manuel<br>Repl. Haldex: 104 507 401<br>145 / +56mm                | 3464201838        | <b>TM13870</b><br> |
| 655 SK<br>307 O 305<br>307 O 307   | Brake Slack Adjuster<br>Automatic<br>Repl. Haldex: 70775<br>ø14x130x79° / Double Bent            | 3074200338        | <b>TM15007</b><br> |
| -396 OH SERIES   | Brake Slack Adjuster<br>Automatic<br>Repl. Haldex: 70706<br>ø14x115x61° / Double Bent            | 3054202638        | <b>TM14948</b><br> |





| TM No.  | Replaces Ref. No:        | Description  | Model / Details   |
|---|--------------------------|--|---|
| <b>TM37315</b><br>   | 3464201538               | Brake Slack Adjuster   | 653 MK  |
|   | 3894200338<br>6204200038 | Left, Automatic<br>Repl. Haldex: 70753<br>ø14x145x339° / Double<br>Bent  | 621 NG<br>624 NG<br>646 NG<br>649 NG<br>655 SK<br>656 SK  |
| <b>TM15103</b><br>   | 3074200138               | Brake Slack Adjuster   | 950 AXOR 2  |
|   |                          | Left, Automatic<br>Repl. Haldex: 70772<br>ø14x115x346° / Double<br>Bent  |   |
| <b>TM37316</b><br>   | 3074200238               | Brake Slack Adjuster   | 950 AXOR 2  |
|   |                          | Right, Automatic<br>Repl. Haldex: 70771<br>ø14x115x346° / Double<br>Bent |   |
| <b>TM37317</b><br> | 3464201638               | Brake Slack Adjuster   | 653 MK  |
|   | 9424200738               | Right, Automatic<br>Repl. Haldex: 70754<br>ø14x145x339° / Double<br>Bent | 621 NG<br>624 NG<br>646 NG<br>649 NG<br>655 SK<br>656 SK  |
| <b>TM13633</b><br> | 0004200092               | Repair Kit, Brake Slack Adjuster   | 958 ATEGO 2<br>950 AXOR 2   |
|   |                          | Repl. Haldex: 76046<br>ø14x160x155° / Double<br>Bent                     | 344 L 1113/L 1114<br>344 L 1118<br>344 LK 1113/LK 1114<br>344 LK 1118<br>344 LPO/OF 1113/1114   |
| <b>TM15493</b><br> | 3039930410               | Spring, Brake Slack Adjuster   | 338 LPS 1418<br>338 LS 1418   |
|   |                          | ø27x214  | 341 L 1112<br>341 L 1114<br>341 L 914<br>341 LA 1112<br>341 LK 1114                             |
| <b>TM14083</b><br> | 0004217287               | Dust Cover, Brake Adjuster   | 970 ATEGO<br>972 ATEGO<br>976 ATEGO<br>970 ATEGO 2<br>972 ATEGO 2<br>976 ATEGO 2<br>967 ATEGO 3 |
|   |                          | ø48x22,75  |   |



| Model / Details  | Description  | Replaces Ref. No:                                    | TM No.  |
|--|--|--|---|
| -  | Repair Kit, Brake Adjuster<br>Repl. Wabco: 12 999<br>287VT | 0004213890   | <b>TM37318</b><br>   |
| 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3 | Brake Disc<br>ø430x45/132,5xø211/<br>ø238x12xM14           | 942421212<br>9424211212<br>9424210912<br>9424230012  | <b>TM15094</b><br>   |
| 613 TOURISMO   | Brake Disc<br>438x45/135xø195/<br>ø235x10xM14              | 3564211012<br>3564210312<br>3564211212               | <b>TM15090</b><br>   |
| 375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>375 ATEGO 2<br>970 ATEGO 2<br>972 ATEGO 2          | Brake Disc<br>ø377x45/134xø105/<br>ø138x14xø14,5           | 9754210212<br>9754210012<br>9754210112               | <b>TM13592</b><br> |
| 375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>375 ATEGO 2<br>970 ATEGO 2<br>974 ATEGO 2          | Brake Disc<br>ø377x45/138,5xø176/<br>ø201x8xM14            | 9754230612<br>9754230312<br>9754230012               | <b>TM13598</b><br> |
| 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3 | Brake Disc<br>ø430x45/143,5xø131/<br>ø168x10xø21           | 9434210312<br>9434210412                             | <b>TM13745</b><br> |
| 934 ACTROS 2/3<br>963 ACTROS MP4<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>970 ATEGO 2<br>972 ATEGO 2  | Brake Disc<br>ø335x34/102,5xø91,5/<br>ø120x10xø14,5        | 9704210612<br>9704210112<br>9704210212<br>9704210012 | <b>TM13596</b><br> |

| TM No.  | Replaces Ref. No:                      | Description  | Model / Details  |
|---|--|--|--|
| <b>TM13601</b><br>   | 9704230412<br>9704230612               | Brake Disc<br>ø335x34x111/ø131/<br>ø177x8xM12x1,5                              | 979 ACCELO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>970 ATEGO 2<br>972 ATEGO 2<br>975 ATEGO 2         |
| <b>TM15089</b><br>   | 6137127082<br>6231000870<br>6274210012 | Brake Disc<br>ø432x45/135xø194/<br>ø220x10xM16x1,5                             | -  |
| <b>TM16247</b><br>   | 9704230212                             | Brake Disc<br>ø330x34/ø145xø177/<br>M12x1,5                                    | -  |
| <b>TM27719</b><br> | 910105014019                           | Screw, Brake Disc<br>M14x1,5/60  | 979 ACCELO<br>375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3     |
| <b>TM25128</b><br> | 9429902804<br>9429900004               | Screw, Brake Disc<br>M14x1,5/75  | 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3 |
| <b>TM37319</b><br> | 910105014009                           | Screw, Brake Disc<br>M14x1,5/70  | 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3 |
| <b>TM13623</b><br> | 0024200820<br>0024205520               | Kit, Brake Disc Pad<br>Repl. WVA: 29083 / 29030<br>/ 29113<br>249,5x118,2x28,2 | 613 TOURISMO   |



| Model / Details  | Description  | Replaces Ref. No:                                    | TM No.             |
|--|--|--|--------------------|
| 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3         | Kit, Brake Disc Pad<br>Repl. WVA: 29087 / 29059<br>/ 29061<br>/ 29108 / 29163 / 29179 /<br>29201 /<br>29202 / 29042 / 29106 /<br>29105 /<br>248x109x30 | 0044206020<br>0044201020<br>0034201620<br>0034202020 | <b>TM13795</b><br> |
| 375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>375 ATEGO 2<br>970 ATEGO 2<br>972 ATEGO 2                  | Kit, Brake Disc Pad<br>Repl. WVA: 29145 / 29093<br>/ 29094 /<br>29095 / 29096 / 29184 /<br>29197<br>210,4x92,4x30                                      | 0004210710<br>0004210810<br>0004215010<br>0024207820 | <b>TM13653</b><br> |
| 375 ACTROS<br>950 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3 | Kit, Brake Disc Pad<br>Repl. WVA: 29244 / 29245<br>207,6x111,7x30  | 0064201520   | <b>TM15703</b><br> |
| 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3         | Kit, Brake Disc Pad<br>Repl. WVA: 29246 / 29247<br>244,6x111,7x30  | 0064201420   | <b>TM15702</b><br> |
| 934 ACTROS 2/3<br>749 AIRMASTER<br>749 STEERMASTER   | Kit, Brake Disc Pad<br>Without E Mark, 4 pcs.<br>Brake Pad and<br>Accessory<br>Repl. WVA: 29158<br>210,7x107,1x30                                      | 0044207020   | <b>TM13622</b><br> |
| 669 T2/LN1<br>670 T2/LN1   | Spring Clamp, Brake Disc<br>Pad<br>97x90x16  | 0004213591   | <b>TM37320</b><br> |
| 906 SPRINTER<br>639 VIANO  | Sensor, Brake Disc Pad<br>Green<br>L: 109 mm   | 9065401417<br>9065401517                             | <b>TM15176</b><br> |





| TM No.  | Replaces Ref. No: | Description             | Model / Details |
|---|-------------------|-------------------------|-----------------|
| <b>TM15033</b><br>   | 0014202601        | Brake Caliper           | 375 ACTROS      |
|   | 0014205301        | Right                   | 950 ACTROS      |
|   | 0014207001        | Repl. Knorr: K003799    | 952 ACTROS      |
|   | 0024201583        | 22,5"                   | 953 ACTROS      |
|   |                   |                         | 954 ACTROS      |
|   |                   |                         | 930 ACTROS 2/3  |
|   |                   |                         | 932 ACTROS 2/3  |
| <b>TM15032</b><br>   | 0014202501        | Brake Caliper           | 375 ACTROS      |
|   | 0014205201        | Left                    | 950 ACTROS      |
|   | 0014206901        | Repl. Knorr: K003800    | 952 ACTROS      |
|   | 0024201483        | 22,5"                   | 953 ACTROS      |
|   |                   |                         | 954 ACTROS      |
|   |                   |                         | 930 ACTROS 2/3  |
|   |                   |                         | 932 ACTROS 2/3  |
| <b>TM14026</b><br>  | 0034209183        | Brake Caliper           | 934 ACTROS 2/3  |
|   | 0054202583        | Left                    | 749 AIRMASTER   |
|   | 9464202201        | Repl. Knorr: K012633    | 749 STEERMASTER |
|   |                   | 22,5"                   |                 |
| <b>TM14027</b><br> | 0034209283        | Brake Caliper           | 934 ACTROS 2/3  |
|   | 0054202683        | Right                   | 749 AIRMASTER   |
|   | 9464202301        | Repl. Knorr: K012634    | 749 STEERMASTER |
|   |                   | 22,5"                   |                 |
| <b>TM15869</b><br> | 0501005860        | Brake Caliper           | -               |
|   | 6274300090        | Left                    |                 |
|   |                   | Repl. Knorr: K003803    |                 |
|   |                   | 22,5"                   |                 |
| <b>TM16418</b><br> | 0501005859        | Brake Caliper           | -               |
|   | 6274300190        | Right                   |                 |
|   |                   | Repl. Knorr: K003804    |                 |
|   |                   | 22,5"                   |                 |
| <b>TM14031</b><br> | 0044207583        | Brake Caliper           | 375 ACTROS      |
|   | 0054200183        | Left                    | 950 ACTROS      |
|   |                   | Repl. Knorr: K052380K50 | 954 ACTROS      |
|   |                   | 22,5"                   | 930 ACTROS 2/3  |
|   |                   |                         | 932 ACTROS 2/3  |
|   |                   |                         | 933 ACTROS 2/3  |
|   |                   |                         | 934 ACTROS 2/3  |









| Model / Details  | Description  | Replaces Ref. No:                      | TM No.  |
|--|--|--|---|
| 375 ACTROS<br>950 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3 | Brake Caliper<br>Right<br>Repl. Knorr: K052381K50<br>22,5" | 0044207683<br>0054200283               | <b>TM14053</b><br>   |
| 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3         | Brake Caliper<br>Left<br>Repl. Knorr: K052390K50<br>22,5"  | 0044207183<br>0044209783               | <b>TM37321</b><br>   |
| 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3         | Brake Caliper<br>Right<br>Repl. Knorr: K052391K50<br>22,5" | 0044207283<br>0044209883               | <b>TM37322</b><br>  |
| 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS   | Brake Caliper<br>Left<br>Repl. Knorr: K046529K50<br>22,5"  | 0044208083<br>0054200683<br>9604200501 | <b>TM37323</b><br> |
| 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS   | Brake Caliper<br>Right<br>Repl. Knorr: K046528K50<br>22,5" | 0044207983<br>0054200583<br>9604200601 | <b>TM37324</b><br> |
| 375 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3<br>375 AXOR<br>375 AXOR 2   | Brake Caliper<br>Left<br>Repl. Knorr: K052382K50<br>22,5"  | 0044207783<br>9444201202               | <b>TM37325</b><br> |
| 375 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3<br>375 AXOR<br>374 AXOR 2   | Brake Caliper<br>Right<br>Repl. Knorr: K052383K50<br>22,5" | 0044207883<br>9444201302               | <b>TM37326</b><br> |





| TM No.  | Replaces Ref. No: | Description               | Model / Details |
|---|-------------------|---------------------------|-----------------|
| <b>TM37327</b><br>   | 0044207383        | Brake Caliper             | 375 ACTROS      |
|   | 9444207901        | Left                      | 950 ACTROS      |
|   | 9444208801        | Repl. Knorr: K052392K50   | 952 ACTROS      |
|   |                   | 22,5"                     | 953 ACTROS      |
|   |                   |                           | 954 ACTROS      |
|   |                   |                           | 930 ACTROS 2/3  |
|   |                   |                           | 932 ACTROS 2/3  |
| <b>TM37328</b><br>   | 0044207483        | Brake Caliper             | 375 ACTROS      |
|   | 9444208001        | Right                     | 950 ACTROS      |
|   | 9444208901        | Repl. Knorr: K052393K50   | 952 ACTROS      |
|   |                   | 22,5"                     | 953 ACTROS      |
|   |                   |                           | 954 ACTROS      |
|   |                   |                           | 930 ACTROS 2/3  |
|   |                   |                           | 932 ACTROS 2/3  |
| <b>TM15079</b><br>   | 0024204983        | Brake Caliper             | 375 ACTROS      |
|   | 0044202583        | Left                      | 950 ACTROS      |
|   |                   | Repl. Knorr: K003782      | 952 ACTROS      |
|   |                   | 22,5"                     | 953 ACTROS      |
|   |                   |                           | 954 ACTROS      |
|   |                   |                           | 930 ACTROS 2/3  |
|   |                   |                           | 932 ACTROS 2/3  |
| <b>TM15080</b><br> | 0024205083        | Brake Caliper             | 375 ACTROS      |
|   | 0044202683        | Right                     | 950 ACTROS      |
|   |                   | Repl. Knorr: K003781      | 952 ACTROS      |
|   |                   | 22,5"                     | 953 ACTROS      |
|   |                   |                           | 954 ACTROS      |
|   |                   |                           | 930 ACTROS 2/3  |
|   |                   |                           | 932 ACTROS 2/3  |
| <b>TM15031</b><br> | 0004211106        | Carrier, Brake Caliper    | 375 ACTROS      |
|   |                   | Knorr Type, Front, Front, | 950 ACTROS      |
|   |                   | Left/Right                | 952 ACTROS      |
|   |                   | 22,5"                     | 953 ACTROS      |
|   |                   |                           | 954 ACTROS      |
|   |                   |                           | 930 ACTROS 2/3  |
|   |                   |                           | 932 ACTROS 2/3  |
| <b>TM37329</b><br> | -                 | Carrier, Brake Caliper    | -               |
|   |                   | Knorr Type, Front, Front, |                 |
|   |                   | Left/Right                |                 |
|   |                   | 22,5"                     |                 |
| <b>TM15027</b><br> | 0004230606        | Carrier, Brake Caliper    | 375 ACTROS      |
|   |                   | Knorr Type, Front, Front, | 950 ACTROS      |
|   |                   | Left/Right                | 952 ACTROS      |
|   |                   | 22,5"                     | 953 ACTROS      |
|   |                   |                           | 954 ACTROS      |
|   |                   |                           | 930 ACTROS 2/3  |
|   |                   |                           | 932 ACTROS 2/3  |



| Model / Details  | Description  | Replaces Ref. No: | TM No.  |
|--|--|-------------------|---|
| -  | Carrier, Brake Caliper<br>Knorr Type, Left/Right<br>22,5"                  | -                 | <b>TM37330</b><br>   |
| 382 OH SERIES<br>382 O 500   | Carrier, Brake Caliper<br>Knorr Type, Rear Left<br>22,5"                   | 0004213806        | <b>TM15708</b><br>   |
| 382 OH SERIES<br>382 O 500   | Carrier, Brake Caliper<br>Knorr Type, Rear Right<br>22,5"                  | 0004213706        | <b>TM37331</b><br>   |
| 375 ACTROS<br>950 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3 | Carrier, Brake Caliper<br>Knorr Type, Rear Right<br>22,5"                  | 0004231006        | <b>TM37332</b><br> |
| -  | Carrier, Brake Caliper<br>Knorr Type, Front, Front,<br>Left/Right<br>22,5" | -                 | <b>TM37333</b><br> |
| -  | Carrier, Brake Caliper<br>Knorr Type, Left/Right<br>22,5"                  | -                 | <b>TM37334</b><br> |
| 375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>375 ATEGO 2<br>970 ATEGO 2<br>972 ATEGO 2                  | Carrier, Brake Caliper<br>Knorr Type, Left/Right<br>19,5"                  | 0004213106        | <b>TM37335</b><br> |












| TM No.             | Replaces Ref. No: | Description   | Model / Details  |
|--------------------|-------------------|---|--|
| <b>TM37336</b><br> | -                 | Carrier, Brake Caliper<br>Knorr Type, Left/Right<br>19,5" | -  |
| <b>TM37337</b><br> | 0004213006        | Carrier, Brake Caliper<br>Knorr Type, Left/Right<br>17,5" | 979 ACCELO<br>934 ACTROS 2/3<br>963 ACTROS MP4<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>970 ATEGO 2 |
| <b>TM37338</b><br> | -                 | Cover, Brake Caliper<br>3 Cable, For Mercedes<br>131x61,5 | -  |
| <b>TM37339</b><br> | -                 | Cover, Brake Caliper<br>3 Cable, For Mercedes             | -  |
| <b>TM37340</b><br> | -                 | Cover, Brake Caliper<br>3 Cable, For Mercedes             | -  |
| <b>TM37341</b><br> | -                 | Cover, Brake Caliper<br>3 Cable, For Mercedes             | -  |
| <b>TM37342</b><br> | -                 | Cover, Brake Caliper<br>3 Cable, For Mercedes             | -  |



| Model / Details   | Description  | Replaces Ref. No:                                    | TM No.  |
|---|--|--|---|
| 375 ACTROS<br>950 ACTROS<br>953 ACTROS<br>930 ACTROS 2/3<br>375 ATEGO<br>950 AXOR 2<br>695 L 1622 / L 1620                      | Repair Kit, Brake Caliper<br>Repl. Knorr: K000696          | 0024200383   | <b>TM15753</b><br>   |
| 970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>970 ATEGO 2<br>972 ATEGO 2<br>975 ATEGO 2<br>976 ATEGO 2                                 | Repair Kit, Brake Caliper<br>Repl. Knorr: II339680062      | 0004201282<br>0004202282<br>0004200782<br>0014205283 | <b>TM15745</b><br>   |
| 934 ACTROS 2/3<br>382 OH SERIES<br>749 AIRMASTER<br>749 STEERMASTER<br>634 O 500<br>634 O 500 RSD /<br>2736/8X2/30<br>634 TOURO | Repair Kit, Brake Caliper<br>Repl. Knorr: K010603<br>ø69,3 | 0004202382<br>0004204082<br>0004204982               | <b>TM14549</b><br>  |
| 695 L 1622 / L 1620<br>382 OH SERIES<br>693 1938 S<br>693 1944 S<br>382 O 500<br>628 CITARO                                     | Repair Kit, Brake Caliper<br>Repl. Knorr: K010604<br>ø74,3 | 0004200682<br>0004203982<br>0004204882               | <b>TM13808</b><br> |
| 905 SPRINTER<br>668 VARIO<br>670 VARIO  | Repair Kit, Brake Caliper<br>Repl. Meritor: SJ1035         | 0004200476   | <b>TM15749</b><br> |
| 398 LO 814<br>669 T2/LN1<br>670 T2/LN1<br>688 1114<br>688 709<br>688 912<br>688 913   | Repair Kit, Brake Caliper<br>Repl. Meritor: SP8902         | 0004211463   | <b>TM17505</b><br> |
| 613 TOURISMO  | Repair Kit, Brake Caliper<br>Repl. Meritor: SJ1213         | 0004200176   | <b>TM14541</b><br> |












| TM No.  | Replaces Ref. No: | Description   | Model / Details   |
|---|-------------------|---|---|
| <b>TM37343</b><br>   | 0004200276        | Repair Kit, Brake Caliper<br>Repl. Meritor: MCK1213       | 613 TOURISMO  |
| <b>TM37344</b><br>   | 0004210880        | Repair Kit, Brake Caliper<br>Repl. Wabco: 12 999<br>552VT | 612 O 405   |
| <b>TM15750</b><br>  | 0004206883        | Repair Kit, Brake Caliper<br>Repl. Wabco: 12 999<br>197VT | 358 L 1113 B<br>601 208/210<br>602 307 D/308 D<br>602 308/310   |
| <b>TM16685</b><br> | 0004200482        | Repair Kit, Brake Caliper<br>Repl. Wabco: 12 999<br>543VT | 690 SPRINTER<br>901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER<br>909 SPRINTER<br>667 VARIO     |
| <b>TM37345</b><br> | 0004200982        | Repair Kit, Brake Caliper<br>Repl. Wabco: 12 999<br>551VT | 612 O 405   |
| <b>TM37346</b><br> | 0004202182        | Repair Kit, Brake Caliper<br>Repl. Knorr: K000132         | 375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>375 ATEGO 2<br>970 ATEGO 2<br>972 ATEGO 2                 |
| <b>TM37347</b><br> | 0025865342        | Repair Kit, Brake Caliper                                 | 358 L 1113 B<br>358 T2/L<br>611 T1/TN<br>601 207 D/208 D<br>601 208/210<br>601 209 D/210 D<br>602 307 D/308 D |



















| Model / Details   | Description   | Replaces Ref. No: | TM No.  |
|---|---|-------------------|---|
| BM MODEL<br>690 SPRINTER<br>903 SPRINTER<br>904 SPRINTER<br>909 SPRINTER  | Repair Kit, Brake Caliper                                 | 0014202583        | <b>TM15712</b><br>   |
| 669 T2/LN1<br>670 T2/LN1<br>677 LK/LN2<br>679 LK/LN2<br>651 MK<br>652 MK<br>653 MK                                  | Repair Kit, Brake Caliper                                 | 0004218386        | <b>TM15713</b><br>   |
| BM MODEL<br>690 SPRINTER<br>901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>909 SPRINTER<br>638 VITO<br>638 V-CLASS | Repair Kit, Brake Caliper                                 | 0014202383        | <b>TM13788</b><br>  |
| 901 SPRINTER<br>902 SPRINTER  | Repair Kit, Brake Caliper                                 | 0014202483        | <b>TM15752</b><br> |
| 405 UNIMOG<br>437 UNIMOG  | Repair Kit, Brake Caliper<br>Repl. Wabco: 12 999<br>734VT | 4054200076        | <b>TM15746</b><br> |
| 405 UNIMOG<br>437 UNIMOG  | Repair Kit, Brake Caliper<br>Repl. Wabco: 12 999<br>733VT | 4054200083        | <b>TM15747</b><br> |
| 669 T2/LN1<br>670 T2/LN1  | Repair Kit, Brake Caliper                                 | 0004201444        | <b>TM37348</b><br> |





| TM No.  | Replaces Ref. No:                      | Description  | Model / Details  |
|---|--|--|--|
| <b>TM14551</b><br>   | 0004216174<br>0004204682<br>0004203482 | Repair Kit, Brake Caliper<br>Repl. Knorr: K001470              | 970 ATEGO 2<br>382 OH SERIES<br>749 AIRMASTER<br>749 STEERMASTER<br>634 O 500<br>634 O 500 RSD /<br>2736/8X2/30<br>634 TOURO |
| <b>TM37349</b><br>   | 0004201182                             | Repair Kit, Brake Caliper<br>Repl. Knorr: I1358510062          | -  |
| <b>TM37350</b><br>  | 0004201382                             | Repair Kit, Brake Caliper<br>Repl. Knorr: I1370760065<br>ø74,3 | 979 ACCELO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>970 ATEGO 2<br>972 ATEGO 2<br>975 ATEGO 2                               |
| <b>TM15748</b><br> | 0004202582                             | Repair Kit, Brake Caliper<br>Repl. Knorr: K000133              | 979 ACCELO<br>934 ACTROS 2/3<br>963 ACTROS MP4<br>375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO                           |
| <b>TM15833</b><br> | 0004230316                             | Repair Kit, Brake Caliper<br>Repl. Knorr: K046523K50<br>ø69,2  | 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3                       |
| <b>TM37351</b><br> | -                                      | Repair Kit, Brake Caliper<br>Knorr Type, New Type              | -  |
| <b>TM37352</b><br> | -                                      | Repair Kit, Brake Caliper<br>Knorr Type, Old Type              | -  |










| Model / Details  | Description  | Replaces Ref. No: | TM No.  |
|--|--|-------------------|---|
| 375 ATEGO<br>375 ATEGO 2<br>967 ATEGO 3<br>970 ATEGO 2<br>970 ATEGO<br>972 ATEGO 2<br>972 ATEGO- | Repair Kit, Brake Caliper<br>Repl. Knorr: K001925          | 0004204382        | <b>TM15705</b><br>   |
| -  | Repair Kit, Brake Caliper<br>Repl. Knorr: K001929<br>ø69,3 | 0004204282        | <b>TM37353</b><br>   |
| 375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>375 ATEGO 2<br>970 ATEGO 2<br>972 ATEGO 2    | Repair Kit, Brake Caliper<br>Repl. Knorr: K001928          | 0004204182        | <b>TM37354</b><br>  |
| VARIO  | Repair Kit, Brake Caliper<br>Repl. Meritor: SP8597         | -                 | <b>TM37355</b><br> |
| -  | Repair Kit, Brake Caliper<br>Repl. Meritor: SP8566         | -                 | <b>TM37356</b><br> |
| O 350<br>O 403<br>O 404  | Repair Kit, Brake Caliper<br>Repl. Meritor: SJ1212         | -                 | <b>TM37357</b><br> |
| -  | Repair Kit, Brake Caliper<br>H: 25 mm                      | -                 | <b>TM37358</b><br> |












| TM No.  | Replaces Ref. No: | Description   | Model / Details  |
|---|-------------------|---|--|
| <b>TM37359</b><br>   | -                 | Repair Kit, Brake Caliper<br>H: 25 mm                 | -  |
| <b>TM37360</b><br>   | -                 | Repair Kit, Brake Caliper<br>H: 25 mm                 | -  |
| <b>TM37361</b><br>  | 0501210167        | Repair Kit, Brake Caliper<br>Repl. Knorr: II179320062 | -  |
| <b>TM37362</b><br> | -                 | Repair Kit, Brake Caliper<br>Knorr Type<br>ø39/ø32x80 | -  |
| <b>TM37363</b><br> | -                 | Repair Kit, Brake Caliper<br>Knorr Type<br>ø39/ø32x80 | -  |
| <b>TM37364</b><br> | -                 | Repair Kit, Brake Caliper<br>Knorr Type<br>ø39        | -  |
| <b>TM37365</b><br> | -                 | Repair Kit, Brake Caliper<br>Knorr Type<br>ø39/ø32x80 | 970 ATEGO 2<br>382 OH SERIES<br>749 AIRMASTER<br>749 STEERMASTER<br>634 O 500<br>634 O 500 RSD /<br>2736/8X2/30<br>634 TOURO |



| Model / Details   | Description   | Replaces Ref. No: | TM No.  |
|---|---|-------------------|---|
| -   | Repair Kit, Brake Caliper<br>Knorr Type<br>ø35/ø32x80 | -                 | <b>TM37366</b><br>   |
| 970 ATEGO 2<br>382 OH SERIES<br>749 AIRMASTER<br>749 STEERMASTER<br>634 O 500<br>634 O 500 RSD /<br>2736/8X2/30 | Repair Kit, Brake Caliper<br>Knorr Type<br>ø39        | -                 | <b>TM37367</b><br>   |
| -   | Repair Kit, Brake Caliper<br>Knorr Type<br>ø35        | -                 | <b>TM37368</b><br>  |
| 900 SPRINTER<br>906 SPRINTER  | Repair Kit, Brake Caliper                             | 0004230563        | <b>TM15751</b><br> |
| 900 SPRINTER<br>906 SPRINTER  | Repair Kit, Brake Caliper                             | 0004230663        | <b>TM37369</b><br> |
| 900 SPRINTER<br>906 SPRINTER<br>639 VIANO   | Repair Kit, Brake Caliper                             | 0004210850        | <b>TM15754</b><br> |
| 900 SPRINTER<br>906 SPRINTER<br>639 VIANO   | Repair Kit, Brake Caliper                             | 0004210850S       | <b>TM37370</b><br> |





| TM No.  | Replaces Ref. No:                      | Description                                       | Model / Details  |
|---|--|---|--|
| <b>TM37371</b><br>   | 0004205082<br>0004205682               | Repair Kit, Brake Caliper<br>Repl. Knorr: K010766 | 934 ACTROS 2/3<br>749 STEERMASTER  |
| <b>TM15477</b><br>   | 4614230120                             | Brake Dust Cover<br>Left<br>ø77xø305x41           | 690 SPRINTER<br>901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>909 SPRINTER                               |
| <b>TM15478</b><br>   | 4614230220                             | Brake Dust Cover<br>Right<br>ø77xø305x41          | 690 SPRINTER<br>901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>909 SPRINTER                               |
| <b>TM15347</b><br> | 6594201644<br>6594201744               | Brake Dust Cover<br>ø225xø452x53                  | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 |
| <b>TM37372</b><br> | 3574201744<br>3574201844<br>3074210120 | Brake Dust Cover<br>ø265xø452x15,5                | 972 ATEGO<br>976 ATEGO<br>970 ATEGO 2<br>972 ATEGO 2<br>976 ATEGO 2<br>967 ATEGO 3<br>343 T2/L             |
| <b>TM37373</b><br> | 4474210000                             | Brake Dust Cover<br>Left<br>ø335x10               | 447 VITO - 447 V CLASS -<br>448 VITO - 448<br>V CLASS  |
| <b>TM37374</b><br> | 4474210100                             | Brake Dust Cover<br>Right<br>ø335x10              | 447 VITO - 447 V CLASS -<br>448 VITO - 448<br>V CLASS  |












| Model / Details   | Description   | Replaces Ref. No:          | TM No.  |
|---|---|----------------------------|---|
| 906 SPRINTER<br>900 SPRINTER  | Brake Dust Cover<br>Rear Left, Rear Right<br>ø101xø350/26 | 9064230420                 | <b>TM15476</b><br>   |
| 375 AXOR<br>374 AXOR 2<br>944 AXOR 2<br>958 AXOR 2<br>634 IBC-FAHRG-<br>ESTELL-BUGGY 2-ACHS-<br>ER NAFTA  | Exhaust Brake   | 4571402253S                | <b>TM37375</b><br>   |
| 375 AXOR<br>940 AXOR 2<br>942 AXOR 2<br>943 AXOR 2<br>944 AXOR 2<br>634 IBC-FAHRGESTELL<br>2-ACHSER<br>634 IBC-FAHRGESTELL<br>3-ACHSER                      | Exhaust Brake   | 4571403053S                | <b>TM37376</b><br>  |
| 375 ACTROS<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>375 ATEGO 2<br>958 ATEGO 2  | Exhaust Brake   | 9061400353S<br>9060900128S | <b>TM37377</b><br> |
| 375 ATEGO<br>970 ATEGO 2<br>695 L 1622/1624<br>384 OF SERIES<br>368 OH SERIES<br>405 UNIMOG<br>437 UNIMOG   | Exhaust Brake   | 9041400253S                | <b>TM37378</b><br> |
| 684 1518 INDONESIA<br>684 1518K INDONESIA<br>684 1521 INDONESIA<br>684 1521AK INDONESIA<br>684 1521K INDONESIA<br>684 1521S INDONESIA<br>684 2421 INDONESIA | Exhaust Brake   | 3661403053                 | <b>TM37379</b><br> |
| 970 ATEGO<br>972 ATEGO<br>976 ATEGO<br>375 ATEGO 2<br>970 ATEGO 2<br>972 ATEGO 2<br>974 ATEGO 2   | Exhaust Brake   | 9061400254<br>9061400653   | <b>TM02251</b><br> |





| TM No.  | Replaces Ref. No:                      | Description                            | Model / Details  |
|---|--|--|--|
| <b>TM37380</b><br>   | 9040900128                             | Exhaust Brake                          | 979 ACCELO<br>375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>958 ATEGO 2                 |
| <b>TM37381</b><br>   | 5411404353                             | Exhaust Brake                          | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 |
| <b>TM37382</b><br>  | 5411405353<br>5411408353               | Exhaust Brake                          | 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3                                       |
| <b>TM37383</b><br> | 5411403153                             | Exhaust Brake                          | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 |
| <b>TM02583</b><br> | 5411400063<br>5411400163<br>5411400763 | Throttle, Exhaust Brake                | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 |
| <b>TM37384</b><br> | 9061400063<br>9061400163<br>9061400263 | Throttle, Exhaust Brake<br>For 202.060 | 375 ACTROS<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>375 ATEGO 2<br>958 ATEGO 2               |
| <b>TM02122</b><br> | 0004305926<br>0004306026<br>0004307926 | Cylinder, Exhaust Brake                | 979 ACCELO<br>375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>970 ATEGO 2                 |



| Model / Details  | Description   | Replaces Ref. No:                                    | TM No.  |
|--|---|--|---|
| 979 ACCELO<br>375 ACTROS<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>375 ATEGO 2                        | Cylinder, Exhaust Brake   | 0004307026<br>0004307426<br>0004308126               | <b>TM01961</b><br>   |
| 314 LP<br>316 LP<br>363 LP 2226/6X4<br>363 LP 2232/6X4<br>363 LPB 2226/6X4<br>363 LPK 2226/6X4<br>363 LPK 2232/6X4 | Cylinder, Exhaust Brake<br>Repl. Wabco: 421 429<br>003 0<br>Stroke: 48 / Con-Rod:<br>M8 / Max, Operating<br>Pres,: 8,5 bar / Port<br>Threads: M12x1,5   | 0004301926<br>0004304826<br>0004304926<br>0004303026 | <b>TM01476</b><br>   |
| 336 LP 1924<br>336 LPS 1924<br>338 L 1418<br>338 LK 1418<br>338 LP 1418<br>338 LPS 1418<br>338 LS 1418             | Cylinder, Exhaust Brake<br>Repl. Wabco: 421 411<br>300 0<br>Stroke: 85 / Con-Rod:<br>M12 / Max, Operating<br>Pres,: 10 bar / Port<br>Threads: M12x1,5   | 0004303426<br>0004300126                             | <b>TM01835</b><br>   |
| 958 AXOR 2<br>693 1938<br>693 1938 S<br>693 1944 S<br>382 O 500<br>634 O 500<br>634 O 500 RSD /<br>2736/8X2/30     | Cylinder, Exhaust Brake<br>ø50 x M10 - Strok 48   | 0001400459<br>0001400359<br>0001400859<br>0001400759 | <b>TM01927</b><br> |
| 979 ACCELO<br>667 T2/LN1<br>668 T2/LN1<br>669 T2/LN1<br>670 T2/LN1<br>688 L 710<br>688 710                         | Cylinder, Exhaust Brake   | 0001440718   | <b>TM37385</b><br> |
| 979 ACCELO<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3             | Ball Joint, Exhaust Brake   | 5419910015   | <b>TM25100</b><br> |
| 88 L 1929<br>388 L 1935<br>388 L 1938<br>388 L 1945<br>388 L 2635/6X4/54<br>388 LK 2635/6X4/40<br>388 LS 1929      | Service Brake Chamber<br>Wabco Type, For Drum<br>Brake, Front<br>Repl. Knorr: BZ3538<br>Type: 24, Stroke: 57,<br>Port threads: M16x1,5<br>Port: M16x1,5 | 0074208818<br>0004208924                             | <b>TM13790</b><br> |








| TM No.  | Replaces Ref. No:                                    | Description  | Model / Details   |
|---|--|--|---|
| <b>TM13733</b><br>   | 0064205224   | Service Brake Chamber<br>Wabco Type, For Disc<br>Brake, Rear<br>Repl. Wabco: 423 104<br>710 0<br>Type: 16, Stroke: 57, Push-<br>rod thread: M16x1,5, port:<br>M16x1,5                  | 934 ACTROS 2/3<br>970 ATEGO 2<br>405 UNIMOG   |
| <b>TM13751</b><br>   | 0074201224   | Service Brake Chamber<br>Wabco Type, For Disc<br>Brake, Rear<br>Repl. Wabco: 423 505<br>000 0<br>Type: 20, Stroke: 62, Push-<br>rod thread: M16x1,5, port:<br>M16x1,5                  | 934 ACTROS 2/3<br>970 ATEGO 2   |
| <b>TM13752</b><br>  | 0074201424   | Service Brake Chamber<br>Wabco Type, For Disc<br>Brake, Rear<br>Repl. Wabco: 423 506<br>001 0<br>Type: 24, Stroke: 64, Push-<br>rod thread: M16x1,5, port:<br>M16x1,5                  | 934 ACTROS 2/3<br>970 ATEGO 2   |
| <b>TM15015</b><br> | 0074208718<br>0004207624                             | Service Brake Chamber<br>Wabco Type, For Drum<br>Brake, Front<br>Repl. Wabco: 423 105<br>111 0<br>Type: 20, Stroke: 57, Port<br>threads: M16x1,5 Port:<br>M16x1,5                      | 343 T2/L<br>343 T2/LN1<br>346 L 1924<br>346 L 1928<br>346 LK 1924<br>346 LK 1928<br>346 LS 1924     |
| <b>TM14636</b><br> | 0004209124<br>0004207424<br>0004207524<br>0004209224 | Service Brake Chamber<br>Wabco Type, For Drum<br>Brake, Front<br>Repl. Wabco: 423 106<br>900 0<br>Type: 24, Stroke: 75, Push-<br>rod thread: M16x1,5, port:<br>M16x1,5                 | 336 LP 1924<br>336 LPS 1924<br>343 T2/LN1<br>346 L 1924<br>346 L 1928<br>346 LK 1924<br>346 LK 1928 |
| <b>TM14666</b><br> | 0004208024   | Service Brake Chamber<br>Wabco Type, For Drum<br>Brake,<br>Without Repair Kit<br>Repl. Wabco: 423 107<br>900 0<br>Type: 30, Stroke: 75, Push-<br>rod thread: M16x1,5, port:<br>M16x1,5 | -   |
| <b>TM14291</b><br> | 0004209924<br>0014200224<br>0014200624<br>0014200824 | Service Brake Chamber<br>Wabco Type, For Drum<br>Brake, Front<br>Repl. Wabco: 423 104<br>900 0<br>Type: 16, Stroke: 75, Push-<br>rod thread: M12x1,5, port:<br>M16x1,5                 | 650 MK<br>616 NG<br>684 1521AK INDONESIA<br>684 917 AK INDONESIA                                    |



| Model / Details  | Description   | Replaces Ref. No:                      | TM No.  |
|--|---|--|---|
| -  | Service Brake Chamber<br>Wabco Type, For Drum<br>Brake, Front<br>Repl. Wabco: 423 105<br>900 0<br>Type: 20, Stroke: 75, Push-<br>rod thread: M16x1,5, port:<br>M16x1,5                                      | 0024206518<br>6984203721<br>6994200724 | <b>TM13864</b><br>   |
| 336 LP 1924<br>336 LPS 1924  | Service Brake Chamber<br>Wabco Type, For Drum Brake, Rear<br>Repl. Wabco: 423 106 408 0 S<br>Type 24, Stroke 57, Central Port,<br>Push Rod Lenght 34mm, Lateral<br>Port M22x1,5, Port/Clamp Angle<br>0°/45° | 0014204324S                            | <b>TM37386</b><br>   |
| 934 ACTROS 2/3<br>970 ATEGO 2<br>749 AIRMASTER<br>749 STEERMASTER  | Service Brake Chamber<br>Wabco Type, For Disc<br>Brake<br>Repl. Wabco: 423 110<br>710 0<br>Type: 22, Stroke: 62,<br>Port: M16x1,5   | 0074201324                             | <b>TM37387</b><br>   |
| 375 ATEGO<br>375 ATEGO 2<br>970 ATEGO 2<br>972 ATEGO 2<br>970 ATEGO<br>975 ATEGO 2<br>974 ATEGO 2                                    | Service Brake Chamber<br>Knorr Type, For Disk<br>Brake, Front<br>Repl. Knorr: BS3301<br>Type: 16, Stroke: 57  | 0054203924<br>0054202924               | <b>TM37388</b><br> |
| -  | Diaphragm, Brake Cham-<br>ber<br>Repl. Wabco: 897 120<br>492 4<br>Type 9, Short Strok   | 0001440028                             | <b>TM13980</b><br> |
| 308 L 608 E,L 708 E<br>341 L 1114<br>341 L 914<br>341 LA 1114<br>341 LK 1114<br>341 LO 1114<br>341 LS 1114                           | Diaphragm, Brake Cham-<br>ber<br>Repl. Wabco: 897 120<br>505 4<br>Type 12, Short Strok  | 0004311728                             | <b>TM13634</b><br> |
| 958 ATEGO 2<br>338 LPS 1418<br>338 LS 1418<br>345 L 1313,1314<br>345 L 1313,1314,1316<br>345 L 1313,1316<br>345 L 1316,L 1317,L 1318 | Diaphragm, Brake Cham-<br>ber<br>Repl. Wabco: 897 120<br>510 4<br>Type 16, Short Strok  | 0004212986                             | <b>TM13636</b><br> |





| TM No.  | Replaces Ref. No: | Description   | Model / Details  |
|---|-------------------|---|--|
| <b>TM13757</b><br> | 0004310728        | Diaphragm, Brake Chamber<br>Repl. Wabco: 897 120<br>520 4<br>Type 20, Short Strok | 972 ATEGO<br>976 ATEGO<br>958 ATEGO 2<br>970 ATEGO 2<br>972 ATEGO 2<br>976 ATEGO 2<br>343 T2/L             |
| <b>TM13756</b><br> | 0004212086        | Diaphragm, Brake Chamber<br>Repl. Wabco: 897 120<br>530 4<br>Type 24, Short Strok | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 |
| <b>TM13635</b><br> | 0004231286        | Diaphragm, Brake Chamber<br>Repl. Wabco: 897 120<br>540 4<br>Type 30, Short Strok | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 |





















| Model / Details  | Description   | Replaces Ref. No:        | TM No.  |
|--|---|--------------------------|---|
| -  | Diaphragm, Brake Chamber<br>Repl. Wabco: 897 120<br>550 4<br>Type 36, Short Strok | -                        | <b>TM37389</b><br>   |
| 345 L 1516,L 1517,L 1518<br>345 L 1518 ,LS 1518<br>351 L 1514<br>351 L 1518<br>351 L 1521<br>351 L 1526<br>351 LK 1514 | Diaphragm, Brake Chamber<br>Repl. Wabco: 897 120<br>516 4<br>Type 16, Long Strok  | 0004312028               | <b>TM14670</b><br>   |
| -  | Diaphragm, Brake Chamber<br>Repl. Wabco: 897 120<br>526 4<br>Type 20, Long Strok  | -                        | <b>TM37390</b><br>   |
| 952 ACTROS<br>932 ACTROS 2/3<br>934 ACTROS 2/3<br>346 L 1924<br>346 LA 1924<br>346 LAK 1924<br>346 LAS 1924            | Diaphragm, Brake Chamber<br>Repl. Wabco: 897 120<br>536 4<br>Type 24, Long Strok  | 0004233486<br>0004313486 | <b>TM15597</b><br> |
| -  | Diaphragm, Brake Chamber<br>Repl. Wabco: 897 120<br>546 4<br>Type 30, Long Strok  | -                        | <b>TM37391</b><br> |
| 900 SPRINTER<br>906 SPRINTER   | Hose, Brake Chamber<br>L: 440 mm  | 9064280535<br>9064281235 | <b>TM15606</b><br> |
| 611 T1/TN<br>667 T2/LN1<br>668 T2/LN1<br>669 T2/LN1<br>670 T2/LN1<br>601 207 D/208 D<br>601 208/210                    | Hose, Brake Chamber   | 0014289535<br>0024287735 | <b>TM15609</b><br> |





| <i>TM No.</i>   | <i>Replaces Ref. No:</i> | <i>Description</i>           | <i>Model / Details</i>   |
|---|--------------------------|------------------------------|--|
| <b>TM15610</b>  | 9064280335               | Hose, Brake Chamber<br>Rear  | 900 SPRINTER<br>906 SPRINTER   |
|    |                          |                              |  |
| <b>TM37393</b>  | 9064280635               | Hose, Brake Chamber<br>Front | 906 SPRINTER   |
|    |                          |                              |  |
| <b>TM37394</b>  | 9064280835               | Hose, Brake Chamber<br>Rear  | 906 SPRINTER   |
|    |                          |                              |  |
| <b>TM15605</b>  | 9014280435               | Hose, Brake Chamber          | 690 SPRINTER<br>901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER<br>905 SPRINTER<br>909 SPRINTER |
|  |                          |                              |  |
| <b>TM37395</b>  | 9014280535               | Hose, Brake Chamber          | BM MODEL<br>901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER   |
|  |                          |                              |  |
| <b>TM37396</b>  | 0004200848<br>6744200848 | Hose, Brake Chamber          | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>934 ACTROS 2/3   |
|  |                          |                              |  |
| <b>TM15594</b>  | 0004203148<br>9414200548 | Hose, Brake Chamber          | 950 ACTROS<br>952 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>934 ACTROS 2/3<br>375 AXOR     |
|  |                          |                              |  |



| Model / Details   | Description  | Replaces Ref. No:                                    | TM No.  |
|---|--|--|---|
| 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3      | Hose, Brake Chamber  | 0004203048<br>6554203548                             | <b>TM15593</b><br>   |
| 950 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>934 ACTROS 2/3<br>940 AXOR 2<br>950 AXOR 2<br>954 AXOR 2      | Hose, Brake Chamber<br>Front Axle<br>L : 510 mm  | 0004201148<br>0004200748<br>9414200348<br>6744200748 | <b>TM37397</b><br>   |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3  | Hose, Brake Chamber<br>600 mm  | 0004299535<br>3844207248<br>3844209848<br>3894205648 | <b>TM15587</b><br>  |
| BM MODEL<br>625 NG<br>625 SK<br>371 2624K,2627K3027<br>6X4/38,5OTOMARSAN/<br>TUERKEI<br>371 3031 K/6X4/38,5 | Spring Brake Chamber<br>Wabco Type, For Drum<br>Brake,<br>Diaphragm-Piston, Without<br>Repair Kit<br>Repl. Wabco: 925 321<br>160 0 | 0084202318   | <b>TM37398</b><br> |
| 652 MK<br>653 MK<br>617 NG<br>619 NG<br>625 NG<br>649 NG<br>625 SK  | Spring Brake Chamber<br>Wabco Type, For Drum<br>Brake,<br>Diaphragm-Piston, Without<br>Repair Kit<br>Repl. Wabco: 925 321<br>164 7 | 0104201918   | <b>TM37399</b><br> |
| 934 ACTROS 2/3<br>970 ATEGO 2   | Spring Brake Chamber<br>Wabco Type, For Disc<br>Brake,<br>Diaphragm-Piston, Left,<br>Rear<br>Repl. Wabco: 925 464<br>500 0         | 0184205318   | <b>TM15221</b><br> |
| 934 ACTROS 2/3<br>970 ATEGO 2   | Spring Brake Chamber<br>Wabco Type, For Disc<br>Brake,<br>Diaphragm-Piston, Right,<br>Rear<br>Repl. Wabco: 925 464<br>501 0        | 0184205218   | <b>TM15222</b><br> |






| TM No.  | Replaces Ref. No: | Description                             | Model / Details                        |
|---|-------------------|---|--|
| <b>TM14438</b><br>   | 0154208018        | Spring Brake Chamber                    | 375 ACTROS                             |
|   | 0194205818        | Wabco Type, For Disc                    | 950 ACTROS                             |
|   | 0204205918        | Brake,                                  | 952 ACTROS                             |
|   | 0154206218        | Diaphragm-Piston, Right,<br>Rear        | 953 ACTROS<br>954 ACTROS               |
|   |                   | Repl. Wabco: 925 484<br>021 0           |  |
| <b>TM15392</b><br>   | 0154203318        | Spring Brake Chamber                    | 375 ACTROS                             |
|   | 0194205318        | Wabco Type, For Disc                    | 950 ACTROS                             |
|   |                   | Brake,                                  | 952 ACTROS                             |
|   |                   | Diaphragm-Piston, Left,<br>Rear         | 953 ACTROS<br>954 ACTROS               |
|   |                   | Repl. Wabco: 925 484<br>010 0           |  |
| <b>TM14171</b><br>   | 0154208118        | Spring Brake Chamber                    | MODEL                                  |
|   | 0194205918        | Wabco Type, For Disc                    | 375 ACTROS                             |
|   | 0204206018        | Brake,                                  | 950 ACTROS                             |
|   | 0154206318        | Diaphragm-Piston, Left,<br>Rear         | 952 ACTROS<br>953 ACTROS<br>954 ACTROS |
|   |                   | Repl. Wabco: 925 484<br>020 0           |  |
| <b>TM15389</b><br> | 0154209018        | Spring Brake Chamber                    | 950 ACTROS                             |
|   | 0204204118        | Wabco Type, For Disc                    | 953 ACTROS                             |
|   |                   | Brake,                                  | 930 ACTROS 2/3                         |
|   |                   | Diaphragm-Piston, Without<br>Repair Kit | 932 ACTROS 2/3<br>933 ACTROS 2/3       |
|   |                   | Repl. Wabco: 925 461<br>001 0           |  |
| <b>TM15391</b><br> | 0154204018        | Spring Brake Chamber                    | 375 ACTROS                             |
|   | 0194205218        | Wabco Type, For Disc                    | 950 ACTROS                             |
|   | 0194206218        | Brake,                                  | 952 ACTROS                             |
|   | 0154203418        | Diaphragm-Piston, Right,<br>Rear        | 953 ACTROS<br>954 ACTROS               |
|   |                   | Repl. Wabco: 925 484<br>011 0           |  |
| <b>TM15403</b><br> | 0214206518        | Spring Brake Chamber                    | 375 ATEGO                              |
|   |                   | Wabco Type, For Disc                    | 970 ATEGO                              |
|   |                   | Brake,                                  | 972 ATEGO                              |
|   |                   | Diaphragm-Piston, Left,<br>Rear         | 975 ATEGO                              |
|   |                   | Repl. Wabco: 925 484<br>022 0           |  |
| <b>TM37400</b><br> | 0214207518        | Spring Brake Chamber                    | 979 ACCELO                             |
|   |                   | Wabco Type, For Disc                    | 979 LO 916 /45                         |
|   |                   | Brake,                                  | 979 LO 916 /48                         |
|   |                   | Diaphragm-Piston, Left,<br>Rear         |  |
|   |                   | Repl. Wabco: 925 484<br>026 0           |  |



| Model / Details  | Description  | Replaces Ref. No:        | TM No.  |
|--|--|--------------------------|---|
| 979 ACCELO<br>979 LO 916 /45<br>979 LO 916 /48   | Spring Brake Chamber<br>Wabco Type, For Disc<br>Brake,<br>Diaphragm-Piston, Right,<br>Rear<br>Repl. Wabco: 925 484<br>027 0        | 0214207618               | <b>TM37401</b><br>   |
| 375 ATEGO<br>375 ATEGO 2<br>970 ATEGO 2<br>970 ATEGO<br>972 ATEGO 2<br>972 ATEGO<br>974 ATEGO 2                | Spring Brake Chamber<br>Wabco Type, For Disc<br>Brake,<br>Diaphragm-Piston, Left<br>Repl. Wabco: 925 486<br>010 0                  | 0204203118               | <b>TM15397</b><br>   |
| 375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>375 ATEGO 2<br>970 ATEGO 2<br>972 ATEGO 2                  | Spring Brake Chamber<br>Wabco Type, For Disc<br>Brake,<br>Diaphragm-Piston, Right<br>Repl. Wabco: 925 486<br>011 0                 | 0204203218               | <b>TM15396</b><br>  |
| 375 ACTROS<br>950 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>934 ACTROS 2/3<br>375 ATEGO<br>970 ATEGO           | Spring Brake Chamber<br>Wabco Type, For Disc<br>Brake,<br>Diaphragm-Piston, Left,<br>Front/Rear<br>Repl. Wabco: 925 488<br>014 0   | 0154205718               | <b>TM15399</b><br> |
| 375 ACTROS<br>950 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>934 ACTROS 2/3<br>375 ATEGO<br>970 ATEGO           | Wabco Type, For Disc<br>Brake,<br>Diaphragm-Piston, Right,<br>Front/Rear<br>Repl. Wabco: 925 488<br>015 0                          | 0154205818               | <b>TM15398</b><br> |
| 950 ACTROS<br>953 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3<br>942 AXOR 2 | Spring Brake Chamber<br>Wabco Type, For Disc<br>Brake,<br>Diaphragm-Piston, Without<br>Repair Kit<br>Repl. Wabco: 925 461<br>000 0 | 0204204218<br>0124209118 | <b>TM15390</b><br> |
| 950 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>934 ACTROS 2/3<br>375 AXOR<br>940 AXOR 2<br>950 AXOR 2           | Spring Brake Chamber<br>Wabco Type, For Disc<br>Brake,<br>Diaphragm-Piston, Without<br>Repair Kit<br>Repl. Wabco: 925 468<br>010 0 | 0154206118               | <b>TM15395</b><br> |





| TM No.  | Replaces Ref. No: | Description  | Model / Details  |
|---|-------------------|--|--|
| <b>TM14434</b><br>   | 0194205718        | Spring Brake Chamber   | 375 ACTROS   |
|   | 0154209318        | Wabco Type, For Disc Brake,  | 950 ACTROS   |
|   | 0194206718        | Diaphragm-Piston, Right  | 952 ACTROS   |
|   |                   | Repl. Wabco: 925 481 012 0   | 953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3                   |
| <b>TM37402</b><br>   | 0074201318        | Spring Brake Chamber   | 346 L 1924   |
|   | 0054209318        | Wabco Type, For Disk Brake,  | 346 LA 1924  |
|   | 0054200818        | Diaphragm-Diaphragm, Without Repair Kit  | 346 LAK 1924<br>346 LAS 1924<br>346 LK 1924                                    |
|   |                   | Repl. Wabco: 925 321 203 0   | 346 LS 1924<br>349 L 1621  |
| <b>TM37403</b><br>  | 0044206418S       | Spring Brake Chamber   | 346 L 1924   |
|   | 0074201218S       | Wabco Type, For Drum Brake,  | 346 LK 1924  |
|   | 0104207318S       | Diaphragm-Piston, Without Repair Kit   | 346 LS 1924<br>349 L 1621<br>349 L 1921  |
|   |                   | Repl. Wabco: 925 321 202 0 S   | 349 LK 1621<br>349 LK 1921   |
| <b>TM37404</b><br> | 0114202218        | Spring Brake Chamber Wabco Type, For Drum Brake,                               | 653 MK<br>658 SK   |
|   |                   | Diaphragm-Piston, Type: 16/16 IBV, Stroke: 57/57<br>Repl. Wabco: 925 494 107 0 |  |
| <b>TM37405</b><br> | 0194208718        | Spring Brake Chamber Left, Wabco Type, For Drum Brake,                         | 950 ACTROS<br>952 ACTROS   |
|   |                   | Diaphragm-Piston, Type: 16/24 IBV, Stroke: 57/57<br>Repl. Wabco: 925 494 910 0 | 953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 |
| <b>TM37406</b><br> | 0194208818        | Spring Brake Chamber Right, Wabco Type, For Drum Brake,                        | 950 ACTROS<br>952 ACTROS   |
|   |                   | Diaphragm-Piston, Type: 16/24 IBV, Stroke: 57/57<br>Repl. Wabco: 925 494 911 0 | 953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 |
| <b>TM37407</b><br> | 0094207318        | Spring Brake Chamber Wabco Type, For Drum Brake,                               | 388 L 1938<br>388 LS 1929  |
|   | 0104200018        | Diaphragm-Piston, Type: 20/30 IBV, Stroke: 65/65<br>Repl. Wabco: 925 490 121 0 | 388 LS 1935<br>388 LS 1941<br>388 LS 1945<br>382 OH SERIES<br>398 OH SERIES    |





| Model / Details  | Description  | Replaces Ref. No:                                    | TM No.  |
|--|--|--|---|
| 397 2426 /6X4<br>397 2426 B/6X4<br>671 O 345   | Spring Brake Chamber<br>Wabco Type, For Drum<br>Brake,<br>Diaphragm-Piston, Type:<br>30/30 IBV,<br>Stroke: 65/65<br>Repl. Wabco: 925 492<br>102 0        | 0134201818<br>0134206418<br>0134206618<br>0164200418 | <b>TM37408</b><br>   |
| 950 AXOR 2   | Spring Brake Chamber<br>Left, Wabco Type, For<br>Drum Brake,<br>Diaphragm-Piston, Type:<br>30/30,<br>Stroke: 64/64<br>Repl. Wabco: 925 322<br>251 0      | 0064205318   | <b>TM15401</b><br>   |
| 950 AXOR 2   | Spring Brake Chamber<br>Right, Wabco Type, For<br>Drum Brake,<br>Diaphragm-Piston, Type:<br>30/30,<br>Stroke: 64/64<br>Repl. Wabco: 925 322<br>241 0     | 0064205218   | <b>TM15016</b><br>  |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3 | Spring Brake Chamber<br>Wabco Type, For Drum<br>Brake,<br>Diaphragm-Piston, Type:<br>30/30 IBV,<br>Stroke: 65/65<br>Repl. Wabco: 925 492<br>203 0        | 0164202118<br>0194208118                             | <b>TM15405</b><br> |
| 934 ACTROS 2/3<br>970 ATEGO 2<br>749 AIRMASTER   | Spring Brake Chamber<br>Left, Wabco Type, For Disc<br>Brake,<br>Diaphragm-Piston, Type:<br>16/16 IBV,<br>Stroke: 57/57<br>Repl. Wabco: 925 464<br>450 0  | 0174208818   | <b>TM13734</b><br> |
| BM MODEL<br>934 ACTROS 2/3<br>970 ATEGO 2<br>749 AIRMASTER   | Spring Brake Chamber<br>Right, Wabco Type, For<br>Disc Brake,<br>Diaphragm-Piston, Type:<br>16/16 IBV,<br>Stroke: 57/57<br>Repl. Wabco: 925 464<br>451 0 | 0174208918   | <b>TM13749</b><br> |
| 950 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>934 ACTROS 2/3<br>950 AXOR 2<br>957 ECONIC                       | Spring Brake Chamber<br>Left, Wabco Type, For Disc<br>Brake,<br>Diaphragm-Piston, Type:<br>16/16 IBV,<br>Stroke: 57/57<br>Repl. Wabco: 925 486<br>400 0  | 0154201618<br>0204207218                             | <b>TM37409</b><br> |












| TM No.  | Replaces Ref. No:                      | Description  | Model / Details   |
|---|--|--|---|
| <b>TM37410</b><br>   | 0154201518                             | Spring Brake Chamber<br>Right, Wabco Type, For<br>Disc Brake,<br>Diaphragm-Piston, Type:<br>16/16 IBV,<br>Stroke: 57/57<br>Repl. Wabco: 925 486<br>401 0 | 950 ACTROS  |
|   | 0204207118                             |  | 954 ACTROS<br>930 ACTROS 2/3<br>934 ACTROS 2/3<br>950 AXOR 2<br>957 ECONIC                    |
| <b>TM15393</b><br>   | 0154203018                             | Spring Brake Chamber<br>Left, Wabco Type, For Disc<br>Brake,<br>Diaphragm-Piston, Type:<br>14/24 IBV,<br>Stroke: 64/64<br>Repl. Wabco: 925 488<br>001 0  | 375 ACTROS  |
|   | 0204201418                             |  | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3      |
| <b>TM15394</b><br>  | 0154202918                             | Spring Brake Chamber<br>Right, Wabco Type, For<br>Disc Brake,<br>Diaphragm-Piston, Type:<br>14/24 IBV,<br>Stroke: 64/64<br>Repl. Wabco: 925 488<br>000 0 | 375 ACTROS  |
|   | 0204201318                             |  | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3      |
| <b>TM15242</b><br> | 0184206318                             | Spring Brake Chamber<br>Wabco Type, For Disc<br>Brake, Diaphragm-<br>Piston, Type: 20/24 IBV,<br>Stroke: 57/57<br>Repl. Wabco: 925 480<br>035 0          | BM MODEL  |
|   | 0204205818                             |  | 375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>375 ATEGO 2<br>970 ATEGO 2<br>972 ATEGO 2 |
| <b>TM14437</b><br> | 0154207618                             | Spring Brake Chamber<br>Left, Wabco Type, For Disc<br>Brake,<br>Diaphragm-Piston, Type:<br>20/24 IBV,<br>Stroke: 64/64<br>Repl. Wabco: 925 480<br>011 0  | 375 ACTROS  |
|   | 0154208618<br>0204203418<br>0204205018 |  | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3      |
| <b>TM15214</b><br> | 0154207518                             | Spring Brake Chamber<br>Right, Wabco Type, For<br>Disc Brake,<br>Diaphragm-Piston, Type:<br>20/24 IBV,<br>Stroke: 64/64<br>Repl. Wabco: 925 480<br>010 0 | 375 ACTROS  |
|   | 0154208518<br>0204203318<br>0204204918 |  | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3      |
| <b>TM15238</b><br> | 0184205618                             | Spring Brake Chamber<br>Wabco Type, For Disc<br>Brake, Diaphragm-<br>Piston, Type: 20/24 IBV,<br>Stroke: 64/64<br>Repl. Wabco: 925 460<br>101 0          | 934 ACTROS 2/3  |
|   |  |  | 970 ATEGO 2<br>749 AIRMASTER  |



| Model / Details  | Description  | Replaces Ref. No:                                    | TM No.  |
|--|--|--|---|
| 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3     | Spring Brake Chamber<br>Left, Wabco Type, For Disc<br>Brake,<br>Diaphragm-Piston, Type:<br>20/24 IBV,<br>Stroke: 64/64<br>Repl. Wabco: 925 480<br>005 0  | 0154204418<br>0154204618<br>0194205418<br>0194206418 | <b>TM15213</b><br>   |
| 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3     | Spring Brake Chamber<br>Right, Wabco Type, For<br>Disc Brake,<br>Diaphragm-Piston, Type:<br>20/24 IBV,<br>Stroke: 64/64<br>Repl. Wabco: 925 480<br>004 0 | 0154204318<br>0154204718<br>0194205518<br>0194206518 | <b>TM15212</b><br>   |
| 950 ACTROS<br>930 ACTROS 2/3<br>375 AXOR<br>940 AXOR 2<br>950 AXOR 2                                       | Spring Brake Chamber<br>Left, Wabco Type, For Disc<br>Brake,<br>Diaphragm-Piston, Type:<br>12/16 IBV,<br>Stroke: 57/57<br>Repl. Wabco: 925 486<br>110 0  | 0214202618   | <b>TM37411</b><br>   |
| 950 ACTROS<br>930 ACTROS 2/3<br>375 AXOR<br>940 AXOR 2<br>950 AXOR 2                                       | Spring Brake Chamber<br>Right, Wabco Type, For<br>Disc Brake,<br>Diaphragm-Piston, Type:<br>12/16 IBV,<br>Stroke: 57/57<br>Repl. Wabco: 925 486<br>111 0 | 0923250214202718                                     | <b>TM37412</b><br> |
| 950 ACTROS<br>930 ACTROS 2/3<br>375 AXOR<br>940 AXOR 2<br>950 AXOR 2<br>688 LO 812<br>688 LO 812 814 /42,5 | Spring Brake Chamber<br>Wabco Type, For Disc<br>Brake, Diaphragm-<br>Piston, Type: 12/16 IBV,<br>Stroke: 57/57<br>Repl. Wabco: 925 486<br>101 0          | 0154201418<br>0194204718<br>0214200118               | <b>TM15232</b><br> |
| 979 ACCELO<br>375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3         | Spring Brake Chamber<br>Wabco Type, For Disc<br>Brake, Diaphragm-<br>Piston, Type: 12/16 IBV,<br>Stroke: 57/57<br>Repl. Wabco: 925 486<br>108 0          | 0164207218<br>0194204818                             | <b>TM37413</b><br> |
| -  | Mounting Kit, Brake<br>Chamber<br>Repl. Wabco: 423 000<br>534 2  | 6984200047   | <b>TM37414</b><br> |





| TM No.  | Replaces Ref. No:                                    | Description  | Model / Details  |
|---|--|--|--|
| <b>TM10043</b><br>   | 3555420273   | ABS Socket<br>Repl. Wabco: 899 759<br>815 4<br>ø16xø18x30,6/31,5 | 979 ACCELO<br>375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3                 |
| <b>TM10696</b><br>   | 0025423118   | Sensor, ABS<br>Repl. Wabco: 441 032<br>921 2<br>L: 400 mm        | 934 ACTROS 2/3<br>970 ATEGO 2<br>749 AIRMASTER<br>749 STEERMASTER  |
| <b>TM11850</b><br>   | 0025423818<br>0015428518<br>0015420818<br>0025423718 | Sensor, ABS<br>Repl. Wabco: 441 032<br>920 0<br>L: 2500 mm       | BM MODEL<br>375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3 |
| <b>TM11849</b><br> | 0025422518<br>0025422218                             | Sensor, ABS<br>Repl. Wabco: 441 032<br>851 0<br>L: 1500 mm       | 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3             |
| <b>TM11873</b><br> | 0035423518<br>0045424518                             | Sensor, ABS<br>Repl. Wabco: 441 032<br>941 0<br>L: 3400 mm       | 950 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>934 ACTROS 2/3<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO            |
| <b>TM10881</b><br> | 0035424218<br>6205420517<br>6205420217               | Sensor, ABS<br>Repl. Wabco: 441 032<br>920 2<br>L: 3555 mm       | 699 MK<br>382 OH SERIES<br>397 OH SERIES<br>437 UNIMOG<br>613 TOURISMO   |
| <b>TM11876</b><br> | 0005403417   | Sensor, ABS<br>Repl. Wabco: 441 032<br>767 0<br>L: 1500 mm       | 613 TOURISMO   |










| Model / Details  | Description  | Replaces Ref. No:                                     | TM No.  |
|--|--|---|---|
| -  | Sensor, ABS<br>Repl. Wabco: 441 032<br>731 0<br>L: 2055 mm | 3575401217  | <b>TM37415</b><br>   |
| 613 TOURISMO   | Sensor, ABS<br>Repl. Wabco: 441 032<br>765 0<br>L: 1440 mm | 3565400617  | <b>TM11875</b><br>   |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>950 AXOR 2<br>952 AXOR 2                               | Sensor, ABS<br>Repl. Wabco: 441 032<br>728 0<br>L: 2000 mm | 0015420518<br>0015428218<br>0015428718S<br>0005429618 | <b>TM11787</b><br>  |
| 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3<br>374 AXOR 2<br>942 AXOR 2<br>943 AXOR 2 | Sensor, ABS<br>Repl. Wabco: 441 032<br>946 0<br>L: 3600 mm | 0035424618<br>0045424618                              | <b>TM11874</b><br> |
| 375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>375 ATEGO 2<br>958 ATEGO 2                    | Sensor, ABS<br>Repl. Wabco: 441 032<br>821 0<br>L: 1260 mm | 0015427818<br>0015427618                              | <b>TM11851</b><br> |
| 950 ACTROS<br>952 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3 | Sensor, ABS<br>Repl. Wabco: 441 032<br>820 0<br>L: 1350 mm | 0015426818<br>0005426918                              | <b>TM11872</b><br> |
| 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3<br>374 AXOR 2<br>942 AXOR 2<br>943 AXOR 2 | Sensor, ABS<br>Repl. Wabco: 441 032<br>947 0<br>L: 4000 mm | 0035424518<br>0045424718                              | <b>TM11871</b><br> |







| TM No.  | Replaces Ref. No:   | Description  | Model / Details  |
|---|---|--|--|
| <b>TM37416</b><br>   | 6255420018  | Sensor, ABS<br>Repl. Wabco: 441 032<br>860 0<br>L: 3000 mm   | 972 ATEGO<br>970 ATEGO 2<br>976 ATEGO 2  |
|   | <b>TM11603</b><br>   | 0015428818<br>0025422318<br>0015423518<br>0015428418         | Sensor, ABS<br>Repl. Wabco: 441 032<br>921 0<br>L: 3000 mm   |
| <b>TM37417</b><br>   | 0025420518<br>0025420418  | Sensor, ABS<br>Repl. Wabco: 441 032<br>819 0<br>L: 80 mm     | 972 ATEGO<br>976 ATEGO<br>958 ATEGO 2<br>970 ATEGO 2<br>972 ATEGO 2<br>976 ATEGO 2                         |
|   | <b>TM11847</b><br> | 6555400817<br>6505400217                                     | Sensor, ABS<br>Left<br>Repl. Knorr: 0265050103<br>L: 475 mm  |
| <b>TM11848</b><br> | 6555400717<br>6505400117  | Sensor, ABS<br>Right<br>Repl. Knorr: 0265050102<br>L: 475 mm | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 |
|   | <b>TM26121</b><br> | 3855420317   | Ring, ABS<br>ø150,5/ø160xø172x18   |
| <b>TM26346</b><br> | 9463340615<br>9463340015  | Ring, ABS<br>ø168xø202x12                                    | 375 ACTROS   |












| Model / Details  | Description                                | Replaces Ref. No:                      | TM No.         |
|--|--|--|----------------|
| 970 ATEGO 2  | Ring, ABS<br>ø160xø188x12                  | 9463340115                             | <b>TM26380</b> |
| 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3         | Ring, ABS<br>ø160xø188x12                  | 9423340015<br>9423340115               | <b>TM26294</b> |
| 375 ACTROS<br>950 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>934 ACTROS 2/3<br>963 ACTROS MP4<br>964 ACTROS MP4 | Ring, ABS<br>ø154,5xø196,3x17              | 9423560715<br>9423560315<br>9423560015 | <b>TM26198</b> |
| 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3         | Ring, ABS<br>ø140xø178x14,5                | 9433340115                             | <b>TM26374</b> |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3     | Ring, ABS<br>ø152,5xø204,4x11,3 /<br>Z=100 | 9423560515                             | <b>TM26345</b> |
| 375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>375 ATEGO 2<br>970 ATEGO 2<br>972 ATEGO 2                  | Ring, ABS<br>ø143,8xø177x11,7 /<br>Z=80    | 9753340415                             | <b>TM26373</b> |
| 375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>375 ATEGO 2<br>970 ATEGO 2<br>972 ATEGO 2                  | Ring, ABS<br>ø139,5xø177x11,7 /<br>Z=80    | 9753340315                             | <b>TM37418</b> |





| TM No.  | Replaces Ref. No:        | Description                        | Model / Details   |
|---|--------------------------|------------------------------------|---|
| <b>TM26348</b><br>   | 9763560015               | Ring, ABS<br>ø139xø175x18          | 375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>970 ATEGO 2<br>972 ATEGO 2           |
| <b>TM26123</b><br>   | 9703560415<br>9703560315 | Ring, ABS<br>ø102xø162x80          | 979 ACCELO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>970 ATEGO 2<br>972 ATEGO 2<br>975 ATEGO 2        |
| <b>TM26378</b><br>   | 9733561015               | Ring, ABS<br>ø146xø200x14,5 / Z=80 | 375 ATEGO<br>970 ATEGO<br>375 ATEGO 2<br>970 ATEGO 2<br>974 ATEGO 2<br>976 ATEGO 2<br>967 ATEGO 3     |
| <b>TM26344</b><br> | 9463340515               | Ring, ABS<br>ø151xø179x12 / Z=90   | 749 AIRMASTER<br>749 STEERMASTER  |
| <b>TM26375</b><br> | 9723340115               | Ring, ABS<br>ø134xø138x15 / Z=80   | 934 ACTROS 2/3<br>963 ACTROS MP4<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>970 ATEGO 2<br>972 ATEGO 2 |
| <b>TM26353</b><br> | 6683560515               | Ring, ABS<br>ø101xø142x76          | 905 SPRINTER<br>668 VARIO<br>670 VARIO  |
| <b>TM26379</b><br> | 9753340515               | Ring, ABS<br>ø144xø177x12          | -   |










| Model / Details  | Description         | Replaces Ref. No:                                     | TM No.  |
|--|---------------------|---|---|
| 690 SPRINTER<br>904 SPRINTER<br>904 SPRINTER<br>690 SPRINTER<br>901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER | Pad, Brake Pedal    | 6382920082<br>3192920082                              | <b>TM22545</b><br>   |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3 | Pad, Brake Pedal    | 2012920082<br>2012910282                              | <b>TM22543</b><br>   |
| 638 VITO<br>638 V-CLASS<br>639 VIANO<br>639 VIANO<br>639 VITO<br>636 VIANO   | Pad, Brake Pedal    | 1244270382  | <b>TM37419</b><br>  |
| 314 LP<br>316 LP<br>318 LP<br>336 LP 1924<br>336 LPS 1924<br>343 T2/LN1<br>344 LK 1118                                       | Switch, Brake Pedal | 00054549091<br>0005455209<br>0005457909<br>0005458309 | <b>TM37420</b><br> |
| 625 SK<br>901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER<br>667 VARIO<br>668 VARIO                             | Switch, Brake Pedal | 0005459809  | <b>TM11711</b><br> |
| 309 T2/L<br>309 TL2/L<br>310 LF 508 D/LF 608 D<br>310 LT 608 D<br>310 T2/L<br>313 T2/L<br>314 LP                             | Switch, Brake Pedal | 0005456909<br>6885457009<br>6885457109<br>6935457309  | <b>TM10243</b><br> |
| 979 ACCELO<br>375 ACTROS<br>375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO                                    | Switch, Brake Pedal | 0015452409<br>6435450009                              | <b>TM11785</b><br> |
















| TM No.  | Replaces Ref. No:        | Description                         | Model / Details   |
|---|--------------------------|-------------------------------------|---|
| <b>TM15425</b><br>   | 9014201885               | Cable, Parking Brake                | 690 SPRINTER<br>901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>909 SPRINTER                                  |
| <b>TM15418</b><br>   | 9044200185               | Cable, Parking Brake                | 690 SPRINTER<br>904 SPRINTER<br>909 SPRINTER  |
| <b>TM15419</b><br>   | 9044200285               | Cable, Parking Brake                | 690 SPRINTER<br>904 SPRINTER<br>909 SPRINTER  |
| <b>TM37421</b><br> | 6684202885               | Cable, Parking Brake<br>Rear, Left  | BM MODEL<br>668 T2/LN1<br>669 T2/LN1<br>670 T2/LN1<br>688 L 710<br>688 L 710 D<br>688 L 913 D<br>688 LO 813 D |
| <b>TM37422</b><br> | 6684202985               | Cable, Parking Brake<br>Rear, Right | 668 T2/LN1<br>669 T2/LN1<br>670 T2/LN1<br>688 L 710<br>688 L 710 D<br>688 L 913 D<br>688 LO 813 D             |
| <b>TM37423</b><br> | 6684204985<br>6684201685 | Cable, Parking Brake<br>Rear, Right | 669 T2/LN1<br>670 T2/LN1  |
| <b>TM37424</b><br> | 6684205085<br>6684201585 | Cable, Parking Brake<br>Rear, Left  | 669 T2/LN1<br>670 T2/LN1  |












| <i>Model / Details</i>   | <i>Description</i>                  | <i>Replaces Ref. No:</i>               | <i>TM No.</i>   |
|--|-------------------------------------|--|---|
| 611 T1/TN  | Cable, Parking Brake<br>Rear, Left  | 6114201685                             | <b>TM37425</b><br>   |
| 611 T1/TN  | Cable, Parking Brake<br>Rear, Right | 6114201785                             | <b>TM37426</b><br>   |
| 690 SPRINTER<br>901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER | Cable, Parking Brake                | 9044200385                             | <b>TM15420</b><br>  |
| 690 SPRINTER<br>901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER                 | Cable, Parking Brake                | 9014202085                             | <b>TM15413</b><br> |
| 690 SPRINTER<br>903 SPRINTER<br>904 SPRINTER<br>909 SPRINTER                 | Cable, Parking Brake                | 9044200485                             | <b>TM15436</b><br> |
| 906 SPRINTER   | Cable, Parking Brake<br>Rear        | 9064203185<br>9064204585               | <b>TM37427</b><br> |
| 906 SPRINTER   | Cable, Parking Brake<br>Rear, Left  | 9064203085<br>9064204485<br>9064207085 | <b>TM15443</b><br> |





| TM No.  | Replaces Ref. No:        | Description                         | Model / Details  |
|---|--------------------------|-------------------------------------|--|
| <b>TM37428</b><br>   | 6384270338               | Cable, Parking Brake<br>Rear        | 638 VITO<br>638 V-CLASS  |
| <b>TM15414</b><br>   | 9014202185               | Cable, Parking Brake                | 690 SPRINTER<br>901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER<br>909 SPRINTER |
| <b>TM15415</b><br>  | 9014202285               | Cable, Parking Brake                | 903 SPRINTER<br>904 SPRINTER<br>909 SPRINTER   |
| <b>TM15437</b><br> | 9044200585               | Cable, Parking Brake<br>Rear, Left  | 690 SPRINTER<br>904 SPRINTER<br>909 SPRINTER   |
| <b>TM15438</b><br> | 9044200685               | Cable, Parking Brake<br>Rear, Right | 690 SPRINTER<br>904 SPRINTER<br>909 SPRINTER   |
| <b>TM37429</b><br> | 6394270438<br>6394203585 | Cable, Parking Brake<br>Left        | 639 VIANO  |
| <b>TM37430</b><br> | 6394270538<br>6394203685 | Cable, Parking Brake<br>Right       | 639 VIANO  |



| Model / Details  | Description                                      | Replaces Ref. No:        | TM No.  |
|--|--|--------------------------|---|
| 690 SPRINTER<br>901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER<br>909 SPRINTER                                 | Leaf Spring, Spring Suspension                   | 9043200601               | <b>TM37432</b><br>   |
| 906 SPRINTER<br>900 SPRINTER<br>901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER<br>906 SPRINTER<br>690 SPRINTER | Leaf Spring, Spring Suspension<br>3.5 - 3.88 ton | 9063211503<br>9063211003 | <b>TM37433</b><br>   |
| 901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>909 SPRINTER   | Leaf Spring, Spring Suspension                   | 9033200501               | <b>TM28086</b><br>  |
| 906 SPRINTER   | Leaf Spring, Spring Suspension<br>3.2 - 3.5 ton  | 9063211403<br>9063210903 | <b>TM37434</b><br> |
| 906 SPRINTER   | Leaf Spring, Spring Suspension<br>3.88 - 4.2 ton | 9063211603<br>9063211103 | <b>TM37435</b><br> |
| 900 SPRINTER<br>906 SPRINTER   | Leaf Spring, Spring Suspension<br>4.2 - 4.6 ton  | 9063211703<br>9063211203 | <b>TM37436</b><br> |
| 906 SPRINTER   | Leaf Spring, Spring Suspension<br>4.6 - 5.0 ton  | 9063211803<br>9063211303 | <b>TM37437</b><br> |





| TM No.  | Replaces Ref. No: | Description  | Model / Details |
|---|-------------------|--|-----------------|
| <b>TM27453</b><br>   | 0003220623        | Rod, Spring Suspension<br>Left<br>L: 1815 mm       | 950 ACTROS      |
|   | 0003220323        |  | 952 ACTROS      |
|   |                   |  | 953 ACTROS      |
|   |                   |  | 930 ACTROS 2/3  |
|   |                   |  | 932 ACTROS 2/3  |
|   |                   |  | 933 ACTROS 2/3  |
|   |                   |  | 942 AXOR 2      |
| <b>TM27860</b><br>   | 3753220523        | Rod, Spring Suspension<br>Right<br>L: 1815 mm      | 942 AXOR 2      |
|   | 3753220123        |  | 943 AXOR 2      |
| <b>TM27459</b><br>  | 0003220723        | Rod, Spring Suspension<br>Right<br>L: 1815 mm      | 950 ACTROS      |
|   | 0003220423        |  | 952 ACTROS      |
|   |                   |  | 953 ACTROS      |
|   |                   |  | 930 ACTROS 2/3  |
|   |                   |  | 932 ACTROS 2/3  |
|   |                   |  | 933 ACTROS 2/3  |
| <b>TM37438</b><br> | 6383240584        | Spring Stop, Spring Sus-<br>pension<br>Rear, Top   | 638 VITO        |
|   |                   |  |                 |
| <b>TM37439</b><br> | 6383240884        | Spring Stop, Spring Sus-<br>pension<br>Rear, Lower | 638 V-CLASS     |
|   | 6383240684        |  | 638 VITO        |
|   |                   |  | 638 V-CLASS     |
| <b>TM37440</b><br> | 6383240784        | Spring Bracket, Spring<br>Suspension               | 638 VITO        |
|   |                   |  |                 |
| <b>TM37441</b><br> | 6383240084S       | Spring Bracket, Spring<br>Suspension               | 638 VITO        |
|   |                   |  |                 |



| <b>Model / Details</b>   | <b>Description</b>                                  | <b>Replaces Ref. No:</b>               | <b>TM No.</b>   |
|--|---|--|---|
| 639 VIANO<br>639 VIANO<br>639 VITO   | Spring Bracket, Spring<br>Suspension<br>Rear, Lower | 6393240384                             | <b>TM37442</b><br>   |
| BM MODEL<br>639 VIANO<br>639 VIANO<br>639 VITO   | Spring Bracket, Spring<br>Suspension<br>Rear, Top   | 6393240308                             | <b>TM37443</b><br>   |
| 639 VIANO<br>639 VIANO<br>639 VITO   | Spring Bracket, Spring<br>Suspension<br>Rear, Top   | 6393240308S                            | <b>TM37444</b><br>  |
| 309 T2/L<br>309 O 309 B<br>309 O 309 D   | Rubber Bushing, Spring<br>ø30xø42x40                | 3193240450<br>3193240750               | <b>TM37445</b><br> |
| 314 LP<br>316 LP<br>318 LP<br>398 LO 814<br>667 T2/LN1<br>668 T2/LN1<br>669 T2/LN1                               | Rubber Bushing, Spring<br>ø29,5xø42x46              | 3183220250<br>6673220350               | <b>TM27696</b><br> |
| 611 T1/TN<br>601 207 D/208 D<br>601 208/210<br>601 209 D/210 D<br>602 307 D/308 D<br>602 307 D/308D<br>602 308 D | Rubber Bushing, Spring<br>ø12xø33x70                | 0003210350<br>0003210150<br>0003210050 | <b>TM28279</b><br> |
| 673 LK/LN2<br>674 LK/LN2<br>675 LK/LN2<br>676 LK/LN2<br>677 LK/LN2<br>678 LK/LN2                                 | Rubber Bushing, Spring<br>ø16xø46x96                | 6733200050                             | <b>TM28193</b><br> |



| TM No.  | Replaces Ref. No:                      | Description                              | Model / Details  |
|---|--|--|--|
| <b>TM27777</b><br>   | 6753200050                             | Rubber Bushing, Spring<br>ø18xø48,5x96   | 674 LK/LN2<br>675 LK/LN2<br>676 LK/LN2<br>677 LK/LN2<br>678 LK/LN2<br>679 LK/LN2                           |
| <b>TM37446</b><br>   | 3103200050                             | Rubber Bushing, Spring<br>ø30xø52x77     | 310 LF 508 D/LF 608 D<br>310 T2/L<br>313 T2/L<br>378 L 608 E<br>378 LO 608 D<br>310 O 309 D<br>313 O 309 D |
| <b>TM27775</b><br>   | 6753200150                             | Rubber Bushing, Spring<br>ø36xø63,5x96   | 675 LK/LN2<br>676 LK/LN2<br>677 LK/LN2<br>678 LK/LN2<br>679 LK/LN2   |
| <b>TM28237</b><br> | 0003210250<br>0003210450               | Rubber Bushing, Spring<br>ø16xø39x80     | 611 T1/TN<br>690 SPRINTER<br>900 SPRINTER<br>904 SPRINTER<br>905 SPRINTER<br>906 SPRINTER<br>909 SPRINTER  |
| <b>TM27778</b><br> | 6113240050<br>6113240350<br>6113240450 | Rubber Bushing, Spring<br>ø16xø50x80     | 611 T1/TN  |
| <b>TM28337</b><br> | 6673200044                             | Rubber Bushing, Spring<br>ø30xø52x86,5   | 668 T2/LN1<br>669 T2/LN1<br>670 T2/LN1<br>667 VARIO<br>668 VARIO<br>670 VARIO                              |
| <b>TM28212</b><br> | 6733200250                             | Rubber Bushing, Spring<br>ø36,5xø58,5x48 | 673 LK/LN2<br>674 LK/LN2<br>675 LK/LN2<br>676 LK/LN2<br>677 LK/LN2<br>678 LK/LN2<br>697 O 402              |





| Model / Details  | Description                            | Replaces Ref. No:                                    | TM No.  |
|--|--|--|---|
| 673 LK/LN2<br>674 LK/LN2<br>675 LK/LN2<br>676 LK/LN2<br>677 LK/LN2<br>678 LK/LN2                                   | Rubber Bushing, Spring<br>ø36xø58x96   | 6733200150   | <b>TM27776</b><br>   |
| 601 207 D/208 D<br>601 208/210<br>601 209 D/210 D<br>602 307 D/308 D<br>602 307 D/308D<br>602 308 D<br>602 308/310 | Rubber Bushing, Spring<br>ø12xø49x70   | 6013240050<br>6013240150<br>6023240050<br>6023240150 | <b>TM28277</b><br>   |
| 690 SPRINTER<br>901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER   | Rubber Bushing, Spring<br>ø12xø50x80   | 9013240250<br>9013240350                             | <b>TM28280</b><br>  |
| BM MODEL<br>670 T2/LN1<br>620 NG<br>621 NG<br>622 NG<br>623 NG<br>624 NG<br>625 NG                                 | Rubber Bushing, Spring<br>ø36xø58x86,5 | 6703200344   | <b>TM37447</b><br> |
| 979 ACCELO<br>398 LO 814<br>667 T2/LN1<br>668 T2/LN1<br>669 T2/LN1<br>670 T2/LN1<br>688 1114                       | Rubber Bushing, Spring<br>ø30xø52x86,5 | 6703200444   | <b>TM37448</b><br> |
| 650 MK<br>651 MK<br>652 MK<br>653 MK<br>654 MK<br>382 OH SERIES<br>390 OHL 1316                                    | Rubber Bushing, Spring<br>ø22xø60x76   | 0003220385<br>0003220585                             | <b>TM28158</b><br> |
| 652 MK<br>653 MK<br>657 SK   | Rubber Bushing, Spring<br>ø24xø62x86   | 0003221985   | <b>TM28236</b><br> |





| TM No.  | Replaces Ref. No: | Description   | Model / Details |
|---|-------------------|---|-----------------|
| <b>TM28160</b><br>   | 0003223485        | Rubber Bushing, Spring<br>ø24xø62x96                          | 375 ACTROS      |
|   | 0003221285        |   | 950 ACTROS      |
|   | 0003222185        |   | 952 ACTROS      |
|   | 0003222285        |   | 953 ACTROS      |
|   |                   |   | 954 ACTROS      |
|   | 930 ACTROS 2/3    |   | 932 ACTROS 2/3  |
| <b>TM37449</b><br>   | 0003221285S2      | Rubber Bushing, Spring<br>011.072's alternative<br>ø24xø61x96 | 375 ACTROS      |
|   | 0003222285S2      |   | 950 ACTROS      |
|   | 0003223285S2      |   | 952 ACTROS      |
|   | 3753220185S2      |   | 953 ACTROS      |
|   |                   |   | 954 ACTROS      |
|   | 930 ACTROS 2/3    |   | 932 ACTROS 2/3  |
| <b>TM37450</b><br>   | 6673220650        | Rubber Bushing, Spring<br>ø30xø42x43,5                        | 688 709         |
|   | 6313240050        |   | 688 912         |
|   |                   |   | 688 LO 809      |
|   |                   |   | 688 LO 812      |
|   |                   |   | 688 712 E       |
|   | 667 VARIO         |   | 668 VARIO       |
| <b>TM37451</b><br> | 6753250585        | Rubber Bushing, Spring<br>ø18xø64,5x96                        | 970 ATEGO       |
|   |                   |   | 970 ATEGO 2     |
|   |                   |   | 974 ATEGO 2     |
|   |                   |   | 975 ATEGO 2     |
|   |                   |   | 976 ATEGO 2     |
|   |                   |   | 674 LK/LN2      |
|   |                   |   | 675 LK/LN2      |
| <b>TM28177</b><br> | 0003250285        | Rubber Bushing, Spring<br>ø24xø62x106                         | 950 ACTROS      |
|   | 0003251385        |   | 952 ACTROS      |
|   | 0003250785        |   | 954 ACTROS      |
|   | 0003250885        |   | 930 ACTROS 2/3  |
|   |                   |   | 932 ACTROS 2/3  |
|   | 934 ACTROS 2/3    |   | 964 AROCS       |
| <b>TM27699</b><br> | 9743200044        | Rubber Bushing, Spring<br>ø22,5xø63,5x96                      | 375 ATEGO       |
|   |                   |   | 970 ATEGO       |
|   |                   |   | 972 ATEGO       |
|   |                   |   | 975 ATEGO       |
|   |                   |   | 976 ATEGO       |
|   |                   |   | 958 ATEGO 2     |
|   |                   |   | 970 ATEGO 2     |
| <b>TM28234</b><br> | 9703200044        | Rubber Bushing, Spring<br>ø16xø50x95,5                        | 375 ATEGO       |
|   |                   |   | 970 ATEGO       |
|   |                   |   | 972 ATEGO       |
|   |                   |   | 975 ATEGO       |
|   |                   |   | 976 ATEGO       |
|   |                   |   | 958 ATEGO 2     |
|   |                   |   | 970 ATEGO 2     |



| Model / Details   | Description                            | Replaces Ref. No:        | TM No.  |
|---|--|--------------------------|---|
| 690 SPRINTER<br>901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER                                  | Rubber Bushing, Spring<br>ø12xø32,5x80 | 9013240150               | <b>TM28281</b><br>   |
| 690 SPRINTER<br>901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>909 SPRINTER                  | Rubber Bushing, Spring<br>ø12xø32x134  | 9013240050               | <b>TM28278</b><br>   |
| 375 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>970 ATEGO 2<br>972 ATEGO 2<br>974 ATEGO 2 | Rubber Bushing, Spring<br>ø22,5xø66x96 | 9743200244               | <b>TM28338</b><br>   |
| 375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>375 ATEGO 2<br>958 ATEGO 2   | Rubber Bushing, Spring<br>ø18xø56x96   | 9703200344<br>6753250485 | <b>TM27698</b><br> |
| 667 VARIO<br>668 VARIO<br>670 VARIO   | Rubber Bushing, Spring<br>ø36xø58x86,5 | 6673200144               | <b>TM37452</b><br> |
| 900 SPRINTER<br>906 SPRINTER  | Rubber Bushing, Spring<br>ø12xø62,5x80 | 9063240050               | <b>TM28299</b><br> |
| 396 OH SERIES<br>373 O 302<br>300 O 303<br>301 O 303<br>373 O 303<br>600 O 303<br>307 O 305   | Rubber Bushing, Spring<br>ø12xø43x45   | 0009884211               | <b>TM08356</b><br> |



| TM No.  | Replaces Ref. No:                                    | Description                            | Model / Details   |
|---|--|--|---|
| <b>TM28356</b><br>   | 9743200544   | Rubber Bushing, Spring<br>ø22xø62x96   | 375 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>958 ATEGO 2<br>970 ATEGO 2<br>972 ATEGO 2           |
| <b>TM37453</b><br>   | 9053240050   | Rubber Bushing, Spring<br>ø18xø50,5x80 | 905 SPRINTER  |
| <b>TM28308</b><br>   | 9603231685<br>9603232985<br>9603234585<br>0009980142 | Rubber Bushing, Spring<br>ø24xø62x104  | 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS  |
| <b>TM28282</b><br> | 9603231385<br>9603234485                             | Rubber Bushing, Spring<br>ø24xø67x104  | 963 ACTROS MP4  |
| <b>TM28288</b><br> | 9603231285<br>9603234385                             | Rubber Bushing, Spring<br>ø24xø67x96   | 963 ACTROS MP4  |
| <b>TM28235</b><br> | 9703200144<br>3753200744                             | Rubber Bushing, Spring<br>ø18xø50x95,5 | BM MODEL<br>375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>958 ATEGO 2<br>970 ATEGO 2 |
| <b>TM28315</b><br> | 9603231785<br>9603234185                             | Rubber Bushing, Spring<br>ø20xø64x44   | 964 AROCS   |



| Model / Details   | Description                                | Replaces Ref. No:        | TM No.  |
|---|--|--------------------------|---|
| 964 ACTROS MP4<br>964 ANTOS<br>964 AROCS  | Rubber Bushing, Spring<br>ø24xø62,45x104   | 9603232885<br>9603234685 | <b>TM28313</b><br>   |
| 934 ACTROS 2/3<br>944 AXOR 2  | Rubber Bushing, Spring<br>ø59,5x18/22/128  | 0003330217               | <b>TM28466</b><br>   |
| 963 ACTROS MP4<br>964 AROCS   | Rubber Bushing, Spring<br>21,25x130xø60,3  | 9603220019               | <b>TM37454</b><br>   |
| 375 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>958 ATEGO 2<br>970 ATEGO 2<br>972 ATEGO 2 | Mounting, Spring<br>Old Type<br>105x112x51 | 9703200095               | <b>TM28017</b><br> |
| 972 ATEGO<br>970 ATEGO 2<br>976 ATEGO 2   | Mounting, Spring<br>New Type<br>105x117x90 | 9703200195               | <b>TM28084</b><br> |
| 900 SPRINTER<br>906 SPRINTER  | Mounting, Spring<br>47x82x33               | 9063220619               | <b>TM37455</b><br> |
| 900 SPRINTER<br>906 SPRINTER  | Mounting, Spring<br>78,1x76,5x33,45        | 9063220019               | <b>TM37456</b><br> |





| TM No.  | Replaces Ref. No:                      | Description                     | Model / Details  |
|---|--|---------------------------------|--|
| <b>TM28068</b><br>   | 3093200177                             | Buffer, Spring<br>ø66x119       | 308 L 608 E,L 708 E<br>308 L/LO 608 D<br>308 LO 608 D,LO 708 D/E<br>309 T2/L<br>309 TL2/L<br>310 LF 508 D/LF 608 D<br>310 T2/L |
| <b>TM37457</b><br>   | 6733250144                             | Buffer, Spring<br>M8/65,5x81x19 | 667 T2/LN1<br>668 T2/LN1<br>669 T2/LN1<br>670 T2/LN1<br>673 LK/LN2<br>674 LK/LN2<br>675 LK/LN2                                 |
| <b>TM37458</b><br>   | 6733250284                             | Buffer, Spring<br>65x80,5x13    | 673 LK/LN2<br>674 LK/LN2<br>675 LK/LN2<br>676 LK/LN2<br>677 LK/LN2<br>679 LK/LN2   |
| <b>TM37459</b><br> | 6013210062                             | Buffer, Spring<br>50x70x15      | 611 T1/TN<br>601 207 D/208 D<br>601 208/210<br>601 209 D/210 D<br>602 307 D/308 D<br>602 307 D/308D<br>602 308 D               |
| <b>TM37460</b><br> | 6733240408                             | Buffer, Spring<br>68x88x85      | 972 ATEGO<br>976 ATEGO<br>958 ATEGO 2<br>970 ATEGO 2<br>972 ATEGO 2<br>976 ATEGO 2<br>967 ATEGO 3                              |
| <b>TM37461</b><br> | 6753240008                             | Buffer, Spring<br>68x88x85      | 375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>375 ATEGO 2<br>958 ATEGO 2<br>970 ATEGO 2                                  |
| <b>TM35112</b><br> | 9013250744<br>9063250044<br>9063251444 | Buffer, Spring<br>70x80x41      | 690 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER<br>909 SPRINTER   |





| Model / Details  | Description                       | Replaces Ref. No:        | TM No.  |
|--|-----------------------------------|--------------------------|---|
| 901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>909 SPRINTER   | Buffer, Spring<br>42x134x94,5     | 9013222519               | <b>TM37462</b><br>   |
| 690 SPRINTER<br>901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER<br>905 SPRINTER<br>909 SPRINTER | Buffer, Spring<br>45,5x134,5x94,5 | 9013220619               | <b>TM37463</b><br>   |
| 309 T2/L<br>310 LF 508 D/LF 608 D<br>310 T2/L<br>313 T2/L<br>668 T2/LN1<br>669 T2/LN1<br>670 T2/LN1          | Buffer, Spring<br>ø92x110         | 6673200077<br>3093200277 | <b>TM37464</b><br>  |
| 667 T2/LN1<br>668 T2/LN1<br>669 T2/LN1<br>670 T2/LN1<br>690 SPRINTER<br>903 SPRINTER<br>904 SPRINTER         | Buffer, Spring<br>55x80,5x14      | 6673250084               | <b>TM28849</b><br> |
| 673 LK/LN2<br>674 LK/LN2<br>675 LK/LN2<br>676 LK/LN2<br>677 LK/LN2<br>679 LK/LN2                             | Buffer, Spring<br>55,5x75x21,5    | 6743250244               | <b>TM19691</b><br> |
| 673 LK/LN2<br>674 LK/LN2<br>675 LK/LN2<br>676 LK/LN2<br>677 LK/LN2<br>679 LK/LN2<br>382 OH SERIES            | Buffer, Spring<br>75,5x85,5x33    | 6743250344               | <b>TM06041</b><br> |
| 615 LK/LN2<br>650 MK<br>651 MK<br>652 MK<br>380 NG<br>381 NG<br>383 NG                                       | Buffer, Spring<br>ø66x86,5        | 3853200077               | <b>TM28211</b><br> |





| TM No.  | Replaces Ref. No:                      | Description                       | Model / Details  |
|---|--|-----------------------------------|--|
| <b>TM37465</b><br>   | 6753250184                             | Buffer, Spring<br>70,5x90,5x13    | 375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>958 ATEGO 2<br>970 ATEGO 2<br>972 ATEGO 2   |
| <b>TM28264</b><br>   | 6753250144<br>3753200844               | Buffer, Spring<br>M6/70,5x94x18,5 | 375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>958 ATEGO 2<br>970 ATEGO 2                  |
| <b>TM06454</b><br>   | 6753250284<br>9703250184<br>9703250084 | Buffer, Spring<br>70x90x18,5      | 375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>958 ATEGO 2<br>970 ATEGO 2                  |
| <b>TM37466</b><br> | 9013221619                             | Buffer, Spring<br>45,5x134,5x94,5 | 901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>909 SPRINTER   |
| <b>TM35118</b><br> | 9013221219                             | Buffer, Spring<br>65,5x100,5x40   | 901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER<br>909 SPRINTER                                 |
| <b>TM35119</b><br> | 9013220019                             | Buffer, Spring<br>65,5x100,5x32   | 690 SPRINTER<br>901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER<br>905 SPRINTER<br>909 SPRINTER |
| <b>TM35120</b><br> | 9013220419                             | Buffer, Spring<br>45,5x100,5x29,5 | 690 SPRINTER<br>901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER<br>905 SPRINTER<br>909 SPRINTER |



| Model / Details  | Description                     | Replaces Ref. No:                                    | TM No.  |
|--|---------------------------------|--|---|
| 950 ACTROS<br>954 ACTROS<br>950 AXOR 2<br>954 AXOR 2   | Buffer, Spring<br>84,5x110,5x22 | 9433235184   | <b>TM28208</b>  |
|  |                                 |  |    |
| 375 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>958 ATEGO 2<br>970 ATEGO 2<br>972 ATEGO 2                | Buffer, Spring<br>76x121x19     | 6753250584   | <b>TM06453</b>  |
|  |                                 |  |    |
| 690 SPRINTER<br>901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER<br>905 SPRINTER<br>909 SPRINTER | Buffer, Spring<br>59,5x89,5x7,5 | 9013250084   | <b>TM35104</b>  |
|  |                                 |  |   |
| 375 ACTROS<br>950 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>934 ACTROS 2/3<br>375 AXOR<br>374 AXOR 2         | Buffer, Spring<br>84x110x18     | 9433235384<br>9433238384<br>9433238684<br>3753230084 | <b>TM28209</b>  |
|  |                                 |  |  |
| 375 ACTROS<br>950 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>934 ACTROS 2/3<br>375 AXOR<br>374 AXOR 2         | Buffer, Spring<br>84,5x115x23   | 9433236184<br>9433238584<br>9433238484               | <b>TM37467</b>  |
|  |                                 |  |  |
| 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3       | Buffer, Spring<br>79x110        | 0003220244   | <b>TM28198</b>  |
|  |                                 |  |  |
| 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3       | Buffer, Spring<br>79x75         | 0003220044<br>0003220144                             | <b>TM28240</b>  |
|  |                                 |  |  |





| TM No.  | Replaces Ref. No: | Description                       | Model / Details  |
|---|-------------------|-----------------------------------|--|
| <b>TM37468</b><br>   | 9013222219        | Buffer, Spring<br>41x80x36        | BM MODEL<br>690 SPRINTER<br>901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER<br>909 SPRINTER   |
| <b>TM35121</b><br>   | 9013222619        | Buffer, Spring<br>58x80x33        | -  |
| <b>TM35113</b><br>   | 9013250144        | Buffer, Spring<br>55x132x69       | 690 SPRINTER<br>901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>906 SPRINTER<br>909 SPRINTER   |
| <b>TM37469</b><br> | 9013222119        | Buffer, Spring<br>40x80x31        | 690 SPRINTER<br>901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER<br>909 SPRINTER   |
| <b>TM28210</b><br> | 9493220044        | Buffer, Spring<br>M14x1,5x29      | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>942 AXOR 2   |
| <b>TM37470</b><br> | 9013221119        | Buffer, Spring<br>45,5x100,5x34,5 | 690 SPRINTER<br>901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER<br>905 SPRINTER<br>909 SPRINTER   |
| <b>TM27528</b><br> | 3833240008        | Buffer, Spring<br>ø62,5x85,5      | 958 ATEGO 2<br>376 LP 1219 MBTC-USA<br>376 LP 1419 MBTC-USA<br>376 LPS 1525 MBTC-USA<br>397 LP 1517<br>397 LP/LPK 1314 MB-<br>SA-RSA<br>397 LP/LPK 1417,1617<br>MBSA-RSA |



| Model / Details   | Description                          | Replaces Ref. No:                      | TM No.  |
|---|--------------------------------------|--|---|
| 905 SPRINTER  | Buffer, Spring<br>ø75,5xø85,5x38     | 9053250144<br>9063250144<br>9063251544 | <b>TM37471</b><br>   |
| 963 ACTROS MP4  | Buffer, Spring<br>M12x1,5/84x112x55  | 9603220084                             | <b>TM28018</b><br>   |
| 963 ACTROS MP4  | Buffer, Spring<br>ø12x50/84x112x37,5 | 9603220184                             | <b>TM28019</b><br>   |
| 901 SPRINTER<br>903 SPRINTER<br>904 SPRINTER  | Buffer, Spring<br>45,5x134,5x94,5    | 9013221819                             | <b>TM37472</b><br> |
| 690 SPRINTER<br>901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER<br>909 SPRINTER<br>0 | Buffer, Spring<br>94,5x134,5x42,5    | 9013222319                             | <b>TM37473</b><br> |
| 900 SPRINTER<br>906 SPRINTER  | Buffer, Spring<br>ø18/87x92          | 9063221019<br>9063220319               | <b>TM37474</b><br> |
| 900 SPRINTER<br>906 SPRINTER  | Buffer, Spring<br>ø18/87x92          | 9063220919                             | <b>TM37475</b><br> |





| TM No.  | Replaces Ref. No:        | Description                       | Model / Details  |
|---|--------------------------|-----------------------------------|--|
| <b>TM37476</b><br>   | 6383200177               | Buffer, Spring<br>26x65,5x113,5   | 638 VITO<br>638 V-CLASS  |
| <b>TM35107</b><br>   | 0009983041<br>9609984541 | Buffer, Spring<br>M12x1,5         | 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS   |
| <b>TM35106</b><br>   | 9473250044<br>9603250644 | Buffer, Spring<br>36,5x225x29     | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 |
| <b>TM35108</b><br> | 9603200477<br>9603200977 | Buffer, Spring<br>ø11,5/90x77     | 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS   |
| <b>TM35111</b><br> | 9603250344<br>9603251244 | Buffer, Spring<br>36,3x228,5x43,2 | 964 AROCS  |
| <b>TM37477</b><br> | 9603200577               | Buffer, Spring<br>ø11,5           | 963 ACTROS MP4   |
| <b>TM37478</b><br> | 9013250844               | Buffer, Spring<br>ø21/45x152      | 900 SPRINTER<br>901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>906 SPRINTER                               |












| Model / Details  | Description                   | Replaces Ref. No:                      | TM No.  |
|--|-------------------------------|--|---|
| 900 SPRINTER<br>906 SPRINTER   | Buffer, Spring<br>55,5x135x95 | 9063251144                             | <b>TM37479</b>  |
|  |                               |  |    |
| 611 T1/TN<br>904 SPRINTER<br>904 SPRINTER<br>611 T1/TN<br>690 SPRINTER<br>900 SPRINTER<br>904 SPRINTER     | Buffer, Spring                | 6113250044                             | <b>TM37480</b>  |
|  |                               |  |    |
| 8 V-CLASS<br>638 VITO<br>638 V-CLASS   | Buffer, Spring                | 6383200077                             | <b>TM37481</b>  |
|  |                               |  |   |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 | Buffer, Spring<br>h: 119 mm   | 0003250896<br>0003250696<br>0003241308 | <b>TM28169</b>  |
|  |                               |  |  |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 | Buffer, Spring<br>h: 152 mm   | 0003250596<br>0003250796               | <b>TM28183</b>  |
|  |                               |  |  |
| 950 ACTROS<br>953 ACTROS<br>954 ACTROS   | Cushion, Spring<br>h: 132 mm  | 0003250496                             | <b>TM37482</b>  |
|  |                               |  |  |
| 942 AXOR 2<br>943 AXOR 2   | Cushion, Spring<br>h:152 mm   | 9473250296                             | <b>TM28367</b>  |
|  |                               |  |  |







| Model / Details   | Description   | Replaces Ref. No:  | TM No.  |
|---|---|--|---|
| 964 AROCS   | Cushion, Spring<br>Right Front and Left Rear<br>235x145 | 9603250596<br>9603250285                                 | <b>TM28341</b><br>   |
| 343 T2/L<br>388 L 2635/6X4/54<br>388 LK 2635/6X4/40<br>388 LS 2635/6X4/40<br>696 L 1938<br>696 L 2638<br>696 LK 2638      | Bolt, Spring<br>M20x1,5/210                             | 6599900001<br>3959900201<br>000960020127<br>000960020150 | <b>TM27701</b><br>   |
| 942 AXOR 2<br>943 AXOR 2<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3<br>957 ECONIC            | Bolt, Spring<br>M24x2/220                               | 0069908604<br>308765024012                               | <b>TM37483</b><br>  |
| 942 AXOR 2<br>943 AXOR 2<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>964 ACTROS/ANTOS/<br>AROCS<br>964 AROCS | Bolt, Spring<br>M24x2/130                               | 000000005506<br>308765024015                             | <b>TM37484</b><br> |
| 930 ACTROS 2/3<br>964 AROCS<br>437 UNIMOG   | Bolt, Spring<br>M24x2/200                               | 000000005507<br>308765024017                             | <b>TM37485</b><br> |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3                | Bolt, Spring<br>M20x1,5/290                             | 000000007028   | <b>TM37486</b><br> |
| 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3<br>963 ACTROS MP4<br>964 AROCS<br>375 AXOR 2         | Bolt, Spring<br>M24x2/150                               | 000000005714<br>308765024014                             | <b>TM37487</b><br> |







| TM No.  | Replaces Ref. No:                      | Description                | Model / Details  |
|---|--|----------------------------|--|
| <b>TM37488</b>  | 9493220250                             | Nut, Spring                | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>964 AROCS                          |
|    |  |                            |  |
| <b>TM37489</b>  | 3703220030<br>3953220330               | Pin, Spring                | 387 NG<br>389 NG<br>393 NG<br>395 NG   |
|    |  |                            |  |
| <b>TM37490</b>  | 3893250074                             | Pin, Spring                | 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3                             |
|    |  |                            |  |
| <b>TM37491</b>  | 3193240750S<br>3193240450S             | Bushing, Spring            | 308 L 608 E,L 708 E<br>308 L/LO 608 D<br>308 LO 608 D,LO 708 D/E<br>309 T2/L<br>309 TL2/L<br>310 LF 508 D/LF 608 D<br>310 LT 608 D |
|  |  |                            |  |
| <b>TM37492</b>  | 6733240150                             | Bushing, Spring<br>Plastic | 673 LK/LN2<br>674 LK/LN2<br>675 LK/LN2<br>676 LK/LN2<br>677 LK/LN2<br>678 LK/LN2<br>679 LK/LN2                                     |
|  |  |                            |  |
| <b>TM27525</b>  | 9493200073<br>0003223085<br>0003222385 | Bushing, Spring            | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>942 AXOR 2                         |
|  |  |                            |  |
| <b>TM27774</b>  | 9493200173<br>0003223185<br>0003222885 | Bushing, Spring            | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>964 AROCS                          |
|  |  |                            |  |



| Model / Details  | Description     | Replaces Ref. No: | TM No.  |
|------------------|-----------------|-------------------|---|
| 387 NG           | Bushing, Spring | 3703220050        | <b>TM27766</b><br>   |
| 389 NG           | Bronze          | 3043210150        |   |
| 391 NG           | ø25xø30x81      | 3043210050        |   |
| 393 NG           |                 | 3473210050        |   |
| 395 NG           |                 |                   |   |
| 620 NG<br>621 NG |                 |                   |   |
| 380 NG           | Bushing, Spring | 3523250150        | <b>TM27054</b><br>   |
| 381 NG           | Bronze          | 3963250050        |   |
| 383 NG           | ø30xø35x77      | 3273255050        |   |
| 385 NG           |                 | 3853250050        |   |
| 615 NG           |                 |                   |   |
| 616 NG<br>617 NG |                 |                   |   |
| 314 LP           | Bushing, Spring | 3163240350        | <b>TM37493</b><br>   |
| 316 LP           | Bronze          | 3163240050        |   |
| 318 LP           | ø25xø30x77,5    | 3163240250        |   |
| 375 AXOR 2       | Bushing, Spring | 3353240350        | <b>TM27100</b><br> |
| 940 AXOR 2       | Bronze          | 3043240050        |   |
| 375 ACTROS       | ø30xø36x90      |                   |   |
| 387 NG           |                 |                   |   |
| 389 NG           |                 |                   |   |
| 391 NG<br>393 NG |                 |                   |   |
| 616 NG           | Bushing, Spring | 3353910050        | <b>TM37494</b><br> |
| 619 NG           | Bronze          |                   |   |
| 623 NG           | ø30xø40x90      |                   |   |
| 648 NG           |                 |                   |   |
| 658 SK           |                 |                   |   |
| 387 NG           | Bushing, Spring | 3873240050        | <b>TM37495</b><br> |
| 389 NG           | Bronze          |                   |   |
| 621 NG           | ø30xø35x90      |                   |   |
| 646 NG           |                 |                   |   |
| 655 SK           |                 |                   |   |
| 656 SK<br>699 MK |                 |                   |   |
| 380 NG           | Bushing, Spring | 3853220050        | <b>TM27053</b><br> |
| 381 NG           | Bronze          | 3523220050        |   |
| 383 NG           | ø25xø30x67      | 3123241050        |   |
| 385 NG           |                 | 3123241250        |   |
| 615 NG           |                 |                   |   |
| 616 NG<br>617 NG |                 |                   |   |





| TM No.  | Replaces Ref. No:        | Description                             | Model / Details  |
|---|--------------------------|---|--|
| <b>TM37497</b><br>   | 6243220050               | Bushing, Spring<br>Bronze<br>ø30xø36x25 | 625 NG<br>625 SK   |
| <b>TM37498</b><br>   | 9413220020               | Shackle, Spring                         | 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3                             |
| <b>TM37499</b><br>   | 9413250320               | Shackle, Spring<br>55,5x175x18/M22      | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3                         |
| <b>TM37500</b><br> | 9493220020               | Shackle, Spring<br>70x174x14/ø24        | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3                         |
| <b>TM27814</b><br> | 6253250319<br>6243251119 | Bracket, Spring<br>Right<br>173x223x202 | BM MODEL<br>958 AXOR 2<br>388 L 2635/6X4/54<br>388 LK 2635/6X4/40<br>388 LS 2635/6X4/40<br>696 L 1938<br>696 L 2638<br>696 LK 2638 |
| <b>TM27813</b><br> | 6253250219<br>6243251019 | Bracket, Spring<br>Left<br>173x223x202  | 958 AXOR 2<br>388 L 2635/6X4/54<br>388 LK 2635/6X4/40<br>388 LS 2635/6X4/40<br>696 L 1938<br>696 L 2638<br>696 LK 2638             |
| <b>TM28344</b><br> | 9013220131               | Bracket, Spring<br>Left<br>194x162x24   | 690 SPRINTER<br>901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER<br>909 SPRINTER                                       |





| Model / Details   | Description                            | Replaces Ref. No:        | TM No.  |
|---|--|--------------------------|---|
| 690 SPRINTER<br>901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER<br>909 SPRINTER                      | Bracket, Spring<br>Right<br>194x162x24 | 9013220231               | <b>TM28345</b><br>   |
| 350 LS 1924A,1929,1930<br>350 LS 1932,1933<br>350 LS 1934<br>388 L 1929<br>388 L 1935<br>388 L 1938<br>388 L 1945 | Bracket, Spring                        | 6203220103<br>6203220003 | <b>TM37501</b><br>   |
| 375 ACTROS<br>375 AXOR<br>375 AXOR 2<br>940 AXOR 2  | Bracket, Spring<br>Rear Left           | 3753220103<br>9413220203 | <b>TM37502</b><br>  |
| 655 SK<br>656 SK<br>657 SK<br>658 SK<br>659 SK<br>397 2435 S/6X4<br>397 2545 S/6X4                                | Bracket, Spring                        | 6553220601               | <b>TM37503</b><br> |
| 388 LS 1929<br>388 LS 1935<br>388 LS 1938<br>388 LS 1941<br>388 LS 1945<br>660 LS 1929<br>660 LS 1935             | Bracket, Spring<br>Left                | 6213250003               | <b>TM37504</b><br> |
| 388 LS 1929<br>388 LS 1935<br>388 LS 1941<br>388 LS 1945<br>660 LS 1929<br>660 LS 1935<br>620 NG                  | Bracket, Spring<br>Right               | 6213250004               | <b>TM37505</b><br> |
| 930 322 04 01   | Bracket, Spring<br>Left                | 9303220401               | <b>TM37506</b><br> |












| TM No.  | Replaces Ref. No:        | Description                             | Model / Details  |
|---|--------------------------|---|--|
| <b>TM37507</b><br>   | 9303220501               | Bracket, Spring<br>Right                | 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3                                       |
| <b>TM37508</b><br>   | 9413310526               | Bracket, Spring                         | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 |
| <b>TM37509</b><br>  | 3753250003               | Bracket, Spring                         | 375 ACTROS<br>375 AXOR 2<br>940 AXOR 2   |
| <b>TM37510</b><br> | 9473510126<br>9473510226 | Bracket, Spring                         | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 |
| <b>TM37511</b><br> | 9413310426<br>9413310126 | Bracket, Spring                         | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 |
| <b>TM37512</b><br> | 9493201327<br>9493221679 | Bracket, Spring<br>Left<br>178x183x268  | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>942 AXOR 2 |
| <b>TM37513</b><br> | 9493201427<br>9493221779 | Bracket, Spring<br>Right<br>178x183x268 | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>942 AXOR 2 |





| Model / Details  | Description  | Replaces Ref. No:                                    | TM No.  |
|--|--|--|---|
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>942 AXOR 2     | Bracket, Spring<br>Left<br>171x179x251,4           | 9493201127<br>9493221379<br>9493221979               | <b>TM37514</b><br>   |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>942 AXOR 2     | Bracket, Spring<br>Right<br>171x179x251,4          | 9493201227<br>9493221479<br>9493222079               | <b>TM37515</b><br>   |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>942 AXOR 2     | Bracket, Spring<br>Left                            | 9493230484   | <b>TM37516</b><br>  |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>942 AXOR 2     | Bracket, Spring<br>Right                           | 9493230584   | <b>TM37517</b><br> |
| 375 ACTROS<br>375 AXOR<br>375 AXOR 2<br>940 AXOR 2<br>942 AXOR 2<br>943 AXOR 2                                 | Bracket, Spring<br>Without Bushing, Rear,<br>Right | 3753220003<br>9413220003                             | <b>TM37518</b><br> |
| 352 L 1313<br>352 L 1813/6X2<br>352 L 1813/6X4<br>352 LA 1313<br>352 LAK 1313<br>352 LAKO 1313<br>352 LAS 1313 | Repair Kit, Spring<br>ø25x126                      | 3853200165<br>3855860332<br>3855860032               | <b>TM28411</b><br> |
| 336 LP 1924<br>336 LPS 1924<br>343 T2/L<br>346 L 1924<br>346 L 1928<br>346 LA 1924<br>346 LAK 1924             | Repair Kit, Spring<br>ø25x140                      | 3953200265<br>3955860232<br>3953200065<br>3955860032 | <b>TM28395</b><br> |











| TM No.  | Replaces Ref. No: | Description                           | Model / Details    |
|---|-------------------|---------------------------------------|--------------------|
| <b>TM28400</b><br>   | 3953200165        | Repair Kit, Spring<br>ø25x140,5       | 388 L 1929         |
|   | 3955860332        |                                       | 388 L 1935         |
| 3955860132  | 388 L 1938        |                                       |                    |
|   |                   |                                       | 388 L 1945         |
|   |                   |                                       | 388 L 2635/6X4/54  |
|   |                   |                                       | 388 LK 2635/6X4/40 |
|   |                   |                                       | 388 LS 1929        |
| <b>TM37519</b><br>   | 3143200065        | Repair Kit, Spring<br>ø25x140,5       | 314 LP             |
|   | 3145860532        |                                       | 316 LP             |
|   | 3145860232        |                                       | 318 LP             |
|   |                   |                                       | 625 SK             |
| <b>TM27067</b><br>   | 3293200065        | Repair Kit, Spring<br>M24x1,5/ø25x160 | 343 T2/LN1         |
|   | 3295860032        |                                       |                    |
|   | 3045860032        |                                       |                    |
| <b>TM28412</b><br> | 3853200065        | Repair Kit, Spring<br>ø30x136         | 352 L 1313         |
|   | 3855860232        |                                       | 352 LA 1313        |
|   |                   |                                       | 352 LAK 1313       |
|   |                   |                                       | 352 LAKO 1313      |
|   |                   |                                       | 352 LAS 1313       |
|   |                   |                                       | 352 LF 1313        |
|   |                   |                                       | 352 LK 1313        |
| <b>TM37520</b><br> | 6223200065        | Repair Kit, Spring<br>ø30x136         | 652 MK             |
|   | 6225860032        |                                       | 653 MK             |
|   |                   |                                       | 385 NG             |
|   |                   |                                       | 619 NG             |
|   |                   |                                       | 622 NG             |
|   |                   |                                       | 647 NG             |
|   |                   |                                       | 625 SK             |
| <b>TM27692</b><br> | 3893200065        | Repair Kit, Spring<br>ø30x148         | 336 LP 1924        |
|   | 3895860132        |                                       | 336 LPS 1924       |
|   | 3895860032        |                                       | 346 L 1924         |
|   |                   |                                       | 346 L 1928         |
|   |                   |                                       | 346 LA 1924        |
|   |                   |                                       | 346 LAK 1924       |
|   |                   |                                       | 346 LAS 1924       |
| <b>TM27695</b><br> | 6583200065        | Repair Kit, Spring<br>ø30x160         | 346 L 1924         |
|   |                   |                                       | 346 L 1928         |
|   |                   |                                       | 346 LK 1924        |
|   |                   |                                       | 346 LK 1928        |
|   |                   |                                       | 346 LS 1924        |
|   |                   |                                       | 346 LS 1928        |
|   |                   |                                       | 388 L 1929         |



| Model / Details  | Description                       | Replaces Ref. No:  | TM No.  |
|--|-----------------------------------|--|---|
| 625 NG<br>625 SK   | Repair Kit, Spring<br>ø30x206     | 6253200165<br>6243200064                                 | <b>TM37521</b><br>   |
| 387 NG<br>389 NG<br>621 NG<br>646 NG<br>655 SK<br>656 SK   | Repair Kit, Spring<br>ø30x148     | 3893200265   | <b>TM37522</b><br>   |
| 950 ACTROS<br>952 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>934 ACTROS 2/3<br>964 AROCS<br>375 AXOR    | Repair Kit, Spring<br>ø24xø62x106 | 0003250285S<br>0003250885S<br>0003251385S<br>0003250785S | <b>TM37523</b><br>  |
| 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 | Repair Kit, Spring<br>ø24xø62x96  | 0003221285S<br>0003222285S<br>0003223285S<br>3753220185S | <b>TM37526</b><br> |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>942 AXOR 2<br>943 AXOR 2 | Repair Kit, Spring<br>ø24xø45x96  | 9493200073S<br>0003223085S<br>0003222385S                | <b>TM37527</b><br> |
| 950 ACTROS<br>952 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>934 ACTROS 2/3<br>964 AROCS<br>375 AXOR    | Repair Kit, Spring<br>ø24xø62x106 | 9413250320S  | <b>TM37529</b><br> |






| TM No.  | Replaces Ref. No:                      | Description                                  | Model / Details  |
|---|--|--|--|
| <b>TM37530</b><br>   | 9493220020S                            | RepairKit, Spring<br>ø24xø62x96              | 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 |
| <b>TM27715</b><br>   | 9433510025                             | U Bolt, Spring<br>With Nut<br>M24x2/102x440  | 950 ACTROS<br>952 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>934 ACTROS 2/3<br>375 AXOR<br>374 AXOR 2   |
| <b>TM27731</b><br>  | 9463510025<br>6203510025<br>3353510725 | U Bolt, Spring<br>With Nut<br>M24x2/102x465  | 950 ACTROS<br>952 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>934 ACTROS 2/3<br>375 AXOR<br>374 AXOR 2   |
| <b>TM27716</b><br> | 9433510125                             | U Bolt, Spring<br>With Nut<br>M24x2/102x525  | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>934 ACTROS 2/3<br>374 AXOR 2 |
| <b>TM27732</b><br> | 9433510225                             | U Bolt, Spring<br>With Nut<br>M24x2/102x490  | 950 ACTROS<br>952 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>934 ACTROS 2/3<br>375 AXOR<br>374 AXOR 2   |
| <b>TM37531</b><br> | 6793510325<br>3213512325               | U Bolt, Spring<br>With Nut<br>M18x1,5/81x385 | 970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>958 ATEGO 2<br>970 ATEGO 2<br>976 ATEGO 2<br>675 LK/LN2<br>676 LK/LN2             |












| Model / Details  | Description                                  | Replaces Ref. No:                      | TM No.  |
|--|--|--|---|
| 375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>958 ATEGO 2<br>970 ATEGO 2<br>976 ATEGO 2              | U Bolt, Spring<br>With Nut<br>M18x1,5/81x415 | 9743510425                             | <b>TM37532</b>  |
|  |  |  |    |
| 375 AXOR 2   | U Bolt, Spring<br>With Nut<br>M24x2/130x268  | 3753280026                             | <b>TM37533</b>  |
|  |  |  |    |
| 970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>970 ATEGO 2<br>972 ATEGO 2<br>975 ATEGO 2<br>976 ATEGO 2            | U Bolt, Spring<br>With Nut<br>M16x1,5/85x180 | 3143510625<br>6733510025               | <b>TM37534</b>  |
|  |  |  |    |
| 314 LP<br>318 LP<br>669 T2/LN1<br>670 T2/LN1<br>688 710<br>688 710, LO610, LO712,-<br>LO 812               | U Bolt, Spring<br>With Nut<br>M16x1,5/75x191 | 3143510525<br>3273310225<br>6703510225 | <b>TM37535</b>  |
|  |  |  |  |
| 375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>375 ATEGO 2<br>958 ATEGO 2                | U Bolt, Spring<br>With Nut<br>M18x1,5/84x201 | 9703511425                             | <b>TM27730</b>  |
|  |  |  |  |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 | U Bolt, Spring<br>With Nut<br>M20x1,5/92x240 | 9413310225                             | <b>TM27727</b>  |
|  |  |  |  |
| 318 LP<br>673 LK/LN2<br>674 LK/LN2<br>676 LK/LN2<br>678 LK/LN2   | U Bolt, Spring<br>With Nut<br>M16x1,5/85x300 | 3183510125                             | <b>TM37536</b>  |
|  |  |  |  |












| TM No.  | Replaces Ref. No:        | Description                                  | Model / Details   |
|---|--------------------------|--|---|
| <b>TM37537</b><br>   | 3213511125               | U Bolt, Spring<br>With Nut<br>M18x1,5/84x321 | 975 ATEGO<br>970 ATEGO 2<br>972 ATEGO 2<br>967 ATEGO 3<br>675 LK/LN2<br>676 LK/LN2<br>677 LK/LN2            |
| <b>TM27001</b><br>   | 3213511625<br>3423510025 | U Bolt, Spring<br>With Nut<br>M18x1,5/84x341 | 972 ATEGO<br>970 ATEGO 2<br>976 ATEGO 2<br>967 ATEGO 3<br>675 LK/LN2<br>676 LK/LN2<br>677 LK/LN2            |
| <b>TM37538</b><br>   | 3143510725<br>3143510225 | U Bolt, Spring<br>With Nut<br>M16x1,5/85x221 | 970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>970 ATEGO 2<br>972 ATEGO 2<br>975 ATEGO 2<br>976 ATEGO 2             |
| <b>TM27728</b><br> | 3163510025<br>3143510325 | U Bolt, Spring<br>With Nut<br>M16x1,5/85x242 | 316 LP<br>318 LP<br>673 LK/LN2<br>674 LK/LN2<br>675 LK/LN2<br>676 LK/LN2<br>677 LK/LN2                      |
| <b>TM37539</b><br> | 3143510825               | U Bolt, Spring<br>With Nut<br>M16x1,5/85x201 | BM MODEL<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>970 ATEGO 2<br>972 ATEGO 2<br>974 ATEGO 2<br>975 ATEGO 2 |
| <b>TM27721</b><br> | 9493310025<br>9493310525 | U Bolt, Spring<br>With Nut<br>M20x1,5/92x285 | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3  |
| <b>TM27720</b><br> | 9493310125               | U Bolt, Spring<br>With Nut<br>M20x1,5/92x225 | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3  |









| Model / Details   | Description                                   | Replaces Ref. No:        | TM No.  |
|---|---|--------------------------|---|
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3  | U Bolt, Spring<br>With Nut<br>M20x1,5/92x205  | 9493310225               | <b>TM27729</b><br>   |
| 601 207 D/208 D<br>601 208/210<br>601 209 D/210 D<br>602 307 D/308 D<br>602 307 D/308D<br>602 308 D<br>602 308/310  | U Bolt, Spring<br>With Nut<br>M12x1,5/62x76   | 6013220225               | <b>TM37540</b><br>   |
| 602 307 D/308 D<br>602 307 D/308D<br>602 308 D<br>602 308/310<br>602 309 D/310 D<br>602 310 D   | U Bolt, Spring<br>With Nut<br>M12x1,5/62x110  | 6013250447               | <b>TM37541</b><br>   |
| 611 T1/TN   | U Bolt, Spring<br>With Nut<br>M12x1,5/62x122  | 6113220025               | <b>TM37542</b><br> |
| 343 T2/L<br>343 T2/LN1<br>395 NG<br>624 NG<br>625 NG<br>649 NG<br>625 SK  | U Bolt, Spring<br>With Nut<br>M24x1,5/101x340 | 3953510125<br>3433510225 | <b>TM27155</b><br> |
| 625 NG<br>648 NG<br>625 SK  | U Bolt, Spring<br>With Nut<br>M24x1,5/91x312  | 6233510125               | <b>TM37543</b><br> |
| 388 L 2635/6X4/54<br>388 LK 2635/6X4/40<br>388 LS 2635/6X4/40<br>625 NG<br>625 SK<br>371 2622 K/6X4/38,5<br>OTOMARSAN/TUERKEI<br>371 2624K,2627K3027<br>6X4/38, | U Bolt, Spring<br>With Nut<br>M24x1,5/101x430 | 3953510625               | <b>TM27718</b><br> |





| TM No.  | Replaces Ref. No:        | Description                                   | Model / Details  |
|---|--------------------------|---|--|
| <b>TM37544</b><br>   | 3873310325<br>3873310225 | U Bolt, Spring<br>With Nut<br>M20x1,5/91x458  | 625 NG<br>625 SK<br>659 SK<br>398 1926/AK 4X4  |
| <b>TM27105</b><br>   | 3363310025<br>3333310125 | U Bolt, Spring<br>With Nut<br>M20x1,5/91x313  | 336 LPS 1924<br>343 T2/L<br>346 LA 1924<br>346 LAK 1924<br>346 LAS 1924<br>363 LPB 2226/6X4<br>363 LPK 2226/6X4                |
| <b>TM37545</b><br>   | 3043311925<br>3343310125 | U Bolt, Spring<br>With Nut<br>M20x1,5x91x279  | 336 LPS 1924<br>343 T2/LN1<br>350 LS 1924<br>350 LS 1924A,1929<br>350 LS 1924A,1929,1930<br>363 LP 2226/6X4<br>363 LP 2232/6X4 |
| <b>TM37546</b><br> | 6253510025<br>6243510025 | U Bolt, Spring<br>With Nut<br>M24x1,5/101x495 | 625 NG<br>625 SK   |
| <b>TM27734</b><br> | 9493310425               | U Bolt, Spring<br>With Nut<br>M20x1,5/92x350  | 952 ACTROS   |
| <b>TM37547</b><br> | 3213510925               | U Bolt, Spring<br>With Nut<br>M18x1,5/83x290  | 972 ATEGO<br>976 ATEGO<br>970 ATEGO 2<br>972 ATEGO 2<br>976 ATEGO 2<br>328 T2/   |
| <b>TM37548</b><br> | 3183510025               | U Bolt, Spring<br>With Nut<br>M16x1,5/85x340  | 318 LP<br>676 LK/LN2   |



| Model / Details  | Description                                    | Replaces Ref. No:                      | TM No.  |
|--|--|--|---|
| 669 T2/LN1<br>670 T2/LN1   | U Bolt, Spring<br>With Nut<br>M16x1,5/75x251   | 6703510825<br>6703510725<br>3123511125 | <b>TM37549</b><br>   |
| 634 O 500<br>634 O 500 RSD /<br>2736/8X2/30<br>634 TOURO<br>628 CITARO<br>633 INTEGRO<br>633 INTOURO<br>613 TOURISMO   | U Bolt, Spring<br>With Nut<br>M24x2/155x398    | 6293510125                             | <b>TM27723</b><br>   |
| 388 L 1929<br>388 L 1935<br>388 L 1938<br>388 L 1945<br>387 NG<br>389 NG<br>656 SK   | U Bolt, Spring<br>With Nut<br>M24x1,5/100x550  | 3893510025                             | <b>TM37550</b><br>   |
| 690 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER<br>909 SPRINTER   | U Bolt, Spring<br>With Nut<br>M14x1,5/75x131   | 9013250847                             | <b>TM27738</b><br> |
| 901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER   | U Bolt, Spring<br>With Nut<br>M14x1,5/74x115,5 | 9013250747                             | <b>TM27736</b><br> |
| 900 SPRINTER<br>904 SPRINTER<br>906 SPRINTER   | U Bolt, Spring<br>With Nut<br>M14x1,5/75x155   | 9063250747<br>9013250947               | <b>TM27737</b><br> |
| 388 L 2635/6X4/54<br>388 LK 2635/6X4/40<br>388 LS 2635/6X4/40<br>397 2624 A/6X6 MB-<br>SA-RSA<br>397 2624 AK/6X6 MB-<br>SA-RSA<br>397 2624 K/6X4 MB-<br>SA-RSA | U Bolt, Spring<br>With Nut<br>M24x1,5/102/431  | 3433510325<br>3483510325<br>3953510225 | <b>TM37551</b><br> |





| TM No.  | Replaces Ref. No:                                    | Description                                   | Model / Details   |
|---|--|---|---|
| <b>TM37552</b><br>   | 3953510525   | U Bolt, Spring<br>With Nut<br>M24x1,5/102/372 | -   |
| <b>TM27724</b><br>   | 9473510425   | U Bolt, Spring<br>With Nut<br>M27x2/102x448   | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3  |
| <b>TM37553</b><br>   | 6673250053   | Spacer Tube, Spring<br>ø12,5x81,5             | 398 LO 814<br>667 T2/LN1<br>668 T2/LN1<br>669 T2/LN1<br>670 T2/LN1<br>688 1114<br>688 709   |
| <b>TM37554</b><br> | 000000005513   | Screw, Spring<br>M14x1,5/160                  | 934 ACTROS 2/3<br>963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS<br>967 ATEGO 3<br>375 AXOR   |
| <b>TM27006</b><br> | 0003270101<br>0003270201<br>3073270101<br>3073270001 | Air Spring<br>ø130,8xø210x395                 | Blacktech RL 9755<br>CF Gomma 92574<br>Contitech 644 N<br>Firestone 1R1A-390-295<br>Firestone W01-095-0118<br>Goodyear 8017<br>Phoenix 1 E 21<br>Vibracoustic V 1 E 21<br>Wabco 896 130 105 4     |
| <b>TM27647</b><br> | 6133270201   | Air Spring<br>ø150,8xø243x391                 | Blacktech RL 9772<br>CF Gomma 91016<br>Contitech 661 N<br>Firestone 1R1C-390-310<br>Firestone W01-095-0021<br>Goodyear 8018<br>Phoenix 1 E 25<br>Vibracoustic V 1 E 25<br>Wabco 896 130 117 4     |
| <b>TM27047</b><br> | 3833270001<br>6213280001                             | Air Spring<br>ø130,8xø240x370                 | Blacktech RL 9784<br>CF Gomma 88786<br>Contitech 673 N<br>Firestone 1R1A-370-285<br>Firestone W01-095-0198<br>Goodyear 9051<br>Phoenix 1 F 21 A<br>Vibracoustic V 1 F 21 A<br>Wabco 896 130 007 4 |





| Model / Details  | Description                               | Replaces Ref. No:        | TM No.  |
|--|---|--------------------------|---|
| Blacktech RL 9826<br>CF Gomma 93518<br>Contitech 715 N<br>Firestone 1R1C-335-310<br>Firestone W01-095-0087<br>Goodyear 8015<br>Phoenix 1 F 25<br>Vibracoustic V 1 F 25                         | Air Spring<br>ø150,8xø260x350             | 3633280001               | <b>TM27757</b><br>   |
| Blacktech RL 9831<br>CF Gomma 88802<br>Contitech 720 N<br>Firestone 1R2A-460-295<br>Firestone W01-095-0195<br>Goodyear 9008<br>Phoenix 1 F 21<br>Vibracoustic V 1 F 21<br>Wabco 896 130 013 4  | Air Spring<br>ø130,8xø240x465             | 3873280101<br>3873280001 | <b>TM27546</b><br>   |
| Blacktech RL 9848<br>CF Gomma 89756<br>Contitech 737 N<br>Firestone 1R1A-480-330<br>Firestone W01-095-0211<br>Goodyear 9075<br>Phoenix 1 F 26<br>Vibracoustic V 1 F 26<br>Wabco 896 130 164 4  | Air Spring<br>ø130,8xø265x485             | 3933280101<br>3933280201 | <b>TM28137</b><br>  |
| Blacktech RL 9868<br>Contitech 757 N<br>Firestone 1R2A-380-305<br>Firestone W01-095-0212<br>Goodyear 9077<br>Phoenix 1 F 26 C<br>Vibracoustic V 1 F 26 C<br>Wabco 896 130 166 4                | Air Spring<br>ø130,8xø265x385             | 3633280201               | <b>TM28138</b><br> |
| Airtech 3819<br>Blacktech RL 9920<br>CF Gomma 90609<br>Contitech 819 N   | Air Spring<br>ø100,8xø160x350             | 0003280101               | <b>TM28224</b><br> |
| Blacktech RL 9949<br>Contitech 838 N<br>Goodyear 9074<br>Phoenix 1 F 26 D<br>Vibracoustic V 1 F 26 D<br>Wabco 896 130 163 4  | Air Spring<br>ø130,8xø265x595             | 6743280001               | <b>TM28259</b><br> |
| Blacktech RL 9993<br>CF Gomma 97042<br>Contitech 882 N1<br>Firestone 1R4R-465-260<br>Firestone W01-095-0435<br>Goodyear 9048<br>Phoenix 1 F 16<br>Vibracoustic V 1 F 16<br>Wabco 896 130 008 4 | Air Spring<br>ø100,8/ø130,8x-<br>ø210x465 | 6993280101               | <b>TM28677</b><br> |





| TM No.  | Replaces Ref. No:                        | Description                   | Model / Details  |
|---|--|-------------------------------|--|
| <b>TM27135</b><br>   | 9463280401<br>9463281101                 | Air Spring<br>ø310x415        | Blacktech RML 70081 C<br>Firestone 1T17B-11<br>Firestone W01-M58-8747<br>Goodyear 1R13-150<br>Phoenix 1 DK 25-1<br>Phoenix 1 DK 25-8747<br>Vibracoustic V 1 DK 25-8747<br>Wabco 951 813 150 0      |
| <b>TM37555</b><br>   | 9463281401S                              | Air Spring<br>ø248x488        | Airtech 39002-A8 P<br>Blacktech RML 75268-4<br>Blacktech RML 79003 A8  |
| <b>TM28694</b><br>  | 9463281401                               | Air Spring<br>ø280x395        | Airtech 39002-A8 KPP<br>Blacktech RML 75268 CP4<br>Blacktech RML 79003 A8 CP<br>Contitech 4157 N P04<br>Contitech 4157 N P14<br>Firestone 1T15MPW-7<br>Firestone W01-M58-6297<br>Goodyear 1R11-111 |
| <b>TM28192</b><br> | 9463281901                               | Air Spring<br>ø328x340        | Blacktech RML 71901 C<br>Firestone W01-M58-6222<br>Goodyear 1R14-825<br>Phoenix 1 D 28 A-13<br>Vibracoustic V 1 DK 28 A-13   |
| <b>TM37556</b><br> | -  | Air Spring<br>ø150,8xø290x460 | Airtech 34183-24 K<br>Blacktech RML 95294 C24<br>Contitech 4183 N P24<br>Contitech 4183 N P26<br>Vibracoustic V 1 KF 32-23-232   |
| <b>TM37557</b><br> | 9743280201<br>9423203021S<br>9743200021S | Air Spring<br>ø150,8xø290x489 | Airtech 34185-01 P<br>Airtech 34185-21 P<br>Blacktech RML 95296  |
| <b>TM27144</b><br> | 9423203021<br>9743200021                 | Air Spring<br>ø322x280        | Airtech 34185-01 K<br>Airtech 34185-21 K<br>Blacktech RML 95296 C21<br>Contitech 4185 N P01<br>Contitech 4185 N P21  |



| Model / Details   | Description                   | Replaces Ref. No:                         | TM No.  |
|---|-------------------------------|---|---|
| Airtech 34186-24 P  | Air Spring<br>ø334x230        | 9423201721<br>9423202521<br>9423207121    | <b>TM28249</b><br>   |
| Airtech 34186-23 K<br>Contitech 4186 N P21<br>Contitech 4186 N P23                            | Air Spring<br>ø150,8xø290x424 | 9423201621S<br>9423202421S<br>9423207021S | <b>TM37558</b><br>   |
| Airtech 34187-21 P<br>Blacktech RML 95298-1<br>Contitech 4187 N3                              | Air Spring<br>ø150,8xø290x460 | 9423202621S<br>9423207221S                | <b>TM28456</b><br>  |
| Airtech 34391-21 P<br>Blacktech RML 95402-1<br>Contitech 4391 N1                              | Air Spring<br>ø130,8xø240x369 | 9423280601                                | <b>TM37559</b><br> |
| Airtech 34391-22 P<br>Blacktech RML 95402-2<br>Contitech 4391 N2                              | Air Spring<br>ø130,8xø240x369 | 9423280701                                | <b>TM28260</b><br> |
| Airtech 34391-21 K<br>Blacktech RML 95402 C21<br>Contitech 4391 N P01<br>Contitech 4391 N P21 | Air Spring<br>ø300x240        | 9423200621<br>9423205321                  | <b>TM27158</b><br> |
| Airtech 34391-22 K<br>Blacktech RML 95402 C22<br>Contitech 4391 N P02<br>Contitech 4391 N P22 | Air Spring<br>ø300x240        | 9423200721<br>9423205421                  | <b>TM27752</b><br> |





| TM No.  | Replaces Ref. No:                      | Description                   | Model / Details  |
|---------|--|-------------------------------|--|
| TM27205 | 9423203721<br>9463200321<br>9463203721 | Air Spring<br>ø330x268        | Airtech 34737-21 K<br>Blacktech RML 95848 C21<br>Contitech 4737 N P01<br>Contitech 4737 N P21<br>Dunlop D13T04<br>Goodyear 9523                        |
| TM37560 | 9423203921<br>9463200521               | Air Spring<br>ø330x268        | Airtech 34737-22 K<br>Blacktech RML 95848 C22<br>Contitech 4737 N P02<br>Contitech 4737 N P22<br>Dunlop D13T05<br>Goodyear 9524                        |
| TM28226 | 9573200117<br>9573200317               | Air Spring<br>ø330x248        | Blacktech RML 95848 C25<br>Contitech 4737 N P05<br>Contitech 4737 N P25<br>Goodyear 9539   |
| TM27169 | 9423204821<br>9453200017               | Air Spring<br>ø326x265        | Airtech 34758-01 K<br>Airtech 34758-21 K<br>Blacktech RML 95869 C21<br>Contitech 4758 N P01<br>Contitech 4758 N P21<br>Vibracoustic V 1 KF 23-1-232    |
| TM28166 | 9463280001                             | Air Spring<br>ø130,8xø260x590 | Airtech 34838-21 P<br>Blacktech RML 95949<br>Contitech 4838 N<br>Firestone 1R7Z-595-330-C<br>Firestone W01-M58-0912<br>Vibracoustic V 1 KF 25-1-232 NP |
| TM37561 | 9423202221<br>9423206821               | Air Spring<br>ø328x280        | Airtech 34183-23 K<br>Blacktech RML 95294 C23<br>Contitech 4183 N P23<br>Contitech 4183 N P25  |
| TM27146 | 9423202621<br>9423207221<br>9423201821 | Air Spring<br>ø328x260        | Airtech 34187-21 K<br>Blacktech RML 95298 C21<br>Contitech 4187 N P01<br>Contitech 4187 N P23  |






| Model / Details   | Description                   | Replaces Ref. No:                      | TM No.  |
|---|-------------------------------|--|---|
| Airtech 34390-03 K<br>Airtech 34390-23 K<br>Blacktech RML 95401 C23<br>Contitech 4390 N P03<br>Contitech 4390 N P23<br>Dunlop D12T11<br>Goodyear 9563<br>Vibracoustic V 1 KF 21-4-232                           | Air Spring<br>ø268x290        | 9423205221<br>9423200421               | <b>TM28216</b><br>   |
| Airtech 34390-01 P<br>Blacktech RML 95401-1<br>Contitech 4390 N1<br>Goodyear 9507<br>Phoenix 1 KF 21-1 NP<br>Vibracoustic V 1 KF 21-1 NP<br>Wabco 896 130 171 4   | Air Spring<br>ø130,8xø240x437 | 9423280001                             | <b>TM28164</b><br>   |
| Airtech 34390-01 K<br>Airtech 34390-21 K<br>Blacktech RML 95401 C21<br>Contitech 4390 N P01<br>Contitech 4390 N P21<br>Firestone 1R7Z-440-290<br>Firestone W01-M58-8514<br>Goodyear 9505<br>Phoenix 1 KF 21-1   | Air Spring<br>ø268x290        | 9423200121<br>9423202821<br>9423204921 | <b>TM27751</b><br>  |
| Airtech 34390-02 P<br>Blacktech RML 95401-2<br>Contitech 4390 N2<br>Goodyear 9508<br>Phoenix 1 KF 21-2 NP<br>Vibracoustic V 1 KF 21-2 NP<br>Wabco 896 130 172 4   | Air Spring<br>ø130,8xø240x437 | 9423280101                             | <b>TM28159</b><br> |
| Airtech 34390-02 K<br>Airtech 34390-22 K<br>Blacktech RML 95401 C22<br>Contitech 4390 N P02<br>Contitech 4390 N P22<br>Goodyear 9506<br>Phoenix 1 KF 21-2<br>Phoenix 1 KF 21-22<br>Vibracoustic V 1 KF 21-2     | Air Spring<br>ø268x290        | 9423200221<br>9423202921<br>9423205021 | <b>TM28165</b>  |
| Airtech 34757-01 P<br>Blacktech RML 95868-1<br>Contitech 4757 N1<br>Goodyear 9517<br>Phoenix 1 KF 24-1 NP   | Air Spring<br>ø130,8xø260x446 | 9423270001                             | <b>TM28223</b><br> |
| Airtech 34757-01 K<br>Airtech 34757-21 K<br>Blacktech RML 95868 C21<br>Contitech 4757 N P01<br>Contitech 4757 N P21<br>Firestone 1R7Z-460-305-A<br>Firestone W01-M58-8521<br>Goodyear 9519<br>Phoenix 1 KF 24-1 | Air Spring<br>ø292x240        | 9423200117<br>9423204321               | <b>TM27206</b><br> |







| TM No.  | Replaces Ref. No: | Description                   | Model / Details  |
|---|-------------------|-------------------------------|--|
| <b>TM28220</b><br>   | 9743280001        | Air Spring<br>ø130,8xø260x446 | Airtech 34757-02 P<br>Blacktech RML 95868-2<br>Contitech 4757 N2<br>Goodyear 9518<br>Phoenix 1 KF 24-2 NP<br>Vibracoustic V 1 KF 24-2-232 NP   |
|   | 9743280101        |                               |  |
| <b>TM28195</b><br>   | 9743200417        | Air Spring<br>ø292x240        | Airtech 34757-02 K<br>Airtech 34757-29 K<br>Blacktech RML 95868 C29<br>Contitech 4757 N P09<br>Contitech 4757 N P29<br>Goodyear 9520<br>Phoenix 1 KF 24-29<br>Phoenix 1 KF 24-9                |
|   | 9423203221        |                               |  |
|   | 9743200217        |                               |  |
| <b>TM28167</b><br>   | 9463200421        | Air Spring<br>ø314x360        | Airtech 34838-01 K<br>Airtech 34838-21 K<br>Blacktech RML 95949 C21<br>Contitech 4838 N P01<br>Contitech 4838 N P21<br>Firestone W01-M58-8512<br>Goodyear 9521<br>Vibracoustic V 1 KF 25-1-232 |
|   | 9423203821        |                               |  |
| <b>TM28168</b><br> | 9463200121        | Air Spring<br>ø314x360        | Airtech 34838-03 K<br>Airtech 34838-23 K<br>Blacktech RML 95949 C23<br>Blacktech RML 95949 C3<br>Contitech 4838 N P03<br>Contitech 4838 N P23<br>Goodyear 9536<br>Vibracoustic V 1 KF 25-3-232 |
|   | 9423203521        |                               |  |
|   | 3753200421        |                               |  |
| <b>TM37562</b><br> | 9423203621        | Air Spring<br>ø314x360        | Airtech 34838-22 K<br>Blacktech RML 95949 C22<br>Contitech 4838 N P02<br>Contitech 4838 N P22<br>Goodyear 9522<br>Vibracoustic V 1 KF 25-2-232   |
|   | 9463200221        |                               |  |
| <b>TM29004</b><br> | 3823277101        | Air Spring<br>ø198,1xø300x390 | Airtech 3762<br>Blacktech RL 9873<br>CF Gomma 92594<br>Contitech 762 N<br>Firestone W01-095-0190<br>Goodyear 9010<br>Phoenix 1 F 32<br>Taurus BL143<br>Vibracoustic V 1 F 32                   |
|   |                   |                               |  |
| <b>TM28906</b><br> | 0003280001        | Air Spring<br>ø130,8xø190x410 | Airtech 3921<br>Blacktech RL 9032<br>CF Gomma 202728<br>Contitech 921 N<br>Dunlop D10S04<br>Firestone W01-095-0226<br>Goodyear 8043<br>Phoenix 1 E 17  |
|   |                   |                               |  |












| Model / Details  | Description                   | Replaces Ref. No:                                    | TM No.  |
|--|-------------------------------|--|---|
| Airtech 3946<br>Blacktech RL 9057<br>Contitech 946 N<br>Phoenix 1 F 20 C<br>Vibracoustic V 1 F 21 C-6                          | Air Spring<br>ø130,8xø230x435 | 6283230092   | <b>TM28225</b><br>   |
| Airtech 34183-24 K<br>Blacktech RML 95294 C24<br>Contitech 4183 N P24<br>Contitech 4183 N P26<br>Vibracoustic V 1 KF 32-23-232 | Air Spring<br>ø328x280        | 9423202321<br>9423201321<br>9423201421<br>3753200021 | <b>TM28186</b><br>   |
| Airtech 34759-21 P<br>Blacktech RML 95860<br>Contitech 4759 N  | Air Spring<br>ø130,8xø260x335 | 9423270401   | <b>TM28221</b><br>   |
| Airtech 34759-21 K<br>Blacktech RML 95860 C21<br>Contitech 4759 N P01<br>Contitech 4759 N P21<br>Vibracoustic V 1 KF 27-1-232  | Air Spring<br>ø293x200        | 9423204421<br>9423200217                             | <b>TM27170</b><br> |
| Airtech 34183-23 P<br>Airtech 34183 P<br>Blacktech RML 95294-1<br>Contitech 4183 N2  | Air Spring<br>ø150,8xø290x460 | -  | <b>TM37563</b><br> |
| Blacktech RML 78263 C<br>Goodyear 1R11-847<br>Vibracoustic V 1 DK 22 G-1   | Air Spring<br>ø284x300        | 9423205921   | <b>TM28214</b><br> |
| Airtech 30283 K<br>Blacktech RML 71501 C<br>Goodyear 1R14-823<br>Phoenix 1 DK 28 F-3<br>Vibracoustic V 1 DK 28 F-3             | Air Spring<br>ø320x380        | 9463281501   | <b>TM27134</b><br> |





| TM No.  | Replaces Ref. No:                         | Description                   | Model / Details   |
|---|---|-------------------------------|---|
| <b>TM37564</b>  | 9603203257                                | Air Spring                    | Contitech 4019 N1 P01   |
|    |   |                               |   |
| <b>TM28329</b>  | 9603200121                                | Air Spring<br>ø305x224        | Contitech 6126 N P40  |
|    |   |                               |   |
| <b>TM28326</b>  | 9603200221                                | Air Spring<br>ø305x224        | Contitech 6126 N P41  |
|    |   |                               |   |
| <b>TM27149</b>  | 9463280901<br>9463281201                  | Air Spring<br>ø320x395        | Firestone W01-M58-6276<br>Goodyear 1R12-807<br>Goodyear 1R12-433<br>Goodyear 1R12-739<br>Wabco 951 812 739 0  |
|  |   |                               |   |
| <b>TM28257</b>  | 9423270601<br>9423206021                  | Air Spring<br>ø220x206        | Blacktech 2C 21-210 P15<br>CF Gomma 207065<br>Contitech FD 200-19 P02<br>Firestone W01-M58-7756<br>Goodyear 2B9-234   |
|  |   |                               |   |
| <b>TM28256</b>  | 9463281601                                | Air Spring<br>ø225x256        | Airkraft 113012<br>Contitech FD 200-25 1/4<br>M10<br>Firestone W01-M58-7679<br>Goodyear 2B9-269<br>Phoenix SP 2 B 12 RA-10<br>Vibracoustic V SP 2 B 12<br>RA-10 |
|  |   |                               |   |
| <b>TM37565</b>  | 9423201721S<br>9423202521S<br>9423207121S | Air Spring<br>ø150,8xø290x424 | Airtech 34186-24 P  |
|  |   |                               |   |



| Model / Details  | Description                   | Replaces Ref. No:  | TM No.  |
|--|-------------------------------|--|---|
| Airtech 34186-23 K<br>Contitech 4186 N P21<br>Contitech 4186 N P23   | Air Spring<br>ø334x230        | 9423201621<br>9423202421<br>9423207021                   | <b>TM37566</b><br>   |
| Blacktech RML 95298-2<br>Contitech 4187 N4   | Air Spring<br>ø150,8xø290x460 | 3753200121S<br>9423201921S<br>9423202721S<br>9423207321S | <b>TM37567</b><br>   |
| Airtech 34187-22 K<br>Blacktech RML 95298 C22<br>Contitech 4187 N P22<br>Contitech 4187 N P24                  | Air Spring<br>ø328x260        | 3753200121<br>9423201921<br>9423202721<br>9423207321     | <b>TM28252</b><br>   |
| Airtech 34390-24 K<br>Blacktech RML 95401 C24<br>Contitech 4390 N P04<br>Contitech 4390 N P24<br>Goodyear 9564 | Air Spring<br>ø268x290        | 9423200321<br>9423205121                                 | <b>TM28222</b><br> |
| Contitech 4737 N P26<br>Goodyear 9565  | Air Spring<br>ø330x265        | 9423206321<br>9423201017                                 | <b>TM28333</b><br> |
| Contitech 4757 N P23   | Air Spring<br>ø292x240        | 9573200417   | <b>TM37568</b><br> |





| TM No.  | Replaces Ref. No:                      | Description  | Model / Details  |
|---|--|--|--|
| <b>TM28253</b><br>   | 9423200617<br>9423203321               | Air Spring<br>ø326x265   | Blacktech RML 95869 C23<br>Contitech 4758 N P23  |
| <b>TM28254</b><br>   | 9423204521<br>9743200117               | Air Spring<br>ø238x225   | Airtech 34786 K<br>Airtech 34786-21 K<br>Contitech 4786 N P01<br>Contitech 4786 N P21                    |
| <b>TM37569</b><br>   | 9423200121S<br>9423200221S             | Piston, Air Spring<br>For SP 554390-K01 and<br>SP 554390-K02<br>ø200x165 | BM MODEL<br>950 ACTROS<br>952 ACTROS<br>954 ACTROS<br>375 AXOR<br>944 AXOR 2<br>950 AXOR 2<br>954 AXOR 2 |
| <b>TM37570</b><br> | 9743200417S                            | Piston, Air Spring<br>ø280x155   | BM MODEL<br>970 ATEGO<br>970 ATEGO 2<br>974 ATEGO 2<br>975 ATEGO 2                                       |
| <b>TM37571</b><br> | 9423202221S                            | Piston, Air Spring<br>For SP 554183-K and<br>SP 554183-K02<br>ø263x173   | BM MODEL<br>934 ACTROS 2/3<br>375 AXOR<br>944 AXOR 2   |
| <b>TM27840</b><br> | 3573200134<br>3573201534<br>6133200034 | Piston, Air Spring   | BM MODEL<br>396 OH SERIES<br>300 O 303<br>301 O 303<br>373 O 303<br>600 O 303<br>373 O 304<br>373 O 330  |
| <b>TM37572</b><br> | 3933201018                             | Piston, Air Spring   | BM MODEL<br>620 NG<br>645 NG<br>646 NG<br>655 SK   |



| Model / Details                              | Description  | Replaces Ref. No:                      | TM No.  |
|--|--|--|---|
| -  | Piston, Air Spring<br>For SP 554157-KP14<br>ø199x172 | -                                      | <b>TM37573</b><br>   |
| Contitech 6120 N P48                         | Air Spring<br>ø315x280                               | 9603201357                             | <b>TM28327</b><br>   |
| Contitech 6120 N P49                         | Air Spring<br>ø315x280                               | 9603201757                             | <b>TM28334</b><br>  |
| Contitech 6121 N P44                         | Air Spring<br>ø260x280                               | 9603201257<br>9603206257               | <b>TM28332</b><br> |
| Airtech 36122-01 KPP<br>Contitech 6122 N P47 | Air Spring<br>ø280x280                               | 9603200157<br>9603206857<br>9603207721 | <b>TM28328</b><br> |
| Airtech 36122 KPP<br>Contitech 6122 N P46    | Air Spring<br>ø280x280                               | 9603200057<br>9603206757<br>9603207021 | <b>TM28325</b><br> |
| Contitech 6123 N P40                         | Air Spring<br>ø285x400                               | 9603200657<br>9603207157               | <b>TM28324</b><br> |





| TM No.  | Replaces Ref. No:        | Description                        | Model / Details  |
|---|--------------------------|------------------------------------|--|
| <b>TM28331</b>  | 9603200321               | Air Spring<br>ø260x239             | Contitech 6127 N P40   |
|    |                          |                                    |  |
| <b>TM28330</b>  | 9603203457<br>9603207657 | Air Spring<br>ø330x303             | Contitech 6131 N P40   |
|    |                          |                                    |  |
| <b>TM28163</b>  | 3053240108               | Buffer, Air Spring<br>ø16xø115x9   | 368 OH SERIES<br>382 OH SERIES<br>396 OH SERIES<br>300 O 303<br>301 O 303<br>373 O 303<br>600 O 303  |
|    |                          |                                    |  |
| <b>TM28261</b>  | 3053240308               | Buffer, Air Spring<br>ø14xø100x115 | BM MODEL<br>699 MK<br>396 OH SERIES<br>300 O 303<br>301 O 303<br>373 O 303<br>600 O 303<br>373 O 304 |
|  |                          |                                    |  |
| <b>TM37574</b>  | 9423252409               | Bracket, Air Spring<br>Left        | 934 ACTROS 2/3<br>375 AXOR<br>374 AXOR 2<br>944 AXOR 2<br>954 AXOR 2                                 |
|  |                          |                                    |  |
| <b>TM37575</b>  | 9423252509               | Bracket, Air Spring<br>Right       | 934 ACTROS 2/3<br>375 AXOR<br>374 AXOR 2<br>944 AXOR 2<br>954 AXOR 2                                 |
|  |                          |                                    |  |
| <b>TM28350</b>  | 9603280011<br>9603281311 | Centering Cone, Air Spring         | 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS   |
|  |                          |                                    |  |





| Model / Details   | Description                                       | Replaces Ref. No:                                    | TM No.  |
|---|---|--|---|
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3            | Bogie Bearing<br>ø146,5                           | 9473250012<br>9473251012                             | <b>TM37576</b>  |
|   |   |  |    |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3            | Bogie Bearing<br>ø146,5                           | 9473250042   | <b>TM37577</b>  |
|   |   |  |    |
| 343 T2/L<br>388 L 2635/6X4/54<br>388 LK 2635/6X4/40<br>388 LS 2635/6X4/40<br>696 L 2638<br>696 LK 2638<br>696 LS 2638 | Bogie Bearing<br>ø137/ø170                        | 3953250312<br>6243250012<br>6243250112<br>6243250212 | <b>TM37578</b>  |
|   |   |  |    |
| 964 AROCS   | Bogie Bearing<br>ø150                             | 9603250912   | <b>TM37579</b>  |
|   |   |  |  |
| 964 AROCS   | Rubber Bushing, Bogie Suspension<br>ø121xø150x100 | 9603250085   | <b>TM27531</b>  |
|   |   |  |  |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3            | Rubber Bushing, Bogie Suspension<br>ø107x170      | 0003250485<br>0003250985                             | <b>TM28178</b>  |
|   |   |  |  |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3            | Seal Ring, Bogie Suspension<br>ø136xø174x10       | 9473250050   | <b>TM28179</b>  |
|   |   |  |  |



| TM No.  | Replaces Ref. No:        | Description   | Model / Details  |
|---|--------------------------|---|--|
| <b>TM27051</b><br>   | 0059978447<br>0099978846 | Seal Ring, Bogie Suspension<br>ø170xø190x8,5/9,5 /<br>NBR | 343 T2/L<br>388 L 2635/6X4/54<br>388 LK 2635/6X4/40<br>388 LS 2635/6X4/40<br>696 L 2638<br>696 LK 2638<br>696 LS 2638                          |
| <b>TM31944</b><br>   | 3953200067               | Seal Ring, Bogie Suspension<br>ø200xø218x10               | 343 T2/L<br>388 L 2635/6X4/54<br>388 LK 2635/6X4/40<br>388 LS 2635/6X4/40<br>696 L 2638<br>696 LK 2638<br>696 LS 2638                          |
| <b>TM27653</b><br>   | 0119973746<br>0099975346 | Seal Ring, Bogie Suspension<br>ø143xø165x8,5 / NBR        | 345 L 2225<br>386 L 2314,2414<br>386 L 2318,2418<br>386 L 2325,2425,LA<br>2425/6X6<br>386 LB 2318,2418<br>386 LB 2325,2425<br>386 LK 2318,2418 |
| <b>TM27767</b><br> | 3893251062               | Thrust Washer, Bogie Suspension<br>ø115/ø150xø189x24      | BM MODEL<br>343 T2/L<br>388 L 2635/6X4/54<br>388 LK 2635/6X4/40<br>388 LS 2635/6X4/40<br>696 L 2638<br>696 LK 2638<br>696 LS 2638              |
| <b>TM27771</b><br> | 3873250162               | Thrust Washer, Bogie Suspension<br>ø94/ø125xø143x24       | 345 L 2225<br>386 L 2314,2414<br>386 L 2318,2418<br>386 L 2325,2425,LA<br>2425/6X6<br>386 LB 2318,2418<br>386 LB 2325,2425<br>386 LK 2318,2418 |
| <b>TM27802</b><br> | 3893200684               | Cover, Bogie Suspension<br>12,46x222,14x64,9              | BM MODEL<br>343 T2/L<br>388 L 2635/6X4/54<br>388 LK 2635/6X4/40<br>388 LS 2635/6X4/40<br>696 L 2638<br>696 LK 2638<br>696 LS 2638              |
| <b>TM27855</b><br> | 3833200084               | Cover, Bogie Suspension                                   | 345 L 2225<br>386 L 2314,2414<br>386 L 2318,2418<br>386 L 2325,2425,LA<br>2425/6X6<br>386 LB 2318,2418<br>386 LB 2325,2425<br>386 LK 2318,2418 |

| Model / Details  | Description  | Replaces Ref. No:                                    | TM No.  |
|--|--|--|---|
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3                                     | Screw, Bogie Suspension  | 000000005728<br>910105020025                         | <b>TM37580</b><br>   |
| 964 AROCS<br>967 ATEGO 3<br>388 L 2635/6X4/54<br>388 LK 2635/6X4/40<br>388 LS 2635/6X4/40<br>384 OF SERIES<br>368 OH SERIES                    | Screw, Bogie Suspension  | 000000005579<br>910105020032                         | <b>TM37581</b><br>   |
| 375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>976 ATEGO<br>375 ATEGO 2<br>958 ATEGO 2<br>970 ATEGO 2  | Bearing, Bogie Suspension<br>Repl. FAG: 32022X<br>ø110xø170x38 | 0029815005<br>0029815305<br>0059819005<br>0069819205 | <b>TM30371</b><br>   |
| 343 T2/L<br>388 L 2635/6X4/54<br>388 LK 2635/6X4/40<br>388 LS 2635/6X4/40<br>696 L 2638<br>696 LK 2638<br>696 LS 2638                          | Bearing, Bogie Suspension<br>ø105xø170x38                      | 0049810605<br>0039816805<br>0079810305               | <b>TM27816</b><br> |
| 343 T2/L<br>388 L 2635/6X4/54<br>388 LK 2635/6X4/40<br>388 LS 2635/6X4/40<br>696 L 2638<br>696 LK 2638<br>696 LS 2638                          | Nut, Bogie Suspension<br>M90x2/28                              | 3893252152   | <b>TM37582</b><br> |
| 343 T2/L<br>388 L 2635/6X4/54<br>388 LK 2635/6X4/40<br>388 LS 2635/6X4/40<br>696 L 2638<br>696 LK 2638<br>696 LS 2638                          | Nut, Bogie Suspension<br>M80x2/18                              | 3899905060<br>3899905080                             | <b>TM27709</b><br> |
| 345 L 2225<br>386 L 2314,2414<br>386 L 2318,2418<br>386 L 2325,2425,LA<br>2425/6X6<br>386 LB 2318,2418<br>386 LB 2325,2425<br>386 LK 2318,2418 | Nut, Bogie Suspension<br>M80x2/25                              | 3933250052   | <b>TM37583</b><br> |



| TM No.  | Replaces Ref. No:                         | Description                                   | Model / Details  |
|---|---|---|--|
| <b>TM30513</b><br>   | 3939900060                                | Nut, Bogie Suspension<br>M70x2/18             | 345 L 2225<br>386 L 2314,2414<br>386 L 2318,2418<br>386 L 2325,2425,LA<br>2425/6X6<br>386 LB 2318,2418<br>386 LB 2325,2425<br>386 LK 2318,2418 |
| <b>TM37584</b><br>   | 0003250485S<br>0003250985S<br>9473250050S | Repair Kit, Bogie Suspension<br>ø107xø150x170 | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3                                     |
| <b>TM28016</b><br>   | 3753230165<br>9433230265<br>9433230565    | Stabilizer Bar<br>920x345/ø40                 | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS   |
| <b>TM28015</b><br> | 9493230265                                | Stabilizer Bar<br>956x399/ø50                 | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>942 AXOR 2                                     |
| <b>TM37585</b><br> | 9433230365                                | Stabilizer Bar<br>1080x279/ø30                | 950 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>934 ACTROS 2/3<br>374 AXOR 2<br>950 AXOR 2   |
| <b>TM28014</b><br> | 3753230065<br>9433230465                  | Stabilizer Bar<br>1080x334/ø40                | 950 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>934 ACTROS 2/3<br>374 AXOR 2<br>950 AXOR 2   |
| <b>TM37586</b><br> | 9433260365<br>9433260565                  | Stabilizer Bar<br>ø16x649x340/ø50             | 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3   |



| Model / Details   | Description                                       | Replaces Ref. No:                      | TM No.  |
|---|---|--|---|
| 964 ACTROS MP4<br>964 ANTOS<br>964 AROCS  | Stabilizer Bar<br>1100x290/ø40                    | 9603230217                             | <b>TM37587</b><br>   |
| 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS  | Stabilizer Bar<br>1100x338/ø36                    | 9603230617<br>9603231365               | <b>TM37588</b><br>   |
| 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS  | Stabilizer Bar<br>1100x238/ø36                    | 9603230717<br>9603230817<br>9603231465 | <b>TM37589</b><br>  |
| 964 AROCS   | Stabilizer Bar<br>1080x333/ø36                    | 9603230917<br>9603231565               | <b>TM37590</b><br> |
| 964 AROCS   | Stabilizer Bar<br>1080x373/ø45                    | 9603230417<br>9603231265               | <b>TM37591</b><br> |
| 651 MK<br>652 MK<br>653 MK<br>654 MK<br>655 SK<br>656 SK<br>658 SK  | Rubber Bushing, Stabilizer<br>Bar<br>ø16xø68x60   | 6533260481                             | <b>TM28188</b><br> |
| 611 T1/TN<br>601 207 D/208 D<br>601 208/210<br>601 209 D/210 D<br>602 307 D/308 D<br>602 308 D<br>602 308/310 | Rubber Bushing, Stabilizer<br>Bar<br>ø16xø26,5x26 | 6023210050<br>6023210250               | <b>TM37592</b><br> |







| TM No.  | Replaces Ref. No:        | Description                                    | Model / Details   |
|---|--------------------------|--|---|
| <b>TM28268</b>  | 6013210350               | Rubber Bushing, Stabilizer Bar<br>ø12xø26x26   | 611 T1/TN<br>667 T2/LN1<br>668 T2/LN1<br>669 T2/LN1<br>670 T2/LN1<br>405 UNIMOG<br>408 UNIMOG     |
|    |                          |  |   |
| <b>TM28176</b>  | 3093200073<br>3143260153 | Rubber Bushing, Stabilizer Bar<br>ø12xø28,5x30 | 970 ATEGO<br>972 ATEGO<br>970 ATEGO 2<br>972 ATEGO 2<br>974 ATEGO 2<br>975 ATEGO 2<br>976 ATEGO 2 |
|    |                          |  |   |
| <b>TM28205</b>  | 6673200073               | Rubber Bushing, Stabilizer Bar<br>ø12xø32,5x36 | 979 ACCELO<br>398 LO 814<br>667 T2/LN1<br>668 T2/LN1<br>669 T2/LN1<br>670 T2/LN1<br>688 1114      |
|    |                          |  |   |
| <b>TM28229</b>  | 3563230081               | Rubber Bushing, Stabilizer Bar<br>ø20xø49x40   | 356 O 404<br>613 TOURISMO   |
|  |                          |  |   |
| <b>TM28194</b>  | 3183200073               | Rubber Bushing, Stabilizer Bar<br>ø16xø34x40   | 375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>375 ATEGO 2<br>958 ATEGO 2       |
|  |                          |  |   |
| <b>TM28200</b>  | 9743280181               | Rubber Bushing, Stabilizer Bar<br>ø22xø47,5x40 | 970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>958 ATEGO 2<br>970 ATEGO 2<br>974 ATEGO 2<br>975 ATEGO 2   |
|  |                          |  |   |
| <b>TM28346</b>  | 9743270181               | Rubber Bushing, Stabilizer Bar<br>ø22xø68x60   | 970 ATEGO<br>970 ATEGO 2<br>967 ATEGO 3<br>384 OF SERIES<br>368 OH SERIES                         |
|  |                          |  |   |





| Model / Details  | Description  | Replaces Ref. No:                          | TM No.  |
|--|--|--|---|
| 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3     | Rubber Bushing, Stabilizer<br>Bar<br>ø40xø70x46,5                          | 0003237985<br>0003237485<br>0003237585     | <b>TM28170</b><br>   |
| 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3     | Rubber Bushing, Stabilizer<br>Bar<br>011.142's alternative<br>ø40xø65x46,5 | 0003237985S2<br>0003237485S<br>0003237585S | <b>TM28441</b><br>   |
| 650 MK<br>651 MK<br>652 MK<br>653 MK<br>654 MK<br>625 SK<br>658 SK   | Rubber Bushing, Stabilizer<br>Bar<br>ø32xø60x52                            | 0003262381<br>0003262281<br>0003262781     | <b>TM28173</b><br>  |
| 650 MK<br>651 MK<br>652 MK<br>653 MK<br>654 MK<br>625 SK<br>437 UNIMOG                                     | Rubber Bushing, Stabilizer<br>Bar<br>ø18,5xø60x52                          | 0003263781<br>0003263681<br>0003263881     | <b>TM28213</b><br> |
| 972 ATEGO<br>976 ATEGO<br>958 ATEGO 2<br>970 ATEGO 2<br>972 ATEGO 2<br>976 ATEGO 2<br>967 ATEGO 3          | Rubber Bushing, Stabilizer<br>Bar<br>ø16xø39,5x40                          | 9743200444                                 | <b>TM37593</b><br> |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 | Rubber Bushing, Stabilizer<br>Bar<br>ø40xø80x46                            | 0003238185                                 | <b>TM27533</b><br> |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 | Rubber Bushing, Stabilizer<br>Bar<br>011.210's alternative<br>ø40xø75x46   | 0003238185S                                | <b>TM37594</b><br> |



| TM No.  | Replaces Ref. No:          | Description                                      | Model / Details   |
|---|----------------------------|--|---|
| <b>TM37595</b><br>   | 4603525014                 | Rubber Bushing, Stabilizer Bar<br>ø16xø65x60     | -   |
| <b>TM37596</b><br>   | 4603330314                 | Rubber Bushing, Stabilizer Bar<br>ø16xø70x50     | -   |
| <b>TM37597</b><br>  | 6583230085                 | Rubber Bushing, Stabilizer Bar<br>ø31xø68x60     | 652 MK<br>653 MK<br>655 SK<br>657 SK<br>658 SK                  |
| <b>TM37598</b><br> | 6553230085                 | Rubber Bushing, Stabilizer Bar<br>ø48xø71,5x41   | 652 MK<br>653 MK<br>397 OH SERIES<br>655 SK<br>657 SK<br>658 SK |
| <b>TM28302</b><br> | 9603261781<br>0003265581   | Rubber Bushing, Stabilizer Bar<br>ø35xø80x47     | 963 ACTROS MP4<br>964 AROCS                                     |
| <b>TM28307</b><br> | 9603231985<br>9603233185   | Rubber Bushing, Stabilizer Bar<br>ø20,3xø70x55,6 | 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS      |
| <b>TM37599</b><br> | 9603231985S<br>9603233185S | Rubber Bushing, Stabilizer Bar<br>ø20,3xø65x55,6 | 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS      |



| Model / Details  | Description   | Replaces Ref. No:          | TM No.  |
|--|---|----------------------------|---|
| 963 ACTROS MP4   | Rubber Bushing, Stabilizer<br>Bar<br>ø18xø57x46     | 9603232285<br>9603233585   | <b>TM28309</b><br>   |
| 964 AROCS  | Rubber Bushing, Stabilizer<br>Bar<br>ø20xø75x70     | 0009980642<br>9609980142   | <b>TM28304</b><br>   |
| 963 ACTROS MP4   | Rubber Bushing, Stabilizer<br>Bar<br>ø18,3xø70x55,6 | 9603231085<br>9603233485   | <b>TM28305</b><br>  |
| 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS   | Rubber Bushing, Stabilizer<br>Bar<br>ø18xø80x51     | 9603232385<br>9603233685   | <b>TM28310</b><br> |
| 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS   | Rubber Bushing, Stabilizer<br>Bar<br>ø18xø75x51     | 9603232385S<br>9603233685S | <b>TM37600</b><br> |
| 950 ACTROS<br>952 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>934 ACTROS 2/3<br>963 ACTROS MP4 | Rubber Bushing, Stabilizer<br>Bar<br>ø88xø20,5/130  | 9423260050                 | <b>TM27527</b><br> |
| 950 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>934 ACTROS 2/3<br>963 ACTROS MP4<br>964 ACTROS MP4<br>964 AROCS  | Rubber Bushing, Stabilizer<br>Bar<br>ø73,5xø19/100  | 9413230050                 | <b>TM28180</b><br> |











| TM No.  | Replaces Ref. No:        | Description                                      | Model / Details   |
|---|--------------------------|--|---|
| <b>TM37601</b><br>   | 3603230085               | Rubber Bushing, Stabilizer Bar<br>ø24,3xø80,5x60 | 963 ACTROS MP4<br>964 AROCS   |
| <b>TM28348</b><br>   | 9603233785<br>9603235185 | Rubber Bushing, Stabilizer Bar<br>ø18xø70,5x62,5 | 963 ACTROS MP4  |
| <b>TM37602</b><br>  | 9603260781               | Rubber Bushing, Stabilizer Bar<br>ø80/19x23      | 963 ACTROS MP4<br>964 AROCS   |
| <b>TM37603</b><br> | 0003239185               | Rubber Bushing, Stabilizer Bar<br>ø20,3xø80,5x60 | 964 AROCS   |
| <b>TM37604</b><br> | 0003238885               | Rubber Bushing, Stabilizer Bar<br>ø32xø76,5x53   | 964 AROCS   |
| <b>TM37605</b><br> | 9413250250               | Bushing, Stabilizer Bar                          | 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3  |
| <b>TM37606</b><br> | 3603230085               | Bushing, Stabilizer Bar<br>ø39x37                | 345 L 1313<br>345 L 1313,1314<br>345 L 1313,1314,1316<br>345 L 1313,1316<br>345 L 1316,L 1317,L 1318<br>345 L 1418 MBTC-USA<br>345 L 1513,1514,1516 |



| Model / Details   | Description                             | Replaces Ref. No: | TM No.         |
|---|---|-------------------|----------------|
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS  | Bushing, Stabilizer Bar<br>ø40xø52x24   | 9413230350        | <b>TM28157</b> |
| 345 L 1313<br>345 L 1313,1314<br>345 L 1313,1314,1316<br>345 L 1313,1316<br>345 L 1316,L 1317,L 1318<br>345 L 1418 MBTC-USA<br>345 L 1513,1514,1516 | Bushing, Stabilizer Bar<br>ø39,5xø65x22 | 3603230151        | <b>TM27299</b> |
| 388 L 1929<br>388 L 1935<br>388 L 1938<br>388 L 1945<br>388 L 2635/6X4/54<br>388 LK 2635/6X4/40<br>388 LS 1929                                      | Bushing, Stabilizer Bar<br>ø25,2xø35x25 | 6203230250        | <b>TM28151</b> |
| 336 LPS 1924<br>346 LS 1924<br>346 LS 1928<br>350 LS 1924<br>350 LS 1924A,1929<br>350 LS 1924A,1929,1930<br>363 LP 2226/6X4                         | Bushing, Stabilizer Bar<br>ø25xø35x28   | 0003230950        | <b>TM27789</b> |
| 619 NG<br>620 NG<br>621 NG<br>623 NG<br>624 NG<br>625 NG<br>625 SK  | Bushing, Stabilizer Bar<br>ø25xø35x30,5 | 6203230050        | <b>TM28150</b> |
| 336 LPS 1924<br>346 LS 1924<br>363 LP 2226/6X4<br>363 LP 2232/6X4<br>363 LPB 2226/6X4<br>363 LPK 2226/6X4<br>363 LPK 2232/6X4                       | Bushing, Stabilizer Bar<br>ø32xø44x35   | 0003260250        | <b>TM28153</b> |
| 696 L 2638<br>620 NG<br>621 NG<br>622 NG<br>623 NG<br>625 NG<br>645 NG  | Bushing, Stabilizer Bar<br>ø32xø44x36,5 | 3873260050        | <b>TM28145</b> |





| TM No.  | Replaces Ref. No:        | Description                                   | Model / Details   |
|---|--------------------------|---|---|
| <b>TM28134</b><br>   | 0003232150               | Bushing, Stabilizer Bar<br>ø32,5xø44x25       | 346 LS 1924<br>346 LS 1928<br>350 LS 1924<br>350 LS 1924A,1929<br>350 LS 1924A,1929,1930<br>388 L 1929<br>388 L 1935          |
| <b>TM37607</b><br>   | 6173260050               | Bushing, Stabilizer Bar<br>ø35xø55x19         | 615 LK/LN2<br>650 MK<br>651 MK<br>652 MK<br>615 NG<br>616 NG<br>617 NG  |
| <b>TM28133</b><br>  | 0003260650               | Bushing, Stabilizer Bar<br>ø40,5xø52x25       | 336 LPS 1924<br>346 LS 1924<br>363 LP 2226/6X4<br>363 LP 2232/6X4<br>363 LPB 2226/6X4<br>363 LPK 2226/6X4<br>363 LPK 2232/6X4 |
| <b>TM28148</b><br> | 6203230350               | Bushing, Stabilizer Bar<br>ø44xø56x25         | 652 MK<br>653 MK<br>654 MK<br>620 NG<br>621 NG<br>622 NG<br>623 NG  |
| <b>TM28147</b><br> | 6203230150               | Bushing, Stabilizer Bar<br>ø58,5xø70x19       | 652 MK<br>653 MK<br>654 MK<br>620 NG<br>621 NG<br>622 NG<br>623 NG  |
| <b>TM37608</b><br> | 9603231885<br>9603233085 | Bushing, Stabilizer Bar<br>ø20,3xø80x55,5     | 964 AROCS   |
| <b>TM28141</b><br> | 3173331164<br>3173330964 | Bushing, Stabilizer Bar<br>ø53,5xø82/ø85,5x40 | 396 OH SERIES<br>373 O 302<br>300 O 303<br>301 O 303<br>373 O 303<br>600 O 303<br>373 O 304                                   |












| Model / Details  | Description                                  | Replaces Ref. No:            | TM No.  |
|--|--|------------------------------|---|
| 396 OH SERIES<br>373 O 302<br>300 O 303<br>301 O 303<br>373 O 303<br>600 O 303<br>373 O 304                                    | Mounting, Stabilizer Bar<br>ø53,5xø84/ø89x40 | 3173331164S<br>3173330964S   | <b>TM37609</b><br>   |
| 396 OH SERIES<br>373 O 302<br>300 O 303<br>301 O 303<br>373 O 303<br>600 O 303<br>373 O 304                                    | Mounting, Stabilizer Bar<br>ø53,5xø80/ø84x39 | 3173331164S3<br>3173330964S3 | <b>TM37610</b><br>   |
| 652 MK<br>653 MK<br>382 OH SERIES<br>397 OH SERIES<br>655 SK<br>657 SK<br>658 SK   | Bearing, Stabilizer Bar<br>ø51,5xø89x60      | 6583260581                   | <b>TM28233</b><br>  |
| 345 LS 1524/1525<br>376 LPS 1525 MBTC-USA<br>376 LS 1418 MBTC-USA<br>384 LAK 1418<br>384 LK 1214<br>384 LK 1215<br>384 LK 1414 | Bearing, Stabilizer Bar<br>ø51xø81,5x100,5   | 3833260181                   | <b>TM37611</b><br> |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS   | Bearing, Stabilizer Bar<br>ø40xø65x46        | 9413260350                   | <b>TM28156</b><br> |
| 314 LP<br>316 LP<br>318 LP<br>684 508   INDONESIA  | Bearing, Stabilizer Bar<br>ø25,5x35x37,5     | 3183210085                   | <b>TM37612</b><br> |
| 314 LP   | Bearing, Stabilizer Bar<br>ø29,5x40x62       | 3143260381                   | <b>TM37613</b><br> |





| TM No.  | Replaces Ref. No: | Description                              | Model / Details   |
|---|-------------------|--|---|
| <b>TM37614</b><br>   | 3163260081        | Bearing, Stabilizer Bar<br>ø35x40x62     | 314 LP<br>316 LP<br>318 LP<br>408 UNIMOG<br>684 508   INDONESIA   |
| <b>TM37615</b><br>   | 3143260081        | Bearing, Stabilizer Bar<br>ø30x40x56,5   | 314 LP  |
| <b>TM37616</b><br>  | 3183260081        | Bearing, Stabilizer Bar<br>ø38x40x62     | 316 LP<br>318 LP<br>684 508   INDONESIA   |
| <b>TM37617</b><br> | 0003261781        | Bearing, Stabilizer Bar<br>ø56xø86x63    | 393 NG  |
| <b>TM37618</b><br> | 0003261581        | Bearing, Stabilizer Bar<br>ø50,5xø86x63  | 387 NG<br>389 NG<br>393 NG  |
| <b>TM37619</b><br> | 0003233285        | Bearing, Stabilizer Bar<br>ø36,5x70x63,5 | 336 LPS 1924<br>346 LS 1924<br>363 LP 2226/6X4<br>363 LP 2232/6X4<br>363 LPB 2226/6X4<br>363 LPK 2226/6X4<br>363 LPK 2232/6X4 |
| <b>TM28135</b><br> | 0003260881        | Bearing, Stabilizer Bar<br>ø40,5x70x63,5 | 336 LPS 1924<br>346 LS 1924   |



| Model / Details  | Description                             | Replaces Ref. No: | TM No.  |
|--|---|-------------------|---|
| 436 UNIMOG   | Bearing, Stabilizer Bar<br>ø32,5xø70x62 | 4353230085        | <b>TM37620</b><br>   |
| 346 LS 1924<br>346 LS 1928<br>385 NG<br>387 NG<br>389 NG<br>391 NG<br>393 NG   | Bearing, Stabilizer Bar<br>ø37xø70x62   | 0003233785        | <b>TM28143</b><br>   |
| 346 LS 1924<br>346 LS 1928<br>350 LS 1924<br>350 LS 1924A,1929<br>350 LS 1924A,1929,1930<br>388 L 1929<br>388 L 1935 | Bearing, Stabilizer Bar<br>ø37xø70x62   | 3873230285        | <b>TM28149</b><br>  |
| 387 NG<br>389 NG<br>393 NG<br>395 NG   | Bearing, Stabilizer Bar<br>ø41xø70x62   | 0003233985        | <b>TM37621</b><br> |
| 615 LK/LN2<br>650 MK<br>651 MK<br>652 MK<br>385 NG<br>387 NG<br>389 NG   | Bearing, Stabilizer Bar<br>ø41xø70x62   | 3873230385        | <b>TM28161</b><br> |
| 385 NG<br>387 NG<br>389 NG<br>619 NG<br>621 NG   | Bearing, Stabilizer Bar<br>ø46xø70x62   | 3873230185        | <b>TM37622</b><br> |
| 387 NG<br>389 NG   | Bearing, Stabilizer Bar<br>ø46xø70x62   | 0003233485        | <b>TM37623</b><br> |



| TM No.  | Replaces Ref. No: | Description                             | Model / Details   |
|---|-------------------|---|---|
| <b>TM28152</b><br>   | 0003261681        | Bearing, Stabilizer Bar<br>ø45xø86x63   | 336 LPS 1924<br>346 LS 1924<br>363 LP 2226/6X4<br>363 LP 2232/6X4<br>363 LPB 2226/6X4<br>363 LPK 2226/6X4<br>363 LPK 2232/6X4 |
| <b>TM28146</b><br>   | 3873260281        | Bearing, Stabilizer Bar<br>ø45xø86x63   | 336 LPS 1924<br>346 LS 1924<br>363 LP 2226/6X4<br>363 LP 2232/6X4<br>363 LPB 2226/6X4<br>363 LPK 2226/6X4<br>363 LPK 2232/6X4 |
| <b>TM28144</b><br>   | 3873260181        | Bearing, Stabilizer Bar<br>ø50,5xø86x63 | 387 NG<br>389 NG<br>393 NG<br>620 NG<br>621 NG<br>622 NG<br>623 NG  |
| <b>TM27565</b><br> | 3933260481        | Bearing, Stabilizer Bar<br>ø56xø86x63   | 696 L 2638<br>393 NG<br>623 NG<br>625 NG<br>648 NG<br>396 OH SERIES<br>625 SK   |
| <b>TM28162</b><br> | 6213230085        | Bearing, Stabilizer Bar<br>ø35xø70x62   | 621 NG<br>624 NG<br>646 NG<br>649 NG<br>625 SK<br>655 SK<br>656 SK  |
| <b>TM37624</b><br> | 0003260981        | Bearing, Stabilizer Bar<br>ø45,5x70x70  | 336 LPS 1924<br>346 LS 1924<br>363 LP 2226/6X4<br>363 LP 2232/6X4<br>363 LPB 2226/6X4<br>363 LPK 2226/6X4<br>363 LPK 2232/6X4 |
| <b>TM28189</b><br> | 6523260381        | Bearing, Stabilizer Bar<br>ø65xø114x65  | 651 MK<br>652 MK<br>653 MK<br>654 MK<br>655 SK  |



| Model / Details  | Description                           | Replaces Ref. No:                      | TM No.  |
|--|---------------------------------------|--|---|
| 621 NG<br>646 NG<br>655 SK<br>656 SK<br>657 SK<br>658 SK   | Bearing, Stabilizer Bar<br>ø69,5x65,5 | 6553260481                             | <b>TM28154</b><br>   |
| 620 NG<br>622 NG<br>623 NG<br>645 NG<br>647 NG<br>648 NG<br>655 SK                                     | Bearing, Stabilizer Bar<br>ø64x65,5   | 6553260581                             | <b>TM27822</b><br>   |
| 652 MK<br>653 MK<br>654 MK   | Bearing, Stabilizer Bar<br>ø44x60,5   | 6533260381                             | <b>TM37625</b><br>   |
| 673 LK/LN2   | Bearing, Stabilizer Bar<br>ø28x60     | 6733230485                             | <b>TM28263</b><br> |
| 673 LK/LN2<br>674 LK/LN2<br>676 LK/LN2   | Bearing, Stabilizer Bar<br>ø28x60     | 6733230385                             | <b>TM28228</b><br> |
| 674 LK/LN2<br>675 LK/LN2<br>676 LK/LN2<br>677 LK/LN2   | Bearing, Stabilizer Bar<br>ø35x59,5   | 6753230485                             | <b>TM28245</b><br> |
| 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3 | Bearing, Stabilizer Bar<br>ø39x56     | 0003262481<br>0003235985<br>0003262981 | <b>TM28155</b><br> |



| TM No.  | Replaces Ref. No: | Description                             | Model / Details  |
|---|-------------------|---|--|
| <b>TM28269</b><br>   | 9013230285        | Bearing, Stabilizer Bar<br>ø13,5xø26x24 | 690 SPRINTER<br>901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER<br>909 SPRINTER |
| <b>TM27482</b><br>   | 9013230185        | Bearing, Stabilizer Bar<br>ø22x30,5x39  | 690 SPRINTER<br>901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER                                 |
| <b>TM27483</b><br>   | 9043230085        | Bearing, Stabilizer Bar<br>ø25x30,5x39  | 690 SPRINTER<br>901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER<br>909 SPRINTER |
| <b>TM28286</b><br> | 6113260081        | Bearing, Stabilizer Bar<br>ø32x58       | 611 T1/TN  |
| <b>TM28270</b><br> | 6013260482        | Bearing, Stabilizer Bar<br>ø24x38       | -  |
| <b>TM28271</b><br> | 9013260081        | Bearing, Stabilizer Bar<br>ø22x38       | 690 SPRINTER<br>901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER                                 |
| <b>TM37626</b><br> | 6023260482        | Bearing, Stabilizer Bar<br>ø30x49       | 601 207 D/208 D<br>601 208/210<br>601 209 D/210 D  |





| Model / Details  | Description                         | Replaces Ref. No: | TM No.  |
|--|-------------------------------------|-------------------|---|
| 611 T1/TN<br>601 207 D/208 D<br>601 208/210<br>601 209 D/210 D   | Bearing, Stabilizer Bar<br>ø30,5x49 | 6023260882        | <b>TM28273</b><br>   |
| 308 L 608 E,L 708 E<br>308 L/LO 608 D<br>308 LO 608 D,LO 708 D/E<br>309 T2/L<br>310 LF 508 D/LF 608 D<br>310 T2/L<br>378 L 608 E | Bearing, Stabilizer Bar<br>ø37x84   | 3093260481        | <b>TM28283</b><br>   |
| 308 L 608 E,L 708 E<br>308 L/LO 608 D<br>308 LO 608 D,LO 708 D/E<br>309 T2/L<br>309 TL2/L<br>310 LF 508 D/LF 608 D<br>310 T2/L   | Bearing, Stabilizer Bar<br>ø30x50   | 3093230385        | <b>TM37627</b><br>   |
| BM MODEL<br>308 L/LO 608 D<br>308 LO 608 D,LO 708 D/E<br>309 T2/L<br>378 L 608 E<br>378 LO 608 D<br>309 O 309 B<br>309 O 309 D   | Bearing, Stabilizer Bar<br>ø34x84   | 3093260281        | <b>TM37628</b><br> |
| 669 T2/LN1<br>670 T2/LN1<br>688 LO 712/37<br>688 LO 809<br>688 LO 812<br>692 LO 813 D<br>685 914/42                              | Bearing, Stabilizer Bar<br>ø41x80   | 6683260181        | <b>TM28206</b><br> |
| 670 T2/LN1<br>667 VARIO<br>668 VARIO<br>670 VARIO  | Bearing, Stabilizer Bar<br>ø34,5x50 | 6673230585        | <b>TM28267</b><br> |
| 670 T2/LN1<br>667 VARIO<br>668 VARIO<br>670 VARIO  | Bearing, Stabilizer Bar<br>ø40x53   | 6703230385        | <b>TM37629</b><br> |





| TM No.  | Replaces Ref. No: | Description                         | Model / Details  |
|---|-------------------|-------------------------------------|--|
| <b>TM37630</b><br>   | 6673230485        | Bearing, Stabilizer Bar<br>ø29,5x50 | 668 T2/LN1<br>669 T2/LN1<br>688 709<br>692 L 710 D<br>667 VARIO<br>668 VARIO<br>670 VARIO                          |
| <b>TM37631</b><br>   | 6673260681        | Bearing, Stabilizer Bar<br>ø46x80   | 669 T2/LN1<br>670 T2/LN1<br>667 VARIO<br>668 VARIO<br>670 VARIO  |
| <b>TM37632</b><br>   | 6673230385        | Bearing, Stabilizer Bar<br>ø26x50   | 667 T2/LN1   |
| <b>TM37633</b><br> | 6673260081        | Bearing, Stabilizer Bar<br>ø36x80   | 667 T2/LN1<br>668 T2/LN1   |
| <b>TM37634</b><br> | 6673230285        | Bearing, Stabilizer Bar<br>ø30x50,5 | 667 T2/LN1<br>667 VARIO<br>668 VARIO<br>670 VARIO  |
| <b>TM37635</b><br> | 6023260282        | Bearing, Stabilizer Bar<br>ø33x49   | 601 207 D/208 D<br>601 208/210<br>601 209 D/210 D<br>602 307 D/308 D<br>602 307 D/308D<br>602 308 D<br>602 308/310 |
| <b>TM37636</b><br> | 3093230285        | Bearing, Stabilizer Bar<br>ø25x50   | 309 T2/L<br>309 O 309 B<br>309 O 309 D   |



| Model / Details  | Description                           | Replaces Ref. No:        | TM No.  |
|--|---------------------------------------|--------------------------|---|
| 667 VARIO<br>668 VARIO<br>670 VARIO                                | Bearing, Stabilizer Bar<br>ø50x80     | 6693260081               | <b>TM37637</b>  |
|  |                                       |                          |    |
| 673 LK/LN2<br>674 LK/LN2   | Bearing, Stabilizer Bar<br>ø36x46     | 6733260281<br>6733260581 | <b>TM37638</b>  |
|  |                                       |                          |    |
| 674 LK/LN2<br>676 LK/LN2<br>697 O 402<br>697 O 301                 | Bearing, Stabilizer Bar<br>ø38,5x46   | 6733260681<br>6733260181 | <b>TM37639</b>  |
|  |                                       |                          |    |
| 674 LK/LN2<br>676 LK/LN2<br>697 O 402<br>697 O 301                 | Bearing, Stabilizer Bar<br>ø45x46     | 6733260781<br>6733260381 | <b>TM37640</b>  |
|  |                                       |                          |  |
| 674 LK/LN2<br>675 LK/LN2<br>676 LK/LN2<br>677 LK/LN2<br>679 LK/LN2 | Bearing, Stabilizer Bar<br>ø44,5x59,5 | 6753260681               | <b>TM37641</b>  |
|  |                                       |                          |  |
| 675 LK/LN2<br>676 LK/LN2<br>677 LK/LN2                             | Bearing, Stabilizer Bar<br>ø50x59     | 6753260781               | <b>TM37642</b>  |
|  |                                       |                          |  |
| 674 LK/LN2<br>675 LK/LN2<br>676 LK/LN2<br>677 LK/LN2               | Bearing, Stabilizer Bar<br>ø40x56     | 6753260481<br>6753260181 | <b>TM37643</b>  |
|  |                                       |                          |  |



| TM No.  | Replaces Ref. No:                      | Description                           | Model / Details  |
|---|--|---------------------------------------|--|
| <b>TM28207</b><br>   | 6753261281<br>6753261081               | Bearing, Stabilizer Bar<br>ø47x55,5   | 675 LK/LN2<br>676 LK/LN2<br>677 LK/LN2<br>678 LK/LN2   |
| <b>TM37644</b><br>   | 6753232185                             | Bearing, Stabilizer Bar<br>ø38,5x56   | 675 LK/LN2<br>676 LK/LN2<br>678 LK/LN2   |
| <b>TM37645</b><br>   | 6753231285                             | Bearing, Stabilizer Bar<br>ø35x59,5   | 675 LK/LN2<br>676 LK/LN2<br>677 LK/LN2<br>678 LK/LN2<br>679 LK/LN2                                       |
| <b>TM28227</b><br> | 6753231885                             | Bearing, Stabilizer Bar<br>ø35x59     | 674 LK/LN2<br>675 LK/LN2<br>676 LK/LN2<br>677 LK/LN2<br>679 LK/LN2                                       |
| <b>TM37646</b><br> | 6743260081                             | Bearing, Stabilizer Bar<br>ø41,5x59,5 | 74 LK/LN2<br>676 LK/LN2  |
| <b>TM37647</b><br> | 6673260181                             | Bearing, Stabilizer Bar<br>ø46x80     | 398 LO 814<br>667 T2/LN1<br>668 T2/LN1<br>688 1114<br>688 LO 812<br>688 LO 812 814 /42,5<br>688 LO 813 D |
| <b>TM28172</b><br> | 0003262681<br>0003263081<br>0003263281 | Bearing, Stabilizer Bar<br>ø48x56,5   | 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3   |



| Model / Details   | Description                           | Replaces Ref. No:                                    | TM No.         |
|---|---------------------------------------|--|----------------|
| 690 SPRINTER<br>904 SPRINTER<br>909 SPRINTER  | Bearing, Stabilizer Bar<br>ø33x46x50  | 9043261081   | <b>TM28274</b> |
| 904 SPRINTER<br>906 SPRINTER  | Bearing, Stabilizer Bar<br>ø30x46x50  | 9043260981   | <b>TM37648</b> |
| 690 SPRINTER<br>904 SPRINTER<br>906 SPRINTER  | Bearing, Stabilizer Bar<br>ø27x46x50  | 9043260881   | <b>TM28276</b> |
| 375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>375 ATEGO 2<br>970 ATEGO 2<br>972 ATEGO 2 | Bearing, Stabilizer Bar<br>ø33,5x47,5 | 9703231585<br>9583200144<br>9793200444<br>9743230085 | <b>TM28196</b> |
| -   | Bearing, Stabilizer Bar<br>ø42x59,5   | 6753231585   | <b>TM37649</b> |
| -   | Bearing, Stabilizer Bar<br>ø62x60     | 6763260581   | <b>TM37650</b> |
| 970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>958 ATEGO 2<br>970 ATEGO 2<br>972 ATEGO 2 | Bearing, Stabilizer Bar<br>ø37,5x56   | 9743230285   | <b>TM28243</b> |



| TM No.  | Replaces Ref. No:        | Description                           | Model / Details   |
|---|--------------------------|---------------------------------------|---|
| <b>TM28201</b><br>   | 9743230385               | Bearing, Stabilizer Bar<br>ø42x55,5   | 970 ATEGO<br>972 ATEGO<br>976 ATEGO<br>970 ATEGO 2<br>972 ATEGO 2<br>974 ATEGO 2<br>976 ATEGO 2 |
| <b>TM37651</b><br>   | 6733230585               | Bearing, Stabilizer Bar<br>ø35x60     | -   |
| <b>TM37652</b><br>  | 6733230685               | Bearing, Stabilizer Bar<br>ø35x60     | 674 LK/LN2<br>676 LK/LN2  |
| <b>TM28262</b><br> | 6753231985               | Bearing, Stabilizer Bar<br>ø37,5x59,5 | 675 LK/LN2<br>676 LK/LN2<br>678 LK/LN2  |
| <b>TM37653</b><br> | 6753231385               | Bearing, Stabilizer Bar<br>ø41,5x59,5 | 677 LK/LN2  |
| <b>TM37654</b><br> | 6753231685               | Bearing, Stabilizer Bar<br>ø43x56     | 676 LK/LN2<br>677 LK/LN2<br>678 LK/LN2  |
| <b>TM37655</b><br> | 6753260581<br>6753260281 | Bearing, Stabilizer Bar<br>ø47x56     | 675 LK/LN2  |





| Model / Details   | Description                            | Replaces Ref. No:        | TM No.         |
|---|--|--------------------------|----------------|
| 674 LK/LN2<br>675 LK/LN2<br>676 LK/LN2<br>678 LK/LN2                                    | Bearing, Stabilizer Bar<br>ø35x56      | 6753231785               | <b>TM37656</b> |
| 675 LK/LN2<br>676 LK/LN2<br>677 LK/LN2<br>679 LK/LN2                                    | Bearing, Stabilizer Bar<br>ø56x60      | 6763260481<br>6763260281 | <b>TM37657</b> |
| 674 LK/LN2<br>675 LK/LN2<br>676 LK/LN2<br>677 LK/LN2<br>678 LK/LN2<br>679 LK/LN2        | Bearing, Stabilizer Bar<br>ø41x56      | 6753260981               | <b>TM37658</b> |
| 676 LK/LN2<br>677 LK/LN2  | Bearing, Stabilizer Bar<br>ø45,5x56    | 6743280381               | <b>TM37659</b> |
| 675 LK/LN2<br>676 LK/LN2<br>677 LK/LN2  | Bearing, Stabilizer Bar<br>ø34,5x57x60 | 6753230785               | <b>TM37660</b> |
| 398 LO 814<br>688 1114<br>688 912<br>688 913<br>688 914<br>688 L 913 D<br>688 LO 712/37 | Bearing, Stabilizer Bar<br>ø36x50      | 6673230685               | <b>TM28246</b> |
| 675 LK/LN2<br>676 LK/LN2<br>677 LK/LN2  | Bearing, Stabilizer Bar<br>ø35x59,5    | 6753231485               | <b>TM37661</b> |





| TM No.  | Replaces Ref. No:        | Description                           | Model / Details  |
|---|--------------------------|---------------------------------------|--|
| <b>TM28171</b><br>   | 0003264481<br>0003264781 | Bearing, Stabilizer Bar<br>ø57,5x56   | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 |
| <b>TM28244</b><br>   | 0003250685               | Bearing, Stabilizer Bar<br>ø52x56     | 950 ACTROS<br>952 ACTROS<br>954 ACTROS<br>950 AXOR 2<br>952 AXOR 2   |
| <b>TM28175</b><br>   | 0003236285<br>0003237185 | Bearing, Stabilizer Bar<br>ø28,5x55,5 | 950 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>934 ACTROS 2/3<br>374 AXOR 2<br>950 AXOR 2                   |
| <b>TM37662</b><br> | 6743280281<br>6743280081 | Bearing, Stabilizer Bar<br>ø44x56     | 675 LK/LN2<br>676 LK/LN2<br>677 LK/LN2   |
| <b>TM27690</b><br> | 9743270281               | Bearing, Stabilizer Bar<br>ø65xø93x67 | 934 ACTROS 2/3<br>970 ATEGO<br>970 ATEGO 2<br>967 ATEGO 3<br>384 OF SERIES<br>368 OH SERIES                |
| <b>TM27818</b><br> | 9703231785               | Bearing, Stabilizer Bar<br>ø38x47,5   | 375 ATEGO<br>970 ATEGO<br>975 ATEGO<br>375 ATEGO 2<br>958 ATEGO 2<br>970 ATEGO 2<br>974 ATEGO 2            |
| <b>TM28202</b><br> | 9703231285               | Bearing, Stabilizer Bar<br>ø25x47,5   | 972 ATEGO<br>970 ATEGO 2<br>972 ATEGO 2<br>976 ATEGO 2<br>967 ATEGO 3                                      |





| Model / Details  | Description                             | Replaces Ref. No:                      | TM No.         |
|--|---|--|----------------|
| 651 MK<br>652 MK<br>653 MK<br>654 MK<br>655 SK   | Bearing, Stabilizer Bar<br>ø69xø110xø65 | 6523260481                             | <b>TM37663</b> |
| 950 ACTROS<br>952 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>934 ACTROS 2/3<br>963 ACTROS MP4 | Bearing, Stabilizer Bar<br>ø82x110x66,5 | 9413260050                             | <b>TM28182</b> |
| 638 VITO<br>638 V-CLASS  | Bearing, Stabilizer Bar<br>ø13,5x35x46  | 6383260281                             | <b>TM37664</b> |
| 639 VIANO<br>638 VITO<br>638 V-CLASS   | Bearing, Stabilizer Bar<br>ø24x35x46    | 6383230285                             | <b>TM37665</b> |
| 650 MK<br>651 MK<br>652 MK<br>653 MK<br>654 MK   | Bearing, Stabilizer Bar<br>ø35x56,5     | 0003235885<br>0003235585<br>0003235385 | <b>TM28174</b> |
| 675 LK/LN2<br>676 LK/LN2<br>677 LK/LN2<br>679 LK/LN2   | Bearing, Stabilizer Bar<br>ø43x64       | 6753232385                             | <b>TM37666</b> |
| 905 SPRINTER<br>667 VARIO<br>668 VARIO<br>670 VARIO  | Bearing, Stabilizer Bar<br>ø41x60       | 6673261381                             | <b>TM28339</b> |





| TM No.  | Replaces Ref. No:        | Description                             | Model / Details   |
|---|--------------------------|---|---|
| <b>TM37667</b><br>   | 6673261481               | Bearing, Stabilizer Bar<br>ø46x60       | 667 VARIO<br>668 VARIO<br>670 VARIO   |
| <b>TM37668</b><br>   | 6673261081<br>6703260181 | Bearing, Stabilizer Bar<br>ø46x60       | 667 VARIO<br>668 VARIO<br>670 VARIO   |
| <b>TM28190</b><br>   | 0003265081<br>0003265681 | Bearing, Stabilizer Bar<br>ø47,5x56     | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3    |
| <b>TM28181</b><br> | 9413230150               | Bearing, Stabilizer Bar<br>ø70xø98x67   | 950 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>934 ACTROS 2/3<br>963 ACTROS MP4<br>964 ACTROS MP4<br>964 AROCS |
| <b>TM28230</b><br> | 0003265181               | Bearing, Stabilizer Bar<br>ø53x56       | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3    |
| <b>TM28204</b><br> | 9703231485               | Bearing, Stabilizer Bar<br>ø28xø53x47,5 | 979 ACCELO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>970 ATEGO 2<br>972 ATEGO 2<br>975 ATEGO 2                |
| <b>TM28203</b><br> | 9703232085               | Bearing, Stabilizer Bar<br>ø37xø62x55   | 970 ATEGO<br>970 ATEGO 2<br>967 ATEGO 3   |



| Model / Details  | Description                         | Replaces Ref. No:        | TM No.  |
|--|-------------------------------------|--------------------------|---|
| 900 SPRINTER<br>906 SPRINTER   | Bearing, Stabilizer Bar<br>ø32x25   | 9063260481               | <b>TM37669</b><br>   |
| 906 SPRINTER   | Bearing, Stabilizer Bar<br>ø23x35   | 9063231685               | <b>TM28241</b><br>   |
| 900 SPRINTER<br>906 SPRINTER   | Bearing, Stabilizer Bar<br>ø16x35   | 9063260781<br>9063260381 | <b>TM28242</b><br>  |
| 906 SPRINTER   | Bearing, Stabilizer Bar<br>ø20x35   | 9063231485<br>9063233585 | <b>TM28272</b><br> |
| 906 SPRINTER   | Bearing, Stabilizer Bar<br>ø20x35   | 9063260881<br>9063260281 | <b>TM28287</b><br> |
| 667 VARIO<br>668 VARIO<br>670 VARIO  | Bearing, Stabilizer Bar<br>ø50,5x60 | 6673261581               | <b>TM37670</b><br> |
| 964 AROCS<br>972 ATEGO<br>970 ATEGO 2<br>972 ATEGO 2<br>976 ATEGO 2<br>967 ATEGO 3 | Bearing, Stabilizer Bar<br>ø34x55   | 9743230185               | <b>TM28349</b><br> |



| TM No.  | Replaces Ref. No:        | Description                            | Model / Details  |
|---|--------------------------|--|--|
| <b>TM37671</b><br>   | 6393230285               | Bearing, Stabilizer Bar<br>ø23x46/35   | 375 ACTROS<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>375 ATEGO 2<br>958 ATEGO 2 |
| <b>TM28284</b><br>   | 9013260181               | Bearing, Stabilizer Bar<br>ø26,5x38,5  | 901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER   |
| <b>TM37672</b><br>  | 6393261081<br>6393260781 | Bearing, Stabilizer Bar<br>ø18x39/25   | 639 VIANO  |
| <b>TM37673</b><br> | 9063233685<br>9063233785 | Bearing, Stabilizer Bar<br>ø20x50,5    | 900 SPRINTER<br>906 SPRINTER   |
| <b>TM37674</b><br> | 6673260981               | Bearing, Stabilizer Bar<br>ø41x60      | 667 VARIO<br>668 VARIO<br>670 VARIO  |
| <b>TM37675</b><br> | 6703260281               | Bearing, Stabilizer Bar<br>ø50x60      | 667 VARIO<br>668 VARIO<br>670 VARIO  |
| <b>TM37676</b><br> | 9603260081               | Bearing, Stabilizer Bar<br>ø70xø110x65 | 963 ACTROS MP4   |





| Model / Details  | Description                                     | Replaces Ref. No:        | TM No.  |
|--|---|--------------------------|---|
| BM MODEL<br>963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS<br>405 UNIMOG                   | Bearing, Stabilizer Bar<br>ø55x101x66           | 4053230085               | <b>TM37677</b><br>   |
| 963 ACTROS MP4   | Bearing, Stabilizer Bar<br>ø35x62x55,5          | 9603231185               | <b>TM28312</b><br>   |
| 396 OH SERIES  | Half Bearing, Stabilizer Bar<br>ø54xø93,5x70/80 | 3963230050               | <b>TM27572</b><br>   |
| 356 O 404<br>613 TOURISMO  | Half Bearing, Stabilizer Bar<br>ø38xø66x60      | 3563260081               | <b>TM28231</b><br> |
| 384 LA 1418<br>384 LAK 1418<br>384 LK 1214<br>384 LK 1215<br>384 LK 1218<br>384 LK 1414<br>384 LK 1418 | Half Bearing, Stabilizer Bar<br>ø50xø82x80      | 3013260081               | <b>TM37678</b><br> |
| 634 O 500<br>634 TOURO<br>628 CITARO<br>628 CONECTO<br>633 INTEGRO<br>633 INTOURO<br>632 TOURISMO      | Bearing, Stabilizer Bar<br>ø46xø76x70           | 6283220050               | <b>TM28265</b><br> |
| 906 SPRINTER   | Bearing, Stabilizer Bar<br>ø22,5x52x48x57       | 9063260981<br>9063262381 | <b>TM28300</b><br> |












| TM No.  | Replaces Ref. No:                      | Description                               | Model / Details  |
|---|--|---|--|
| <b>TM37679</b><br>   | 6393231985<br>6393230585<br>6393231285 | Bearing, Stabilizer Bar<br>ø23x55x35x52,5 | 639 VIANO  |
| <b>TM28306</b><br>   | 9603232085<br>9603233285               | Bearing, Stabilizer Bar<br>ø34xø62x56     | 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS |
| <b>TM28311</b><br>   | 9603232585<br>9603233385               | Bearing, Stabilizer Bar<br>ø42xø73x56     | 964 AROCS  |
| <b>TM37680</b><br> | 9063262681                             | Bearing, Stabilizer Bar<br>ø33x69x71      | 900 SPRINTER<br>906 SPRINTER                               |
| <b>TM37681</b><br> | 9063262281                             | Bearing, Stabilizer Bar<br>ø18x52x57      | 906 SPRINTER   |
| <b>TM37682</b><br> | 9063262181                             | Bearing, Stabilizer Bar<br>ø11x52x55      | 900 SPRINTER<br>906 SPRINTER                               |
| <b>TM37683</b><br> | 4473260481                             | Bearing, Stabilizer Bar<br>ø12x45x50      | 447 VITO - 447 V CLASS -<br>448 VITO - 448<br>V CLASS      |







| Model / Details   | Description                                  | Replaces Ref. No:                      | TM No.  |
|---|--|--|---|
| 906 SPRINTER  | Bearing, Stabilizer Bar<br>ø30x70x68         | 9063262581                             | <b>TM28275</b>  |
|   |  |  |    |
| 382 OH SERIES<br>382 O 500<br>382 O 500 M / 1725<br>382 O 500 M / 1725 / 1726<br>382 O 500 M / 1728<br>382 O 500 R / 1830 / 30<br>382 O 500 U / 1725 / 59 | Half Bearing, Stabilizer Bar<br>ø45,5xø78x80 | 6343260081                             | <b>TM37684</b>  |
|   |  |  |    |
| 930 ACTROS 2/3<br>934 ACTROS 2/3<br>632 TRAVEGO<br>634 MULTEGO  | Bolt, Stabilizer Bar<br>M18x1,5/35           | 00000005561<br>910105018020            | <b>TM37685</b>  |
|   |  |  |   |
| 380 NG<br>381 NG<br>383 NG<br>385 NG<br>387 NG<br>389 NG<br>391 NG  | Bearing, Stabilizer Bar<br>ø20xø35x12/16     | 0009817231<br>0009817331<br>0009810931 | <b>TM37686</b>  |
|   |  |  |  |
| 380 NG<br>381 NG<br>383 NG<br>385 NG<br>615 NG<br>616 NG<br>617 NG  | Bearing, Stabilizer Bar<br>ø35xø55x20/25     | 0009810831<br>0009811231               | <b>TM37687</b>  |
|   |  |  |  |
| 380 NG<br>381 NG<br>383 NG<br>385 NG<br>387 NG<br>389 NG<br>393 NG  | Bearing, Stabilizer Bar<br>ø30xø55x20/32     | 0009817431<br>0009816131               | <b>TM27700</b>  |
|   |  |  |  |
| 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3  | Bearing, Stabilizer Bar<br>ø27x62x47         | 9703231385                             | <b>TM37688</b>  |
|   |  |  |  |










| TM No.  | Replaces Ref. No:        | Description                | Model / Details  |
|---|--------------------------|----------------------------|--|
| <b>TM28414</b><br>   | 6203200028               | Repair Kit, Stabilizer Bar | 696 L 2638<br>650 MK<br>620 NG<br>621 NG<br>645 NG<br>646 NG<br>647 NG   |
| <b>TM28404</b><br>   | 6203200628<br>6193200128 | Repair Kit, Stabilizer Bar | 388 L 1929<br>388 L 1935<br>388 L 1938<br>388 L 1945<br>388 L 2635/6X4/54<br>388 LK 2635/6X4/40<br>388 LS 1929 |
| <b>TM28424</b><br>   | 6213200228               | Repair Kit, Stabilizer Bar | 621 NG<br>624 NG<br>646 NG<br>649 NG<br>625 SK<br>655 SK<br>659 SK   |
| <b>TM28402</b><br> | 6213200428               | Repair Kit, Stabilizer Bar | 620 NG<br>621 NG<br>622 NG<br>623 NG<br>645 NG<br>646 NG<br>647 NG   |
| <b>TM27694</b><br> | 6243200028<br>6253200028 | Repair Kit, Stabilizer Bar | 621 NG<br>624 NG<br>625 NG   |
| <b>TM28431</b><br> | 6253200611               | Repair Kit, Stabilizer Bar | 650 MK<br>651 MK<br>652 MK<br>653 MK<br>654 MK<br>625 SK   |
| <b>TM37689</b><br> | 6473200028               | Repair Kit, Stabilizer Bar | 625 NG<br>647 NG<br>625 SK<br>657 SK   |










| Model / Details  | Description                | Replaces Ref. No:                       | TM No.  |
|--|----------------------------|---|---|
| 620 NG<br>621 NG<br>623 NG<br>624 NG<br>625 NG<br>625 SK<br>397 1924 K MBSA-RSA          | Repair Kit, Stabilizer Bar | 6203200428<br>6203200232<br>6205860232  | <b>TM28403</b><br>   |
| 346 LS 1924<br>346 LS 1928<br>387 NG<br>389 NG<br>391 NG<br>393 NG<br>395 NG             | Repair Kit, Stabilizer Bar | 6203200228<br>6205860032                | <b>TM28397</b><br>   |
| 620 NG<br>621 NG<br>622 NG<br>623 NG<br>625 NG<br>625 SK                                 | Repair Kit, Stabilizer Bar | 6203200128                              | <b>TM28401</b><br>  |
| 385 NG<br>615 NG<br>616 NG<br>617 NG<br>619 NG<br>625 NG<br>352 OF SERIES                | Repair Kit, Stabilizer Bar | 6173200128                              | <b>TM28416</b><br> |
| 387 NG<br>389 NG<br>393 NG<br>395 NG<br>623 NG<br>648 NG<br>658 SK                       | Repair Kit, Stabilizer Bar | 3933200328<br>3935860432                | <b>TM37690</b><br> |
| 387 NG<br>389 NG<br>393 NG   | Repair Kit, Stabilizer Bar | 3873200428<br>3875860432                | <b>TM37691</b><br> |
| BM MODEL<br>346 LS 1924<br>346 LS 1928<br>387 NG<br>389 NG<br>391 NG<br>393 NG<br>395 NG | Repair Kit, Stabilizer Bar | 3873200028<br>3875860032<br>0003233785S | <b>TM28396</b><br> |



| TM No.  | Replaces Ref. No:  | Description                                | Model / Details   |   |
|---|--|--|---|---|
| <b>TM28417</b><br>   | 3603200341   | RepairKit, Stabilizer Bar<br>ø35xø55x20/25 | 344 LAS 1113  |   |
|   | 3605860332   |  | 344 LP 1113<br>344 LPO 1113<br>344 LPO/OF 1113/1114<br>344 LS 1113<br>345 LAK 1313,1314,1317<br>345 LK 1313 |   |
| <b>TM28398</b><br>   | 3873200128   | Repair Kit, Stabilizer Bar                 | 336 LPS 1924  |   |
|   | 3875860132   |  | 346 LS 1924   |   |
| 0003261681S   | 363 LP 2226/6X4<br>363 LP 2232/6X4<br>363 LPB 2226/6X4<br>363 LPK 2226/6X4<br>363 LPK 2232/6X4 |  |   |   |
| <b>TM28399</b><br>  | 3873200528   | Repair Kit, Stabilizer Bar                 | BM MODEL  |   |
|   | 3875860532   |  | 346 LS 1924<br>387 NG<br>389 NG<br>391 NG   |   |
| <b>TM37692</b><br> | 3143260481S  |  | Repair Kit, Stabilizer Bar<br>ø18xø26,5x14,5  | 308 L 608 E,L 708 E<br>308 L/LO 608 D<br>308 LO 608 D,LO 708 D/E<br>309 T2/L<br>309 TL2/L<br>310 T2/L<br>314 LP |
|   |  |  |   | <b>TM28436</b><br>           |
| <b>TM37695</b><br> | 3933200228   |  | Repair Kit, Stabilizer Bar  | 393 NG  |
|   | 3935860332   |  |   |   |
| <b>TM37696</b><br> | 6173200028   | Repair Kit, Stabilizer Bar                 | 615 LK/LN2<br>615 NG<br>616 NG<br>617 NG<br>619 NG<br>397 1419 S MBSA-RSA                                   |   |












| Model / Details  | Description                | Replaces Ref. No:        | TM No.  |
|--|----------------------------|--------------------------|---|
| 615 LK/LN2<br>650 MK<br>651 MK<br>652 MK<br>615 NG<br>616 NG<br>617 NG | Repair Kit, Stabilizer Bar | 6173200228               | <b>TM37697</b><br>   |
| 653 MK<br>385 NG<br>619 NG   | Repair Kit, Stabilizer Bar | 6203200328<br>6205860132 | <b>TM28415</b><br>   |
| 623 NG<br>648 NG<br>396 OH SERIES<br>625 SK<br>658 SK                  | Repair Kit, Stabilizer Bar | 6233200041<br>6235860032 | <b>TM37698</b><br>  |
| 625 NG<br>625 SK   | Repair Kit, Stabilizer Bar | 6253200111               | <b>TM28434</b><br> |
| BM MODEL<br>651 MK<br>652 MK<br>653 MK<br>654 MK                       | Repair Kit, Stabilizer Bar | 6523200511               | <b>TM28433</b><br> |
| 621 NG<br>646 NG<br>656 SK<br>657 SK<br>658 SK                         | Repair Kit, Stabilizer Bar | 6213200011               | <b>TM28407</b><br> |
| 620 NG<br>622 NG<br>623 NG<br>645 NG<br>647 NG<br>648 NG<br>655 SK     | Repair Kit, Stabilizer Bar | 6203200111               | <b>TM27019</b><br> |












| TM No.  | Replaces Ref. No: | Description                                 | Model / Details          |
|---|-------------------|---|--------------------------|
| <b>TM28405</b><br>   | 3873200328        | Repair Kit, Stabilizer Bar                  | 387 NG                   |
|   | 3875860332        |   | 393 NG                   |
|   |                   |   | 620 NG                   |
|   |                   |   | 622 NG                   |
|   |                   |   | 623 NG                   |
|   |                   |   | 645 NG                   |
|   |                   |   | 647 NG                   |
| <b>TM27500</b><br>   | 3803200028        | Repair Kit, Stabilizer Bar                  | 380 NG                   |
|   | 3805860032        |   | 381 NG                   |
|   | 3933260281S       |   | 383 NG                   |
|   |                   |   | 385 NG                   |
|   |                   |   | 616 NG                   |
|   |                   |   | 617 NG                   |
|   |                   |   | 619 NG                   |
| <b>TM28406</b><br>   | 6213200128        | Repair Kit, Stabilizer Bar                  | 389 NG                   |
|   | 3893260081S       |   | 621 NG                   |
|   |                   |   | 646 NG                   |
|   |                   |   | 656 SK                   |
| <b>TM37699</b><br> | 6253200711        | Repair Kit, Stabilizer Bar                  | 625 NG                   |
|   |                   |   | 625 SK                   |
| <b>TM28435</b><br> | 6553200111        | Repair Kit, Stabilizer Bar                  | 652 MK                   |
|   |                   |   | 653 MK                   |
|   |                   |   | 654 MK                   |
| <b>TM28413</b><br> | 3603200041        | Repair Kit, Stabilizer Bar<br>ø20xø35x12/16 | 345 L 1313               |
|   | 3605860032        |   | 345 L 1313,1314          |
|   |                   |   | 345 L 1313,1314,1316     |
|   |                   |   | 345 L 1313,1316          |
|   |                   |   | 345 L 1316,L 1317,L 1318 |
|   |                   |   | 345 L 1418 MBTC-USA      |
|   |                   |   | 345 L 1513,1514,1516     |
| <b>TM37700</b><br> | 6013200711        | Repair Kit, Stabilizer Bar                  | 601 207 D/208 D          |
|   | 6013200083        |   | 601 208/210              |
|   | 6015860032        |   | 601 209 D/210 D          |
|   |                   |   | 602 307 D/308 D          |
|   |                   |   | 602 307 D/308D           |
|   |                   |   | 602 308 D                |
|   |                   |   | 602 308/310              |



| Model / Details  | Description                                | Replaces Ref. No:        | TM No.  |
|--|--|--------------------------|---|
| 601 207 D/208 D<br>601 208/210<br>601 209 D/210 D  | Repair Kit, Stabilizer Bar                 | 6013200183<br>6015860132 | <b>TM37701</b><br>   |
| 611 T1/TN<br>601 207 D/208 D<br>601 208/210<br>601 209 D/210 D   | Repair Kit, Stabilizer Bar                 | 6013200411               | <b>TM28438</b><br>   |
| -  | Repair Kit, Stabilizer Bar                 | 6013200328               | <b>TM37702</b><br>  |
| 611 T1/TN  | Repair Kit, Stabilizer Bar                 | 6113200311               | <b>TM37703</b><br> |
| 387 NG<br>389 NG<br>393 NG   | Repair Kit, Stabilizer Bar                 | 3873200228<br>3875860232 | <b>TM37704</b><br> |
| BM MODEL<br>375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 | Repair Kit, Stabilizer Bar<br>ø40xø70x46,5 | 0003237985S              | <b>TM37705</b><br> |
| 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3             | Repair Kit, Stabilizer Bar<br>40xø70x46,5  | 0003237985S1             | <b>TM28440</b><br> |



| TM No.  | Replaces Ref. No:          | Description                                | Model / Details  |
|---|----------------------------|--|--|
| <b>TM28427</b><br>   | 0003237985S3               | Repair Kit, Stabilizer Bar<br>ø40xø70x46,5 | 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3     |
| <b>TM37707</b><br>   | 0003237985S4               | Repair Kit, Stabilizer Bar<br>ø40xø70x46,5 | -  |
| <b>TM37708</b><br>   | 0003237985S5               | Repair Kit, Stabilizer Bar<br>ø40xø70x46,5 | 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3     |
| <b>TM37709</b><br> | 0003238185S1               | Repair Kit, Stabilizer Bar<br>40xø80x46    | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3 |
| <b>TM37710</b><br> | 0003238185S2               | Repair Kit, Stabilizer Bar<br>ø40xø80x46   | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3 |
| <b>TM37711</b><br> | 4473260481S<br>4473260240S | Repair Kit, Stabilizer Bar<br>ø12x45x50    | 447 VITO - 447 V CLASS -<br>448 VITO - 448<br>V CLASS  |
| <b>TM37714</b><br> | 6023260140                 | Bearing Cap, Stabilizer Bar<br>58x62,5x31  | BM MODEL<br>611 T1/TN<br>601 207 D/208 D<br>601 208/210<br>601 209 D/210 D<br>602 307 D/308 D<br>602 307 D/308D<br>602 308 D |



| Model / Details  | Description                                     | Replaces Ref. No: | TM No.         |
|--|---|-------------------|----------------|
| 904 SPRINTER<br>909 SPRINTER   | Bearing Cap, Stabilizer Bar<br>42x60xø11/80     | 9043261340        | <b>TM37715</b> |
|  |   |                   |                |
| 690 SPRINTER<br>904 SPRINTER   | Bearing Cap, Stabilizer Bar<br>42x60xø11/80     | 9043260840        | <b>TM37716</b> |
|  |   |                   |                |
| 690 SPRINTER<br>901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER<br>909 SPRINTER               | Bearing Cap, Stabilizer Bar<br>35x65x44         | 9013230288        | <b>TM37717</b> |
|  |   |                   |                |
| 690 SPRINTER<br>901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER   | Bearing Cap, Stabilizer Bar<br>40x63x58         | 9019950110        | <b>TM37718</b> |
|  |   |                   |                |
| 667 T2/LN1<br>668 T2/LN1<br>669 T2/LN1<br>670 T2/LN1<br>688 1114<br>688 LO 712/37<br>688 LO 809            | -Bearing Cap, Stabilizer<br>Bar<br>94x115x72    | 6673261440        | <b>TM37719</b> |
|  |   |                   |                |
| 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3     | Bearing Cap, Stabilizer Bar<br>ø13/96x57/132x48 | 9413230521        | <b>TM27951</b> |
|  |   |                   |                |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 | Bearing Cap, Stabilizer Bar<br>ø15/96x58/131x51 | 9433260164        | <b>TM27952</b> |
|  |   |                   |                |





| TM No.  | Replaces Ref. No:        | Description                                  | Model / Details  |
|---|--------------------------|--|--|
| <b>TM28002</b><br>   | 9063230040               | Bearing Cap, Stabilizer Bar<br>47x60/ø11x184 | 950 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3   |
| <b>TM28036</b><br>   | 9413230421               | Bearing Cap, Stabilizer Bar                  | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 |
| <b>TM37720</b><br>  | 9063261940<br>0009953402 | Bearing Cap, Stabilizer Bar<br>ø11x75,5      | 906 SPRINTER   |
| <b>TM27991</b><br> | 9433260064               | Bearing Cap, Stabilizer Bar<br>ø77           | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>944 AXOR 2<br>950 AXOR 2<br>952 AXOR 2             |
| <b>TM37721</b><br> | 9413250035               | Bearing Cap, Stabilizer Bar<br>ø107          | 950 ACTROS<br>952 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>934 ACTROS 2/3<br>970 ATEGO  |
| <b>TM37722</b><br> | 9493230021               | Bearing Cap, Stabilizer Bar                  | 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>934 ACTROS 2/3 |
| <b>TM37723</b><br> | 9603250435               | Bearing Cap, Stabilizer Bar<br>ø21/45x152    | 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS   |






| Model / Details  | Description  | Replaces Ref. No:          | TM No.         |
|--|--|----------------------------|----------------|
| 447 VITO - 447 V CLASS -<br>448 VITO - 448<br>V CLASS  | Bearing Cap, Stabilizer Bar<br>ø43                         | 4473260240                 | <b>TM37712</b> |
| 374 AXOR 2<br>375 AXOR 2<br>940 AXOR 2<br>942 AXOR 2<br>943 AXOR 2<br>950 AXOR 2<br>952 AXOR 2             | Link, Stabilizer Bar<br>ø75/340x105/445x35                 | 9483260447                 | <b>TM27896</b> |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 | Link, Stabilizer Bar<br>With Bushing<br>ø40/340x105/445x35 | 9483260447S                | <b>TM37724</b> |
| 374 AXOR 2<br>375 AXOR 2<br>940 AXOR 2<br>942 AXOR 2<br>943 AXOR 2<br>944 AXOR 2<br>950 AXOR 2             | Link, Stabilizer Bar<br>ø40/ø85x534x38/82                  | 9433230211<br>9433230616   | <b>TM27894</b> |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 | Link, Stabilizer Bar<br>With Bushing<br>ø40x460x81,5       | 9433230211S<br>9433230616S | <b>TM37725</b> |
| 375 AXOR 2<br>952 AXOR 2<br>933 ACTROS 2/3<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS         | Link, Stabilizer Bar<br>ø75/280x100/380x35                 | 9483260347                 | <b>TM37726</b> |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>933 ACTROS 2/3<br>375 AXOR 2<br>952 AXOR 2         | Link, Stabilizer Bar<br>With Bushing<br>ø40/280x100/380x35 | 9483260347S                | <b>TM37727</b> |





| TM No.  | Replaces Ref. No: | Description  | Model / Details |
|---|-------------------|--|-----------------|
| <b>TM27930</b><br>   | 9493230011        | Link, Stabilizer Bar<br>ø40/ø65x37/380                   | 950 ACTROS      |
|   | 9493230116        |  | 952 ACTROS      |
|   |                   |  | 953 ACTROS      |
|   |                   |  | 954 ACTROS      |
|   |                   |  | 930 ACTROS 2/3  |
|   |                   |  | 932 ACTROS 2/3  |
|   |                   |  | 933 ACTROS 2/3  |
| <b>TM37728</b><br>   | 9493230011S       | Link, Stabilizer Bar<br>With Bushing<br>ø40/ø40x46,5/380 | 950 ACTROS      |
|   | 9493230116S       |  | 952 ACTROS      |
|   |                   |  | 953 ACTROS      |
|   |                   |  | 954 ACTROS      |
|   |                   |  | 930 ACTROS 2/3  |
|   |                   |  | 932 ACTROS 2/3  |
|   |                   |  | 933 ACTROS 2/3  |
| <b>TM27895</b><br>   | 9433230111        | Link, Stabilizer Bar<br>ø40/ø65x494x38/82                | 374 AXOR 2      |
|   | 9433230516        |  | 375 AXOR        |
|   |                   |  | 375 AXOR 2      |
|   |                   |  | 940 AXOR 2      |
|   |                   |  | 942 AXOR 2      |
|   |                   |  | 943 AXOR 2      |
|   |                   |  | 944 AXOR 2      |
| <b>TM37729</b><br> | 9433230111S       | Link, Stabilizer Bar<br>With Bushing<br>ø40x46,5/494     | BM MODEL        |
|   | 9433230516S       |  | 375 ACTROS      |
|   |                   |  | 950 ACTROS      |
|   |                   |  | 952 ACTROS      |
|   |                   |  | 953 ACTROS      |
|   |                   |  | 954 ACTROS      |
|   |                   |  | 930 ACTROS 2/3  |
|   |                   |  | 932 ACTROS 2/3  |
| <b>TM27931</b><br> | 9433260447        | Link, Stabilizer Bar<br>ø65x365                          | 375 AXOR        |
|   |                   |  | 375 AXOR 2      |
|   |                   |  | 940 AXOR 2      |
|   |                   |  | 950 AXOR 2      |
|   |                   |  | 952 AXOR 2      |
|   |                   |  | 953 AXOR 2      |
|   |                   |  | 375 ACTROS      |
| <b>TM37730</b><br> | 9433260447S       | Link, Stabilizer Bar<br>With Bushing<br>ø40x365          | 375 ACTROS      |
|   |                   |  | 950 ACTROS      |
|   |                   |  | 952 ACTROS      |
|   |                   |  | 953 ACTROS      |
|   |                   |  | 954 ACTROS      |
|   |                   |  | 375 AXOR        |
|   |                   |  | 375 AXOR 2      |
| <b>TM28004</b><br> | 9483260547        | Link, Stabilizer Bar<br>ø75x365                          | 374 AXOR 2      |
|   |                   |  | 375 AXOR        |
|   |                   |  | 940 AXOR 2      |
|   |                   |  | 942 AXOR 2      |
|   |                   |  | 943 AXOR 2      |
|   |                   |  | 944 AXOR 2      |
|   |                   |  | 950 AXOR 2      |



| Model / Details  | Description  | Replaces Ref. No: | TM No.             |
|--|--|-------------------|--------------------|
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 | Link, Stabilizer Bar<br>With Bushing<br>ø40x365    | 9483260547S       | <b>TM37731</b><br> |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 | Link, Stabilizer Bar<br>ø75x420x34                 | 9483260647        | <b>TM27899</b><br> |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 | Link, Stabilizer Bar<br>With Bushing<br>ø40x420x34 | 9483260647S       | <b>TM37732</b><br> |
| 964 AROCS  | Link, Stabilizer Bar<br>ø20,6xø75x55,5/380         | 9603200937        | <b>TM28358</b><br> |
| 375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>375 ATEGO 2<br>958 ATEGO 2<br>970 ATEGO 2              | Link, Stabilizer Bar<br>ø22x40x430                 | 9743201937        | <b>TM37733</b><br> |
| 975 ATEGO<br>970 ATEGO 2<br>976 ATEGO 2  | Link, Stabilizer Bar<br>ø22x40x450                 | 9703200437        | <b>TM37734</b><br> |
| 970 ATEGO<br>972 ATEGO<br>970 ATEGO 2<br>974 ATEGO 2<br>976 ATEGO 2<br>967 ATEGO 3                         | Link, Stabilizer Bar<br>ø43,57x59x28               | 9703200237        | <b>TM37735</b><br> |












| TM No.  | Replaces Ref. No: | Description                                       | Model / Details  |
|---|-------------------|---|--|
| <b>TM37736</b><br>   | 9603204937        | Link, Stabilizer Bar<br>ø35x450                   | 964 AROCS  |
| <b>TM37737</b><br>   | 9603204837        | Link, Stabilizer Bar<br>ø35x470                   | 964 AROCS  |
| <b>TM37738</b><br>  | 9603204637        | Link, Stabilizer Bar<br>ø35x500                   | 964 AROCS  |
| <b>TM28359</b><br> | 9603201537        | Link, Stabilizer Bar<br>ø18xø20,3/480             | 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS |
| <b>TM28360</b><br> | 9603204337        | Link, Stabilizer Bar<br>ø18x420                   | 963 ACTROS MP4   |
| <b>TM27955</b><br> | 9053200589        | Link, Stabilizer Bar<br>Right<br>M10/166x58/128,5 | 903 SPRINTER<br>905 SPRINTER                               |
| <b>TM27954</b><br> | 9053200489        | Link, Stabilizer Bar<br>Left<br>M10/166x58/128,5  | 903 SPRINTER<br>905 SPRINTER                               |



| Model / Details   | Description                             | Replaces Ref. No:                                    | TM No.  |
|---|---|--|---|
| BM MODEL<br>638 V-CLASS   | Link, Stabilizer Bar<br>M10/135,5       | 6383260016<br>6383260116                             | <b>TM37739</b><br>   |
| 963 ACTROS MP4  | Link, Stabilizer Bar<br>Front<br>ø18x46 | 9603206937   | <b>TM28361</b><br>   |
| 376 LP 1219 MBTC-USA<br>376 LP 1419 MBTC-USA<br>376 LPS 1525 MBTC-USA<br>380 NG<br>381 NG<br>383 NG<br>385 NG | Link, Stabilizer Bar<br>L: 328 mm       | 6173200089<br>6173200189<br>3813200589<br>3813200789 | <b>TM27862</b><br>  |
| 690 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER<br>905 SPRINTER<br>906 SPRINTER<br>909 SPRINTER  | Link, Stabilizer Bar<br>L: 230 mm       | 9013200589   | <b>TM27979</b><br> |
| 906 SPRINTER  | Link, Stabilizer Bar<br>L: 212 mm       | 9063201389   | <b>TM27475</b><br> |
| 901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER<br>690 SPRINTER<br>909 SPRINTER                  | Link, Stabilizer Bar<br>L: 115 mm       | 9013200289   | <b>TM27974</b><br> |
| 901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER<br>690 SPRINTER<br>909 SPRINTER                  | Link, Stabilizer Bar<br>L: 115 mm       | 9013200389   | <b>TM27975</b><br> |





| TM No.  | Replaces Ref. No:                      | Description                             | Model / Details  |
|---|--|---|--|
| <b>TM27976</b><br>   | 9013200089                             | Link, Stabilizer Bar<br>L: 95 mm        | 690 SPRINTER<br>901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER   |
| <b>TM27980</b><br>   | 9013200689                             | Link, Stabilizer Bar                    | 904 SPRINTER   |
| <b>TM37740</b><br>  | 6393260616                             | Link, Stabilizer Bar<br>Rear<br>M10/145 | 639 VIANO<br>636 VIANO<br>639 VIANO<br>639 VITO  |
| <b>TM27234</b><br> | 9473500105<br>9443500005<br>3753500005 | V Arm<br>L: 622 mm                      | 950 ACTROS<br>952 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>934 ACTROS 2/3<br>940 AXOR 2 |
| <b>TM27903</b><br> | 9743500505<br>9743500005<br>9743500405 | V Arm<br>L: 761,7 mm                    | 970 ATEGO<br>970 ATEGO 2<br>974 ATEGO 2<br>975 ATEGO 2<br>967 ATEGO 3                                      |
| <b>TM27430</b><br> | 9483502305<br>9483500905               | V Arm<br>L: 667 mm                      | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 |
| <b>TM27837</b><br> | 9483503005<br>9483500405<br>9483501105 | V Arm<br>L: 622 mm                      | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 |

















| Model / Details   | Description          | Replaces Ref. No:                      | TM No.  |
|---|----------------------|--|---|
| 954 ACTROS<br>934 ACTROS 2/3<br>963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS<br>375 AXOR        | V Arm<br>L: 622 mm   | 9423501205<br>9423500805<br>9423500505 | <b>TM27402</b><br>   |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3    | V Arm<br>L: 622 mm   | 9443500605<br>9443500505<br>9473500905 | <b>TM37743</b><br>   |
| 950 ACTROS<br>930 ACTROS 2/3<br>375 AXOR<br>940 AXOR 2<br>950 AXOR 2<br>957 ECONIC                            | V Arm<br>L: 622 mm   | 9423501105<br>9423500105<br>3753500105 | <b>TM27431</b><br>  |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3    | V Arm<br>L: 621,5 mm | 9483502205<br>9483501705               | <b>TM27787</b><br> |
| 613 TOURISMO  | V Arm<br>L: 507 mm   | 6133330104<br>3563331304<br>6133330004 | <b>TM27454</b><br> |
| 385 NG<br>616 NG<br>620 NG<br>623 NG<br>655 SK<br>656 SK<br>657 SK  | V Arm<br>L: 622 mm   | 6583500205<br>6563500005               | <b>TM27566</b><br> |
| 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3<br>964 AROCS<br>374 AXOR 2<br>942 AXOR 2 | V Arm<br>L: 667 mm   | 9483502805                             | <b>TM27110</b><br> |












| TM No.  | Replaces Ref. No:                      | Description             | Model / Details   |
|---|--|-------------------------|---|
| <b>TM27111</b><br>   | 9483502905                             | V Arm<br>L: 622 mm      | 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3<br>964 AROCS<br>374 AXOR 2<br>940 AXOR 2 |
| <b>TM27156</b><br>   | 9443500405                             | V Arm<br>L: 622 mm      | 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3<br>964 AROCS<br>942 AXOR 2<br>943 AXOR 2 |
| <b>TM27109</b><br>   | 9483502705                             | V Arm<br>L: 625 mm      | 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3<br>964 AROCS<br>374 AXOR 2<br>940 AXOR 2 |
| <b>TM27157</b><br> | 9423500905<br>9423501305               | V Arm<br>L: 622 mm      | 934 ACTROS 2/3<br>976 ATEGO 2   |
| <b>TM28061</b><br> | 9603500405<br>9603503405               | V Arm<br>L: 568 mm      | 963 ACTROS MP4<br>964 AROCS   |
| <b>TM27431</b><br> | 9423501105<br>9423500105<br>3753500105 | V Arm<br>L: 622 mm      | 950 ACTROS<br>930 ACTROS 2/3<br>375 AXOR<br>940 AXOR 2<br>950 AXOR 2<br>957 ECONIC                            |
| <b>TM27563</b><br> | 6583500206<br>6583500006<br>6553500006 | Torque Rod<br>L: 585 mm | 387 NG<br>389 NG<br>393 NG<br>620 NG<br>621 NG<br>623 NG<br>625 NG  |










| Model / Details  | Description             | Replaces Ref. No:                      | TM No.  |
|--|-------------------------|--|---|
| 343 T2/L<br>395 NG<br>624 NG<br>625 NG<br>649 NG<br>625 SK<br>659 SK                                       | Torque Rod<br>L: 579 mm | 6593503406<br>3953500006<br>6243500006 | <b>TM37746</b><br>   |
| 651 MK<br>652 MK<br>653 MK<br>380 NG<br>381 NG<br>383 NG<br>385 NG   | Torque Rod<br>L: 522 mm | 6523500306<br>3813500606<br>6533500106 | <b>TM27411</b><br>   |
| 653 MK<br>385 NG<br>619 NG   | Torque Rod              | 3853500006<br>6533500006               | <b>TM27857</b><br>  |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 | Torque Rod              | 9483502405<br>9483502005<br>9483501305 | <b>TM27131</b><br> |
| 950 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>934 ACTROS 2/3<br>950 AXOR 2                                 | Torque Rod              | 9453300007                             | <b>TM27063</b><br> |
| 625 NG<br>625 SK   | Torque Rod              | 6593503206<br>6593500906<br>3953501206 | <b>TM37748</b><br> |
| 950 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>934 ACTROS 2/3<br>950 AXOR 2                                 | Torque Rod              | 9453300011                             | <b>TM27922</b><br> |





| TM No.  | Replaces Ref. No:        | Description             | Model / Details   |
|---|--------------------------|-------------------------|---|
| <b>TM37749</b><br>   | 6273500106               | Torque Rod<br>L: 658 mm | 633 INTEGRO<br>632 TOURISMO<br>629 TRAVEGO<br>632 TRAVEGO<br>410 SETRA<br>629 SETRA<br>632 SETRA                    |
|   | 6273500006               |                         |   |
| <b>TM27907</b><br>   | 3573330205               | Torque Rod<br>L: 750 mm | 357 O 405<br>612 O 405<br>671 CONECTO<br>671 O 345<br>698 BGT-N 2   |
|   |                          |                         |   |
| <b>TM27865</b><br>   | 6293501206               | Torque Rod<br>L: 630 mm | 628 CITARO<br>633 INTEGRO<br>633 INTOURO<br>632 TOURISMO<br>629 TRAVEGO<br>632 TRAVEGO<br>629 SETRA                 |
|   | 6293502806<br>6293500106 |                         |   |
| <b>TM05232</b><br> | 6593503506               | Torque Rod<br>L: 579 mm | 343 T2/L<br>395 NG<br>624 NG<br>625 NG<br>649 NG<br>625 SK<br>659 SK  |
|   | 6593501206<br>6243500106 |                         |   |
| <b>TM27417</b><br> | 9413300007               | Torque Rod<br>L: 845 mm | 950 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>934 ACTROS 2/3<br>940 AXOR 2<br>950 AXOR 2<br>954 AXOR 2              |
|   | 3753300007               |                         |   |
| <b>TM27684</b><br> | 9483502505               | Torque Rod<br>L: 615 mm | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3          |
|   | 9453500105<br>9483501005 |                         |   |
| <b>TM27901</b><br> | 6243500406               | Torque Rod<br>L: 629 mm | 388 L 2635/6X4/54<br>388 LK 2635/6X4/40<br>388 LS 2635/6X4/40<br>696 L 2638<br>696 LK 2638<br>696 LS 2638<br>625 NG |
|   | 6593501506<br>6593503806 |                         |   |



| Model / Details  | Description             | Replaces Ref. No:                      | TM No.  |
|--|-------------------------|--|---|
| 28 CITARO  | Torque Rod<br>L: 664 mm | 6283330003<br>6283330005<br>6283331005 | <b>TM27416</b><br>   |
| 950 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>934 ACTROS 2/3<br>940 AXOR 2<br>950 AXOR 2<br>954 AXOR 2 | Torque Rod<br>L: 754 mm | 9413300011<br>3753300111<br>9413300111 | <b>TM27923</b><br>   |
| 970 ATEGO<br>970 ATEGO 2<br>974 ATEGO 2<br>967 ATEGO 3   | Torque Rod<br>L: 655 mm | 9723500906                             | <b>TM27957</b><br>   |
| 375 ACTROS<br>375 ATEGO 2<br>375 AXOR 2<br>940 AXOR 2  | Torque Rod<br>L: 579 mm | 3753500006                             | <b>TM37750</b><br> |
| 970 ATEGO<br>970 ATEGO 2<br>967 ATEGO 3  | Torque Rod<br>L: 813 mm | 9743300107                             | <b>TM37751</b><br> |
| BM MODEL<br>954 ACTROS<br>930 ACTROS 2/3<br>934 ACTROS 2/3   | Torque Rod<br>L: 951 mm | 9423300507                             | <b>TM37753</b><br> |
| 934 ACTROS 2/3   | Torque Rod<br>L: 925 mm | 9423300707                             | <b>TM37754</b><br> |



















| TM No.  | Replaces Ref. No:                                    | Description                                      | Model / Details  |
|---|--|--|--|
| <b>TM30475</b><br>   | 9603300107   | Torque Rod<br>L: 860 mm                          | 963 ACTROS MP4   |
| <b>TM27480</b><br>   | 9603300311   | Torque Rod<br>L: 600 mm                          | 963 ACTROS MP4<br>964 AROCS  |
| <b>TM37756</b><br>   | 3753500306   | Torque Rod<br>L: 585 mm                          | 964 AROCS<br>942 AXOR 2<br>943 AXOR 2  |
| <b>TM27460</b><br> | 9603500906   | Torque Rod<br>L: 532 mm                          | 963 ACTROS MP4   |
| <b>TM27341</b><br> | 9603500706<br>9603501306                             | Torque Rod<br>L: 532 mm                          | 963 ACTROS MP4   |
| <b>TM37757</b><br> | 000000005464<br>308674024000                         | Nut, Axle Rod<br>M24x2                           | 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3 |
| <b>TM28408</b><br> | 0003500213<br>0005861433<br>0003500505<br>0003500305 | Repair Kit, Axle Rod<br>With Bolt<br>ø80xø21/152 | 314 LP<br>316 LP<br>318 LP<br>360 L 1817,1819/6X4<br>360 L 1819/6X4<br>651 MK<br>652 MK                |





| Model / Details   | Description  | Replaces Ref. No:                                    | TM No.  |
|---|--|--|---|
| 616 NG<br>617 NG<br>619 NG<br>620 NG<br>621 NG<br>622 NG<br>623 NG                      | Repair Kit, Axle Rod<br>Without Bolt<br>ø80        | 0005861533   | <b>TM28420</b><br>   |
| 343 T2/LN1<br>352 L 1813/6X2<br>352 L 1813/6X4<br>360 L 1817,1819/6X4<br>360 L 1819/6X4 | Repair Kit, Axle Rod<br>M39x1,5/ø80x162,5          | 3435860032<br>0005861633                             | <b>TM37758</b><br>   |
| 352 L 1813/6X4<br>352 L 1813/6X2<br>360 L 1819/6X4<br>343 T2/LN1<br>360 L 1817,1819/6X4 | Repair Kit, Axle Rod<br>Without Bolt<br>ø80        | 0005860632   | <b>TM37759</b><br>  |
| 380 NG<br>381 NG<br>383 NG<br>385 NG<br>387 NG<br>389 NG<br>393 NG                      | Repair Kit, Axle Rod<br>M24x1,5/ø90x62             | 0003500405<br>0005860135<br>0005861833<br>0005861933 | <b>TM28419</b><br> |
| 651 MK<br>652 MK<br>653 MK<br>654 MK<br>380 NG<br>381 NG<br>383 NG                      | Repair Kit, Axle Rod<br>M20x1,5/ø80x46             | 0003500205<br>0005861035S                            | <b>TM37760</b><br> |
| 651 MK<br>652 MK<br>653 MK<br>654 MK<br>655 SK<br>656 SK<br>657 SK                      | Repair Kit, Axle Rod<br>With Bolt<br>ø80x21/26x152 | 0003501405   | <b>TM37761</b><br> |
| 651 MK<br>652 MK<br>653 MK<br>654 MK<br>655 SK<br>656 SK<br>657 SK                      | Repair Kit, Axle Rod<br>M24x1,5/ø90x60             | 0003501505   | <b>TM37762</b><br> |










| TM No.  | Replaces Ref. No:                      | Description   | Model / Details   |
|---|--|---|---|
| <b>TM37763</b><br>   | 0003500805                             | Repair Kit, Axle Rod<br>With Bolt<br>M24x1,5/ø90x57,5 | -   |
| <b>TM37764</b><br>   | 0003500513                             | Repair Kit, Axle Rod<br>M24x1,5/ø90x59                | 396 OH SERIES   |
| <b>TM37745</b><br>   | 0003503005<br>0003500613<br>0005861135 | Repair Kit, Axle Rod<br>ø85xø21/152                   | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3  |
| <b>TM37747</b><br> | 0003500413<br>0005861235               | Repair Kit, Axle Rod<br>ø95xø21/152                   | 343 T2/L<br>388 L 2635/6X4/54<br>388 LK 2635/6X4/40<br>388 LS 2635/6X4/40<br>696 L 2638<br>696 LK 2638<br>696 LS 2638                                 |
| <b>TM28409</b><br> | 0003500113                             | Repair Kit, Axle Rod<br>ø108xø21/152                  | 388 L 2635/6X4/54<br>388 LK 2635/6X4/40<br>388 LS 2635/6X4/40<br>696 L 2638<br>696 LK 2638<br>696 LS 2638<br>625 NG                                   |
| <b>TM27577</b><br> | 0003500506<br>0003300611               | Repair Kit, Axle Rod<br>ø85xø19/130                   | 382 O 500<br>382 O 500 M / 1725<br>382 O 500 M / 1725 / 1726<br>382 O 500 M / 1728<br>382 O 500 R / 1830 / 30<br>382 O 500 U / 1725 / 59<br>634 O 500 |
| <b>TM28418</b><br> | 0003300075                             | Repair Kit, Axle Rod<br>ø85xø16,5/130                 | 396 OH SERIES<br>697 O 402<br>357 O 405<br>612 O 405<br>697 O 301<br>698 BGT-25<br>698 BGU-25   |










| Model / Details  | Description                          | Replaces Ref. No:          | TM No.         |
|--|--------------------------------------|----------------------------|----------------|
| 613 TOURISMO   | Repair Kit, Axle Rod<br>ø75xø17/130  | 0003501305                 | <b>TM28447</b> |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 | Repair Kit, Axle Rod<br>ø75xø25/130  | 0003502205                 | <b>TM27062</b> |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 | Repair Kit, Axle Rod<br>ø85xø25/152  | 0003502305                 | <b>TM28422</b> |
| 314 LP<br>316 LP<br>318 LP<br>360 L 1817,1819/6X4<br>360 L 1819/6X4<br>651 MK<br>652 MK                    | Repair Kit, Axle Rod<br>ø80xø21/152  | 0003500213S<br>0005861433S | <b>TM37765</b> |
| 357 O 405<br>698 BGT-N 2   | Repair Kit, Axle Rod<br>ø75xø19/130  | 0003300207                 | <b>TM27589</b> |
| 357 O 405<br>612 O 405<br>628 CITARO<br>628 CONECTO<br>698 BGT-N 2   | Repair Kit, Axle Rod<br>ø67xø19/130  | 0003300511                 | <b>TM28735</b> |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 | Repair Kit, Axle Rod<br>ø100xø25/152 | 0003502405                 | <b>TM27583</b> |



| TM No.  | Replaces Ref. No:        | Description                           | Model / Details  |
|---|--------------------------|---------------------------------------|--|
| <b>TM28442</b><br>   | 0003301411               | Repair Kit, Axle Rod<br>ø67xø17/100   | 950 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>934 ACTROS 2/3<br>940 AXOR 2<br>950 AXOR 2<br>954 AXOR 2     |
| <b>TM28063</b><br>   | 0003502105               | Repair Kit, Axle Rod<br>ø75xø25/152   | 950 ACTROS<br>930 ACTROS 2/3<br>970 ATEGO<br>970 ATEGO 2<br>974 ATEGO 2<br>975 ATEGO 2<br>375 AXOR         |
| <b>TM28451</b><br>  | 0003501005               | Repair Kit, Axle Rod<br>ø67xø15/115   | 613 TOURISMO   |
| <b>TM28432</b><br> | 0003501805               | Repair Kit, Axle Rod<br>ø85x21/26x152 | 651 MK<br>652 MK<br>653 MK<br>654 MK<br>655 SK<br>656 SK<br>657 SK   |
| <b>TM37766</b><br> | 0003302611<br>0003302511 | Repair Kit, Axle Rod<br>ø56xø15/90    | -  |
| <b>TM27507</b><br> | 0003504805<br>0003503305 | Repair Kit, Axle Rod<br>ø85xø23/130   | 954 ACTROS<br>934 ACTROS 2/3<br>375 AXOR<br>374 AXOR 2<br>940 AXOR 2<br>944 AXOR 2<br>954 AXOR 2           |
| <b>TM37767</b><br> | 0003502505               | Repair Kit, Axle Rod<br>ø75xø25/130   | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 |










| Model / Details  | Description                           | Replaces Ref. No:                      | TM No.  |
|--|---------------------------------------|--|---|
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3     | Repair Kit, Axle Rod<br>ø108xø25/152  | 0003503605                             | <b>TM28065</b><br>   |
| 613 TOURISMO   | Repair Kit, Axle Rod<br>ø75x19/28x126 | 0003501205<br>0003300410               | <b>TM28452</b><br>   |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3     | Repair Kit, Axle Rod<br>ø75xø25/130   | 0003503405<br>0003503205<br>6293300407 | <b>TM27294</b><br>  |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3     | Repair Kit, Axle Rod<br>ø85xø25/152   | 0003503105                             | <b>TM28423</b><br> |
| BM MODEL<br>950 ACTROS<br>930 ACTROS 2/3<br>970 ATEGO<br>970 ATEGO 2<br>974 ATEGO 2<br>975 ATEGO 2<br>375 AXOR | Repair Kit, Axle Rod<br>ø67xø23/130   | 0003502005                             | <b>TM28064</b><br> |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3     | Repair Kit, Axle Rod<br>ø85xø23/130   | 0003503705<br>0003504205               | <b>TM28067</b><br> |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3     | Repair Kit, Axle Rod<br>ø85xø21/152   | 0003502705                             | <b>TM28066</b><br> |














| TM No.  | Replaces Ref. No:        | Description                          | Model / Details  |
|---|--------------------------|--------------------------------------|--|
| <b>TM37768</b><br>   | 0003503505               | RepairKit, Axle Rod<br>ø100xø25/152  | 375 AXOR 2   |
| <b>TM37769</b><br>   | 0003502905               | Repair Kit, Axle Rod<br>ø108xø25/152 | -  |
| <b>TM37770</b><br>   | 0003504105               | Repair Kit, Axle Rod<br>ø75xø23/130  | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 |
| <b>TM37741</b><br> | 0003504505<br>0003505205 | Repair Kit, Axle Rod<br>ø75xø25/130  | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 |
| <b>TM37771</b><br> | 0003504605               | Repair Kit, Axle Rod<br>ø75xø25/152  | 950 ACTROS<br>930 ACTROS 2/3<br>970 ATEGO<br>970 ATEGO 2<br>974 ATEGO 2<br>975 ATEGO 2<br>967 ATEGO 3      |
| <b>TM37772</b><br> | 0003504405<br>0003505105 | Repair Kit, Axle Rod<br>ø85xø25/152  | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 |
| <b>TM28444</b><br> | 0003504905               | Repair Kit, Axle Rod<br>ø100xø25/152 | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 |












| Model / Details  | Description                          | Replaces Ref. No: | TM No.  |
|--|--------------------------------------|-------------------|---|
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 | Repair Kit, Axle Rod<br>ø75xø21/152  | 0003501313        | <b>TM37773</b><br>   |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 | Repair Kit, Axle Rod<br>ø85xø25/152  | 0003504005        | <b>TM37774</b><br>   |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 | Repair Kit, Axle Rod<br>ø75xø21/152  | 0003502605        | <b>TM28448</b><br>  |
| 950 ACTROS<br>930 ACTROS 2/3<br>970 ATEGO<br>970 ATEGO 2<br>974 ATEGO 2<br>975 ATEGO 2<br>967 ATEGO 3      | Repair Kit, Axle Rod<br>ø67xø23/130  | 0003504705        | <b>TM37744</b><br> |
| -  | Repair Kit, Axle Rod<br>ø85xø19/130  | -                 | <b>TM37775</b><br> |
| -  | Repair Kit, Axle Rod<br>ø108xø25/152 | 3753500605S1      | <b>TM37776</b><br> |
| -  | Repair Kit, Axle Rod<br>ø85xø23/130  | 3753500605S2      | <b>TM37777</b><br> |












| TM No.  | Replaces Ref. No:        | Description                         | Model / Details  |
|---|--------------------------|-------------------------------------|--|
| <b>TM37778</b><br>   | 0003300210<br>3133330104 | Repair Kit, Axle Rod<br>ø75xø15/115 | -  |
| <b>TM27591</b><br>   | 0003502805               | Repair Kit, Axle Rod<br>ø85xø25/130 | -  |
| <b>TM27505</b><br>  | 0003300707<br>0003302711 | Repair Kit, Axle Rod<br>ø75xø17/115 | 382 OH SERIES<br>357 O 405<br>382 O 500<br>382 O 500 U / 1725 / 59<br>628 CITARO   |
| <b>TM27598</b><br> | 0003501513               | Repair Kit, Axle Rod<br>ø85xø19/130 | 628 CITARO<br>444 TOURINO<br>632 TRAVEGO<br>410 SETRA<br>632 SETRA<br>634 IBC-FAHRG-<br>ESTELL-BUGGY 3-ACHS-<br>ER NAFTA                                     |
| <b>TM27516</b><br> | 0003302011               | Repair Kit, Axle Rod<br>ø75xø19/130 | 368 OH SERIES<br>382 O 500<br>382 O 500 M / 1725<br>382 O 500 M / 1725 / 1726<br>382 O 500 M / 1728<br>382 O 500 R / 1830 / 30<br>382 O 500 U / 1725 / 59    |
| <b>TM28450</b><br> | 0003302111               | Repair Kit, Axle Rod<br>ø67xø17/115 | 628 CITARO   |
| <b>TM28126</b><br> | 0003500906               | Repair Kit, Axle Rod<br>ø85xø19/130 | 382 OH SERIES<br>382 O 500<br>382 O 500 M / 1725 / 1726<br>382 O 500 R / 1830 / 30<br>382 O 500 U / 1725 / 59<br>634 O 500<br>634 O 500 RSD /<br>2736/8X2/30 |









| Model / Details   | Description                               | Replaces Ref. No: | TM No.         |
|---|---|-------------------|----------------|
| -   | Repair Kit, Axle Rod<br>ø75xø19/115       | 6293300007        | <b>TM27306</b> |
| 444 TOURINO<br>444 MBC-FAHRGESTELL<br>EURO 3  | Repair Kit, Axle Rod<br>ø67xø17/115       | 4443330127        | <b>TM37779</b> |
| -   | Repair Kit, Axle Rod<br>M36x1,5/ø85x171   | 6293300107        | <b>TM27295</b> |
| 385 NG  | Repair Kit, Axle Rod<br>M39x1,5/ø85x172,5 | 0003501013        | <b>TM29125</b> |
| 382 OH SERIES<br>357 O 405<br>382 O 500<br>382 O 500 U / 1725 / 59<br>628 CITARO<br>698 BGT-N 2 | Repair Kit, Axle Rod<br>M36x1,5/ø85x248   | 0003300107        | <b>TM37780</b> |
| 651 MK<br>652 MK<br>653 MK<br>654 MK<br>655 SK<br>656 SK<br>657 SK                              | Repair Kit, Axle Rod<br>M24x1,5/ø108x68   | 0003501705        | <b>TM28421</b> |
| 613 TOURISMO  | Repair Kit, Axle Rod<br>M24x1,5/ø95x72    | 0003500905        | <b>TM28446</b> |





| TM No.  | Replaces Ref. No:        | Description  | Model / Details  |
|---|--------------------------|--|--|
| <b>TM29003</b><br>   | 0003501905               | Repair Kit, Axle Rod<br>M24x1,5/ø95x72             | 651 MK<br>652 MK<br>653 MK<br>654 MK<br>616 NG<br>619 NG<br>655 SK   |
| <b>TM28445</b><br>   | 0003501105               | Repair Kit, Axle Rod<br>M24x1,5/ø95x72             | 613 TOURISMO   |
| <b>TM37781</b><br>  | 0003500105               | Repair Kit, Axle Rod<br>M24x1,5/ø90x60             | 651 MK<br>652 MK<br>653 MK<br>654 MK<br>616 NG<br>617 NG<br>619 NG   |
| <b>TM37742</b><br> | 81432706126              | Repair Kit, Axle Rod<br>For 095.277<br>ø85xø23/130 | 374 AXOR 2<br>375 AXOR<br>944 AXOR 2<br>954 AXOR 2<br>934 ACTROS 2/3<br>954 ACTROS<br>963 ACTROS MP4       |
| <b>TM37782</b><br> | 81432706134              | Repair Kit, Axle Rod<br>For 095.407<br>ø85xø25/152 | 942 AXOR 2<br>943 AXOR 2<br>950 AXOR 2<br>952 AXOR 2<br>953 AXOR 2<br>930 ACTROS 2/3<br>932 ACTROS 2/3     |
| <b>TM37783</b><br> | 9484230533<br>9484230133 | Bracket, Axle Rod<br>Rear<br>161x435x205           | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 |
| <b>TM37785</b><br> | 9473251909<br>9473250209 | Bracket, Axle Rod<br>Rear<br>162x257x140           | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 |



| Model / Details | Description       | Replaces Ref. No: | TM No.  |
|-----------------|-------------------|-------------------|---|
| 950 ACTROS      | Bracket, Axle Rod | 9473250426        | <b>TM27856</b><br>   |
| 952 ACTROS      | M20x1,5/125x-     | 9473250226        |   |
| 953 ACTROS      | 43/167x34         |                   |   |
| 954 ACTROS      |                   |                   |   |
| 930 ACTROS 2/3  |                   |                   |   |
| 932 ACTROS 2/3  |                   |                   |   |
| 933 ACTROS 2/3  |                   |                   |   |
| BM MODEL        | Bracket, Axle Rod | 9483254909        | <b>TM37786</b><br>   |
| 930 ACTROS 2/3  | Rear, Bottom      | 9483250409        |   |
| 932 ACTROS 2/3  | 199x353x145       |                   |   |
| 933 ACTROS 2/3  |                   |                   |   |
| 934 ACTROS 2/3  |                   |                   |   |
| 374 AXOR 2      |                   |                   |   |
| 940 AXOR 2      |                   |                   |   |
| 942 AXOR 2      |                   |                   |   |
| 950 ACTROS      | Bracket, Axle Rod | 9483251809        | <b>TM37787</b><br>  |
| 952 ACTROS      | Left              |                   |   |
| 953 ACTROS      | 35x395x152        |                   |   |
| 954 ACTROS      |                   |                   |   |
| 930 ACTROS 2/3  |                   |                   |   |
| 932 ACTROS 2/3  |                   |                   |   |
| 933 ACTROS 2/3  |                   |                   |   |
| 950 ACTROS      | Bracket, Axle Rod | 9483251909        | <b>TM37788</b><br> |
| 952 ACTROS      | Right             |                   |   |
| 953 ACTROS      | 235x395x152       |                   |   |
| 954 ACTROS      |                   |                   |   |
| 930 ACTROS 2/3  |                   |                   |   |
| 932 ACTROS 2/3  |                   |                   |   |
| 933 ACTROS 2/3  |                   |                   |   |
| 950 ACTROS      | Bracket, Axle Rod | 9483254209        | <b>TM37789</b><br> |
| 952 ACTROS      | Left              | 9483252309        |   |
| 953 ACTROS      | ø21/182x125/458,5 | 9483251009        |   |
| 954 ACTROS      |                   |                   |   |
| 930 ACTROS 2/3  |                   |                   |   |
| 932 ACTROS 2/3  |                   |                   |   |
| 933 ACTROS 2/3  |                   |                   |   |
| 950 ACTROS      | Bracket, Axle Rod | 9483254309        | <b>TM37790</b><br> |
| 952 ACTROS      | Right             | 9483252409        |   |
| 953 ACTROS      | 233,5x458,5x163,5 | 9483251109        |   |
| 954 ACTROS      |                   |                   |   |
| 930 ACTROS 2/3  |                   |                   |   |
| 932 ACTROS 2/3  |                   |                   |   |
| 933 ACTROS 2/3  |                   |                   |   |
| 930 ACTROS 2/3  | Bracket, Axle Rod | 9483255209        | <b>TM37791</b><br> |
| 932 ACTROS 2/3  | 254x354,5x155,5   | 9483250809        |   |
| 934 ACTROS 2/3  |                   |                   |   |
| 374 AXOR 2      |                   |                   |   |
| 942 AXOR 2      |                   |                   |   |
| 943 AXOR 2      |                   |                   |   |
| 952 AXOR 2      |                   |                   |   |





| TM No.  | Replaces Ref. No:        | Description                    | Model / Details  |
|---|--------------------------|--------------------------------|--|
| <b>TM37792</b>  | 9423250309               | Bracket, Axle Rod              | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3     |
|  |                          |                                |  |
| <b>TM37793</b>  | 9483250909<br>9483255109 | Bracket, Axle Rod<br>152x201,5 | 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3<br>374 AXOR 2<br>940 AXOR 2<br>942 AXOR 2 |
|  |                          |                                |  |
| <b>TM37794</b>  | 9483251209               | Bracket, Axle Rod              | 952 ACTROS<br>954 ACTROS<br>932 ACTROS 2/3<br>934 ACTROS 2/3<br>374 AXOR 2<br>942 AXOR 2<br>943 AXOR 2         |
|  |                          |                                |  |







| Model / Details  | Description  | Replaces Ref. No:  | TM No.  |
|--|--|--|---|
| 343 T2/L<br>388 L 2635/6X4/54<br>388 LK 2635/6X4/40<br>388 LS 2635/6X4/40<br>696 L 1938<br>696 L 2638<br>696 LK 2638 | Screw, Axle Rod<br>M20x1,5/210                           | 6599900001<br>3959900201<br>000960020127<br>000960020150 | <b>TM27701</b><br>   |
| 357 O 405<br>612 O 405<br>357 O 407<br>612 O 407<br>357 O 408<br>612 O 408   | Rubber Bushing, Axle Rod<br>ø87xø17/130                  | 0003300080   | <b>TM28449</b><br>   |
| 954 ACTROS<br>375 AXOR<br>944 AXOR 2   | Rubber Bushing, Axle Rod<br>ø74,5xø21/130                | 9423260250   | <b>TM27897</b><br>   |
| 950 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>934 ACTROS 2/3<br>940 AXOR 2<br>950 AXOR 2<br>954 AXOR 2               | Rubber Bushing, Axle Rod<br>ø77xø24x96                   | 0003310017   | <b>TM27898</b><br> |
| 970 ATEGO<br>970 ATEGO 2<br>967 ATEGO 3  | Rubber Bushing, Axle Rod<br>For 095.438<br>ø76xø20,5x119 | 9743300107S  | <b>TM37752</b><br> |
| 963 ACTROS MP4   | Rubber Bushing, Axle Rod<br>For 095.441<br>ø70xø17x100   | 9603300107S  | <b>TM37755</b><br> |
| 970 ATEGO<br>970 ATEGO 2<br>974 ATEGO 2<br>967 ATEGO 3   | Rubber Bushing, Axle Rod<br>For 095.436<br>ø77xø17/115   | 9723500906S  | <b>TM37795</b><br> |












| TM No.  | Replaces Ref. No:                                    | Description   | Model / Details  |
|---|--|---|--|
| <b>TM37796</b><br>   | 0019964045   | Grip Head, Connecting Rod Right<br>ø24,2/M38x1,5  | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>942 AXOR 2 |
|   | 0019964145   | Grip Head, Connecting Rod Left<br>ø24,2/M38x1,5   | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>942 AXOR 2 |
| <b>TM37798</b><br>   | 3753260200   | Shock Absorber Rear<br>ø16x506/854  | 942 AXOR 2<br>943 AXOR   |
|   | 0053261100<br>0053262500<br>0053267400<br>0063260100 | Shock Absorber Rear<br>Repl. Sachs: 124 359 / 131 623<br>Repl. Monroe: T5171<br>ø20x443/723 | 954 ACTROS<br>954 AXOR 2   |
| <b>TM27830</b><br> | 0063266700<br>0053260900<br>0053265700<br>0053265800 | Shock Absorber Rear<br>Repl. Sachs: 124 567<br>Repl. Monroe: T1201<br>ø16x514/854           | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 |
|   | 9043200231<br>9043260100<br>9043200131               | Shock Absorber Rear<br>Repl. Sachs: 124 654<br>ø14x325/515                                  | 690 SPRINTER<br>904 SPRINTER<br>909 SPRINTER   |
| <b>TM27904</b><br> | 9013200631<br>9033200031<br>9013200231<br>9013200431 | Shock Absorber Rear<br>Repl. Sachs: 290 377<br>Repl. Monroe: V1116<br>ø12/ø14x324/524       | 901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER   |



| Model / Details                                    | Description                        | Replaces Ref. No: | TM No.  |
|--|------------------------------------|-------------------|---|
| 950 ACTROS   | Shock Absorber                     | 0053239500        | <b>TM27831</b><br>   |
| 952 ACTROS   | Front                              | 0063236100        |   |
| 953 ACTROS   | Repl. Sachs: 310 805               | 0063233700        |   |
| 954 ACTROS   | ø16x479/804                        | 3753230800        |   |
| 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 |                                    |                   |   |
| 950 ACTROS   | Shock Absorber                     | 0063238300        | <b>TM27849</b><br>   |
| 954 ACTROS   | Front                              | 0053239900        |   |
| 930 ACTROS 2/3                                     | Repl. Sachs: 310 807 /             |                   |   |
| 940 AXOR 2   | 124 375                            |                   |   |
| 950 AXOR 2   | Repl. Monroe: T5360                |                   |   |
| 957 ECONIC   | ø20x446/731                        |                   |   |
| 375 ATEGO  | Shock Absorber                     | 9743230000        | <b>TM27943</b><br>   |
| 970 ATEGO  | Front                              | 9743230600        |   |
| 972 ATEGO  | Repl. Sachs: 125 909               | 9753230000        |   |
| 975 ATEGO  | Repl. Monroe: T1246                |                   |   |
| 375 ATEGO 2<br>970 ATEGO 2<br>972 ATEGO 2          | ø14x437/725                        |                   |   |
| 970 ATEGO  | Shock Absorber                     | 9703230000        | <b>TM28082</b><br> |
| 972 ATEGO  | Front                              | 9703230300        |   |
| 975 ATEGO  | Repl. Sachs: 313 766 /             | 9703230700        |   |
| 976 ATEGO  | 280 929                            | 9703231000        |   |
| 970 ATEGO 2<br>972 ATEGO 2<br>975 ATEGO 2          | Repl. Monroe: T1255<br>ø14x410/690 |                   |   |
| 970 ATEGO  | Shock Absorber                     | 9703260000        | <b>TM27874</b><br> |
| 972 ATEGO  | Rear                               | 9703260200        |   |
| 975 ATEGO  | Repl. Sachs: 125 911               |                   |   |
| 970 ATEGO 2  | Repl. Monroe: T1256                |                   |   |
| 972 ATEGO 2<br>975 ATEGO 2<br>976 ATEGO 2          | ø14/ø16x430/725                    |                   |   |
| 950 ACTROS   | Shock Absorber                     | 0063233300        | <b>TM27848</b><br> |
| 952 ACTROS   | Front                              | 0063233900        |   |
| 953 ACTROS   | Repl. Sachs: 124 639               | 0063234000        |   |
| 954 ACTROS   | ø16x461/771                        | 0063237400        |   |
| 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 |                                    |                   |   |
| 950 ACTROS   | Shock Absorber                     | 0053239600        | <b>TM27846</b><br> |
| 952 ACTROS   | Front                              | 0063237300        |   |
| 953 ACTROS   | Repl. Sachs: 124 678               |                   |   |
| 954 ACTROS   | ø16x479/804                        |                   |   |
| 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 |                                    |                   |   |





| TM No.  | Replaces Ref. No: | Description  | Model / Details  |
|---|-------------------|--|--|
| <b>TM27888</b><br>   | 0053239100        | Shock Absorber<br>Front<br>Repl. Sachs: 310 804 /<br>124 312<br>Repl. Monroe: T1251<br>ø16x503/853 | 954 ACTROS   |
|   |                   |  |  |
| <b>TM27833</b><br>   | 0053261000        | Shock Absorber<br>Rear<br>Repl. Sachs: 124 313<br>Repl. Monroe: T1210<br>ø16x465/765               | 950 ACTROS<br>952 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>934 ACTROS 2/3<br>950 AXOR 2<br>952 AXOR 2 |
|   |                   |  |  |
| <b>TM27832</b><br>  | 0063231600        | Shock Absorber<br>Front<br>Repl. Sachs: 124 358<br>ø16x503/853                                     | 950 ACTROS<br>954 ACTROS<br>950 AXOR 2<br>954 AXOR 2   |
|   |                   |  |  |
| <b>TM27847</b><br> | 0053239700        | Shock Absorber<br>Front<br>Repl. Sachs: 125 898<br>ø16x503/853                                     | 950 ACTROS   |
|   | 0063232100        |  | 952 ACTROS   |
|   | 0063237200        |  | 953 ACTROS   |
|   | 3753230100        |  | 954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3                                       |
| <b>TM27829</b><br> | 0053263300        | Shock Absorber<br>Rear<br>Repl. Sachs: 311 191 /<br>125 908<br>Repl. Monroe: T1200<br>ø16x465/765  | 950 ACTROS   |
|   | 0053263400        |  | 952 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>934 ACTROS 2/3<br>964 AROCS            |
| <b>TM27795</b><br> | 0063235100        | Shock Absorber<br>Front<br>Repl. Sachs: 131 944 /<br>131 056<br>Repl. Monroe: T1220<br>ø16x479/804 | 375 ACTROS   |
|   | 0063236000        |  | 950 ACTROS   |
|   | 0063237800        |  | 954 ACTROS   |
|   | 0063237900        |  | 934 ACTROS 2/3<br>375 AXOR<br>374 AXOR 2<br>375 AXOR 2   |
| <b>TM27825</b><br> | 0053261200        | Shock Absorber<br>Rear<br>Repl. Sachs: 124 360<br>Repl. Monroe: T5137<br>ø20x473/783               | 950 ACTROS   |
|   | 0063265600        |  | 952 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>940 AXOR 2<br>950 AXOR 2               |



| Model / Details  | Description   | Replaces Ref. No:                                    | TM No.  |
|--|---|--|---|
| 954 ACTROS<br>934 ACTROS 2/3   | Shock Absorber<br>Rear<br>Repl. Sachs: 280 940<br>Repl. Monroe: T5363<br>ø20x473/783            | 0053266800<br>0063262900                             | <b>TM27915</b><br>   |
| 950 ACTROS<br>375 AXOR<br>950 AXOR 2   | Shock Absorber<br>Rear<br>Repl. Sachs: 124 376<br>Repl. Monroe: T5256<br>ø20x520/875            | 0053261400<br>0063260500                             | <b>TM27826</b><br>   |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 | Shock Absorber<br>Rear<br>Repl. Sachs: 124 638<br>Repl. Monroe: T5372 /<br>T1211<br>ø16x535/895 | 0053266000<br>0053266400<br>0063266800<br>0053266600 | <b>TM27834</b><br>   |
| 375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>970 ATEGO 2<br>976 ATEGO 2                             | Shock Absorber<br>Rear<br>Repl. Sachs: 125 912<br>Repl. Monroe: T5178<br>ø16/ø20x418/668        | 9703260400<br>9743260400<br>9743260000               | <b>TM27863</b><br> |
| 954 ACTROS<br>944 AXOR 2   | Shock Absorber<br>Rear<br>Repl. Sachs: 300 019<br>ø20x444/689                                   | 0053266700<br>0053269700                             | <b>TM27824</b><br> |
| 906 SPRINTER   | Shock Absorber<br>Rear<br>Repl. Sachs: 314 608<br>ø12/ø14x321/502                               | 9063200131<br>9063200031<br>9063200531<br>9063200731 | <b>TM27972</b><br> |
| 601 207 D/208 D<br>601 208/210<br>601 209 D/210 D  | Shock Absorber<br>Rear<br>Repl. Sachs: 101 497<br>Repl. Monroe: V1066<br>ø12/ø14x320/520        | 6013200431<br>6013200631<br>6013200831<br>6013201231 | <b>TM27996</b><br> |





| TM No.  | Replaces Ref. No: | Description  | Model / Details   |
|---|-------------------|--|---|
| <b>TM37799</b><br>   | 6013200030        | Shock Absorber   | 601 207 D/208 D   |
|   | 6013200130        | Front  | 601 208/210   |
|   | 6013200730        | Repl. Sachs: 101 496                                       | 601 209 D/210 D   |
|   |                   | Repl. Monroe: V1036<br>ø12x360/605                         | 602 307 D/308 D<br>602 307 D/308D<br>602 308 D<br>602 308/310 |
| <b>TM37800</b><br>   | 0023232700        | Shock Absorber   | 309 T2/L  |
|   | 0023239400        | Rear   | 309 TL2/L   |
|   | 0023239600        | Repl. Sachs: 725 002 /<br>723 101                          | 310 T2/L<br>313 T2/L  |
|   | 0033235500        | Repl. Monroe: V2021<br>ø14x376/626                         | 309 O 309 B<br>309 O 309 D<br>310 LF 508 D/LF 608 D           |
| <b>TM27852</b><br>   | 0043238800        | Shock Absorber   | 668 T2/LN1  |
|   | 0043238900        | Front  | 669 T2/LN1  |
|   | 0053230200        | Repl. Sachs: 112 370                                       | 670 T2/LN1  |
|   | 0053230300        | Repl. Monroe: T1064 /<br>V1089<br>ø14x376/626              |   |
| <b>TM27968</b><br> | 9043200730        | Shock Absorber   | 904 SPRINTER  |
|   | 9043200830        | Front  | 909 SPRINTER  |
|   | 9043201630        | Repl. Sachs: 115 904 / 115<br>901                          |   |
|   | 9043201830        | Repl. Monroe: V4507<br>M16x375/558                         |   |
| <b>TM27964</b><br> | 9063260800        | Shock Absorber<br>Rear                                     | 906 SPRINTER  |
|   |                   |  |   |
| <b>TM27963</b><br> | 9063205630        | Shock Absorber   | 906 SPRINTER  |
|   | 9063206330        | Front  |   |
|   |                   | Repl. Sachs: 314 421<br>Repl. Monroe: V4510<br>M16x249/440 |   |
| <b>TM27999</b><br> | 0043261300        | Shock Absorber   | 668 T2/LN1  |
|   |                   | Rear   | 669 T2/LN1  |
|   |                   | Repl. Sachs: 310 775 /<br>112 023                          | 670 T2/LN1<br>667 VARIO                                       |
|   |                   | Repl. Monroe: T1194<br>ø14x402/652                         | 668 VARIO<br>670 VARIO  |





| Model / Details  | Description   | Replaces Ref. No:                                    | TM No.  |
|--|---|--|---|
| 638 VITO   | Shock Absorber<br>Rear<br>Repl. Sachs: 313 970 /<br>312 124<br>Repl. Monroe: V1501<br>ø14x364/487 | 6383260700   | <b>TM37801</b><br>   |
| 638 VITO<br>638 V-CLASS  | Shock Absorber<br>Front<br>Repl. Sachs: 310 016<br>Repl. Monroe: V4301<br>M14x420/576             | 6383200313<br>6383200613<br>6383200713<br>6383200813 | <b>TM37802</b><br>   |
| 950 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>934 ACTROS 2/3<br>375 AXOR<br>374 AXOR 2<br>942 AXOR 2       | Shock Absorber<br>Front<br>Repl. Sachs: 131 622<br>Repl. Monroe: T1304<br>ø16x479/804             | 0063235400   | <b>TM27845</b><br>  |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 | Shock Absorber<br>Front<br>Repl. Sachs: 290 242<br>Repl. Monroe: T1275<br>ø16x420/670             | 0063234500   | <b>TM27869</b><br> |
| 954 ACTROS<br>934 ACTROS 2/3   | Shock Absorber<br>Front<br>Repl. Sachs: 310 163 /<br>131 431<br>ø16x479/804                       | 0053236000<br>0053236500<br>0063239500               | <b>TM27867</b><br> |
| 972 ATEGO<br>970 ATEGO 2   | Shock Absorber<br>Rear<br>Repl. Sachs: 311 666<br>Repl. Monroe: T5403<br>ø20x459/744              | 0063262000<br>0063267100<br>9743261000               | <b>TM27872</b><br> |
| 970 ATEGO<br>970 ATEGO 2<br>974 ATEGO 2<br>975 ATEGO 2   | Shock Absorber<br>Front<br>Repl. Sachs: 300 022<br>ø14x439/736                                    | 9743231100   | <b>TM27885</b><br> |












| TM No.  | Replaces Ref. No: | Description           | Model / Details |
|---|-------------------|-----------------------|-----------------|
| <b>TM27944</b><br>   | 0063264200        | Shock Absorber        | 934 ACTROS 2/3  |
|   | 0063264300        | Rear                  | 970 ATEGO 2     |
|   | 9463260000        | Repl. Sachs: 312 644  |                 |
|   | 9463260100        | Repl. Monroe: F5251   |                 |
|   |                   | ø20x270/380           |                 |
| <b>TM28136</b><br>   | 0003232885        | Rubber Bushing, Shock | 979 ACCELO      |
|   | 0003232444        | Absorber              | 375 ACTROS      |
|   |                   | ø20xø40x39,5          | 950 ACTROS      |
|   |                   |                       | 952 ACTROS      |
|   |                   |                       | 953 ACTROS      |
|   |                   |                       | 954 ACTROS      |
|   |                   |                       | 930 ACTROS 2/3  |
| <b>TM35105</b><br>   | 0003237885        | Rubber Bushing, Shock | 901 SPRINTER    |
|   |                   | Absorber              | 902 SPRINTER    |
|   |                   | ø18x32,5x31           | 903 SPRINTER    |
| <b>TM35102</b><br> | 9013230085        | Rubber Bushing, Shock | 690 SPRINTER    |
|   |                   | Absorber              | 901 SPRINTER    |
|   |                   | ø16xø87x33            | 902 SPRINTER    |
|   |                   |                       | 903 SPRINTER    |
|   |                   |                       | 904 SPRINTER    |
|   |                   |                       | 905 SPRINTER    |
|   |                   |                       | 909 SPRINTER    |
| <b>TM35101</b><br> | 9013231185        | Rubber Bushing, Shock | 690 SPRINTER    |
|   |                   | Absorber              | 901 SPRINTER    |
|   |                   | ø16xø84,5x3           | 902 SPRINTER    |
|   |                   |                       | 903 SPRINTER    |
|   |                   |                       | 904 SPRINTER    |
|   |                   |                       | 905 SPRINTER    |
|   |                   |                       | 909 SPRINTER    |
| <b>TM28185</b><br> | 0003200144        | Rubber Bushing, Shock | 950 ACTROS      |
|   | 0003201444        | Absorber              | 952 ACTROS      |
|   |                   | ø16xø42x50            | 953 ACTROS      |
|   |                   |                       | 954 ACTROS      |
|   |                   |                       | 930 ACTROS 2/3  |
|   |                   |                       | 932 ACTROS 2/3  |
|   |                   |                       | 933 ACTROS 2/3  |
| <b>TM35053</b><br> | 0003234385        | Rubber Bushing, Shock | 375 ACTROS      |
|   | 0003232644        | Absorber              | 950 ACTROS      |
|   |                   | ø16xø35x28,5          | 952 ACTROS      |
|   |                   |                       | 953 ACTROS      |
|   |                   |                       | 954 ACTROS      |
|   |                   |                       | 930 ACTROS 2/3  |
|   |                   |                       | 932 ACTROS 2/3  |









| Model / Details  | Description                                       | Replaces Ref. No:                      | TM No.         |
|--|---|--|----------------|
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3             | Rubber Bushing, Shock Absorber<br>ø16xø54x105     | 0003200644                             | <b>TM28184</b> |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3             | Rubber Bushing, Shock Absorber<br>ø14,2xø43x50    | 0008903101                             | <b>TM37803</b> |
| 900 SPRINTER<br>906 SPRINTER   | Bearing, Shock Absorber<br>ø16xø72/133x119,5x46   | 9063230520<br>9063230320               | <b>TM27990</b> |
| 638 VITO<br>638 V-CLASS  | Bearing, Shock Absorber<br>ø14,3xø112x68          | 6383230420                             | <b>TM37804</b> |
| 638 VITO<br>638 V-CLASS  | Bearing, Shock Absorber<br>ø36xø106x44            | 6389810120                             | <b>TM37805</b> |
| 639 VIANO  | Rubber Bearing, Shock Absorber<br>ø16,5xø118,5x65 | 6393230520<br>6393230420<br>6393230120 | <b>TM37806</b> |
| 375 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3<br>963 ACTROS MP4<br>964 ACTROS MP4 | Screw, Shock Absorber                             | 910105016010<br>000000005540           | <b>TM37807</b> |










| TM No.  | Replaces Ref. No: | Description                            | Model / Details                   |
|---|-------------------|--|-----------------------------------|
| <b>TM15207</b><br>   | 4571304415        | Compressor                             | 375 AXOR                          |
|   | 4571302415        | Repl. Wabco: 412 352                   | 374 AXOR 2                        |
|   | 4571302615        | 014 0                                  | 940 AXOR 2                        |
|   | 4571304515        |  | 942 AXOR 2                        |
|   |                   |  | 943 AXOR 2                        |
|   |                   | 944 AXOR 2                             |                                   |
|   |                   | 386 LS 1625                            |                                   |
| <b>TM13737</b><br>   | 4571303615        | Compressor                             | 375 AXOR                          |
|   | 4571304815        | Repl. Wabco: 912 510                   | 944 AXOR 2                        |
|   | 4571303715        | 103 0                                  | 386 LS 1625                       |
|   | 4571304915        |  | 613 TOURISMO                      |
|   |                   |  | 634 CBC - FAHRGESTELL<br>2-ACHSER |
|   |                   | 634 CBC - FAHRGESTELL<br>OC500 CNG GAS |                                   |
|   |                   | 634 IBC FAHRGESTELL                    |                                   |
| <b>TM15201</b><br>   | 4571302915        | Compressor                             | 374 AXOR 2                        |
|   | 4571304715        | Repl. Wabco: 911 553                   | 944 AXOR 2                        |
|   | 4571305815        | 200 0                                  | 386 LS 1625                       |
|   | 4761300215        |  | 634 O 500                         |
|   |                   |  | 613 TOURISMO                      |
|   |                   | 634 IBC FAHRGESTELL<br>2-ACHSER        |                                   |
|   |                   | 634 IBC-FAHRGESTELL<br>2-ACHSER        |                                   |
| <b>TM15208</b><br> | 4571304615        | Compressor                             | 944 AXOR 2                        |
|   | 4571302015        | Repl. Wabco: 911 553                   | 613 TOURISMO                      |
|   |                   | 007 0                                  | 634 IBC FAHRGESTELL<br>2-ACHSER   |
| <b>TM15224</b><br> | 9061304715        | Compressor                             | 375 ATEGO 2                       |
|   | 9061305215        | Repl. Wabco: 411 553                   | 958 ATEGO 2                       |
|   | 9061301515        | 003 0                                  | 970 ATEGO 2                       |
|   | 9061301815        |  | 976 ATEGO 2                       |
|   |                   |  | 375 AXOR                          |
|   |                   | 374 AXOR 2                             |                                   |
|   |                   | 375 AXOR 2                             |                                   |
| <b>TM15205</b><br> | 4471302815        | Compressor                             | 671 O 345                         |
|   |                   |  |                                   |
| <b>TM15336</b><br> | 9061302515        | Compressor                             | 958 ATEGO 2                       |
|   | 9061302715        | Repl. Wabco: 912 510                   | 957 ECONIC                        |
|   | 9061304615        | 001 0                                  | 693 2423K/ 6X4                    |
|   |                   |  | 671 CONECTO                       |



| Model / Details   | Description                                 | Replaces Ref. No:                                    | TM No.  |
|---|---|--|---|
| 970 ATEGO 2<br>374 AXOR 2<br>950 AXOR 2<br>958 AXOR 2<br>957 ECONIC<br>685 OH SERIES<br>382 O 500   | Compressor<br>Repl. Wabco: 412 636<br>003 0 | 9061300915<br>9061302215<br>9061303215<br>9061304515 | <b>TM15206</b><br>   |
| 397 OF SERIES<br>397 1419 MBSA-RSA<br>397 1924 MBSA-RSA<br>397 1928 MBSA-RSA<br>397 2219 6X4 MBSA-RSA<br>397 2219 B/6X4 MB-<br>SA-RSA<br>397 2624 A/6X6 MB-<br>SA-RSA | Compressor                                  | 4071300515<br>4071301715<br>4961300015<br>4961300215 | <b>TM15465</b><br>   |
| 375 AXOR<br>374 AXOR 2<br>944 AXOR 2<br>613 TOURISMO<br>634 IBC FAHRGESTELL<br>2-ACHSER   | Compressor<br>Repl. Wabco: 412 352<br>010 0 | 4571300815<br>4571301115<br>4571301715               | <b>TM37808</b><br>   |
| 979 ACCELO<br>375 ATEGO<br>375 ATEGO 2<br>958 ATEGO 2<br>970 ATEGO 2<br>976 ATEGO 2<br>375 AXOR   | Compressor<br>Repl. Wabco: 411 154<br>000 0 | 9061301215<br>9061302915<br>9061304215               | <b>TM15197</b><br> |
| 958 ATEGO 2<br>976 ATEGO 2<br>958 AXOR 2<br>694 L 1218/1318/1319<br>695 L 1622/1624<br>979 LO 916 /45<br>384 OF SERIES  | Compressor<br>Repl. Wabco: 411 154<br>004 0 | 9061304915<br>9061305115<br>9061305315<br>9061306015 | <b>TM37809</b><br> |
| 375 ATEGO<br>970 ATEGO 2<br>375 AXOR<br>374 AXOR 2<br>375 AXOR 2<br>950 AXOR 2<br>673 LK/LN2  | Compressor<br>Repl. Wabco: 411 151<br>008 0 | 9061300715<br>9061301115<br>9061302815<br>9061304115 | <b>TM15226</b><br> |
| 979 ACCELO<br>375 ATEGO<br>970 ATEGO 2<br>976 ATEGO 2<br>375 AXOR<br>374 AXOR 2<br>375 AXOR 2   | Compressor<br>Repl. Wabco: 411 151<br>000 0 | 9061300615<br>9061310501                             | <b>TM15198</b><br> |





| TM No.  | Replaces Ref. No: | Description          | Model / Details     |
|---|-------------------|----------------------|---------------------|
| <b>TM15230</b><br>   | 9061301315        | Compressor           | 979 ACCELO          |
|   | 9061301415        | Repl. Wabco: 412 352 | 958 ATEGO 2         |
|   | 9061303015        | 025 0                | 970 ATEGO 2         |
|   | 9061304315        |                      | 374 AXOR 2          |
|   |                   |                      | 950 AXOR 2          |
|   |                   | 958 AXOR 2           |                     |
|   |                   | 957 ECONIC           |                     |
| <b>TM15227</b><br>   | 4571301815        | Compressor           | AXOR                |
|   | 9115530020        |                      |                     |
| <b>TM37810</b><br>   | 4571301215        | Compressor           | 375 AXOR            |
|   | 4571302215        | Repl. Wabco: 911 553 | 944 AXOR 2          |
|   | 4571301915        | 103 0                | 613 TOURISMO        |
|   | 4571302515        |                      | 634 IBC FAHRGESTELL |
|   |                   |                      | 2-ACHSER            |
| <b>TM15225</b><br> | 9061301615        | Compressor           | 958 ATEGO 2         |
|   |                   | Repl. Wabco: 412 636 | 957 ECONIC          |
|   |                   | 001 0                | 693 2423B/ 6X4      |
|   |                   |                      | 693 2423K/ 6X4      |
|   |                   |                      | 671 CONECTO         |
| <b>TM15209</b><br> | 9061305415        | Compressor           | 979 ACCELO          |
|   |                   | Repl. Wabco: 411 151 | 375 ACTROS          |
|   |                   | 009 0                | 375 ATEGO           |
|   |                   |                      | 970 ATEGO           |
|   |                   |                      | 972 ATEGO           |
|   |                   | 975 ATEGO            |                     |
|   |                   | 976 ATEGO            |                     |
| <b>TM37811</b><br> | 4471302015        | Compressor           | 357 O 405           |
|   |                   | Repl. Wabco: 447 130 |                     |
|   |                   | 201 5                |                     |
| <b>TM15337</b><br> | 4571306915        | Compressor           | 934 ACTROS 2/3      |
|   | 4571307215        | Repl. Wabco: 912 510 | 375 AXOR            |
|   |                   | 201 0                | 374 AXOR 2          |
|   |                   |                      | 940 AXOR 2          |
|   |                   |                      | 942 AXOR 2          |
|   |                   | 943 AXOR 2           |                     |
|   |                   | 944 AXOR 2           |                     |












| Model / Details   | Description                                 | Replaces Ref. No:                        | TM No.  |
|---|---|--|---|
| 375 ACTROS<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>375 ATEGO 2<br>958 ATEGO 2              | Compressor<br>Repl. Wabco: 912 510<br>005 0 | 9061306415<br>9061306715<br>9061306815   | <b>TM37812</b><br>   |
| 671 O 345   | Gear, Compressor                            | 4071321005<br>4071321105<br>4471320205   | <b>TM13889</b><br>   |
| 386 L 1625,1725<br>386 L 1633<br>386 LB 2325,2425<br>388 L 1929<br>388 L 1935<br>388 L 1938<br>388 L 1945 | Gear, Compressor<br>20T                     | 4661320005                               | <b>TM37813</b><br>   |
| 653 MK<br>621 NG<br>624 NG<br>645 NG<br>646 NG<br>647 NG<br>648 NG  | Hose, Compressor<br>ø30/ø35x275             | 4421341282                               | <b>TM15588</b><br> |
| 615 NG<br>616 NG<br>617 NG<br>619 NG<br>620 NG<br>621 NG<br>622 NG  | Hose, Compressor<br>ø21,5/ø31x140           | 4031340282                               | <b>TM15581</b><br> |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO               | Hose, Compressor<br>ø18xø26x1000            | 900271018038<br>9738320194<br>9738320294 | <b>TM35075</b><br> |
| 650 MK<br>651 MK<br>652 MK<br>653 MK<br>654 MK<br>617 NG<br>619 NG  | Hose, Compressor<br>ø24/ø30/ø35x378         | 4411340882                               | <b>TM15589</b><br> |












| TM No.  | Replaces Ref. No:                                      | Description   | Model / Details   |
|---|--|---|---|
| <b>TM08229</b><br>   | 6585010082<br>6205011682                               | Hose, Compressor<br>ø27/ø32x125                         | 957 ECONIC<br>620 NG<br>621 NG<br>622 NG<br>623 NG<br>624 NG<br>645 NG  |
| <b>TM02380</b><br>   | 4031340482<br>4031340182                               | Hose, Compressor<br>ø21/ø31x135                         | BM MODEL<br>363 LP 2226/6X4<br>363 LPB 2226/6X4<br>363 LPK 2226/6X4<br>363 LPS 2226/6X4<br>650 MK<br>651 MK<br>652 MK |
| <b>TM15582</b><br>   | 4969970082   | Hose, Compressor<br>ø21xø27x1000                        | 336 LP 1924<br>336 LPS 1924<br>338 L 1418<br>338 LK 1418<br>338 LP 1418<br>338 LPS 1418<br>338 LS 1418                |
| <b>TM23357</b><br> | 0119974746<br>0029972747<br>0099979746<br>003760025100 | Seal Ring, Compressor<br>ø25xø35x7 / NBR                | 336 LP 1924<br>336 LPS 1924<br>338 L 1418<br>338 LK 1418<br>338 LP 1418<br>338 LPS 1418<br>338 LS 1418                |
| <b>TM15694</b><br> | 0011301015   | Repair Kit, Compressor<br>Repl. Wabco: 412 352<br>002 2 | 958 AXOR 2<br>695 LS 1634EL<br>695 LS 1634EL 1635 S<br>696 L 1938<br>696 L 2638<br>696 LK 2638<br>696 LS 1938         |
| <b>TM37814</b><br> | -  | Repair Kit, Compressor                                  | -   |
| <b>TM37815</b><br> | -  | Repair Kit, Compressor                                  | -   |










| Model / Details   | Description            | Replaces Ref. No: | TM No.         |
|---|------------------------|-------------------|----------------|
| -   | Repair Kit, Compressor | 4021300220        | <b>TM37816</b> |
|   |                        |                   |                |
| -   | Repair Kit, Compressor | -                 | <b>TM37817</b> |
|   |                        |                   |                |
| -   | Repair Kit, Compressor | -                 | <b>TM37818</b> |
|   |                        |                   |                |
| 979 ACCELO<br>375 ACTROS<br>375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO | Repair Kit, Compressor | -                 | <b>TM37819</b> |
|   |                        |                   |                |
| 979 ACCELO<br>950 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>934 ACTROS 2/3            | Repair Kit, Compressor | -                 | <b>TM37820</b> |
|   |                        |                   |                |
| 979 ACCELO<br>375 ACTROS<br>375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO | Repair Kit, Compressor | -                 | <b>TM37821</b> |
|   |                        |                   |                |
| 979 ACCELO<br>375 ACTROS<br>375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO | Repair Kit, Compressor | -                 | <b>TM37822</b> |
|   |                        |                   |                |





| TM No.  | Replaces Ref. No: | Description                     | Model / Details   |
|---|-------------------|---------------------------------|---|
| <b>TM37823</b><br>   | 0001307315S       | Repair Kit, Compressor          | 696 L 1938  |
|   | 0011300415S       | Repl. Wabco: 911 153 933<br>2 S | 696 L 2638<br>693 1938<br>634 O 500<br>664 O 400 RSE BUGGY  |
| <b>TM37824</b><br>   | -                 | Repair Kit, Compressor          | 979 ACCELO<br>375 ACTROS<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>958 ATEGO 2   |
|   | -                 | Repair Kit, Compressor          | 375 AXOR<br>940 AXOR 2<br>944 AXOR 2<br>634 TOURO<br>671 CONECTO<br>613 TOURISMO<br>634 CBC - FAHRGESTELL<br>2-ACHSER                   |
| <b>TM37825</b><br>  | -                 | Repair Kit, Compressor          | 375 AXOR<br>940 AXOR 2<br>944 AXOR 2<br>634 TOURO<br>671 CONECTO<br>613 TOURISMO<br>634 CBC - FAHRGESTELL<br>2-ACHSER                   |
|   | -                 | Repair Kit, Compressor          | 375 AXOR<br>940 AXOR 2<br>944 AXOR 2<br>386 LS 1625<br>382 O 500<br>634 TOURO<br>613 TOURISMO   |
| <b>TM37826</b><br> | -                 | Repair Kit, Compressor          | 375 AXOR<br>940 AXOR 2<br>944 AXOR 2<br>386 LS 1625<br>382 O 500<br>634 TOURO<br>613 TOURISMO   |
|   | -                 | Repair Kit, Compressor          | 375 AXOR<br>374 AXOR 2<br>940 AXOR 2<br>942 AXOR 2<br>943 AXOR 2<br>944 AXOR 2<br>386 LS 1625   |
| <b>TM37827</b><br> | -                 | Repair Kit, Compressor          | 375 AXOR<br>374 AXOR 2<br>940 AXOR 2<br>942 AXOR 2<br>943 AXOR 2<br>944 AXOR 2<br>386 LS 1625   |
|   | -                 | Repair Kit, Compressor          | 944 AXOR 2<br>634 TOURO<br>671 CONECTO<br>613 TOURISMO<br>634 CBC - FAHRGESTELL<br>2-ACHSER<br>634 IBC 1836 / OC 500 RF<br>634 IBC 1842 |
| <b>TM37828</b><br> | -                 | Repair Kit, Compressor          | 944 AXOR 2<br>634 TOURO<br>671 CONECTO<br>613 TOURISMO<br>634 CBC - FAHRGESTELL<br>2-ACHSER<br>634 IBC 1836 / OC 500 RF<br>634 IBC 1842 |
|   | -                 | Repair Kit, Compressor          | -   |
| <b>TM37829</b><br> | -                 | Repair Kit, Compressor          | -   |
|   | -                 | Repl. Wabco: 411 553 923<br>2 S | -   |



| Model / Details  | Description   | Replaces Ref. No: | TM No.  |
|--|---|-------------------|---|
| -  | Repair Kit, Compressor                                  | -                 | <b>TM37830</b><br>   |
| 671 O 345  | Repair Kit, Compressor                                  | -                 | <b>TM37831</b><br>   |
| 958 ATEGO 2<br>957 ECONIC<br>693 2423B/ 6X4<br>693 2423K/ 6X4<br>671 CONECTO | Repair Kit, Compressor                                  | -                 | <b>TM37832</b><br>  |
| -  | Repair Kit, Compressor                                  | -                 | <b>TM37833</b><br> |
| -  | Repair Kit, Compressor                                  | -                 | <b>TM37834</b><br> |
| -  | Repair Kit, Compressor<br>Repl. Wabco: 912 510<br>935 2 | -                 | <b>TM37835</b><br> |
| -  | Repair Kit, Compressor                                  | -                 | <b>TM37836</b><br> |












| TM No.             | Replaces Ref. No: | Description   | Model / Details |
|--------------------|-------------------|---|-----------------|
| <b>TM37837</b><br> | -                 | Repair Kit, Compressor                                  | -               |
| <b>TM37838</b><br> | -                 | Repair Kit, Compressor<br>Repl. Wabco: 411 151<br>925 2 | -               |
| <b>TM37839</b><br> | -                 | Repair Kit, Compressor<br>Repl. Wabco: 411 154<br>003 2 | -               |
| <b>TM37840</b><br> | -                 | Repair Kit, Compressor                                  | -               |
| <b>TM37841</b><br> | -                 | Repair Kit, Compressor                                  | -               |
| <b>TM37842</b><br> | -                 | Repair Kit, Compressor                                  | -               |
| <b>TM37843</b><br> | -                 | Repair Kit, Compressor                                  | -               |



















| Model / Details  | Description   | Replaces Ref. No:                                    | TM No.  |
|--|---|--|---|
| -  | Repair Kit, Compressor  | -  | <b>TM37844</b>  |
|  |   |  |    |
| 375 AXOR<br>374 AXOR 2<br>940 AXOR 2<br>942 AXOR 2<br>943 AXOR 2<br>944 AXOR 2<br>386 LS 1625          | Gasket Kit, Compressor<br>Complete<br>Repl. Wabco: 412 352<br>923 2 | 0011302615   | <b>TM15732</b>  |
|  |   |  |    |
| 979 ACCELO<br>375 ATEGO<br>375 ATEGO 2<br>958 ATEGO 2<br>970 ATEGO 2<br>976 ATEGO 2<br>375 AXOR        | Gasket Kit, Compressor<br>Repl. Wabco: 411 154<br>000 2             | 0001306815   | <b>TM15690</b>  |
|  |   |  |   |
| 979 ACCELO<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3 | Pipe, Compressor  | 5410100855   | <b>TM37845</b>  |
|  |   |  |  |
| 979 ACCELO<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3 | Pipe, Compressor  | 5412000452<br>5412000852<br>5412001652<br>5412001952 | <b>TM37846</b>  |
|  |   |  |  |
| 979 ACCELO<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3 | Pipe, Compressor  | 5412000552<br>5412000952                             | <b>TM37847</b>  |
|  |   |  |  |
| 979 ACCELO<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3 | Pipe, Compressor  | 5412001052   | <b>TM37848</b>  |
|  |   |  |  |












| TM No.  | Replaces Ref. No: | Description  | Model / Details     |
|---|-------------------|--|---------------------|
| <b>TM08427</b><br>   | 5412001252        | Pipe, Compressor   | 979 ACCELO          |
|   | 5412003552        |  | 950 ACTROS          |
|   |                   |  | 952 ACTROS          |
|   |                   |  | 953 ACTROS          |
|   |                   |  | 954 ACTROS          |
|   |                   |  | 930 ACTROS 2/3      |
|   |                   |  | 932 ACTROS 2/3      |
| <b>TM37849</b><br>   | 5412001352        | Pipe, Compressor   | 979 ACCELO          |
|   | 5412001852        |  | 950 ACTROS          |
|   |                   |  | 952 ACTROS          |
|   |                   |  | 953 ACTROS          |
|   |                   |  | 954 ACTROS          |
|   |                   |  | 930 ACTROS 2/3      |
|   |                   |  | 932 ACTROS 2/3      |
| <b>TM37850</b><br>  | 5412001752        | Pipe, Compressor   | 979 ACCELO          |
|   | 5412002052        |  | 950 ACTROS          |
|   |                   |  | 952 ACTROS          |
|   |                   |  | 953 ACTROS          |
|   |                   |  | 954 ACTROS          |
|   |                   |  | 930 ACTROS 2/3      |
|   |                   |  | 932 ACTROS 2/3      |
| <b>TM37851</b><br> | 9404202026        | Pipe, Compressor   | 374 AXOR 2          |
|   |                   |  | 375 AXOR            |
|   |                   |  | 940 AXOR 2          |
|   |                   |  | 942 AXOR 2          |
|   |                   |  | 943 AXOR 2          |
|   |                   |  | 944 AXOR 2          |
| <b>TM05217</b><br> | 0001320710        | Follower, Compressor                                       | 336 LP 1924         |
|   | 0001320310        |  | 336 LPS 1924        |
|   |                   |  | 343 T2/L            |
|   |                   |  | 343 T2/LN1          |
|   |                   |  | 345 L 1418 MBTC-USA |
|   |                   |  | 345 L 1519          |
|   |                   |  | 345 L 1519,1520     |
| <b>TM37852</b><br> | 51541006043       | Cylinder Head<br>Complete<br>Repl. Wabco: 411 151<br>920 2 | 696 L 1938          |
|   |                   |  | 696 L 2638          |
|   |                   |  | 696 LK 2638         |
|   |                   |  | 696 LS 1938         |
|   |                   |  | 696 LS 2638         |
|   |                   |  | 693 1938            |
|   |                   |  | 693 1938 S          |
| <b>TM15276</b><br> | 0001312121        | Cylinder Head<br>Upper<br>Repl. Wabco: 411 151<br>651 4    | 979 ACCELO          |
|   | 0001312221        |  | 375 ACTROS          |
|   |                   |  | 375 ATEGO           |
|   |                   |  | 970 ATEGO           |
|   |                   |  | 972 ATEGO           |
|   |                   |  | 975 ATEGO           |
|   |                   |  | 976 ATEGO           |










| Model / Details   | Description  | Replaces Ref. No:          | TM No.  |
|---|--|----------------------------|---|
| 979 ACCELO<br>375 ACTROS<br>375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO   | Cylinder Head<br>Lower<br>Repl. Wabco: 411 151<br>652 2    | 0001310909<br>0001310809   | <b>TM15052</b><br>   |
| 375 AXOR<br>374 AXOR 2<br>940 AXOR 2<br>942 AXOR 2<br>943 AXOR 2<br>944 AXOR 2<br>386 LS 1625   | Cylinder Head<br>Complete<br>Repl. Wabco: 412 352<br>922 2 | 0011301215<br>0011305219   | <b>TM15266</b><br>   |
| 958 ATEGO 2<br>976 ATEGO 2<br>694 L 1218 R<br>694 L 1218/1318/1319<br>694 LK 1218 - 1318 -<br>1319/42<br>695 L 1622 / L 1620<br>695 L 1622/1624 | Cylinder Head<br>Complete                                  | 0001315119<br>0001315319   | <b>TM15184</b><br>  |
| -   | Cylinder Head<br>Complete                                  | 0001304119S<br>0001303919S | <b>TM37853</b><br> |
| -   | Cylinder Head<br>With Plate                                | -                          | <b>TM37854</b><br> |
| 375 AXOR<br>958 AXOR 2<br>386 LS 1625<br>382 O 500<br>613 TOURISMO<br>634 IBC-FAHRGESTELL<br>2-ACHSER   | Cylinder Head<br>Complete<br>Repl. Wabco: 912 510<br>920 2 | 0011304715                 | <b>TM15319</b><br> |
| 374 AXOR 2<br>944 AXOR 2<br>386 LS 1625<br>613 TOURISMO<br>634 IBC FAHRGESTELL<br>2-ACHSER<br>634 IBC-FAHRGESTELL<br>2-ACHSER<br>634 IBC-       | Cylinder Head<br>Complete<br>Repl. Wabco: 911 553<br>924 2 | 0011302515                 | <b>TM15182</b><br> |





| TM No.  | Replaces Ref. No:          | Description  | Model / Details  |
|---|----------------------------|--|--|
| <b>TM15181</b><br>   | 0011301615                 | Cylinder Head<br>Complete<br>Repl. Wabco: 911 553<br>921 2   | 944 AXOR 2<br>613 TOURISMO<br>634 IBC FAHRGESTELL<br>2-ACHSER  |
| <b>TM15692</b><br>   | 0011303015                 | Cylinder Head<br>Complete<br>Repl. Wabco: 411 553<br>921 2   | BM MODEL<br>375 ATEGO 2<br>958 ATEGO 2<br>970 ATEGO 2<br>976 ATEGO 2<br>375 AXOR<br>374 AXOR 2<br>375 AXOR 2 |
| <b>TM37855</b><br>  | 4421310519                 | Cylinder Head  | 671 O 345  |
| <b>TM37856</b><br> | 0011311415<br>0011313715   | Cylinder Head<br>Complete<br>Repl. Wabco: 912 510<br>922 2   | 958 ATEGO 2<br>957 ECONIC<br>693 2423B/ 6X4<br>693 2423K/ 6X4<br>671 CONECTO                                 |
| <b>TM15179</b><br> | 0001315519                 | Cylinder Head<br>Complete<br>Repl. Wabco: 412 636 001<br>2 S | 970 ATEGO 2<br>374 AXOR 2<br>950 AXOR 2<br>958 AXOR 2<br>957 ECONIC<br>685 OH SERIES<br>382 O 500            |
| <b>TM14974</b><br> | 5411310919<br>5411311219   | Cylinder Head  | 979 ACCELO<br>950 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>934 ACTROS 2/3                               |
| <b>TM37857</b><br> | 5411310619S<br>5411311119S | Cylinder Head  | 979 ACCELO<br>950 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>934 ACTROS 2/3                               |



| Model / Details   | Description  | Replaces Ref. No:        | TM No.  |
|---|--|--------------------------|---|
| 979 ACCELO<br>950 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>934 ACTROS 2/3  | Cylinder Head  | -                        | <b>TM37858</b>  |
|   |  |                          |    |
| 979 ACCELO<br>375 ATEGO<br>970 ATEGO 2<br>976 ATEGO 2<br>375 AXOR<br>374 AXOR 2<br>375 AXOR 2   | Cylinder Head<br>Complete<br>Repl. Wabco: 411 151 800<br>2 S | 0001314919               | <b>TM15314</b>  |
|   |  |                          |    |
| 979 ACCELO<br>375 ATEGO<br>375 ATEGO 2<br>958 ATEGO 2<br>970 ATEGO 2<br>976 ATEGO 2<br>375 AXOR                                       | Cylinder Head<br>Complete<br>Repl. Wabco: 412 352<br>801 2   | 0001315419               | <b>TM15315</b>  |
|   |  |                          |    |
| 375 AXOR<br>374 AXOR 2<br>942 AXOR 2<br>944 AXOR 2<br>386 LS 1625<br>613 TOURISMO<br>634 IBC-FAHRGESTELL<br>2-ACHSER                  | Cylinder Head<br>Complete<br>Repl. Wabco: 911 553<br>001 2   | 0011300815<br>0011305915 | <b>TM15696</b>  |
|   |  |                          |  |
| -   | Cylinder Head<br>Complete                                    | 4421317119               | <b>TM37859</b>  |
|   |  |                          |  |
| -   | Cylinder Head<br>Complete                                    | 4421303419               | <b>TM15267</b>  |
|   |  |                          |  |
| 386 L 1625,1725<br>386 L 1633<br>386 L 2325,2425,LA<br>2425/6X6<br>386 LB 2325,2425<br>386 LK 2325,2425<br>386 LS 1630<br>386 LS 1633 | Cylinder Head  | 4071300519               | <b>TM13905</b>  |
|   |  |                          |  |












| TM No.         | Replaces Ref. No:                      | Description  | Model / Details   |
|----------------|--|--|---|
| <b>TM37860</b> | -                                      | Cylinder Head<br>Complete                                  | -   |
|                |  |  |   |
| <b>TM15317</b> | 0011315619                             | Cylinder Head<br>Complete<br>Repl. Wabco: 412 636<br>920 2 | -   |
|                |  |  |   |
| <b>TM37861</b> | -                                      | Cylinder Head<br>Complete<br>Repl. Wabco: 912 510 930      | -   |
|                |  |  |   |
| <b>TM37862</b> | -                                      | Cylinder Head<br>Complete<br>Repl. Wabco: 912 510<br>934 2 | -   |
|                |  |  |   |
| <b>TM37863</b> | -                                      | Disc, Cylinder Head  | 375 AXOR<br>374 AXOR 2<br>940 AXOR 2<br>942 AXOR 2<br>943 AXOR 2<br>944 AXOR 2<br>634 TOURO   |
|                |  |  |   |
| <b>TM37864</b> | -                                      | Disc, Cylinder Head  | 375 AXOR<br>940 AXOR 2<br>944 AXOR 2<br>386 LS 1625<br>382 O 500<br>634 TOURO<br>613 TOURISMO |
|                |  |  |   |
| <b>TM13909</b> | 4411300120<br>4411300220<br>4421300620 | Disc, Cylinder Head  | 650 MK<br>651 MK<br>652 MK<br>653 MK<br>615 NG<br>617 NG<br>619 NG                            |
|                |  |  |   |












| Model / Details   | Description  | Replaces Ref. No:        | TM No.  |
|---|--|--------------------------|---|
| 671 O 345   | Disc, Cylinder Head  | -                        | <b>TM37865</b><br>   |
| -   | Disc, Cylinder Head  | -                        | <b>TM37866</b><br>   |
| 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3                          | Disc, Cylinder Head  | -                        | <b>TM37867</b><br>   |
| 958 ATEGO 2<br>957 ECONIC<br>693 2423B/ 6X4<br>693 2423K/ 6X4<br>671 CONECTO                  | Disc, Cylinder Head  | -                        | <b>TM37868</b><br> |
| 979 ACCELO<br>950 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>934 ACTROS 2/3                | Disc, Cylinder Head<br>Repl. Knorr: II38147F0064           | 5411300820               | <b>TM15051</b><br> |
| 375 AXOR<br>374 AXOR 2<br>940 AXOR 2<br>942 AXOR 2<br>943 AXOR 2<br>944 AXOR 2<br>386 LS 1625 | Gasket Kit, Cylinder Head<br>Repl. Wabco: 911 553<br>925 2 | 0011302315<br>0011302815 | <b>TM15697</b><br> |
| 375 ACTROS<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>958 ATEGO 2<br>970 ATEGO 2  | Gasket Kit, Cylinder Head<br>Repl. Wabco: 412 636<br>921 2 | 0011303515               | <b>TM15806</b><br> |












| TM No.  | Replaces Ref. No:                      | Description  | Model / Details  |
|---|--|--|--|
| <b>TM37869</b><br>   | -                                      | Gasket Kit, Cylinder Head<br>Repl. Wabco: 912 510<br>921 2 | -  |
| <b>TM37870</b><br>   | -                                      | Gasket Kit, Cylinder Head                                  | -  |
| <b>TM37871</b><br>  | -                                      | Gasket Kit, Cylinder Head<br>Repl. Wabco: 912 510<br>931 2 | -  |
| <b>TM37872</b><br> | -                                      | Repair Kit, Cylinder Head<br>Repl. Wabco: 912 510<br>929 2 | -  |
| <b>TM37873</b><br> | -                                      | Repair Kit, Cylinder Head                                  | -  |
| <b>TM37874</b><br> | -                                      | Repair Kit, Cylinder Head                                  | -  |
| <b>TM13906</b><br> | 4421300220<br>4421300020<br>4071300120 | Plate Kit, Cylinder Head                                   | 650 MK<br>651 MK<br>652 MK<br>653 MK<br>654 MK<br>615 NG<br>616 NG |












| Model / Details   | Description                 | Replaces Ref. No:        | TM No.  |
|---|-----------------------------|--------------------------|---|
| 979 ACCELO<br>950 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>934 ACTROS 2/3  | Plate Kit, Cylinder Head    | 5411300620               | <b>TM14975</b>  |
|   |                             |                          |    |
| 671 O 345   | Plate Kit, Cylinder Head    | 4421301120               | <b>TM15726</b>  |
|   |                             |                          |    |
| 386 L 1625,1725<br>386 L 1633<br>386 L 2325,2425,LA<br>2425/6X6<br>386 LB 2325,2425<br>386 LK 2325,2425<br>386 LS 1630<br>386 LS 1633             | Plate Kit, Cylinder Head    | 4421300720               | <b>TM14945</b>  |
|   |                             |                          |   |
| BM MODEL<br>386 L 1625,1725<br>386 L 1633<br>386 L 2325,2425,LA<br>2425/6X6<br>386 LB 2325,2425<br>386 LK 2325,2425<br>386 LS 1630<br>386 LS 1633 | Cylinder Block              | 4471310315               | <b>TM37875</b>  |
|   |                             |                          |  |
| 363 LP 2226/6X4<br>363 LP 2232/6X4<br>363 LPB 2226/6X4<br>363 LPK 2226/6X4<br>363 LPK 2232/6X4<br>363 LPS 2226/6X4<br>363 LPS 2232/6X4            | Crank Shaft, Cylinder Block | 4031310716               | <b>TM13877</b>  |
|   |                             |                          |  |
| -   | Crank Shaft, Cylinder Block | -                        | <b>TM37876</b>  |
|   |                             |                          |  |
| 979 ACCELO<br>950 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>934 ACTROS 2/3  | Crank Shaft, Cylinder Block | 5411300014<br>5411300214 | <b>TM37877</b>  |
|   |                             |                          |  |












| TM No.  | Replaces Ref. No:                      | Description  | Model / Details  |
|---|--|--|--|
| <b>TM13884</b><br>   | 0001314250<br>4031310450               | Bushing, Cylinder Block  | 363 LP 2226/6X4<br>363 LP 2232/6X4<br>363 LPB 2226/6X4<br>363 LPK 2226/6X4<br>363 LPK 2232/6X4<br>363 LPS 2226/6X4<br>363 LPS 2232/6X4 |
| <b>TM14954</b><br>   | 4421310050                             | Bushing, Cylinder Block  | 979 ACCELO<br>950 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>934 ACTROS 2/3<br>650 MK<br>651 MK                                     |
| <b>TM37878</b><br>  | 0009925229<br>9069920325               | Bushing, Cylinder Block  | 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS<br>967 ATEGO 3<br>405 UNIMOG  |
| <b>TM37879</b><br> | 0001312321                             | Cover, Cylinder Block<br>Bottom<br>Repl. Wabco: 895 073<br>589 4 | 979 ACCELO<br>375 ACTROS<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>958 ATEGO 2  |
| <b>TM15286</b><br> | 0001312932                             | Cover, Cylinder Block<br>Repl. Wabco: 411 147<br>603 4           | 375 AXOR<br>374 AXOR 2<br>940 AXOR 2<br>942 AXOR 2<br>943 AXOR 2<br>944 AXOR 2<br>634 TOURO  |
| <b>TM14383</b><br> | 4031301645                             | Cover, Cylinder Block<br>Cast Iron                               | -  |
| <b>TM13907</b><br> | 4421300145<br>4421300445<br>4421311342 | Cover, Cylinder Block  | 650 MK<br>651 MK<br>652 MK<br>653 MK<br>615 NG<br>617 NG<br>619 NG   |



| Model / Details  | Description  | Replaces Ref. No:          | TM No.  |
|--|--|----------------------------|---|
| 979 ACCELO<br>950 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>934 ACTROS 2/3   | Cover, Cylinder Block  | 5411310142<br>5411310242   | <b>TM14036</b><br>   |
| 671 O 345  | Cover, Cylinder Block  | 4471300045                 | <b>TM05489</b><br>   |
| 375 AXOR<br>374 AXOR 2<br>942 AXOR 2<br>944 AXOR 2<br>958 AXOR 2<br>386 LS 1625<br>695 LS 1634EL   | Gasket, Cylinder Block   | 4571310180                 | <b>TM14693</b><br>   |
| 386 LB 2318,2418<br>397 LP 1014 MBSA-RSA<br>397 LP 1114,1214 MB-SA-RSA<br>397 LP/LPK 1314 MB-SA-RSA<br>397 LPK 1414 MBSA-RSA<br>615 LK/LN2<br>673 LK/LN2 | Piston<br>Without Ring<br>Repl. Knorr: SEB22539 S<br>ø75 / PD: 18x63 / CT:<br>2x2x4            | 0001302217S                | <b>TM37880</b><br> |
| -  | Piston<br>Without Ring<br>ø75+0,25 / PD: 18x63 /<br>CT: 2x2x4                                  | -                          | <b>TM37881</b><br> |
| -  | Piston<br>Without Ring<br>Repl. Knorr: SEB22515 S<br>ø75+0,50 / PD: 18x63 /<br>CT: 2x2x4       | -                          | <b>TM37882</b><br> |
| 685 L 1218<br>685 L 1418<br>685 L 1618<br>685 LK 1418<br>688 LO 914/42,5<br>688 LO 915/48<br>694 L 1218 R  | Piston<br>Without Ring<br>Repl. Wabco: 911 501 624<br>2 S<br>ø85 / PD: 19,05x60 /<br>CT: 2x2x4 | 0001303417S<br>0001305317S | <b>TM37883</b><br> |












| TM No.  | Replaces Ref. No:  | Description  | Model / Details  |
|---|--|--|--|
| <b>TM37884</b><br>   | -  | Piston<br>Without Ring<br>ø85+0,25 / PD:<br>19,05x60 / CT: 2x2x4                         | 685 L 1218<br>685 L 1418<br>685 L 1618<br>685 LK 1418<br>688 LO 914/42,5<br>688 LO 915/48<br>694 L 1218 R                              |
| <b>TM37885</b><br>   | -  | Piston<br>Without Ring<br>ø85+0,50 / PD:<br>19,05x60 / CT: 2x2x4                         | 685 L 1218<br>685 L 1418<br>685 L 1618<br>685 LK 1418<br>688 LO 914/42,5<br>688 LO 915/48<br>694 L 1218 R                              |
| <b>TM37886</b><br>   | 0001302517S  | Piston<br>Without Ring<br>Repl. Knorr: I81169004 S<br>ø88 / PD: 18x63 / CT:<br>2,5x2,5x4 | 343 T2/L<br>343 T2/LN1<br>346 L 1924<br>346 L 1928<br>346 LA 1924<br>346 LAK 1924<br>346 LAS 1924                                      |
| <b>TM37887</b><br> | -  | Piston<br>Without Ring<br>ø88+0,25 / PD: 18x63 /<br>CT: 2,5x2,5x4                        | 343 T2/L<br>343 T2/LN1<br>346 L 1924<br>346 L 1928<br>346 LA 1924<br>346 LAK 1924<br>346 LAS 1924                                      |
| <b>TM37888</b><br> | -  | Piston<br>Without Ring<br>ø88+0,50 / PD: 18x63 /<br>CT: 2,5x2,5x4                        | 343 T2/L<br>343 T2/LN1<br>346 L 1924<br>346 L 1928<br>346 LA 1924<br>346 LAK 1924<br>346 LAS 1924                                      |
| <b>TM37889</b><br> | 4031310002S<br>4031300117S<br>4031300008S<br>4421300008S | Piston<br>Without Ring<br>ø90 / PD: 20x60 / CT:<br>2,5x2,5x2,5x4                         | 363 LP 2226/6X4<br>363 LP 2232/6X4<br>363 LPB 2226/6X4<br>363 LPK 2226/6X4<br>363 LPK 2232/6X4<br>363 LPS 2226/6X4<br>363 LPS 2232/6X4 |
| <b>TM37890</b><br> | -  | Piston<br>Without Ring<br>ø90+0,50 / PD: 20x60 /<br>CT: 2,5x2,5x2,5x4                    | 363 LP 2226/6X4<br>363 LP 2232/6X4<br>363 LPB 2226/6X4<br>363 LPK 2226/6X4<br>363 LPK 2232/6X4<br>363 LPS 2226/6X4<br>363 LPS 2232/6X4 |



















| Model / Details  | Description                                      | Replaces Ref. No: | TM No.  |
|--|--|-------------------|---|
| 363 LP 2226/6X4<br>363 LP 2232/6X4<br>363 LPB 2226/6X4<br>363 LPK 2226/6X4<br>363 LPK 2232/6X4<br>363 LPS 2226/6X4<br>363 LPS 2232/6X4 | Piston<br>Without Ring                           | -                 | <b>TM37891</b><br>   |
| -  | Piston<br>Without Ring<br>Repl. Knorr: K006026 S | -                 | <b>TM37892</b><br>   |
| -  | Piston<br>Without Ring                           | -                 | <b>TM37893</b><br>  |
| -  | Piston<br>Without Ring                           | -                 | <b>TM37894</b><br> |
| 979 ACCELO<br>314 LP<br>316 LP<br>318 LP<br>341 L 1114<br>341 L 914<br>341 LA 1114   | Piston<br>Without Ring                           | 3521300108S       | <b>TM37895</b><br> |
| BM MODEL<br>979 ACCELO<br>314 LP<br>316 LP<br>318 LP<br>341 L 1114<br>341 L 914<br>341 LA 1114   | Piston<br>Without Ring                           | -                 | <b>TM37896</b><br> |
| 979 ACCELO<br>314 LP<br>316 LP<br>318 LP<br>341 L 1114<br>341 L 914<br>341 LA 1114   | Piston<br>Without Ring                           | -                 | <b>TM37897</b><br> |





| TM No.  | Replaces Ref. No: | Description  | Model / Details            |
|---|-------------------|--|----------------------------|
| <b>TM15166</b><br>   | 0001312517        | Connecting Rod, Piston<br>Repl. Wabco: 412 352<br>928 2    | 979 ACCELO                 |
|   | 0001312917        |  | 375 ACTROS                 |
|   |                   |  | 375 ATEGO                  |
|   |                   |  | 970 ATEGO                  |
|   |                   |  | 972 ATEGO                  |
|   |                   |  | 975 ATEGO                  |
|   |                   |  | 976 ATEGO                  |
| <b>TM15168</b><br>   | 0001312717        | Connecting Rod, Piston<br>Repl. Wabco: 411 151<br>928 2    | 979 ACCELO                 |
|   |                   |  | 375 ACTROS                 |
|   |                   |  | 375 ATEGO                  |
|   |                   |  | 970 ATEGO                  |
|   |                   |  | 972 ATEGO                  |
|   |                   |  | 975 ATEGO                  |
|   |                   |  | 976 ATEGO                  |
| <b>TM15167</b><br>  | 0001312417        | Connecting Rod, Piston<br>Repl. Wabco: 912 512<br>929 2    | 375 ACTROS                 |
|   |                   |  | 375 ATEGO                  |
|   |                   |  | 970 ATEGO                  |
|   |                   |  | 972 ATEGO                  |
|   |                   |  | 975 ATEGO                  |
|   |                   |  | 976 ATEGO                  |
|   |                   |  | 375 ATEGO 2                |
| <b>TM14955</b><br> | 5411310117        | Connecting Rod, Piston                                     | 979 ACCELO                 |
|   | 5411310017        |  | 950 ACTROS                 |
|   | 4421310217        |  | 952 ACTROS                 |
|   | 4421310017        |  | 953 ACTROS                 |
|   |                   |  | 954 ACTROS                 |
|   |                   |  | 930 ACTROS 2/3             |
|   |                   |  | 932 ACTROS 2/              |
| <b>TM13880</b><br> | 4031302816        | Connecting Rod, Piston                                     | 363 LP 2226/6X4            |
|   | 4031303616        |  | 363 LP 2232/6X4            |
|   | 4031302216        |  | 363 LPB 2226/6X4           |
|   |                   |  | 363 LPK 2226/6X4           |
|   |                   |  | 363 LPK 2232/6X4           |
|   |                   |  | 363 LPS 2226/6X4           |
|   |                   |  | 363 LPS 2232/6X4           |
| <b>TM37898</b><br> | 0001318811        | Ring Kit, Piston<br>Repl. Knorr: I801770061<br>ø75 / 2x2x4 | 397 LP 1014 MBSA-RSA       |
|   |                   |  | 397 LP 1114,1214 MB-SA-RSA |
|   |                   |  | 397 LP/LPK 1314 MB-SA-RSA  |
|   |                   |  | 397 LPK 1414 MBSA-RSA      |
|   |                   |  | 615 LK/LN2                 |
|   |                   |  | 673 LK/LN2                 |
|   |                   |  | 674 LK/LN2                 |
| <b>TM37899</b><br> | -                 | Ring Kit, Piston<br>ø75+0,25 / 2x2x4                       | 397 LP 1014 MBSA-RSA       |
|   |                   |  | 397 LP 1114,1214 MB-SA-RSA |
|   |                   |  | 397 LP/LPK 1314 MB-SA-RSA  |
|   |                   |  | 397 LPK 1414 MBSA-RSA      |
|   |                   |  | 615 LK/LN2                 |
|   |                   |  | 673 LK/LN2                 |
|   |                   |  | 674 LK/LN2                 |










| Model / Details  | Description  | Replaces Ref. No: | TM No.  |
|--|--|-------------------|---|
| 397 LP 1014 MBSA-RSA<br>397 LP 1114,1214 MB-SA-RSA<br>397 LP/LPK 1314 MB-SA-RSA<br>397 LPK 1414 MBSA-RSA<br>615 LK/LN2<br>673 LK/LN2<br>674 LK/LN2 | Ring Kit, Pisto  | -                 | <b>TM37900</b><br>   |
| 979 ACCELO<br>375 ACTROS<br>375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO  | Ring Kit, Piston<br>Repl. Wabco: 911 501<br>920 2<br>ø85 / 2x2x4   | 0011311111        | <b>TM15684</b><br>   |
| BM MODEL<br>979 ACCELO<br>375 ACTROS<br>375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO  | Ring Kit, Piston   | -                 | <b>TM37901</b><br>  |
| 979 ACCELO<br>375 ACTROS<br>375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO  | Ring Kit, Piston   | -                 | <b>TM37902</b><br> |
| 397 LP 1014 MBSA-RSA<br>397 LP 1114,1214 MB-SA-RSA<br>397 LP/LPK 1314 MB-SA-RSA<br>397 LPK 1414 MBSA-RSA<br>615 LK/LN2<br>673 LK/LN2<br>674 LK/LN2 | Ring Kit, Piston<br>Repl. Knorr: I811690062  | 0011310611        | <b>TM14614</b><br> |
| 397 LP 1014 MBSA-RSA<br>397 LP 1114,1214 MB-SA-RSA<br>397 LP/LPK 1314 MB-SA-RSA<br>397 LPK 1414 MBSA-RSA<br>615 LK/LN2<br>673 LK/LN2<br>674 LK/LN2 | Ring Kit, Piston   | -                 | <b>TM37903</b><br> |
| 397 LP 1014 MBSA-RSA<br>397 LP 1114,1214 MB-SA-RSA<br>397 LP/LPK 1314 MB-SA-RSA<br>397 LPK 1414 MBSA-RSA<br>615 LK/LN2<br>673 LK/LN2<br>674 LK/LN2 | 397 LP 1014 MBSA-RSA<br>397 LP 1114,1214 MB-SA-RSA<br>397 LP/LPK 1314 MB-SA-RSA<br>397 LPK 1414 MBSA-RSA<br>615 LK/LN2<br>673 LK/LN2<br>674 LK/LN2 | -                 | <b>TM37904</b><br> |





| TM No.             | Replaces Ref. No: | Description                   | Model / Details     |
|--------------------|-------------------|-------------------------------|---------------------|
| <b>TM37905</b><br> | 0001318011S       | Ring Kit, Piston              | 363 LP 2226/6X4     |
|                    | 0001316511S       | ø90 / 2,5x2,5x4               | 363 LP 2232/6X4     |
|                    | 0001318611S       |                               | 363 LPB 2226/6X4    |
|                    | 0001315611S       |                               | 363 LPK 2226/6X4    |
|                    |                   |                               |                     |
|                    |                   |                               | 363 LPS 2226/6X4    |
|                    |                   |                               | 363 LPS 2232/6X4    |
| <b>TM37906</b><br> | -                 | Ring Kit, Piston              | 363 LP 2226/6X4     |
|                    |                   | ø90+0,50 / 2,5x2,5x4          | 363 LP 2232/6X4     |
|                    |                   |                               | 363 LPB 2226/6X4    |
|                    |                   |                               | 363 LPK 2226/6X4    |
|                    |                   |                               | 363 LPK 2232/6X4    |
|                    |                   |                               | 363 LPS 2226/6X4    |
|                    |                   |                               | 363 LPS 2232/6X4    |
| <b>TM37907</b><br> | -                 | Ring Kit, Piston              | 363 LP 2226/6X4     |
|                    |                   | ø90+1,00 / 2,5x2,5x4          | 363 LP 2232/6X4     |
|                    |                   |                               | 363 LPB 2226/6X4    |
|                    |                   |                               | 363 LPK 2226/6X4    |
|                    |                   |                               | 363 LPK 2232/6X4    |
|                    |                   |                               | 363 LPS 2226/6X4    |
|                    |                   | 363 LPS 2232/6X4              |                     |
| <b>TM37908</b><br> | 0001318211S       | Ring Kit, Piston              | 345 L 1418 MBTC-USA |
|                    |                   | Repl. Wabco: 411 042 001      | 345 L 1519          |
|                    |                   | 2 S                           | 345 L 1519,1520     |
|                    |                   | ø90 / 2,5x2,5x2,5x4           | 345 L 2219,2220     |
|                    |                   |                               | 345 L 2225          |
|                    |                   |                               | 345 LB 2219,2220    |
|                    |                   | 345 LG 1819/1820              |                     |
| <b>TM37909</b><br> | 0001318311S       | Ring Kit, Piston              | 345 L 1418 MBTC-USA |
|                    |                   | Repl. Wabco: 411 042 002      | 345 L 1519          |
|                    |                   | 2 S                           | 345 L 1519,1520     |
|                    |                   | ø90+0,50 / 2,5x2,5x-<br>2,5x4 | 345 L 2219,2220     |
|                    |                   |                               | 345 L 2225          |
|                    |                   |                               | 345 LB 2219,2220    |
|                    |                   | 345 LG 1819/1820              |                     |
| <b>TM37910</b><br> | 0001318411S       | Ring Kit, Piston              | 345 L 1418 MBTC-USA |
|                    |                   | Repl. Wabco: 411 042 003      | 345 L 1519          |
|                    |                   | 2 S                           | 345 L 1519,1520     |
|                    |                   | ø90+1,00 / 2,5x2,5x-<br>2,5x4 | 345 L 2219,2220     |
|                    |                   |                               | 345 L 2225          |
|                    |                   |                               | 345 LB 2219,2220    |
|                    |                   | 345 LG 1819/1820              |                     |
| <b>TM37911</b><br> | -                 | Ring Kit, Piston              | -                   |
|                    |                   | ø92 / 2,5x2,5x4               |                     |



| Model / Details  | Description                                | Replaces Ref. No:                      | TM No.  |
|--|--|--|---|
| -  | Ring Kit, Piston<br>ø92+0,25 / 2,5x2,5x4   | -                                      | <b>TM37912</b><br>   |
| -  | Ring Kit, Piston<br>ø92+0,50 / 2,5x2,5x4   | -                                      | <b>TM37913</b><br>   |
| 314 LP<br>316 LP<br>318 LP<br>341 L 1114<br>341 L 914<br>341 LA 1114<br>341 LK 1114                    | Ring Kit, Piston<br>ø94 / 2,5x2,5x2,5      | 0001317811<br>0001319211               | <b>TM37914</b><br>   |
| 314 LP<br>316 LP<br>318 LP<br>341 L 1114<br>341 L 914<br>341 LA 1114<br>341 LK 1114                    | Ring Kit, Piston<br>ø94+0,50 / 2,5x2,5x2,5 | -                                      | <b>TM37915</b><br> |
| 314 LP<br>316 LP<br>318 LP<br>341 L 1114<br>341 L 914<br>341 LA 1114<br>341 LK 1114                    | Ring Kit, Piston<br>ø94+1,00 / 2,5x2,5x2,5 | -                                      | <b>TM37916</b><br> |
| 979 ACCELO<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3 | Ring Kit, Piston<br>ø100 / 2,5x2,5x4       | 0011310111<br>0001319411<br>0001319511 | <b>TM37917</b><br> |
| 979 ACCELO<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3 | Ring Kit, Piston<br>ø100+0,50 / 2,5x2,5x4  | -                                      | <b>TM37918</b><br> |












| TM No.  | Replaces Ref. No:                                    | Description                                      | Model / Details   |
|---|--|--|---|
| <b>TM37919</b><br>   | -  | Ring Kit, Piston<br>ø100+1,00 / 2,5x2,5x4        | 979 ACCELO<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3  |
| <b>TM14971</b><br>   | 541130008  | Cylinder Liner & Piston<br>With Rings,<br>Piston | 979 ACCELO<br>950 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>934 ACTROS 2/3  |
| <b>TM15794</b><br>  | 5411310208   | Cylinder Liner & Piston<br>With Rings,<br>Piston | -   |
| <b>TM13878</b><br> | 403130008<br>4031310002<br>4421300008<br>4421300002  | Cylinder Liner & Piston<br>With Rings,<br>Piston | 363 LP 2226/6X4<br>363 LP 2232/6X4<br>386 L 1625,1725<br>386 L 1633<br>386 LB 2325,2425<br>388 L 1929<br>388 L 1935 363 LP<br>2226/6X4<br>363 LP 2232/6X4 |
| <b>TM14972</b><br> | 5411300108   | Cylinder Liner & Piston<br>With Rings,<br>Piston | 979 ACCELO<br>950 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>934 ACTROS 2/3  |
| <b>TM14367</b><br> | 4021300308<br>4021300608<br>4021310502<br>4271300008 | Cylinder Liner & Piston<br>With Rings,<br>Piston | -   |
| <b>TM13631</b><br> | 4411300008   | Cylinder Liner & Piston<br>With Rings,<br>Piston | 650 MK<br>651 MK<br>652 MK<br>653 MK<br>654 MK<br>615 NG<br>616 NG  |












| Model / Details   | Description            | Replaces Ref. No: | TM No.  |
|---|------------------------|-------------------|---|
| -   | Cylinder Liner, Piston | -                 | <b>TM37920</b>  |
|   |                        |                   |    |
| -   | Cylinder Liner, Piston | -                 | <b>TM37921</b>  |
|   |                        |                   |    |
| -   | Cylinder Liner, Piston | -                 | <b>TM37922</b>  |
|   |                        |                   |    |
| -   | Cylinder Liner, Piston | -                 | <b>TM37923</b>  |
|   |                        |                   |  |
| -   | Cylinder Liner, Piston | -                 | <b>TM37924</b>  |
|   |                        |                   |  |
| -   | Cylinder Liner, Piston | -                 | <b>TM37925</b>  |
|   |                        |                   |  |
| 363 LP 2226/6X4<br>363 LP 2232/6X4<br>386 L 1625,1725<br>386 L 1633<br>386 LB 2325,2425<br>388 L 1929<br>388 L 1935 | Bearing Kit, Piston    | 4031310233S       | <b>TM13881</b>  |
|   |                        |                   |  |









| TM No.  | Replaces Ref. No: | Description   | Model / Details  |
|---|-------------------|---|--|
| <b>TM37926</b><br>   | 9414301240        | Strap, Air Tank                                     | 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3 |
|   | 9414300540        |   |  |
| <b>TM37927</b><br>   | 0005480370        | Heater, Air Tank<br>Repl. Wabco: 894 260<br>040 2   | 357 O 405<br>357 O 407<br>671 CONECTO<br>613 TOURISMO  |
|   |                   |   |  |
| <b>TM14422</b><br>   | 0004291795        | Air Line Filter<br>Repl. Wabco: 432 500<br>020 0    | 436 UNIMOG<br>373 O 302<br>300 O 303<br>301 O 303<br>373 O 303<br>600 O 303<br>307 O 305               |
|   | 0004292995        |   |  |
|   | 0004293895        |   |  |
| <b>TM37928</b><br> | 0004294795        | Air Line Filter<br>Repl. Wabco: 432 500<br>021 0    | 427 UNIMOG<br>435 UNIMOG<br>437 UNIMOG   |
|   |                   |   |  |
| <b>TM14647</b><br> | 9404200048        | Hose, Air Tank                                      | 950 AXOR 2<br>952 AXOR 2<br>953 AXOR 2<br>954 AXOR 2   |
|   |                   |   |  |
| <b>TM14648</b><br> | 9404200548        | Hose, Air Tank                                      | 930 ACTROS 2/3<br>375 AXOR<br>374 AXOR 2<br>375 AXOR 2<br>950 AXOR 2<br>952 AXOR 2<br>953 AXOR 2       |
|   |                   |   |  |
| <b>TM14254</b><br> | 0004300970        | Silencer, Air Tank<br>Repl. Wabco: 432 407<br>070 0 | 699 MK<br>356 O 404<br>357 O 405<br>612 O 405<br>357 O 407<br>357 O 408<br>613 TOURISMO                |
|   | 0004302170        |   |  |
|   | 0004302470        |   |  |




| Model / Details   | Description   | Replaces Ref. No:                                    | TM No.         |
|---|---|--|----------------|
| 954 ACTROS<br>964 AROCS<br>970 ATEGO<br>375 AXOR<br>940 AXOR 2<br>970 ATEGO 2<br>930 ACTROS 2/3 | Silencer, Air Tank<br>Repl. Wabco: 432 407<br>060 0   | 0004300370<br>0004300870<br>0004302370               | <b>TM13763</b> |
| -   | Coupling<br>Automatic, For Emergency,<br>Red<br>Repl. Wabco: 452 200<br>211 0<br>Max, Operating Pres.:<br>8 bar / Port Threads:<br>M22x1,5  | 0004293530   | <b>TM24721</b> |
| 950 ACTROS<br>952 ACTROS<br>954 ACTROS<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO      | Coupling<br>Automatic, For Emergency,<br>Red<br>Repl. Wabco: 952 200<br>221 0<br>Max, Operating Pres.:<br>10 bar / Port Threads:<br>M16x1,5 | 0004293930<br>0004295530<br>0004295830<br>0004296130 | <b>TM14420</b> |
| 950 ACTROS<br>952 ACTROS<br>954 ACTROS<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO      | Coupling<br>Automatic, For Brake,<br>Yellow<br>Repl. Wabco: 952 200<br>222 0<br>Max, Operating Pres.:<br>10 bar / Port Threads:<br>M16x1,5  | 0004294030<br>0004295630<br>0004296230<br>0004298130 | <b>TM24598</b> |
| 950 ACTROS<br>952 ACTROS<br>954 ACTROS<br>976 ATEGO<br>976 ATEGO 2<br>950 AXOR 2<br>952 AXOR 2  | Coupling<br>Standard, For Emergency,<br>Red<br>Repl. Wabco: 952 200<br>021 0<br>Max, Operating Pres.:<br>10 bar / Port Threads:<br>M16x1,5  | 0004297630<br>0004297730                             | <b>TM14419</b> |
| 436 UNIMOG  | Coupling<br>Standard, For Brake,<br>Yellow<br>Repl. Wabco: 952 200<br>022 0<br>Max, Operating Pres.:<br>8 bar / Port Threads:<br>M16x1,5    | 0004293830<br>0004295430<br>0004295930<br>0004297930 | <b>TM14418</b> |
| 950 ACTROS<br>952 ACTROS<br>954 ACTROS<br>976 ATEGO<br>976 ATEGO 2<br>950 AXOR 2<br>952 AXOR 2  | Seal Ring, Coupling<br>Repl. Wabco: 897 550<br>020 4  | 0004292184<br>0004292484<br>0004290327               | <b>TM24867</b> |





| TM No.  | Replaces Ref. No:                                    | Description   | Model / Details  |
|---|--|---|--|
| <b>TM14236</b><br>   | 0014292444   | Check Valve<br>Repl. Wabco: 434 208<br>000 0  | 314 LP<br>316 LP<br>318 LP<br>350 LS 1924<br>350 LS 1924A,1929<br>350 LS 1924A,1929,1930<br>615 LK/LN2   |
|   | 0034292944<br>0034290744<br>0004290444<br>0054296644 | Check Valve<br>Repl. Wabco: 434 014<br>000 0  | 979 ACCELO<br>958 ATEGO 2<br>958 ATEGO 2<br>958 AXOR 2<br>364 O 370<br>364 O 371<br>382 OH SERIES<br>384 OF SERIES                                   |
| <b>TM15162</b><br>   | 0004294144<br>0004207655                             | Quick Release Valve<br>Repl. Wabco: 973 500<br>000 0<br>Max, Operating Pres, :<br>10 bar / Port Threads:<br>M22x1,5   | 376 L 1113 MBTC-USA<br>376 L 1117 MBTC-USA<br>376 L 1319 MBTC-USA<br>376 LP 1219 MBTC-USA<br>376 LP 1419 MBTC-USA<br>376 LPS 1525 MBTC-USA<br>653 MK |
|   | 828370600  | Quick Release Valve<br>Repl. Wabco: 963 001<br>013 0  | -  |
| <b>TM14992</b><br> | 0044292344<br>0044292944                             | Quick Release Valve<br>Repl. Wabco: 973 500<br>028 0  | 970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>970 ATEGO 2<br>972 ATEGO 2<br>974 ATEGO 2  |
|   | 0054294944   | Quick Release Valve<br>Repl. Wabco: 973 500<br>042 0  | 405 UNIMOG   |
| <b>TM13769</b><br> | 0004340501<br>0004341001<br>0004342101<br>0004342301 | Multiway Valve<br>Plastic Handle<br>Repl. Wabco: 463 013<br>110 0<br>Stroke: 5,7 / Max, Op-<br>erating Pres, : 10 bar /<br>Port Threads: M12x1,5 /<br>Handle Length: 46,9 | 318 LP<br>336 LP 1924<br>336 LPS 1924<br>344 LP 1113<br>350 LS 1924<br>350 LS 1924A,1929<br>350 LS 1924A,1929,1930                                   |










| Model / Details       | Description             | Replaces Ref. No: | TM No.  |
|-----------------------|-------------------------|-------------------|---|
| 338 L 1418            | Multiway Valve          | 0004342401        | <br><b>TM14651</b>   |
| 338 LK 1418           | Repl. Wabco: 463 013    | 0004340801        |   |
| 338 LP 1418           | 114 0                   | 0004341101        |   |
| 338 LPS 1418          | Stroke: 5,7 / Max, Op-  | 0004343001        |   |
| 338 LS 1418           | erating Pres,: 10 bar / |                   |   |
| 341 LA 1114           | Port Threads: M12x1,5 / |                   |   |
| 343 T2/L              | Handle Length: 95,6     |                   |   |
| 350 LS 1924           | Multiway Valve          | 0002601457        | <br><b>TM32011</b>   |
| 350 LS 1924A,1929     | Repl. Wabco: 571 003    | 0002605957        |   |
| 363 LP 2232/6X4       | 104 0                   |                   |   |
| 363 LPK 2232/6X4      |                         |                   |   |
| 363 LPS 2232/6X4      |                         |                   |   |
| 387 NG                |                         |                   |   |
| 617 NG                |                         |                   |   |
| 314 LP                | Multiway Valve          | 0014311306        | <br><b>TM16454</b>  |
|                       | Repl. Wabco: 934 702    | 0024310706        |   |
|                       | 040 0                   | 0014315906        |   |
|                       |                         | 0014314506        |   |
| 343 T2/L              | Multiway Valve          | 0019975036        | <br><b>TM31943</b> |
| 346 LK 1924           | Wabco Type              | 0039975936        |   |
| 346 LK 1928           | Repl. Wabco: 463 036    | 0019976136        |   |
| 615 LK/LN2            | 000 0                   | 0039976036        |   |
| 699 MK                |                         |                   |   |
| 380 NG                |                         |                   |   |
| 381 NG                |                         |                   |   |
| 384 L 1215            | Multiway Valve          | 0024319406        | <br><b>TM16955</b> |
| 384 L 1218            | Repl. Wabco: 934 702    |                   |   |
| 384 LK 1215           | 320 0                   |                   |   |
| 384 LK 1218           |                         |                   |   |
| 386 L 1615            |                         |                   |   |
| 386 L 1620            |                         |                   |   |
| 386 L 1622            |                         |                   |   |
| 376 LPS 1525 MBTC-USA | Multiway Valve          | 0004343801        | <br><b>TM22395</b> |
| 679 LK/LN2            | Repl. Wabco: 463 013    |                   |   |
| 652 MK                | 200 0                   |                   |   |
| 653 MK                |                         |                   |   |
| 617 NG                |                         |                   |   |
| 620 NG                |                         |                   |   |
| 621 NG                |                         |                   |   |
| 957 ECONIC            | Multiway Valve          | 0014290544        | <br><b>TM16408</b> |
| 653 MK                | Plastic Handle          | 0034296844        |   |
| 385 NG                | Repl. Wabco: 571 040    |                   |   |
| 393 NG                | 000 0                   |                   |   |
| 619 NG                |                         |                   |   |
| 623 NG                |                         |                   |   |
| 648 NG                |                         |                   |   |














| TM No.  | Replaces Ref. No:                                    | Description   | Model / Details   |
|---|--|---|---|
| <b>TM15113</b><br>   | 0034319706   | Multiway Valve<br>Repl. Knorr: AE4800   | 375 ATEGO<br>972 ATEGO<br>975 ATEGO<br>375 ATEGO 2<br>958 ATEGO 2<br>970 ATEGO 2<br>972 ATEGO 2   |
| <b>TM15021</b><br>   | 0059971136<br>0049978536                             | Multiway Valve<br>Repl. Wabco: 472 072<br>639 0   | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3                                  |
| <b>TM37929</b><br>  | 9584300281   | Multiway Valve<br>Repl. Knorr: K010108A   | 958 ATEGO 2<br>958 ATEGO 2  |
| <b>TM37930</b><br> | 9584300381   | Multiway Valve<br>Repl. Knorr: K010108B1  | 958 AXOR 2  |
| <b>TM13802</b><br> | 0004322107<br>0004322407<br>0004321107<br>0004320607 | Drain Valve<br>Repl. Knorr: EE1100<br>Max, Operating Pres. :<br>20 bar / Port Threads:<br>M22x1,5 | 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS<br>970 ATEGO<br>970 ATEGO 2<br>967 ATEGO 3   |
| <b>TM13803</b><br> | 0004295444<br>0034293544                             | Drain Valve<br>Repl. Wabco: 434 300<br>000 0  | 376 L 1113 MBTC-USA<br>376 L 1116 MBTC-USA<br>376 L 1117 MBTC-USA<br>376 L 1316 MBTC-USA<br>376 L 1317 MBTC-USA<br>376 L 1319 MBTC-USA<br>376 L 1418 MBTC-USA |
| <b>TM14949</b><br> | 0034313806<br>0024318706<br>0024315206<br>0024311506 | Drain Valve<br>Repl. Wabco: 975 303<br>474 0  | 670 T2/LN1<br>673 LK/LN2<br>674 LK/LN2<br>675 LK/LN2<br>676 LK/LN2<br>677 LK/LN2<br>678 LK/LN2  |







| Model / Details  | Description   | Replaces Ref. No:                                    | TM No.  |
|--|---|--|---|
| 310 LT 608 D<br>310 T2/L<br>313 T2/L<br>314 LP<br>316 LP<br>318 LP<br>343 T2/L   | Drain Valve<br>Wabco Type<br>Repl. Wabco: 975 300<br>110 0            | 0014310006S  | <b>TM37931</b><br>   |
| 397 LP 1114,1214 MB-SA-RSA<br>397 LP 1214 A MBSA-RSA<br>397 LP 1617 A MBSA-RSA<br>397 LP/LPK 1314 MB-SA-RSA<br>397 LP/LPK 1417,1617 MBSA-RSA | Pressure Control Valve<br>Repl. Wabco: 973 002<br>521 0               | 0034310205<br>0024310105<br>0014318705<br>0034310005 | <b>TM14698</b><br>   |
| -  | Pressure Control Valve<br>Repl. Wabco: 975 303<br>085 0               | 0024316606   | <b>TM37932</b><br>  |
| 314 LP<br>316 LP<br>318 LP<br>338 L 1418<br>338 LK 1418<br>338 LP 1418<br>338 LPS 1418   | Pressure Control Valve<br>Repl. Wabco: 975 303<br>447 0               | 0014312226<br>0024315906<br>0024313506<br>0024316006 | <b>TM37933</b><br> |
| 318 LP<br>625 NG<br>625 SK   | Pressure Control Valve<br>Repl. Wabco: 475 010<br>000 0               | 0014292544   | <b>TM37934</b><br> |
| 310 LT 608 D<br>310 T2/L<br>313 T2/L<br>314 LP<br>316 LP<br>318 LP<br>343 T2/L   | Pressure Control Valve<br>Wabco Type<br>Repl. Wabco: 975 303<br>473 0 | 0014313406   | <b>TM13975</b><br> |
| 314 LP<br>318 LP<br>615 LK/LN2<br>678 LK/LN2<br>385 NG<br>615 NG<br>307 O 305  | Pressure Control Valve<br>Wabco Type<br>Repl. Wabco: 973 002<br>402 0 | 0014311805<br>0014313705<br>0014313405<br>0014314805 | <b>TM14867</b><br> |












| TM No.  | Replaces Ref. No: | Description            | Model / Details  |
|---|-------------------|------------------------|--|
| <b>TM14942</b><br>   | 0014316705        | Pressure Control Valve | 385 NG   |
|   | 0014316905        | Wabco Type             | 625 NG   |
|   | 0024314005        | Repl. Wabco: 973 002   | 625 SK   |
|   | 0024314805        | 520 0                  | 684 917 S INDONESIA  |
|   |                   |                        |  |
| <b>TM14233</b><br>   | 0034318205        | Pressure Control Valve | 386 LS 1622  |
|   | 0034311305        | Wabco Type, 43=M16,    | 386 LS 1625  |
|   | 0034311405        | Others=M22             | 386 LS 1630  |
|   | 0034313505        | Repl. Wabco: 973 009   | 386 LS 1633  |
|   |                   | 001 0                  | 388 LS 1929<br>388 LS 1935<br>388 LS 1938  |
| <b>TM15123</b><br>   | 0014310006        | Pressure Control Valve | 673 LK/LN2   |
|   | 0014310606        | Repl. Knorr: DR3200    | 674 LK/LN2<br>675 LK/LN2<br>676 LK/LN2<br>677 LK/LN2<br>678 LK/LN2<br>679 LK/LN2 |
|   |                   |                        |  |
|   |                   |                        |  |
|   |                   |                        |  |
| <b>TM37937</b><br> | 0054290344        | Pressure Control Valve | 950 ACTROS   |
|   |                   | Repl. Wabco: 475 010   | 952 ACTROS   |
|   |                   | 325 0                  | 953 ACTROS<br>954 ACTROS<br>934 ACTROS 2/3<br>375 ATEGO<br>970 ATEGO 2           |
|   |                   |                        |  |
|   |                   |                        |  |
| <b>TM13953</b><br> | 0004318713        | Pressure Control Valve | 950 ACTROS   |
|   | 0004318913        | Repl. Wabco: 480 204   | 952 ACTROS   |
|   | 0004319413        | 002 0                  | 953 ACTROS<br>954 ACTROS   |
|   |                   |                        |  |
| <b>TM14985</b><br> | 0004313715        | Air Dryer              | 699 MK   |
|   | 0004313635        | Repl. Wabco: 432 420   | 645 NG   |
|   | 0004316515        | 002 0                  | 646 NG<br>647 NG<br>648 NG<br>649 NG   |
|   | 0004313615        |                        | 397 OH SERIES  |
|   |                   |                        |  |
| <b>TM37938</b><br> | 0014312215        | Air Dryer              | 670 T2/LN1   |
|   | 0004318015        | Repl. Knorr: II36933   | 673 LK/LN2<br>674 LK/LN2<br>675 LK/LN2<br>676 LK/LN2<br>677 LK/LN2<br>678 LK/LN2 |
|   |                   |                        |  |
|   |                   |                        |  |
|   |                   |                        |  |





| Model / Details   | Description   | Replaces Ref. No:                                    | TM No.  |
|---|---|--|---|
| 374 AXOR 2  | Air Dryer<br>With Air Processing Unit<br>Repl. Wabco: 932 500<br>015 0                | 0024310315   | <b>TM37939</b><br>   |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS  | Air Dryer<br>With Air Processing Unit<br>Repl. Wabco: 932 500<br>006 0                | 0014316415<br>0014317815<br>0014318115               | <b>TM37940</b><br>   |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>976 ATEGO<br>976 ATEGO 2<br>375 AXOR  | Air Dryer<br>10 Bar, With Air Processing<br>Unit<br>Repl. Knorr: II38310F             | 0024310515<br>0024310715                             | <b>TM15110</b><br>   |
| 371 1817 K/4X2/36 MBT<br>371 1821 AK/4X4/36 MBT<br>371 1821 K/4X2/36 MBT<br>371 1938 S/35 LS/35<br>OTOMARSAN/TUERKEI<br>371 2521/6X2/48<br>OTOMARSAN/TUERKEI<br>371 2521K/6X2/36<br>OTOMARSAN/TUERKEI | Air Dryer<br>Heated<br>Repl. Knorr: LA8225  | 3714317015   | <b>TM37941</b><br> |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO   | Air Dryer<br>Wabco Type, With Air<br>Processing Unit<br>Repl. Wabco: 932 500<br>007 0 | 0014317915<br>0014318215<br>0014316815<br>0014316515 | <b>TM37942</b><br> |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3  | Air Dryer<br>Wabco Type   | 0004301315<br>0004303015<br>0004301215<br>0004302915 | <b>TM14986</b><br> |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3  | Air Dryer<br>Repl. Wabco: 932 500<br>013 0  | 0024310615   | <b>TM15128</b><br> |





| TM No.  | Replaces Ref. No:                      | Description  | Model / Details  |
|---|--|--|--|
| <b>TM15146</b><br>   | 0004309715                             | Air Dryer<br>Knorr Type  | 375 ATEGO<br>972 ATEGO<br>975 ATEGO<br>375 ATEGO 2<br>970 ATEGO 2<br>972 ATEGO 2<br>975 ATEGO 2                      |
| <b>TM15126</b><br>   | 6934207871<br>6934207971               | Air Dryer<br>With Air Processing Unit<br>Repl. Wabco: 932 500<br>003 0 | 384 OF SERIES<br>382 O 500<br>382 O 500  |
| <b>TM15100</b><br>  | 0004301515                             | Air Dryer<br>Repl. Wabco: 932 400<br>003 0                             | 384 OF SERIES<br>382 O 500<br>382 O 500<br>398 OH SERIES   |
| <b>TM15071</b><br> | 0044299344<br>0054291344               | Relay Valve<br>Repl. Wabco: 480 202<br>005 0                           | 950 ACTROS<br>952 ACTROS<br>953 ACTROS   |
| <b>TM16338</b><br> | 0003276825                             | Solenoid Valve<br>Repl. Wabco: 472 905<br>111 0                        | 950 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>934 ACTROS 2/3<br>970 ATEGO 2<br>375 AXOR<br>940 AXOR 2                |
| <b>TM13711</b><br> | 0004296544<br>0014293044<br>0034295244 | Relay Valve<br>Repl. Wabco: 973 001<br>010 0                           | 338 LPS 1418<br>338 LS 1418<br>343 T2/LN1<br>345 L 1418 MBTC-USA<br>345 L 1519<br>345 L 1519,1520<br>345 L 2013,2014 |
| <b>TM14204</b><br> | 0014292144                             | Relay Valve<br>Repl. Wabco: 473 017<br>000 0                           | 625 NG<br>625 SK   |










| Model / Details  | Description   | Replaces Ref. No:                                    | TM No.  |
|--|---|--|---|
| 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3         | Relay Valve<br>Repl. Wabco: 973 006<br>003 0                    | 0044296344   | <b>TM14202</b><br>   |
| 673 LK/LN2<br>674 LK/LN2<br>675 LK/LN2<br>676 LK/LN2<br>677 LK/LN2<br>678 LK/LN2<br>679 LK/LN2                 | Relay Valve<br>Wabco Type<br>Repl. Wabco: 973 006<br>001 0      | 0044290644<br>0044291144                             | <b>TM14205</b><br>   |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3     | Relay Valve<br>Wabco Type<br>Repl. Wabco: 973 011<br>205 0      | 0054291044   | <b>TM15069</b><br>   |
| 375 ACTROS<br>950 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>934 ACTROS 2/3<br>963 ACTROS MP4<br>964 ACTROS MP4 | Relay Valve<br>Wabco Type, M16<br>Repl. Wabco: 973 011<br>001 0 | 0044293844   | <b>TM14208</b><br> |
| 310 LT 608 D<br>310 T2/L<br>313 T2/L<br>314 LP<br>316 LP<br>318 LP<br>341 L 1114                               | Relay Valve<br>Wabco Type<br>Repl. Wabco: 973 001<br>020 0      | 0014296844<br>0004293044                             | <b>TM14920</b><br> |
| 310 LT 608 D<br>310 T2/L<br>313 T2/L<br>314 LP<br>316 LP<br>318 LP<br>341 L 1114                               | Relay Valve<br>Wabco Type<br>Repl. Wabco: 973 011<br>000 0      | 0034295344<br>0024290744<br>0024291644<br>0014292044 | <b>TM14704</b><br> |
| 957 ECONIC<br>653 MK<br>385 NG<br>393 NG<br>619 NG<br>623 NG<br>648 NG   | Relay Valve<br>Repl. Wabco: 973 011<br>004 0                    | 0044297844<br>0044296244                             | <b>TM15068</b><br> |







| TM No.  | Replaces Ref. No:        | Description                                     | Model / Details  |
|---|--------------------------|---|--|
| <b>TM15463</b><br>   | 0054298944               | Relay Valve<br>Repl. Wabco: 480 202<br>009 0    | 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3<br>934 ACTROS 2/3<br>930 ACTROS 2/3<br>930 ACTROS 2/3               |
| <b>TM13958</b><br>   | 0054293644               | Relay Valve<br>Repl. Wabco: 480 205<br>106 0    | 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3<br>934 ACTROS 2/3<br>930 ACTROS 2/3<br>930 ACTROS 2/3<br>944 AXOR 2 |
| <b>TM27815</b><br>  | 0003276225               | Solenoid Valve<br>Repl. Wabco: 472 900<br>001 0 | 651 MK<br>652 MK<br>390 OH SERIES<br>655 SK<br>656 SK<br>612 O 405   |
| <b>TM14234</b><br> | 0044296544               | Solenoid Valve<br>Repl. Wabco: 472 195<br>016 0 | 979 ACCELO<br>375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3                                       |
| <b>TM37943</b><br> | 0005434085               | Solenoid Valve<br>Repl. Wabco: 442 200<br>222 1 | 950 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>934 ACTROS 2/3<br>970 ATEGO<br>970 ATEGO 2<br>974 ATEGO 2                                  |
| <b>TM32595</b><br> | 4052640389<br>9452601957 | Solenoid Valve                                  | 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3                                   |
| <b>TM27627</b><br> | 0003278525               | Solenoid Valve<br>Repl. Wabco: 472 880<br>000 0 | 930 ACTROS 2/3<br>932 ACTROS 2/3<br>934 ACTROS 2/3<br>970 ATEGO<br>970 ATEGO 2<br>974 ATEGO 2<br>975 ATEGO 2                             |





| Model / Details  | Description  | Replaces Ref. No:                                    | TM No.         |
|--|--|--|----------------|
| 930 ACTROS 2/3<br>934 ACTROS 2/3<br>970 ATEGO<br>970 ATEGO 2<br>940 AXOR 2<br>950 AXOR 2<br>954 AXOR 2   | Solenoid Valve<br>Without Silencer<br>Repl. Wabco: 472 880<br>021 0                        | 0003278425   | <b>TM14658</b> |
| 615 LK/LN2<br>699 MK<br>615 NG<br>616 NG<br>617 NG<br>619 NG<br>620 NG                                   | Safety Valve<br>Four Circuit, Wabco Type<br>Repl. Wabco: 934 002<br>221 0                  | 0034315006<br>0024319106<br>0024312706<br>0024310206 | <b>TM14697</b> |
| 670 T2/LN1<br>673 LK/LN2<br>674 LK/LN2<br>675 LK/LN2<br>676 LK/LN2<br>677 LK/LN2<br>678 LK/LN2           | Safety Valve<br>Four Circuit, Wabco Type<br>Repl. Wabco: 934 702<br>261 0                  | 0034314106<br>0024317806<br>0024317606<br>0024317306 | <b>TM13962</b> |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS   | Safety Valve<br>Multi Circuit, Wabco Type,<br>With Sensor<br>Repl. Wabco: 934 705<br>005 0 | 0034315406<br>0034316106                             | <b>TM13791</b> |
| 312 L 312<br>338 L 1418<br>338 LP 1418   | Overflow Valve<br>Repl. Bosch: 1 457 413<br>010  | 0004770329   | <b>TM13609</b> |
| 979 ACCELO<br>950 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>934 ACTROS 2/3<br>375 AXOR<br>374 AXOR 2 | Overflow Valve   | 4221800315<br>5411800715<br>4221800215<br>4031801615 | <b>TM01700</b> |
| 336 LP 1924<br>341 L 1112<br>341 L 1114<br>341 L 911<br>341 L 914<br>341 LA 1114<br>341 LO 1112          | Overflow Valve<br>Repl. Bosch: 1 417 413<br>047  | 0000747684<br>0000746584<br>0000740684<br>0000743884 | <b>TM24136</b> |





| TM No.  | Replaces Ref. No:                      | Description                                     | Model / Details  |
|---|--|---|--|
| <b>TM23747</b><br>   | 5410980557<br>9040980057<br>4570980057 | Overflow Valve                                  | 386 LS 1625<br>695 L 1622 / L 1620<br>695 L 1622/1624<br>693 1318 / 1518<br>693 1718 - 1719/36<br>693 1718 - 1719/48<br>634 O 500 RSD /<br>2736/8X2/30 |
| <b>TM14940</b><br>   | 0004297544                             | Overflow Valve<br>Repl. Wabco: 434 100<br>125 0 | 352 LAS 1313<br>352 LS 1313<br>353 LP<br>353 T2/L<br>358 LAS 1113 B<br>358 LS 1113 B<br>355 OF SERIES  |
| <b>TM29750</b><br>   | 0014299444<br>0024298344               | Overflow Valve<br>Repl. Wabco: 434 100<br>130 0 | 407 UNIMOG<br>417 UNIMOG   |
| <b>TM02049</b><br> | 9060920410<br>9060920510               | Overflow Valve                                  | 979 ACCELO<br>375 ACTROS<br>375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO  |
| <b>TM23810</b><br> | 4570980257                             | Overflow Valve                                  | 375 AXOR<br>374 AXOR 2<br>940 AXOR 2<br>942 AXOR 2<br>943 AXOR 2<br>944 AXOR 2<br>958 AXOR 2   |
| <b>TM23241</b><br> | 0000749984                             | Overflow Valve<br>Repl. Bosch: 2 417 413<br>082 | 650 MK<br>651 MK<br>652 MK<br>653 MK<br>654 MK<br>621 NG<br>625 SK   |
| <b>TM23893</b><br> | 4570980357                             | Overflow Valve                                  | 979 ACCELO<br>375 AXOR<br>940 AXOR 2<br>944 AXOR 2<br>386 LS 1625<br>634 TOURO<br>671 CONECTO  |



| Model / Details   | Description   | Replaces Ref. No:        | TM No.  |
|---|---|--------------------------|---|
| 380 NG<br>381 NG<br>383 NG<br>616 NG<br>617 NG<br>620 NG<br>621 NG<br>623 NG  | Overflow Valve<br>Repl. Wabco: 434 100<br>033 0                   | 0024294244               | <b>TM14195</b><br>   |
| 628 CITARO<br>634 O 500<br>382 OH SERIES<br>382 OH SERIES<br>634 O 500<br>628 CITARO<br>628 CITARO  | Overflow Valve<br>Repl. Wabco: 434 100<br>232 0                   | 0054291444               | <b>TM14747</b><br>   |
| 950 ACTROS<br>952 ACTROS<br>930 ACTROS 2/3<br>963 ACTROS MP4<br>964 AROCS<br>963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS                                | Overflow Valve<br>Repl. Wabco: 434 100<br>051 0                   | 0054296344               | <b>TM01585</b><br>  |
| 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>970 ATEGO<br>972 ATEGO  | Hand Brake Valve<br>Knorr Type<br>Repl. Knorr: DPM21AK            | 0034306881               | <b>TM15155</b><br> |
| 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>970 ATEGO<br>972 ATEGO  | Hand Brake Valve<br>Knorr Type<br>Repl. Knorr: DPM22AK            | 0034307381<br>0034307481 | <b>TM13968</b><br> |
| 382 OH SERIES<br>382 O 500<br>382 O 500 M / 1725<br>382 O 500 M / 1725 / 1726<br>382 O 500 M / 1728<br>382 O 500 R / 1830 / 30<br>382 O 500 U / 1725 / 59 | Levelling Valve<br>Repl. Wabco: 441 050<br>011 0                  | 0005424018               | <b>TM27108</b><br> |
| 950 ACTROS<br>952 ACTROS<br>954 ACTROS<br>950 AXOR 2<br>954 AXOR 2  | Levelling Valve<br>Repl. Wabco: 441 050<br>120 0<br>441 050 121 0 | 0025426718<br>0035422618 | <b>TM10146</b><br> |












| TM No.  | Replaces Ref. No:          | Description   | Model / Details  |
|---|----------------------------|---|--|
| <b>TM35143</b><br>   | 0003201758                 | Levelling Valve<br>Repl. Wabco: 441 050<br>006 0                  | -  |
| <b>TM27622</b><br>   | 0003282030                 | Levelling Valve<br>Manuel, Right<br>Repl. Bosch: 0 501 005<br>001 | 654 MK<br>385 NG<br>619 NG<br>647 NG<br>384 OF SERIES<br>368 OH SERIES<br>382 OH SERIES                    |
| <b>TM34839</b><br>   | 0003284530                 | Levelling Valve<br>Wabco Type<br>Repl. Wabco: 464 007<br>011 0    | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>934 ACTROS 2/3 |
| <b>TM27810</b><br> | 0003283330<br>0003283230   | Levelling Valve<br>Knorr Type<br>Repl. Knorr: SV1280              | 674 LK/LN2<br>675 LK/LN2<br>676 LK/LN2<br>677 LK/LN2<br>679 LK/LN2<br>651 MK<br>652 MK                     |
| <b>TM27623</b><br> | 0003282130<br>000328213080 | Levelling Valve<br>Manuel, Left<br>Repl. Bosch: 0 500 005<br>002  | 654 MK<br>384 OF SERIES<br>368 OH SERIES<br>382 OH SERIES<br>396 OH SERIES<br>373 O 302<br>300 O 303       |
| <b>TM35142</b><br> | 0105427818                 | Levelling Valve<br>Repl. Wabco: 441 050<br>008 0                  | 437 UNIMOG   |
| <b>TM27844</b><br> | 0015420018                 | Levelling Valve<br>Repl. Wabco: 441 050<br>012 0                  | 950 ACTROS<br>952 ACTROS<br>954 ACTROS<br>970 ATEGO<br>970 ATEGO 2<br>974 ATEGO 2<br>975 ATEGO 2           |



| Model / Details  | Description                                       | Replaces Ref. No:                                    | TM No.  |
|--|---|--|---|
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3   | Hand Brake Valve<br>Repl. Wabco: 961 723<br>421 0 | 0034305981   | <b>TM15067</b><br>   |
| 699 MK<br>615 NG<br>616 NG<br>617 NG<br>619 NG<br>620 NG<br>621 NG   | Hand Brake Valve<br>Repl. Wabco: 961 722<br>210 0 | 0014305681<br>0004309181<br>0014303481<br>0014306681 | <b>TM14965</b><br>   |
| 650 MK<br>651 MK<br>652 MK<br>653 MK<br>654 MK<br>699 MK<br>625 SK   | Hand Brake Valve<br>Repl. Wabco: 961 723<br>005 0 | 0024307481<br>0024307681<br>0024307881               | <b>TM14993</b><br>  |
| 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO  | Hand Brake Valve<br>Repl. Knorr: DPM64A           | 0004200384   | <b>TM15446</b><br> |
| 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO  | Hand Brake Valve<br>Repl. Knorr: DPM65A           | 0004200484   | <b>TM15445</b><br> |
| 375 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3<br>375 ATEGO<br>970 ATEGO | Hand Brake Valve<br>Repl. Knorr: DPM66A           | 0004200284   | <b>TM15154</b><br> |
| 375 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3<br>375 ATEGO<br>970 ATEGO | Hand Brake Valve<br>Repl. Knorr: DPM67A           | 0004200184   | <b>TM15444</b><br> |







| TM No.  | Replaces Ref. No: | Description                | Model / Details      |
|---|-------------------|----------------------------|----------------------|
| <b>TM37944</b><br>   | 0044314905S       | Foot Brake Valve           | 375 ACTROS           |
|   | 0044296205S       | Without Fittings           | 950 ACTROS           |
|   | 0044316205S       | Repl. Wabco: 461 319 274   | 952 ACTROS           |
|   |                   | 0 S                        | 953 ACTROS           |
|   |                   |                            | 954 ACTROS           |
|   |                   |                            | 970 ATEGO            |
|   |                   |                            | 972 ATEGO            |
| <b>TM15160</b><br>   | 0044315905        | Foot Brake Valve           | 375 ACTROS           |
|   | 0044314605        | Wabco Type                 | 375 AXOR             |
|   |                   | Repl. Wabco: 461 315 264 0 | 374 AXOR 2           |
|   |                   |                            | 375 AXOR 2           |
|   |                   |                            | 940 AXOR 2           |
|   |                   |                            | 942 AXOR 2           |
|   |                   |                            | 943 AXOR 2           |
| <b>TM14950</b><br>   | 0024310605        | Foot Brake Valve           | 615 LK/LN2           |
|   | 0024311005        | Wabco Type                 | 615 NG               |
|   | 0024312005        | Repl. Wabco: 461 319 008 0 | 616 NG               |
|   |                   |                            | 617 NG               |
|   |                   |                            | 619 NG               |
|   |                   |                            | 620 NG               |
|   |                   |                            | 621 NG               |
| <b>TM13700</b><br> | 0024312705        | Foot Brake Valve           | 341 L 1114           |
|   | 0014318305        | Wabco Type                 | 341 L 914            |
|   | 0014318905        | Repl. Haldex: 320 023 001  | 341 LK 1114          |
|   | 0014319105        |                            | 341 LO 914           |
|   |                   |                            | 341 LS 1114          |
|   |                   |                            | 345 L 1313,1314      |
|   |                   |                            | 345 L 1313,1314,1316 |
| <b>TM37945</b><br> | 0034311505        | Foot Brake Valve           | 670 T2/LN1           |
|   | 0034311905        | Repl. Wabco: 461 315 258 0 | 650 MK               |
|   | 0034312605        |                            | 651 MK               |
|   | 0034312905        |                            | 699 MK               |
|   |                   |                            | 625 SK               |
|   |                   |                            | 405 UNIMOG           |
|   |                   |                            | 437 UNIMOG           |
| <b>TM37946</b><br> | 0024317005        | Foot Brake Valve           | 673 LK/LN2           |
|   | 0024318105        | Repl. Wabco: 461 319 260 0 | 674 LK/LN2           |
|   | 0024318805        |                            | 676 LK/LN2           |
|   | 9924318105        |                            | 678 LK/LN2           |
|   |                   |                            | 405 UNIMOG           |
| <b>TM15158</b><br> | 0034319506        | Foot Brake Valve           | 930 ACTROS 2/3       |
|   |                   | Repl. Wabco: 480 003 000 0 | 932 ACTROS 2/3       |
|   |                   |                            | 933 ACTROS 2/3       |
|   |                   |                            | 934 ACTROS 2/3       |
|   |                   |                            | 934 ACTROS 2/3       |
|   |                   |                            | 930 ACTROS 2/3       |
|   |                   |                            | 930 ACTROS 2/3       |
|   |                   |                            | 634 O 500            |








| Model / Details | Description              | Replaces Ref. No: | TM No.  |
|-----------------|--------------------------|-------------------|---|
| 336 LP 1924     | Shut-Off Valve           | 0004291031        | <b>TM14911</b><br>   |
| 336 LPS 1924    | Repl. Wabco: 452 002     | 0004291431        |   |
| 338 L 1418      | 107 0                    | 0004290631        |   |
| 338 LK 1418     | Comments: 2/3,           | 0004291631        |   |
| 338 LP 1418     | M22x1,5 / Lever Actua-   |                   |   |
| 338 LPS 1418    | tion: 90                 |                   |   |
| 338 LS 1418     |                          |                   |   |
| 375 ACTROS      | Shut-Off Valve           | 0022602457        | <b>TM32623</b><br>   |
| 950 ACTROS      |                          | 0012608857        |   |
| 952 ACTROS      |                          | 0012609057        |   |
| 953 ACTROS      |                          | 0022600157        |   |
| 954 ACTROS      |                          |                   |   |
| 930 ACTROS 2/3  |                          |                   |   |
| 932 ACTROS 2/3  |                          |                   |   |
| 385 NG          | Non Return Valve         | 0003272125        | <b>TM13800</b><br>  |
| 384 OF SERIES   | Repl. Knorr: 0500100006  |                   |   |
| 368 OH SERIES   |                          |                   |   |
| 382 OH SERIES   |                          |                   |   |
| 390 OHL 1421    |                          |                   |   |
| 397 OH SERIES   |                          |                   |   |
| 398 OH SERIES   |                          |                   |   |
|                 |                          |                   |   |
| 673 LK/LN2      | Brake Pressure Regulator | 0014318312        | <b>TM15261</b><br> |
| 674 LK/LN2      | Repl. Wabco: 475 710     | 0014318112        |   |
| 675 LK/LN2      | 036 0                    | 0014318712        |   |
| 676 LK/LN2      |                          |                   |   |
| 677 LK/LN2      |                          |                   |   |
| 678 LK/LN2      |                          |                   |   |
| 679 LK/LN2      |                          |                   |   |
| 674 LK/LN2      | Brake Pressure Regulator | 0014319412        | <b>TM37947</b><br> |
| 675 LK/LN2      | Repl. Wabco: 475 711     |                   |   |
| 676 LK/LN2      | 024 0                    |                   |   |
| 677 LK/LN2      |                          |                   |   |
| 679 LK/LN2      |                          |                   |   |
| 652 MK          |                          |                   |   |
| 655 SK          |                          |                   |   |
|                 |                          |                   |   |
| 950 ACTROS      | Brake Pressure Regulator | 0034312612        | <b>TM15066</b><br> |
| 952 ACTROS      | Wabco Type               | 0034312712        |   |
| 953 ACTROS      | Repl. Wabco: 475 710     |                   |   |
| 954 ACTROS      | 136 0                    |                   |   |
| 970 ATEGO       |                          |                   |   |
| 972 ATEGO       |                          |                   |   |
| 975 ATEGO       |                          |                   |   |
| 964 AROCS       | Brake Pressure Regulator | 0044317812        | <b>TM14008</b><br> |
| 375 ATEGO       | Repl. Wabco: 475 720     |                   |   |
| 970 ATEGO       | 005 0                    |                   |   |
| 972 ATEGO       |                          |                   |   |
| 975 ATEGO       |                          |                   |   |
| 970 ATEGO 2     |                          |                   |   |
| 972 ATEGO 2     |                          |                   |   |












| TM No.  | Replaces Ref. No:        | Description                                    | Model / Details  |
|---|--------------------------|--|--|
| <b>TM15073</b><br>   | 0004292497               | Air Dryer Cartridge                            | 963 ACTROS MP4   |
|   | 0004293995<br>0004295495 | Wabco Type<br>Repl. Wabco: 432 410<br>220 2    |  |
| <b>TM13638</b><br>   | 0004293795               | Air Dryer Cartridge                            | 375 ACTROS   |
|   | 0004293695               | Repl. Mann: TB 1374 x                          | 950 ACTROS   |
|   | 0004290897               | Repl. Hengst: T250W                            | 952 ACTROS   |
|   | 0004300969               |  | 953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3                             |
| <b>TM15452</b><br>   | 0004295795               | Air Dryer Cartridge                            | 375 ACTROS   |
|   | 0004295695               | Repl. Mann: TB 1394/1 x<br>Repl. Hengst: T280W | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3 |
| <b>TM27103</b><br> | 0003290425               | Raise Lower Valve                              | 314 LP   |
|   | 0003290825               | Repl. Knorr: SV3111                            | 316 LP<br>318 LP<br>674 LK/LN2<br>675 LK/LN2<br>676 LK/LN2<br>677 LK/LN2                 |



| Model / Details  | Description                 | Replaces Ref. No: | TM No.  |
|--|-----------------------------|-------------------|---------|
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS                                       | Front Panel                 | 9417500009        | TM18679 |
| 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3                       | Front Panel<br>Top          | 9437500009        | TM37948 |
| 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3                       | Front Panel                 | 9437500109        | TM19336 |
| 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS                                 | Front Panel                 | 9607500409        | TM19323 |
| 375 ACTROS<br>375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>375 ATEGO 2 | Hinge, Front Panel<br>Left  | 9737500451        | TM18793 |
| 375 ACTROS<br>375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>375 ATEGO 2 | Hinge, Front Panel<br>Right | 9737500351        | TM18792 |
| 906 SPRINTER   | Frame, Front Panel          | 9068880051        | TM19571 |








| TM No.  | Replaces Ref. No: | Description               | Model / Details   |
|---|-------------------|---------------------------|---|
| <b>TM19222</b><br>   | 9066200024        | Frame, Front Panel        | 900 SPRINTER<br>906 SPRINTER  |
| <b>TM37949</b><br>   | 9618851453        | Frame, Front Panel        | 963 ACTROS MP4<br>964 AROCS<br>963 ACTROS MP4<br>964 ACTROS MP4<br>964 AROCS<br>964 AROCS |
| <b>TM37969</b><br>   | 9618850253        | Frame, Front Panel        | 963 ACTROS MP4<br>964 AROCS<br>963 ACTROS MP4<br>964 ACTROS MP4<br>964 AROCS<br>964 AROCS |
| <b>TM37970</b><br> | 9608852354        | Frame, Front Panel        | 963 ACTROS MP4<br>964 AROCS<br>963 ACTROS MP4<br>964 ACTROS MP4<br>964 AROCS<br>964 AROCS |
| <b>TM37971</b><br> | 9618850753        | Frame, Front Panel        | 963 ACTROS MP4<br>964 AROCS<br>963 ACTROS MP4<br>964 ACTROS MP4<br>964 AROCS<br>964 AROCS |
| <b>TM37972</b><br> | 9618850553        | Lid, Front Panel<br>Left  | 963 ACTROS MP4<br>964 AROCS<br>963 ACTROS MP4<br>964 ACTROS MP4<br>964 AROCS<br>964 AROCS |
| <b>TM37973</b><br> | 9618850653        | Lid, Front Panel<br>Right | 963 ACTROS MP4<br>964 AROCS<br>963 ACTROS MP4<br>964 ACTROS MP4<br>964 AROCS<br>964 AROCS |



| Model / Details   | Description               | Replaces Ref. No: | TM No.             |
|---|---------------------------|-------------------|--------------------|
| BM MODEL<br>963 ACTROS MP4<br>964 AROCS<br>963 ACTROS MP4<br>964 ACTROS MP4<br>964 AROCS<br>964 AROCS | Lid, Front Panel<br>Left  | 9618851153        | <b>TM37974</b><br> |
| 963 ACTROS MP4<br>964 AROCS<br>963 ACTROS MP4<br>964 ACTROS MP4<br>964 AROCS<br>964 AROCS             | Lid, Front Panel<br>Right | 9618851253        | <b>TM37975</b><br> |
| 963 ACTROS MP4<br>964 AROCS<br>963 ACTROS MP4<br>964 ACTROS MP4<br>964 AROCS<br>964 AROCS             | Lid, Front Panel<br>Left  | 9618850353        | <b>TM37976</b><br> |
| 963 ACTROS MP4<br>964 AROCS<br>963 ACTROS MP4<br>964 ACTROS MP4<br>964 AROCS<br>964 AROCS             | Lid, Front Panel<br>Right | 9618850453        | <b>TM37977</b><br> |
| 963 ACTROS MP4<br>964 AROCS<br>963 ACTROS MP4<br>964 ACTROS MP4<br>964 AROCS<br>964 AROCS             | Lid, Front Panel<br>Left  | 9618850953        | <b>TM37978</b><br> |
| 963 ACTROS MP4<br>964 AROCS<br>963 ACTROS MP4<br>964 ACTROS MP4<br>964 AROCS<br>964 AROCS             | Lid, Front Panel<br>Right | 9618851053        | <b>TM37979</b><br> |
| 963 ACTROS MP4<br>964 AROCS<br>963 ACTROS MP4<br>964 ACTROS MP4<br>964 AROCS<br>964 AROCS             | Lid, Front Panel<br>Left  | 9618851553        | <b>TM37980</b><br> |





| TM No.  | Replaces Ref. No:                      | Description               | Model / Details   |
|---|--|---------------------------|---|
| <b>TM37981</b><br>   | 9618851653                             | Lid, Front Panel<br>Right | 963 ACTROS MP4<br>964 AROCS<br>963 ACTROS MP4<br>964 ACTROS MP4<br>964 AROCS<br>964 AROCS     |
| <b>TM18798</b><br>   | 9738840185                             | Grille, Front Panel       | 375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>375 ATEGO 2<br>970 ATEGO 2   |
| <b>TM18791</b><br>   | 9417511218<br>9417511018<br>9417510518 | Grille, Front Panel       | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS  |
| <b>TM37982</b><br> | 9408880123                             | Grille, Front Panel       | 375 ACTROS<br>375 AXOR<br>375 AXOR 2<br>944 AXOR 2<br>950 AXOR 2<br>952 AXOR 2<br>953 AXOR 2  |
| <b>TM18060</b><br> | 9437500218                             | Grille, Front Panel       | 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3                          |
| <b>TM18800</b><br> | 9437500518                             | Grille, Front Panel       | 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3                          |
| <b>TM19501</b><br> | 9448800085                             | Grille, Front Panel       | 375 ACTROS<br>375 ATEGO<br>375 ATEGO 2<br>970 ATEGO 2<br>375 AXOR<br>374 AXOR 2<br>375 AXOR 2 |














| Model / Details   | Description         | Replaces Ref. No:        | TM No.         |
|---|---------------------|--------------------------|----------------|
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS  | Grille, Front Panel | 9417501218               | <b>TM37983</b> |
| 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3                          | Grille, Front Panel | 9437501418               | <b>TM37984</b> |
| 901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER<br>905 SPRINTER<br>909 SPRINTER  | Grille, Front Panel | 9018800385               | <b>TM37985</b> |
| 690 SPRINTER<br>901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER<br>905 SPRINTER  | Grille, Front Panel | 9018800085               | <b>TM37986</b> |
| 375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>976 ATEGO<br>375 ATEGO 2<br>958 ATEGO 2<br>970 ATEGO 2 | Grille, Front Panel | 9588800585<br>9738800585 | <b>TM37987</b> |
| 906 SPRINTER  | Grille, Front Panel | 9068800785               | <b>TM37988</b> |
| 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3                          | Grille, Front Panel | 9437501518               | <b>TM19549</b> |





| TM No.  | Replaces Ref. No: | Description                   | Model / Details   |
|---|-------------------|-------------------------------|---|
| <b>TM19320</b><br>   | 9618850053        | Grille, Front Panel           | 963 ACTROS MP4<br>964 ACTROS MP4<br>964 AROCS   |
| <b>TM19316</b><br>   | 9618851353        | Grille, Front Panel           | 963 ACTROS MP4<br>964 ACTROS MP4<br>964 AROCS   |
| <b>TM19318</b><br>  | 9608852584        | Grille, Front Panel<br>Left   | 963 ACTROS MP4<br>964 ACTROS MP4<br>964 AROCS   |
| <b>TM19319</b><br> | 9608852684        | Grille, Front Panel<br>Right  | 963 ACTROS MP4  |
| <b>TM19317</b><br> | 9618850153        | Grille, Front Panel<br>Center | 963 ACTROS MP4<br>964 ACTROS MP4<br>964 AROCS   |
| <b>TM37989</b><br> | 9607500618        | Grille, Front Panel           | 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS                                |
| <b>TM37990</b><br> | 9618850853        | Grille, Front Panel           | 963 ACTROS MP4<br>964 AROCS<br>963 ACTROS MP4<br>964 ACTROS MP4<br>964 AROCS<br>964 AROCS |



| Model / Details  | Description                   | Replaces Ref. No:                      | TM No.  |
|--|-------------------------------|--|---|
| 963 ACTROS MP4<br>964 AROCS<br>963 ACTROS MP4<br>964 ACTROS MP4<br>964 AROCS<br>964 AROCS        | Grille, Front Panel<br>Left   | 9608852454                             | <b>TM37991</b>  |
|  |                               |  |    |
| 963 ACTROS MP4<br>964 AROCS<br>963 ACTROS MP4<br>964 ACTROS MP4<br>964 AROCS<br>964 AROCS        | Grille, Front Panel<br>Right  | 9608852554                             | <b>TM37992</b>  |
|  |                               |  |    |
| 963 ACTROS MP4<br>964 AROCS<br>963 ACTROS MP4<br>964 ACTROS MP4<br>964 AROCS<br>964 AROCS        | Grille, Front Panel<br>Center | 9608852654                             | <b>TM37993</b>  |
|  |                               |  |   |
| 932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3<br>934 ACTROS 2/3<br>942 AXOR 2<br>943 AXOR 2 | Grille, Front Panel<br>Center | 9608801990                             | <b>TM37994</b>  |
|  |                               |  |  |
| 906 SPRINTER   | Firewall, Front Panel         | 9068800203<br>9068800003<br>9068800603 | <b>TM37995</b>  |
|  |                               |  |  |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS   | Firewall, Front Panel         | 9417501272<br>9417500972<br>9417500272 | <b>TM37996</b>  |
|  |                               |  |  |
| 970 ATEGO 2<br>375 AXOR<br>374 AXOR 2<br>940 AXOR 2<br>942 AXOR 2<br>943 AXOR 2<br>944 AXOR 2    | Step, Front Panel             | 9448800105                             | <b>TM37997</b>  |
|  |                               |  |  |






| TM No.  | Replaces Ref. No: | Description                       | Model / Details  |
|---|-------------------|-----------------------------------|--|
| <b>TM37998</b><br>   | 9737500193        | Pull Handle, Front Panel          | BM MODEL<br>375 ACTROS<br>375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>375 ATEGO 2 |
| <b>TM37999</b><br>   | 9608801820        | Pull Handle, Front Panel<br>Left  | 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS   |
| <b>TM38000</b><br>   | 9608801920        | Pull Handle, Front Panel<br>Right | 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS   |
| <b>TM38001</b><br> | 9608842222        | Handle Cover, Front Panel         | 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS   |
| <b>TM38002</b><br> | 0009985205        | Grille Rubber, Front Panel        | 900 SPRINTER<br>906 SPRINTER   |
| <b>TM38003</b><br> | 9607501884        | Front Panel Lock<br>Left          | 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS   |
| <b>TM38004</b><br> | 9607501984        | Front Panel Lock<br>Right         | 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS   |



| Model / Details  | Description                | Replaces Ref. No:                      | TM No.  |
|--|----------------------------|--|---|
| 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS | Front Panel Lock<br>Left   | 9607502084                             | <b>TM38005</b><br>   |
| 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS | Front Panel Lock<br>Right  | 9607502184                             | <b>TM38006</b><br>   |
| 906 SPRINTER   | Strip, Side Panel<br>Left  | 9066902562<br>9066904782               | <b>TM38007</b><br>   |
| 906 SPRINTER   | Strip, Side Panel<br>Right | 9066902662<br>9066904882               | <b>TM38008</b><br> |
| 906 SPRINTER   | Strip, Side Panel<br>Left  | 9066900162<br>9066900400<br>9066904982 | <b>TM38009</b><br> |
| 906 SPRINTER   | Strip, Side Panel<br>Right | 9066900262<br>9066900500<br>9066905082 | <b>TM38010</b><br> |
| 906 SPRINTER   | Strip, Side Panel<br>Left  | 9066901182<br>9066903062               | <b>TM38011</b><br> |





| TM No.  | Replaces Ref. No:                      | Description                | Model / Details |
|---|--|----------------------------|-----------------|
| <b>TM38012</b><br>   | 9066901282<br>9066903362               | Strip, Side Panel<br>Right | 906 SPRINTER    |
| <b>TM38013</b><br>   | 9066900800<br>9066905382               | Strip, Side Panel<br>Left  | 906 SPRINTER    |
| <b>TM38014</b><br>  | 9066901000<br>9066905482               | Strip, Side Panel<br>Right | 906 SPRINTER    |
| <b>TM38015</b><br> | 9066901382<br>9066903200               | Strip, Side Panel<br>Left  | 906 SPRINTER    |
| <b>TM38016</b><br> | 9066901482<br>9066903300               | Strip, Side Panel<br>Right | 906 SPRINTER    |
| <b>TM38017</b><br> | 9066901582<br>9066901962<br>9066903400 | Strip, Side Panel<br>Left  | 906 SPRINTER    |
| <b>TM38018</b><br> | 9066901682<br>9066902062<br>9066903500 | Strip, Side Panel<br>Right | 906 SPRINTER    |





| Model / Details  | Description                | Replaces Ref. No:        | TM No.  |
|--|----------------------------|--------------------------|---|
| 906 SPRINTER   | Strip, Side Panel<br>Left  | 9066902582<br>9066903162 | <b>TM38019</b><br>   |
| 906 SPRINTER   | Strip, Side Panel<br>Right | 9066902682<br>9066903462 | <b>TM38020</b><br>   |
| 906 SPRINTER   | Strip, Side Panel<br>Left  | 9066902782<br>9066903262 | <b>TM38021</b><br>  |
| 906 SPRINTER   | Strip, Side Panel<br>Right | 9066902882<br>9066903562 | <b>TM38022</b><br> |
| 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS           | Cover, Side Panel<br>Left  | 9608847275               | <b>TM38023</b><br> |
| 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS           | Cover, Side Panel<br>Right | 9608847375               | <b>TM38024</b><br> |
| 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3 | Door<br>Left               | 9437201405<br>9437200105 | <b>TM19389</b><br> |





| TM No.  | Replaces Ref. No: | Description | Model / Details   |
|---|-------------------|-------------|---|
| <b>TM19390</b><br>   | 9437201605        | Door        | 930 ACTROS 2/3  |
|   | 9437200205        | Right       | 932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3  |
| <b>TM19391</b><br>   | 9417200805        | Door        | 950 ACTROS  |
|   |                   | Left        | 952 ACTROS<br>953 ACTROS<br>954 ACTROS  |
| <b>TM19392</b><br>   | 9417200905        | Door        | 950 ACTROS  |
|   |                   | Right       | 952 ACTROS<br>953 ACTROS<br>954 ACTROS  |
| <b>TM19388</b><br> | 9407200405        | Door        | 970 ATEGO 2   |
|   |                   | Right       | 967 ATEGO 3<br>375 AXOR<br>374 AXOR 2<br>940 AXOR 2<br>942 AXOR 2<br>943 AXOR 2<br>944 AXOR 2   |
| <b>TM19385</b><br> | 9737203105        | Door        | 375 ATEGO   |
|   |                   | Left        | 970 ATEGO<br>972 ATEGO<br>976 ATEGO<br>375 ATEGO 2<br>970 ATEGO 2<br>972 ATEGO 2<br>974 ATEGO 2 |
| <b>TM19386</b><br> | 9737203205        | Door        | 375 ATEGO   |
|   |                   | Right       | 970 ATEGO<br>972 ATEGO<br>976 ATEGO<br>375 ATEGO 2<br>970 ATEGO 2<br>972 ATEGO 2<br>974 ATEGO 2 |
| <b>TM19387</b><br> | 9407200305        | Door        | 970 ATEGO 2   |
|   |                   | Left        | 967 ATEGO 3<br>375 AXOR<br>374 AXOR 2<br>940 AXOR 2<br>942 AXOR 2<br>943 AXOR 2<br>944 AXOR 2   |



| Model / Details  | Description                       | Replaces Ref. No: | TM No.  |
|--|-----------------------------------|-------------------|---|
| 690 SPRINTER<br>901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER<br>909 SPRINTER               | Mounting Plate, Door<br>Left, Top | 9017660219        | <b>TM38025</b><br>   |
| 690 SPRINTER<br>901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER<br>909 SPRINTER               | Mounting Plate, Door<br>Bottom    | 9017660119        | <b>TM38026</b><br>   |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS   | Panel, Door<br>Left               | 9417200470        | <b>TM38027</b><br>  |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS   | Panel, Door<br>Right              | 9417200570        | <b>TM38028</b><br> |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 | Panel, Door<br>Left               | 9417280856        | <b>TM19205</b><br> |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 | Panel, Door<br>Right              | 9417280956        | <b>TM19206</b><br> |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 | Panel, Door<br>Left               | 9417200348        | <b>TM19207</b><br> |





| TM No.  | Replaces Ref. No:        | Description          | Model / Details  |
|---|--------------------------|----------------------|--|
| <b>TM19208</b><br>   | 9417200448               | Panel, Door<br>Right | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 |
| <b>TM38029</b><br>   | 9607201101<br>9607201801 | Panel, Door<br>Left  | 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS   |
| <b>TM38030</b><br>   | 9607201201<br>9607201901 | Panel, Door<br>Right | 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS   |
| <b>TM38031</b><br> | 9607200701               | Panel, Door<br>Left  | 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS   |
| <b>TM38032</b><br> | 9607200801               | Panel, Door<br>Right | 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS   |
| <b>TM19407</b><br> | 9607200901               | Panel, Door<br>Left  | 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS   |
| <b>TM19408</b><br> | 9607201001               | Panel, Door<br>Right | 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS   |



| Model / Details  | Description                    | Replaces Ref. No:                                    | TM No.  |
|--|--------------------------------|--|---|
| 650 MK<br>651 MK<br>652 MK<br>653 MK<br>654 MK<br>699 MK<br>615 NG   | Lock, Door<br>Left             | 3817230201   | <b>TM18413</b><br>   |
| 650 MK<br>651 MK<br>652 MK<br>653 MK<br>654 MK<br>699 MK<br>615 NG   | Lock, Door<br>Right            | 3817230301   | <b>TM18412</b><br>   |
| 328 T2/L<br>338 L 1418<br>338 LK 1418<br>338 LS 1418<br>343 T2/L<br>343 T2/LN1<br>346 L 1924               | Lock, Door<br>Left             | 3227200035   | <b>TM18036</b><br>  |
| 328 T2/L<br>338 L 1418<br>338 LK 1418<br>338 LS 1418<br>343 T2/L<br>343 T2/LN1<br>346 L 1924               | Lock, Door<br>Right            | 3227200135   | <b>TM18035</b><br> |
| 405 UNIMOG<br>690 SPRINTER<br>901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER<br>905 SPRINTER | Lock, Door<br>Right            | 9017201135   | <b>TM19371</b><br> |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS   | Lock, Door<br>Left             | 9017201035<br>9017200135<br>0007206535<br>0007206735 | <b>TM18926</b><br> |
| 690 SPRINTER<br>901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER                               | Lock, Door<br>Right, Side Door | 9017301335   | <b>TM19377</b><br> |





| TM No.  | Replaces Ref. No:                      | Description         | Model / Details  |
|---|--|---------------------|--|
| <b>TM18930</b><br>   | 9737200735                             | Lock, Door<br>Left  | 375 ACTROS<br>375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>375 ATEGO 2                 |
| <b>TM18931</b><br>   | 9737200835                             | Lock, Door<br>Right | 375 ACTROS<br>375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>375 ATEGO 2                 |
| <b>TM18924</b><br>  | 9737200535                             | Lock, Door<br>Left  | 375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>976 ATEGO<br>375 ATEGO 2<br>958 ATEGO 2<br>970 ATEGO 2              |
| <b>TM18925</b><br> | 9737200635                             | Lock, Door<br>Right | 375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>976 ATEGO<br>375 ATEGO 2<br>958 ATEGO 2<br>970 ATEGO 2              |
| <b>TM18928</b><br> | 9437200635<br>0007205535<br>0007205735 | Lock, Door<br>Left  | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 |
| <b>TM18929</b><br> | 9437200735<br>0007205635<br>0007205835 | Lock, Door<br>Right | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 |
| <b>TM18927</b><br> | 0007206635<br>0007206835<br>9017200235 | Lock, Door<br>Right | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS   |





| Model / Details  | Description         | Replaces Ref. No: | TM No.  |
|--|---------------------|-------------------|---|
| 901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER   | Lock, Door<br>Left  | 9017301835        | <b>TM19378</b><br>   |
| 690 SPRINTER<br>901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER                             | Lock, Door<br>Right | 9017301935        | <b>TM19379</b><br>   |
| 901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER<br>638 VITO                                 | Lock, Door<br>Left  | 9017301035        | <b>TM19374</b><br>  |
| 690 SPRINTER<br>901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER<br>909 SPRINTER<br>638 VITO | Lock, Door<br>Right | 9017301135        | <b>TM19375</b><br> |
| 375 ACTROS<br>375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>375 ATEGO 2               | Lock, Door<br>Left  | 9737200135        | <b>TM18922</b><br> |
| 375 ACTROS<br>375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>375 ATEGO 2               | Lock, Door<br>Right | 9737200235        | <b>TM18923</b><br> |
| 690 SPRINTER<br>901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER                             | Lock, Door          | 9017400135        | <b>TM19380</b><br> |





| TM No.  | Replaces Ref. No:           | Description                                      | Model / Details  |
|---|-----------------------------|--|--|
| <b>TM18736</b><br>   | 6417600259                  | Handle, Door<br>Outside, Left                    | 650 MK<br>651 MK<br>652 MK<br>653 MK<br>654 MK<br>625 SK<br>655 SK   |
| <b>TM18737</b><br>   | 6417600359                  | Handle, Door<br>Outside, Right                   | 650 MK<br>651 MK<br>652 MK<br>653 MK<br>654 MK<br>625 SK<br>655 SK   |
| <b>TM18762</b><br>   | 6417230088                  | Handle, Door<br>Inside                           | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>650 MK<br>651 MK<br>652 MK   |
| <b>TM18748</b><br> | 9417600459                  | Handle, Door<br>Outside, Left                    | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3                   |
| <b>TM18952</b><br> | 9417600459S<br>6707600205S1 | Handle, Door<br>Left, With Cylinder and<br>Keys  | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3 |
| <b>TM18749</b><br> | 9417600559                  | Handle, Door<br>Outside, Right                   | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3                   |
| <b>TM18953</b><br> | 9417600559S<br>6707600205S2 | Handle, Door<br>Right, With Cylinder and<br>Keys | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3 |



| Model / Details   | Description                         | Replaces Ref. No:                                    | TM No.         |
|---|-------------------------------------|--|----------------|
| 375 ACTROS<br>375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>375 ATEGO 2  | Handle, Door<br>Outside, Left/Right | 0007601359   | <b>TM18675</b> |
| 690 SPRINTER<br>901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER<br>909 SPRINTER  | Handle, Door<br>Outside, Left/Right | 9017600459   | <b>TM19259</b> |
| 375 ACTROS<br>375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>958 ATEGO 2  | Handle, Door<br>Inside, Left        | 0007230035   | <b>TM18947</b> |
| 375 ACTROS<br>375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>958 ATEGO 2  | Handle, Door<br>Inside, Right       | 0007230135   | <b>TM18948</b> |
| 328 T2/L<br>343 T2/L<br>343 T2/LN1<br>346 L 1924<br>346 L 1928<br>346 LA 1924<br>346 LAK 1924   | Handle, Door<br>Outside, Left/Right | 3227660701   | <b>TM18041</b> |
| 397 LP 1014 MBSA-RSA<br>397 LP 1114,1214 MB-SA-RSA<br>397 LP 1517<br>397 LP/LPK 1314 MB-SA-RSA<br>397 LPK 1414 MBSA-RSA<br>611 T1/TN<br>667 T2/LN1  | Handle, Door<br>With Key, Outside   | 6707600159<br>6017600059<br>6017600159<br>3817660901 | <b>TM18414</b> |
| 397 LP 1014 MBSA-RSA<br>397 LP 1114,1214 MB-SA-RSA<br>397 LP 1517<br>397 LP/LPK 1314 MB-SA-RSA<br>397 LPK 1414 MBSA-RSA<br>667 T2/LN1<br>668 T2/LN1 | Handle, Door<br>Brown               | 6737200075   | <b>TM19444</b> |










| TM No.  | Replaces Ref. No:        | Description                           | Model / Details  |
|---|--------------------------|---------------------------------------|--|
| <b>TM19261</b><br>   | 9017200066<br>0007200375 | Handle, Door<br>Door Panelling, Left  | 690 SPRINTER<br>901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER                               |
| <b>TM19260</b><br>   | 9017200166               | Handle, Door<br>Door Panelling, Right | 690 SPRINTER<br>901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER                               |
| <b>TM18945</b><br>   | 9417200066               | Handle, Door<br>Inside, Left          | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>957 ECONIC   |
| <b>TM18946</b><br> | 9417200166               | Handle, Door<br>Inside, Right         | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>957 ECONIC   |
| <b>TM18955</b><br> | 9418900472<br>9418900272 | Handle, Door<br>Inside, Left          | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 |
| <b>TM18956</b><br> | 9418900572<br>9418900372 | Handle, Door<br>Inside, Right         | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 |
| <b>TM38033</b><br> | 9417600659               | Handle, Door<br>Outside, Left         | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>967 ATEGO 3  |



| Model / Details  | Description  | Replaces Ref. No:          | TM No.  |
|--|--|----------------------------|---|
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>967 ATEGO 3                        | Handle, Door<br>Outside, Right                       | 9417600759                 | <b>TM18949</b>  |
|  |  |                            |    |
| 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3<br>967 ATEGO 3        | Handle, Door<br>Outside, Left                        | 9437600159                 | <b>TM18950</b>  |
|  |  |                            |    |
| 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3<br>967 ATEGO 3        | Handle, Door<br>Outside, Right                       | 9437600259                 | <b>TM18951</b>  |
|  |  |                            |   |
| 900 SPRINTER<br>906 SPRINTER   | Handle, Door   | 9067600070                 | <b>TM18044</b>  |
|  |  |                            |  |
| 900 SPRINTER<br>906 SPRINTER   | Handle, Door   | 9067600170                 | <b>TM19258</b>  |
|  |  |                            |  |
| 375 ACTROS<br>375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>375 ATEGO 2 | Handle, Door<br>Outside, Left/Right, With<br>204.121 | 0007601359S<br>6707600205S | <b>TM18675</b>  |
|  |  |                            |  |
| 690 SPRINTER<br>901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER               | Cable, Door<br>Door Panelling                        | 9017600704<br>9017600304   | <b>TM38034</b>  |
|  |  |                            |  |



| TM No.  | Replaces Ref. No: | Description                   | Model / Details  |
|---|-------------------|-------------------------------|--|
| <b>TM18905</b><br>   | 9417200137        | Hinge, Door<br>Left           | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 |
| <b>TM18906</b><br>   | 9417200337        | Hinge, Door<br>Right          | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 |
| <b>TM38035</b><br>   | 9737200737        | Hinge, Door<br>Left           | 375 ACTROS<br>375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>375 ATEGO 2                 |
| <b>TM38036</b><br> | 9737200837        | Hinge, Door<br>Right          | 375 ACTROS<br>375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>375 ATEGO 2                 |
| <b>TM18902</b><br> | 9737201516        | Stop, Door<br>Left            | 375 ACTROS<br>375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>375 ATEGO 2                 |
| <b>TM18901</b><br> | 9737201416        | Stop, Door<br>Right           | 375 ACTROS<br>375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>375 ATEGO 2                 |
| <b>TM19349</b><br> | 9017600428        | Stop, Door<br>Rear Door, 180° | 628 SETRA<br>629 SETRA<br>690 SPRINTER<br>901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER     |





| Model / Details  | Description             | Replaces Ref. No:                      | TM No.  |
|--|-------------------------|--|---|
| 900 SPRINTER<br>906 SPRINTER   | Stop, Door<br>Rear      | 9067600228<br>9067600328               | <b>TM38037</b><br>   |
| 650 MK<br>651 MK<br>652 MK<br>653 MK<br>654 MK<br>625 SK<br>655 SK   | Arm Rest, Door<br>Left  | 6417200095                             | <b>TM34823</b><br>   |
| 650 MK<br>651 MK<br>652 MK<br>653 MK<br>654 MK<br>625 SK<br>655 SK   | Arm Rest, Door<br>Right | 6417200195                             | <b>TM34824</b><br>   |
| 638 V-CLASS<br>690 SPRINTER<br>638 V-CLASS<br>904 SPRINTER<br>904 SPRINTER<br>690 SPRINTER<br>901 SPRINTER<br>902 SPRINTER | Locking Eye, Door       | 9017660161<br>9017660061               | <b>TM38038</b><br> |
| 375 ACTROS<br>375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>375 ATEGO 2                                 | Lock Cylinder, Door     | 6707600205                             | <b>TM18899</b><br> |
| 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3                     | Lock Cylinder, Door     | 6708906367<br>0004620179<br>9014620179 | <b>TM05378</b><br> |
| 639 VIANO<br>900 SPRINTER<br>906 SPRINTER<br>639 VIANO<br>639 VITO   | Handle Cover, Door      | 6397470187                             | <b>TM38039</b><br> |












| TM No.  | Replaces Ref. No: | Description  | Model / Details  |
|---|-------------------|--|--|
| <b>TM38040</b><br>   | 9017601361        | Lever, Door<br>Side Door, Inside                   | 690 SPRINTER<br>901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER                 |
| <b>TM19263</b><br>   | 9017601047        | Slide Mechanism, Door<br>Side Door, Right, Top     | 690 SPRINTER<br>901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER<br>909 SPRINTER |
| <b>TM19262</b><br>   | 9017601347        | Slide Mechanism, Door<br>Side Door, Right, Top     | 690 SPRINTER<br>901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER<br>909 SPRINTER |
| <b>TM38041</b><br> | 9067600547S       | Slide Mechanism, Door<br>Side Door, Right, Top     | 900 SPRINTER<br>906 SPRINTER   |
| <b>TM19367</b><br> | 9067600347        | Slide Mechanism, Door<br>Side Door, Right, Top     | 900 SPRINTER<br>906 SPRINTER   |
| <b>TM19368</b><br> | 9067600147S       | Slide Mechanism, Door<br>Side Door, Right, Top     | 900 SPRINTER<br>906 SPRINTER   |
| <b>TM38042</b><br> | 6397601547S       | Slide Mechanism, Door<br>Side Door, Right, Central | 639 VIANO  |



| Model / Details  | Description                                       | Replaces Ref. No: | TM No.  |
|--|---|-------------------|---|
| 636 VIANO<br>639 VIANO   | Slide Mechanism, Door<br>Side Door, Right, Top    | 6397601347        | <b>TM38043</b><br>   |
| 636 VIANO<br>639 VIANO   | Slide Mechanism, Door<br>Side Door, Right, Bottom | 6397601747        | <b>TM38044</b><br>   |
| 901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER<br>906 SPRINTER<br>690 SPRINTER<br>900 SPRINTER<br>909 SPRINTER | Rawlplug, Door                                    | 9019880025        | <b>TM38045</b><br>   |
| 690 SPRINTER<br>901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER<br>909 SPRINTER                                 | Bracket, Door<br>Side Doors, Right, Bottom        | 9017600128        | <b>TM19220</b><br> |
| 900 SPRINTER<br>906 SPRINTER   | Bracket, Door<br>Rear                             | 9067600428        | <b>TM19352</b><br> |
| 650 MK<br>651 MK<br>652 MK<br>653 MK<br>654 MK<br>625 SK<br>655 SK   | Lift, Door Window<br>Left                         | 6417200246        | <b>TM18745</b><br> |
| 650 MK<br>651 MK<br>652 MK<br>653 MK<br>654 MK<br>625 SK<br>655 SK   | Lift, Door Window<br>Right                        | 6417200346        | <b>TM18746</b><br> |












| TM No.  | Replaces Ref. No: | Description       | Model / Details                          |
|---|-------------------|-------------------|--|
| <b>TM18099</b><br>   | 3717250302        | Lift, Door Window | 371 1817 K/4X2/36 MBT                    |
|   | 3717250002        | Left              | 371 1821 AK/4X4/36 MBT                   |
|   | 3717250902        |                   | 371 1821 K/4X2/36 MBT                    |
|   | 3817250002        |                   | 371 1922 K OTOMARSAN/<br>TUERKEI         |
|   |                   |                   |  |
|   |                   |                   | 371 1935 S/35,LS/35<br>OTOMARSAN/TUERKEI |
| <b>TM18411</b><br>   | 3717250402        | Lift, Door Window | 371 1817 K/4X2/36 MBT                    |
|   | 3717250102        | Right             | 371 1821 AK/4X4/36 MBT                   |
|   | 3717251002        |                   | 371 1821 K/4X2/36 MBT                    |
|   | 3817250102        |                   | 371 1922 K OTOMARSAN/<br>TUERKEI         |
|   |                   |                   |  |
|   |                   |                   | 371 1935 S/35,LS/35<br>OTOMARSAN/TUERKEI |
| <b>TM18759</b><br>   | 0007250002        | Lift, Door Window | 950 ACTROS                               |
|   |                   | Left              | 952 ACTROS                               |
|   |                   |                   | 953 ACTROS                               |
|   |                   |                   | 954 ACTROS                               |
|   |                   |                   |  |
| <b>TM18760</b><br> | 0007250102        | Lift, Door Window | 950 ACTROS                               |
|   |                   | Right             | 952 ACTROS                               |
|   |                   |                   | 953 ACTROS                               |
|   |                   |                   | 954 ACTROS                               |
|   |                   |                   |  |
| <b>TM18757</b><br> | 9417200446        | Lift, Door Window | BM MODEL                                 |
|   |                   | Left              | 950 ACTROS                               |
|   |                   |                   | 952 ACTROS                               |
|   |                   |                   | 953 ACTROS                               |
|   |                   |                   | 954 ACTROS                               |
| <b>TM18758</b><br> | 9417200546        | Lift, Door Window | 950 ACTROS                               |
|   |                   | Right             | 952 ACTROS                               |
|   |                   |                   | 953 ACTROS                               |
|   |                   |                   | 954 ACTROS                               |
|   |                   |                   |  |
| <b>TM18914</b><br> | 9017201446        | Lift, Door Window | 405 UNIMOG                               |
|   |                   | Left              | 690 SPRINTER                             |
|   |                   |                   | 901 SPRINTER                             |
|   |                   |                   | 902 SPRINTER                             |
|   |                   |                   | 903 SPRINTER                             |
|   |                   |                   | 904 SPRINTER                             |
|   |                   | 905 SPRINTER      |  |



| Model / Details  | Description   | Replaces Ref. No:        | TM No.  |
|--|---|--------------------------|---|
| 405 UNIMOG<br>690 SPRINTER<br>901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER<br>905 SPRINTER | Lift, Door Window<br>Right                              | 9017201546               | <b>TM18915</b><br>   |
| 375 ACTROS<br>375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>375 ATEGO 2                 | Lift, Door Window<br>With Electrical Motor, Left        | 9737200346               | <b>TM18910</b><br>   |
| 375 ACTROS<br>375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>375 ATEGO 2                 | Lift, Door Window<br>With Electrical Motor, Right       | 9737200446               | <b>TM18911</b><br>   |
| 375 ACTROS<br>375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>375 ATEGO 2                 | Lift, Door Window<br>Left                               | 9737200146<br>6937200146 | <b>TM18908</b><br> |
| 375 ACTROS<br>375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>375 ATEGO 2                 | Lift, Door Window<br>Right                              | 9737200246<br>6937200246 | <b>TM18909</b><br> |
| 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3                                       | Lift, Door Window<br>Without Electrical Motor,<br>Left  | 0007200079               | <b>TM18916</b><br> |
| 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3                                       | Lift, Door Window<br>Without Electrical Motor,<br>Right | 0007200179               | <b>TM18917</b><br> |





| TM No.  | Replaces Ref. No:          | Description                 | Model / Details  |
|---|----------------------------|-----------------------------|--|
| <b>TM18918</b><br>   | 0058209042                 | Motor, Door Window<br>Left  | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>405 UNIMOG       |
| <b>TM18919</b><br>   | 0058209142                 | Motor, Door Window<br>Right | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>405 UNIMOG       |
| <b>TM19082</b><br>   | 0008205108<br>0008202608   | Motor, Door Window<br>Left  | 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3     |
| <b>TM19083</b><br> | 0008205208<br>0008202708   | Motor, Door Window<br>Right | 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3     |
| <b>TM18921</b><br> | 0008205008<br>0008202908   | Motor, Door Window<br>Right | 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3     |
| <b>TM18920</b><br> | 0008204908<br>0008202808   | Motor, Door Window<br>Left  | 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3     |
| <b>TM18726</b><br> | 3817250043S<br>3817250060S | Crank, Door Window          | 309 T2/L<br>310 T2/L<br>313 T2/L<br>314 LP<br>316 LP<br>318 LP<br>353 LP |












| Model / Details   | Description        | Replaces Ref. No:        | TM No.  |
|---|--------------------|--------------------------|---|
| 901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER                                    | Crank, Door Window | 9017600302               | <b>TM38046</b><br>   |
| 979 ACCELO<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>958 ATEGO 2<br>958 AXOR 2 | Crank, Door Window | 9417600102               | <b>TM18941</b><br>   |
| 375 ACTROS<br>375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>375 ATEGO 2      | Crank, Door Window | 9737600002               | <b>TM18942</b><br>  |
| 650 MK<br>651 MK<br>652 MK<br>653 MK<br>654 MK<br>625 SK<br>655 SK                              | Crank, Door Window | 6417600004               | <b>TM18735</b><br> |
| 375 ACTROS<br>375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>375 ATEGO 2      | Crank, Door Window | 9737600004<br>9737600204 | <b>TM18935</b><br> |





| TM No.  | Replaces Ref. No:                                    | Description         | Model / Details  |
|---|--|---------------------|--|
| <b>TM18936</b><br>   | 9737600104<br>9737600304                             | Cable, Door Window  | 375 ACTROS<br>375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>375 ATEGO 2                   |
| <b>TM38047</b><br>   | 9017600504<br>9017660239                             | Cable, Door Window  | 690 SPRINTER<br>901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER<br>905 SPRINTER<br>906 SPRINTER |
| <b>TM19299</b><br>  | 9017600104   | Cable, Door Window  | 690 SPRINTER<br>901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER<br>909 SPRINTER                 |
| <b>TM18933</b><br> | 0007200213   | Cable, Door Window  | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS   |
| <b>TM18932</b><br> | 0007200113   | Cable, Door Window  | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS   |
| <b>TM18934</b><br> | 0007200513   | Cable, Door Window  | 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3   |
| <b>TM11893</b><br> | 0035455113<br>0025455113<br>0015450613<br>0045455113 | Switch, Door Window | 375 ACTROS<br>375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>976 ATEGO<br>375 ATEGO 2<br>958 ATEGO 2                 |



| Model / Details   | Description                  | Replaces Ref. No:                                    | TM No.  |
|---|------------------------------|--|---|
| 375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>976 ATEGO<br>375 ATEGO 2<br>970 ATEGO 2<br>972 ATEGO 2 | Switch, Door Window          | 0015452013<br>0045452013<br>0035452013<br>0025452013 | <b>TM12129</b><br>   |
| 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3                          | Switch, Door Window<br>Left  | 9438200097   | <b>TM11800</b><br>   |
| 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3                          | Switch, Door Window<br>Right | 9438200197   | <b>TM11801</b><br>  |
| 375 ACTROS<br>375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>976 ATEGO<br>375 ATEGO 2<br>958 ATEGO 2  | Switch, Door Window          | 0015451204<br>0015455913<br>0025455913<br>0035455913 | <b>TM12130</b><br> |
| 900 SPRINTER<br>906 SPRINTER  | Switch, Door Window<br>Left  | 9065450213<br>9065451213                             | <b>TM11939</b><br> |
| 900 SPRINTER<br>906 SPRINTER  | Switch, Door Window<br>Right | 9065450913<br>9065451913                             | <b>TM11943</b><br> |
| 639 VIANO<br>636 VIANO<br>639 VIANO<br>639 VITO   | Switch, Door Window<br>Left  | 6395450913   | <b>TM11940</b><br> |





| TM No.  | Replaces Ref. No:        | Description                                 | Model / Details                                      |
|---|--------------------------|---|--|
| <b>TM11941</b><br>   | 9065451513<br>9065450513 | Switch, Door Window<br>Right                | 906 SPRINTER   |
| <b>TM38048</b><br>   | 6397200146S              | Repair Kit, Door Window<br>Window Regulator | 639 VIANO  |
| <b>TM38049</b><br>   | 6397200046S              | Repair Kit, Door Window<br>Window Regulator | 639 VIANO  |
| <b>TM18772</b><br> | 9418840222               | Cab Corner<br>Left                          | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS |
| <b>TM18771</b><br> | 9418840322               | Cab Corner<br>Right                         | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS |
| <b>TM18782</b><br> | 9418840422               | Cab Corner<br>Left                          | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS |
| <b>TM18781</b><br> | 9418840522               | Cab Corner<br>Right                         | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS |



| Model / Details                                      | Description         | Replaces Ref. No: | TM No.  |
|--|---------------------|-------------------|---|
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS | Cab Corner<br>Left  | 9418840622        | <b>TM18849</b><br>   |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS | Cab Corner<br>Right | 9418840722        | <b>TM18850</b><br>   |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS | Cab Corner<br>Left  | 9418800344        | <b>TM38050</b><br>  |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS | Cab Corner<br>Right | 9418800444        | <b>TM38051</b><br> |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS | Cab Corner<br>Left  | 9418841122        | <b>TM18780</b><br> |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS | Cab Corner<br>Right | 9418841222        | <b>TM18779</b><br> |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS | Cab Corner<br>Left  | 9418841422        | <b>TM18770</b><br> |





| TM No.  | Replaces Ref. No: | Description         | Model / Details  |
|---|-------------------|---------------------|--|
| <b>TM18769</b><br>   | 9418841522        | Cab Corner<br>Right | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS                 |
| <b>TM18862</b><br>   | 9438840023        | Cab Corner<br>Left  | 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3 |
| <b>TM18861</b><br>   | 9438840123        | Cab Corner<br>Right | 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3 |
| <b>TM18864</b><br> | 9438840223        | Cab Corner<br>Left  | 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3 |
| <b>TM18863</b><br> | 9438840323        | Cab Corner<br>Right | 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3 |
| <b>TM18872</b><br> | 9438840623        | Cab Corner<br>Left  | 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3 |
| <b>TM18871</b><br> | 9438840723        | Cab Corner<br>Right | 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3 |



















| Model / Details   | Description                | Replaces Ref. No: | TM No.         |
|---|----------------------------|-------------------|----------------|
| 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3                          | Cab Corner<br>Inner, Left  | 9438841722        | <b>TM19252</b> |
|   |                            |                   |                |
| 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3                          | Cab Corner<br>Inner, Right | 9438841822        | <b>TM19253</b> |
|   |                            |                   |                |
| 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3                          | Cab Corner<br>Outer, Left  | 9438841922        | <b>TM19250</b> |
|   |                            |                   |                |
| 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3                          | Cab Corner<br>Outer, Right | 9438842022        | <b>TM19251</b> |
|   |                            |                   |                |
| 970 ATEGO 2<br>375 AXOR<br>374 AXOR 2<br>375 AXOR 2<br>940 AXOR 2<br>942 AXOR 2<br>943 AXOR 2 | Cab Corner<br>Left         | 9448840422        | <b>TM19106</b> |
|   |                            |                   |                |
| 970 ATEGO 2<br>375 AXOR<br>374 AXOR 2<br>375 AXOR 2<br>940 AXOR 2<br>942 AXOR 2<br>943 AXOR 2 | Cab Corner<br>Right        | 9448840522        | <b>TM19105</b> |
|   |                            |                   |                |
| 375 ACTROS<br>375 AXOR<br>375 AXOR 2<br>944 AXOR 2<br>950 AXOR 2<br>952 AXOR 2<br>953 AXOR 2  | Cab Corner<br>Left         | 9408800344        | <b>TM19569</b> |
|   |                            |                   |                |





| TM No.  | Replaces Ref. No: | Description         | Model / Details  |
|---|-------------------|---------------------|--|
| <b>TM19570</b><br>   | 9408800444        | Cab Corner<br>Right | 375 ACTROS<br>375 AXOR<br>375 AXOR 2<br>944 AXOR 2<br>950 AXOR 2<br>952 AXOR 2<br>953 AXOR 2 |
| <b>TM19431</b><br>   | 9608859908        | Cab Corner<br>Left  | 963 ACTROS MP4   |
| <b>TM19430</b><br>   | 9608859808        | Cab Corner<br>Right | 963 ACTROS MP4   |
| <b>TM19314</b><br> | 9607510430        | Cab Corner<br>Left  | 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS                                   |
| <b>TM19315</b><br> | 9607510530        | Cab Corner<br>Right | 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS                                   |
| <b>TM19503</b><br> | 9607511030        | Cab Corner<br>Left  | 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS                                   |
| <b>TM19504</b><br> | 9607511130        | Cab Corner<br>Right | 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS                                   |



| Model / Details  | Description         | Replaces Ref. No: | TM No.  |
|--|---------------------|-------------------|---|
| 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS   | Cab Corner<br>Left  | 9607510630        | <b>TM19519</b><br>   |
| 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS   | Cab Corner<br>Right | 9607510730        | <b>TM19520</b><br>   |
| 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS   | Cab Corner<br>Left  | 9607511230        | <b>TM19505</b><br>  |
| 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS   | Cab Corner<br>Right | 9607511330        | <b>TM19506</b><br> |
| 375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>976 ATEGO<br>375 ATEGO 2<br>958 ATEGO 2<br>970 ATEGO 2<br>972 ATEGO 2 | Cab Corner<br>Left  | 9738840222        | <b>TM19507</b><br> |
| 375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>976 ATEGO<br>375 ATEGO 2<br>958 ATEGO 2<br>970 ATEGO 2<br>972 ATEGO 2 | Cab Corner<br>Right | 9738840322        | <b>TM19508</b><br> |
| 375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>976 ATEGO<br>375 ATEGO 2<br>958 ATEGO 2<br>970 ATEGO 2<br>972 ATEGO 2 | Cab Corner<br>Left  | 9738840422        | <b>TM19557</b><br> |












| TM No.  | Replaces Ref. No:        | Description                        | Model / Details  |
|---|--------------------------|------------------------------------|--|
| <b>TM19558</b><br>   | 9738840522               | Cab Corner<br>Right                | 375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>976 ATEGO<br>375 ATEGO 2<br>958 ATEGO 2<br>970 ATEGO 2<br>972 ATEGO 2 |
| <b>TM19517</b><br>   | 9738840722               | Cab Corner<br>Left                 | 375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>976 ATEGO<br>375 ATEGO 2<br>970 ATEGO 2<br>972 ATEGO 2<br>974 ATEGO 2 |
| <b>TM19518</b><br>   | 9738840822               | Cab Corner<br>Right                | 375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>976 ATEGO<br>375 ATEGO 2<br>970 ATEGO 2<br>972 ATEGO 2<br>974 ATEGO 2 |
| <b>TM19110</b><br> | 9448840022               | Air Deflector, Cab Corner<br>Left  | 375 ATEGO<br>375 ATEGO 2<br>970 ATEGO 2<br>375 AXOR<br>374 AXOR 2<br>375 AXOR 2<br>940 AXOR 2                |
| <b>TM19109</b><br> | 9448840122<br>9448840722 | Air Deflector, Cab Corner<br>Right | 375 ATEGO<br>375 ATEGO 2<br>970 ATEGO 2<br>375 AXOR<br>374 AXOR 2<br>375 AXOR 2<br>940 AXOR 2                |
| <b>TM19108</b><br> | 9448840222               | Air Deflector, Cab Corner<br>Left  | 375 ATEGO<br>375 ATEGO 2<br>970 ATEGO 2<br>375 AXOR<br>374 AXOR 2<br>375 AXOR 2<br>940 AXOR 2                |
| <b>TM19107</b><br> | 9448840322               | Air Deflector, Cab Corner<br>Right | 375 ATEGO<br>375 ATEGO 2<br>970 ATEGO 2<br>375 AXOR<br>374 AXOR 2<br>375 AXOR 2<br>940 AXOR 2                |



| Model / Details  | Description                  | Replaces Ref. No: | TM No.         |
|--|------------------------------|-------------------|----------------|
| 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3                                       | Bracket, Cab Corner<br>Left  | 9438850063        | <b>TM19209</b> |
| 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3                                       | Bracket, Cab Corner<br>Right | 9438850163        | <b>TM19210</b> |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 | Gas Spring                   | 0019808464        | <b>TM18961</b> |












| TM No.  | Replaces Ref. No:                      | Description                  | Model / Details  |
|---|--|------------------------------|--|
| <b>TM38052</b><br>   | -                                      | Gas Spring<br>735 mm / 270 N | -  |
| <b>TM18755</b><br>   | 0009809064<br>0009806264               | Gas Spring<br>775 mm / 220 N | 650 MK<br>651 MK<br>652 MK<br>653 MK<br>654 MK<br>625 SK<br>655 SK                         |
| <b>TM18963</b><br>  | 0009806964<br>0009804964<br>0007503180 | Gas Spring<br>540 mm / 490 N | 668 T2/LN1<br>669 T2/LN1<br>670 T2/LN1<br>697 O 402<br>357 O 405<br>612 O 405<br>667 VARIO |
| <b>TM18965</b><br> | 6297501236                             | Gas Spring<br>585 mm / 800 N | 632 TOURISMO<br>629 TRAVEGO<br>632 TRAVEGO<br>629 SETRA<br>632 SETRA                       |
| <b>TM19300</b><br> | 6297500236                             | Gas Spring<br>753 mm / 320 N | 632 TOURISMO<br>629 TRAVEGO<br>632 TRAVEGO<br>410 SETRA<br>629 SETRA<br>632 SETRA          |
| <b>TM38053</b><br> | 6297500336                             | Gas Spring<br>753 mm / 420 N | 632 TOURISMO<br>629 TRAVEGO<br>632 TRAVEGO<br>410 SETRA<br>629 SETRA<br>632 SETRA          |
| <b>TM18957</b><br> | 6297500436                             | Gas Spring<br>753 mm / 220 N | 632 TRAVEGO<br>410 SETRA<br>629 SETRA<br>632 SETRA   |







| Model / Details  | Description | Replaces Ref. No:        | TM No.  |
|--|-------------|--------------------------|---|
| 632 TOURISMO<br>629 TRAVEGO<br>632 TRAVEGO<br>629 SETRA<br>632 SETRA                               | Gas Spring  | 6297500536               | <b>TM19301</b><br>   |
| 629 TRAVEGO<br>632 TRAVEGO   | Gas Spring  | 6297500636               | <b>TM19302</b><br>   |
| 632 TOURISMO<br>629 TRAVEGO<br>632 TRAVEGO<br>629 SETRA<br>632 SETRA                               | Gas Spring  | 6297500736               | <b>TM38054</b><br>  |
| 633 INTEGRO<br>633 INTOURO<br>632 TOURISMO<br>629 TRAVEGO<br>632 TRAVEGO<br>632 SETRA<br>633 SETRA | Gas Spring  | 0029801564               | <b>TM19305</b><br> |
| 629 SETRA  | Gas Spring  | 6297501436               | <b>TM19307</b><br> |
| 668 T2/LN1<br>669 T2/LN1<br>670 T2/LN1<br>697 O 402<br>357 O 405<br>612 O 405<br>667 VARIO         | Gas Spring  | 0009807064<br>0009801064 | <b>TM18966</b><br> |
| 357 O 405<br>612 O 405   | Gas Spring  | 0007503080<br>0009804864 | <b>TM38055</b><br> |





| TM No.  | Replaces Ref. No: | Description                  | Model / Details  |
|---|-------------------|------------------------------|--|
| <b>TM19303</b><br>   | 6297500936        | Gas Spring<br>580 mm / 520 N | 633 INTEGRO<br>633 INTOURO<br>632 TOURISMO<br>629 TRAVEGO<br>632 SETRA<br>633 SETRA                          |
| <b>TM18964</b><br>   | 0007502980        | Gas Spring<br>535 mm / 220 N | 697 O 402<br>357 O 405<br>612 O 405<br>628 CITARO  |
| <b>TM18962</b><br>   | 0007500336        | Gas Spring<br>582 mm / 150 N | 375 AXOR<br>944 AXOR 2<br>628 CITARO<br>632 TRAVEGO  |
| <b>TM18056</b><br> | 0009881501        | Gas Spring<br>512 mm / 120 N | 970 ATEGO 2<br>375 AXOR<br>374 AXOR 2<br>940 AXOR 2<br>942 AXOR 2<br>943 AXOR 2<br>944 AXOR 2                |
| <b>TM19450</b><br> | 0029808164        | Gas Spring<br>620 mm / 300 N | 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3   |
| <b>TM19449</b><br> | 0019807764        | Gas Spring<br>165 mm / 400 N | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3   |
| <b>TM38056</b><br> | 9017500359        | Hood Wire, Engine Bonnet     | 690 SPRINTER<br>901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER<br>905 SPRINTER<br>909 SPRINTER |



| Model / Details  | Description                                   | Replaces Ref. No:        | TM No.  |
|--|---|--------------------------|---|
| 906 SPRINTER   | Hood Wire, Engine Bonnet                      | 9068800059               | <b>TM38057</b>  |
|  |   |                          |    |
| 375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>375 ATEGO 2<br>958 ATEGO 2                | Hood Wire, Engine Bonnet                      | 9588910000               | <b>TM34876</b>  |
|  |   |                          |    |
| 636 VIANO<br>639 VIANO   | Hood Wire, Engine Bonnet                      | 6397500359<br>6397500159 | <b>TM38058</b>  |
|  |   |                          |   |
| 900 SPRINTER   | Grille, Engine Bonnet<br>Left                 | 9008360018               | <b>TM38059</b>  |
|  |   |                          |  |
| 900 SPRINTER   | Grille, Engine Bonnet<br>Right                | 9008360118               | <b>TM38060</b>  |
|  |   |                          |  |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 | Air Bellow, Seat<br>Repl. Monroe: SD0008      | 0008001236               | <b>TM35832</b>  |
|  |   |                          |  |
| 900 SPRINTER<br>906 SPRINTER   | Reflector, Lamp<br>Rear, Left, Without E Mark | 9068260040               | <b>TM38061</b>  |
|  |   |                          |  |





| TM No.  | Replaces Ref. No:                                    | Description                                       | Model / Details   |
|---|--|---|---|
| <b>TM38062</b><br>   | 9068260140   | Reflector, Lamp<br>Rear, Right, Without E<br>Mark | 900 SPRINTER<br>906 SPRINTER  |
| <b>TM11796</b><br>   | 0085450924<br>0075454024                             | Retarder Control Arm                              | 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3            |
| <b>TM11591</b><br>   | 6205400145   | Wiper Control Arm                                 | 615 LK/LN2<br>615 NG<br>616 NG<br>617 NG<br>619 NG<br>620 NG<br>621 NG  |
| <b>TM38063</b><br> | 0055457424<br>0065457824                             | Wiper Control Arm                                 | 611 T1/TN<br>601 207 D/208 D<br>601 208/210<br>601 209 D/210 D<br>602 307 D/308 D<br>602 307 D/308D<br>602 308 D  |
| <b>TM11505</b><br> | 0085450124<br>0075458224<br>0075453124               | Signal Control Arm<br>Turn Signal                 | 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3            |
| <b>TM11682</b><br> | 0055455124<br>0055451024<br>0055453824<br>0045454224 | Signal Control Arm<br>Turn Signal                 | 376 LP 1419 MBTC-USA<br>376 LPS 1525 MBTC-USA<br>615 LK/LN2<br>380 NG<br>381 NG<br>383 NG<br>385 NG               |
| <b>TM11683</b><br> | 6205400045<br>6955407045<br>6985407045<br>6885407045 | Signal Control Arm<br>Turn Signal                 | 376 LP 1219 MBTC-USA<br>376 LP 1419 MBTC-USA<br>376 LPS 1525 MBTC-USA<br>615 LK/LN2<br>699 MK<br>615 NG<br>616 NG |



| Model / Details   | Description                       | Replaces Ref. No:                                    | TM No.  |
|---|-----------------------------------|--|---|
| 650 MK<br>651 MK<br>652 MK<br>653 MK<br>654 MK<br>699 MK<br>625 SK                                      | Signal Control Arm<br>Turn Signal | 6555400045   | <b>TM11687</b><br>   |
| 373 O 302<br>373 O 303<br>373 O 304<br>373 O 330<br>600 O 330<br>600 O 340<br>357 O 405                 | Signal Control Arm<br>Turn Signal | 3575400045<br>3575409545                             | <b>TM11696</b><br>   |
| 314 LP<br>316 LP<br>318 LP<br>336 LP 1924<br>336 LPS 1924<br>338 L 1418<br>338 LK 1418                  | Signal Control Arm<br>Turn Signal | 0035458324<br>0025450424<br>0025453524<br>0035458124 | <b>TM11688</b><br>  |
| 667 T2/LN1<br>668 T2/LN1<br>669 T2/LN1<br>670 T2/LN1<br>673 LK/LN2<br>674 LK/LN2<br>675 LK/LN2          | Signal Control Arm<br>Turn Signal | 6735400445<br>6735400145                             | <b>TM11694</b><br> |
| 615 LK/LN2<br>380 NG<br>381 NG<br>383 NG<br>385 NG<br>387 NG<br>389 NG                                  | Signal Control Arm                | 0055455224<br>0055453924<br>0055451124<br>0045455324 | <b>TM11689</b><br> |
| 650 MK<br>651 MK<br>652 MK<br>653 MK<br>654 MK<br>699 MK<br>625 SK                                      | Signal Control Arm                | 6555400145   | <b>TM11693</b><br> |
| 690 SPRINTER<br>901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER<br>638 VITO<br>638 V-CLASS | Signal Control Arm                | 0005407445<br>0015404645                             | <b>TM10052</b><br> |





| TM No.  | Replaces Ref. No:        | Description   | Model / Details  |
|---|--------------------------|---|--|
| <b>TM11503</b><br>   | 0015404745               | Complete Control Arm  | 405 UNIMOG<br>901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER<br>905 SPRINTER                 |
| <b>TM11510</b><br>   | 0015404945               | Complete Control Arm  | 638 VITO<br>638 V-CLASS  |
| <b>TM34848</b><br>   | 0008301218               | Filter, Cab Heating &<br>Ventilation<br>Pollen<br>Repl. Mann: CU 3855<br>Repl. Hengst: E982LI                               | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 |
| <b>TM34978</b><br> | 6398350247               | Filter, Cab Heating &<br>Ventilation<br>Pollen<br>Repl. Mann: CU 3540<br>Repl. Hengst: E2913LI                              | 636 VIANO<br>639 VIANO   |
| <b>TM38064</b><br> | 6398350347               | Filter, Cab Heating &<br>Ventilation<br>Pollen, Activated Carbon<br>Filter<br>Repl. Mann: CUK 3540<br>Repl. Hengst: E2913LC | 636 VIANO<br>639 VIANO   |
| <b>TM34819</b><br> | 0008301118               | Filter, Cab Heating &<br>Ventilation<br>Pollen<br>Repl. Mann: CU3869<br>Repl. Hengst: E931LI                                | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 |
| <b>TM34888</b><br> | 0008301318<br>0008303418 | Filter, Cab Heating &<br>Ventilation<br>Pollen, Activated Carbon<br>Filter<br>Repl. Mann: CUK 3823<br>Repl. Hengst: E931LC  | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS   |





| Model / Details   | Description  | Replaces Ref. No:                                    | TM No.  |
|---|--|--|---|
| 375 ACTROS<br>970 ATEGO 2<br>375 AXOR<br>374 AXOR 2<br>375 AXOR 2<br>940 AXOR 2<br>942 AXOR 2 | Filter, Cab Heating &<br>Ventilation<br>Pollen<br>Repl. Mann: CU 4469<br>Repl. Hengst: E980LI  | 9408350047   | <b>TM34847</b><br>   |
| 375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>375 ATEGO 2<br>958 ATEGO 2   | Filter, Cab Heating &<br>Ventilation<br>Pollen<br>Repl. Mann: CU 5877<br>Repl. Hengst: E933LI  | 9738350147   | <b>TM34885</b><br>   |
| 375 ACTROS<br>970 ATEGO 2<br>375 AXOR<br>374 AXOR 2<br>375 AXOR 2<br>940 AXOR 2<br>942 AXOR 2 | Filter, Cab Heating &<br>Ventilation<br>Pollen<br>Repl. Mann: CU 4408<br>Repl. Hengst: E1945LI | 9408350247   | <b>TM34889</b><br>   |
| 690 SPRINTER<br>901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER<br>905 SPRINTER  | Filter, Cab Heating &<br>Ventilation<br>Pollen<br>Repl. Mann: CU 3858<br>Repl. Hengst: E912LI  | 0008303318<br>9018300018<br>9018300518               | <b>TM34977</b><br> |
| 906 SPRINTER  | Filter, Cab Heating &<br>Ventilation<br>Pollen<br>Repl. Mann: CU 3569<br>Repl. Hengst: E2916LI | 9068300218   | <b>TM34953</b><br> |
| 638 VITO<br>638 V-CLASS   | Filter, Cab Heating &<br>Ventilation<br>Pollen<br>Repl. Mann: CU 3759<br>Repl. Hengst: E963LI  | 0008353047<br>0018353047<br>0028350847<br>6388350047 | <b>TM38065</b><br> |
| -   | Fan Motor, Cab Heating &<br>Ventilation<br>Repl. Hella: 8EW 009<br>160-021                     | 0018300208   | <b>TM34575</b><br> |





| TM No.  | Replaces Ref. No: | Description  | Model / Details  |
|---|-------------------|--|--|
| <b>TM34576</b><br>   | 0018300308        | Fan Motor, Cab Heating & Ventilation<br>Repl. Behr: 8EW 009<br>160-641 | 650 MK<br>651 MK<br>652 MK<br>653 MK<br>654 MK<br>625 SK<br>655 SK   |
| <b>TM34893</b><br>   | 0018308708        | Fan Motor, Cab Heating & Ventilation<br>Repl. Behr: 8EW 009<br>158-071 | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS                 |
| <b>TM34894</b><br>  | 0028308408        | Fan Motor, Cab Heating & Ventilation<br>Repl. Behr: 8EW 351<br>024-481 | 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3 |
| <b>TM34899</b><br> | 0038300508        | Fan Motor, Cab Heating & Ventilation<br>Repl. Behr: 8EW 351<br>029-041 | 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3 |





| Model / Details   | Description                                 | Replaces Ref. No:        | TM No.  |
|---|---|--------------------------|---|
| 375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>976 ATEGO<br>375 ATEGO 2<br>958 ATEGO 2<br>970 ATEGO 2 | Heater Fan, Cab Heating & Ventilation       | 0038300108               | <b>TM35006</b><br>   |
| -   | Fuel Tank, Cab Heating & Ventilation        | 3714707002<br>3718307361 | <b>TM38066</b><br>   |
| 375 ACTROS<br>375 ATEGO<br>375 ATEGO 2<br>970 ATEGO 2<br>375 AXOR<br>374 AXOR 2<br>375 AXOR 2 | Heating Hoses,<br>Cab Heating & Ventilation | 9408320094               | <b>TM38067</b><br>   |
| 375 ACTROS<br>375 AXOR<br>375 AXOR 2<br>944 AXOR 2<br>950 AXOR 2<br>952 AXOR 2<br>953 AXOR 2  | Heating Hoses,<br>Cab Heating & Ventilation | 9408320023               | <b>TM38068</b><br> |
| 375 ACTROS<br>375 AXOR<br>375 AXOR 2<br>944 AXOR 2<br>950 AXOR 2<br>952 AXOR 2<br>953 AXOR 2  | Heating Hoses,<br>Cab Heating & Ventilation | 9408320123               | <b>TM38069</b><br> |
| 375 AXOR<br>374 AXOR 2<br>940 AXOR 2<br>942 AXOR 2<br>943 AXOR 2<br>944 AXOR 2<br>958 AXOR 2  | Heating Hoses,<br>Cab Heating & Ventilation | 9405061835               | <b>TM35095</b><br> |
| 375 AXOR<br>374 AXOR 2<br>940 AXOR 2<br>942 AXOR 2<br>943 AXOR 2<br>944 AXOR 2<br>958 AXOR 2  | Heating Hoses,<br>Cab Heating & Ventilation | 9405061735               | <b>TM08367</b><br> |







| TM No.  | Replaces Ref. No:                        | Description  | Model / Details  |
|---|--|--|--|
| <b>TM38070</b><br>   | 9705010882                               | Heating Hoses,<br>Cab Heating & Ventilation                  | 375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>958 ATEGO 2<br>970 ATEGO 2  |
| <b>TM35080</b><br>   | 6555060035                               | Heating Hoses,<br>Cab Heating & Ventilation                  | 650 MK<br>651 MK<br>652 MK<br>653 MK<br>654 MK<br>625 SK<br>655 SK                           |
| <b>TM35098</b><br>   | 9405063035                               | Heating Hoses,<br>Cab Heating & Ventilation                  | 375 AXOR<br>374 AXOR 2<br>940 AXOR 2<br>942 AXOR 2<br>943 AXOR 2<br>944 AXOR 2<br>958 AXOR 2 |
| <b>TM38071</b><br> | 9405000475                               | Heating Hoses,<br>Cab Heating & Ventilation                  | 950 AXOR 2<br>952 AXOR 2<br>953 AXOR 2<br>954 AXOR 2<br>958 AXOR 2                           |
| <b>TM35075</b><br> | 900271018038<br>9738320194<br>9738320294 | Heating Hoses,<br>Cab Heating & Ventilation<br>ø18xø26x1000  | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO  |
| <b>TM38072</b><br> | 9405061435                               | Heating Hoses,<br>Cab Heating & Ventilation<br>ø18/ø19,5x290 | 950 AXOR 2<br>952 AXOR 2   |
| <b>TM38073</b><br> | 9018323823                               | Heating Hoses,<br>Cab Heating & Ventilation<br>ø18xø15x293   | 690 SPRINTER<br>901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER                 |



| Model / Details  | Description                                 | Replaces Ref. No:                                    | TM No.  |
|--|---|--|---|
| 690 SPRINTER<br>901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER<br>905 SPRINTER<br>906 SPRINTER | Heating Hoses,<br>Cab Heating & Ventilation | 9018320123   | <b>TM38080</b><br>   |
| 901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER   | Heating Hoses,<br>Cab Heating & Ventilation | 9018325923<br>9018326723<br>9018323423<br>9018325123 | <b>TM38081</b><br>   |
| 901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER   | Heating Hoses,<br>Cab Heating & Ventilation | 9018326123<br>9018324123                             | <b>TM38082</b><br>  |
| 901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER   | Heating Hoses,<br>Cab Heating & Ventilation | 9018326023<br>9018324623                             | <b>TM38083</b><br> |
| 901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER<br>909 SPRINTER                                 | Heating Hoses,<br>Cab Heating & Ventilation | 9018323723   | <b>TM38084</b><br> |
| 690 SPRINTER<br>901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER                                 | Heating Hoses,<br>Cab Heating & Ventilation | 9018323923<br>9018327823                             | <b>TM38085</b><br> |
| 375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>958 ATEGO 2<br>970 ATEGO 2                  | Heating Hoses,<br>Cab Heating & Ventilation | 9705010482   | <b>TM38086</b><br> |












| TM No.  | Replaces Ref. No: | Description                                 | Model / Details  |
|---|-------------------|---|--|
| <b>TM38087</b><br>   | 9738300096        | Heating Hoses,<br>Cab Heating & Ventilation | 375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>375 ATEGO 2<br>958 ATEGO 2                  |
| <b>TM38088</b><br>   | 9068322223        | Heating Hoses,<br>Cab Heating & Ventilation | 906 SPRINTER   |
| <b>TM38089</b><br>   | 9018322823        | Heating Hoses,<br>Cab Heating & Ventilation | 690 SPRINTER<br>901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER<br>905 SPRINTER<br>909 SPRINTER |
| <b>TM38090</b><br> | 9018324223        | Heating Hoses,<br>Cab Heating & Ventilation | 690 SPRINTER<br>901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER<br>905 SPRINTER<br>909 SPRINTER |
| <b>TM38091</b><br> | 9018323623        | Heating Hoses,<br>Cab Heating & Ventilation | 690 SPRINTER<br>901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER<br>905 SPRINTER<br>909 SPRINTER |
| <b>TM38092</b><br> | 9018324723        | Heating Hoses,<br>Cab Heating & Ventilation | 690 SPRINTER<br>901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER<br>905 SPRINTER<br>909 SPRINTER |
| <b>TM38093</b><br> | 9018324323        | Heating Hoses,<br>Cab Heating & Ventilation | 690 SPRINTER<br>901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER<br>905 SPRINTER<br>909 SPRINTER |





















| Model / Details  | Description                                 | Replaces Ref. No: | TM No.  |
|--|---|-------------------|---|
| 690 SPRINTER<br>901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER<br>905 SPRINTER<br>909 SPRINTER | Heating Hoses,<br>Cab Heating & Ventilation | 9018324923        | <b>TM38094</b><br>   |
| 690 SPRINTER<br>901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER<br>905 SPRINTER<br>909 SPRINTER | Heating Hoses,<br>Cab Heating & Ventilation | 9018324823        | <b>TM38095</b><br>   |
| 690 SPRINTER<br>901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER                                 | Heating Hoses,<br>Cab Heating & Ventilation | 9018325523        | <b>TM38096</b><br>  |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3   | Heating Hoses,<br>Cab Heating & Ventilation | 9418300196        | <b>TM38097</b><br> |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3   | Heating Hoses,<br>Cab Heating & Ventilation | 9418300096        | <b>TM38098</b><br> |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS   | Heating Hoses,<br>Cab Heating & Ventilation | 9418300396        | <b>TM38099</b><br> |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS   | Heating Hoses,<br>Cab Heating & Ventilation | 9418300296        | <b>TM38100</b><br> |







| TM No.  | Replaces Ref. No:                                    | Description   | Model / Details  |
|---|--|---|--|
| <b>TM08198</b><br>   | 9305060235   | Heating Hoses,<br>Cab Heating & Ventilation         | 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3                                       |
| <b>TM34764</b><br>   | 0009107238   | Valve, Seat   | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 |
| <b>TM38101</b><br>   | 9418902290<br>9418900390<br>9418901190<br>9408900090 | Storage Box, Accessory<br>Left                      | 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>970 ATEGO 2<br>375 AXOR              |
| <b>TM38102</b><br> | 9418900490   | Storage Box, Accessory<br>Right                     | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS   |
| <b>TM34903</b><br> | 9408900576   | Storage Compartment<br>Panel,<br>Accessory<br>Left  | 970 ATEGO 2<br>375 AXOR<br>374 AXOR 2<br>940 AXOR 2<br>942 AXOR 2<br>943 AXOR 2<br>944 AXOR 2              |
| <b>TM34904</b><br> | 9408900676   | Storage Compartment<br>Panel,<br>Accessory<br>Right | 970 ATEGO 2<br>375 AXOR<br>374 AXOR 2<br>940 AXOR 2<br>942 AXOR 2<br>943 AXOR 2<br>944 AXOR 2              |
| <b>TM34877</b><br> | 9418900070   | Storage Box Cable, Ac-<br>cessory                   | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 |



| Model / Details  | Description   | Replaces Ref. No:                       | TM No.  |
|--|---|---|---|
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS   | Storage Box Cable, Accessory  | 9418900170                              | <b>TM38103</b><br>   |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS   | Storage Box Cable, Accessory  | 9418900291                              | <b>TM38104</b><br>   |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS   | Storage Box Cable, Accessory  | 9418900091                              | <b>TM38105</b><br>  |
| 697 O 402<br>357 O 405<br>612 O 405  | Mirror<br>Repl. Mekra: 51.25301.20H<br>ø18/370x182                                      | 0008102716<br>3818102516<br>3818107116  | <b>TM18021</b><br> |
| 314 LP<br>316 LP<br>318 LP<br>673 LK/LN2<br>674 LK/LN2<br>675 LK/LN2<br>676 LK/LN2               | Mirror<br>With E Mark<br>Repl. Mekra:<br>51.25401.20H<br>ø18/305x183                    | 0008100416<br>3148101316                | <b>TM19070</b><br> |
| -  | Mirror<br>With E Mark<br>Repl. Mekra:<br>51.25401.40H<br>ø18/305x183                    | 3148102016                              | <b>TM38106</b><br> |
| 384 L 1215<br>384 LK 1215<br>386 L 1615<br>386 L 1620<br>386 L 1622<br>386 L 1633<br>386 LK 1615 | Mirror<br>Repl. Mekra:<br>51.25801.20H<br>Repl. Mekra:<br>51.25801.40H S<br>ø18/423x203 | 3818103716<br>3848107116<br>3818103816S | <b>TM18025</b><br> |





| TM No.  | Replaces Ref. No:          | Description   | Model / Details  |
|---|----------------------------|---|--|
| <b>TM38107</b><br>   | 6738104616<br>6738104716S  | Mirror<br>Repl. Mekra:<br>56.28501.20H<br>Repl. Mekra:<br>56.2850.140H S<br>ø18/184x184 | -  |
| <b>TM38108</b><br>   | 6418104716<br>6418106316   | Mirror<br>Repl. Mekra:<br>59.26901.27H<br>294x164                                       | 650 MK<br>651 MK<br>652 MK<br>653 MK<br>654 MK<br>625 SK<br>655 SK   |
| <b>TM38109</b><br>   | 6418104616                 | Mirror<br>Repl. Mekra:<br>56.36701.47H<br>ø28/225x185                                   | 650 MK<br>651 MK<br>652 MK<br>653 MK<br>654 MK<br>625 SK<br>655 SK   |
| <b>TM38110</b><br> | 6418104216                 | Mirror<br>Repl. Mekra: 51.36801.47H<br>ø28/440x182                                      | 650 MK<br>651 MK<br>652 MK<br>653 MK<br>654 MK<br>625 SK<br>655 SK   |
| <b>TM19001</b><br> | 9408102616                 | Mirror<br>Repl. Mekra:<br>59.37931.27H<br>310x170                                       | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/  |
| <b>TM38111</b><br> | 0008111307S<br>0018109216S | Mirror<br>With E Mark<br>ø28/200x200  | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 |
| <b>TM19002</b><br> | 0018109116                 | Mirror<br>With E Mark<br>Repl. Mekra:<br>61.37831.67H<br>ø28/433x188                    | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 |



| Model / Details  | Description  | Replaces Ref. No:         | TM No.  |
|--|--|---------------------------|---|
| 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3 | Mirror<br>With E Mark  | 9438105116                | <b>TM19218</b><br>   |
| -  | Mirror<br>Left, With E Mark<br>Repl. Mekra:<br>51.5892.113.199<br>344x450        | 9068102293S<br>9068106416 | <b>TM38112</b><br>   |
| -  | Mirror<br>Right, With E Mark<br>Repl. Mekra:<br>51.5892.213.199<br>344x450       | 9068102393S<br>9068106516 | <b>TM38113</b><br>  |
| 906 SPRINTER   | Mirror Glass<br>Left, With E Mark<br>Repl. Mekra:<br>19.5890.011.099<br>263x155  | 0028115233                | <b>TM38114</b><br> |
| 906 SPRINTER   | Mirror Glass<br>Right, With E Mark<br>Repl. Mekra:<br>19.5890.012.099<br>263x155 | 0028115333                | <b>TM38115</b><br> |
| 906 SPRINTER   | Cover, Mirror<br>Left<br>Repl. Mekra:<br>13.5890.110                             | 0008111022                | <b>TM19269</b><br> |
| 906 SPRINTER   | Cover, Mirror<br>Right<br>Repl. Mekra:<br>13.5890.210                            | 0008111122                | <b>TM19268</b><br> |





| TM No.   | Replaces Ref. No:                      | Description  | Model / Details  |
|--|--|--|--|
| <b>TM38116</b><br>                                                           | 9608101619<br>9608103516               | Mirror<br>Left, With E Mark<br>Repl. Mekra:<br>59.6000.003.099<br>912x340x140  | 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS |
| <b>TM38117</b><br>                                                     | 9608102219<br>9608103616<br>9608104716 | Mirror<br>Right, With E Mark<br>Repl. Mekra:<br>59.6000.015.099<br>912x338x140 | 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS |
| <b>TM38118</b><br>                                            | 9068103293                             | Mirror<br>Left, With E Mark  | 906 SPRINTER   |
| <b>TM38119</b><br>                                   | 9068103393                             | Mirror<br>Right, With E Mark   | 906 SPRINTER   |
| <b>TM38120</b><br>                           | 6398100619                             | Mirror<br>Left, Manual, With E Mark  | 639 VIANO  |
| <b>TM38121</b><br>                   | 6398100719                             | Mirror<br>Right, Manual, With E Mark   | 639 VIANO  |
| <b>TM38122</b><br>          | 6398100819                             | Mirror<br>Left, Electrical, With E<br>Mark                                     | 639 VIANO<br>639 VITO                                      |





| Model / Details  | Description   | Replaces Ref. No:        | TM No.  |
|--|---|--------------------------|---|
| 639 VIANO<br>639 VITO                                      | Mirror<br>Right, Electrical, With E<br>Mark   | 6398100919               | <b>TM38123</b><br>   |
| 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS | Mirror Glass<br>Left, With E Mark<br>Repl. Mekra:<br>15.6000.001.099<br>430x193x34  | 0028116333<br>0028118933 | <b>TM19130</b><br>   |
| 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS | Mirror Glass<br>Right, With E Mark<br>Repl. Mekra:<br>15.6000.002.099<br>430x193x34 | 0028116433<br>0028119033 | <b>TM19131</b><br>  |
| 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS | Cover, Mirror<br>Left<br>700x256x98   | 9608111007               | <b>TM38124</b><br> |
| 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS | Cover, Mirror<br>Right<br>700x256x98  | 9608111107               | <b>TM38125</b><br> |
| 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS | Arm, Mirror<br>Left<br>Repl. Mekra:<br>58.6000.003.099<br>912x78xø28                | 0018117614               | <b>TM38126</b><br> |
| 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS | Arm, Mirror<br>Right<br>Repl. Mekra:<br>58.6000.011.099<br>912x102xø28              | 0018117714<br>0018117814 | <b>TM38127</b><br> |












| TM No.  | Replaces Ref. No:        | Description   | Model / Details  |
|---|--------------------------|---|--|
| <b>TM19132</b><br>   | 0028116533<br>0028119133 | Mirror Glass<br>Left, With E Mark<br>Repl. Mekra:<br>15.6000.003.099<br>204x236x5     | 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS |
| <b>TM19133</b><br>   | 0028116633<br>0028119233 | Mirror Glass<br>Right, With E Mark<br>Repl. Mekra:<br>15.6000.004.099<br>204x236x51   | 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS |
| <b>TM19630</b><br>   | 9608112007               | Cover, Mirror<br>Left<br>254x184x92   | 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS |
| <b>TM19629</b><br> | 9608112107               | Cover, Mirror<br>Right<br>254x184x92  | 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS |
| <b>TM38128</b><br> | 9608111407               | Cover, Mirror<br>Left<br>Repl. Mekra:<br>11.6001.110.099<br>254x184x92<br>254x184x92  | 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS |
| <b>TM38129</b><br> | 9608111507               | Cover, Mirror<br>Right<br>Repl. Mekra:<br>11.6001.210.099<br>254x184x92<br>254x184x92 | 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS |
| <b>TM38130</b><br> | 9608111807               | Cover, Mirror<br>Left<br>Repl. Mekra:<br>11.6001.136.099<br>254x184x92<br>254x184x92  | 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS |



| Model / Details  | Description  | Replaces Ref. No:                      | TM No.  |
|--|--|--|---|
| 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS | Cover, Mirror<br>Right<br>Repl. Mekra:<br>11.6001.236.099<br>254x184x92        | 9608111907                             | <b>TM38131</b><br>   |
| 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS | Mirror<br>Left, With E Mark<br>Repl. Mekra:<br>59.6000.001.099<br>912x440x140  | 9608101416<br>9608103316               | <b>TM38132</b><br>   |
| 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS | Mirror<br>Right, With E Mark<br>Repl. Mekra:<br>59.6000.013.099<br>912x437x140 | 9608102019<br>9608103416<br>9608104316 | <b>TM38133</b><br>   |
| 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS | Cover, Mirror<br>Left<br>Repl. Mekra:<br>11.6000.110.099                       | 9608110607                             | <b>TM38134</b><br> |
| 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS | Cover, Mirror<br>Right<br>Repl. Mekra:<br>11.6000.210.099                      | 9608110707                             | <b>TM38135</b><br> |
| 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS | Arm, Mirror<br>Left<br>Repl. Mekra:<br>58.6000.001.099                         | 0018117014                             | <b>TM38136</b><br> |
| 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS | Arm, Mirror<br>Right<br>Repl. Mekra:<br>58.6000.009.099                        | 0018117114<br>0018117214               | <b>TM38137</b><br> |





| TM No.  | Replaces Ref. No:                        | Description  | Model / Details  |
|---|--|--|--|
| <b>TM38138</b><br>   | 9068102693S<br>9068105616S<br>9068106816 | Mirror<br>Left, With E Mark<br>Repl. Mekra:<br>51.5893.113.199<br>344x543  | -  |
| <b>TM38139</b><br>   | 9068102793S<br>9068105716S<br>9068106916 | Mirror<br>Right, With E Mark<br>Repl. Mekra:<br>51.5893.213.199<br>344x543 | -  |
| <b>TM38140</b><br>   | 9068103893                               | Mirror<br>Left, With E Mark<br>Repl. Mekra:<br>51.5893.112.199<br>344x543  | -  |
| <b>TM38141</b><br> | 9068103993                               | Mirror<br>Right, With E Mark<br>Repl. Mekra:<br>51.5893.212.199<br>344x543 | -  |
| <b>TM38142</b><br> | 0028111933S<br>0028113933                | Mirror Glass<br>Left, With E Mark<br>154x59                                | 906 SPRINTER   |
| <b>TM38143</b><br> | 0028112033S<br>0028114033                | Mirror Glass<br>Right, With E Markk<br>154x59                              | 906 SPRINTER   |
| <b>TM19115</b><br> | 9608103016                               | Mirror<br>With E Mark<br>Repl. Mekra:<br>59.6030.001.099<br>666x319x249    | 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS |



| Model / Details  | Description   | Replaces Ref. No:                          | TM No.  |
|--|---|--|---|
| 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS   | Mirror Glass<br>With E Mark<br>Repl. Mekra:<br>61.6030.001.099<br>243x182x3 | 0028116233                                 | <b>TM19459</b><br>   |
| 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS   | Cover, Mirror<br>Repl. Mekra:<br>20.6031.210.099<br>440x236x42              | 9608113007                                 | <b>TM38144</b><br>   |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 | Mirror Glass<br>With E Mark<br>Repl. Mekra:<br>15.37808.40H<br>ø28/433x188  | 0028110433                                 | <b>TM18888</b><br>   |
| 375 ACTROS<br>375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>375 ATEGO 2                 | Mirror<br>With E Mark<br>ø28/380x170  | 0008100279S<br>0008111307S1<br>0018113433S | <b>TM38145</b><br> |
| 375 ACTROS<br>375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>375 ATEGO 2                 | Mirror<br>With E Mark<br>ø28/380x170  | 0008100379S<br>0008111307S2<br>0018113433S | <b>TM38146</b><br> |
| 375 ACTROS<br>375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>375 ATEGO 2                 | Mirror Glass<br>With E Mark<br>Repl. Mekra:<br>15.37524.70H<br>ø28/380x170  | 0018113433                                 | <b>TM18880</b><br> |
| 375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>976 ATEGO<br>375 ATEGO 2<br>970 ATEGO 2<br>972 ATEGO 2              | Mirror<br>With E Mark<br>Repl. Mekra:<br>61.57701.47H<br>ø28/215x199        | 0008101679                                 | <b>TM19066</b><br> |





| TM No.  | Replaces Ref. No:         | Description  | Model / Details  |
|---|---------------------------|--|--|
| <b>TM18885</b>  | 0028110033                | Mirror Glass<br>With E Mark<br>Repl. Mekra:<br>15.57708.70H<br>ø28/192x186 | 375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>976 ATEGO<br>375 ATEGO 2<br>970 ATEGO 2<br>972 ATEGO 2              |
|    |                           |  |  |
| <b>TM19064</b>  | 0008101879<br>0008101779S | Mirror<br>With E Mark<br>Repl. Mekra:<br>61.57511.67H<br>ø28/435x215       | 375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>976 ATEGO<br>375 ATEGO 2<br>970 ATEGO 2<br>972 ATEGO 2              |
|    |                           |  |  |
| <b>TM19065</b>  | 0008101579<br>0008101479S | Mirror<br>With E Mark<br>Repl. Mekra:<br>61.57521.67H<br>ø28/435x215       | 375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>976 ATEGO<br>375 ATEGO 2<br>970 ATEGO 2<br>972 ATEGO 2              |
|    |                           |  |  |
| <b>TM18884</b>  | 0018119933                | Mirror Glass<br>With E Mark<br>Repl. Mekra:<br>15.57508.40H<br>ø28/431x186 | 375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>976 ATEGO<br>375 ATEGO 2<br>970 ATEGO 2<br>972 ATEGO 2              |
|  |                           |  |  |
| <b>TM19003</b>  | 0028100816                | Mirror<br>With E Mark<br>Repl. Mekra:<br>59.57901.10H<br>303x163           | 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3     |
|  |                           |  |  |
| <b>TM19004</b>  | 0028112233                | Mirror Glass<br>With E Mark<br>Repl. Mekra:<br>15.57914.70H<br>303x163     | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 |
|  |                           |  |  |














| Model / Details   | Description  | Replaces Ref. No:         | TM No.  |
|---|--|---------------------------|---|
| 906 SPRINTER  | Mirror<br>With E Mark<br>Repl. Mekra:<br>51.58911.13H<br>344x318 | 9068106016<br>9068104816S | <b>TM19248</b><br>   |
| 906 SPRINTER  | Mirror<br>Repl. Mekra:<br>51.58912.13H<br>344x318                | 9068106116<br>9068104916S | <b>TM19249</b><br>   |
| 906 SPRINTER  | Mirror Glass<br>Left<br>Repl. Mekra:<br>15.58917.41H<br>236x155  | 0028111533                | <b>TM38147</b><br>   |
| 906 SPRINTER  | Mirror Glass<br>Right<br>Repl. Mekra:<br>15.58917.42H<br>236x155 | 0028111633                | <b>TM38148</b><br> |
| 375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>375 ATEGO 2<br>970 ATEGO 2 | Mirror   | 9408107316                | <b>TM19445</b><br> |
| 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3                        | Mirror<br>Left   | 0028102616S               | <b>TM38149</b><br> |
| 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3                        | Mirror<br>Right  | 0028102716S               | <b>TM38150</b><br> |





| TM No.  | Replaces Ref. No: | Description   | Model / Details  |
|---|-------------------|---|--|
| <b>TM19084</b><br>   | 0028113333        | Mirror Glass<br>Left<br>401x200                         | 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3                                       |
| <b>TM19085</b><br>   | 0028113433        | Mirror Glass<br>Right<br>401x200                        | 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3                                       |
| <b>TM38151</b><br>   | 9438110307        | Cover, Mirror<br>Left                                   | 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3                                       |
| <b>TM38152</b><br> | 9438110407        | Cover, Mirror<br>Right                                  | 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3                                       |
| <b>TM19086</b><br> | 0028113733        | Mirror Glass<br>Left<br>191x193                         | 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3                                       |
| <b>TM19087</b><br> | 0028113833        | Mirror Glass<br>Right<br>191x193                        | 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3                                       |
| <b>TM18883</b><br> | 0028110333        | Mirror Glass<br>Repl. Mekra:<br>15.37914.70H<br>310x170 | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 |



| Model / Details   | Description                         | Replaces Ref. No: | TM No.  |
|---|-------------------------------------|-------------------|---|
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS  | Arm, Mirror<br>Without Cable, Left  | 0018104414S       | <b>TM38153</b><br>   |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS  | Arm, Mirror<br>Without Cable, Right | 0018104514S       | <b>TM38154</b><br>   |
| 375 ACTROS<br>375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>375 ATEGO 2    | Arm, Mirror<br>Left                 | 9738100314        | <b>TM18895</b><br>  |
| 375 ACTROS<br>375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>375 ATEGO 2    | Arm, Mirror<br>Right                | 9738100414        | <b>TM18896</b><br> |
| 375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>976 ATEGO<br>375 ATEGO 2<br>970 ATEGO 2<br>972 ATEGO 2 | Arm, Mirror<br>Right, With Cable    | 0018109814        | <b>TM19011</b><br> |
| 375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>976 ATEGO<br>375 ATEGO 2<br>970 ATEGO 2<br>972 ATEGO 2 | Arm, Mirror<br>Left, With Cable     | 0018109714        | <b>TM19010</b><br> |
| 906 SPRINTER  | Bracked Cover, Mirror               | 9068110007        | <b>TM38155</b><br> |












| TM No.  | Replaces Ref. No: | Description             | Model / Details  |
|---|-------------------|-------------------------|--|
| <b>TM38156</b><br>   | 9068110107        | Bracketed Cover, Mirror | 906 SPRINTER   |
| <b>TM18844</b><br>   | 9738110410        | Sun Visor               | 375 ACTROS<br>375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>375 ATEGO 2 |
| <b>TM18843</b><br>   | 9418101010        | Sun Visor               | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS                                       |
| <b>TM18846</b><br> | 9418110810        | Sun Visor               | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS                                       |
| <b>TM18847</b><br> | 9438110010        | Sun Visor               | 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3                       |
| <b>TM18848</b><br> | 9438110210        | Sun Visor               | 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3                       |
| <b>TM18680</b><br> | 9418100010        | Sun Visor               | BM MODEL<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS                           |





| Model / Details   | Description                                    | Replaces Ref. No:                       | TM No.         |
|---|--|---|----------------|
| 970 ATEGO<br>972 ATEGO<br>976 ATEGO<br>958 ATEGO 2<br>970 ATEGO 2<br>972 ATEGO 2<br>974 ATEGO 2         | Sun Visor                                      | 9738110510                              | <b>TM19075</b> |
| 375 ACTROS<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>970 ATEGO 2<br>972 ATEGO 2            | Sun Visor                                      | 9738110310                              | <b>TM38157</b> |
| 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3                                    | Sun Visor                                      | 9438100910                              | <b>TM38158</b> |
| 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3                                    | Sun Visor                                      | 9438100810                              | <b>TM38159</b> |
| 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS  | Sun Visor                                      | 9608110110<br>9608112310                | <b>TM19406</b> |
| 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS  | Lamp, Sun Visor<br>Led, With E Mark            | 0038203256<br>0038207356                | <b>TM12002</b> |
| 375 ACTROS<br>375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>375 ATEGO 2<br>958 ATEGO | Windscreen Wiper, Mech-<br>anism<br>With Motor | 9738200181<br>0028204441<br>0058209642S | <b>TM19469</b> |





| TM No.  | Replaces Ref. No:  | Description  | Model / Details   |
|---|--|--|---|
| <b>TM19228</b><br>   | 9018200044   | Arm, Windscreen Wiper<br>Left                                  | 690 SPRINTER<br>901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER<br>905 SPRINTER<br>909 SPRINTER  |
| <b>TM19229</b><br>   | 9018200144   | Arm, Windscreen Wiper<br>Right                                 | 690 SPRINTER<br>901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER<br>905 SPRINTER<br>909 SPRINTER  |
| <b>TM38160</b><br>   | 9068200644<br>0018205844                                 | Arm, Windscreen Wiper<br>Left                                  | 906 SPRINTER  |
| <b>TM38161</b><br> | 0018205944   | Arm, Windscreen Wiper<br>Right                                 | 906 SPRINTER  |
| <b>TM38162</b><br> | 3898200045S<br>0018201145S<br>0018200145S<br>0018204745S | Blade, Windscreen Wiper<br>Without Nozzle, Click-fit           | 375 ACTROS<br>375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>375 ATEGO 2  |
| <b>TM38163</b><br> | 0018201245S<br>0018204845S<br>0018206945S                | Blade, Windscreen Wiper<br>Without Nozzle, Click-fit<br>700 mm | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3  |
| <b>TM38164</b><br> | 0008208245S<br>0008205045S<br>0008209245S<br>0008209345S | Blade, Windscreen Wiper<br>Without Nozzle, Click-fit<br>600 mm | 397 LP 1014 MBSA-RSA<br>397 LP 1114,1214 MB-<br>SA-RSA<br>397 LP 1517<br>397 LP/LPK 1314 MB-<br>SA-RSA<br>397 LPK 1414 MBSA-RSA<br>673 LK/LN2<br>674 LK/LN2 |





| Model / Details  | Description   | Replaces Ref. No:  | TM No.  |
|--|---|--|---|
| 699 MK<br>615 NG<br>616 NG<br>617 NG<br>619 NG<br>620 NG<br>621 NG   | Blade, Windscreen Wiper<br>Without Nozzle, Screw<br>Connection<br>700 mm                | 0008203645S<br>0008203745S<br>0008207345S<br>0008209745S | <b>TM38165</b><br>   |
| ATEGO - ATEGO 2 - AXOR<br>- AXOR 2   | Blade, Windscreen Wiper<br>Without Nozzle, Hook<br>Connection,<br>Banana Type<br>650 mm | -  | <b>TM38166</b><br>   |
| 397 LP 1014 MBSA-RSA<br>397 LP 1114,1214 MB-<br>SA-RSA<br>397 LP/LPK 1314 MB-<br>SA-RSA<br>397 LPK 1414 MBSA-RSA<br>673 LK/LN2<br>674 LK/LN2<br>675 LK/LN2 | Motor, Windscreen Wiper   | 0048206742<br>0038205042<br>0018241501<br>0038202742     | <b>TM18898</b><br>   |
| 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3   | Washer Container, Wind-<br>screen Wiper   | 9438690320<br>9438690020                                 | <b>TM38167</b><br> |
| 638 V-CLASS<br>638 V-CLASS<br>904 SPRINTER<br>904 SPRINTER<br>901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER                                 | Washer Container Cap,<br>Windscreen<br>Wiper  | 6388690008   | <b>TM38168</b><br> |
| 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3   | Washer Container Pump,<br>Windscreen<br>Wiper   | 0008694021   | <b>TM17987</b><br> |
| 970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>970 ATEGO 2<br>972 ATEGO 2<br>974 ATEGO 2<br>975 ATEGO 2   | Nozzle, Windscreen Wiper  | 6318690024   | <b>TM38169</b><br> |



| TM No.  | Replaces Ref. No:        | Description                        | Model / Details  |
|---|--------------------------|------------------------------------|--|
| <b>TM18467</b><br>   | 0008602326               | Motor, Head Lamp Wiper             | BM MODEL   |
|   | 0008602826<br>0008604726 | Repl. Hella: 8TW 004<br>764-041    | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 |
| <b>TM18983</b><br>   | 0058209642               | Motor, Head Lamp Wiper             | 375 ACTROS   |
|   |                          | Repl. Valeo: 404398                | 375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>375 ATEGO 2<br>958 ATEGO 2                |
| <b>TM28266</b><br>   | 0005531010               | Compressor Air Spring,<br>Climate  | 375 ACTROS   |
|   |                          | Repl. Contitech: SZ 35-11          | 970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>958 ATEGO 2<br>970 ATEGO 2                             |
| <b>TM18865</b><br> | 9418811501               | Mudguard<br>With reflector, Left   | BM MODEL   |
|   |                          |                                    | 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>375 AXOR<br>374 AXOR 2               |
| <b>TM18866</b><br> | 9418811601               | Mudguard<br>With reflector, Right  | 375 ACTROS   |
|   |                          |                                    | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>375 AXOR<br>374 AXOR 2                             |
| <b>TM38170</b><br> | 9415220004S              | Mudguard<br>Center, Without Rubber | 954 ACTROS   |
|   |                          |                                    | 375 AXOR<br>944 AXOR 2<br>954 AXOR 2   |
| <b>TM21836</b><br> | 9415200119               | Mudguard<br>Left                   | 954 ACTROS   |
|   |                          |                                    | 375 AXOR<br>944 AXOR 2<br>954 AXOR 2   |



| Model / Details  | Description                | Replaces Ref. No:          | TM No.  |
|--|----------------------------|----------------------------|---|
| 954 ACTROS<br>375 AXOR<br>944 AXOR 2<br>954 AXOR 2   | Mudguard<br>Right          | 9415200219                 | <b>TM18776</b>  |
|  |                            |                            |    |
| 954 ACTROS<br>375 AXOR<br>944 AXOR 2<br>954 AXOR 2   | Mudguard<br>Left           | 9415200320<br>9415200120   | <b>TM18778</b>  |
|  |                            |                            |    |
| 954 ACTROS<br>375 AXOR<br>944 AXOR 2<br>954 AXOR 2   | Mudguard<br>Right          | 9415201620<br>9415200220   | <b>TM18777</b>  |
|  |                            |                            |    |
| 954 ACTROS<br>934 ACTROS 2/3<br>375 AXOR<br>374 AXOR 2<br>944 AXOR 2<br>954 AXOR 2<br>958 AXOR 2 | Mudguard                   | 9305200020                 | <b>TM19030</b>  |
|  |                            |                            |  |
| 954 ACTROS<br>934 ACTROS 2/3<br>375 AXOR<br>374 AXOR 2<br>944 AXOR 2<br>954 AXOR 2<br>958 AXOR 2 | Mudguard<br>Without Rubber | 9305200007S<br>9305200207S | <b>TM38171</b>  |
|  |                            |                            |  |
| 954 ACTROS<br>934 ACTROS 2/3<br>375 AXOR<br>374 AXOR 2<br>944 AXOR 2<br>954 AXOR 2<br>958 AXOR 2 | Mudguard<br>Left           | 9305200019                 | <b>TM19029</b>  |
|  |                            |                            |  |
| 954 ACTROS<br>934 ACTROS 2/3<br>375 AXOR<br>374 AXOR 2<br>944 AXOR 2<br>954 AXOR 2<br>958 AXOR 2 | Mudguard<br>Right          | 9305200119                 | <b>TM19031</b>  |
|  |                            |                            |  |





| TM No.  | Replaces Ref. No:        | Description                                  | Model / Details  |
|---|--------------------------|--|--|
| <b>TM19032</b>  | 9305200120               | Mudguard                                     | 954 ACTROS<br>934 ACTROS 2/3<br>375 AXOR<br>374 AXOR 2<br>944 AXOR 2<br>954 AXOR 2<br>958 AXOR 2           |
|    |                          |  |  |
| <b>TM19529</b>  | 9438800406               | Mudguard<br>Right                            | 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3                                       |
|    |                          |  |  |
| <b>TM19528</b>  | 9438800306               | Mudguard<br>Left                             | 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3                                       |
|    |                          |  |  |
| <b>TM38172</b>  | 9438813701<br>9418814201 | Mudguard<br>Rear Left                        | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 |
|  |                          |  |  |
| <b>TM38173</b>  | 9438813801<br>9418814301 | Mudguard<br>Rear Right                       | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 |
|  |                          |  |  |
| <b>TM19577</b>  | 9705210601<br>9705212801 | Mudguard<br>Front Wheel, Rear Left/<br>Right | 375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>375 ATEGO 2<br>970 ATEGO 2<br>974 ATEGO 2              |
|  |                          |  |  |
| <b>TM38174</b>  | 9745220402               | Mudguard<br>Rear Wheel, Top Left/Right       | 970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>970 ATEGO 2<br>974 ATEGO 2<br>975 ATEGO 2<br>976 ATEGO 2            |
|  |                          |  |  |



| Model / Details   | Description                                       | Replaces Ref. No: | TM No.         |
|---|---|-------------------|----------------|
| 970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>970 ATEGO 2<br>974 ATEGO 2<br>975 ATEGO 2<br>976 ATEGO 2 | Mudguard<br>Rear Wheel, Front/Rear/<br>Left/Right | 9745220501        | <b>TM38175</b> |
|   |   |                   |                |
| 906 SPRINTER  | Mudguard<br>Front Wheel, Top Left                 | 9066377719        | <b>TM38176</b> |
|   |   |                   |                |
| 906 SPRINTER  | Mudguard<br>Front Wheel, Top Right                | 9066377819        | <b>TM38177</b> |
|   |   |                   |                |
| 900 SPRINTER<br>906 SPRINTER  | Mudguard<br>Front Wheel, Rear Left                | 9066302007        | <b>TM19582</b> |
|   |   |                   |                |
| 900 SPRINTER<br>906 SPRINTER  | Mudguard<br>Front Wheel, Rear Right               | 9066302107        | <b>TM19583</b> |
|   |   |                   |                |
| 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS                                      | Mudguard<br>Rear Wheel, Front Left                | 9605200019        | <b>TM19325</b> |
|   |   |                   |                |
| 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS                                      | Mudguard<br>Rear Wheel, Front Right               | 9605200119        | <b>TM19324</b> |
|   |   |                   |                |





| TM No.  | Replaces Ref. No: | Description   | Model / Details   |
|---|-------------------|---|---|
| <b>TM19327</b><br>   | 9605200007        | Mudguard<br>Rear Wheel, Top Left/Right<br>1190x185x700 mm | 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS  |
| <b>TM19328</b><br>   | 9605200107        | Mudguard<br>Rear Wheel, Top Left/Right<br>1225x215x700 mm | 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS  |
| <b>TM19326</b><br>  | 9605200520        | Mudguard<br>Rear Wheel, Rear Left/<br>Right               | 963 ACTROS MP4<br>964 ACTROS MP4<br>964 AROCS   |
| <b>TM19595</b><br> | 9605200220        | Mudguard<br>Rear Wheel, Rear Left/<br>Right               | 963 ACTROS MP4<br>964 AROCS<br>963 ACTROS MP4<br>964 ACTROS MP4<br>964 AROCS<br>964 AROCS                           |
| <b>TM38178</b><br> | 9068810101        | Mudguard<br>Left  | 906 SPRINTER  |
| <b>TM38179</b><br> | 9068810201        | Mudguard<br>Right   | 906 SPRINTER  |
| <b>TM19473</b><br> | 9608817102        | Mudguard<br>Left  | 963 ACTROS MP4<br>964 AROCS<br>964 AROCS<br>963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS<br>964 AROCS |





| Model / Details   | Description                     | Replaces Ref. No: | TM No.  |
|---|---------------------------------|-------------------|---|
| 963 ACTROS MP4<br>964 AROCS<br>964 AROCS<br>963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS<br>964 AROCS | Mudguard<br>Right               | 9608813403        | <b>TM19474</b><br>   |
| 963 ACTROS MP4<br>964 AROCS<br>964 AROCS<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS<br>964 AROCS                   | Mudguard<br>Left                | 9608813503        | <b>TM38180</b><br>   |
| 963 ACTROS MP4<br>964 AROCS<br>964 AROCS<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS<br>964 AROCS                   | Mudguard<br>Right               | 9608813603        | <b>TM38181</b><br>  |
| 375 ACTROS<br>970 ATEGO 2<br>375 AXOR<br>374 AXOR 2<br>375 AXOR 2<br>940 AXOR 2<br>942 AXOR 2<br>943 AXOR 2         | Mudguard<br>Left                | 9408803006        | <b>TM38182</b><br> |
| 375 ACTROS<br>970 ATEGO 2<br>375 AXOR<br>374 AXOR 2<br>375 AXOR 2<br>940 AXOR 2<br>942 AXOR 2<br>943 AXOR 2         | Mudguard<br>Right               | 9408803106        | <b>TM38183</b><br> |
| 900 SPRINTER<br>906 SPRINTER  | Bracket, Mudguard<br>Top, Left  | 9066230525        | <b>TM38184</b><br> |
| 900 SPRINTER<br>906 SPRINTER  | Bracket, Mudguard<br>Top, Right | 9066230625        | <b>TM38185</b><br> |





| TM No.  | Replaces Ref. No:        | Description                             | Model / Details  |
|---|--------------------------|---|--|
| <b>TM38186</b><br>   | 9066230725               | Bracket, Mudguard<br>Bottom, Left       | 900 SPRINTER<br>906 SPRINTER   |
| <b>TM38187</b><br>   | 9066230825               | Bracket, Mudguard<br>Bottom, Right      | 900 SPRINTER<br>906 SPRINTER   |
| <b>TM38188</b><br>  | 6386980430               | Wheel Housing, Mudguard<br>Front, Left  | 638 V-CLASS<br>638 V-CLASS<br>638 V-CLASS<br>638 VITO<br>638 V-CLASS |
| <b>TM38189</b><br> | 6386980530               | Wheel Housing, Mudguard<br>Front, Right | 638 V-CLASS<br>638 V-CLASS<br>638 V-CLASS<br>638 VITO<br>638 V-CLASS |
| <b>TM38190</b><br> | 9066841777<br>9066840377 | Wheel Housing, Mudguard<br>Front Right  | 906 SPRINTER   |
| <b>TM38191</b><br> | 9066840277               | Wheel Housing, Mudguard<br>Front Left   | 906 SPRINTER   |
| <b>TM38192</b><br> | 9066841877<br>9066841377 | Wheel Housing, Mudguard<br>Rear Right   | 906 SPRINTER   |



| <i>Model / Details</i>   | <i>Description</i>                   | <i>Replaces Ref. No:</i> | <i>TM No.</i>   |
|--|--------------------------------------|--------------------------|---|
| 906 SPRINTER   | Wheel Housing, Mudguard<br>Rear Left | 9066841277               | <b>TM38193</b>  |
|  |                                      |                          |    |
| 901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER<br>905 SPRINTER<br>909 SPRINTER | Mudflap, Mudguard<br>Front, Left     | 9018820105               | <b>TM38194</b>  |
|  |                                      |                          |    |
| 901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER<br>905 SPRINTER<br>909 SPRINTER | Mudflap, Mudguard<br>Front, Right    | 9018820405               | <b>TM38195</b>  |
|  |                                      |                          |    |
| 906 SPRINTER   | Mudflap, Mudguard<br>Front, Left     | 9068820004               | <b>TM38196</b>  |
|  |                                      |                          |  |
| 906 SPRINTER   | Mudflap, Mudguard<br>Front, Right    | 9068820104               | <b>TM38197</b>  |
|  |                                      |                          |  |
| 906 SPRINTER   | Mudflap, Mudguard<br>Rear, Left      | 9068820204               | <b>TM38198</b>  |
|  |                                      |                          |  |
| 906 SPRINTER   | Mudflap, Mudguard<br>Rear, Right     | 9068820304               | <b>TM38199</b>  |
|  |                                      |                          |  |





| TM No.  | Replaces Ref. No: | Description                       | Model / Details  |
|---|-------------------|-----------------------------------|--|
| <b>TM38200</b><br>   | B66580000         | Mudflap, Mudguard<br>Front, Left  | -  |
| <b>TM38201</b><br>   | B66580000R        | Mudflap, Mudguard<br>Front, Right | -  |
| <b>TM38202</b><br>   | B66580001         | Mudflap, Mudguard<br>Rear, Left   | -  |
| <b>TM38203</b><br> | B66580001R        | Mudflap, Mudguard<br>Rear, Right  | -  |
| <b>TM19023</b><br> | 9415240029        | Cover, Mudguard<br>Left           | 954 ACTROS<br>375 AXOR<br>944 AXOR 2<br>954 AXOR 2                   |
| <b>TM19024</b><br> | 9415240129        | Cover, Mudguard<br>Right          | 954 ACTROS<br>375 AXOR<br>944 AXOR 2<br>954 AXOR 2                   |
| <b>TM38204</b><br> | 9436660837        | Cover, Mudguard<br>Left           | 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3 |



| Model / Details   | Description              | Replaces Ref. No:        | TM No.         |
|---|--------------------------|--------------------------|----------------|
| 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3  | Cover, Mudguard<br>Right | 9436660937               | <b>TM38205</b> |
|   |                          |                          |                |
| 970 ATEGO 2<br>375 AXOR<br>374 AXOR 2<br>940 AXOR 2<br>942 AXOR 2<br>943 AXOR 2<br>944 AXOR 2                       | Cover, Mudguard<br>Left  | 9408900525               | <b>TM34905</b> |
|   |                          |                          |                |
| 970 ATEGO 2<br>375 AXOR<br>374 AXOR 2<br>940 AXOR 2<br>942 AXOR 2<br>943 AXOR 2<br>944 AXOR 2                       | Cover, Mudguard<br>Right | 9408900625               | <b>TM34906</b> |
|   |                          |                          |                |
| 963 ACTROS MP4<br>964 AROCS<br>964 AROCS<br>963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS<br>964 AROCS | Cover, Mudguard<br>Left  | 9608816803<br>9608817203 | <b>TM19477</b> |
|   |                          |                          |                |
| 963 ACTROS MP4<br>964 AROCS<br>964 AROCS<br>963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS<br>964 AROCS | Cover, Mudguard<br>Right | 9608816903<br>9608817303 | <b>TM19478</b> |
|   |                          |                          |                |
| 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS  | Rubber Strap, Mudguard   | 9605200067               | <b>TM19329</b> |
|   |                          |                          |                |
| 954 ACTROS<br>375 AXOR<br>944 AXOR 2<br>954 AXOR 2  | Rubber Strap, Mudguard   | 9415220067               | <b>TM18787</b> |
|   |                          |                          |                |



| TM No.  | Replaces Ref. No:                                    | Description            | Model / Details  |
|---|--|------------------------|--|
| <b>TM18977</b><br>   | 9415220167   | Rubber Strap, Mudguard | 954 ACTROS<br>934 ACTROS 2/3<br>375 AXOR<br>374 AXOR 2<br>944 AXOR 2<br>954 AXOR 2<br>958 AXOR 2 |
| <b>TM38208</b><br>   | 9416601928   | Step                   | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS   |
| <b>TM38209</b><br>  | 9416602128   | Step                   | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS   |
| <b>TM38210</b><br> | 9065200031<br>9065200331<br>9065200531<br>9065200631 | Step<br>Rear           | 906 SPRINTER   |
| <b>TM19237</b><br> | 9606661703<br>9616661601                             | Step<br>Left           | 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS                                       |
| <b>TM19236</b><br> | 9606661903<br>9616661801                             | Step<br>Right          | 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS                                       |
| <b>TM38211</b><br> | 9616662401   | Step<br>Left           | 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS                                       |





| Model / Details  | Description                            | Replaces Ref. No: | TM No.  |
|--|--|-------------------|---|
| 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS | Step<br>Right                          | 9616662601        | <b>TM38212</b>  |
|  |  |                   |    |
| 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS | Step<br>Left                           | 9606664103        | <b>TM19635</b>  |
|  |  |                   |    |
| 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS | Step<br>Right                          | 9606665103        | <b>TM19636</b>  |
|  |  |                   |   |
| 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS | Step<br>Left                           | 9606662628        | <b>TM38213</b>  |
|  |  |                   |  |
| 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS | Step<br>Right                          | 9606662528        | <b>TM38214</b>  |
|  |  |                   |  |
| 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS | Plate, Step<br>Upper/Lower, Left/Right | 9606662228        | <b>TM19231</b>  |
|  |  |                   |  |
| 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS | Plate, Step<br>Upper, Left/Right       | 9606662128        | <b>TM19648</b>  |
|  |  |                   |  |





| TM No.             | Replaces Ref. No: | Description          | Model / Details  |
|--------------------|-------------------|----------------------|--|
| <b>TM18824</b><br> | 9736661528        | Plate, Step<br>Left  | 375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>375 ATEGO 2<br>958 ATEGO 2                |
| <b>TM18825</b><br> | 9736661628        | Plate, Step<br>Right | 375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>375 ATEGO 2<br>958 ATEGO 2                |
| <b>TM18826</b><br> | 9736661428        | Plate, Step          | 375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>375 ATEGO 2<br>958 ATEGO 2                |
| <b>TM18837</b><br> | 9416663328        | Plate, Step          | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 |
| <b>TM18838</b><br> | 9416663428        | Plate, Step          | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 |
| <b>TM18839</b><br> | 9416663528        | Plate, Step          | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 |
| <b>TM18840</b><br> | 9416663728        | Plate, Step<br>Left  | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 |










| Model / Details  | Description           | Replaces Ref. No: | TM No.         |
|--|-----------------------|-------------------|----------------|
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 | Plate, Step<br>Right  | 9416663828        | <b>TM18841</b> |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS   | Plate, Step<br>Left   | 9416601028        | <b>TM18834</b> |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS   | Plate, Step<br>Right  | 9416601128        | <b>TM18835</b> |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS   | Plate, Step<br>Center | 9416600428        | <b>TM18700</b> |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS   | Plate, Step<br>Left   | 9416601628        | <b>TM18836</b> |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS   | Plate, Step<br>Right  | 9416601728        | <b>TM38215</b> |
| 970 ATEGO 2<br>375 AXOR<br>374 AXOR 2<br>940 AXOR 2<br>942 AXOR 2<br>943 AXOR 2<br>944 AXOR 2              | Plate, Step           | 9436660028        | <b>TM18821</b> |





| <i>TM No.</i>   | <i>Replaces Ref. No:</i> | <i>Description</i>     | <i>Model / Details</i>   |
|---|--------------------------|------------------------|--|
| <b>TM19230</b><br>   | 9406660428               | Plate, Step<br>Bottom  | 375 ACTROS<br>970 ATEGO 2<br>375 AXOR<br>374 AXOR 2<br>375 AXOR 2<br>940 AXOR 2<br>942 AXOR 2              |
| <b>TM18817</b><br>   | 9406660128               | Plate, Step<br>Top     | 375 ACTROS<br>970 ATEGO 2<br>375 AXOR<br>374 AXOR 2<br>375 AXOR 2<br>940 AXOR 2<br>942 AXOR 2              |
| <b>TM38216</b><br>   | 9586662301               | Housing, Step<br>Left  | 958 AXOR 2   |
| <b>TM38217</b><br> | 9586662401               | Housing, Step<br>Right | 958 AXOR 2   |
| <b>TM18822</b><br> | 9736663101<br>9736661301 | Housing, Step<br>Left  | 375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>375 ATEGO 2<br>970 ATEGO 2                |
| <b>TM18823</b><br> | 9736663201<br>9736661401 | Housing, Step<br>Right | 375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>375 ATEGO 2<br>970 ATEGO 2                |
| <b>TM21837</b><br> | 9416661901               | Housing, Step<br>Left  | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 |



| Model / Details  | Description            | Replaces Ref. No:        | TM No.  |
|--|------------------------|--------------------------|---|
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 | Housing, Step<br>Right | 9416662001               | <b>TM18678</b>  |
|  |                        |                          |    |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS   | Housing, Step<br>Left  | 9416603601               | <b>TM19050</b>  |
|  |                        |                          |    |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS   | Housing, Step<br>Right | 9416603701               | <b>TM19051</b>  |
|  |                        |                          |   |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS   | Housing, Step<br>Left  | 9416600201<br>9416660201 | <b>TM18774</b>  |
|  |                        |                          |  |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS   | Housing, Step<br>Right | 9416600301<br>9416660301 | <b>TM18773</b>  |
|  |                        |                          |  |
| 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3                                       | Housing, Step<br>Left  | 9436601001               | <b>TM18796</b>  |
|  |                        |                          |  |
| 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3                                       | Housing, Step<br>Right | 9436601101               | <b>TM18797</b>  |
|  |                        |                          |  |





| TM No.  | Replaces Ref. No:        | Description            | Model / Details   |
|---|--------------------------|------------------------|---|
| <b>TM19019</b><br>   | 9436600801               | Housing, Step<br>Left  | 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3                          |
| <b>TM19018</b><br>   | 9436600901               | Housing, Step<br>Right | 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3                          |
| <b>TM19040</b><br>   | 9436660801               | Housing, Step<br>Left  | 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/                           |
| <b>TM19041</b><br> | 9436660901               | Housing, Step<br>Right | 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3                          |
| <b>TM19062</b><br> | 9446661301<br>9586662101 | Housing, Step<br>Left  | 970 ATEGO 2<br>375 AXOR<br>374 AXOR 2<br>940 AXOR 2<br>942 AXOR 2<br>943 AXOR 2<br>944 AXOR 2 |
| <b>TM19063</b><br> | 9446661401<br>9586662001 | Housing, Step<br>Right | 970 ATEGO 2<br>375 AXOR<br>374 AXOR 2<br>940 AXOR 2<br>942 AXOR 2<br>943 AXOR 2<br>944 AXOR 2 |
| <b>TM19052</b><br> | 9406662401               | Housing, Step<br>Left  | 970 ATEGO 2<br>375 AXOR<br>374 AXOR 2<br>940 AXOR 2<br>942 AXOR 2<br>943 AXOR 2<br>944 AXOR 2 |












| Model / Details   | Description                           | Replaces Ref. No:                                       | TM No.  |
|---|---------------------------------------|---|---|
| BM MODEL<br>970 ATEGO 2<br>375 AXOR<br>374 AXOR 2<br>940 AXOR 2<br>942 AXOR 2<br>943 AXOR 2<br>944 AXOR 2 | Housing, Step<br>Right                | 9406662501<br>9406602201<br>9446603301                  | <b>TM19053</b><br>   |
| 375 ACTROS<br>375 AXOR<br>375 AXOR 2  | Housing, Step<br>Left                 | 3756661001<br>9406660101S<br>9406604701S<br>9406600101S | <b>TM19054</b><br>   |
| 375 ACTROS<br>375 AXOR<br>375 AXOR 2  | Housing, Step<br>Right                | 3756661101<br>9406660201S<br>9406604801S<br>9406600201S | <b>TM19049</b><br>  |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS  | Housing, Step<br>Left                 | 9416600401<br>9416660401                                | <b>TM18831</b><br> |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS  | Housing, Step<br>Right                | 9416600501<br>9416660501                                | <b>TM18832</b><br> |
| 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3                                      | Housing, Step<br>Without Cover, Left  | 9436600601S   | <b>TM38218</b><br> |
| 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3                                      | Housing, Step<br>Without Cover, Right | 9436600701S   | <b>TM38219</b><br> |






| TM No.  | Replaces Ref. No: | Description            | Model / Details |
|---|-------------------|------------------------|-----------------|
| <b>TM18815</b><br>   | 9436660401        | Housing, Step<br>Left  | 950 ACTROS      |
|   | 9416662101        |                        | 952 ACTROS      |
|   | 9416662601        |                        | 953 ACTROS      |
|   | 9436664201        |                        | 954 ACTROS      |
|   |                   |                        | 930 ACTROS 2/3  |
|   |                   |                        | 932 ACTROS 2/3  |
|   |                   |                        | 933 ACTROS 2/3  |
| <b>TM18816</b><br>   | 9436660501        | Housing, Step<br>Right | 950 ACTROS      |
|   | 9416662201        |                        | 952 ACTROS      |
|   | 9416662701        |                        | 953 ACTROS      |
|   | 9436664301        |                        | 954 ACTROS      |
|   |                   |                        | 930 ACTROS 2/3  |
|   |                   |                        | 932 ACTROS 2/3  |
|   |                   |                        | 933 ACTROS 2/3  |
| <b>TM38220</b><br>  | 9446660201        | Housing, Step<br>Right | 970 ATEGO 2     |
|   |                   |                        | 375 AXOR        |
|   |                   |                        | 374 AXOR 2      |
|   |                   |                        | 940 AXOR 2      |
|   |                   |                        | 942 AXOR 2      |
|   |                   |                        | 943 AXOR 2      |
|   |                   |                        | 944 AXOR 2      |
|   |                   |                        |                 |
|   |                   |                        |                 |
|   |                   |                        |                 |
| <b>TM38221</b><br> | 9446660101        | Housing, Step<br>Left  | 970 ATEGO 2     |
|   |                   |                        | 375 AXOR        |
|   |                   |                        | 374 AXOR 2      |
|   |                   |                        | 940 AXOR 2      |
|   |                   |                        | 942 AXOR 2      |
|   |                   |                        | 943 AXOR 2      |
|   |                   |                        | 944 AXOR 2      |
| <b>TM19396</b><br> | 9446601901        | Housing, Step<br>Right | 970 ATEGO 2     |
|   | 9446660401        |                        | 374 AXOR 2      |
|   |                   |                        | 940 AXOR 2      |
|   |                   |                        | 942 AXOR 2      |
|   |                   |                        | 943 AXOR 2      |
|   |                   |                        | 944 AXOR 2      |
|   | 958 AXOR 2        |                        |                 |
| <b>TM19397</b><br> | 9446601801        | Housing, Step<br>Left  | 970 ATEGO 2     |
|   | 9446660301        |                        | 374 AXOR 2      |
|   |                   |                        | 940 AXOR 2      |
|   |                   |                        | 942 AXOR 2      |
|   |                   |                        | 943 AXOR 2      |
|   |                   |                        | 944 AXOR 2      |
|   | 958 AXOR 2        |                        |                 |
| <b>TM38222</b><br> | 9406662101        | Housing, Step<br>Left  | 375 AXOR        |
|   |                   |                        | 944 AXOR 2      |
|   |                   |                        |                 |
|   |                   |                        |                 |
|   |                   |                        |                 |



| Model / Details   | Description            | Replaces Ref. No:        | TM No.  |
|---|------------------------|--------------------------|---|
| 375 AXOR<br>944 AXOR 2  | Housing, Step<br>Right | 9406662201               | <b>TM38223</b><br>   |
| 375 ACTROS<br>970 ATEGO 2<br>375 AXOR<br>374 AXOR 2<br>375 AXOR 2<br>940 AXOR 2<br>942 AXOR 2 | Bracket, Step<br>Left  | 9406601830<br>3756600030 | <b>TM19541</b><br>   |
| 375 ACTROS<br>970 ATEGO 2<br>375 AXOR<br>374 AXOR 2<br>375 AXOR 2<br>940 AXOR 2<br>942 AXOR 2 | Bracket, Step<br>Right | 9406601930<br>3756600130 | <b>TM19542</b><br>  |
| 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3                          | Bracket, Step<br>Left  | 9436660178               | <b>TM19103</b><br> |
| 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3                          | Bracket, Step<br>Right | 9436660278               | <b>TM19104</b><br> |
| 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3                          | Bracket, Step<br>Left  | 9436600131<br>9436601531 | <b>TM38224</b><br> |
| 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3                          | Bracket, Step<br>Right | 9436600231<br>9436601631 | <b>TM38225</b><br> |






| TM No.  | Replaces Ref. No: | Description               | Model / Details  |
|---|-------------------|---------------------------|--|
| <b>TM38226</b><br>   | 9606601130        | Bracket, Step<br>Left     | 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS   |
| <b>TM38227</b><br>   | 9606601230        | Bracket, Step<br>Right    | 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS   |
| <b>TM19242</b><br>   | 9606660605        | Cover, Step<br>Left/Right | 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS   |
| <b>TM18833</b><br> | 9416660105        | Cover, Step               | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 |
| <b>TM19046</b><br> | 9438850422        | Cover, Step<br>Left       | 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3                                       |
| <b>TM19045</b><br> | 9438850522        | Cover, Step<br>Right      | 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3                                       |
| <b>TM19543</b><br> | 9406660005        | Cover, Step               | 970 ATEGO 2<br>375 AXOR<br>374 AXOR 2<br>940 AXOR 2<br>942 AXOR 2<br>943 AXOR 2<br>944 AXOR 2              |



| Model / Details  | Description   | Replaces Ref. No:                      | TM No.  |
|--|---|--|---|
| 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3                                       | Cover, Step<br>Left   | 9438850222                             | <b>TM19211</b>  |
|  |   |  |    |
| 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3                                       | Cover, Step<br>Right  | 9438850322                             | <b>TM19212</b>  |
|  |   |  |    |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 | Shock Absorber, with Air<br>Bellow, Cab<br>Repl. Sachs: 313 676 /<br>105 392<br>Repl. Monroe: CB0089 /<br>CB0107<br>ø14/ø25x243/347 | 9428902919<br>9428900119<br>9428906919 | <b>TM34860</b>  |
|  |   |  |   |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 | Shock Absorber, with Air<br>Bellow, Cab<br>Repl. Sachs: 311 189 /<br>290 997<br>Repl. Monroe: CB0090<br>ø14x247/317                 | 9428900219<br>9428906019<br>9438903919 | <b>TM34861</b>  |
|  |   |  |  |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 | Shock Absorber, with Air<br>Bellow, Cab<br>Repl. Sachs: 311 663 /<br>290 998<br>Repl. Monroe: CB0115<br>ø14/ø25x254/361             | 9428905919<br>9428905319<br>9438903819 | <b>TM34862</b>  |
|  |   |  |  |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS   | Shock Absorber, with Air<br>Bellow, Cab<br>Repl. Sachs: 313 675 /<br>105 408<br>Repl. Monroe: CB0108<br>ø14/ø25x250/353             | 9428905219<br>9428907019               | <b>TM34869</b>  |
|  |   |  |  |
| 930 ACTROS 2/3<br>932 ACTROS 2/3<br>934 ACTROS 2/3<br>375 AXOR<br>944 AXOR 2                               | Shock Absorber, with Air<br>Bellow, Cab<br>Repl. Sachs: 311 664<br>Repl. Monroe: CB0116<br>ø14x248/322                              | 9428906119                             | <b>TM34902</b>  |
|  |   |  |  |



| TM No.  | Replaces Ref. No:                      | Description  | Model / Details  |
|---|--|--|--|
| <b>TM34916</b><br>   | 9408904919                             | Shock Absorber, with Air   | 375 AXOR   |
|   | 9588900819<br>9588900919               | Bellow, Cab<br>Repl. Sachs: 315 153<br>ø14x241/344                               | 374 AXOR 2<br>940 AXOR 2<br>942 AXOR 2<br>943 AXOR 2<br>944 AXOR 2                           |
| <b>TM28055</b><br>   | 9603106155                             | Shock Absorber, with Air   | 963 ACTROS MP4   |
|   | 9603109555                             | Bellow, Cab<br>Right, Rear<br>Repl. Sachs: 315 147<br>M12/ø14x350/442            | 964 ACTROS MP4<br>964 ANTOS<br>964 AROCS   |
| <b>TM38235</b><br>   | 9603106255                             | Shock Absorber, with Air   | 963 ACTROS MP4   |
|   | 9603109655                             | Bellow, Cab<br>Rear Left<br>Repl. Sachs: 315 146<br>M12/ø14x350/442              | 964 ACTROS MP4<br>964 ANTOS<br>964 AROCS   |
| <b>TM34950</b><br> | 9583170603                             | Shock Absorber, Cab  | 958 ATEGO 2  |
|   | 9703171803<br>9703174203               | Front<br>Repl. Sachs: 131 726<br>ø14/ø50x295/309                                 |  |
| <b>TM34951</b><br> | 9583170503                             | Shock Absorber, Cab  | 958 ATEGO 2  |
|   | 9703171703<br>9703174103               | Front<br>Repl. Sachs: 131 676<br>Repl. Sabo: 895321<br>ø14/ø50x295/301           |  |
| <b>TM34809</b><br> | 0008911805                             | Shock Absorber, Cab  | 650 MK   |
|   | 0008911905<br>0008912205<br>3718917005 | Rear<br>Repl. Sachs: 313 424 /<br>101 456<br>Repl. Monroe: CB0071<br>ø18x196/248 | 652 MK<br>380 NG<br>381 NG<br>383 NG<br>385 NG<br>387 NG                                     |
| <b>TM34852</b><br> | 9428904719                             | Shock Absorber, Cab  | 950 ACTROS   |
|   |  | Rear<br>Repl. Sachs: 131 275<br>Repl. Monroe: CB0096<br>ø12x302/372              | 952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 |












| Model / Details   | Description  | Replaces Ref. No:                                    | TM No.  |
|---|--|--|---|
| 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3      | Shock Absorber, Cab<br>Front<br>Repl. Sachs: 313 941 /<br>290 268<br>Repl. Monroe: CB0148<br>ø12x164/208         | 9428900519<br>9583170703                             | <b>TM34857</b><br>   |
| 375 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3<br>375 ATEGO<br>375 AXOR | Shock Absorber, Cab<br>Repl. Sachs: 290 995<br>Repl. Monroe: CB0097<br>ø12x302/372                               | 9408903919<br>3758900519<br>9408904119<br>9583172103 | <b>TM34853</b><br>   |
| 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3  | Shock Absorber, Cab<br>Rear<br>Repl. Sachs: 312 649<br>Repl. Monroe: CB0164<br>ø12x211/229                       | 9438905019   | <b>TM34915</b><br>   |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3  | Shock Absorber, Cab<br>Repl. Monroe: SD0003<br>ø16x153/213   | 0019191245   | <b>TM34884</b><br> |
| 940 AXOR 2<br>942 AXOR 2<br>943 AXOR 2<br>944 AXOR 2  | Shock Absorber, Cab<br>Rear<br>ø12x187/232   | 3753170003<br>9583170003                             | <b>TM34549</b><br> |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3  | Compression Spring, Cab<br>Rear<br>Repl. Sachs: 313 763 /<br>105 423<br>Repl. Monroe: CB0101<br>ø14x280/313      | 9428903119<br>9438900919<br>9438900819<br>9428902319 | <b>TM34859</b><br> |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3  | Compression Spring, Cab<br>Front<br>Repl. Sachs: 313 948 /<br>290 250<br>Repl. Monroe: CB0122<br>ø14/ø25x280/348 | 9428905419<br>9438900319                             | <b>TM34866</b><br> |









| TM No.  | Replaces Ref. No:                                    | Description   | Model / Details  |
|---|--|---|--|
| <b>TM28027</b><br>   | 9408903119   | Compression Spring, Cab<br>Front<br>ø14x252/330   | 950 AXOR 2<br>952 AXOR 2<br>953 AXOR 2<br>954 AXOR 2<br>693 1938<br>693 1938 S                             |
|   | 9428902819<br>9428902219                             | Compression Spring, Cab<br>Front<br>Repl. Sachs: 131 850<br>Repl. Monroe: CB0100<br>ø14/ø25x275/340         | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS   |
| <b>TM34871</b><br>  | 9408904619<br>9408904519<br>9583171503<br>3758900819 | Compression Spring, Cab<br>Front<br>Repl. Sachs: 290 996<br>Repl. Monroe: CB0163<br>ø14x252/281             | 375 ACTROS<br>375 AXOR<br>374 AXOR 2<br>375 AXOR 2<br>940 AXOR 2<br>942 AXOR 2<br>943 AXOR 2               |
|   | 9408904719<br>9408903819<br>3758900419<br>3758900919 | Compression Spring, Cab<br>Rear<br>Repl. Sachs: 313 949 /<br>290 251<br>Repl. Monroe: CB0150<br>ø14x284/320 | 375 ACTROS<br>375 AXOR<br>374 AXOR 2<br>375 AXOR 2<br>940 AXOR 2<br>944 AXOR 2<br>950 AXOR 2               |
| <b>TM34863</b><br> | 9428903919<br>9438901319                             | Compression Spring, Cab<br>Rear<br>Repl. Sachs: 313 944 /<br>290 257<br>Repl. Monroe: CB0144<br>ø14x327/360 | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 |
|   | 9428900419<br>9428901519<br>9438901219<br>9438902419 | Compression Spring, Cab<br>Rear<br>Repl. Sachs: 313 942 /<br>290 245<br>Repl. Monroe: CB0147<br>ø14x327/360 | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 |
| <b>TM34917</b><br> | 9438904619<br>9438904919                             | Compression Spring, Cab<br>Repl. Sachs: 313 957 /<br>312 651<br>ø14x349/384                                 | 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3                                       |



| Model / Details  | Description  | Replaces Ref. No:                                    | TM No.  |
|--|--|--|---|
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS   | Compression Spring, Cab<br>Front<br>Repl. Sachs: 313 950 /<br>290 258<br>ø14/ø25x280/345                         | 9428904919   | <b>TM34865</b><br>   |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS   | Compression Spring, Cab<br>Front<br>Repl. Sachs: 313 951 /<br>290 259<br>Repl. Monroe: CB0127<br>ø14/ø25x280/345 | 9428905019<br>9428905119                             | <b>TM34867</b><br>   |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 | Compression Spring, Cab<br>Front<br>Repl. Sachs: 313 947 /<br>290 249<br>Repl. Monroe: CB0121<br>ø14/ø25x280/348 | 9428905619<br>9438900219                             | <b>TM34868</b><br>  |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 | Compression Spring, Cab<br>Front<br>Repl. Sachs: 313 945 /<br>290 247<br>Repl. Monroe: CB0158<br>ø14x280/313     | 9428903619<br>9438901019<br>9438901119<br>9438901619 | <b>TM34850</b><br> |
| 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3                                       | Compression Spring, Cab<br>Rear<br>Repl. Sachs: 313 952 /<br>312 645<br>Repl. Monroe: CB0161<br>ø14x284/320      | 9438902919<br>9438903019                             | <b>TM34912</b><br> |
| 930 ACTROS 2/3<br>934 ACTROS 2/3   | Compression Spring, Cab<br>Repl. Sachs: 313 954 /<br>312 647<br>Repl. Monroe: CB0156<br>ø14x284/320              | 9438903119<br>9438903219                             | <b>TM37963</b><br> |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 | Compression Spring, Cab<br>Rear<br>Repl. Sachs: 313 943 /<br>290 246<br>Repl. Monroe: CB0165<br>ø14x327/360      | 9428901119<br>9428903519<br>9438900519<br>9438902319 | <b>TM34900</b><br> |



| TM No.  | Replaces Ref. No:                                    | Description  | Model / Details  |
|---|--|--|--|
| <b>TM34957</b><br>   | 9438904419   | Compression Spring, Cab<br>Rear<br>Repl. Sachs: 313 956 /<br>312 650<br>ø14x249/305                          | 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3                                       |
|   | 9438903319<br>9438903419                             | Compression Spring, Cab<br>Rear<br>Repl. Sachs: 313 953 /<br>312 646<br>Repl. Monroe: CB0157<br>ø14x284/320  | 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3                                       |
| <b>TM34901</b><br>  | 9438903519   | Compression Spring, Cab<br>Rear<br>Repl. Sachs: 313 955 /<br>312 648<br>Repl. Monroe: CB0155<br>ø14x284/320  | 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3                                       |
|   | 9428905519<br>9438900119                             | Compression Spring, Cab<br>Front<br>Repl. Sachs: 313 946 /<br>290 248<br>ø14/ø25x282/348                     | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 |
| <b>TM38236</b><br> | 3818900719<br>3818900919<br>3878901019<br>3878901319 | Compression Spring, Cab<br>Rear<br>Repl. Sachs: 101 329<br>Repl. Monroe: CB0104<br>M12x250/290               | 387 NG<br>389 NG<br>393 NG<br>395 NG   |
|   | 6938900519<br>9408900519<br>9408901019<br>9408903719 | Compression Spring, Cab<br>Front<br>Repl. Sachs: 280 939 /<br>311 887<br>Repl. Monroe: CB0162<br>ø14x276/344 | 693 1938<br>693 1938 S<br>693 1944 S   |
| <b>TM38237</b><br> | 9408904819   | Compression Spring, Cab<br>Front   | 958 AXOR 2<br>374 AXOR 2<br>954 AXOR 2<br>943 AXOR 2<br>944 AXOR 2<br>950 AXOR 2<br>952 AXOR 2             |



| Model / Details   | Description                           | Replaces Ref. No:                      | TM No.  |
|---|---------------------------------------|--|---|
| 63 LP 2226/6X4<br>363 LP 2232/6X4<br>363 LPB 2226/6X4<br>363 LPK 2226/6X4<br>363 LPK 2232/6X4<br>363 LPS 2226/6X4<br>363 LPS 2232/6X4 | Rubber Bushing, Cab<br>ø22xø40x33     | 3638910717                             | <b>TM27792</b><br>   |
| 380 NG<br>381 NG<br>383 NG<br>385 NG<br>387 NG<br>389 NG<br>391 NG  | Rubber Bushing, Cab<br>ø25x65         | 3813171512                             | <b>TM38238</b><br>   |
| 380 NG<br>381 NG<br>383 NG<br>385 NG<br>387 NG<br>389 NG<br>393 NG  | Rubber Bushing, Cab<br>ø25x81         | 3813171712                             | <b>TM38239</b><br>   |
| 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3                                | Rubber Bushing, Cab<br>ø14xø31,5x40   | 0008901401                             | <b>TM35070</b><br> |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>375 AXOR<br>944 AXOR 2<br>950 AXOR 2  | Rubber Bushing, Cab<br>ø16xø65x64     | 9423172212<br>9423100077<br>9423100277 | <b>TM35064</b><br> |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS  | Rubber Bushing, Cab<br>ø16,5x40       | 9423171712                             | <b>TM35071</b><br> |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3                            | Rubber Bushing, Cab<br>ø25xø100x123,5 | 9423172012                             | <b>TM35063</b><br> |







| TM No.  | Replaces Ref. No:        | Description                            | Model / Details  |
|---|--------------------------|--|--|
| <b>TM35062</b>  | 9403171012               | Rubber Bushing, Cab<br>ø25xø100x123,5  | 375 ACTROS<br>967 ATEGO 3<br>375 AXOR<br>374 AXOR 2<br>375 AXOR 2<br>940 AXOR 2<br>942 AXOR 2  |
|    |                          |  |  |
| <b>TM38240</b>  | 9403171112               | -Rubber Bushing, Cab<br>ø25xø100x123,5 | 375 ACTROS<br>967 ATEGO 3<br>375 AXOR<br>374 AXOR 2<br>375 AXOR 2<br>940 AXOR 2<br>942 AXOR 2  |
|    |                          |  |  |
| <b>TM38241</b>  | 9423172112               | Rubber Bushing, Cab<br>ø25xø100x123,5  | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3   |
|    |                          |  |  |
| <b>TM38242</b>  | 6743170812               | Rubber Bushing, Cab<br>ø25x60/61x57    | 673 LK/LN2<br>674 LK/LN2<br>675 LK/LN2<br>676 LK/LN2<br>677 LK/LN2<br>678 LK/LN2<br>679 LK/LN2   |
|  |                          |  |  |
| <b>TM38243</b>  | 6733170112               | Rubber Bushing, Cab<br>ø55x87/88x56    | 397 LP 1014 MBSA-RSA<br>397 LP 1114,1214 MB-<br>SA-RSA<br>397 LP 1214 A MBSA-RSA<br>397 LP 1517<br>397 LP 1617 A MBSA-RSA<br>397 LP/LPK 1314 MB-<br>SA-RSA<br>397 LP/LPK 1417, |
|  |                          |  |  |
| <b>TM35084</b>  | 9303170012<br>9423171812 | Rubber Bushing, Cab<br>ø40x47          | 375 ACTROS<br>375 AXOR<br>375 AXOR 2<br>958 AXOR 2   |
|  |                          |  |  |
| <b>TM38244</b>  | 9703170369               | Rubber Bushing, Cab<br>ø25,5xø58,5x42  | 375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>375 ATEGO 2<br>958 ATEGO  |
|  |                          |  |  |





| Model / Details  | Description                                | Replaces Ref. No:        | TM No.  |
|--|--|--------------------------|---|
| 375 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3<br>375 AXOR<br>375 AXOR 2 | Rubber Bushing, Cab<br>ø16xø69x64          | 0009921603               | <b>TM34789</b><br>   |
| 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3   | Rubber Bushing, Cab<br>ø16xø65x64          | 9423172312               | <b>TM34513</b><br>   |
| 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3       | Rubber Bushing, Cab<br>ø25,3xø59x53        | 9423170069<br>9413170069 | <b>TM35068</b><br>  |
| 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS   | Rubber Bushing, Cab<br>ø24,2x74            | 9603170712               | <b>TM38245</b><br> |
| 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS   | Rubber Bushing, Cab<br>ø24,2x74            | 9603172312               | <b>TM38246</b><br> |
| 667 T2/LN1<br>668 T2/LN1<br>669 T2/LN1<br>670 T2/LN1   | Mounting, Cab<br>Plastic<br>ø20,5xø87x56,5 | 6683177055<br>6673170555 | <b>TM38247</b><br> |
| 375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>375 ATEGO 2<br>958 ATEGO 2                  | Mounting, Cab<br>ø55x69                    | 9703170450               | <b>TM35085</b><br> |





| TM No.  | Replaces Ref. No:        | Description                     | Model / Details   |
|---|--------------------------|---------------------------------|---|
| <b>TM38248</b><br>   | 3813171412               | Mounting, Cab<br>ø46xø87,5x17,5 | -380 NG<br>381 NG<br>383 NG<br>385 NG<br>387 NG<br>389 NG<br>391 NG   |
| <b>TM38249</b><br>   | 6673170012               | Mounting, Cab<br>ø43,5xø85x45,  | 384 L 1214<br>384 L 1215<br>384 L 1218<br>384 L 1414<br>384 L 1418 ,L 1418 E<br>384 LA 1418<br>384 LAK 1418 |
| <b>TM38250</b><br>  | 6673170236               | Mounting, Cab<br>ø18xø78,5x15,5 | 667 T2/LN1 Bearing, Cab<br>668 T2/LN1<br>669 T2/LN1<br>670 T2/LN1<br>667 VARIO<br>668 VARIO<br>670 VARIO    |
| <b>TM38251</b><br> | 6743170712               | Mounting, Cab<br>ø25xø80,5x14   | 673 LK/LN2<br>674 LK/LN2<br>675 LK/LN2<br>676 LK/LN2<br>677 LK/LN2<br>678 LK/LN2<br>679 LK/LN2              |
| <b>TM35086</b><br> | 9703170112               | Mounting, Cab<br>ø59,5x70,5     | 375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>375 ATEGO 2<br>958 ATEGO 2                 |
| <b>TM38252</b><br> | 9408910023<br>9428910523 | Buffer, Cab<br>ø9xø53/ø56x32    | 375 ACTROS<br>375 AXOR<br>374 AXOR 2<br>375 AXOR 2<br>940 AXOR 2<br>942 AXOR 2<br>943 AXOR 2                |
| <b>TM35094</b><br> | 9428910423               | Buffer, Cab<br>ø9xø55x11        | 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3      |



| Model / Details  | Description                                 | Replaces Ref. No:                      | TM No.  |
|--|---|--|---|
| 380 NG<br>381 NG<br>383 NG<br>385 NG<br>387 NG<br>389 NG<br>391 NG   | Bearing, Cab<br>ø20xø35x12/16               | 0009817231<br>0009817331<br>0009810931 | <b>TM37686</b><br>   |
| 363 LP 2226/6X4<br>363 LP 2232/6X4<br>363 LPB 2226/6X4<br>363 LPK 2226/6X4<br>363 LPK 2232/6X4<br>363 LPS 2226/6X4<br>363 LPS 2232/6X4 | Bearing, Cab<br>ø25xø42x25                  | 6208910417                             | <b>TM35051</b><br>   |
| 650 MK<br>652 MK<br>380 NG<br>381 NG<br>383 NG<br>385 NG<br>387 NG   | Bearing, Cab<br>ø21xø35x13,5                | 6208910017                             | <b>TM35054</b><br>   |
| 363 LP 2226/6X4<br>363 LP 2232/6X4<br>363 LPB 2226/6X4<br>363 LPK 2226/6X4<br>363 LPK 2232/6X4<br>363 LPS 2226/6X4<br>363 LPS 2232/6X4 | Bearing, Cab<br>ø25xø34x43                  | 3638910617                             | <b>TM38253</b><br> |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS   | Bearing, Cab<br>ø40xø46,5x31,5              | 9423100049                             | <b>TM35067</b><br> |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>375 AXOR<br>944 AXOR 2<br>950 AXOR 2   | Bearing, Cab<br>ø40xø46,5x31,5              | 9425000050<br>9415000050<br>9423170276 | <b>TM34788</b><br> |
| 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS<br>958 ATEGO 2<br>967 ATEGO 3   | Bushing, Cab<br>Rear, Right<br>ø16,3xø77x60 | 9603172112                             | <b>TM37951</b><br> |



| TM No.  | Replaces Ref. No:                                     | Description                     | Model / Details  |
|---|---|---------------------------------|--|
| <b>TM35117</b><br>   | 9603172212  | Bushing, Cab<br>ø16,3xø45,5x20  | 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS                         |
| <b>TM35123</b><br>   | 9603172412  | Bushing, Cab<br>ø12,3xø45,45x24 | 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS                         |
| <b>TM27770</b><br>   | 9423170376  | Washer, Cab<br>ø25xø65,5        | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS                               |
| <b>TM35133</b><br> | 6203100177  | Repair Kit, Cab<br>ø18          | 652 MK<br>385 NG<br>617 NG<br>620 NG<br>621 NG<br>622 NG<br>623 NG                 |
| <b>TM34787</b><br> | 3873100077<br>3875860131<br>3878911910S               | Repair Kit, Cab                 | 652 MK<br>380 NG<br>381 NG<br>383 NG<br>385 NG<br>387 NG<br>389 NG                 |
| <b>TM35129</b><br> | 3875860531<br>3878910957<br>6203100077<br>3878910272S | Repair Kit, Cab<br>ø18          | 380 NG<br>381 NG<br>383 NG<br>385 NG<br>387 NG<br>389 NG<br>391 NG                 |
| <b>TM28394</b><br> | 3185860031<br>1203331965S<br>1803330165S              | Repair Kit, Cab<br>ø22          | 314 LP<br>316 LP<br>318 LP<br>328 T2/L<br>338 L 1418<br>338 LK 1418<br>338 LS 1418 |



| Model / Details   | Description                      | Replaces Ref. No:          | TM No.         |
|---|----------------------------------|----------------------------|----------------|
| 376 LP 1219 MBTC-USA<br>376 LP 1419 MBTC-USA<br>376 LPS 1525 MBTC-USA<br>615 LK/LN2<br>650 MK<br>651 MK<br>652 MK | Repair Kit, Cab<br>ø25           | 3815860031                 | <b>TM34564</b> |
| 650 MK<br>651 MK<br>652 MK<br>380 NG<br>381 NG<br>383 NG<br>385 NG  | Repair Kit, Cab<br>ø25           | 6205860031                 | <b>TM38254</b> |
| 376 LP 1219 MBTC-USA<br>376 LP 1419 MBTC-USA<br>376 LPS 1525 MBTC-USA<br>651 MK<br>652 MK<br>653 MK<br>654 MK     | Repair Kit, Cab<br>ø25           | 6558902903                 | <b>TM38255</b> |
| 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS  | Repair Kit, Cab<br>ø16,3/M16x1,5 | 9603106255S<br>9603109655S | <b>TM38256</b> |
| 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS  | Repair Kit, Cab<br>M16x1,5       | 9603170712S                | <b>TM38259</b> |
| 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS  | Repair Kit, Cab<br>M16x1,5       | 9603172312S                | <b>TM38264</b> |











| TM No.  | Replaces Ref. No:                                    | Description                      | Model / Details   |
|---|--|----------------------------------|---|
| <b>TM26996</b><br>   | 3878911051<br>3878910651                             | Leaf Spring, Cab                 | 650 MK<br>652 MK<br>380 NG<br>381 NG<br>383 NG<br>385 NG<br>387 NG<br>389 NG                                      |
| <b>TM26997</b><br>   | 3878910551   | Leaf Spring, Cab                 | 652 MK<br>380 NG<br>381 NG<br>383 NG<br>385 NG<br>387 NG<br>391 NG<br>393 NG                                      |
| <b>TM38265</b><br>   | 3878910551   | Lever, Cab<br>Left<br>ø78,5/340  | 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS  |
| <b>TM38266</b><br> | 9603100173   | Lever, Cab<br>Right<br>ø78,5/340 | 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS  |
| <b>TM38267</b><br> | 9603100373   | Lever, Cab<br>Left<br>ø79/340    | 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS  |
| <b>TM38268</b><br> | 9603100473   | Lever, Cab<br>Right<br>ø79/340   | 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS  |
| <b>TM34812</b><br> | 0015533505<br>0015531605<br>0015539505<br>0015531705 | Cylinder, Cab Tilt               | 376 LP 1219 MBTC-USA<br>376 LP 1419 MBTC-USA<br>376 LPS 1525 MBTC-USA<br>615 LK/LN2<br>650 MK<br>651 MK<br>652 MK |





| Model / Details  | Description        | Replaces Ref. No:                                    | TM No.  |
|--|--------------------|--|---|
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS   | Cylinder, Cab Tilt | 0025531005<br>0025531305<br>0025531405<br>0025530905 | <b>TM34826</b><br>   |
| 375 AXOR<br>374 AXOR 2<br>940 AXOR 2<br>944 AXOR 2   | Cylinder, Cab Tilt | 0025534405   | <b>TM34837</b><br>   |
| 375 ACTROS<br>375 AXOR<br>374 AXOR 2<br>375 AXOR 2<br>950 AXOR 2<br>952 AXOR 2<br>953 AXOR 2 | Cylinder, Cab Tilt | 0025538205   | <b>TM34933</b><br>  |
| 375 AXOR<br>374 AXOR 2<br>940 AXOR 2<br>944 AXOR 2   | Cylinder, Cab Tilt | 0025538505<br>0025535505                             | <b>TM34932</b><br> |
| 375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>375 ATEGO 2<br>958 ATEGO 2  | Cylinder, Cab Tilt | 9735530005<br>3755530005                             | <b>TM34931</b><br> |
| 650 MK<br>652 MK<br>380 NG<br>381 NG<br>383 NG<br>385 NG<br>387 NG                           | Cylinder, Cab Tilt | 0015534205<br>0005537205<br>0005535105<br>0005537305 | <b>TM34805</b><br> |
| 652 MK<br>653 MK<br>646 NG<br>649 NG<br>625 SK<br>655 SK<br>656 SK                           | Cylinder, Cab Tilt | 0015539605<br>0015532505<br>3715537405               | <b>TM34825</b><br> |












| TM No.  | Replaces Ref. No: | Description        | Model / Details     |
|---|-------------------|--------------------|---------------------|
| <b>TM34813</b><br>   | 0015531005        | Cylinder, Cab Tilt | 655 SK              |
|   | 0015534305        |                    | 371 1938 S/35 LS/35 |
|   | 3715537105        |                    | OTOMARSAN/TUERKEI   |
|   | 0005537405        |                    | 397 1928 MBSA-RSA   |
|   |                   |                    | 397 1928 S MBSA-RSA |
| <b>TM34814</b><br>   | 0005538705        | Cylinder, Cab Tilt | 620 NG              |
|   | 0015534505        |                    | 621 NG              |
|   |                   |                    | 622 NG              |
|   |                   |                    | 623 NG              |
|   |                   |                    | 645 NG              |
|   |                   |                    | 646 NG              |
|   |                   |                    | 647 NG              |
| <b>TM34806</b><br>   | 0015534605        | Cylinder, Cab Tilt | 380 NG              |
|   | 0005537505        |                    | 381 NG              |
|   | 0005534605        |                    | 383 NG              |
|   | 0005533705        |                    | 385 NG              |
|   |                   |                    | 387 NG              |
| <b>TM34827</b><br> | 0025538805        | Cylinder, Cab Tilt | 950 ACTROS          |
|   | 0025538405        |                    | 952 ACTROS          |
|   | 0025536605        |                    | 953 ACTROS          |
|   | 0025535405        |                    | 954 ACTROS          |
|   |                   |                    | 930 ACTROS 2/3      |
|   |                   |                    | 932 ACTROS 2/3      |
|   |                   |                    | 933 ACTROS 2/3      |
| <b>TM34838</b><br> | 0025535905        | Cylinder, Cab Tilt | 950 ACTROS          |
|   | 0025537805        |                    | 952 ACTROS          |
|   | 0025539205        |                    | 954 ACTROS          |
|   |                   |                    | 930 ACTROS 2/3      |
| <b>TM34829</b><br> | 0025535705        | Cylinder, Cab Tilt | 950 ACTROS          |
|   | 0025537705        |                    | 952 ACTROS          |
|   | 0025539105        |                    | 954 ACTROS          |
|   |                   |                    | 930 ACTROS 2/3      |
|   |                   |                    | 934 ACTROS 2/3      |
| <b>TM34828</b><br> | 0025536805        | Cylinder, Cab Tilt | 950 ACTROS          |
|   |                   |                    | 952 ACTROS          |
|   |                   |                    | 953 ACTROS          |
|   |                   |                    | 954 ACTROS          |



| Model / Details  | Description                      | Replaces Ref. No:                      | TM No.         |
|--|----------------------------------|--|----------------|
| 374 AXOR 2<br>942 AXOR 2<br>943 AXOR 2   | Cylinder, Cab Tilt               | 3755530305                             | <b>TM34817</b> |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 | Cylinder, Cab Tilt               | 9305530682<br>9425530382               | <b>TM34771</b> |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS   | Cylinder, Cab Tilt               | 9425530482                             | <b>TM35093</b> |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 | Cylinder, Cab Tilt               | 9425530782<br>9425530882<br>9425532882 | <b>TM34772</b> |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 | Cylinder, Cab Tilt<br>L: 1370 mm | 9425530182                             | <b>TM34769</b> |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 | Cylinder, Cab Tilt               | 9425530582                             | <b>TM35091</b> |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS   | Cylinder, Cab Tilt               | 9425530982<br>9425531082<br>9425532082 | <b>TM35092</b> |





| TM No.  | Replaces Ref. No: | Description    | Model / Details |
|---|-------------------|----------------|-----------------|
| <b>TM35090</b><br>   | 9305530582        | Hose, Cab Tilt | 950 ACTROS      |
|   | 9425530682        |                | 952 ACTROS      |
|   |                   |                | 953 ACTROS      |
|   |                   |                | 954 ACTROS      |
|   |                   |                | 930 ACTROS 2/3  |
|   |                   |                | 932 ACTROS 2/3  |
|   |                   |                | 933 ACTROS 2/3  |
| <b>TM38269</b><br>   | 9405532082        | Hose, Cab Tilt | BM MODEL        |
|   | 9425533382        |                | 375 AXOR        |
|   |                   |                | 374 AXOR 2      |
|   |                   |                | 940 AXOR 2      |
|   |                   |                | 942 AXOR 2      |
|   |                   |                | 943 AXOR 2      |
|   |                   |                | 944 AXOR 2      |
| <b>TM38270</b><br>   | 9405532582        | Hose, Cab Tilt | 375 AXOR        |
|   | 9405533782        |                | 374 AXOR 2      |
|   |                   |                | 940 AXOR 2      |
|   |                   |                | 942 AXOR 2      |
|   |                   |                | 943 AXOR 2      |
|   |                   |                | 944 AXOR 2      |
| <b>TM38271</b><br> | 9305530057        | Hose, Cab Tilt | 930 ACTROS 2/3  |
|   |                   |                | 932 ACTROS 2/3  |
|   |                   |                | 933 ACTROS 2/3  |
|   |                   |                | 934 ACTROS 2/3  |
| <b>TM38272</b><br> | 9405532282        | Hose, Cab Tilt | 958 ATEGO 2     |
|   |                   |                | 375 AXOR        |
|   |                   |                | 374 AXOR 2      |
|   |                   |                | 940 AXOR 2      |
|   |                   |                | 942 AXOR 2      |
|   |                   |                | 943 AXOR 2      |
|   |                   |                | 944 AXOR 2      |
| <b>TM35049</b><br> | 6555530582        | Hose, Cab Tilt | 650 MK          |
|   | 6205530182        |                | 651 MK          |
|   | 6155530082        |                | 652 MK          |
|   |                   |                | 653 MK          |
|   |                   |                | 654 MK          |
|   |                   |                | 615 NG          |
|   |                   |                | 616 NG          |
| <b>TM38273</b><br> | 9425531982        | Hose, Cab Tilt | 950 ACTROS      |
|   |                   |                | 954 ACTROS      |
|   |                   |                | 930 ACTROS 2/3  |
|   |                   |                | 932 ACTROS 2/3  |
|   |                   |                | 933 ACTROS 2/3  |
|   |                   |                | 934 ACTROS 2/3  |



| Model / Details  | Description                         | Replaces Ref. No:                                    | TM No.  |
|--|-------------------------------------|--|---|
| 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3   | Hose, Cab Tilt<br>M12x1,5 / 1910 mm | 9405530482<br>9425530282                             | <b>TM34770</b>  |
|  |                                     |  |    |
| 375 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3<br>375 ATEGO<br>375 AXOR  | Hose, Cab Tilt<br>L: 1770 mm        | 9405530282   | <b>TM35100</b>  |
|  |                                     |  |    |
| 958 AXOR 2   | Hand Pump, Cab Tilt                 | 9585530201<br>9585530501                             | <b>TM38274</b>  |
|  |                                     |  |    |
| 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3   | Hand Pump, Cab Tilt                 | 0015533901   | <b>TM34971</b>  |
|  |                                     |  |  |
| 958 AXOR 2<br>693 1938<br>693 1938 S<br>693 1944 S   | Hand Pump, Cab Tilt                 | 6935537001   | <b>TM38275</b>  |
|  |                                     |  |  |
| 371 1817 K/4X2/36 MBT<br>371 1821 AK/4X4/36 MBT<br>371 1821 K/4X2/36 MBT<br>371 1922 K OTOMARSAN/<br>TUERKEI<br>371 1928 S OTOMARSAN/<br>TUERKEI<br>371 1935 S/35,LS/35<br>OTOMARSAN/TUERKEI | Hand Pump, Cab Tilt                 | 3715537001<br>0005537901<br>0005533701<br>0005532701 | <b>TM34807</b>  |
|  |                                     |  |  |
| 375 ACTROS<br>375 ATEGO<br>967 ATEGO 3<br>375 AXOR<br>374 AXOR 2<br>375 AXOR 2<br>950 AXOR 2   | Hand Pump, Cab Tilt                 | 0015535901<br>3755530001                             | <b>TM34833</b>  |
|  |                                     |  |  |












| TM No.  | Replaces Ref. No:        | Description         | Model / Details   |
|---|--------------------------|---------------------|---|
| <b>TM34832</b>  | 0015533601               | Hand Pump, Cab Tilt | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>375 AXOR<br>374 AXOR 2<br>940 AXOR 2    |
|    |                          |                     |   |
| <b>TM34831</b>  | 0015533701               | Hand Pump, Cab Tilt | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>967 ATEGO 3<br>375 AXOR<br>940 AXOR 2   |
|    |                          |                     |   |
| <b>TM34927</b>  | 0015533801               | Hand Pump, Cab Tilt | 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3                            |
|    |                          |                     |   |
| <b>TM34834</b>  | 0015533401               | Hand Pump, Cab Tilt | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS  |
|  |                          |                     |   |
| <b>TM38276</b>  | 0015530001               | Hand Pump, Cab Tilt | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>967 ATEGO 3<br>950 AXOR 2<br>952 AXOR 2 |
|  |                          |                     |   |
| <b>TM34533</b>  | 0005539901<br>0015531401 | Hand Pump, Cab Tilt | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS  |
|  |                          |                     |   |
| <b>TM34836</b>  | 0015534001               | Hand Pump, Cab Tilt | 930 ACTROS 2/3<br>934 ACTROS 2/3  |
|  |                          |                     |   |












| Model / Details  | Description                  | Replaces Ref. No:                      | TM No.  |
|--|------------------------------|--|---|
| 930 ACTROS 2/3<br>934 ACTROS 2/3   | Hand Pump, Cab Tilt          | 0015534101                             | <b>TM34835</b><br>   |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 | Cab Tilt Lock<br>Rear, Right | 9423100383                             | <b>TM34844</b><br>   |
| 375 ACTROS<br>375 AXOR<br>374 AXOR 2<br>375 AXOR 2<br>940 AXOR 2<br>942 AXOR 2<br>943 AXOR 2               | Cab Tilt Lock<br>Rear, Left  | 9423100283                             | <b>TM34843</b><br>  |
| 375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>375 ATEGO 2<br>958 ATEGO 2                | Cable, Cab Tilt Lock         | 9703170318<br>9703170218<br>9703170118 | <b>TM34875</b><br> |



| TM No.  | Replaces Ref. No:           | Description                        | Model / Details   |
|---|-----------------------------|------------------------------------|---|
| <b>TM35109</b><br>   | 9603250044                  | Bump Stop, Traverse<br>96x140,5x50 | 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS  |
| <b>TM25131</b><br>   | 910105014010                | Screw, Traverse<br>M14x1,5/45      | 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3                |
| <b>TM38277</b><br>   | 910105014013                | Screw, Traverse<br>M14x1,5/35      | 979 ACCELO<br>375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3                    |
| <b>TM38278</b><br> | 3469903304                  | Screw, Traverse<br>M16x1,5/150     | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3            |
| <b>TM38279</b><br> | 00000005541<br>910105016011 | Screw, Traverse<br>M16x1,5/140     | 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3<br>963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS |
| <b>TM18802</b><br> | 9738800470                  | Bumper<br>Left                     | 970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>970 ATEGO 2<br>972 ATEGO 2<br>974 ATEGO 2                         |
| <b>TM18801</b><br> | 9738800570                  | Bumper<br>Right                    | 970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>970 ATEGO 2<br>972 ATEGO 2<br>974 ATEGO 2                         |










| Model / Details   | Description      | Replaces Ref. No: | TM No.  |
|---|------------------|-------------------|---|
| 970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>970 ATEGO 2<br>972 ATEGO 2<br>974 ATEGO 2 | Bumper<br>Center | 9738801070        | <b>TM18803</b><br>   |
| 375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>375 ATEGO 2<br>958 ATEGO 2   | Bumper<br>Left   | 9738801670        | <b>TM18807</b><br>   |
| 375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>375 ATEGO 2<br>958 ATEGO 2   | Bumper<br>Right  | 9738801770        | <b>TM18808</b><br>  |
| 375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>375 ATEGO 2<br>958 ATEGO 2   | Bumper<br>Center | 9738801170        | <b>TM18809</b><br> |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS  | Bumper<br>Left   | 9418802770        | <b>TM18804</b><br> |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS  | Bumper<br>Right  | 9418802870        | <b>TM18805</b><br> |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS  | Bumper<br>Center | 9418851301        | <b>TM18806</b><br> |





| TM No.  | Replaces Ref. No:        | Description      | Model / Details  |
|---|--------------------------|------------------|--|
| <b>TM18790</b><br>   | 9418800970               | Bumper<br>Left   | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS                 |
| <b>TM18789</b><br>   | 9418801070               | Bumper<br>Right  | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS                 |
| <b>TM18784</b><br>   | 9418802470               | Bumper<br>Right  | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS                 |
| <b>TM18785</b><br> | 9418802370               | Bumper<br>Left   | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS                 |
| <b>TM18811</b><br> | 9438800270               | Bumper<br>Left   | 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3 |
| <b>TM18810</b><br> | 9438800370               | Bumper<br>Right  | 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3 |
| <b>TM18812</b><br> | 9438850201<br>9438850001 | Bumper<br>Center | 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3 |










| Model / Details  | Description      | Replaces Ref. No:        | TM No.  |
|--|------------------|--------------------------|---|
| 375 ACTROS<br>375 AXOR<br>374 AXOR 2<br>375 AXOR 2<br>950 AXOR 2<br>952 AXOR 2<br>953 AXOR 2 | Bumper<br>Left   | 9448800270               | <b>TM19200</b><br>   |
| 375 ACTROS<br>375 AXOR<br>374 AXOR 2<br>375 AXOR 2<br>950 AXOR 2<br>952 AXOR 2<br>953 AXOR 2 | Bumper<br>Right  | 9448800370               | <b>TM19201</b><br>   |
| 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3                         | Bumper<br>Center | 9438850301<br>9438850101 | <b>TM38280</b><br>  |
| 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3                         | Bumper<br>Right  | 9438809870<br>9438807470 | <b>TM19037</b><br> |
| 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3                         | Bumper<br>Left   | 9438807570               | <b>TM19036</b><br> |
| 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3                         | Bumper<br>Left   | 9438800670               | <b>TM19013</b><br> |
| 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3                         | Bumper<br>Right  | 9438800770               | <b>TM19012</b><br> |



| TM No.   | Replaces Ref. No:   | Description   | Model / Details   |   |   |   |  |
|--|---|---|---|---|---|---|--|
| <b>TM19016</b><br>  | 9438800104  | Bumper  | 930 ACTROS 2/3  |   |   |   |  |
|  | 9438806270  | Right   | 932 ACTROS 2/3  |   |   |   |  |
|  | 9438807270  |   | 933 ACTROS 2/3  |   |   |   |  |
|  |   |   | 934 ACTROS 2/3  |   |   |   |  |
| <b>TM19017</b><br>  | 9438800004  | -   | 930 ACTROS 2/3  |   |   |   |  |
|  | 9438807370  |   | 932 ACTROS 2/3  |   |   |   |  |
|  | 9438806170  |   | 933 ACTROS 2/3  |   |   |   |  |
|  |   |   | 934 ACTROS 2/3  |   |   |   |  |
| <b>TM19202</b><br> | 9448800104  | Bumper<br>Left  | 970 ATEGO 2<br>375 AXOR<br>374 AXOR 2<br>940 AXOR 2<br>942 AXOR 2<br>943 AXOR 2<br>944 AXOR           |   |   |   |  |
|  | <b>TM19203</b><br> | 9448800204  | Bumper<br>Right   | 970 ATEGO 2<br>375 AXOR<br>374 AXOR 2<br>940 AXOR 2<br>942 AXOR 2<br>943 AXOR 2<br>944 AXOR 2         |   |   |  |
|  |   | <b>TM38281</b><br> | 6708800372  | Bumper<br>Rear, Right   | 667 T2/LN1<br>668 T2/LN1<br>669 T2/LN1<br>670 T2/LN1<br>667 VARIO<br>668 VARIO<br>670 VARIO |   |  |
|  |   |   | <b>TM38282</b><br> | 6708800272  | Bumper<br>Rear, Left  | 667 T2/LN1<br>668 T2/LN1<br>669 T2/LN1<br>670 T2/LN1<br>667 VARIO<br>668 VARIO<br>670 VARIO |  |
|  |   |   |   | <b>TM38283</b><br> | 9018800471  | Bumper<br>Rear, Right   | 690 SPRINTER<br>901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER<br>909 SPRINTER |












| Model / Details   | Description           | Replaces Ref. No: | TM No.  |
|---|-----------------------|-------------------|---|
| 690 SPRINTER<br>901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER<br>909 SPRINTER  | Bumper<br>Rear, Left  | 9018800371        | <b>TM38284</b><br>   |
| 906 SPRINTER  | Bumper<br>Rear, Left  | 9068801071        | <b>TM19614</b><br>   |
| 906 SPRINTER  | Bumper<br>Rear, Right | 9068801171        | <b>TM19615</b><br>  |
| 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3                          | Bumper<br>Left        | 9438851625        | <b>TM19276</b><br> |
| 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3                          | Bumper<br>Right       | 9438851725        | <b>TM19274</b><br> |
| 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3                          | Bumper                | 9438851825        | <b>TM19401</b><br> |
| 375 ACTROS<br>970 ATEGO 2<br>375 AXOR<br>374 AXOR 2<br>375 AXOR 2<br>940 AXOR 2<br>942 AXOR 2 | Bumper<br>Middle      | 9408850122        | <b>TM38285</b><br> |





| TM No.  | Replaces Ref. No:                      | Description  | Model / Details   |
|---|--|--|---|
| <b>TM38286</b><br>   | 9408850322                             | Bumper<br>Left   | 375 ACTROS<br>970 ATEGO 2<br>375 AXOR<br>374 AXOR 2<br>375 AXOR 2<br>940 AXOR 2<br>942 AXOR 2 |
| <b>TM38287</b><br>   | 9408850422                             | Bumper<br>Right  | 375 ACTROS<br>970 ATEGO 2<br>375 AXOR<br>374 AXOR 2<br>375 AXOR 2<br>940 AXOR 2<br>942 AXOR 2 |
| <b>TM38288</b><br>  | 9408802870                             | Bumper<br>Left   | 375 AXOR<br>944 AXOR  |
| <b>TM38289</b><br> | 9408802970                             | Bumper<br>Right  | 375 AXOR<br>944 AXOR 2  |
| <b>TM38290</b><br> | 3758800670<br>9408800770<br>9408804370 | Bumper<br>Left   | 375 ACTROS<br>375 AXOR<br>375 AXOR 2<br>950 AXOR 2<br>952 AXOR 2<br>953 AXOR 2<br>954 AXOR 2  |
| <b>TM38291</b><br> | 3758801070<br>9408804470               | Bumper<br>Right  | 375 ACTROS<br>375 AXOR<br>375 AXOR 2<br>950 AXOR 2<br>952 AXOR 2<br>953 AXOR 2<br>954 AXOR 2  |
| <b>TM38292</b><br> | 9068801370                             | Bumper<br>Front, With Fog Lamp<br>Hole, With<br>Parking Sensor | 906 SPRINTER  |



| Model / Details  | Description  | Replaces Ref. No:                                    | TM No.  |
|--|--|--|---|
| 906 SPRINTER   | Bumper<br>Front, With Fog Lamp<br>Hole,<br>No Parking Sensor | 9068800570   | <b>TM19360</b><br>   |
| 906 SPRINTER   | Bumper<br>Front, No Fog Lamp Hole<br>No Parking<br>Sensor    | 9068800170   | <b>TM19359</b><br>   |
| 906 SPRINTER   | Bumper<br>Front, No Fog Lamp Hole<br>With Parking<br>Sensor  | 9068800370<br>9068801070<br>9068801270               | <b>TM38293</b><br>  |
| 906 SPRINTER   | Bumper<br>Rear, With Inner Liner,<br>DN14118,<br>DN14119     | 9068800571<br>9068802571<br>9068803171<br>9068803271 | <b>TM19661</b><br> |
| 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3 | Bumper<br>Left   | 9438851125   | <b>TM19275</b><br> |
| 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3 | Bumper<br>Right  | 9438851225   | <b>TM19273</b><br> |
| 963 ACTROS MP4   | Bumper<br>Center   | 9608801790   | <b>TM38294</b><br> |





| TM No.  | Replaces Ref. No:        | Description            | Model / Details                  |
|---|--------------------------|------------------------|----------------------------------|
| <b>TM19286</b><br>   | 9608854925               | Bumper<br>Left         | 963 ACTROS MP4                   |
| <b>TM19285</b><br>   | 9608855025               | Bumper<br>Right        | 963 ACTROS MP4                   |
| <b>TM19283</b><br>  | 9608855525               | Bumper<br>Left         | 963 ACTROS MP4<br>963 ACTROS MP4 |
| <b>TM19282</b><br> | 9608855625               | Bumper<br>Right        | 963 ACTROS MP4<br>963 ACTROS MP4 |
| <b>TM19616</b><br> | 9068800171<br>9068800371 | Bumper<br>Rear, Center | 906 SPRINTER                     |
| <b>TM38295</b><br> | 9068809600<br>9068803971 | Bumper<br>Rear, Center | 906 SPRINTER                     |
| <b>TM38296</b><br> | 9608801890               | Bumper<br>Center       | 963 ACTROS MP4<br>963 ACTROS MP4 |



| Model / Details  | Description             | Replaces Ref. No:        | TM No.         |
|--|-------------------------|--------------------------|----------------|
| 375 ACTROS<br>375 AXOR<br>375 AXOR 2<br>950 AXOR 2<br>952 AXOR 2<br>953 AXOR 2<br>954 AXOR 2 | Bumper<br>Left          | 9408805870               | <b>TM38297</b> |
| 375 ACTROS<br>375 AXOR<br>375 AXOR 2<br>950 AXOR 2<br>952 AXOR 2<br>953 AXOR 2<br>954 AXOR 2 | Bumper<br>Right         | 9408805970               | <b>TM38298</b> |
| 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3                         | Bumper<br>Left          | 9438806072               | <b>TM19039</b> |
| 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3                         | Bumper<br>Right         | 9438806172               | <b>TM19038</b> |
| 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3                         | Bumper<br>Left          | 9438800870               | <b>TM38299</b> |
| 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3                         | Bumper<br>Right         | 9438808770<br>9438800970 | <b>TM38300</b> |
| 375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>958 ATEGO 2<br>970 ATEGO 2  | Bracket, Bumper<br>Left | 9705253439               | <b>TM18818</b> |








| TM No.  | Replaces Ref. No: | Description                           | Model / Details  |
|---|-------------------|---------------------------------------|--|
| <b>TM18819</b><br>   | 9705253539        | Bracket, Bumper<br>Right              | 375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>958 ATEGO 2<br>970 ATEGO 2                  |
| <b>TM38301</b><br>   | 9408851031        | Bracket, Bumper<br>Left               | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS   |
| <b>TM38302</b><br>   | 9408851131        | Bracket, Bumper<br>Right              | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS   |
| <b>TM38303</b><br> | 9018800114        | Bracket, Bumper<br>Front Bumper       | 690 SPRINTER<br>901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER<br>905 SPRINTER<br>909 SPRINTER |
| <b>TM38304</b><br> | 9018800314        | Bracket, Bumper<br>Rear Bumper, Left  | 690 SPRINTER<br>901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER<br>909 SPRINTER                 |
| <b>TM38305</b><br> | 9018800414        | Bracket, Bumper<br>Rear Bumper, Right | 690 SPRINTER<br>901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER<br>909 SPRINTER                 |
| <b>TM19215</b><br> | 9438853414        | Bracket, Bumper<br>Left               | 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3   |





| Model / Details   | Description              | Replaces Ref. No: | TM No.  |
|---|--------------------------|-------------------|---|
| 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3                          | Bracket, Bumper<br>Right | 9438853514        | <b>TM19216</b>  |
|   |                          |                   |    |
| 906 SPRINTER  | Bracket, Bumper<br>Left  | 9068890014        | <b>TM19631</b>  |
|   |                          |                   |    |
| 906 SPRINTER  | Bracket, Bumper<br>Right | 9068890114        | <b>TM19632</b>  |
|   |                          |                   |   |
| 900 SPRINTER<br>906 SPRINTER  | Bracket, Bumper<br>Left  | 9068821014        | <b>TM38306</b>  |
|   |                          |                   |  |
| 900 SPRINTER<br>906 SPRINTER  | Bracket, Bumper<br>Right | 9068821114        | <b>TM38307</b>  |
|   |                          |                   |  |
| 375 ACTROS<br>970 ATEGO 2<br>375 AXOR<br>374 AXOR 2<br>375 AXOR 2<br>940 AXOR 2<br>942 AXOR 2 | Spoiler, Bumper<br>Left  | 9408850125        | <b>TM19460</b>  |
|   |                          |                   |  |
| 375 ACTROS<br>970 ATEGO 2<br>375 AXOR<br>374 AXOR 2<br>375 AXOR 2<br>940 AXOR 2<br>942 AXOR 2 | Spoiler, Bumper<br>Right | 9408850225        | <b>TM19461</b>  |
|   |                          |                   |  |








| TM No.  | Replaces Ref. No: | Description              | Model / Details   |
|---|-------------------|--------------------------|---|
| <b>TM38308</b><br>   | 9438852225        | Spoiler, Bumper          | 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3                          |
| <b>TM38309</b><br>   | 9418850825        | Spoiler, Bumper<br>Left  | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS  |
| <b>TM18851</b><br>  | 9418850925        | Spoiler, Bumper<br>Right | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS  |
| <b>TM38310</b><br> | 9418850922        | Spoiler, Bumper          | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS  |
| <b>TM19057</b><br> | 9448850725        | Spoiler, Bumper<br>Left  | 375 ACTROS<br>970 ATEGO 2<br>375 AXOR<br>374 AXOR 2<br>375 AXOR 2<br>940 AXOR 2<br>942 AXOR 2 |
| <b>TM19058</b><br> | 9448850125        | Spoiler, Bumper<br>Right | 375 ACTROS<br>970 ATEGO 2<br>375 AXOR<br>374 AXOR 2<br>375 AXOR 2<br>940 AXOR 2<br>942 AXOR 2 |
| <b>TM19055</b><br> | 9448850525        | Spoiler, Bumper<br>Left  | 375 ACTROS<br>970 ATEGO 2<br>375 AXOR<br>374 AXOR 2<br>375 AXOR 2<br>940 AXOR 2<br>942 AXOR 2 |



| Model / Details   | Description               | Replaces Ref. No: | TM No.         |
|---|---------------------------|-------------------|----------------|
| 375 ACTROS<br>970 ATEGO 2<br>375 AXOR<br>374 AXOR 2<br>375 AXOR 2<br>940 AXOR 2<br>942 AXOR 2 | Spoiler, Bumper<br>Right  | 9448850625        | <b>TM19056</b> |
| 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3                          | Spoiler, Bumper<br>Left   | 9438850325        | <b>TM18857</b> |
| 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3                          | Spoiler, Bumper<br>Right  | 9438850425        | <b>TM18856</b> |
| 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3                          | Spoiler, Bumper<br>Center | 9438850525        | <b>TM18858</b> |
| 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3                          | Spoiler, Bumper<br>Right  | 9438850125        | <b>TM18874</b> |
| 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3                          | Spoiler, Bumper<br>Center | 9438850225        | <b>TM18875</b> |
| 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3                          | Spoiler, Bumper<br>Left   | 9438850025        | <b>TM18873</b> |












| TM No.  | Replaces Ref. No: | Description                  | Model / Details   |
|---|-------------------|------------------------------|---|
| <b>TM19365</b><br>   | 9608854725        | Spoiler, Bumper<br>Left      | 963 ACTROS MP4  |
| <b>TM19364</b><br>   | 9608854825        | Spoiler, Bumper<br>Right     | 963 ACTROS MP4  |
| <b>TM18786</b><br>  | 9418801670        | Step Plate, Bumper<br>Center | 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>970 ATEGO 2<br>375 AXOR |
| <b>TM38311</b><br> | 9438830001        | Step Plate, Bumper           | 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3                          |
| <b>TM19221</b><br> | 9068850011        | Step Plate, Bumper           | 906 SPRINTER  |
| <b>TM38312</b><br> | 9608850311        | Step Plate, Bumper           | 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS                                    |
| <b>TM19552</b><br> | 9438830501        | Step Plate, Bumper<br>Center | 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3                          |



| Model / Details   | Description                 | Replaces Ref. No: | TM No.  |
|---|-----------------------------|-------------------|---|
| 970 ATEGO 2<br>375 AXOR<br>374 AXOR 2<br>940 AXOR 2<br>942 AXOR 2<br>943 AXOR 2<br>944 AXOR 2 | Cover, Bumper<br>Left       | 9448850574        | <b>TM19589</b><br>   |
| 970 ATEGO 2<br>375 AXOR<br>374 AXOR 2<br>940 AXOR 2<br>942 AXOR 2<br>943 AXOR 2<br>944 AXOR 2 | Cover, Bumper<br>Right      | 9448850674        | <b>TM19590</b><br>   |
| 970 ATEGO 2<br>375 AXOR<br>374 AXOR 2<br>940 AXOR 2<br>942 AXOR 2<br>943 AXOR 2<br>944 AXOR 2 | Cover, Bumper<br>Middle     | 9448850774        | <b>TM19588</b><br>  |
| 906 SPRINTER  | Cover, Bumper<br>Rear Left  | 9068802671        | <b>TM38313</b><br> |
| 906 SPRINTER  | Cover, Bumper<br>Rear Right | 9068802771        | <b>TM38314</b><br> |
| 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3                          | Cover, Bumper<br>Center     | 9438851122        | <b>TM19553</b><br> |
| 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3                          | Cover, Bumper               | 9438851822        | <b>TM38315</b><br> |





| TM No.  | Replaces Ref. No: | Description            | Model / Details |
|---|-------------------|------------------------|-----------------|
| <b>TM19451</b><br>   | 9608859408        | Cover, Bumper<br>Left  | 963 ACTROS MP4  |
| <b>TM19452</b><br>   | 9608859508        | Cover, Bumper<br>Right | 963 ACTROS MP4  |
| <b>TM19363</b><br>   | 9608859608        | Cover, Bumper<br>Left  | 963 ACTROS MP4  |
| <b>TM19362</b><br> | 9608859708        | Cover, Bumper<br>Right | 963 ACTROS MP4  |
| <b>TM19609</b><br> | 9608856601        | Cover, Bumper<br>Left  | 963 ACTROS MP4  |
| <b>TM19610</b><br> | 9608856701        | Cover, Bumper<br>Right | 963 ACTROS MP4  |
| <b>TM19289</b><br> | 9608853674        | Cover, Bumper<br>Left  | 963 ACTROS MP4  |





| Model / Details   | Description             | Replaces Ref. No:        | TM No.  |
|---|-------------------------|--------------------------|---------|
| 963 ACTROS MP4  | Cover, Bumper<br>Right  | 9608853774               | TM19288 |
|   |                         |                          |         |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS  | Cover, Bumper<br>Left   | 9418853422               | TM38316 |
|   |                         |                          |         |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS  | Cover, Bumper<br>Right  | 9418853522               | TM38317 |
|   |                         |                          |         |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS  | Cover, Bumper           | 9418853822               | TM38318 |
|   |                         |                          |         |
| 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>970 ATEGO 2<br>375 AXOR | Cover, Bumper<br>Center | 9418851401<br>3758850001 | TM18788 |
|   |                         |                          |         |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS  | Cover, Bumper<br>Left   | 9418850074               | TM38319 |
|   |                         |                          |         |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS  | Cover, Bumper<br>Right  | 9418850174               | TM38320 |
|   |                         |                          |         |





| TM No.  | Replaces Ref. No:        | Description             | Model / Details  |
|---|--------------------------|-------------------------|--|
| <b>TM19059</b><br>   | 9438850374               | Cover, Bumper<br>Center | 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3 |
| <b>TM18820</b><br>   | 9438850426<br>9438850226 | Cover, Bumper           | 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3 |
| <b>TM19345</b><br>   | 9438840060               | Cover, Bumper<br>Left   | 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3 |
| <b>TM19346</b><br> | 9438840160               | Cover, Bumper<br>Right  | 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3 |
| <b>TM19554</b><br> | 9438851222               | Cover, Bumper<br>Left   | 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3 |
| <b>TM19555</b><br> | 9438851322               | Cover, Bumper<br>Right  | 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3 |
| <b>TM19355</b><br> | 9438851422               | Cover, Bumper<br>Left   | 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3 |



| Model / Details   | Description                                 | Replaces Ref. No: | TM No.         |
|---|---|-------------------|----------------|
| 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3  | Cover, Bumper<br>Right                      | 9438851522        | <b>TM19356</b> |
| 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3  | Cover, Bumper<br>Center<br>1737 / 227 / 107 | 9438851325        | <b>TM19277</b> |
| 906 SPRINTER  | Cover, Bumper                               | 0008850024        | <b>TM38321</b> |
| 375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>375 ATEGO 2<br>958 ATEGO 2<br>970 ATEGO 2          | Cover, Bumper<br>Left                       | 9738800025        | <b>TM18765</b> |
| 963 ACTROS MP4<br>964 AROCS<br>964 AROCS<br>963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS<br>964 AROCS | Cover, Bumper                               | 9608852108        | <b>TM19287</b> |
| 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3  | Cover, Bumper<br>Left                       | 9438841674        | <b>TM38322</b> |
| 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3  | Cover, Bumper<br>Right                      | 9438841474        | <b>TM38323</b> |





| TM No.  | Replaces Ref. No:        | Description              | Model / Details  |
|---|--------------------------|--------------------------|--|
| <b>TM38324</b><br>   | 9438850526<br>9438850026 | Cover, Bumper<br>Center  | 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3   |
| <b>TM38325</b><br>   | 9418851501               | Cover, Bumper<br>Center  | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>374 AXOR 2<br>950 AXOR 2<br>952 AXOR 2<br>953 AXOR 2 |
| <b>TM19343</b><br>  | 9068850053               | Grille, Bumper<br>Center | 906 SPRINTER   |
| <b>TM38326</b><br> | 9418801970               | Plate, Bumper<br>Center  | 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>970 ATEGO 2<br>375 AXOR                |
| <b>TM18842</b><br> | 9438850326               | Plate, Bumper            | 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3   |
| <b>TM38327</b><br> | 9068850075               | Plate, Bumper<br>Center  | 906 SPRINTER   |
| <b>TM38328</b><br> | 9066860074               | Strip, Bumper<br>Rear    | 906 SPRINTER   |



| Model / Details              | Description            | Replaces Ref. No:        | TM No.             |
|------------------------------|------------------------|--------------------------|--------------------|
| 906 SPRINTER                 | Strip, Bumper<br>Rear  | 9066861574<br>9066860174 | <b>TM38329</b><br> |
| 906 SPRINTER                 | Strip, Bumper<br>Left  | 9066375009               | <b>TM38330</b><br> |
| 906 SPRINTER                 | Strip, Bumper<br>Right | 9066375109               | <b>TM38331</b><br> |
| 900 SPRINTER<br>906 SPRINTER | Strip, Bumper<br>Left  | 9066375609               | <b>TM38332</b><br> |
| 900 SPRINTER<br>906 SPRINTER | Strip, Bumper<br>Right | 9066375709               | <b>TM38333</b><br> |
| 900 SPRINTER<br>906 SPRINTER | Strip, Bumper<br>Left  | 9066376209               | <b>TM38334</b><br> |
| 900 SPRINTER<br>906 SPRINTER | Strip, Bumper<br>Right | 9066376309               | <b>TM38335</b><br> |





| <i>TM No.</i>   | <i>Replaces Ref. No:</i> | <i>Description</i>     | <i>Model / Details</i>       |
|---|--------------------------|------------------------|------------------------------|
| <b>TM38336</b><br>   | 9066375409               | Strip, Bumper<br>Left  | 900 SPRINTER<br>906 SPRINTER |
| <b>TM38337</b><br>   | 9066375509               | Strip, Bumper<br>Right | 900 SPRINTER<br>906 SPRINTER |
| <b>TM38338</b><br>  | 9066376009               | Strip, Bumper<br>Left  | 900 SPRINTER<br>906 SPRINTER |
| <b>TM38339</b><br> | 9066376109               | Strip, Bumper<br>Right | 900 SPRINTER<br>906 SPRINTER |












| Model / Details   | Description  | Replaces Ref. No:                                    | TM No.  |
|---|--|--|---|
| 364 O 370<br>364 O 370,371<br>364 O 371<br>364 O 373 RSD<br>664 O 371<br>664 O 374<br>664 O 400 RSD BUGGY | Relay, Central Electric Unit                                       | 3645427319   | <b>TM10065</b><br>   |
| 632 TOURISMO<br>629 TRAVEGO<br>632 TRAVEGO<br>629 SETRA<br>632 SETRA                                      | Flasher Relay, Central Electric Unit<br>Repl. Bosch: 0 332 014 203 | 0015421119<br>0008201710                             | <b>TM09995</b><br>   |
| 903 SPRINTER<br>639 VIANO   | Flasher Relay, Central Electric Unit                               | 0015310260<br>0045455805<br>7375111000<br>0035459805 | <b>TM11185</b><br>  |
| 615 LK/LN2<br>674 LK/LN2<br>675 LK/LN2<br>676 LK/LN2<br>677 LK/LN2<br>679 LK/LN2<br>699 MK                | Flasher Relay, Central Electric Unit                               | 0035440632<br>0025446432<br>0025441432<br>0025445932 | <b>TM11703</b><br> |
| 310 LF 508 D/LF 608 D<br>352 OF SERIES<br>357 O 405<br>612 O 405<br>357 O 407<br>612 O 407<br>357 O 408   | Flasher Relay, Central Electric Unit                               | 0025440432<br>0025447932                             | <b>TM11182</b><br> |
| 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>375 ATEGO<br>970 ATEGO              | Flasher Relay, Central Electric Unit                               | 0035443032<br>0035443732<br>0035444332<br>0035445032 | <b>TM11792</b><br> |
| 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3    | Flasher Relay, Central Electric Unit                               | 0025422719<br>0045453505<br>0045457405<br>0045457505 | <b>TM11184</b><br> |





| TM No.  | Replaces Ref. No:                                    | Description   | Model / Details  |
|---|--|---|--|
| <b>TM38340</b>  | -  | Tachograph Disc Set,<br>Central Electric Unit<br>125 km/h | -  |
|    |  |   |  |
| <b>TM10000</b>  | 0051543402<br>0071542702<br>0091540702<br>3661500750 | Alternator  | 674 LK/LN2<br>675 LK/LN2<br>676 LK/LN2<br>677 LK/LN2<br>615 NG<br>616 NG<br>619 NG                     |
|    |  |   |  |
| <b>TM10016</b>  | 0121546702   | Alternator<br>Repl. Bosch: 0 124 655<br>016               | 979 ACCELO<br>375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>932 ACTROS 2/3     |
|   |  |   |  |
| <b>TM11527</b>  | 0111548702<br>0131544102                             | Alternator<br>Repl. Bosch: 0 124 655<br>001               | 979 ACCELO<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>933 ACTROS 2/3 |
|  |  |   |  |
| <b>TM11528</b>  | 0121540502<br>0131544202                             | Alternator<br>Repl. Bosch: 0 124 655<br>004               | 979 ACCELO<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>933 ACTROS 2/3 |
|  |  |   |  |
| <b>TM11854</b>  | 0111548602<br>0131542802                             | Alternator<br>Repl. Bosch: 0 124 555<br>001               | 979 ACCELO<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>933 ACTROS 2/3 |
|  |  |   |  |
| <b>TM11674</b>  | 0021548406<br>0001541705<br>0021546706<br>0021546406 | Regulator, Alternator                                     | 668 VARIO  |
|  |  |   |  |



| Model / Details   | Description                             | Replaces Ref. No:                      | TM No.  |
|---|---|--|---|
| 611 T1/TN<br>408 UNIMOG<br>601 207 D/208 D<br>601 209 D/210 D<br>602 307 D/308 D<br>602 307 D/308D<br>602 308 D | Pulley, Alternator<br>M16xø55,5x23/37,5 | 6021500060<br>6041500360<br>6041500060 | <b>TM11966</b><br>   |
| 979 ACCELO<br>375 ACTROS<br>375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO                       | Pulley, Alternator<br>ø17xø71,8x36,7    | 0011552115                             | <b>TM11778</b><br>   |
| -   | Pulley, Alternator                      | 6111550415<br>6111550015<br>6111500360 | <b>TM10015</b><br>  |
| 979 ACCELO<br>375 ATEGO<br>375 ATEGO 2<br>958 ATEGO 2<br>970 ATEGO 2<br>976 ATEGO 2<br>375 AXOR                 | Pulley, Alternator                      | 9061551715                             | <b>TM11964</b><br> |
| 979 ACCELO<br>950 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>934 ACTROS 2/3<br>375 AXOR<br>374 AXOR 2        | Pulley, Alternator<br>ø84xø17x42        | 0011554615                             | <b>TM11965</b><br> |
| 638 VITO<br>638 V-CLASS   | Pulley, Alternator                      | 6041500160                             | <b>TM10439</b><br> |
| -   | Pulley, Alternator                      | 6481550015<br>6461500260               | <b>TM07053</b><br> |





| TM No.  | Replaces Ref. No:                                    | Description                                | Model / Details  |
|---|--|--|--|
| <b>TM10423</b><br>   | 6461550115   | Pulley, Alternator                         | 906 SPRINTER<br>909 SPRINTER<br>636 VIANO<br>639 VIANO   |
| <b>TM12099</b><br>   | 6041500660<br>6041500460                             | Pulley, Alternator                         | 668 VARIO<br>670 VARIO   |
| <b>TM11643</b><br>  | 9061551515<br>9062000815<br>9061550815               | Pulley, Alternator                         | 979 ACCELO<br>375 ACTROS<br>375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO                |
| <b>TM11645</b><br> | 9061551315<br>9061550315                             | Pulley, Alternator                         | 979 ACCELO<br>375 ACTROS<br>375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO                |
| <b>TM10650</b><br> | 6111550215<br>6111500160<br>6111550315<br>6111550515 | Pulley, Alternator                         | 690 SPRINTER<br>901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER<br>905 SPRINTER<br>638 VITO |
| <b>TM11777</b><br> | 0011551915   | Pulley, Alternator<br>ø84xø17x37,2         | 979 ACCELO<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3   |
| <b>TM10913</b><br> | 6421500360<br>6421500660                             | Pulley, Alternator<br>Repl. Dayco: ALP2389 | 906 SPRINTER<br>639 VIANO  |



| Model / Details   | Description                                    | Replaces Ref. No:                      | TM No.  |
|---|--|--|---|
| 979 ACCELO<br>375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3  | Seal Ring, Alternator<br>ø20xø35x7 / NBR       | 0069977447                             | <b>TM01245</b>  |
|   |  |  |    |
| 363 LP 2226/6X4<br>363 LPB 2226/6X4<br>363 LPK 2226/6X4<br>363 LPS 2226/6X4<br>650 MK<br>651 MK<br>652 MK   | Starter Motor                                  | 0031514101<br>0031514501<br>0041516001 | <b>TM11654</b>  |
|   |  |  |    |
| -   | Starter Motor                                  | 0001417075                             | <b>TM10091</b>  |
|   |  |  |    |
| -   | Starter Motor<br>Repl. Bosch: 0 001 417<br>037 | 0031516201                             | <b>TM38341</b>  |
|   |  |  |  |
| 363 LP 2232/6X4<br>363 LPK 2232/6X4<br>363 LPS 2232/6X4<br>619 NG<br>620 NG<br>621 NG<br>623 NG   | Starter Motor<br>Repl. Bosch: 0 001 417<br>001 | 0011519701<br>0031514601<br>0041516101 | <b>TM10187</b>  |
|   |  |  |  |
| 944 AXOR 2<br>634 TOURO<br>671 CONECTO<br>613 TOURISMO<br>634 CBC - FAHRGESTELL<br>2-ACHSER<br>634 CBC - FAHRGESTELL<br>OC500 CNG GAS<br>634 IBC 1842 | Starter Motor<br>Repl. Bosch: 0 001 372<br>005 | 4571510301                             | <b>TM10159</b>  |
|   |  |  |  |
| 375 ACTROS<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>375 ATEGO 2<br>970 ATEGO 2  | Starter Motor                                  | 0061514801<br>0061516801<br>0071510801 | <b>TM11581</b>  |
|   |  |  |  |







| TM No.  | Replaces Ref. No: | Description             | Model / Details  |
|---|-------------------|-------------------------|------------------|
| <b>TM10631</b><br>   | 0001516013        | Gear, Starter Motor     | 338 L 1418       |
|   | 0011510513        | Repl. Bosch: 2 006 382  | 338 LK 1418      |
|   | 0011510613        | 020                     | 338 LP 1418      |
|   |                   |                         | 338 LPS 1418     |
|   |                   |                         | 338 LS 1418      |
|   |                   |                         | 343 T2/L         |
|   |                   |                         | 346 L 1924       |
| <b>TM10882</b><br>   | 0001514015        | Rotor, Starter Motor    | 979 ACCELO       |
|   |                   | Repl. Bosch: 2 004 005  | 950 ACTROS       |
|   |                   | 022                     | 952 ACTROS       |
|   |                   |                         | 953 ACTROS       |
|   |                   |                         | 954 ACTROS       |
|   |                   |                         | 930 ACTROS 2/3   |
|   |                   |                         | 933 ACTROS 2/3   |
| <b>TM11704</b><br>   | 0001514815        | Rotor, Starter Motor    | 314 LP           |
|   | 0001515315        | Repl. Bosch: 2 004 014  | 316 LP           |
|   |                   | 975                     | 674 LK/LN2       |
|   |                   |                         | 675 LK/LN2       |
|   |                   |                         | 678 LK/LN2       |
|   |                   |                         | 616 NG           |
|   |                   |                         | 352 OF SERIES    |
| <b>TM10670</b><br> | 0001517055        | Stator, Starter Motor   | 314 LP           |
|   |                   | Repl. Bosch: 2 004 125  | 316 LP           |
|   |                   | 078                     | 336 LP 1924      |
|   |                   |                         | 336 LPS 1924     |
|   |                   |                         | 338 L 1418       |
|   |                   |                         | 338 LK 1418      |
|   |                   |                         | 338 LPS 1418     |
| <b>TM10671</b><br> | 0001518055        | Stator, Starter Motor   | 944 AXOR 2       |
|   |                   | Repl. Bosch: 2 004 125  | 363 LP 2232/6X4  |
|   |                   | 083                     | 363 LPK 2232/6X4 |
|   |                   |                         | 363 LPS 2232/6X4 |
|   |                   |                         | 615 NG           |
|   |                   |                         | 619 NG           |
|   |                   |                         | 621 NG           |
| <b>TM10144</b><br> | 0011528810        | Solenoid, Starter Motor | 944 AXOR 2       |
|   | 0001524210        | Repl. Bosch: 0 331 450  | 314 LP           |
|   |                   | 001                     | 316 LP           |
|   |                   |                         | 336 LP 1924      |
|   |                   |                         | 336 LPS 1924     |
|   |                   |                         | 338 L 1418       |
|   |                   |                         | 338 LK 1418      |
| <b>TM10595</b><br> | 0011529010        | Solenoid, Starter Motor | 944 AXOR 2       |
|   | 0001524010        | Repl. Bosch: 0 331 101  | 314 LP           |
|   |                   | 006                     | 316 LP           |
|   |                   |                         | 336 LP 1924      |
|   |                   |                         | 336 LPS 1924     |
|   |                   |                         | 338 L 1418       |
|   |                   |                         | 338 LK 1418      |





| Model / Details  | Description  | Replaces Ref. No:                                    | TM No.  |
|--|--|--|---|
| 309 T2/L<br>309 TL2/L<br>310 LF 508 D/LF 608 D<br>310 LT 608 D<br>310 T2/L<br>313 T2/L<br>314 LP   | Switch, Starter Motor                                      | 0015454914<br>0015450214<br>0005456314<br>3455457314 | <b>TM10839</b><br>   |
| 650 MK<br>651 MK<br>652 MK<br>653 MK<br>654 MK<br>699 MK<br>625 SK   | Switch, Starter Motor                                      | 6555450008   | <b>TM05375</b><br>   |
| 397 LP 1014 MBSA-RSA<br>397 LP 1114,1214 MB-SA-RSA<br>397 LP 1214 A MBSA-RSA<br>397 LP 1617 A MBSA-RSA<br>397 LP/LPK 1314 MB-SA-RSA<br>397 LP/LPK 1417,1617 MBSA-RSA | Switch, Starter Motor                                      | 6675450013   | <b>TM05373</b><br>   |
| 314 LP<br>316 LP<br>318 LP<br>328 T2/L<br>336 LP 1924<br>336 LPS 1924<br>338 LK 1418   | Disc Coupling, Starter Motor<br>Repl. Bosch: 2 006 401 527 | 0001510633   | <b>TM10630</b><br> |
| 979 ACCELO<br>375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3   | Temperature Sensor   | 0031538428<br>0041530428                             | <b>TM07874</b><br> |
| 352 L 1313<br>352 L 1813/6X2<br>352 L 1813/6X4<br>352 LA 1313<br>352 LAK 1313<br>352 LAKO 1313<br>352 LAS 1313   | Temperature Sensor   | 0025427317<br>0075420917<br>0045425617<br>3845427017 | <b>TM00329</b><br> |
| 350 LS 1924<br>350 LS 1924A,1929<br>350 LS 1924A,1929,1930<br>345 OH SERIES<br>321 O 362<br>344 O 355<br>364 O 364   | Temperature Sensor<br>Repl. Bosch: 0 281 002 011           | 0015422417<br>0075422417                             | <b>TM38347</b><br> |



| TM No.  | Replaces Ref. No: | Description   | Model / Details  |
|---|-------------------|---|--|
| <b>TM11276</b><br>   | 0041534328        | Temperature Sensor                                  | 979 ACCELO<br>375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3                                 |
|   | 0041534228        |   |  |
| <b>TM07158</b><br>   | 0015422317        | Temperature Sensor<br>47xSW:19                      | 308 L 608 E,L 708 E<br>308 L/LO 608 D<br>308 LO 608 D,LO 708 D/E<br>309 T2/L<br>309 TL2/L<br>310 LF 508 D/LF 608 D<br>310 LT 608 D |
|   |                   |   |  |
| <b>TM10186</b><br>   | 0041531628        | Temperature Sensor<br>Repl. VDO: 323 805 041<br>003 | 979 ACCELO<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3                             |
|   | 0041532528        |   |  |
| <b>TM12493</b><br> | 0004303807        | Pressure Sensor<br>Repl. Knorr: I139746F004         | 972 ATEGO<br>975 ATEGO<br>958 ATEGO 2<br>972 ATEGO 2<br>975 ATEGO 2<br>976 ATEGO 2<br>954 AXOR 2                                   |
|   |                   |   |  |
| <b>TM12075</b><br> | 0041539828        | Pressure Sensor                                     | 651 MK<br>652 MK<br>653 MK<br>654 MK<br>625 SK<br>655 SK<br>656 SK   |
|   | 0061536028        |   |  |
| 0071534328  |                   |   |  |
| 0091535028  |                   |   |  |
| <b>TM01993</b><br> | 0031537628        | Pressure Sensor                                     | 979 ACCELO<br>375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3                                 |
|   |                   |   |  |
| <b>TM11950</b><br> | 0041536728        | Pressure Sensor                                     | 906 SPRINTER<br>909 SPRINTER<br>636 VIANO<br>639 VIANO   |
|   | 0051531528        |   |  |
|   | 0061533328        |   |  |
|   | 0061536528        |   |  |



| Model / Details   | Description                                      | Replaces Ref. No:                                    | TM No.  |
|---|--|--|---|
| 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO | Pressure Sensor<br>Repl. Kongsberg:<br>630767AM  | 9705420018<br>9705420218                             | <b>TM11769</b><br>   |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>942 AXOR 2  | Pressure Sensor<br>0,55 Bar<br>M12x1,5x55xSW27   | 0045458614   | <b>TM12068</b><br>   |
| 628 CITARO<br>628 CONECTO<br>633 INTEGRO<br>632 TOURISMO<br>629 TRAVEGO<br>628 SETRA<br>629 SETRA           | Pressure Sensor<br>Repl. Wabco: 441 043<br>002 1 | 0034317706<br>0034316406<br>0025422118<br>6284200061 | <b>TM15124</b><br>  |
| 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3      | Pressure Sensor<br>Repl. Wabco: 932 500<br>501 1 | 0004303907<br>0035427418<br>0015429218<br>0015426518 | <b>TM11768</b><br> |
| 950 ACTROS<br>952 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>934 ACTROS 2/3<br>375 AXOR    | Pressure Sensor<br>Repl. Wabco: 441 044<br>101 0 | 0015421718<br>0035422518<br>0055425818               | <b>TM11147</b><br> |
| 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3      | Pressure Sensor<br>6,5 Bar                       | 0065451114<br>0045455514                             | <b>TM10217</b><br> |
| 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3      | Pressure Sensor<br>5,5 Bar                       | 0045455414   | <b>TM11710</b><br> |





| <i>TM No.</i>   | <i>Replaces Ref. No:</i>                             | <i>Description</i>      | <i>Model / Details</i>   |
|---|--|-------------------------|--|
| <b>TM38348</b><br>   | 0055451114   | Pressure Sensor         | 667 VARIO<br>668 VARIO<br>670 VARIO  |
| <b>TM38349</b><br>   | 0045456914   | Pressure Sensor         | 957 ECONIC<br>905 SPRINTER<br>667 VARIO<br>668 VARIO<br>670 VARIO                                      |
| <b>TM01995</b><br>   | 0011532120<br>0011533120                             | Speed Sensor            | 979 ACCELO<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3 |
| <b>TM32555</b><br> | 0075422517<br>0105428017<br>0125424617               | Speed Sensor            | 375 ACTROS<br>970 ATEGO<br>972 ATEGO<br>976 ATEGO<br>970 ATEGO 2<br>972 ATEGO 2<br>974 ATEGO           |
| <b>TM01990</b><br> | 0011530420<br>0001539420<br>0001539720<br>0001538620 | Speed Sensor            | 650 MK<br>651 MK<br>652 MK<br>653 MK<br>654 MK<br>621 NG<br>625 SK                                     |
| <b>TM01989</b><br> | 0011530220<br>0001539320<br>0001533872<br>0001539620 | Speed Sensor            | 650 MK<br>651 MK<br>652 MK<br>653 MK<br>654 MK<br>621 NG<br>625 SK                                     |
| <b>TM10686</b><br> | 0055429417<br>0065424617                             | Speed Sensor<br>M22x1,5 | 343 T2/L<br>346 L 1924<br>346 L 1928<br>346 LK 1924<br>346 LK 1928<br>346 LS 1924<br>346 LS 1928       |



| Model / Details  | Description  | Replaces Ref. No:                                    | TM No.  |
|--|--|--|---|
| 976 ATEGO<br>976 ATEGO 2<br>950 AXOR 2<br>952 AXOR 2<br>673 LK/LN2<br>674 LK/LN2<br>675 LK/LN2         | Speed Sensor<br>M22x1,5                              | 0095421017   | <b>TM31666</b><br>   |
| 979 ACCELO<br>375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3     | Speed Sensor   | 0155422417<br>0135426217                             | <b>TM32592</b><br>   |
| 952 ACTROS<br>954 ACTROS<br>972 ATEGO<br>976 ATEGO<br>970 ATEGO 2<br>972 ATEGO 2<br>976 ATEGO 2        | Speed Sensor   | 0075423617   | <b>TM11900</b><br>   |
| 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3 | Speed Sensor   | 0135425717<br>0145427817<br>0155423717<br>0165421617 | <b>TM11767</b><br> |
| 979 ACCELO<br>375 ACTROS<br>934 ACTROS 2/3<br>375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO         | Oil Pressure Sensor<br>Repl. Bosch: 0 281 006<br>283 | 0041532028<br>0091534728                             | <b>TM11764</b><br> |
| 979 ACCELO<br>375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3     | Oil Pressure Sensor                                  | 0041534928<br>0071530828                             | <b>TM01996</b><br> |
| 344 L 1113<br>344 L 1116<br>344 LA 1113<br>344 LAK 1113<br>344 LAS 1113<br>344 LK 1113<br>344 LS 1113  | Oil Pressure Sensor                                  | 0015425617   | <b>TM10796</b><br> |














| TM No.  | Replaces Ref. No:        | Description                           | Model / Details  |
|---|--------------------------|---------------------------------------|--|
| <b>TM01554</b><br>   | 0001539932               | Oil Pressure Sensor                   | 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3     |
| <b>TM02962</b><br>   | 0015423817               | Oil Pressure Sensor<br>45xSW:21       | -  |
| <b>TM12156</b><br>  | 0061531228               | Oil Level Sensor<br>M14x1,5x215xSW:27 | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 |
| <b>TM02078</b><br> | 0041536328               | Oil Level Sensor                      | 979 ACCELO<br>375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>958 ATEGO 2                 |
| <b>TM01992</b><br> | 0041534428               | Oil Level Sensor                      | 979 ACCELO<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3     |
| <b>TM01991</b><br> | 0031539828<br>0041531728 | Oil Level Sensor                      | 979 ACCELO<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3     |
| <b>TM11739</b><br> | 0018201461<br>0018202161 | Head Lamp<br>Left, Without Bulb       | -  |





| Model / Details  | Description   | Replaces Ref. No:        | TM No.  |
|--|---|--------------------------|---|
| -  | Head Lamp<br>Right, Without Bulb  | 0018201561<br>0018202261 | <b>TM11738</b><br>   |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>375 AXOR<br>944 AXOR 2<br>950 AXOR 2   | Head Lamp<br>Left, With Signal Equip-<br>ment, Manuel,<br>Without Bulb    | 9418205161<br>9418202561 | <b>TM11726</b><br>   |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>375 AXOR<br>944 AXOR 2<br>950 AXOR 2   | Head Lamp<br>Right, With Signal Equip-<br>ment, Manuel,<br>Without Bulb   | 9418205261<br>9418202661 | <b>TM11725</b><br>  |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>950 AXOR 2<br>952 AXOR 2<br>953 AXOR 2 | Head Lamp<br>Left, With Signal Equip-<br>ment, Electric,<br>Without Bulb  | 9418204361               | <b>TM10812</b><br> |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>950 AXOR 2<br>952 AXOR 2<br>953 AXOR 2 | Head Lamp<br>Right, With Signal Equip-<br>ment, Electric,<br>Without Bulb | 9418204461               | <b>TM10811</b><br> |
| 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>375 AXOR<br>375 AXOR 2   | Head Lamp<br>Left, Electric, Without Bulb                                 | 9418205561<br>9418202961 | <b>TM11724</b><br> |
| 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>375 AXOR<br>375 AXOR 2   | Head Lamp<br>Right, Electric, Without<br>Bulb                             | 9418205661<br>9418203061 | <b>TM11723</b><br> |










| TM No.  | Replaces Ref. No:  | Description  | Model / Details |
|---|--|--|-----------------|
| <b>TM11731</b><br>   | 9738200961   | Head Lamp<br>Left, Without Bulb                      | 970 ATEGO       |
|   |  |  | 972 ATEGO       |
| <b>TM11730</b><br>   | 9738201061   | Head Lamp<br>Right, Without Bulb                     | 975 ATEGO       |
|   |  |  | 976 ATEGO       |
| <b>TM10818</b><br>  | 9738200161   | Head Lamp<br>Left, Electric, Without Bulb            | 958 ATEGO 2     |
|   |  |  | 970 ATEGO 2     |
| <b>TM10817</b><br> | 9738200261   | Head Lamp<br>Right, Electric, Without<br>Bulb        | 972 ATEGO 2     |
|   |  |  | 975 ATEGO 2     |
| <b>TM38350</b><br> | 6418200861S<br>6418200361S<br>3818203961S<br>3818205161S | Head Lamp<br>Left, Plastic Frame, With-<br>out Bulb  | 976 ATEGO       |
|   |  |  | 970 ATEGO 2     |
| <b>TM38351</b><br> | 3818200761S<br>3818203061S<br>3818204461S<br>6418200961S | Head Lamp<br>Right, Plastic Frame, With-<br>out Bulb | 650 MK          |
|   |  |  | 651 MK          |
| <b>TM38352</b><br> | 9408200161   | Head Lamp<br>Left, Without Bulb                      | 652 MK          |
|   |  |  | 653 MK          |
|   |  |  | 654 MK          |
|   |  |  | 699 MK          |
|   |  |  | 615 NG          |
|   |  |  | 970 ATEGO 2     |
|   |  |  | 375 AXOR        |
|   |  |  | 374 AXOR 2      |
|   |  |  | 375 AXOR 2      |
|   |  |  | 940 AXOR 2      |
|   |  |  | 942 AXOR 2      |
|   |  |  | 943 AXOR 2      |



| Model / Details   | Description                                | Replaces Ref. No: | TM No.  |
|---|--|-------------------|---|
| 970 ATEGO 2<br>375 AXOR<br>374 AXOR 2<br>375 AXOR 2<br>940 AXOR 2<br>942 AXOR 2<br>943 AXOR 2   | Head Lamp<br>Right, Without Bulb           | 9408200261        | <b>TM38353</b>  |
|   |  |                   |    |
| 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3                            | Head Lamp<br>Left, Without Bulb            | 9438200161        | <b>TM38354</b>  |
|   |  |                   |    |
| 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3                            | Head Lamp<br>Right, Without Bulb           | 9438200261        | <b>TM38355</b>  |
|   |  |                   |   |
| 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3                            | Head Lamp<br>Left, Electric, Without Bulb  | 9438200361        | <b>TM38356</b>  |
|   |  |                   |  |
| 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3                            | Head Lamp<br>Right, Electric, Without Bulb | 9438200461        | <b>TM38357</b>  |
|   |  |                   |  |
| 970 ATEGO<br>972 ATEGO<br>976 ATEGO<br>958 ATEGO 2<br>970 ATEGO 2<br>972 ATEGO 2<br>974 ATEGO 2 | Head Lamp<br>Left, Without Bulb            | 9738202661        | <b>TM11864</b>  |
|   |  |                   |  |
| 970 ATEGO<br>972 ATEGO<br>976 ATEGO<br>958 ATEGO 2<br>970 ATEGO 2<br>972 ATEGO 2<br>974 ATEGO 2 | Head Lamp<br>Right, Without Bulb           | 9738202761        | <b>TM11865</b>  |
|   |  |                   |  |





| TM No.  | Replaces Ref. No: | Description                                | Model / Details   |
|---|-------------------|--|---|
| <b>TM12057</b><br>   | 9738202861        | Head Lamp<br>Left, Electric, Without Bulb  | 375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>976 ATEGO<br>375 ATEGO 2<br>970 ATEGO 2<br>972 ATEGO 2 |
| <b>TM12058</b><br>   | 9738202961        | Head Lamp<br>Right, Electric, Without Bulb | 375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>976 ATEGO<br>375 ATEGO 2<br>970 ATEGO 2<br>972 ATEGO 2 |
| <b>TM38358</b><br>  | 9438202261        | Head Lamp<br>Left, Xenon, Without Bulb     | 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3                          |
| <b>TM38359</b><br> | 9438202361        | Head Lamp<br>Right, Xenon, Without Bulb    | 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3                          |
| <b>TM38360</b><br> | 9438201661        | Head Lamp<br>Left, Without Bulb            | 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3                          |
| <b>TM38361</b><br> | 9438201761        | Head Lamp<br>Right, Without Bulb           | 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3                          |
| <b>TM38362</b><br> | 9438201461        | Head Lamp<br>Left, Without Bulb            | 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3                          |



| Model / Details   | Description                                       | Replaces Ref. No:                      | TM No.         |
|---|---|--|----------------|
| 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3                          | Head Lamp<br>Right, Without Bulb                  | 9438201561                             | <b>TM38363</b> |
|   |   |  |                |
| 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>375 AXOR<br>375 AXOR 2  | Head Lamp<br>Left, Without Bulb                   | 9418205361<br>9418202761<br>9418200561 | <b>TM11722</b> |
|   |   |  |                |
| 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>375 AXOR<br>375 AXOR 2  | Head Lamp<br>Right, Without Bulb                  | 9418205461<br>9418202861<br>9418200661 | <b>TM11721</b> |
|   |   |  |                |
| 970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>958 ATEGO 2<br>970 ATEGO 2<br>972 ATEGO 2 | Head Lamp<br>LHD, Manual, Left, With<br>E Mark    | 9738201361                             | <b>TM11733</b> |
|   |   |  |                |
| 970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>958 ATEGO 2<br>970 ATEGO 2<br>972 ATEGO 2 | Head Lamp<br>LHD, Manual, Right, With<br>E Mark   | 9738201461                             | <b>TM11732</b> |
|   |   |  |                |
| 375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>970 ATEGO 2<br>972 ATEGO 2   | Head Lamp<br>LHD, Electric, Left, With<br>E Mark  | 9738200561                             | <b>TM10816</b> |
|   |   |  |                |
| 375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>970 ATEGO 2<br>972 ATEGO 2   | Head Lamp<br>LHD, Electric, Right, With<br>E Mark | 9738200661                             | <b>TM10815</b> |
|   |   |  |                |












| TM No.  | Replaces Ref. No: | Description   | Model / Details  |
|---|-------------------|---|--|
| <b>TM10806</b><br>   | 9018200161        | Head Lamp<br>LHD, Left, Without Fog<br>Lamp, Without<br>E Mark<br>Repl. Hella: 1AH 006<br>900-011     | 690 SPRINTER<br>901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER                 |
| <b>TM10805</b><br>   | 9018200261        | Head Lamp<br>LHD, Right, Without Fog<br>Lamp, Without<br>E Mark<br>Repl. Hella: 1AH 006<br>900-021    | 690 SPRINTER<br>901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER                 |
| <b>TM12014</b><br>  | 9018200561        | Head Lamp<br>LHD, Left, With Fog Lamp,<br>Without<br>E Mark<br>Repl. Hella: 1EH 006<br>900-051        | 690 SPRINTER<br>901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER                 |
| <b>TM12015</b><br> | 9018200661        | Head Lamp<br>LHD, Right, With Fog<br>Lamp, Without<br>E Mark<br>Repl. Hella: 1EH 006<br>900-061       | 690 SPRINTER<br>901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER                 |
| <b>TM10824</b><br> | 9018202661        | Head Lamp<br>LHD, Left, With Fog Lamp,<br>H1-H7,<br>With E Mark<br>Repl. Hella: 1EH 246<br>047-051    | 901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER<br>905 SPRINTER<br>909 SPRINTER |
| <b>TM10823</b><br> | 9018202761        | Head Lamp<br>LHD, Right, With Fog<br>Lamp, H1-H7,<br>With E Mark<br>Repl. Hella: 1EH 246<br>047-061   | 901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER<br>905 SPRINTER<br>909 SPRINTER |
| <b>TM10825</b><br> | 9018202461        | Head Lamp<br>LHD, Left, Without Fog<br>Lamp, H7-H3,<br>With E Mark<br>Repl. Hella: 1EH 246<br>047-011 | 901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER<br>905 SPRINTER                 |












| Model / Details  | Description   | Replaces Ref. No: | TM No.  |
|--|---|-------------------|---|
| 901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER<br>905 SPRINTER | Head Lamp<br>LHD, Right, Without Fog<br>Lamp, H7-<br>H3, With E Mark<br>Repl. Hella: 1EH 246<br>047-021 | 9018202561        | <b>TM11977</b><br>   |
| 900 SPRINTER<br>906 SPRINTER   | Head Lamp<br>LHD, Left, Without Fog<br>Lamp, Without<br>E Mark<br>Repl. Hella: 1EB 247<br>012-011       | 9068200161        | <b>TM12021</b><br>   |
| 900 SPRINTER<br>906 SPRINTER   | Head Lamp<br>LHD, Right, Without Fog<br>Lamp, Without<br>E Mark<br>Repl. Hella: 1EB 247<br>012-021      | 9068200261        | <b>TM12020</b><br>  |
| 963 ACTROS MP4   | Head Lamp<br>LHD, Left, With Signal<br>Lamp, With E<br>Mark   | 9608200239        | <b>TM38364</b><br> |
| 963 ACTROS MP4   | Head Lamp<br>LHD, Right, With Signal<br>Lamp, With<br>E Mark  | 9608200339        | <b>TM38365</b><br> |
| 963 ACTROS MP4   | Head Lamp<br>LHD, Left, With Signal<br>Lamp, With<br>Daytime, With E Mark                               | 9608200439        | <b>TM38366</b><br> |
| 963 ACTROS MP4   | Head Lamp<br>LHD, Right, With Signal<br>Lamp, , With<br>Daytime, With E Mark                            | 9608200539        | <b>TM38367</b><br> |



| TM No.  | Replaces Ref. No:        | Description  | Model / Details   |
|---|--------------------------|--|---|
| <b>TM12023</b><br>   | 9068200561               | Head Lamp<br>Left, With Fog Lamp, With-<br>out E Mark<br>Repl. Hella: 1EB 247<br>012-051 | 906 SPRINTER  |
| <b>TM12022</b><br>   | 9068200661               | Head Lamp<br>Right, With Fog Lamp,<br>Without E Mark<br>Repl. Hella: 1EB 247<br>012-061  | 906 SPRINTER  |
| <b>TM11816</b><br>   | 0048261390               | Lens, Head Lamp<br>Left  | BM MODEL<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>970 ATEGO 2<br>972 ATEGO 2<br>974 ATEGO 2 |
| <b>TM11815</b><br> | 0048261290               | Lens, Head Lamp<br>Right   | 375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>958 ATEGO 2<br>970 ATEGO 2               |
| <b>TM38368</b><br> | 0008264210               | Lens, Head Lamp<br>Left  | 970 ATEGO 2<br>375 AXOR<br>374 AXOR 2<br>375 AXOR 2<br>940 AXOR 2<br>942 AXOR 2<br>943 AXOR 2             |
| <b>TM38369</b><br> | 0008264310               | Lens, Head Lamp<br>Right   | 970 ATEGO 2<br>375 AXOR<br>374 AXOR 2<br>375 AXOR 2<br>940 AXOR 2<br>942 AXOR 2<br>943 AXOR 2             |
| <b>TM11728</b><br> | 0048262590<br>0048260690 | Lens, Head Lamp<br>Left  | 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>375 AXOR<br>375 AXOR 2              |



| Model / Details   | Description   | Replaces Ref. No:        | TM No.  |
|---|---|--------------------------|---|
| 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>375 AXOR<br>375 AXOR 2  | Lens, Head Lamp<br>Right  | 0048262690<br>0048260790 | <b>TM11727</b><br>   |
| 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3                          | Lens, Head Lamp<br>Left   | 0008264710               | <b>TM11866</b><br>   |
| 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3                          | Lens, Head Lamp<br>Right  | 0008264610               | <b>TM11867</b><br>  |
| 375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>976 ATEGO<br>375 ATEGO 2<br>958 ATEGO 2<br>970 ATEGO 2 | Lens, Head Lamp<br>LHD, Left, With E Mark   | 0008264410               | <b>TM38370</b><br> |
| 375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>976 ATEGO<br>375 ATEGO 2<br>958 ATEGO 2<br>970 ATEGO 2 | Lens, Head Lamp<br>LHD, Right, With E Mark  | 0008264510               | <b>TM38371</b><br> |
| 690 SPRINTER<br>901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER                  | Lens, Head Lamp<br>LHD, Left, Without E Mark<br>Repl. Hella: 9ES 143<br>775-001     | 0008201666               | <b>TM12027</b><br> |
| 690 SPRINTER<br>901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER                  | Lens, Head Lamp<br>LHD, Right, Without E<br>Mark<br>Repl. Hella: 9ES 143<br>776-001 | 0008201766               | <b>TM12028</b><br> |





| TM No.  | Replaces Ref. No: | Description                     | Model / Details   |
|---|-------------------|---------------------------------|---|
| <b>TM12094</b><br>   | 9608260059        | Frame, Head Lamp<br>LHD, Left   | 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS                                    |
| <b>TM12095</b><br>   | 9608260159        | Frame, Head Lamp<br>LHD, Right  | 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS                                    |
| <b>TM38372</b><br>   | 9608260259        | Frame, Head Lamp<br>LHD, Left   | 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS                                    |
| <b>TM38373</b><br> | 9608260359        | Frame, Head Lamp<br>LHD, Right  | 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS                                    |
| <b>TM38374</b><br> | 9066200224        | Frame, Head Lamp<br>Left        | 906 SPRINTER  |
| <b>TM38375</b><br> | 9066200424        | Frame, Head Lamp<br>Right       | 906 SPRINTER  |
| <b>TM38376</b><br> | 9408850722        | Frame, Head Lamp<br>Left, Black | 375 ACTROS<br>970 ATEGO 2<br>375 AXOR<br>374 AXOR 2<br>375 AXOR 2<br>940 AXOR 2<br>942 AXOR 2 |










| Model / Details   | Description                       | Replaces Ref. No: | TM No.         |
|---|-----------------------------------|-------------------|----------------|
| 375 ACTROS<br>970 ATEGO 2<br>375 AXOR<br>374 AXOR 2<br>375 AXOR 2<br>940 AXOR 2<br>942 AXOR 2 | Frame, Head Lamp<br>Right, Black  | 9408850822        | <b>TM38377</b> |
| 375 ACTROS<br>970 ATEGO 2<br>375 AXOR<br>374 AXOR 2<br>375 AXOR 2<br>940 AXOR 2<br>942 AXOR 2 | Frame, Head Lamp<br>Left, Chrome  | 9408850922        | <b>TM11920</b> |
| 375 ACTROS<br>970 ATEGO 2<br>375 AXOR<br>374 AXOR 2<br>375 AXOR 2<br>940 AXOR 2<br>942 AXOR 2 | Frame, Head Lamp<br>Right, Chrome | 9408851022        | <b>TM11921</b> |
| 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3                          | Frame, Head Lamp<br>Left          | 9438260259        | <b>TM11896</b> |
| 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3                          | Frame, Head Lamp<br>Right         | 9438260359        | <b>TM11897</b> |
| 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>375 AXOR<br>375 AXOR 2  | Bracket, Head Lamp                | 9418260118        | <b>TM11818</b> |
| 970 ATEGO 2<br>375 AXOR<br>374 AXOR 2<br>375 AXOR 2<br>940 AXOR 2<br>942 AXOR 2<br>943 AXOR   | Bracket, Head Lamp                | 9408260013        | <b>TM38378</b> |



| TM No.  | Replaces Ref. No: | Description                              | Model / Details   |
|---|-------------------|--|---|
| <b>TM38379</b><br>   | 9408260113        | Bracket, Head Lamp                       | 970 ATEGO 2<br>375 AXOR<br>374 AXOR 2<br>375 AXOR 2<br>940 AXOR 2<br>942 AXOR 2<br>943 AXOR 2 |
| <b>TM38380</b><br>   | 9438800214        | Bracket, Head Lamp<br>Left               | 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3                          |
| <b>TM38381</b><br>   | 9438800314        | Bracket, Head Lamp<br>Right              | 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3                          |
| <b>TM38382</b><br> | 9438200046        | Bracket, Head Lamp                       | 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3                          |
| <b>TM18975</b><br> | 0008261759        | Bracket, Head Lamp<br>Left, With E Mark  | 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>375 AXOR<br>375 AXOR 2  |
| <b>TM18976</b><br> | 0008261859        | Bracket, Head Lamp<br>Right, With E Mark | 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>375 AXOR<br>375 AXOR 2  |
| <b>TM11983</b><br> | 9608803905        | Protective Cap, Head<br>Lamp<br>Left     | 963 ACTROS MP4  |












| Model / Details  | Description                           | Replaces Ref. No: | TM No.  |
|--|---------------------------------------|-------------------|---|
| 963 ACTROS MP4   | Protective Cap, Head<br>Lamp<br>Right | 9608804005        | <b>TM11982</b><br>   |
| 963 ACTROS MP4<br>963 ACTROS MP4                           | Cover, Head Lamp<br>Left              | 9608809658        | <b>TM38383</b><br>   |
| 963 ACTROS MP4<br>963 ACTROS MP4                           | Cover, Head Lamp<br>Right             | 9608809758        | <b>TM38384</b><br>  |
| 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS | Grille, Head Lamp<br>LHD, Left        | 9608800085        | <b>TM38385</b><br> |
| 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS | Grille, Head Lamp<br>LHD, Right       | 9608800185        | <b>TM38386</b><br> |
| 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS | Grille, Head Lamp<br>LHD, Left        | 9608805985        | <b>TM38387</b><br> |
| 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS | Grille, Head Lamp<br>LHD, Right       | 9608806085        | <b>TM38388</b><br> |





| TM No.  | Replaces Ref. No:        | Description                      | Model / Details   |
|---|--------------------------|----------------------------------|---|
| <b>TM38389</b><br>   | 9438800485               | Grille, Head Lamp<br>Left        | 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3                        |
| <b>TM38390</b><br>   | 9438800585               | Grille, Head Lamp<br>Right       | 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3                        |
| <b>TM11861</b><br>   | 9438800185               | Grille, Head Lamp<br>Left        | 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3                        |
| <b>TM11862</b><br> | 9438800285               | Grille, Head Lamp<br>Right       | 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3                        |
| <b>TM12086</b><br> | 9435450904<br>9435451704 | Switch, Head Lamp<br>75x87x87    | 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3                        |
| <b>TM38391</b><br> | 0005453704<br>0005454704 | Switch, Head Lamp                | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO |
| <b>TM12005</b><br> | 9068200464               | Stop Light<br>Left, Without Bulb | 906 SPRINTER  |



| Model / Details  | Description   | Replaces Ref. No:                                    | TM No.  |
|--|---|--|---|
| 906 SPRINTER   | Stop Light<br>Right, Without Bulb                                   | 9068201764   | <b>TM12006</b><br>   |
| 970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>970 ATEGO 2<br>972 ATEGO 2<br>974 ATEGO 2              | Stop Light<br>Left, Without Bulb                                    | 0025446803<br>0025447003<br>0025446303<br>0025446503 | <b>TM11616</b><br>   |
| 346 L 1924<br>346 L 1928<br>346 LA 1924<br>346 LAK 1924<br>346 LAS 1924<br>346 LK 1924<br>346 LK 1928      | Stop Light<br>Left, Without Bulb                                    | 0015446903<br>0015448003<br>0025440203<br>0015447003 | <b>TM11831</b><br>  |
| 346 L 1924<br>346 L 1928<br>346 LA 1924<br>346 LAK 1924<br>346 LAS 1924<br>346 LK 1924<br>346 LK 1928      | Stop Light<br>Right, Without Bulb                                   | 0015446803<br>0015448103<br>0025440403<br>0005405470 | <b>TM11803</b><br> |
| 970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>970 ATEGO 2<br>972 ATEGO 2<br>974 ATEGO 2              | Stop Light<br>Right, Without Bulb                                   | 0025446903<br>0025447103<br>0025446403<br>0025446603 | <b>TM11234</b><br> |
| 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3     | Stop Light<br>Left, With E Mark<br>Repl. Hella: 2VD 007<br>500-411  | 0015405770<br>0015406270                             | <b>TM11745</b><br> |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 | Stop Light<br>Right, With E Mark<br>Repl. Hella: 2VP 007<br>500-421 | 0015405870<br>0015406370                             | <b>TM11746</b><br> |






| TM No.  | Replaces Ref. No:        | Description  | Model / Details   |
|---|--------------------------|--|---|
| <b>TM11231</b><br>   | 0008261556               | Stop Light<br>Left, With E Mark  | 901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER<br>909 SPRINTER  |
| <b>TM11230</b><br>   | 0008261656               | Stop Light<br>Right, With E Mark   | 901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER<br>909 SPRINTER  |
| <b>TM11869</b><br>  | 0025445503<br>0025447303 | Stop Light<br>Left, With Number Plate,<br>With E Mark<br>Repl. Hella: 2VD 008<br>204-111 | 901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER<br>905 SPRINTER  |
| <b>TM11870</b><br> | 0025445403               | Stop Light<br>Right, No Number Plate,<br>With E Mark<br>Repl. Hella: 2VP 008<br>204-101  | 690 SPRINTER<br>901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER<br>905 SPRINTER                          |
| <b>TM10401</b><br> | 0025444490<br>0025444790 | Stop Light<br>With E Mark<br>Repl. Hella: 9EL 152 891-<br>001                            | 970 ATEGO<br>972 ATEGO<br>976 ATEGO<br>970 ATEGO 2<br>972 ATEGO 2<br>974 ATEGO 2<br>975 ATEGO 2                       |
| <b>TM38392</b><br> | 0035440903<br>0035441703 | Stop Light<br>Left, With Number Plate,<br>With E Mark                                    | 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3<br>963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS |
| <b>TM38393</b><br> | 0035440803<br>0035441603 | Stop Light<br>Right, No Number Plate,<br>No Buzzer,<br>With E Mark                       | 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3<br>963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS |



| Model / Details   | Description  | Replaces Ref. No:                                    | TM No.  |
|---|--|--|---|
| -   | Stop Light<br>Right, No Number Plate,<br>With Buzzer,<br>With E Mark       | 0005441003<br>0005441803                             | <b>TM38394</b><br>   |
| 963 ACTROS MP4<br>964 AROCS<br>964 ACTROS MP4<br>964 ANTOS  | Stop Light<br>Left, With Number Plate,<br>With E Mark                      | 0035441203<br>0035442003<br>0035442303<br>0035442603 | <b>TM38395</b><br>   |
| 963 ACTROS MP4<br>964 AROCS<br>964 ACTROS MP4<br>964 ANTOS  | Stop Light<br>Right, No Number Plate,<br>No Buzzer,<br>With E Mark         | 0035441103<br>0035441903<br>0035442203<br>0035442503 | <b>TM38396</b><br>  |
| 963 ACTROS MP4<br>964 AROCS<br>964 ACTROS MP4<br>964 ANTOS  | Stop Light<br>Right, No Number Plate,<br>With Buzzer,<br>With E Mark       | 0035441303<br>0035442103<br>0035442403<br>0035442703 | <b>TM38397</b><br> |
| 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3                | Lens, Stop Light<br>Left, With E Mark<br>Repl. Hella: 9EL 134 296-<br>041  | 0025441290<br>0025441790<br>0025443690               | <b>TM11691</b><br> |
| 676 LK/LN2<br>650 MK<br>651 MK<br>652 MK<br>653 MK<br>654 MK<br>625 SK  | Lens, Stop Light<br>Right, With E Mark<br>Repl. Hella: 9EL 134 296-<br>051 | 0025441390<br>0025441690<br>0025443590<br>0025443790 | <b>TM11692</b><br> |
| 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3<br>963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS | Lens, Stop Light<br>With E Mark  | 0025447390   | <b>TM38398</b><br> |






| TM No.  | Replaces Ref. No:                      | Description  | Model / Details  |
|---|--|--|--|
| <b>TM11275</b><br>   | 9068262056<br>0008262056<br>0008262256 | Lens, Stop Light<br>Left   | 906 SPRINTER   |
| <b>TM12007</b><br>   | 9068200164                             | Stop Light<br>Left, Without E Mark, With-<br>out Bulb                    | 900 SPRINTER<br>906 SPRINTER   |
| <b>TM12008</b><br>   | 9068200264                             | Stop Light<br>Right, Without E Mark,<br>Without Bulb                     | 900 SPRINTER<br>906 SPRINTER   |
| <b>TM38399</b><br> | 0008261856S<br>0008260756S             | Stop Light<br>Left, Without E Mark, With-<br>out Bulb,<br>Without Socket | 690 SPRINTER<br>904 SPRINTER<br>904 SPRINTER<br>690 SPRINTER<br>901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER |
| <b>TM38400</b><br> | 0008261956S<br>0008260856S             | Stop Light<br>Right, Without E Mark,<br>Without Bulb,<br>Without Socket  | 690 SPRINTER<br>904 SPRINTER<br>904 SPRINTER<br>690 SPRINTER<br>901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER |
| <b>TM11924</b><br> | 9068200456                             | Stop Light<br>Auxiliary, With E Mark                                     | 900 SPRINTER<br>906 SPRINTER   |
| <b>TM12033</b><br> | 0008261856                             | Lens, Stop Light<br>Left, With E Mark                                    | 690 SPRINTER<br>901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER   |





| Model / Details   | Description                                 | Replaces Ref. No:                      | TM No.  |
|---|---|--|---|
| 690 SPRINTER<br>901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER                  | Lens, Stop Light<br>Right, With E Mark      | 0008261956                             | <b>TM12034</b><br>   |
| 906 SPRINTER  | Lens, Stop Light<br>Right                   | 9068262156<br>0008262156<br>0008262356 | <b>TM11218</b><br>   |
| 970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>970 ATEGO 2<br>972 ATEGO 2<br>974 ATEGO 2 | Lens, Stop Light                            | 0025446190                             | <b>TM10397</b><br>  |
| 639 VIANO<br>636 VIANO<br>639 VIANO<br>639 VITO   | Reflector, Stop Light<br>Left, With E Mark  | 6398260440<br>6398260040               | <b>TM38401</b><br> |
| 639 VIANO<br>636 VIANO<br>639 VIANO<br>639 VITO   | Reflector, Stop Light<br>Right, With E Mark | 6398260540<br>6398260140               | <b>TM38402</b><br> |
| 970 ATEGO 2<br>375 AXOR<br>374 AXOR 2<br>375 AXOR 2<br>940 AXOR 2<br>942 AXOR 2<br>943 AXOR 2 | Signal Lamp<br>Left, Without Bulb           | 9408200321                             | <b>TM38403</b><br> |
| 970 ATEGO 2<br>375 AXOR<br>374 AXOR 2<br>375 AXOR 2<br>940 AXOR 2<br>942 AXOR 2<br>943 AXOR 2 | Signal Lamp<br>Right, Without Bulb          | 9408200421                             | <b>TM38404</b><br> |






| TM No.  | Replaces Ref. No:                                    | Description                        | Model / Details  |
|---|--|------------------------------------|--|
| <b>TM11823</b><br>   | 9418200521   | Signal Lamp<br>Left, Without Bulb  | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 |
| <b>TM11837</b><br>   | 9418200921   | Signal Lamp<br>Right, Without Bulb | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 |
| <b>TM11817</b><br>   | 0005447611<br>0005447211<br>0005445411<br>0005445311 | Signal Lamp<br>Without Bulb        | 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3     |
| <b>TM10921</b><br> | 9738200321   | Signal Lamp<br>Left, Without Bulb  | 375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>375 ATEGO 2<br>958 ATEGO 2                |
| <b>TM10920</b><br> | 9738200421   | Signal Lamp<br>Right, Without Bulb | 375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>375 ATEGO 2<br>958 ATEGO 2                |
| <b>TM11824</b><br> | 9418201321   | Signal Lamp<br>Without Bulb        | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS   |
| <b>TM38405</b><br> | 9418200721   | Signal Lamp<br>Without Bulb        | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3 |



| Model / Details   | Description   | Replaces Ref. No: | TM No.         |
|---|---|-------------------|----------------|
| 375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>976 ATEGO<br>375 ATEGO 2<br>958 ATEGO 2<br>970 ATEGO 2 | Signal Lamp<br>Left, With E Mark, Without<br>Bulb                       | 9738200521        | <b>TM11838</b> |
|   |   |                   |                |
| 375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>976 ATEGO<br>375 ATEGO 2<br>958 ATEGO 2<br>970 ATEGO 2 | Signal Lamp<br>Right, With E Mark, With-<br>out Bulb                    | 9738200621        | <b>TM11839</b> |
|   |   |                   |                |
| 690 SPRINTER<br>901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER                  | Signal Lamp<br>Left, Without E Mark<br>Repl. Hella: 2BA 007 016-<br>031 | 9018200121        | <b>TM11996</b> |
|   |   |                   |                |
| 690 SPRINTER<br>901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER                  | Signal Lamp<br>Right, Without E Mark<br>Repl. Hella: 2BA 0070<br>16-041 | 9018200221        | <b>TM12011</b> |
|   |   |                   |                |
| 375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>970 ATEGO 2<br>972 ATEGO     | Signal Lamp<br>Left, With E Mark  | 9738200121        | <b>TM11808</b> |
|   |   |                   |                |
| 375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>970 ATEGO 2<br>972 ATEGO 2   | Signal Lamp<br>Right, With E Mark                                       | 9738200221        | <b>TM11809</b> |
|   |   |                   |                |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO   | Signal Lamp<br>With E Mark  | 0005444111        | <b>TM11749</b> |
|   |   |                   |                |



| TM No.  | Replaces Ref. No: | Description   | Model / Details   |
|---|-------------------|---|---|
| <b>TM11997</b><br>   | 2108200921        | Signal Lamp<br>White, With E Mark                                       | 414 VANEO<br>901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER<br>909 SPRINTER<br>638 VITO   |
| <b>TM11998</b><br>   | 2108200421        | Signal Lamp<br>Amber, With E Mark                                       | 690 SPRINTER<br>901 SPRINTER<br>902 SPRINTER<br>903 SPRINTER<br>904 SPRINTER<br>638 VITO<br>638 V-CLASS |
| <b>TM12081</b><br>   | 0018204921        | Signal Lamp<br>Left, Without E Mark<br>Repl. Hella: 2BM 006<br>692-077  | 405 UNIMOG<br>408 UNIMOG<br>418 UNIMOG<br>436 UNIMOG<br>437 UNIMOG<br>900 SPRINTER<br>901 SPRINTER      |
| <b>TM12082</b><br> | 0018205021        | Signal Lamp<br>Right, Without E Mark<br>Repl. Hella: 2BM 006<br>692-087 | 405 UNIMOG<br>408 UNIMOG<br>418 UNIMOG<br>436 UNIMOG<br>437 UNIMOG<br>900 SPRINTER<br>901 SPRINTER      |
| <b>TM12036</b><br> | 0018228920        | Signal Lamp<br>Left, Without E Mark, With-<br>out Bulb                  | 906 SPRINTER  |
| <b>TM12035</b><br> | 0018229020        | Signal Lamp<br>Right, Without E Mark,<br>Without Bulb                   | 906 SPRINTER  |
| <b>TM11832</b><br> | 9408200056        | Fog Lamp<br>Left, Without Bulb  | 375 ACTROS<br>970 ATEGO 2<br>375 AXOR<br>374 AXOR 2<br>375 AXOR 2<br>940 AXOR 2<br>942 AXOR 2           |



| Model / Details  | Description                                  | Replaces Ref. No:        | TM No.         |
|--|--|--------------------------|----------------|
| 375 ACTROS<br>970 ATEGO 2<br>375 AXOR<br>374 AXOR 2<br>375 AXOR 2<br>940 AXOR 2<br>942 AXOR  | Fog Lamp<br>Right, Without Bulb              | 9408200156               | <b>TM11833</b> |
| 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/                          | Fog Lamp<br>Left, Without Bulb               | 9438200056               | <b>TM10814</b> |
| 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3                         | Fog Lamp<br>Right, Without Bulb              | 9438200156               | <b>TM10813</b> |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>375 AXOR<br>944 AXOR 2               | Fog Lamp<br>Left, Without Bulb               | 9418200156               | <b>TM11729</b> |
| 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>375 AXOR<br>944 AXOR 2               | Fog Lamp<br>Right, Without Bulb              | 9418200256               | <b>TM38406</b> |
| 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>375 AXOR<br>375 AXOR 2 | Fog Lamp<br>High Beam, Left, With E<br>Mark  | 0028207656<br>0028208456 | <b>TM11821</b> |
| 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>375 AXOR<br>375 AXOR 2 | Fog Lamp<br>High Beam, Right, With E<br>Mark | 0028207756<br>0028208556 | <b>TM11822</b> |



| TM No.  | Replaces Ref. No: | Description  | Model / Details |
|---|-------------------|--|-----------------|
| <b>TM11927</b><br>   | 9608200456        |  |                 |
| <b>TM11928</b><br>   | 9608200556        | Fog Lamp<br>LHD, Right, With E Mark                            | 963 ACTROS MP4  |
| <b>TM12090</b><br>  | 9068203861        | Fog Lamp<br>Left, With E Mark<br>Repl. Hella: 1N0 011 250-351  | 906 SPRINTER    |
| <b>TM12091</b><br> | 9068203961        | Fog Lamp<br>Right, With E Mark<br>Repl. Hella: 1N0 011 250-361 | 906 SPRINTER    |
| <b>TM19532</b><br> | 9608857874        | Frame, Fog Lamp<br>Left  | 963 ACTROS MP4  |
| <b>TM19533</b><br> | 9608857974        | Frame, Fog Lamp<br>Right                                       | 963 ACTROS MP4  |
| <b>TM19531</b><br> | 9068850253        | Frame, Fog Lamp<br>Left  | 906 SPRINTER    |





| Model / Details   | Description                     | Replaces Ref. No: | TM No.  |
|---|---------------------------------|-------------------|---|
| 906 SPRINTER  | Frame, Fog Lamp<br>Right        | 9068850353        | <b>TM19530</b>  |
|   |                                 |                   |    |
| 963 ACTROS MP4  | Frame, Fog Lamp<br>Left         | 9608853874        | <b>TM19291</b>  |
|   |                                 |                   |    |
| 963 ACTROS MP4  | Frame, Fog Lamp<br>Right        | 9608853974        | <b>TM19290</b>  |
|   |                                 |                   |   |
| 970 ATEGO 2<br>375 AXOR<br>374 AXOR 2<br>940 AXOR 2<br>942 AXOR 2<br>943 AXOR 2<br>944 AXOR 2                         | Step Lamp<br>Without E Mark     | 0018207501        | <b>TM11748</b>  |
|   |                                 |                   |  |
| 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3<br>963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS | Step Lamp<br>Without E Mark     | 0028200001        | <b>TM12083</b>  |
|   |                                 |                   |  |
| 970 ATEGO 2<br>375 AXOR<br>374 AXOR 2<br>940 AXOR 2<br>942 AXOR 2<br>943 AXOR 2<br>958 AXOR 2                         | Step Signal Lamp<br>With E Mark | 9408200221        | <b>TM11804</b>  |
|   |                                 |                   |  |
| 375 ACTROS<br>958 ATEGO 2<br>375 AXOR<br>374 AXOR 2<br>375 AXOR 2<br>950 AXOR 2<br>952 AXOR 2                         | Step Signal Lamp<br>With E Mark | 9418201021        | <b>TM11834</b>  |
|   |                                 |                   |  |





| TM No.  | Replaces Ref. No:                      | Description   | Model / Details   |
|---|--|---|---|
| <b>TM12079</b><br>   | 9608201021<br>9608200421               | Step Signal Lamp<br>Left                                    | 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS  |
| <b>TM12080</b><br>   | 9608201121<br>9608200521               | Step Signal Lamp<br>Right                                   | 963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS<br>964 AROCS  |
| <b>TM38407</b><br>   | 9438201101                             | Cab Working Lamp<br>Left, Without E Mark                    | 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3<br>963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS |
| <b>TM38408</b><br> | 9438201201                             | Cab Working Lamp<br>Right, Without E Mark                   | 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3<br>963 ACTROS MP4<br>964 ACTROS MP4<br>964 ANTOS |
| <b>TM11639</b><br> | 0005440947<br>0005441347<br>0005441847 | Spot Lamp<br>With E Mark<br>Repl. Hella: 1GA 998<br>522-011 | 950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3            |
| <b>TM12688</b><br> | 6398200256                             | Licence Lamp<br>Without E Mark                              | 906 SPRINTER<br>636 VIANO<br>639 VIANO  |
| <b>TM12018</b><br> | 0038201256<br>0038202956               | Signal Lamp<br>Without E Mark                               | 900 SPRINTER<br>906 SPRINTER  |



| Model / Details   | Description                                      | Replaces Ref. No: | TM No.  |
|---|--|-------------------|---|
| 906 SPRINTER  | Side Marker Lamp<br>With E Mark                  | 9068201456        | <b>TM12104</b>  |
|   |  |                   |    |
| 979 ACCELO<br>375 ACTROS<br>375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO     | Side Marker Lamp<br>Left, White, With E Mark     | 0028205056        | <b>TM10922</b>  |
|   |  |                   |    |
| 979 ACCELO<br>375 ACTROS<br>375 ATEGO<br>970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO     | Side Marker Lamp<br>Right, White, With E Mark    | 0028205156        | <b>TM11811</b>  |
|   |  |                   |    |
| 970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>970 ATEGO 2<br>972 ATEGO 2<br>974 ATEGO 2 | Side Marker Lamp<br>Left, Amber, With E Mark     | 0028206856        | <b>TM12043</b>  |
|   |  |                   |  |
| 970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>970 ATEGO 2<br>972 ATEGO 2<br>974 ATEGO 2 | Side Marker Lamp<br>Right, Amber, With E Mark    | 0028206956        | <b>TM12044</b>  |
|   |  |                   |  |
| 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3<br>963 ACTROS MP4        | Daytime Running Light<br>Led, Left, With E Mark  | 9608200956        | <b>TM11930</b>  |
|   |  |                   |  |
| 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3<br>963 ACTROS MP4        | Daytime Running Light<br>Led, Right, With E Mark | 9608201056        | <b>TM11931</b>  |
|   |  |                   |  |





| TM No.  | Replaces Ref. No:                                    | Description                                    | Model / Details  |
|---|--|--|--|
| <b>TM38409</b><br>   | 9438200756   | Daytime Running Light<br>Left, Without E Mark  | 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3   |
| <b>TM38410</b><br>   | 9438200856   | Daytime Running Light<br>Right, Without E Mark | 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3   |
| <b>TM38411</b><br>   | 9067400030   | Licence Lamp Bracket                           | 906 SPRINTER   |
| <b>TM10074</b><br> | 9415410103   | Cover, Battery                                 | BM MODEL<br>375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3 |
| <b>TM11755</b><br> | 6205410303   | Cover, Battery                                 | 615 LK/LN2<br>650 MK<br>651 MK<br>652 MK<br>653 MK<br>654 MK<br>699 MK   |
| <b>TM38412</b><br> | 9705410005<br>9705410203                             | Cover, Battery                                 | 970 ATEGO<br>972 ATEGO<br>975 ATEGO<br>976 ATEGO<br>970 ATEGO 2<br>972 ATEGO 2<br>974 ATEGO 2                      |
| <b>TM12207</b><br> | 9304200065<br>9304200165<br>9604200344<br>9604200444 | Cover, Battery                                 | 934 ACTROS 2/3<br>375 AXOR<br>944 AXOR 2   |



| Model / Details  | Description   | Replaces Ref. No:        | TM No.  |
|--|---|--------------------------|---|
| 375 ATEGO  | Cover, Battery  | 3755410103               | <b>TM38413</b>  |
|  |   |                          |    |
| 932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3<br>934 ACTROS 2/3<br>942 AXOR 2<br>943 AXOR 2       | Cover, Battery  | 9325400182               | <b>TM38414</b>  |
|  |   |                          |    |
| 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3 | Yoke, Battery   | 0009880385<br>0009880485 | <b>TM38415</b>  |
|  |   |                          |   |
| 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3 | Battery Terminal, Battery<br>Positive Pole            | 072332013100             | <b>TM38416</b>  |
|  |   |                          |  |
| 375 ACTROS<br>950 ACTROS<br>952 ACTROS<br>953 ACTROS<br>954 ACTROS<br>930 ACTROS 2/3<br>932 ACTROS 2/3 | Battery Terminal, Battery<br>Negative Pole            | 072332013200             | <b>TM38417</b>  |
|  |   |                          |  |
| 309 T2/L<br>310 LF 508 D/LF 608 D<br>310 LT 608 D<br>310 T2/L<br>313 T2/L<br>314 LP<br>316 LP          | Electrical Cable, Trailer<br>Electrical<br>Equipments | 3805402181               | <b>TM25183</b>  |
|  |   |                          |  |
| 309 T2/L<br>309 TL2/L<br>310 LF 508 D/LF 608 D<br>310 LT 608 D<br>310 T2/L<br>313 T2/L<br>314 LP       | Electrical Cable, Trailer<br>Electrical<br>Equipments | 3805402281<br>3805400281 | <b>TM11680</b>  |
|  |   |                          |  |





| TM No.  | Replaces Ref. No:        | Description  | Model / Details  |
|---|--------------------------|--|--|
| <b>TM10456</b><br>   | 0015450626<br>0035453126 | Socket, Trailer Electrical<br>Equipments<br>7 Pole Aluminium, 24V, N<br>Type Screw,<br>Black | 387 NG<br>389 NG<br>421 UNIMOG                                       |
| <b>TM02675</b><br>   | 0001807409               | Maintenance Kit  | 940 AXOR 2<br>942 AXOR 2<br>943 AXOR 2<br>944 AXOR 2                 |
| <b>TM02582</b><br>  | 0001806009               | Maintenance Kit  | 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3 |
| <b>TM02604</b><br> | 0001806209               | Maintenance Kit  | 930 ACTROS 2/3<br>932 ACTROS 2/3<br>933 ACTROS 2/3<br>934 ACTROS 2/3 |
| <b>TM02676</b><br> | 0001807309               | Maintenance Kit  | 375 AXOR<br>940 AXOR 2<br>942 AXOR 2<br>943 AXOR 2<br>944 AXOR 2     |





MERCEDES  
PARTS



| <i>Model / Details</i> | <i>Description</i> | <i>Replaces Ref. No:</i> | <i>TM No.</i> |
|------------------------|--------------------|--------------------------|---------------|
|------------------------|--------------------|--------------------------|---------------|

|  |  |  |  |
|--|--|--|--|
|  |  |  |  |
|  |  |  |  |
|  |  |  |  |
|  |  |  |  |
|  |  |  |  |



**YOU STAY SAFE  
WHEREVER YOU ARE GOING**



**TURKOMOTIVE** AFTERMARKET SOLUTIONS' RELIABLE OE-MATCHING QUALITY COMPONENTS ENSURE  
**YOU STAY MOBILE , WHEREVER YOU ARE GOING**

**FOLLOW  
US**

**#turkomotive**

[www.turkomotive.com](http://www.turkomotive.com)

